



**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES  
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS,  
BALLOONS, & AIRSHIPS**

**BIWEEKLY 2010-12**

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation  
Federal Aviation Administration  
Regulatory Support Division  
Delegation and Airworthiness Programs Branch, AIR-140  
P. O. Box 26460  
Oklahoma City, OK 73125-0460  
FAX 405-954-4104



## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;			
<b>Biweekly 2010-01</b>			
2009-26-05		Pilatus Aircraft Ltd	PC-7
2009-26-07	S 2009-12-51	Turbomeca	Engine: Arriel 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S, and 1S1
2009-26-08	S 2006-21-12	AeroSpace Technologies of Australia Pty Ltd	N22B, N22S, and N24A
2009-26-12	S 2008-19-05	Engine Components, Inc. (ECi)	See AD
<b>Biweekly 2010-02</b>			
2009-21-08 R1		PIAGGIO AERO INDUSTRIES S.p.A.	P-180
2010-01-03		Fire Fighting Enterprises Limited	See AD
2010-02-01		Turbomeca S.A	Arriel 1B, 1D, and 1D1
2010-02-51	E	AGUSTA S.p.A	A109A, A109A II, A109C, and A109K2
<b>Biweekly 2010-03</b>			
2009-19-51		Agusta S.p.A	AB139 and AW139
2009-26-11	S 2006-07-15	Thrush Aircraft, Inc.	See AD
2010-02-07		Eurocopter France	Rotorcraft: SE3160, SA315B, SA316B, SA316C, and SA319B
2010-02-08		Turbomeca	Engine: Turmo IV A and IV C
2010-03-01		Eurocopter France	Rotorcraft: AS332L1, AS332L2, and EC225LP
2010-03-02		Lifesaving Systems Corp.	Appliance
<b>Biweekly 2010-04</b>			
2009-23-51		Sikorsky Aircraft Corporation	Rotorcraft: S-92A
2010-03-03		Bell Helicopter Textron, Inc	Rotorcraft: 205B and 212
2010-03-04		PIAGGIO AERO INDUSTRIES S.p.A	P-180
2010-03-06		Turbomeca	Engine: Arriel 2B and 2B1
2010-03-09		Piaggio Aero Industries S.p.A	P-180
<b>Biweekly 2010-05</b>			
2010-04-05	S 2003-12-05	McCaughey Propeller Systems	Propeller: 1A103/TCM
2010-04-06		Thielert Aircraft Engines GmbH	Engine: TAE 125-01
2010-04-07		Turbomeca	Engine: Arriel 2S1
2010-04-11		Extra Flugzeugproduktions- und Vertriebs- GmbH	EA-300/200, EA-300/L
2010-04-14		Augustair, Inc	2150, 2150 <sup>a</sup> , 2180
2010-04-15		SCHEIBE-Flugzeugbau GmbH	Glider: SF 25C
2010-04-16		SICLI	Appliance: portable fire extinguishers
2010-05-02	S 2009-08-10	Pilatus Aircraft Ltd	PC-12/47E
2010-05-51	E	Eurocopter	Rotorcraft: EC120B
<b>Biweekly 2010-06</b>			
2010-05-10		Hawker Beechcraft	B300, B300C
2010-06-02		Hawker Beechcraft	G58

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;			
<b>Biweekly 2010-07</b>			
2010-06-03		Eurocopter France	Rotorcraft: AS355E, AS355F, AS355F1, AS355F2, and AS355N
2010-06-06	S 99-16-13	MD Helicopters, Inc	Rotorcraft: MD-900
2010-06-07		Eurocopter France	Rotorcraft: AS 332 C, L, L1, and L2; AS 350 B3; AS355 F, F1, F2, and N; SA 365N and N1; AS 365 N2 and N3; SA 366G1; EC 130 B4; and EC 155B and B1
2010-06-08		Sikorsky Aircraft Corporation	Rotorcraft: S-76C
2010-06-11		Honeywell International Inc.	Engine: TFE731-2, TFE731-2A, TFE731-2C, TFE731-3, TFE731-3A, TFE731-3AR, TFE731-3B, TFE731-3BR, TFE731-3C, TFE731-3CR, TFE731-3D, TFE731-3DR, TFE731-3R, TFE731-4, TFE731-4R, TFE731-5, TFE731-5AR, TFE731-5BR, and TFE731-5R
2010-06-12		Thielert Aircraft Engines GmbH	Engine: TAE 125-01 and TAE 125-02-99
<b>Biweekly 2010-08</b>			
2009-08-08 R1	R 2010-08-08	Turbomeca S.A	Engine: Arriel 1B, 1D, and 1D1, Arriel 2B and 2B1
2010-07-02	S 2006-22-05	Honeywell, Inc	Appliance: See AD
2010-07-07		Socata	TBM 700
2010-07-08		Kelly Aerospace Energy Systems, LLC	Appliance: See AD
2010-08-01		Aircraft Industries a.s	Glider: L 23 Super Blanik
<b>Biweekly 2010-09</b>			
2009-08-05R1	R	Liberty Aerospace Incorporated	XL-2
2010-08-04	2007-10-14	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, Jetstream Series 3101, and Jetstream Model 3201
2010-09-08		General Electric Company	Engine: GE CJ610 series turbojet and CF700
<b>Biweekly 2010-10</b>			
2010-05-51	FR	Eurocopter France	Rotorcraft: EC120B
2010-09-01		Eurocopter France	Rotorcraft: AS350B, BA, B1, B2, B3, C, D and D1; and AS 355E, F, F1, F2, N, and NP
2010-09-02		British Aerospace Regional Aircraft	Jetstream Series 3101 and Jetstream Model 3201
2010-09-04		Honeywell International Inc	Appliance: Primus EPIC and Primus APEX flight management systems (FMS)
2010-09-09		Piaggio Aero Industries S.p.A.	P-180
2010-09-13		Turbomeca	Engine: Makila 2A
2010-10-01	S 2009-05-01	GA 8 Airvan (Pty) Ltd	Glider: GA8 and GA8-TC320
<b>Biweekly 2010-11</b>			
2010-10-02		Sikorsky Aircraft Corporation	Rotorcraft: S-76A, B, and C
2010-10-03		Sikorsky Aircraft Corporation	Rotorcraft: S-92A
2010-10-09	S 2008-07-01	Turbomeca	Engine: 1B (that incorporate Turbomeca Modification (mod) TU 148), Arriel 1D, 1D1, and 1S1
2010-10-10		Hawker Beechcraft	390
2010-10-14		Eurocopter France	Rotorcraft: AS332L2
2010-10-15		Eurocopter France	Rotorcraft: AS332L1 and AS332L2
2010-11-51	E	Eurocopter France	Rotorcraft: AS350B, BA, B1, B2, C, D, and D1 helicopters and Model AS355E, F, F1, F2, and N
2010-11-52	E	Sikorsky Aircraft	Rotorcraft: S-76A, B, and C

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;

**Biweekly 2010-12**

2007-19-09 R1 2010-10-16	R	Turbomeca Bell Helicopter Textron and Augusta S.P.A.	Engine: ARRIEL 2B1 Rotorcraft: 205A, 205A-1, 205B, 212, 412, 412EP, and 412CF and Agusta S.p.A. Model AB412, AB412EP
2010-11-04 2010-11-05	S 2009-24-52	Teledyne Continental Motors AVOX Systems and B/E Aerospace	Engine: 240, 346, 360, 470, 520, and 550 and IO-240 See AD
2010-11-06	S 97-11-12	AeroSpace Technologies of Australia Pty Ltd	N22B, N22S, and N24A
2010-11-07 2010-11-08 2010-11-10 2010-11-15	S 2008-11-20	Quartz Mountain Aerospace, Inc Stemme GmbH & Co. KG Turbomeca: Socata	11E S10-VT Engine: Astazou XIV B and XIV H TBM 700
2010-12-51	E	Agusta S.p.A.	Rotorcraft: A119 and AW119 MKII



---

**2007-19-09R1 Turbomeca:** Amendment 39-16322. Docket No. FAA-2007-27009; Directorate Identifier 2007-NE-02-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective July 7, 2010.

**Affected ADs**

- (b) This AD revises AD 2007-19-09, Amendment 39-15200.

**Applicability**

(c) This AD applies to Turbomeca ARRIEL 2B1 turboshaft engines that don't incorporate modification TU157. These engines are installed on, but not limited to, Eurocopter AS 350 B3 and EC 130 B4 helicopters.

**Reason**

- (d) European Aviation Safety Agency (EASA) AD No. 2009-0091, dated May 4, 2009, states:

Since the issuance of AD 2007-0126 Turbomeca has released modification TU157 which consists in modifying the pressure relief valve of the HMU by introducing a damping device into the valve. Introduction of this device has demonstrated to decrease the pressure fluctuations in the system, therefore reducing significantly the risk of wear of the delta-P diaphragm fabric. This will delete the need for a periodical replacement of the delta-P diaphragm before overhaul of the HMU. The modification TU157 is therefore considered as the terminating action for this AD.

We are issuing this AD to prevent the loss of automatic control mode coupled with the deteriorated performance of the backup mode, which can lead to the inability to continue safe flight, forced autorotation landing, or an accident.

**Actions and Compliance**

- (e) Unless already done, do the following actions.
  - (1) For ARRIEL 2B1 engines that incorporate modification TU157, no further action is required.
  - (2) For all other ARRIEL 2B1 engines do the following:

(i) Replace the hydromechanical metering unit (HMU) with a serviceable HMU before the HMU accumulates 1,500 hours-since-new, hours-since-last-overhaul (HSO), or since incorporation of Turbomeca Service Bulletin (SB) No. 292 73 2105, whichever occurs later.

(ii) Thereafter, replace the HMU with a serviceable HMU at every 1,500 hours-since new, since last overhaul, or since incorporation of Turbomeca SB No. 292 73 2105, whichever occurs later.

(iii) For the purposes of this AD, a serviceable HMU is an HMU fitted with a new constant delta P diaphragm in accordance with Turbomeca Mandatory Service Bulletin (MSB) No. 292 73 2818, Original Issue, Dated October 18, 2006, Update No. 1, dated April 3, 2007, or Version C, dated January 29, 2009.

### **Optional Terminating Action**

(3) Replacing the HMU with an HMU that has been modified to TU157 terminates the repetitive requirement of paragraph (e)(2)(ii) of this AD.

### **FAA AD Differences**

(f) This AD differs from the Mandatory Continuing Airworthiness Information (MCAI) because the MCAI applies to the ARRIEL 2B1 and 2B1A engines. The ARRIEL 2B1A engine is not type certificated in the United States, so this proposed AD applies to the ARRIEL 2B1 engine model only.

### **Alternative Methods of Compliance (AMOCs)**

(g) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

### **Related Information**

(h) Contact Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: kevin.dickert@faa.gov; telephone (781) 238-7117; fax (781) 238-7199, for more information about this AD.

### **Material Incorporated by Reference**

(i) None.

Issued in Burlington, Massachusetts, on May 24, 2010.  
Peter A. White,  
Assistant Manager, Engine and Propeller Directorate,  
Aircraft Certification Service.



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

**2010-10-16 Bell Helicopter Textron and Agusta S.P.A.:** Amendment 39-16295. Docket No. FAA-2010-0487; Directorate Identifier 2010-SW-032-AD.

**Applicability:** Bell Helicopter Textron Model 205A, 205A-1, 205B, 212, 412, 412EP, and 412CF and Agusta S.p.A. Model AB412, AB412EP helicopters, certificated in any category, with Aeronautical Accessories, Inc. (AAI) Low Skid Landing Gear Forward Crosstube (Crosstube), part number (P/N) 212-320-103, with a serial number (S/N) prefix of "AA" and an S/N of 574 through 628, installed.

**Note 1:** Crosstube, P/N 212-320-103, is also included as part of AAI Low Skid Gear Assembly Kits, P/N 412-320-500 and 412-320-502.

**Compliance:** Required as indicated, unless done previously.

To prevent failure of a crosstube and subsequent collapse of the landing gear, do the following:

(a) Within 25 hours time-in-service, replace any affected crosstube with an airworthy crosstube.

**Note 2:** AAI Alert Service Bulletin No. AA-10012, dated March 5, 2010, references the AAI Instructions for Continued Airworthiness AA-01136, which contains guidance on replacing the crosstubes.

(b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Rotorcraft Certification Office: ATTN: DOT/FAA Southwest Region, Martin R. Crane, ASW-170, Aviation Safety Engineer, Rotorcraft Directorate, Rotorcraft Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5170, fax (817) 222-5783, for information about previously approved alternative methods of compliance.

(c) The Joint Aircraft System/Component (JASC) Code is 3250: Landing Gear System.

(d) This amendment becomes effective on June 8, 2010.

Issued in Fort Worth, Texas, on May 3, 2010.

Mark R. Schilling,  
Acting Manager, Rotorcraft Directorate.  
[FR Doc. 2010-11424 Filed 5-21-10; 8:45 am]  
BILLING CODE 4910-13-P



---

**2010-11-04 Teledyne Continental Motors (Formerly Continental and Rolls-Royce Motors, Ltd.):** Amendment 39-16309. Docket No. FAA-2009-1156; Directorate Identifier 2009-NE-38-AD.

**Effective Date**

(a) This airworthiness directive (AD) becomes effective June 16, 2010.

**Affected ADs**

(b) This AD supersedes AD 2009-24-52.

**Applicability**

(c) This AD applies to all Teledyne Continental Motors (TCM) 240, 346, 360, 470, 520, and 550 series and Rolls-Royce Motors, Ltd. (R-RM) IO-240-A reciprocating engines with hydraulic lifters, part numbers (P/Ns) 657913, 657915, or 657916, installed. These engines are installed on, but not limited to, general aviation airplanes.

**Unsafe Condition**

(d) This AD results from TCM reporting another occurrence of rapid wear on the face of hydraulic lifters, P/Ns 657913, 657915, and 657916, and from the need to expand the applicability of this AD to include the TCM 346 series engines and the R-RM IO-240-A reciprocating engines. We are issuing this AD to prevent excessive hydraulic lifter wear, which can result in loss of engine power and loss of control of the airplane.

**Compliance**

(e) You are responsible for having the actions required by this AD performed before further flight after the effective date of this AD, unless the actions have already been done.

**Excluded Engines**

(f) If your engine was manufactured or rebuilt before June 19, 2009, and you have not had any hydraulic lifters replaced after June 19, 2009, no action is required.

**Determining P/N of Lifters**

(g) If your engine was manufactured or rebuilt on or after June 19, 2009, or if any of your hydraulic lifters were replaced on or after June 19, 2009, and you can't determine the P/N of your hydraulic lifters from the engine records:

(1) Use the list of engine serial numbers in Section A of TCM Mandatory Service Bulletin (MSB) No. MSB09-8A, dated December 4, 2009.

(2) Inspect the hydraulic lifters in each cylinder for P/Ns 657913, 657915, and 657916. Use TCM MSB No. MSB09-8A, dated December 4, 2009, Section I. Action Required, paragraphs 1. through 3. to determine the P/N of the lifters.

### **Replacing the Lifters**

(h) If your engine has any affected hydraulic lifters, replace the hydraulic lifters using TCM MSB No. MSB09-8A, dated December 4, 2009, Step 2, paragraphs 2.a.1) through 2.b.4).

### **Installation Prohibition**

(i) After the effective date of this AD, do not install any hydraulic lifters, P/Ns 657913, 657915, or 657916, into any TCM 240, 346, 360, 470, 520, or 550 series or R-RM IO-240-A reciprocating engine.

### **Alternative Methods of Compliance**

(j) The Manager, Atlanta Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

### **Special Flight Permits**

(k) We will not approve any special flight permits.

### **Related Information**

(l) Contact Anthony Holton, Aerospace Engineer, Atlanta Certification Office, FAA, Small Airplane Directorate, 1701 Columbia Avenue, College Park, GA 30337; e-mail: [anthony.holton@faa.gov](mailto:anthony.holton@faa.gov); telephone (404) 474-5567; fax (404) 474-5606, for more information about this AD.

### **Material Incorporated by Reference**

(m) You must use Teledyne Continental Motors Mandatory Service Bulletin No. MSB09-8A, dated December 4, 2009, to perform the actions required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Teledyne Continental Motors, Inc., P.O. Box 90, Mobile, AL 36601; telephone (251) 438-3411, or go to: <http://tcmlink.com/servicebulletins.cfm>. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on May 12, 2010.

Peter A. White,  
Assistant Manager, Engine and Propeller Directorate,  
Aircraft Certification Service.



**2010-11-05 AVOX Systems and B/E Aerospace:** Amendment 39-16310; Docket No. FAA-2010-0272; Directorate Identifier 2010-CE-009-AD.

**Effective Date**

(a) This AD becomes effective on July 6, 2010.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to oxygen cylinders with a capacity of 114/115 cubic feet, approved under United States Department of Transportation Regulations for Type 3HT cylinders, identified in Table 1 of this AD. These oxygen cylinders may be installed on various 14 CFR part 23 and CAR 3 airplanes, certificated in any category. The affected oxygen cylinders may be installed as a component of, but not limited to, the AVOX Systems Inc. and B/E Aerospace cylinder assemblies listed in Table 2 of this AD.

**Table 1 - Affected Oxygen Cylinder Serial Numbers (S/N)**

<b>Cylinder Manufacturer</b>	<b>Affected S/N</b>
AVOX Systems	ST82307 through ST82309 ST82335 through ST82378 ST82385 through ST82506, except ST82498 (out of service) ST82550 through ST82606 ST82617 through ST82626 ST83896 through ST83905 ST84209 through ST84218 ST84224 through ST84236 ST86138, ST86143, ST86145, ST86150, ST86169, ST86172, and ST86177 ST86299 through ST86307
B/E Aerospace	K495120 through K495121 K629573 through K629577 K674451 through K674455

**Table 2 - Affected Oxygen Cylinder Assembly Part Numbers (P/N)**

<b>Manufacturer</b>	<b>P/Ns</b>
AVOX Systems	*6350A34 series, 800112-03, 800112-10, 800112-13, 801293-03, 801307-00, 801307-01, 801307-02, 801307-03, 801307-07, 801307-09, 801307-23, 801307-24, 801365-04, 801365-14, 801375-00, 801977-05, and *8915 series. (*For example, 6350A34-X-X or 8915XX-XX, where “X” denotes a P/N digit)
B/E Aerospace	176018-115, 176112-115, 176177-115, 176181-115, and 176529-97

**Subject**

(d) Air Transport Association of America (ATA) Code 35: Oxygen.

**Unsafe Condition**

(e) This AD was prompted by the reported rupture of a high-pressure gaseous oxygen cylinder, which had insufficient strength characteristics due to improper heat treatment. We are issuing this AD to prevent an oxygen cylinder from rupturing, which, depending on the location, could result in structural damage and rapid decompression of the airplane, damage to adjacent essential flight equipment, deprivation of the necessary oxygen supply for the flightcrew, and injury to cabin occupants or other support personnel.

**Compliance**

(f) To address this problem, you must do the following, unless already done:

(1) Within 60 days after July 6, 2010 (the effective date of this AD), inspect the oxygen cylinder installed in the airplane to determine the serial number. The serial number is stamped into the steel cylinder near the neck. A review of airplane records is acceptable in lieu of this inspection if the serial number of the oxygen cylinder can be positively determined from that review. For any oxygen cylinder that has a serial number identified in Table 1 of this AD, before further flight, remove it from the airplane and replace it with a serviceable oxygen cylinder. Do the inspection and removal following B/E Aerospace Service Bulletin 176000-35-01, dated November 2, 2009; and Zodiac Aerospace AVOX Systems, Inc. Service Bulletin 6084-34-35-01, Revision 1, dated December 9, 2009, as applicable.

(2) As of July 6, 2010 (the effective date of this AD), do not install on any airplane a United States Department of Transportation Type 3HT oxygen cylinder that has a serial number identified in Table 1 of this AD.

Note: United States Department of Transportation hazardous materials regulations apply to the shipping of oxygen cylinders.

## Alternative Methods of Compliance (AMOCs)

(g) The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: David Hirt, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4050; fax: (816) 329-4090; e-mail: david.hirt@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

## Material Incorporated by Reference

(h) You must use B/E Aerospace Service Bulletin 176000-35-01, dated November 2, 2009; and Zodiac Aerospace AVOX Systems, Inc. Service Bulletin 6084-34-35-01, Revision 1, dated December 9, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact B/E Aerospace, Inc., Commercial Aircraft Products Group, RGA Department, 10800 Pflumm Road, Lenexa, Kansas 66215; telephone: (913) 338-9800; fax: (913) 338-8419; Internet: <http://www.beaerospace.com>; and AVOX Systems, 225 Erie Street, Lancaster, New York 14086-9502; telephone: (716) 683-5100; fax: (716) 681-1089; Internet: <http://www.avoxsys.com>, as applicable.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on May 13, 2010.

Kim Smith,  
Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2010-11-06 AeroSpace Technologies of Australia Pty Ltd:** Amendment 39-16311; Docket No. FAA-2010-0235; Directorate Identifier 2010-CE-010-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective July 6, 2010.

**Affected ADs**

- (b) This AD supersedes AD 97-11-12, Amendment 39-10041.

**Applicability**

- (c) This AD applies to Models N22B, N22S, and N24A airplanes, all serial numbers, certificated in any category.

**Subject**

- (d) Air Transport Association of America (ATA) Code 57: Wings.

**Reason**

- (e) The mandatory continuing airworthiness information (MCAI) states:

The results of full scale fatigue tests being conducted by the manufacturer have shown the need for inspection of critical fastener holes in the stub wing upper front spar cap, near the wing strut attachment.

Amendment 1 adopts the manufacturer's latest service bulletin. Its new inspection method avoids having to remove the Huck bolts and the potential to damage the holes.

**Actions and Compliance**

- (f) Unless already done, do the following actions in accordance with Nomad Service Bulletin NMD-53-22, dated June 4, 2007:

(1) Within the next 100 hours time-in-service (TIS) after July 6, 2010 (the effective date of this AD), or within the next 90 days after July 6, 2010 (the effective date of this AD), whichever occurs first, install an inspection hole in the left-hand and right-hand stub wing bottom skin.

(2) Before further flight after installing the inspection hole required in paragraph (f)(1) of this AD, initially inspect the stub wing front spar cap for cracks. Repetitively thereafter inspect at intervals not to exceed every 600 hours TIS.

(3) If any crack is found during any inspection required in paragraph (f)(2) of this AD, before further flight contact Customer Support Manager, Gippsland Aeronautics Pty Ltd., P.O. Box 881, MORWELL, Victoria, 3040, Australia; phone: +61 3 5172 1200; fax: +61 3 5172 1201; e-mail: support@gippsaero.com, for an FAA-approved repair scheme/modification and incorporate the repair scheme/modification. Due to FAA policy, the repair scheme/modification for crack damage must include an immediate repair of the crack. The repair scheme cannot be by repetitive inspection only. The repair scheme/modification may incorporate repetitive inspections in addition to the repetitive inspections required in paragraph (f)(2) of this AD. Continued operational flight with un-repaired crack damage is not permitted.

### **FAA AD Differences**

Note: This AD differs from the MCAI and/or service information as follows: The MCAI states to follow the service bulletin. The service bulletin does not specifically call out a corrective action if cracks are found. The FAA is including specific instruction of corrective action in the AD.

### **Other FAA AD Provisions**

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et.seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

### **Related Information**

(h) Refer to MCAI Civil Aviation Safety Authority (CASA) AD GAF-N22-52, Amendment 1, dated January 2010; and Nomad Service Bulletin NMD-53-22, dated June 4, 2007, for related information.

### **Material Incorporated by Reference**

(i) You must use Nomad Service Bulletin NMD-53-22, dated June 4, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Gippsland Aeronautics Pty Ltd., Latrobe Regional Airport, P.O. Box 881, Morwell Victoria, 3840, Australia; phone: +61 3 5172 1200; fax: +61 3 5172 1201; Internet: [www.gippsaero.com](http://www.gippsaero.com).

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to:  
[http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on May 13, 2010.

Kim Smith,  
Manager, Small Airplane Directorate,  
Aircraft Certification Service.



**2010-11-07 Quartz Mountain Aerospace, Inc.:** Amendment 39-16312; Docket No. FAA-2010-0261; Directorate Identifier 2010-CE-008-AD.

**Effective Date**

(a) This AD becomes effective on July 6, 2010.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to Model 11E airplanes, all serial numbers, that are certificated in any category.

**Subject**

(d) Air Transport Association of America (ATA) Code 27: Flight Controls.

**Unsafe Condition**

(e) This AD results from reports of the aileron control stick force increasing and of the controls being very noisy. We are issuing this AD to detect and correct insufficient lubrication and residual metallic paint particles in the rod end ball joints, which could result in difficulty actuating aileron controls sometime during flight after takeoff. This failure could lead to difficulty controlling the airplane in flight.

**Compliance**

(f) To address this problem, you must do the following, unless already done:

<b>Actions</b>	<b>Compliance</b>	<b>Procedures</b>
(1) Clean and lubricate the aileron pushrod bearings.	Within the next 10 hours time-in-service (TIS) after July 6, 2010 (the effective date of this AD).	Follow Quartz Mountain Aerospace Service Bulletin No. SB 09-02, dated May 5, 2009.
(2) Lubricate the aileron pushrod bearings.	Within 50 hours TIS after the cleaning and lubrication required by paragraph (f)(1) of this AD. Repetitively thereafter at intervals not to exceed 50 hours TIS.	Follow Quartz Mountain Aerospace Service Bulletin No. SB 09-02, dated May 5, 2009.

## **Special Flight Permit**

(g) Under 14 CFR part 39.23, a special flight is not permitted for this AD.

## **Alternative Methods of Compliance (AMOCs)**

(h) The Manager, Fort Worth Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Garry D. Sills, Aerospace Engineer, Rotorcraft Directorate–Airplane Certification Office, ASW-150, 2601 Meacham Blvd, Fort Worth, Texas 76193; telephone: (817) 222-5154; facsimile: (817) 222-5960. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

## **Material Incorporated by Reference**

(i) You must use Quartz Mountain Aerospace Mandatory Service Bulletin No. SB 09-02, dated May 5, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) Quartz Mountain Aerospace, Inc. is in liquidation. For service information identified in this AD, contact Manager, Fort Worth Aircraft Certification Office, FAA, ATTN: Garry D. Sills, Aerospace Engineer, Rotorcraft Directorate–Airplane Certification Office, ASW-150, 2601 Meacham Blvd, Fort Worth, Texas 76193; telephone: (817) 222-5154; fax: (817) 222-5960.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to:  
[http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on May 14, 2010.

Kim Smith,  
Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2010-11-08 Stemme GmbH & Co. KG:** Amendment 39-16313; Docket No. FAA-2008-0788; Directorate Identifier 2008-CE-039-AD.

**Effective Date**

(a) This airworthiness directive (AD) becomes effective July 6, 2010.

**Affected ADs**

(b) This AD supersedes AD 2008-11-20, Amendment 39-15543.

**Applicability**

(c) This AD applies to Model S10-VT powered sailplanes, serial numbers 11-001 through 11-112, certificated in any category.

**Subject**

(d) Air Transport Association of America (ATA) Code 28: Fuel.

**Reason**

(e) The mandatory continuing airworthiness information (MCAI) states:

AD 2007-0315-E was issued to address a possible fuel leakage in the gear compartment in front of the engine and mandated inspections and replacement of fuel plastic-made connectors by connectors made of metal. Since its publication, another fuel leakage has been reported on a S10-VT which had implemented the STEMME Service Bulletin (SB) A31-10-082 as required by AD 2007-0315-E.

It has been determined that the fuel leak may have been caused by the deformation that the originally installed clamps created on the fuel hoses and thus preventing the new clamps from being sufficiently pinched to perform a correct tightening.

The present Airworthiness Directive (AD) supersedes AD 2007-0315-E and requires you to check the fuel system according to the STEMME SB A31-10-083 as well as to replace single-ear clamps and plastic connectors.

The actions specified by this AD are intended to reduce the potential for a fire to ignite and which could lead to loss of control of the sailplane.

## Actions and Compliance

(f) Unless already done, do the following actions:

(1) For all sailplanes affected by this AD, except for serial numbers 11-036, 11-067, 11-068, and 11-090: Before further flight after March 21, 2008 (the compliance date retained from AD 2008-03-06, which was superseded by AD 2008-11-20), replace all plastic T- and Y-connectors in the fuel system with metal connectors. Do the replacements following STEMME F & D Service Bulletin A31-10-082, AM.-Index: 01.a, dated November 30, 2007, or STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009.

Note 1: Serial numbers 11-036, 11-067, 11-068, and 11-090 had the plastic T- and Y-connectors in the fuel system replaced with metal connectors by the manufacturer.

(2) For all sailplanes affected by this AD: Before further flight after June 23, 2008 (the compliance date retained from AD 2008-11-20), inspect the fuel system for possible leakage. Do the inspection following STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008, or STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009.

(3) For all sailplanes affected by this AD: If any leak is found during the inspection required in paragraph (f)(2) of this AD, before further flight, repair the leak following an FAA-approved procedure and replace all STEMME part number (P/N) M476 single-ear clamps in the fuel system with P/N 10M-181 single-ear clamps. Contact the manufacturer at the address specified in paragraph (i)(4) of this AD to obtain an FAA-approved repair procedure. Do the replacements following STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008, or STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009.

(4) For sailplanes that had P/Ns M476 replaced with P/Ns 10M-181 in compliance with AD 2008-11-20: Before further flight after July 6, 2010 (the effective date of this AD), do a leak test as specified in STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008, or STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009.

(5) For sailplanes that had P/Ns M476 replaced with P/Ns 10M-181 in compliance with AD 2008-11-20: If a leak is found during the leak test required in paragraph (f)(4) of this AD, before further flight, repair the leak following an FAA-approved procedure. Contact the manufacturer at the address specified in paragraph (i)(4) of this AD to obtain an FAA-approved repair procedure.

(6) For all sailplanes affected by this AD: If no leak is found during the inspection required in paragraph (f)(2) of this AD, within the next 12 months after July 6, 2010 (the effective date of this AD), replace all P/Ns M476 in the fuel system with P/Ns 10M-181. Do the replacements following STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008, or STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009.

(7) For all sailplanes affected by this AD: Before further flight after doing the replacement required in paragraph (f)(6) of this AD, do a leak test as specified in STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008, or STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009.

(8) For all sailplanes affected by this AD: If a leak is found during the leak test required in paragraph (f)(7) of this AD, before further flight, repair the leak following an FAA-approved procedure. Contact the manufacturer at the address specified in paragraph (i)(4) of this AD to obtain an FAA-approved repair procedure.

(9) For all sailplanes affected by this AD: After June 23, 2008 (the compliance date retained from AD 2008-11-20), do not install plastic "T" and "Y" shape connectors and P/N M476 single-ear clamps in the fuel system.

## FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No differences.

## Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et. seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

## Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Emergency AD No. 2008-0053-E, dated March 5, 2008; STEMME F & D Service Bulletin A31-10-082, AM.-Index: 01.a, dated November 30, 2007; STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008; and STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009, for related information.

## Material Incorporated by Reference

(i) You must use STEMME F & D Service Bulletin A31-10-082, AM.-Index: 01.a, dated November 30, 2007; STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008; and STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.b, dated May 6, 2009, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On June 23, 2008 (73 FR 31355, June 2, 2008), the Director of the Federal Register previously approved the incorporation by reference of STEMME F & D Service Bulletin A31-10-083, Am-Index: 01.a, dated February 26, 2008, listed in this AD.

(3) On February 20, 2008 (73 FR 5733, January 31, 2008), the Director of the Federal Register previously approved the incorporation by reference of STEMME F & D Service Bulletin A31-10-082, AM.-Index: 01.a, dated November 30, 2007, listed in this AD.

(4) For service information identified in this AD, contact STEMME GmbH & Co. KG, Flugplatzstraße F 2, Nr. 7, 15344 Strausberg, Federal Republic of Germany; Internet: <http://www.stemme.de/man/>.

(5) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(6) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on May 18, 2010.

John Colomy,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2010-11-10 Turbomeca:** Amendment 39-16315. Docket No. FAA-2010-0219; Directorate Identifier 2010-NE-14-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective July 6, 2010.

**Affected ADs**

- (b) None.

**Applicability**

(c) This AD applies to Turbomeca Astazou XIV B and XIV H turboshaft engines with the following part number (P/N) third stage turbine wheels that incorporate modification AB 173 (Turbomeca Service Bulletin (SB) No. 283 72 0091) or modification AB 208 (Turbomeca SB No. 283 72 0117), but that do not incorporate Turbomeca SB No. 283 72 805:

- (1) Third stage turbine wheels P/N 0265257000, all serial numbers (S/Ns);
- (2) Third stage turbine wheels P/N 0265257020, all S/Ns;
- (3) Third stage turbine wheels P/N 0265257060, all S/Ns;
- (4) Third stage turbine wheels P/N 0265257050, of the S/Ns listed in Appendix 1 of Turbomeca Mandatory Service Bulletin (MSB) No. 283 72 0804, Version C, dated October 23, 2009.
- (5) These engines are installed on, but not limited to, single-engine Aerospatiale AS319B "Alouette III" and AS342J "Gazelle" helicopters.

**Reason**

(d) European Aviation Safety Agency (EASA) AD No. 2010-0004, dated January 5, 2010, states:

Investigation of an uncommanded in-flight shutdown (IFSD) revealed that a third stage turbine wheel rupture was not contained by the turbine casings. The released portion consisted of a turbine blade together with the rim piece immediately below the blade. The rim piece was bounded by two adjacent axial slots and a fatigue crack that had developed between the holes in which the slots terminate. The slots and holes, which are closed by riveted plugs, were introduced by modification AB 173 in order to improve the vibration characteristics of the turbine wheel. Modification AB 208 brings an improvement to modification AB 173 by changing only the riveting detail. SN 283 72 0805 provides instructions for re-boring the holes at overhaul or repair in order to improve their surface condition. A manufacturing process modification has been introduced to improve the surface condition of these holes in third stage turbine

wheels. Wheels subject to the improved manufacturing process have S/Ns outside the range specified in Table 1. Although there is only one known event, and although it resulted only in an uncommanded IFSD, with no damage to the aircraft, the possibility exists that additional events may occur, potentially involving damage to the aircraft.

To address the unsafe condition, EASA issued AD 2009-0136, mandating inspection of certain third stage turbine wheels and removal of any damaged wheel. The wheels to be inspected were those whose cycles since new (CSN) would exceed 2,000 by February 1, 2011. Following additional research by Turbomeca on crack initiation and growth, this AD mandates inspections based on new criteria and removal of any damaged wheel.

We are issuing this AD to prevent uncontained failures of the third stage turbine wheel, which could result in damage to the helicopter.

### **Actions and Compliance**

(e) Unless already done, do the following actions.

(1) For any affected third stage turbine wheel that on the effective date of this AD has accumulated fewer than 500 cycles-since-last-overhaul or repair, or since-new if the engine has never been overhauled or repaired:

(i) Within 300 additional cycles, perform a dye penetrant inspection on the rear face of the third stage turbine wheel.

(ii) Use Section 2, Instructions to Be Incorporated, of Turbomeca MSB No. 283 72 0804, Version C, dated October 23, 2009, to do the inspection.

(iii) Perform a second dye penetrant inspection when the engine has accumulated between 450 and 550 cycles from the first inspection.

(2) For any affected third stage turbine wheel that on the effective date of this AD, has accumulated 500 or more but fewer than 700 cycles-since-last-overhaul or repair, or since-new if the engine has never been overhauled or repaired:

(i) Within 200 additional cycles, perform a dye penetrant inspection on the rear face of the third stage turbine wheel.

(ii) Use Section 2, Instructions to Be Incorporated, of Turbomeca MSB No. 283 72 0804, Version C, dated October 23, 2009, to do the inspection.

(3) For any affected third stage turbine wheel that on the effective date of this AD, has accumulated 700 or more but fewer than 1,200 cycles-since-last-overhaul or repair, or since-new if the engine has never been overhauled or repaired:

(i) Within 150 additional cycles, perform a dye penetrant inspection on the rear face of the third stage turbine wheel.

(ii) Use Section 2, Instructions to Be Incorporated, of Turbomeca MSB No. 283 72 0804, Version C, dated October 23, 2009, to do the inspection.

(4) If any crack indication is found, then before further flight, remove the third stage turbine wheel from service.

(5) For any affected third stage turbine wheel that on the effective date of this AD has accumulated 1,200 or more cycles-since-last-overhaul or repair, or since-new if the engine has never been overhauled or repaired, no action is required.

## FAA AD Differences

(f) This AD differs from the Mandatory Continuing Airworthiness Information (MCAI) and or service information as follows:

(1) EASA AD 2010-0004, dated January 5, 2010, requires removing the engine from service before further flight if a third stage turbine wheel is found cracked.

(2) This AD requires removing the third stage turbine wheel from service before further flight if a third stage turbine wheel is found cracked.

## Alternative Methods of Compliance

(g) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

## Related Information

(h) Refer to MCAI EASA AD 2010-0004, dated January 5, 2010, for related information.

(i) Contact Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: kevin.dickert@faa.gov; telephone (781) 238-7117, fax (781) 238-7199, for more information about this AD.

## Material Incorporated by Reference

(j) You must use Turbomeca Mandatory Service Bulletin No. 283 72 0804, Version C, dated October 23, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Turbomeca, 40220 Tarnos, France; telephone (33) 05 59 74 40 00, fax (33) 05 59 74 45 15.

(3) You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on May 19, 2010.

Tracy Murphy,  
Acting Manager, Engine and Propeller Directorate,  
Aircraft Certification Service.



---

**2010-11-15 SOCATA:** Amendment 39-16320; Docket No. FAA-2010-0286; Directorate Identifier 2010-CE-013-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective July 6, 2010.

**Affected ADs**

- (b) None.

**Applicability**

- (c) This AD applies to Model TBM 700 airplanes, all serial numbers (SNs), that:
  - (1) are certificated in any category; and
  - (2) are equipped with part number (P/N) 863520-00 portable fire extinguishers, serial numbers (S/N) as listed in L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009.

**Subject**

- (d) Air Transport Association of America (ATA) Code 26: Fire Protection.

**Reason**

- (e) The mandatory continuing airworthiness information (MCAI) states:

The Civil Aviation Authority of the United Kingdom (UK) has informed EASA that significant quantities of Halon 1211 gas, determined to be outside the required specification, have been supplied to the aviation industry for use in fire extinguishing equipment. Halon 1211 (BCF) is used in portable fire extinguishers, usually fitted or stowed in aircraft passenger cabins and flight decks.

EASA published Safety Information Bulletin (SIB) 2009-39 on 23 October 2009 to make the aviation community aware of this safety concern.

The results of the ongoing investigation have now established that LyonTech Engineering Ltd, a UK-based company, has supplied further consignments of Halon 1211 (BCF) to L'Hotellier that do not meet the required specification. This Halon 1211 has subsequently been used to fill certain P/N 863520-00 portable fire extinguishers that are now likely to be installed in or carried on certain TBM700 aeroplanes.

The contaminated nature of this gas, when used against a fire, may provide reduced fire suppression, endangering the safety of the aeroplane and its occupants. In addition, extinguisher activation may lead to release of toxic fumes, possibly causing injury to aeroplane occupants.

For the reason described above, this EASA AD requires the identification and removal from service of certain batches of fire extinguishers and replacement with serviceable units.

## **Actions and Compliance**

(f) Unless already done, within 3 months after July 6, 2010 (the effective date of this AD), do the following in accordance with DAHER-SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-183, dated January 2010:

(1) Inspect the fire extinguisher(s) installed or carried on board the airplane for any P/N and S/N fire extinguisher listed in L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009; and

(2) If, as a result of the inspection required by paragraph (f)(1) of this AD, you find any fire extinguisher listed in L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009, before further flight, remove it from the airplane and replace it with a serviceable unit in accordance with L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009.

(3) As of July 6, 2010 (the effective date of this AD), do not install any fire extinguisher listed in L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009, on any airplane, unless it has been overhauled with compliant Halon 1211 (BCF) and re-identified, in accordance with the instructions of L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009.

## **FAA AD Differences**

Note: This AD differs from the MCAI and/or service information as follows: No differences.

## **Other FAA AD Provisions**

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

## Related Information

(h) Refer to MCAI EASA AD No.: 2010-0012, dated February 5, 2010; DAHER-SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-183, dated January 2010; and L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009, for related information.

## Material Incorporated by Reference

(i) You must use DAHER-SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-183, dated January 2010; and L'Hotellier Service Bulletin 863520-26-001, dated December 21, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact SOCATA—Direction des Services—65921 Tarbes Cedex 9—France; telephone +33 (0)5 6241-7300, fax +33 (0)5 62 41 76 54, or for North America: SOCATA NORTH AMERICA, 7501 South Airport Road, North Perry Airport (HWO), Pembroke Pines, Florida 33023; telephone: 954-893-1400; fax: 54-964-4141. For details on the fire extinguisher, contact: L'HOTELLIER, 4 rue Henri Poincaré, 92167 ANTONY Cedex, France; telephone +33(0) 1 46 66 08 08; fax +33(0) 1 46 66 23 24; e-mail: alain.dorneau@hs.utc.com. To obtain a copy of the referenced L'Hotellier service bulletin, e-mail: sylvie.laruffa@hs.utc.com.

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on May 19, 2010.

John R. Colomy,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.



**DATE: June 1, 2010**

**AD #: 2010-12-51**

This Emergency Airworthiness Directive (EAD) is prompted by a report of a missing control rod bushing (bushing) from a 90-degree tail rotor gearbox (TGB) installed on a Model AW119 MKII helicopter. The Agusta Model 119 helicopters also have the affected TGB installed; therefore, they are also included in the applicability of this EAD. This condition, if not detected and corrected, could result in abnormal vibration and damage to the tail rotor system, loss of the yaw control function, and subsequent loss of control of the helicopter.

We have reviewed Agusta Alert Bollettino Tecnico No. 119-38, dated March 25, 2010 (ABT), which specifies inspecting the TGB, part number (P/N) 109-0440-06-103, to verify the presence of the bushing. If the bushing is not installed, the ABT specifies replacing the TGB and associated parts with a “new” TGB assembly, P/N 109-0440-06-105. Also, the ABT specifies if the bushing is installed, reidentifying the TGB “by installing an additional nameplate” with P/N 109-0440-06-105.

European Aviation Safety Agency (EASA), the airworthiness authority for Italy, notified the FAA that an unsafe condition may exist on these helicopter models. EASA advises of a missing bushing in the TGB of a Model AW119 MKII helicopter. EASA also advises that “this condition, if not detected and corrected, could cause abnormal vibration of the tail rotor controls possibly leading to their damage and consequent loss of the yaw control function.” EASA classified the ABT as mandatory and issued EAD No. 2010-0059-E, dated March 26, 2010, to ensure the continued airworthiness of these helicopters.

This EAD differs from the EASA EAD in that we refer to flight hours as hours time-in-service (TIS). We also do not refer to a compliance date of June 30, 2010. We added the requirement of the thickness gauge being no wider than 10 mm. We added the determinate that if the depth between the tail rotor control rod (rod) and the hub-locking nut (nut) is between 4 mm and 6 mm, the bushing is installed. We do not require an additional nameplate but require reidentifying the TGB P/N with an etch pen by changing the last three digits of the P/N from -103 to -105.

These helicopter models are manufactured in Italy and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, EASA has kept the FAA informed of the situation described above. The FAA has examined the findings of EASA, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

This unsafe condition is likely to exist or develop on other helicopters of these same type designs. Therefore, this EAD requires, before further flight, removing the forward boot from the nut and inserting a 0.3 millimeter (mm) thickness gauge, not exceeding 10 mm in width, between the rod and nut until the gauge stops. This EAD requires, from the face of the nut, measuring the depth the gauge is inserted between the rod and the nut before it stops. If the depth measurement is between 4 mm and 6 mm, the bushing is installed, and this EAD requires reidentifying the TGB,

P/N 109-0440-06-103, by using an etch pen to change the last three digits of the P/N from -103 to -105. If the depth measurement is greater than 6 mm, this EAD requires, before further flight, replacing the TGB and the associated parts with airworthy parts.

The actions must be accomplished by following specified portions of the ABT described previously.

This rule is issued under 49 U.S.C. Section 44701 pursuant to the authority delegated to me by the Administrator, and is effective immediately upon receipt of this emergency AD.

**2010-12-51 AGUSTA S.p.A.:** Directorate Identifier 2010-SW-045-AD.

**Applicability:** Model A119 and AW119 MKII helicopters, with a 90-degree tail rotor gearbox (TGB), part number (P/N) 109-0440-06-103, installed, certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent abnormal vibration and damage to the tail rotor system, loss of the yaw control function, and subsequent loss of control of the helicopter, do the following:

(a) Before further flight, remove the forward boot, P/N 109-0135-10, from the hub-locking nut (nut), P/N 109-0135-12, as shown in Figure 1 of Agusta Alert Bollettino Tecnico No. 119-38, dated March 25, 2010 (ABT).

(1) Insert a 0.3 millimeter (mm) thickness gauge, not exceeding 10 mm in width, between the tail rotor control rod (rod) and the nut as shown in Figure 2 of the ABT until the gauge stops.

(2) From the face of the nut, measure the depth the gauge is inserted between the rod and the nut before it stops:

(i) If the depth measurement is between 4 mm and 6 mm, the bushing, P/N 109-0135-14-101, is installed. Within 5 hours time-in service, reidentify the TGB, P/N 109-0440-06-103, by using an etch pen to change the last three digits of the P/N from -103 to -105.

Note 1: Installing a new nameplate by following the Compliance Instructions, Part II, of the ABT satisfies the reidentification requirements of the TGB P/N in paragraph (a)(2)(i) of this AD.

(ii) If the depth measurement is greater than 6 mm, before further flight, replace the TGB, P/N 109-0440-06-103, with TGB, P/N 109-0440-06-105, and replace the associated parts listed in the Accomplishment Instructions, Part I, paragraph 4, of the ABT with the associated parts listed in the Accomplishment Instructions, Part I, paragraph 5, of the ABT.

(b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Safety Management Group, FAA, ATTN: Eric Haight, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5204, fax (817) 222-5961, for information about previously approved alternative methods of compliance.

(c) The Joint Aircraft System/Component (JASC) Code is 6520: Tail Rotor Gearbox.

(d) Copies of the applicable service information may be obtained from Agusta, Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA), Italy, telephone 39 0331-229111, fax 39 0331-229605/222595, or at [http://customersupport.agusta.com/technical\\_advice.php](http://customersupport.agusta.com/technical_advice.php).

(e) Emergency AD No. 2010-12-51 issued June 1, 2010, becomes effective upon receipt.

Note 2: The subject of this AD is addressed in the European Aviation Safety Agency Emergency AD No. 2010-0059-E, dated March 26, 2010.

FOR FURTHER INFORMATION CONTACT: Eric Haight, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5204, fax (817) 222-5961.

Issued in Fort Worth, Texas, on June 1, 2010.

Scott A. Horn  
Acting Manager, Rotorcraft Directorate  
Aircraft Certification Service.