



SUBJ: Navigation: VOR or LOC/ILS Approaches with G1000, Perspective™, **SAIB:** CE-09-47
Prodigy™ Integrated Flight Decks Installed With a Garmin GFC 700 Autopilot **Date:** August 7, 2009

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin (SAIB) is being transmitted to owners and operators of aircraft equipped with Garmin G1000, Perspective™, Prodigy™ Integrated Flight Decks installed with a Garmin GFC 700 autopilot. The purpose of this SAIB is to inform pilots of an issue that has been brought to the FAA's attention with the navigational radio auto-tune feature while performing a VOR or ILS Approach.

The airworthiness concern is not an unsafe condition that would warrant airworthiness directive (AD) action under Title 14 of the Code of Federal Regulations (14 CFR) Part 39.

Background

Changes to navigation frequencies that occur between navigation database cycle distributions may cause a mismatch between the automatically tuned LOC/ILS frequency and the frequency shown on the approach chart or applicable NOTAM. In these cases, the mismatched (incorrect) automatically tuned frequency may cause the HSI to automatically slew to the wrong course.

Recommendations

Pilot Action: If the auto-tuned LOC/ILS frequency does not correspond to the frequency shown on the approach chart or applicable NOTAM, the FAA recommends that the pilot:

- 1) Manually tune the navigation receiver to the correct LOC/ILS frequency (On the approach chart or NOTAM).
- 2) Assure that the correct inbound course is selected.
- 3) Manually fly the approach.
- 4) Or choose a different terminal procedure.

The GFC 700 will not capture, track, or give flight director commands for a manually selected course.

Garmin is planning resolution to this issue with GDU software version 10.00 and later versions will provide capability to couple the autopilot to the VOR or LOC/ILS approach when the pilot manually tunes the correct frequency and manually selects the proper course for the approach.

For Further Information Contact

Jason Brys, Flight Test Engineer, 1801 Airport Road, Room 100, Wichita, KS 67209; phone: (316) 946-4138; fax: (316) 946-4107; e-mail: jason.brys@faa.gov

For Related Service Information Contact

Garmin International Inc., 1200 E 151st St, Olathe, KS 66062; phone: (913) 397-8200.