



**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES  
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS,  
BALLOONS, & AIRSHIPS**

**BIWEEKLY 2010-15**

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation  
Federal Aviation Administration  
Regulatory Support Division  
Delegation and Airworthiness Programs Branch, AIR-140  
P. O. Box 26460  
Oklahoma City, OK 73125-0460  
FAX 405-954-4104



## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;			
<b>Biweekly 2010-01</b>			
2009-26-05		Pilatus Aircraft Ltd	PC-7
2009-26-07	S 2009-12-51	Turbomeca	Engine: Arriel 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S, and 1S1
2009-26-08	S 2006-21-12	AeroSpace Technologies of Australia Pty Ltd	N22B, N22S, and N24A
2009-26-12	S 2008-19-05	Engine Components, Inc. (ECi)	See AD
<b>Biweekly 2010-02</b>			
2009-21-08 R1		PIAGGIO AERO INDUSTRIES S.p.A.	P-180
2010-01-03		Fire Fighting Enterprises Limited	See AD
2010-02-01		Turbomeca S.A	Arriel 1B, 1D, and 1D1
2010-02-51	E	AGUSTA S.p.A	A109A, A109A II, A109C, and A109K2
<b>Biweekly 2010-03</b>			
2009-19-51		Agusta S.p.A	AB139 and AW139
2009-26-11	S 2006-07-15	Thrush Aircraft, Inc.	See AD
2010-02-07		Eurocopter France	Rotorcraft: SE3160, SA315B, SA316B, SA316C, and SA319B
2010-02-08		Turbomeca	Engine: Turmo IV A and IV C
2010-03-01		Eurocopter France	Rotorcraft: AS332L1, AS332L2, and EC225LP
2010-03-02		Lifesaving Systems Corp.	Appliance
<b>Biweekly 2010-04</b>			
2009-23-51		Sikorsky Aircraft Corporation	Rotorcraft: S-92A
2010-03-03		Bell Helicopter Textron, Inc	Rotorcraft: 205B and 212
2010-03-04		PIAGGIO AERO INDUSTRIES S.p.A	P-180
2010-03-06		Turbomeca	Engine: Arriel 2B and 2B1
2010-03-09		Piaggio Aero Industries S.p.A	P-180
<b>Biweekly 2010-05</b>			
2010-04-05	S 2003-12-05	McCaughey Propeller Systems	Propeller: 1A103/TCM
2010-04-06		Thielert Aircraft Engines GmbH	Engine: TAE 125-01
2010-04-07		Turbomeca	Engine: Arriel 2S1
2010-04-11		Extra Flugzeugproduktions- und Vertriebs- GmbH	EA-300/200, EA-300/L
2010-04-14		Augustair, Inc	2150, 2150 <sup>a</sup> , 2180
2010-04-15		SCHEIBE-Flugzeugbau GmbH	Glider: SF 25C
2010-04-16		SICLI	Appliance: portable fire extinguishers
2010-05-02	S 2009-08-10	Pilatus Aircraft Ltd	PC-12/47E
2010-05-51	E	Eurocopter	Rotorcraft: EC120B
<b>Biweekly 2010-06</b>			
2010-05-10		Hawker Beechcraft	B300, B300C
2010-06-02		Hawker Beechcraft	G58

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;			
<b>Biweekly 2010-07</b>			
2010-06-03		Eurocopter France	Rotorcraft: AS355E, AS355F, AS355F1, AS355F2, and AS355N
2010-06-06	S 99-16-13	MD Helicopters, Inc	Rotorcraft: MD-900
2010-06-07		Eurocopter France	Rotorcraft: AS 332 C, L, L1, and L2; AS 350 B3; AS355 F, F1, F2, and N; SA 365N and N1; AS 365 N2 and N3; SA 366G1; EC 130 B4; and EC 155B and B1
2010-06-08		Sikorsky Aircraft Corporation	Rotorcraft: S-76C
2010-06-11		Honeywell International Inc.	Engine: TFE731-2, TFE731-2A, TFE731-2C, TFE731-3, TFE731-3A, TFE731-3AR, TFE731-3B, TFE731-3BR, TFE731-3C, TFE731-3CR, TFE731-3D, TFE731-3DR, TFE731-3R, TFE731-4, TFE731-4R, TFE731-5, TFE731-5AR, TFE731-5BR, and TFE731-5R
2010-06-12		Thielert Aircraft Engines GmbH	Engine: TAE 125-01 and TAE 125-02-99
<b>Biweekly 2010-08</b>			
2009-08-08 R1	R 2010-08-08	Turbomeca S.A	Engine: Arriel 1B, 1D, and 1D1, Arriel 2B and 2B1
2010-07-02	S 2006-22-05	Honeywell, Inc	Appliance: See AD
2010-07-07		Socata	TBM 700
2010-07-08		Kelly Aerospace Energy Systems, LLC	Appliance: See AD
2010-08-01		Aircraft Industries a.s	Glider: L 23 Super Blanik
<b>Biweekly 2010-09</b>			
2009-08-05R1	R	Liberty Aerospace Incorporated	XL-2
2010-08-04	2007-10-14	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, Jetstream Series 3101, and Jetstream Model 3201
2010-09-08		General Electric Company	Engine: GE CJ610 series turbojet and CF700
<b>Biweekly 2010-10</b>			
2010-05-51	FR	Eurocopter France	Rotorcraft: EC120B
2010-09-01		Eurocopter France	Rotorcraft: AS350B, BA, B1, B2, B3, C, D and D1; and AS 355E, F, F1, F2, N, and NP
2010-09-02		British Aerospace Regional Aircraft	Jetstream Series 3101 and Jetstream Model 3201
2010-09-04		Honeywell International Inc	Appliance: Primus EPIC and Primus APEX flight management systems (FMS)
2010-09-09		Piaggio Aero Industries S.p.A.	P-180
2010-09-13		Turbomeca	Engine: Makila 2A
2010-10-01	S 2009-05-01	GA 8 Airvan (Pty) Ltd	Glider: GA8 and GA8-TC320
<b>Biweekly 2010-11</b>			
2010-10-02		Sikorsky Aircraft Corporation	Rotorcraft: S-76A, B, and C
2010-10-03		Sikorsky Aircraft Corporation	Rotorcraft: S-92A
2010-10-09	S 2008-07-01	Turbomeca	Engine: 1B (that incorporate Turbomeca Modification (mod) TU 148), Arriel 1D, 1D1, and 1S1
2010-10-10		Hawker Beechcraft	390
2010-10-14		Eurocopter France	Rotorcraft: AS332L2
2010-10-15		Eurocopter France	Rotorcraft: AS332L1 and AS332L2
2010-11-51	E	Eurocopter France	Rotorcraft: AS350B, BA, B1, B2, C, D, and D1 helicopters and Model AS355E, F, F1, F2, and N
2010-11-52	E	Sikorsky Aircraft	Rotorcraft: S-76A, B, and C

## SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; - See AD for additional information;

### Biweekly 2010-12

2007-19-09 R1 2010-10-16	R	Turbomeca Bell Helicopter Textron and Augusta S.P.A.	Engine: ARRIEL 2B1 Rotorcraft: 205A, 205A-1, 205B, 212, 412, 412EP, and 412CF and Agusta S.p.A. Model AB412, AB412EP
2010-11-04 2010-11-05	S 2009-24-52	Teledyne Continental Motors AVOX Systems and B/E Aerospace	Engine: 240, 346, 360, 470, 520, and 550 and IO-240 See AD
2010-11-06	S 97-11-12	AeroSpace Technologies of Australia Pty Ltd	N22B, N22S, and N24A
2010-11-07 2010-11-08 2010-11-10 2010-11-15 2010-12-51	S 2008-11-20    E	Quartz Mountain Aerospace, Inc Stemme GmbH & Co. KG Turbomeca: Socata Agusta S.p.A.	11E S10-VT Engine: Astazou XIV B and XIV H TBM 700 Rotorcraft: A119 and AW119 MKII

### Biweekly 2010-13

2010-10-12 2010-10-16	S 2005-04-09	Bell Helicopter Textron Canada Bell Helicopter Textron and Agusta S.P.A	Rotorcraft: 222, 222B, 222U, 230, 430 Rotorcraft: 205A, 205A-1, 205B, 212, 412, 412EP, and 412CF and Agusta S.p.A. Model AB412, AB412EP
2010-11-09 2010-12-01 2010-12-02 2010-12-04 2010-13-01	S 2009-24-13	Thielert Aircraft Engines GmbH Cessna Aircraft Company Turbomeca S.A. PILATUS Aircraft Ltd Microturbo	Engine: TAE 125-01 and TAE 125-02-99 525A Engine: Makila 1A and 1A1 PC-7 Appliance: See AD

### Biweekly 2010-14

2010-13-07 2010-13-08 2010-13-10	S 2006-08-09	Piper Aircraft Air Tractor Ontic Engineering and Manufacturing, Inc	PA-32R-301T, PA046-350P AT-802 and AT-802A Appliance: See AD
--	--------------	--	--

### Biweekly 2010-15

2010-14-12	See AD		Rotorcraft: AH-1G, AH-1S, HH-1K, TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, and UH-1P Helicopters; and Southwest Florida Aviation Model UH-1B (SW204 and SW204HP) and UH-1H (SW205)
2010-14-15 2010-14-20 2010-14-21 2010-15-51	E	Aircraft Industries a.s. McCauley Propeller Systems Thielert Aircraft Engines GmbH Agusta S.p.A.	Glider: L-13 Blanik Propeller: 4HFR34C653/L106FA Engine: TAE 125-01 A119 and AW119 MKII



**2010-14-12 Arrow Falcon Exporters, Inc. (Previously Utah State University); AST, Inc. (Previously Firefly Aviation Helicopter Services, and Erickson Air-Crane); Rotorcraft Development Corporation (Previously Garlick Helicopters, Inc.); Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC (Previously Western International Aviation, Inc.); International Helicopters, Inc.; Northwest Rotorcraft, LLC (Previously Precision Helicopters, LLC); Robinson Air Crane, Inc.; San Joaquin Helicopters (Previously Hawkins & Powers Aviation); S.M. &T. Aircraft (Previously Us Helicopter Inc., UNC Helicopters, Inc., Southern Aero Corporation, and Wilco Aviation); Smith Helicopters; Southern Helicopter, Inc.; Southwest Florida Aviation International, Inc. (Previously Mr. Jamie R. Hill and Southwest Florida Aviation, Inc.); Tamarack Helicopters, Inc. (Previously Ranger Helicopter Services, Inc.); Us Helicopter, Inc. (Previously Williams Helicopter Tech., Southern Aero Corp., Oregon Helicopters and Lenair Corp); West Coast Fabrications; and Overseas Aircraft Support Inc. (Previously Williams Helicopter Corporation, Scott Paper Company and Offshores Construction):** Amendment 39-16357. Docket No. FAA-2010-0565; Directorate Identifier 2010-SW-034-AD.

**Applicability:** Model AH-1G, AH-1S, HH-1K, TH-1F, TH-1L, UH-1A, UH-1B, UH-1E, UH-1F, UH-1H, UH-1L, and UH-1P Helicopters; and Southwest Florida Aviation Model UH-1B (SW204 and SW204HP) and UH-1H (SW205) helicopters, certificated in any category, with Aeronautical Accessories, Inc. (AAI), Low Skid Landing Gear Forward Crosstube (crosstube), part number (P/N) 212-320-103, with a serial number (S/N) prefix of "AA" and an S/N of 574 through 628.

Note 1: Crosstube, P/N 212-320-103, is also included as part of AAI Low Skid Gear Assembly Kits, P/N 412-320-500 and 412-320-502.

Note 2: Crosstube, P/N 212-320-103, is installed on Rotorcraft Development Corporation; S.M.T. Aircraft; Hagglund Helicopters, LLC; and Southwest Florida Aviation International, Inc., Model UH-1B and UH-1H helicopters, based on Supplemental Type Certificate No. SR01924AT.

**Compliance:** Required as indicated, unless done previously.

To prevent failure of a crosstube and subsequent collapse of the landing gear, do the following:

(a) Within 25 hours time-in-service, replace any affected crosstube with an airworthy crosstube.

Note 3: AAI Alert Service Bulletin ASB No. AA-10012, dated March 5, 2010, contains guidance that pertains to the subject of this AD and references AAI Instructions for Continued Airworthiness AA-01136, which contains the instructions for replacing the crosstubes.

(b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Rotorcraft Certification Office: Attn: DOT/FAA Southwest Region, Martin R. Crane, ASW-170, Aviation Safety Engineer, Rotorcraft Directorate, Rotorcraft Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5170, fax (817) 222-5783, for information about previously approved alternative methods of compliance.

(c) The Joint Aircraft System/Component (JASC) Code is 3250: Landing Gear System.

(d) This amendment becomes effective on July 23, 2010.

Issued in Fort Worth, Texas, on June 25, 2010.

Mark R. Schilling,  
Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.



---

**2010-14-15 Aircraft Industries a.s. (Type Certificate G60EU Previously Held by LETECKÉ ZÁVODY a.s. and LET Aeronautical Works):** Amendment 39-16360; Docket No. FAA-2010-0684; Directorate Identifier 2010-CE-031-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective July 19, 2010.

**Affected ADs**

- (b) None.

**Applicability**

- (c) This AD applies to Models L-13 Blanik gliders, all serial numbers, certificated in any category.

**Subject**

- (d) Air Transport Association of America (ATA) Code 57: Wings.

**Reason**

- (e) The mandatory continuing airworthiness information (MCAI) states:

A fatal accident occurred to a L-13 BLANÍK sailplane, in which the main spar of the right wing failed near the root due to positive load. The right wing detached from the aircraft and the pilots lost control of the sailplane.

The preliminary investigation has revealed that the fracture may have been due to fatigue.

The Emergency AD 2010-0119-E required immediate inspection of the main spar at the root of the wing to detect fatigue cracking and the accomplishment of the relevant corrective actions as necessary. In addition, this AD 2010-0119-E imposed operational limitations. This AD retains the requirements of AD 2010-0119-E, which is superseded, and extends the applicability to L-13 A BLANÍK sailplanes.

The requirements of this AD are considered as interim action to immediately address this unsafe condition. If, as a result of the on-going investigation, a terminating action is later identified, further mandatory actions might be considered.

## **Actions and Compliance**

(f) Unless already done, do the following actions.

(1) As of July 19, 2010, aerobatics maneuvers (i.e., roll, loop, stalled turn, immelmann turn, half roll, and inverted flight) are prohibited. Before further flight after July 19, 2010, insert a copy of this AD into the flight manual to comply with the requirements of this paragraph. The chapter "Aerobatics" in "Pilot's Notes for the L-13 sailplane" (flight manual) is not valid.

(2) Before further flight after July 19, 2010, inspect the wing critical areas following Aircraft Industries a.s. Mandatory Bulletin MB No.: L13/109a, dated June 18, 2010, except use a 10X magnifier.

(3) If any cracks are found during the inspection required by paragraph (f)(2) of this AD, no further flights are permitted.

(4) Within 10 days after the inspection required by paragraph (f)(2) of this AD, submit the following information requested by Aircraft Industries a.s. Mandatory Bulletin MB No.: L13/109a, dated June 18, 2010, for further assessment. Send information to the address listed in paragraph (i)(2) of this AD.

(i) Appendix No. 1, Summary of L-13 glider Log book record; and

(ii) Paragraph H. RECORD IN GLIDER LOGBOOK AFTER BULLETIN EXECUTION.

Note 1: The above limitation is an interim solution until a final action is identified, at which time the European Aviation Safety Agency (EASA) and the FAA may consider further AD action.

## **FAA AD Differences**

Note 2: This AD differs from the MCAI and/or service information as follows. The service information requires a visual inspection with a 6X magnifier. We are requiring a 10X magnifier to detect cracks that could go undetected using only a 6X magnifier.

## **Other FAA AD Provisions**

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et.seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

**Related Information**

(h) Refer to MCAI EASA Emergency AD No.: 2010-0122-E, dated June 23, 2010; and Aircraft Industries a.s. Mandatory Bulletin MB No.: L13/109a, dated June 18, 2010, for related information.

**Material Incorporated by Reference**

(i) You must use Aircraft Industries a.s. Mandatory Bulletin MB No.: L13/109a, dated June 18, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Aircraft Industries, a.s., Na Záhonech 1177, 686 04 Kunovice, Czech Republic; phone: +420 572 817 660; fax: +420 572 816 112; Internet: <http://www.let.cz/>; e-mail: [ots@let.cz](mailto:ots@let.cz).

(3) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(4) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on June 28, 2010.

James E. Jackson,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2010-14-20 McCauley Propeller Systems:** Amendment 39-16365. Docket No. FAA-2007-29176; Directorate Identifier 2007-NE-38-AD.

**Effective Date**

- (a) This airworthiness directive (AD) becomes effective August 17, 2010.

**Affected ADs**

- (b) None.

**Applicability**

- (c) This AD applies to McCauley Propeller Systems model 4HFR34C653/L106FA propellers.

**Unsafe Condition**

(d) This AD results from reports of 10 hubs found cracked during propeller overhaul. We are issuing this AD to prevent failure of the propeller hub, which could cause blade separation, damage to the airplane, and loss of control of the airplane.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

(f) For propeller hubs with 6,000 or more operating hours time-since-new (TSN) on the effective date of this AD, perform the procedures in paragraphs (h) through (k) of this AD within 100 operating hours time-in-service after the effective date of this AD.

(g) For propeller hubs with fewer than 6,000 operating hours TSN on the effective date of this AD, perform the procedures in paragraphs (h) through (k) of this AD before the propeller hub reaches 6,100 operating hours TSN.

**Onetime Propeller Hub Inspection**

(h) Remove and disassemble the propeller, and etch the propeller hub, using paragraphs 1.A. through 2.D. of the Accomplishment Instructions of McCauley Propeller Systems Alert Service Bulletin No. ASB254, dated August 20, 2007.

(i) Perform a onetime fluorescent penetrant inspection (FPI) of the propeller hub, using paragraphs 3.A through 3.G. of the Accomplishment Instructions of McCauley Propeller Systems Alert Service Bulletin No. ASB254, dated August 20, 2007.

(j) For hubs that pass the FPI, perform a onetime eddy current inspection of the propeller hub, using paragraphs 4.A. through 4.F. of the Accomplishment Instructions of McCauley Propeller Systems Alert Service Bulletin No. ASB254, dated August 20, 2007.

(k) Remove cracked hubs from service and any other propeller parts found cracked.

### **Previous Credit**

(l) If you performed the onetime inspection of the propeller hub using McCauley Propeller Systems Service Bulletin No. SB238A, or Alert Service Bulletin ASB254, both dated August 20, 2007, before the effective date of this AD, you have satisfied the inspection requirements of this AD.

### **Interim Action**

(m) These actions are interim actions and we may take further rulemaking actions in the future.

### **Alternative Methods of Compliance**

(n) The Manager, Wichita Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

### **Special Flight Permits**

- (o) Under 14 CFR part 39.23, we are limiting the special flight permits for this AD as follows:
- (1) The propeller must have no signs of external oil leakage from the hub; and
  - (2) The propeller has no current reports of abnormal operation or vibration.

### **Related Information**

(p) Contact Jeff Janusz, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, Small Airplane Directorate, 1801 Airport Road, Wichita, KS 67209; e-mail: jeff.janusz@faa.gov; telephone (316) 946-4148; fax: (316) 946-4107, for more information about this AD.

### **Material Incorporated by Reference**

(q) You must use McCauley Propeller Systems, Service Bulletin No. ASB254, dated August 20, 2007, to perform the inspections required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact McCauley Propeller Systems, P.O. Box 7704, Wichita, KS 67277-7704; telephone (800) 621-7767, for a copy of this service information. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives

and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on July 1, 2010.

Francis A. Favara,  
Manager, Engine and Propeller Directorate,  
Aircraft Certification Service.



**2010-14-21 Thielert Aircraft Engines GmbH:** Amendment 39-16366. Docket No. FAA-2010-0308; Directorate Identifier 2010-NE-17-AD.

**Effective Date**

(a) This airworthiness directive (AD) becomes effective August 17, 2010.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to Thielert Aircraft Engines GmbH model TAE 125-01 reciprocating engines with any of the following part number blow-by oil separators installed:

**Table 1—Part Numbers of Affected Blow-By Oil Separators**

02-7250-18100R1	02-7250-18100R2	02-7250-18100R3
02-7250-18100R4	02-7250-18300R1	02-7250-18300R2
02-7250-18300R3	02-7250-18300R4	02-7250-18300R5

These engines are installed in, but not limited to, Diamond Aircraft Industries Model DA 40, Piper PA-28-161 (Supplemental Type Certificate (STC) No. SA03303AT), and Cessna 172 (STC No. SA01303WI) airplanes.

**Reason**

(d) Service has shown that the small outlet of the blow-by oil separators, part number 02-7250-18100R1; 02-7250-18100R2; 02-7250-18100R3; 02-7250-18100R4; 02-7250-18300R1; 02-7250-18300R2; 02-7250-18300R3; 02-7250-18300R4; or 02-7250-18300R5, may cause a blow-by gas pressure increase inside the crankcase of the engine in excess of the oil seal design pressure limits. Leaking engine oil may adversely affect the gearbox clutch or the engine lubrication system. This condition, if not corrected, could lead to in-flight cases of engine power loss or ultimately, shutdown.

This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. We are issuing this AD to prevent loss of engine power or uncommanded engine shutdown during flight due to excessive crankcase blow-by gas pressure.

### **Actions and Compliance**

(e) Unless already done, do the following actions:

(1) Remove the blow-by oil separators listed by part number in Table 1 of this AD within the next 110 flight hours after the effective date of this AD.

(2) Use the Measures section of Thielert Aircraft Engines GmbH Service Bulletin No. TM TAE 125-0019, Revision 1, dated March 5, 2009, to do the removal from service.

### **FAA AD Differences**

(f) None.

### **Alternative Methods of Compliance (AMOCs)**

(g) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

### **Related Information**

(h) Refer to European Aviation Safety Agency AD 2010-0020, dated February 8, 2010, for related information.

(i) Contact Tara Chaidez, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: tara.chaidez@faa.gov; telephone (781) 238-7773; fax (781) 238-7199, for more information about this AD.

### **Material Incorporated by Reference**

(j) You must use Thielert Aircraft Engines GmbH Service Bulletin No. TM TAE 125-0019, Revision 1, dated March 5, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D-09350, Lichtenstein, Germany, telephone: 37204-696-0; fax: 37204-696- 55; e-mail: info@centurion-engines.com.

(3) You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on July 1, 2010.  
Francis A. Favara,  
Manager, Engine and Propeller Directorate,  
Aircraft Certification Service.



**FAA**  
**Aviation Safety**

## **EMERGENCY**

# **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)

---

**DATE: July 16, 2010**

**AD #: 2010-15-51**

This Emergency Airworthiness Directive (AD) is prompted by a report that an engine rotary variable differential transformer (RVDT) control gear locking pin (locking pin) that was installed on a Model AW119 MKII helicopter moved from its proper position, resulting in loss of connectivity of the pilot and copilot throttle controls. Investigation revealed that the pilot's locking pin had moved from its proper position, which resulted in the loss of the copilot throttle control. The actions specified by this AD are intended to prevent the RVDT locking pin from moving from its proper position, which could lead to loss of manual engine throttle control, and subsequent loss of control of the helicopter.

We have reviewed Agusta Alert Bollettino Tecnico No. 119-39, dated July 2, 2010 (ABT). The ABT describes procedures for inspecting the pilot and copilot control box assembly (control box) for correct positioning of the locking pin. The ABT states that the investigation is still in progress to find a solution to the malfunction. The instructions in the ABT are prescribed as precautionary pending future corrective action.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, notified us that an unsafe condition may exist on Agusta Model A119 and AW119 MKII helicopters. EASA advises of a nonconformity of certain control boxes, unseating of a locking pin, and loss of the pilot and co-pilot engine throttle synchronicity. This condition, if not detected and corrected, could lead to the loss of manual engine throttle control and consequent loss of control of the helicopter. EASA classified the ABT as mandatory and issued AD No. 2010-0142-E, dated July 5, 2010, to ensure the continued airworthiness of these helicopters.

These helicopter models are manufactured in Italy and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, EASA has kept us informed of the situation described. We have examined the findings of EASA, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

This unsafe condition is likely to exist or develop on other helicopters of these same type designs. Therefore, this AD requires, within 5 hours time-in-service (TIS), and thereafter at intervals not to exceed 50 hours TIS, removing the cover of the pilot and copilot control boxes and inspecting the locking pins for proper position. If the locking pin is recessed or extended in excess of 2.0 millimeters from the face of the pin bore, or missing, before further flight, replacing the control box with an airworthy control box that has been inspected in accordance with paragraph (a) of the AD is required. Replacing the control box does not constitute terminating action for the inspection requirements of the AD. This AD differs from EASA Emergency AD No. 2010-0142-E in that we use the term "hours time-in-service" rather than "flight hours." Also, we clarified the inspection requirements and do not use the calendar date of August 31, 2010 as a required compliance time.

This rule is issued under 49 U.S.C. Section 44701 pursuant to the authority delegated to me by the Administrator, and is effective immediately upon receipt of this emergency AD.

**2010-15-51 AGUSTA S.p.A.:** Directorate Identifier 2010-SW-071-AD.

Applicability: Model A119 and AW119 MKII helicopters, with pilot control box assembly (control box), part number (P/N) 109-0010-81-103 and co-pilot control box, P/N 109-0010-81-107, installed, certificated in any category.

Compliance: Required as indicated.

To detect a missing, or improperly fitted, engine rotary variable differential transformer (RVDT) control gear locking pin (locking pin), P/N MS16555-628, which could lead to loss of manual engine throttle control, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 5 hours time-in-service (TIS) unless accomplished previously, and thereafter at intervals not to exceed 50 hours TIS, remove the cover of the pilot and copilot control boxes and inspect the locking pins for proper position by following the Compliance Instructions, Parts I and II, paragraphs 2. through 4.1 for the pilot control box and paragraphs 5. through 7.1 for the co-pilot control box, in Agusta Alert Bollettino Tecnico No. 119-39, dated July 2, 2010.

(b) If the locking pin is recessed or extended in excess of 2.0 millimeters from the face of the pin bore, or missing, before further flight, replace the control box with an airworthy control box that has been inspected in accordance with paragraph (a) of this AD. **Replacing the control box does not constitute terminating action for the inspection requirements of this AD.**

(c) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Safety Management Group, FAA, ATTN: Rao Edupuganti, Aviation Safety Engineer, Rotorcraft Directorate, Regulations and Policy Group, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-4389, fax (817) 222-5961, for information about previously approved alternative methods of compliance.

(d) The Joint Aircraft System/Component (JASC) Code is 6700: Rotors Flight Control.

(e) Copies of the applicable service information may be obtained from Agusta, Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA), Italy, telephone 39 0331-229111, fax 39 0331-229605/222595, or at [http://customersupport.agusta.com/technical\\_advice.php](http://customersupport.agusta.com/technical_advice.php).

(f) Emergency AD 2010-15-51, issued July 16, 2010, becomes effective upon receipt.

Note: The subject of this AD is addressed in European Aviation Safety Agency AD No. 2010-0142-E, dated July 5, 2010.

FOR FURTHER INFORMATION CONTACT: Rao Edupuganti, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Policy Group, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-4389, fax (817) 222-5961.

Issued in Fort Worth, Texas, on July 16, 2010.

Mark R. Schilling,  
Acting Manager, Rotorcraft Directorate,  
Aircraft Certification Service.