

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2016-03

1/25/2016 - 2/7/2016



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes; R - Replaces

Biweekly 2016-01

2015-26-04	S 2002-13-11	Airbus Helicopters	EC120B helicopters
2015-26-08		Piper Aircraft, Inc.	PA-44-180, PA-44-180T airplanes
2015-26-10		Sikorsky Aircraft Corporation	S-76A, S-76B, and S-76C helicopters

Biweekly 2016-02

2015-12-09 R1	R 2015-12-09	Airbus Helicopters Deutschland GmbH	EC135P1, EC135T1, EC135P2, EC135T2, EC135P2+, EC135T2+, and MBB-BK 117 C-2
2016-01-01		Piper Aircraft, Inc.	PA-46-500TP
2016-01-06		Agusta S.p.A.	AB139 and AW139
2016-01-14		Airbus Helicopters Deutschland GmbH	MBB-BK 117 A-1, A-3, A-4, B-1, B-2, C-1, and C-2
2016-01-15		Agusta S.p.A.	AB139 and AW139
2016-01-19		MD Helicopters Inc.	500N and 600N

Biweekly 2016-03

2015-22-51		Agusta S.p.A.	A109A and A109AII helicopters
2016-02-06		Bell Helicopter Textron Canada Limited	429 helicopters



2015-22-51 Agusta S.p.A.: Amendment 39-18386; Docket No. FAA-2016-2069 Directorate Identifier 2015-SW-070-AD.

(a) Applicability

This AD applies to Model A109A and A109AII helicopters with a main rotor blade (blade) part number (P/N) 109-0103-01-7, P/N 109-0103-01-9, or P/N 109-0103-01-115 that has 500 or more hours time-in-service installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in a blade. This condition, if not detected, could result in failure of a blade and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective February 16, 2016 to all persons except those persons to whom it was made immediately effective by Emergency AD 2015-22-51, issued on October 23, 2015, which contains the requirements of this AD.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Before further flight, and thereafter at intervals not to exceed 24 clock-hours, using a 3X or higher power magnifying glass, visually inspect the top and bottom surface of each blade for a crack in the area between the station at the end of the doublers and the station at the beginning of the abrasion strip. If there is a crack, before further flight, replace the blade with an airworthy blade.

(2) Before each flight, check the top and bottom surface of each blade for a crack in the area between the station at the end of the doublers and the station at the beginning of the abrasion strip. If there is a crack, inspect the blade in accordance with paragraph (e)(1) of this AD. The check required by this paragraph may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9 (a)(1) through (a)(4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

(f) Special Flight Permits

A special flight permit may be permitted for the inspection in paragraph (e)(1) of this AD provided there is no crack in a blade.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email: 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

(1) AgustaWestland Mandatory Alert Bollettino Tecnico No. 109-150, dated September 17, 2015, which is not incorporated by reference, contains additional information about the subject of this final rule. For service information identified in this final rule, contact AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D'Angelo; telephone 39-0331-664757; fax 39-0331-664680; or at <http://www.agustawestland.com/technical-bulletins>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2015-0190-E, dated September 18, 2015. You may view the EASA AD on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2016-2069.

(i) Subject

Joint Aircraft Service Component (JASC) Tracking Code: 6210 Main Rotor Blade.

Issued in Fort Worth, Texas, on January 21, 2016.

Lance T. Gant,
Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2016-02-06 Bell Helicopter Textron Canada Limited: Amendment 39-18387; Docket No. FAA-2016-2068; Directorate Identifier 2016-SW-002-AD.

(a) Applicability

This AD applies to Bell Helicopter Textron Canada Limited Model 429 helicopters with a tail rotor (T/R) pitch link (link) part number (P/N) 429-012-112-101, -101FM, -103, or -103FM installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as failure of a T/R link. This condition could result in loss of T/R flight control and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective February 2, 2016.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) For T/R link P/N 429-012-112-101 and 429-012-112-103, within 10 hours time-in-service (TIS):

(i) Remove each T/R link assembly. Prior to cleaning the T/R link bearing bores, using 10X or higher power magnification, inspect each T/R link bearing bore for aluminum oxide corrosion extruding from between the roll staked lip of the bearing outer race and the link bearing bore. Aluminum oxide corrosion appears as a white crystalline material in contrast with the black finish and any accumulated soot. An example of this corrosion is shown in Figure 1 of Bell Helicopter Alert Service Bulletin 429-15-26, dated December 7, 2015 (ASB 429-15-26).

(ii) If there is any aluminum oxide corrosion, replace the T/R link before further flight.

(iii) If there is no aluminum oxide corrosion, clean each T/R link bearing bore with isopropyl alcohol and inspect for pitting.

(A) If there is any pitting, replace the T/R link before further flight.

(B) If there is no pitting, apply corrosion preventative sealant by following the Accomplishment Instructions, paragraph 5. of Part I, of ASB 429-15-26.

(2) For all T/R links listed in paragraph (a) of this AD, within 50 hours TIS and thereafter at intervals not to exceed 50 hours TIS, using 10X or higher power magnification, inspect each T/R link bearing bore for missing corrosion preventative sealant. If any corrosion preventative sealant is missing, perform the actions in paragraph (e)(1)(i) through (e)(1)(iii) of this AD before further flight.

(3) Do not install T/R link P/N 429-012-112-101 or -103 on any helicopter before complying with the actions in paragraph (e)(1) of this AD.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in Transport Canada AD CF-2016-01, dated January 5, 2016. You may view the Transport Canada AD on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2016-2068.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6400, Tail Rotor System.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bell Helicopter Alert Service Bulletin 429-15-26, dated December 7, 2015.

(ii) Reserved.

(3) For Bell Helicopter service information identified in this final rule, contact Bell Helicopter Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; telephone (450) 437-2862 or (800) 363-8023; fax (450) 433-0272; or at <http://www.bellcustomer.com/files/>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on January 22, 2016.

Scott A. Horn,
Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.