

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2015-24**

11/16/2015 - 11/29/2015



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2015-01			
2014-26-03		Saab AB, Saab Aerosystems	340B
Biweekly 2015-02			
2014-25-51		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-25-52		Airbus	A330-223F, -243F, A330-201, -202, -203, -223, -243, A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, -313, A340-541 and A340-642
2014-26-06		ATR–GIE Avions de Transport Régional	ATR42-500 and ATR72-212A
2014-26-07		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G
2014-26-09	R 2014-03-05	Bombardier, Inc.	BD-700-1A10
2014-26-10		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-53		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-01-01	R 2011-09-11	The Boeing Company	777-200 and -300 series
Biweekly 2015-03			
2014-23-15	R 2011-14-06	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-08	R 2011-13-09	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2015-02-02		Bombardier, Inc	CL-215-6B11 (CL-215T Variant), CL-215-6B11 (CL-415 Variant)
2015-02-03		Airbus	A300 B4-601, B4-603, B4-605R, F4-605R, and C4-605R Variant F
2015-02-04		Dassault Aviation	MYSTERE-FALCON 50
2015-02-05		The Boeing Company	717-200, DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F, MD-10-10F and MD-10-30F, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87), MD-88, MD-90-30
2015-02-06		Bombardier, Inc	CL-600-2B16 (CL-604 Variant)
2015-02-08		Rolls-Royce Corporation (RRC)	AE 2100D2, 2100D2A, 2100D3, 2100P and AE 3007A1, A1/1, A1/3, A1E, A1P, A2, A3, C, C1, and C2
2015-02-11		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-02-12		Bombardier, Inc	DHC-8-400, -401 and -402
2015-02-13		Empresa Brasileira de Aeronautica S.A. (Embraer)	EMB -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2015-02-16	R 2009-06-06	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-02-17		Airbus	A330-201, -202, -203, -223, -223F, -243, and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2015-02-18		Airbus	A330-201, -202, -203, -301, -302, and -303
2015-02-19	R 95-24-04	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R, A300 C4-605R Variant F

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-02-20	S 2013-15-10	Rolls-Royce plc (RR)	RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61, 768-60, 772-60, 772B-60, 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, 895-17, 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84
2015-02-23		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants)
2015-02-26	R 2013-24-13	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series, 737-600, -700, -700C, -800, and -900 series
Biweekly 2015-04			
2015-02-24	R 2007-03-18 R2008-17-02 R2012-08-03 R2012-15-14	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, A300 B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-02-25		Bombardier, Inc.	DHC-8-400, -401, and -402
2015-03-01		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2015-03-02		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-03-04		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2015-03-05	R 2012-09-07	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-03-06	R 2007-22-10	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213 -311, -312, -313, -541, and -642
Biweekly 2015-05			
2015-02-14	R 2009-20-05	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, -232.
2015-03-03		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R. A300 C4-605R Variant F.
2015-04-02		CFM International S.A.	CFM56-7B series
2015-04-03		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60
2015-04-06		Rolls-Royce plc	RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17.
Biweekly 2015-06			
2015-04-07		Boeing	767-200 and -300 series airplanes
2015-05-01		Boeing	757-200, -200PF, -200CB, and -300 series airplanes; and 767-200, -300, -300F, and -400ER series airplanes
2015-05-03		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2015-05-07	R 2015-02-06	Bombardier	CL-600-2B16 (CL-604 Variant) airplanes
2015-05-08		Lockheed Martin	382, 382B, 382E, 382F, and 382G airplanes
2015-06-01	S 2014-06-03	British Aerospace	Jetstream Series 3101 and Jetstream 3201 airplanes
Biweekly 2015-07			
2015-04-08	R 2014-06-08	Bombardier, Inc	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2015-05-02	R 2014-23-15	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2015-06-04	R 2011-13-07	Dassault	FALCON 7X
2015-06-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-06-06 2015-06-07 2015-07-01		BAE Systems The Boeing Company Rolls-Royce plc	A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes. 4101 airplanes 737-100, -200, -200C, -300, -400, and -500 series airplanes RB211-524B-02, RB211-524B-B-02, RB211-524B2-19, RB211-524B2-B-19, RB211-524B3-02, RB211-524C2-19, and RB211-524C2-B-19 turbofan engines
Biweekly 2015-08			
2015-06-08	R 2011-09-03	Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G
2015-07-05		BAE Systems (Operations) Limited	146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2015-07-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-07-07 2015-08-02	R 2015-02-04	The Boeing Company Dassault Aviation	777-200, -200LR, -300ER, and 777F series MYSTERE-FALCON 50
Biweekly 2015-09			
2015-06-10		ATR-GIE Avions de Transport Régional	ATR72-212A
2015-07-02		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), CL-600-2B16 (CL-604 Variants)
2015-08-01 2015-08-03 2015-08-05	R 2013-26-05	The Boeing Company Bombardier, Inc. Dassault Aviation	757-200, -200PF, -200CB, and -300 series DHC-8-400, -401, and -402 FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2015-08-06	R 2007-14-05	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-08-08	R 2014-26-53 and 2015-03-02	Airbus	A319-115, A319-132, A319-133, A320-214, A320-232, and A320-233
2015-08-09 2015-09-02 2015-09-03		The Boeing Company Bombardier, Inc. Airbus	737-600 and -700 series CL-600-2E25 (Regional Jet Series 1000)
2015-09-07		The Boeing Company	A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 787
Biweekly 2015-10			
2015-08-07 2015-09-05 2015-09-08		Zodiac Aerotechnics The Boeing Company Airbus	See AD 747-400 and 747-400F
2015-09-09	R 2004-07-11	The Boeing Company	A300 B4-601, B4-603, and B4-605R; and A300 F4-605R; and A300 C4-605R Variant F; and A310-204 and -304 767-200, -300, and -400ER series
Biweekly 2015-11			
2015-10-02	R 2014-20-11	Zodiac Seats France	9140, 9166, 9173, 9174, 9184, 9188, 9196, 91B7, 91B8, 91C0, 91C2, 91C4, 91C5, 91C9, 9301, and 9501 series passenger seat assemblies
2015-10-03	R 2014-09-05	Airbus Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-10-04	R 2012-09-09	International Aero Engines AG	IAE V2500-A1, IAE V2525-D5, IAE V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, and V2533-A5
2015-11-04		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body; 707-300, -300B, -300C, -400; 720 and 720B series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2015-12			
2015-10-01		Bombardier, Inc.	DHC-8-401, -402, and -403
2015-11-02	R 95-26-11	Lockheed Martin Corporation	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2015-11-03		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A; ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A
2015-11-05		The Boeing Company	747-400, 747-400D, 747-400F, 747-8F, and 747-8 series
Biweekly 2015-13			
2015-10-51		Avidyne Corporation	Integrated Flight Displays (IFDs)
2015-12-03	COR R 2007-13-05	The Boeing Company	777-200, -200LR, -300, and -300ER series
2015-12-05	R 2008-06-18	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-12-06		Learjet Inc.	45
2015-12-07		The Boeing Company	747-8F and 747-8 series
2015-12-08		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-12-10		Pratt & Whitney Division	PW6122A and PW6124A
2015-12-11	COR	The Boeing Company	767-200, -300, -300F, and -400ER series, 777-200, -200LR, -300, -300ER, and 777F
2015-12-12		Fokker Services B.V.	F.28 Mark 0070 and 0100
2015-13-01		ATR-GIE Avions de Transport Régional	ATR42-500, ATR72-212A
2015-13-02		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2015-14			
2015-13-08		Dassault Aviation	FALCON 2000EX
2015-14-01		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2015-15			
2015-13-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-13-07	R 98-13-23	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; and A300 C4-605R Variant F
2015-14-03		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2015-14-05		Pratt & Whitney	JT8D-217C and JT8D-219
2015-14-06		The Boeing Company	747-8 and 747-8F series
2015-14-07		The Boeing Company	787-8
2015-14-08		Airbus	A310-203
2015-14-09		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, 747SP, 747-8F, and 747-8 series
2015-15-01	R 2004-13-02	The Boeing Company	747-100, -200B, and -200F series
2015-15-02	R 2012-13-06	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R; and A300 C4-605R Variant F
2015-15-03		General Electric Company	GENx-1B and GENx-2B
2015-15-05	R 98-22-10 R 90-06-02	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-15-08		Bombardier, Inc.	BD-100-1A10 (Challenger 300)
2015-15-09		BAE Systems (Operations) Limited	4101
2015-15-10		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2015-16

2012-11-09 R1		Transport Category Airplanes	Chemical oxygen generators
2015-13-06	R 2013-14-05	The Boeing Company	747-400 and -400F series
2015-15-07	R 2015-10-01	Bombardier, Inc.	DHC-8-400, -401, and -402
2015-15-11		The Boeing Company	747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2015-15-12		Airbus	A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233
2015-15-13		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-15-14		BAE Systems (Operations) Limited	ATP
2015-15-15		The Boeing Company	777-200, 777-200LR, 777-300ER, and 777F series

Biweekly 2015-17

2015-16-01	R 2012-19-11	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series; 737-600, -700, -700C, -800, -900, and -900ER series
2015-16-02	R 2003-14-11 R 2004-11-08 R 2004-13-25 R 2004-18-14 R 2007-05-12 R 2008-06-07 R 2009-18-20 R 2010-15-02 R 2012-04-07	Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2015-16-03		Rolls-Royce plc	RB211-524B-02, RB211-524B2-19, RB211-524B3-02, RB211-524B4-02, RB211-524B4-D-02, RB211-524C2-19, RB211-524D4-19, RB211-524D4-39, and RB211-524D4X-19
2015-16-04		Kidde Graviner	See AD
2015-16-05		British Aerospace Regional Aircraft	Jetstream Series 3101 and Jetstream Model 3201
2015-16-06		British Aerospace Regional Aircraft	Jetstream Model 3201
2015-17-04		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2015-17-06		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-17-09	R 98-18-02	Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F

Biweekly 2015-18

2015-16-08	R 2011-08-51	The Boeing Company	737-300, -400, and -500 series
2015-17-03		Bombardier, Inc	DHC-8-400, -401, and -402
2015-17-05		Bombardier, Inc	BD-700-1A10 and BD-700-1A11
2015-17-07		Airbus	A300 B4-603, B4-605R, B4-620, B4-622, and B4-622R, A300 C4-605R Variant F, A300F4-605R
2015-17-08		Bombardier, Inc	DHC-8-400, -401, and -402 series
2015-17-12		Cessna Aircraft Company	500, 501, 550, 551, S550, 560, 650
2015-17-13		The Boeing Company	777-200 and -300 series
2015-17-14		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-17-15		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000).

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-17-16 2015-17-17		Bombardier, Inc Pratt & Whitney	CL-600-2B19 (Regional Jet Series 100 & 440) PW4164-1D, PW4168-1D, PW4168A-1D and PW4170, PW4164, PW4168, and PW4168A
2015-17-22		Airbus	A330-243, A330-243F, A330-341, A330-342, and A330-343
2015-17-23		Empresa Brasileira de Aeronautica S.A. (Embraer)	EMB-135BJ
2015-17-24 2015-17-25 2015-18-02		The Boeing Company Bombardier, Inc Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	787-8 DHC-8-400, -401, and -402 382, 382B, 382E, 382F, and 382G
Biweekly 2015-19			
2015-17-19 2015-18-04 2015-18-05 2015-19-01 2015-19-02 2015-19-03 2015-19-04	R 97-07-14	Rolls-Royce plc CFM International S.A. Airbus The Boeing Company The Boeing Company The Boeing Company The Boeing Company	RB211 Trent 768-60, 772-60, and 772B-60 CFM56-7B and CFM56-3 A320-211 and -231 777-200, -200LR, -300, -300ER, and 777F series 767-200, -300, -300F, and -400ER series 737-600, -700, -700C, -800, -900, and -900ER series 757-200, -200PF, -200CB, and -300 series
Biweekly 2015-20			
2015-19-06 2015-19-08	R 2012-24-10 R 2011-19-04	The Boeing Company Airbus	747-400 and -400F series A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-19-09 2015-19-12 2015-19-13 2015-19-16 2015-20-02	R 2013-02-10	The Boeing Company The Boeing Company Bombardier, Inc. The Boeing Company Airbus	787-8 767-200, -300, -300F, and -400ER series DHC-8-400, -401, and -402 777-200, -200LR, -300,-300ER, and 777F series A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-20-05		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	188A and 188C
Biweekly 2015-21			
2015-15-06 2015-20-01	R 2003-13-01	The Boeing Company Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	767-200, -300, and -300F series; 67-400ER series 188A and 188C
2015-20-03 2015-20-06 2015-20-07	R 2014-14-02	Pratt & Whitney Canada Corp Viking Air Limited Bombardier, Inc	PW120, PW121, and PW121A; PW124B, PW127, PW127E, PW127F; PW127E, PW127F; and PW127G DHC-7-1 and DHC-7-100 CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
2015-20-08		Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2015-20-10		Gulfstream Aerospace Corporation	GVI
Biweekly 2015-22			
2015-17-21 2015-18-04 2015-21-02 2015-21-03 2015-21-05	COR R 2010-08-08 R2011-06-04	Rolls-Royce plc CFM International S.A. Bombardier, Inc. Airbus Fokker Services B.V.	RB211-535E4-37, RB211-535E4-B-37, and RB211-535E4-C-37 CFM56-7B and CFM56-3 DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 A330-243, -341, -342, and -343; and A330-243F F.27 Mark 200, 300, 400, 500, 600, and 700

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-21-07		Airbus	A330-201, -202, -203, -223, and -243; A330-223F and -243F; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; A340-642
2015-21-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-21-09	R 2015-19-02	The Boeing Company	767-200, -300, -300F, and -400ER series
2015-21-10	R 2015-19-03	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2015-21-11	R 2015-16-01	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series; 737-600, -700, -700C, -800, -900, and -900ER series
2015-22-01	R 2007-16-08	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series
2015-22-03		Pratt & Whitney Division	PW4164, PW4168, PW4168A, PW4164C, PW4164C/B, PW4164-1D, PW4168-1D, PW4168A-1D, PW4170, PW4164C-1D, and PW4164C/B-1D; PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650
Biweekly 2015-23			
2015-21-06	R 2002-07-08	The Boeing Company	737-200, -200C, -300, -400, and -500 series airplanes
2015-22-05	R 2009-18-15	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes; A300 B4-601, B4-603, B4-620, and B4-622 airplanes; A300 B4-605R and B4-622R airplanes; A300 F4-605R and F4-622R, and A300 C4-605R Variant F airplanes; and A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2015-22-06		Airbus	A318-111, -112, -121, and -122 airplanes; A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; A320-211, -212, -214, -231, -232, and -233 airplanes; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.
2015-22-07		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	188A and 188C airplanes
2015-22-08		Airbus	A318-111, -112, -121, and -122 airplanes; A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; A320-211, -212, -214, -231, -232, and -233 airplanes
2015-22-09		The Boeing Company	787-8 airplanes
2015-22-10		Airbus	A318-111, -112, -121, and -122 airplanes; A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; A320-211, -212, -214, -231, -232, and -233 airplanes; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2015-23-04		General Electric Company	GENx-1B model turbofan engines
Biweekly 2015-24			
2015-22-11	R 2011-09-04	Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G airplanes
2015-23-05		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F airplanes, A330-301, -302, -303, -321, -322, -323, -341, -342, -343 airplanes, A340-211, -212, -213, -311, -312, -313 airplanes.
2015-23-06	R 2008-22-20	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-311, -312, and -313 airplanes
2015-23-07		Bombardier, Inc.	BD-100-1A10 (Challenger 300) airplanes
2015-23-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2015-23-09		Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems)	Flightcrew oxygen mask regulators (See AD)
2015-23-10		The Boeing Company	747-8 series airplanes
2015-23-11		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747SR, and 747SP series airplanes
2015-23-12		ATR–GIE Avions de Transport Régional	ATR42-200, -300, -320, -500; and ATR72-101, -201, -102, -202, -211, -212, and -212A airplanes
2015-23-13		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133 A320-211, -212, -214, -231,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-23-14 2015-24-01		Fokker Services B.V. Airbus	-232, and -233 A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes. F.28 Mark 0070 and 0100 airplanes A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes



2015-22-11 Lockheed Martin Corporation/Lockheed Martin Aeronautics Company:
Amendment 39-18316; Docket No. FAA-2014-0427; Directorate Identifier 2013-NM-218-AD.

(a) Effective Date

This AD is effective December 28, 2015.

(b) Affected ADs

This AD replaces AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011).

(c) Applicability

This AD applies to all Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model 382, 382B, 382E, 382F, and 382G airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) that indicated the center wing box (CWB) is subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking of the lower surface of the CWB, which could result in structural failure of the wings.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection, With Revised Service Information

This paragraph restates the actions required by paragraph (g) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011), with revised service information. At the time specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, whichever occurs latest: Do a nondestructive inspection of the lower surface of the CWB for any damage, in accordance with Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007; or Lockheed Service Bulletin 382-57-85 (82-790), Revision 3, dated July 8, 2013, including Appendix A, Revision 3, dated July 8, 2013, and Appendixes B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007. Repeat the inspections thereafter at intervals not to exceed 10,000 flight hours. As of the effective date of this AD, use only Lockheed Service Bulletin 382-57-85 (82-790), Revision 3, dated July 8, 2013, including Appendix A, Revision 3, dated July 8, 2013, and Appendixes B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, for the actions required by this paragraph.

- (1) Prior to the accumulation of 40,000 total flight hours on the center wing.
- (2) Within 365 days after June 22, 2011 (the effective date of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011)).
- (3) Within 10,000 flight hours on the CWB after the accomplishment of the inspection specified in paragraph (g) of this AD, if done before June 22, 2011 (the effective date of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011)).

(h) Retained Corrective Action, With Revised Repair Instructions

This paragraph restates the actions required by paragraph (h) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011), with revised repair instructions. If any damage is found before the effective date of this AD during any inspection required by paragraph (g) of this AD: Before further flight, repair any damage, using a method approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. If any damage is found as of the effective date of this AD, during any inspection required by paragraph (g) of this AD: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(i) Retained Exceptions to Service Information Specifications, With Revised Repair Instructions

(1) This paragraph restates the exception specified in paragraph (i) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011), with revised repair instructions. Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, specifies that operators may adjust thresholds and intervals, use alternative repetitive inspection intervals, and use alternative inspection methods, if applicable. However, this AD requires the applicable approval specified in paragraph (i)(1)(i) or (i)(1)(ii) of this AD.

(i) Before the effective date of this AD: This AD requires that any alternative methods or intervals be approved by the Manager, Atlanta ACO. For any alternative methods or intervals to be approved by the Manager, Atlanta ACO, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

(ii) As of the effective date of this AD, this AD requires that any alternative methods or intervals be approved in accordance with the procedures specified in paragraph (m) of this AD.

(2) This paragraph restates the exception stated in paragraph (j) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011), with no changes. Where Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, specifies that alternative repetitive inspection intervals may be used for cold-worked holes, this AD does not allow the longer interval. This AD requires that all cold-worked and non-cold-worked holes be reinspected at 10,000-flight-hour intervals.

(3) This paragraph restates the exception stated in paragraph (k) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011), with no changes. Where Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, describes procedures for submitting a report of any damages, this AD does not require such action.

(j) New Inspection and Corrective Actions

As of the effective date of this AD, concurrently with accomplishing the inspection required by paragraph (g) of this AD: Do all applicable related investigative actions, in accordance with Appendix A, Revision 3, dated July 8, 2013, of Lockheed Service Bulletin 382-57-85 (82-790), Revision 3, dated July 8, 2013, including Appendix A, Revision 3, dated July 8, 2013, and Appendixes B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007. If any cracking or damage

is found during any related investigative action: Before further flight, repair all cracking and damage, using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(k) New Exceptions to Service Information Specifications

(1) Lockheed Service Bulletin 382-57-85 (82-790), Revision 3, dated July 8, 2013, including Appendix A, Revision 3, dated July 8, 2013, and Appendixes B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, specifies that operators may adjust thresholds and intervals, use alternative repetitive inspection intervals, and use alternative inspection methods. However, this AD requires that any alternative thresholds, intervals, or inspection methods be approved in accordance with the procedures specified in paragraph (m) of this AD.

(2) Where Lockheed Service Bulletin 382-57-85 (82-790), Revision 3, dated July 8, 2013, including Appendix A, Revision 3, dated July 8, 2013, and Appendixes B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, describes procedures for submitting a report of any damages, this AD does not require such action.

(l) Credit for Previous Actions

(1) This paragraph restates the credit provided in paragraph (l) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011). This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before June 22, 2011 (the effective date of AD 2011-09-04), using Lockheed Service Bulletin 382-57-85 (82-790), Revision 1, dated March 8, 2007, which is not incorporated by reference in this AD.

(2) This paragraph restates the credit provided in paragraph (m) of AD 2011-09-04, Amendment 39-16666 (76 FR 28626, May 18, 2011). This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before June 22, 2011 (the effective date of AD 2011-09-04), using Lockheed Service Bulletin 382-57-85 (82-790), dated August 4, 2005, which is not incorporated by reference in this AD.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (n)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by a Delegated Engineering Representative (DER) for the Lockheed Martin Aeronautics Company who has been authorized by the Manager, Atlanta ACO, to make those findings. For a repair method to be approved, the repair approval must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(n) Related Information

(1) For more information about this AD, contact Carl Gray, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, GA 30337; telephone 404-474-5554; fax 404-474-5605; email: carl.w.gray@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(5) and (o)(6) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on December 28, 2015.

(i) Lockheed Service Bulletin 382-57-85 (82-790), Revision 3, dated July 8, 2013, including Appendix A, Revision 3, dated July 8, 2013, and Appendixes B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007.

(ii) Reserved.

(4) The following service information was approved for IBR on June 22, 2011 (76 FR 28626, May 18, 2011).

(i) Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007.

(ii) Reserved.

(5) For Lockheed Martin Corporation/Lockheed Martin Aeronautics Company service information identified in this AD, contact Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column P-58, 86 S. Cobb Drive, Marietta, GA 30063; telephone 770-494-5444; fax 770-494-5445; email ams.portal@lmco.com; Internet <http://www.lockheedmartin.com/ams/tools/TechPubs.html>.

(6) You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 29, 2015.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-05 Airbus: Amendment 39-18321. Docket No. FAA-2014-1043; Directorate Identifier 2013-NM-079-AD.

(a) Effective Date

This AD becomes effective December 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Airbus Model A330-201, -202, -203, -223, -223F, -243, and -243F airplanes.

(2) Airbus Model A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.

(3) Airbus Model A340-211, -212, -213, -311, -312, and -313 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of cracked support strut body ends at a certain frame location of the trimmable horizontal stabilizer (THS). We are issuing this AD to detect and correct cracked support strut body ends of the THS, which could lead to the loss of all four THS support struts and which would make the remaining structure unable to carry limit loads, resulting in the loss of the horizontal tail plane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definition of Strut Types

For the purpose of this AD, a Société Anonyme de Recherche Mécanique Appliquée (SARMA) strut is a strut on which the diameter of the strut end is less than 43 millimeters. All other struts are Technical Airborne Components Industries (TAC) struts.

(h) Repetitive Inspections of TAC Strut Ends

At the applicable time specified in paragraph (i) of this AD, do a high frequency eddy current (HFEC) inspection for cracking of all TAC strut ends of the THS support located at frame (FR) 91 in

the tail cone, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014; or Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014; as applicable. Repeat the inspection thereafter at intervals not to exceed 42 months or 20,000 flight hours, whichever occurs first. For airplanes on which Airbus Modification 203493 or 203834 has been embodied in production, or Airbus Service Bulletin A330-53-3204 or Airbus Service Bulletin A340-53-4199, as applicable, has been embodied in service, remove the clamp from each strut end before accomplishing the inspections required by this paragraph.

(i) Compliance Times for the Actions Required by Paragraphs (h) and (k) of This AD

Do the inspections required by paragraphs (h) and (k) of this AD at the applicable times specified in paragraphs (i)(1), (i)(2), and (i)(3) of this AD.

(1) For Model A330 series airplanes having manufacturer serial numbers 012 through 209 inclusive, and Model A340 series airplanes having manufacturer serial numbers 002 through 210 inclusive: Within 6 months after the effective date of this AD.

(2) For Model A330 series airplanes having manufacturer serial numbers 211 through 422 inclusive, and Model A340 series airplanes having manufacturer serial numbers 212 through 447 inclusive: Within 24 months after the effective date of this AD.

(3) For Model A330 series airplanes having manufacturer serial numbers 423 and subsequent, and Model A340 series airplanes having manufacturer serial numbers 450 through 955 inclusive: Within 36 months after the effective date of this AD or since the first flight of the airplane, whichever occurs later.

(j) Corrective Action for TAC Strut Ends and Installation of Reinforcing Clamps

(1) If, during any inspection required by paragraph (h) of this AD, no cracks are found: Before further flight, reinstall or install, as applicable, reinforcing clamps on the strut ends, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014; or Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014; as applicable.

(2) If, during any inspection required by paragraph (h) of this AD, any crack is found: Before further flight, replace any affected strut with a new or serviceable TAC strut and install reinforcing clamps on the strut end, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014; or Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014; as applicable.

(k) Repetitive Inspections of SARMA Strut Ends

At the applicable time specified in paragraph (i) of this AD, do an HFEC inspection for cracking of all SARMA strut ends of the THS support located at FR 91 in the tail cone, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014; or Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014; as applicable. Repeat the inspection thereafter at intervals not to exceed 12 months.

(l) Corrective Action for SARMA Strut Ends

If any crack is found on a strut end during the inspection required by paragraph (k) of this AD: Before further flight, replace any affected SARMA strut with a new or serviceable TAC strut and install reinforcing clamps on the strut end, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014; or Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014; as applicable.

(m) No Terminating Action

Replacement of THS struts on an airplane does not constitute terminating action for the repetitive inspections required by this AD.

(n) No Reporting

Although Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014; and Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014; specify to submit certain information to the manufacturer, this AD does not include that requirement.

(o) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g), (h), (j), and (k) of this AD, if those actions were performed before the effective date of this AD using any of the service information identified in paragraphs (n)(1) through (n)(6) of this AD. This service information is not incorporated by reference in this AD.

- (1) Airbus Service Bulletin A330-53-3206, dated February 7, 2013.
- (2) Airbus Service Bulletin A330-53-3206, Revision 01, dated June 10, 2013.
- (3) Airbus Service Bulletin A330-53-3206, Revision 02, dated August 8, 2013.
- (4) Airbus Service Bulletin A340-53-4208, dated February 7, 2013.
- (5) Airbus Service Bulletin A340-53-4208, Revision 01, dated June 10, 2013.
- (6) Airbus Service Bulletin A340-53-4208, Revision 02, dated August 8, 2013.

(p) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(q) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0068, dated March 18, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-1043-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (r)(3) and (r)(4) of this AD.

(r) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-53-3206, Revision 03, dated February 28, 2014.

(ii) Airbus Service Bulletin A340-53-4208, Revision 03, dated February 28, 2014.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 30, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-06 Airbus: Amendment 39-18322. Docket No. FAA-2015-0490; Directorate Identifier 2014-NM-018-AD.

(a) Effective Date

This AD becomes effective December 29, 2015.

(b) Affected ADs

This AD replaces AD 2008-22-20, Amendment 39-15717 (73 FR 66747, November 12, 2008).

(c) Applicability

This AD applies to Airbus Model A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes; and Model A340-311, -312, and -313 airplanes; certificated in any category; all manufacturer serial numbers on which Airbus Modification 44205 has been embodied in production, except those on which Airbus Modification 52974 or 53223 has been embodied in production.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by the results of a fatigue and damage tolerance evaluation that concluded existing compliance times must be reduced. We are issuing this AD to prevent fatigue cracking of the upper shell structure of the fuselage, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection for Airbus Model A330-300 and A340-300 Airplanes, Except Model A340-300 Weight Variant (WV) 027 Airplanes

For Model A330-300 and A340-300 airplanes, except Model A340-300 WV 027 airplanes: At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD, do a high frequency eddy current (HFEC) inspection for cracking of the upper shell structure between frame (FR) 80 and FR86, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3168, Revision 02, dated December 21, 2011; or Airbus Service Bulletin A340-53-4174, Revision 02, dated December 21, 2011; as applicable. Repeat the inspection thereafter at the applicable time specified in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3168, Revision 02, dated

December 21, 2011; or Airbus Service Bulletin A340-53-4174, Revision 02, dated December 21, 2011; as applicable.

(1) For airplanes that, as of the effective date of this AD, have not been inspected in accordance with Airbus Service Bulletin A330-53-3168; or Airbus Service Bulletin A340-53-4174; as applicable: Inspect at the later of the times specified in paragraphs (g)(1)(i) and (g)(1)(ii) of this AD.

(i) Before reaching the applicable threshold specified in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3168, Revision 02, dated December 21, 2011; or Airbus Service Bulletin A340-53-4174, Revision 02, dated December 21, 2011; as applicable for airplane model, configuration, and utilization, since the airplane's first flight.

(ii) Within the threshold defined in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3168, Revision 01, dated February 15, 2008; or Airbus Service Bulletin A340-53-4174, Revision 01, dated February 15, 2008; as applicable for airplane model, configuration, and utilization since the airplane's first flight; or within 12 months after the effective date of this AD; whichever occurs first.

(2) For airplanes that, as of the effective date of this AD, have been inspected in accordance with Airbus Service Bulletin A330-53-3168; or Airbus Service Bulletin A340-53-4174; as applicable: Inspect at the later of the times specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD.

(i) Within the applicable interval specified in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3168, Revision 02, dated December 21, 2011; or Airbus Service Bulletin A340-53-4174, Revision 02, dated December 21, 2011; as applicable; to be counted from the last inspection.

(ii) Within 12 months after the effective date of this AD without exceeding the intervals defined in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3168, Revision 01, dated February 15, 2008; or Airbus Service Bulletin A340-53-4174, Revision 01, dated February 15, 2008; as applicable for airplane model, configuration, and utilization to be counted from the last inspection.

(h) Corrective Action for Airbus Model A330-300 and A340-300 Airplanes, Except Model A340-300 WV 027 Airplanes

If any crack is detected during any HFEC inspection required by the introductory text to paragraph (g) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). Accomplishment of a repair for a specific area, as required by this paragraph, is terminating action for the repetitive HFEC inspections required by the introductory text to paragraph (g) of this AD, as applicable, for that specific repaired area only. The need and definition of subsequent repetitive inspections (if any) for that specific repaired area will be defined in the applicable repair method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) or Airbus's EASA Design Organization Approval (DOA).

(i) Optional Terminating Action

For Airbus Model A330-300 and A340-300 airplanes, except Model A340-300 WV 027 airplanes: Modification, which includes inspections and applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3159, Revision 02, dated March 29, 2010; or Airbus Service Bulletin A340-53-4165, Revision 02, dated March 29, 2010; as applicable; terminates the repetitive HFEC inspections required by the introductory text to paragraph (g) of this AD, except where Airbus Service Bulletin A330-53-3159, Revision 02, dated March 29, 2010; or Airbus Service Bulletin A340-53-4165, Revision 02, dated March 29, 2010; as applicable; specifies to contact the manufacturer, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA.

(j) Inspection and Modification for Airbus Model A330-200 Airplanes

Within the compliance times specified in paragraph (j)(1) or (j)(2) of this AD, whichever occurs later: Do all applicable actions, including an eddy current rotating probe test and an HFEC inspection for cracks, and modify the airplane upper shell structure between FR80 and FR86; in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3160, Revision 03, dated January 6, 2012.

(1) Within the compliance times identified in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3160, Revision 03, dated January 6, 2012, as applicable for airplane configuration and utilization since the airplane's first flight.

(2) Within 12 months after the effective date of this AD without exceeding the threshold defined in paragraph 1.E., "COMPLIANCE," of Airbus Service Bulletin A330-53-3160, Revision 02, dated March 29, 2010, since the airplane's first flight.

(k) Inspection and Modification for Airbus Model A340-300 Airplanes, Only WV 027

For Model A340-300 airplanes, WV 027 only: Before the accumulation of 14,200 total flight cycles from the airplane's first flight, do all applicable inspections and modify the airplane upper shell structure between FR80 and FR86; in accordance with the Accomplishment Instructions of Airbus Service Bulletin A340-53-4172, Revision 01, dated July 8, 2009.

(l) Corrective Action for Airbus Model A330-200 Airplanes; and Model A340-300 Airplanes, only WV 027

If any crack is detected during the inspection required by the introductory text to paragraph (j) of this AD, or paragraph (k) of this AD, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA; concurrently with modification required by paragraph the introductory text to paragraph (j) of this AD, or paragraph (k) of this AD.

(m) Definition of "Threshold" and "Interval"

(1) For the purposes of this AD, the term "Threshold," as used in paragraph 1.E., "COMPLIANCE," of the service information specified in paragraphs (m)(2)(i) through (m)(2)(vi) of this AD means the total flight cycles or flight hours accumulated since the airplane's first flight.

(2) For the purposes of this AD, the term "Interval" as used in paragraph 1.E., "COMPLIANCE," of the service information specified in paragraphs (m)(2)(i) through (m)(2)(vi) of this AD means the total flight cycles or flight hours accumulated since the last inspection, as applicable.

(i) Airbus Service Bulletin A330-53-3168, dated September 19, 2007.

(ii) Airbus Service Bulletin A330-53-3168, Revision 01, dated February 15, 2008.

(iii) Airbus Service Bulletin A330-53-3168, Revision 02, dated December 21, 2011.

(iv) Airbus Service Bulletin A340-53-4174, dated September 19, 2007.

(v) Airbus Service Bulletin A340-53-4174, Revision 01, dated February 15, 2008.

(vi) Airbus Service Bulletin A340-53-4174, Revision 02, dated December 21, 2011.

(n) Credit for Previous Actions

(1) For Model A330-300 and A340-300 airplanes, except Model A340-300 WV 027 airplanes: This paragraph provides credit for the modification specified in paragraph (i) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (n)(1)(i), (n)(1)(ii), (n)(1)(iii), or (n)(1)(iv) of this AD, as applicable. This service information is not incorporated by reference in this AD.

- (i) Airbus Service Bulletin A330-53-3159, dated September 19, 2007.
- (ii) Airbus Service Bulletin A330-53-3159, Revision 01, dated June 15, 2009.
- (iii) Airbus Service Bulletin A340-53-4165, dated September 19, 2007.
- (iv) Airbus Service Bulletin A340-53-4165, Revision 01, dated June 17, 2009.

(2) For Model A330-200 airplanes: This paragraph provides credit for the inspection and modification required by the introductory text to paragraph (j) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (n)(2)(i), (n)(2)(ii), or (n)(2)(iii) of this AD, as applicable.

(i) Airbus Service Bulletin A330-53-3160, dated July 9, 2007, which was incorporated by reference in AD 2008-22-20, Amendment 39-15717 (73 FR 66747, November 12, 2008).

(ii) Airbus Service Bulletin A330-53-3160, Revision 01, dated April 28, 2009, which is not incorporated by reference in this AD.

(iii) Airbus Service Bulletin A330-53-3160, Revision 02, dated March 29, 2010, which is not incorporated by reference in this AD.

(3) For Model A340-300 airplanes, WV 027 only: This paragraph provides credit for the inspection and modification required by paragraph (k) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A340-53-4172, dated July 10, 2007, which is was incorporated by reference in AD 2008-22-20, Amendment 39-15717 (73 FR 66747, November 12, 2008).

(o) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(p) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0012R1, dated January 24, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0490.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (q)(3) and (q)(4) of this AD.

(q) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on December 29, 2015.

(i) Airbus Service Bulletin A330-53-3159, Revision 02, dated March 29, 2010.

(ii) Airbus Service Bulletin A330-53-3160, Revision 03, dated January 6, 2012.

(iii) Airbus Service Bulletin A330-53-3168, Revision 02, dated December 21, 2011.

(iv) Airbus Service Bulletin A340-53-4165, Revision 02, dated March 29, 2010.

(v) Airbus Service Bulletin A340-53-4172, Revision 01, dated July 8, 2009.

(vi) Airbus Service Bulletin A340-53-4174, Revision 02, dated December 21, 2011.

(4) The following service information was approved for IBR on December 17, 2008 (73 FR 66747, November 12, 2008).

(i) Airbus Service Bulletin A330-53-3168, Revision 01, dated February 15, 2008.

(ii) Airbus Service Bulletin A340-53-4174, Revision 01, dated February 15, 2008.

(5) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 30, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-07 Bombardier, Inc.: Amendment 39-18323. Docket No. FAA-2015-0929; Directorate Identifier 2014-NM-218-AD.

(a) Effective Date

This AD becomes effective December 22, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes, certificated in any category, having serial numbers 20003 through 20382 inclusive, 20384, and 20386.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Reason

This AD was prompted by multiple reports of chafing found on an electrical wiring harness in the aft equipment bay, caused by contact between the wiring harness and a neighboring hydraulic line. We are issuing this AD to detect and correct chafing on an electrical wiring harness, which could cause an electrical short circuit or lead to a malfunction of the flight control system, the engine indication system, or the hydraulic power control system; which could adversely affect the continued safe operation and landing of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection, Repair, and Preventive Modification

Within 36 months after the effective date of this AD, do the actions required by paragraphs (g)(1) and (g)(2) of this AD.

(1) Do a one-time general visual inspection to detect damage (including wear and chafing) of the wiring harness, in accordance with the Accomplishment Instructions of Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014. Repair any damage before further flight, in accordance with the Accomplishment Instructions of Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014; except, where Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014, specifies to contact Bombardier for repair instructions, repair using a method approved by the Manager, New

York Aircraft Certification Office (ACO), ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO).

(2) Modify the wiring harness routing, in accordance with the Accomplishment Instructions of Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014.

(h) Definition of General Visual Inspection

For the purposes of this AD, a general visual inspection is a visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-32, dated September 8, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0929-0002>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier, Inc. Service Bulletin 100-24-24, dated June 6, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 30, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-08 The Boeing Company: Amendment 39-18324; Docket No. FAA-2014-0436; Directorate Identifier 2014-NM-010-AD.

(a) Effective Date

This AD is effective January 4, 2016.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks in fuselage frames, and a report of a missing strap that was not installed on a fuselage frame during production. We are issuing this AD to detect and correct missing fuselage frame straps and frame cracking that can result in severed frames. Continued operation of the airplane with multiple adjacent severed frames, or the combination of a severed frame and fuselage skin chemical mill cracks, can result in uncontrolled decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Actions for Group 1 Airplanes

For airplanes identified as Group 1 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: At the applicable time specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as provided by

paragraph (n)(1) of this AD, do the inspection for cracking of the frames and applicable repairs using a method approved in accordance with the procedures specified in paragraph (q) of this AD.

(h) Groups 2 Through 7 Airplanes: Inspection for Strap Installation at Station 312

For airplanes identified as Groups 2 through 7 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: At the applicable time specified in tables 2 and 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as provided by paragraph (n)(1) of this AD, do a general visual inspection of the frame at station 312 to determine if the strap adjacent to stringer S-22 right is installed, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013. If the strap is not installed, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (q) of this AD.

(i) Groups 2 Through 6 Airplanes With Less Than 28,300 Total Flight Cycles: Repetitive Inspections, Related Investigative Actions, and Corrective Actions at Stations 328, 344, and 360

For airplanes identified as Groups 2 through 6 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, that have accumulated less than 28,300 total flight cycles as of the effective date of this AD: Do the actions required by paragraphs (i)(1) and (i)(2) of this AD. Operators may do the repair of the frame at station 328 as specified in paragraph (m) of this AD as an optional preventive modification for that frame.

(1) At the applicable times specified in tables 4, 5, 7, and 8 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as provided by paragraphs (n)(1) and (n)(3) of this AD: Do detailed and eddy current inspections of the frame at stations 328, 344, and 360, as applicable, for cracking or a severed frame web; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as specified in paragraph (n)(2) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the applicable inspections thereafter at the applicable time and intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, until the inspection required by paragraph (i)(2) of this AD is done.

(2) At the applicable time specified in tables 4, 5, 7, and 8 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, do the actions specified in paragraph (i)(2)(i) or (i)(2)(ii) of this AD. Accomplishing the initial inspections required by paragraph (i)(2) of this AD terminates the inspections required by paragraph (i)(1) of this AD.

(i) Do detailed and eddy current inspections of the frame at stations 328, 344, and 360, as applicable, for cracking or a severed frame web; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as specified in paragraph (n)(2) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections specified in this paragraph thereafter at the applicable time and intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013.

(ii) Do detailed and eddy current inspections of the frame at stations 328, 344, and 360, as applicable, for cracking or a severed frame web; and external detailed and eddy current inspections of the fuselage skin for cracking; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as specified in paragraph (n)(2) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections specified in this paragraph thereafter at the applicable time and intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013.

(j) Groups 2 Through 6 Airplanes With 28,300 Total Flight Cycles or More: Repetitive Inspections, Related Investigative Actions, and Corrective Actions at Stations 328, 344, and 360

For airplanes identified as Groups 2 through 6 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, that have accumulated 28,300 total flight cycles or more as of the effective date of this AD: At the applicable times specified in tables 4, 5, 7, and 8 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as provided by paragraphs (n)(1) and (n)(3) of this AD, do the inspections specified in paragraph (j)(1) or (j)(2) of this AD; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as specified in paragraph (n)(2) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the applicable inspections specified in paragraph (j)(1) or (j)(2) of this AD thereafter at the applicable time and intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013. Operators may do the repair of the frame at station 328, as specified in paragraph (m) of this AD, as an optional preventive modification for that frame.

(1) Do detailed and eddy current inspections of the frame at stations 328, 344, and 360, as applicable, for cracking or a severed frame web.

(2) Do detailed and eddy current inspections of the frame at stations 328, 344, and 360, as applicable, for cracking or a severed frame web; and external detailed and eddy current inspections of the fuselage skin for cracking.

(k) Group 7 Airplanes: Repetitive Inspections, Related Investigative Actions, and Corrective Actions at Station 328

For airplanes identified as Group 7 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: At the applicable time specified in table 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as provided by paragraph (n)(1) of this AD, do a detailed inspection and eddy current inspection of the frame at station 328 for cracking or a severed frame web; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as specified in paragraph (n)(2) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections specified in this paragraph thereafter at the applicable time and intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013. Operators may do the repair of the frame at station 328, as specified in paragraph (m) of this AD, as an optional preventive modification for that frame.

(l) Groups 2 Through 5 Airplanes: Repetitive Inspections, Related Investigative Actions, and Corrective Actions at Station 380

For airplanes identified as Groups 2 through 5 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: At the applicable time specified in tables 9 and 10 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as provided by paragraph (n)(1) of this AD, do detailed and eddy current inspections of the frame at station 380 for cracking or a severed frame web; and do all applicable corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as specified in paragraph (n)(2) of this AD. Do all applicable corrective actions before further flight. Repeat the inspections specified in this paragraph thereafter at the applicable time and intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013.

(m) Terminating Actions for Airplanes Identified as Groups 2, 3, 4, 5, 6, and 7

(1) For airplanes identified as Groups 2, 3, 4, 5, and 7 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: Accomplishing the repair or preventive modification of the frame at station 328, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as required by paragraph (n)(2) of this AD, terminates the inspections of that frame required by paragraphs (i), (j), and (k) of this AD.

(2) For airplanes identified as Groups 2, 3, 4, and 5 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: Accomplishing the repair or preventive modification of the frame at station 328 and the preventive modification of the frame at station 360, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as required by paragraph (n)(2) of this AD, terminates the inspections of the frame at station 344 and the fuselage skin inspections required by paragraphs (i) and (j) of this AD.

(3) For airplanes identified as Groups 2, 3, 4, and 5 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: Accomplishing the repair or preventive modification of the frame at station 360, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as required by paragraph (n)(2) of this AD, terminates the inspections of that frame required by paragraphs (i) and (j) of this AD.

(4) For airplanes identified as Group 6 in Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013: Accomplishing the repair or preventive modification of the frame at station 328, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, except as required by paragraph (n)(2) of this AD, terminates the fuselage skin inspections and the station 328 frame inspections required by paragraphs (i) and (j) of this AD.

(n) Exceptions to Service Information

(1) Where Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, specifies a compliance time after the "original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) If any cracking is found during any inspection required by this AD, and Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, specifies to contact Boeing for appropriate action: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (q) of this AD.

(3) The Condition column of Tables 4, 5, 7, and 8 in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, refers to total flight cycles "at the original issue date of this service bulletin." This AD, however, applies to the airplanes with the specified total flight cycles as of the effective date of this AD.

(o) Post-Repair Inspections and Post-Modification Inspections

(1) The post-repair and post-modification inspections specified in tables 13 through 15 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, are not required by this AD.

(2) The post-repair and post-modification inspections specified in Tables 13 through 15 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, may be used in support of compliance with section 121.1109(c)(2) or 129.109(b)(2) of the Federal Aviation Regulations (14 CFR 121.1109(c)(2) or 14 CFR 129.109(b)(2)). The corresponding actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013, are not required by this AD.

(p) Credit for Previous Actions

This paragraph provides credit for repairs of the station 328, 344, 360, and 380 frames in the areas addressed by this AD that have been approved by the Boeing Organization Designation Authorization (ODA) via FAA Form 8100-9 (Statement of Compliance with Airworthiness Standards) prior to the effective date of this AD for the repairs specified in paragraphs (i), (j), (k), and (l) of this AD.

(q) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (r) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(r) Related Information

For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

(s) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1323, dated December 6, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 30, 2015.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-09 Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems): Amendment 39-18325. FAA-2015-0927; Directorate Identifier 2013-NM-172-AD.

(a) Effective Date

This AD becomes effective December 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) flightcrew oxygen mask regulators having part number MC10, MF10, and MF20 series, with serial numbers listed in Appendix 1 of Zodiac Services Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012. These oxygen mask regulators are installed on various transport and small airplanes, certificated in any category, including, but not limited to, the airplanes of the manufacturers specified in paragraphs (c)(1), (c)(2), (c)(3), (c)(4), (c)(5), (c)(6), and (c)(7) of this AD. An oxygen mask regulator having part number MC10-04-127 with serial number 48573 is affected only if it is part of part number MSE101-27 with serial number 7521.

- (1) Airbus.
- (2) ATR–GIE Avions de Transport Régional.
- (3) The Boeing Company.
- (4) Bombardier, Inc.
- (5) Cessna Aircraft Company.
- (6) Gulfstream Aerospace Corporation.
- (7) Gulfstream Aerospace LP.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by a report that improper maintenance on oxygen mask regulators was found. During an inspection of the oxygen test bench, incorrect settings were noticed. This test bench setting discrepancy on the oxygen mask regulator could cause an improper mask dilution schedule. We are issuing this AD to detect and correct affected oxygen mask regulators, which could lead, in case of mask usage at or above 10,000 feet after a depressurization event, to the inhalation of air with improper content of oxygen, due to the bad dilution settings, thereby providing inadequate protection to the affected flightcrew against hypoxia. Hypoxia can start from a headache and drowsiness and lead eventually to unconsciousness with severe consequence in terms of airplane controllability.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 30 days after the effective date of this AD, inspect each flightcrew oxygen mask regulator to identify the part number and serial number, in accordance with the Accomplishment Instructions of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012. A review of airplane maintenance records is acceptable to make the determination as specified in this paragraph, provided those records can be relied upon for that purpose, and each flightcrew oxygen mask regulator can be conclusively identified from that review.

(h) Action for Affected Regulators

If the part number and serial number, identified as required by paragraph (g) of this AD, are listed in Appendix 1 of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012, within 30 days after the effective date of this AD, accomplish the actions specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Replace each affected flightcrew oxygen mask regulator with a part identified in paragraph (h)(1)(i) or (h)(1)(ii) of this AD.

(i) A serviceable part, not having a part number and serial number listed in Appendix 1 of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012.

(ii) A part that has been tested and passed the test in accordance with paragraph 3.A.(4) of the Accomplishment Instructions of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012.

(2) Do the actions specified in paragraphs (h)(2)(i) and (h)(2)(ii) of this AD.

(i) Revise the Emergency Procedures section of the airplane flight manual (AFM) by inserting the statement provided in figure 1 to paragraph (h)(2)(i) of this AD. This may be done by inserting a copy of figure 1 to paragraph (h)(2)(i) of this AD into the AFM.

Figure 1 to Paragraph (h)(2)(i) of This AD

In case of depressurization, both pilots must use the mask regulator on 100% demand or Emergency mode only.

Note 1 to paragraph (h)(2)(i) of this AD: For oxygen over-consumption, refer to applicable airplane type certificate holder limitations, if existing, depending on the airplane configuration and/or flight plan.

Note 2 to paragraph (h)(2)(i) of this AD: It is the operators' responsibility to assess the operational consequences of the oxygen over-consumption and ensure that the operational requirements with regard to supplemental oxygen and crew protective breathing equipment are still done. Operators are expected to amend, as applicable, their operations manual(s) accordingly.

(ii) Fabricate and install a placard on the flightcrew oxygen mask container that states: "USE SELECTOR on "100%" OR "EMERGENCY" ONLY."

(i) Regulator Replacement

Within 12 months after the effective date of this AD, unless already accomplished as specified in paragraph (h)(1) of this AD, replace each affected flightcrew oxygen mask regulator identified in paragraph (h) of this AD with a part identified in paragraph (i)(1) or (i)(2) of this AD. After replacement of all affected flightcrew oxygen mask regulators on an airplane, the actions specified in paragraph (h)(2) of this AD are no longer required, the AFM revision specified in paragraph (h)(2)(i) of this AD may be removed from the AFM, and the placard identified in paragraph (h)(2)(ii) of this AD may be removed from the airplane.

(1) A serviceable part, not having a part number and serial number listed in Appendix 1 of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012.

(2) A part that has been tested and passed the test in accordance with paragraph 3.A.(4) of the Accomplishment Instructions of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g), (h)(1)(ii), and (i)(2) of this AD, if those actions were performed before the effective date of this AD using Zodiac Aerospace Service Bulletin MCF-SBU-35-001, dated October 25, 2012, which is not incorporated by reference in this AD.

(k) Parts Installation Limitation

As of the effective date of this AD, no person may install any flightcrew oxygen mask regulator with a part number and serial number listed in Appendix 1 of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012, on any airplane, unless the regulator has been tested and passed the test, in accordance with paragraph 3.A.(4) of the Accomplishment Instructions of Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012.

(l) Alternative Methods of Compliance (AMOCs)

The Manager, Boston Aircraft Certification Office (ACO), ANE-150, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Ian Lucas, Aerospace Engineer, Boston Aircraft Certification Office, ANE-150, FAA, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7757; fax: 781-238-7170; email: ian.lucas@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2012-0254R1, dated December 21, 2012, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0927-0004>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Zodiac Aerospace Service Bulletin MCF-SBU-35-001, Revision 1, dated December 3, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Zodiac Services, Technical Publication Department, Zodiac Aerotechnics, Oxygen Systems Europe, 61 Rue Pierre Curie–CS20001, 78373 Plaisir Cedex, France; phone: (33) 01 61 24 23 23; fax: (33) 01 30 55 71 61; email: yann.laine@zodiac aerospace.com; Internet: <http://www.zodiac aerospace.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 3, 2015.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-10 The Boeing Company: Amendment 39-18326; Docket No. FAA-2015-0932; Directorate Identifier 2014-NM-205-AD.

(a) Effective Date

This AD is effective December 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-8 series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 747-25-3649, dated July 24, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by a report of improperly installed outboard stowage bin modules in the passenger compartment found during maintenance. Further investigation revealed that certain attachment bracket bushings were missing or had moved out of the holes. We are issuing this AD to prevent detachment of the quick-release pin, which could result in separation of the lateral support tie rod and subsequent detachment of the module and consequent injuries to passengers or flightcrew.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Installation

Within 36 months after the effective date of this AD: Install a spacer on the end of each quick-release pin that attaches the outboard stowage bin module to the lateral support tie rods of the main deck passenger compartment, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-25-3649, dated July 24, 2014.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as

appropriate. If sending information directly to the manager of the Seattle ACO, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (h)(3)(i) and (h)(3)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(i) Related Information

For more information about this AD, contact Stanley Chen, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6585; fax: 425-917-6590; email: stanley.chen@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 747-25-3649, dated July 24, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 4, 2015.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-11 The Boeing Company: Amendment 39-18327; Docket No. FAA-2015-1266; Directorate Identifier 2014-NM-151-AD.

(a) Effective Date

This AD is effective December 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747SR, and 747SP series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder indicating that certain fuselage skin lap joints are subject to widespread fatigue damage. We are issuing this AD to detect and correct fatigue cracking in certain fuselage skin lap joints, which could result in rapid depressurization of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Post-Modification Inspections for Airplane Groups 1 Through 3, 7, and 8

For airplanes identified as Groups 1 through 3, 7, and 8 in Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014: Except as provided by paragraph (m) of this AD, at the applicable time specified in table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, do internal detailed and surface high frequency eddy current (HFEC) inspections for cracks in the skin and internal doubler along the edge fastener rows of the modification, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014. In unrepaired areas, repeat the internal detailed and surface HFEC inspections for cracks in the skin or internal doubler along the edge fastener rows of the modification thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(h) Initial Post-Modification Inspections for Airplane Groups 4 Through 6, and 9 Through 11, With External Doublers Installed as Specified in Boeing Service Bulletin 747-53-2272

For airplanes identified as Groups 4 through 6, and 9 through 11, in Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, with external doublers installed as specified in Boeing Service Bulletin 747-53-2272: Except as provided by paragraph (m) of this AD, at the applicable time specified in table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, do external detailed, low frequency eddy current (LFEC), and HFEC inspections for cracks in the skin and external doubler, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(i) Repetitive Post-Modification Inspections for Airplane Groups 4 Through 6, and 9 Through 11 With External Doublers Installed as Specified in Boeing Service Bulletin 747-53-2272

For airplanes with no crack findings during the inspections required by paragraph (h) of this AD: Do the applicable actions required by paragraphs (i)(1) and (i)(2) of this AD.

(1) For airplanes with less than 15,000 flight cycles since stringer 6 external doublers were installed, as specified in Boeing Service Bulletin 747-53-2272: At the applicable intervals specified in table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, in unrepaired areas, repeat the external detailed and LFEC inspections for cracks in the skin, and the external detailed and HFEC inspections for cracks in the external doubler, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(2) For airplanes with 15,000 or more flight cycles since the stringer 6 external doublers were installed, as specified in Boeing Service Bulletin 747-53-2272: At the applicable intervals specified in table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, in unrepaired areas, do external detailed and LFEC inspections for cracks in the skin; and do internal and external detailed and HFEC inspections for cracks in the skin and external doubler; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(j) Repetitive Post-Modification Inspections for Airplane Groups 4 Through 6, and 9 Through 11 With External Doublers Installed as Specified in Boeing Alert Service Bulletin 747-53A2367

For airplanes identified as Groups 4 through 6, and 9 through 11, in Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, with external doublers installed as specified in Boeing Alert Service Bulletin 747-53A2367: Except as provided by paragraph (m) of this AD, at the applicable time specified in table 5 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, do internal detailed and surface HFEC inspections for cracks in the skin and internal doubler along the edge fastener rows of the modification, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014. In unrepaired areas, repeat the internal detailed and surface HFEC inspections for cracks in the skin or internal doubler along the edge fastener rows of the modification thereafter at the applicable interval specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(k) Repetitive Post-Modification Inspections for Airplane Groups 12 and 13

For airplanes identified as Groups 12 and 13 in Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014: Except as provided by paragraph (m) of this AD, at the applicable time specified in table 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-

53A2367, Revision 5, dated July 8, 2014, do internal detailed and surface HFEC inspections for cracks in the skin and internal doubler along the edge fastener rows of the modification, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014. In unrepaired areas, repeat the internal detailed and surface HFEC inspections for cracks in the skin or internal doubler along the edge fastener rows of the modification thereafter at the applicable interval specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(l) Corrective Actions

If any cracking is found during any inspection required by this AD: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(m) Exception to Boeing Alert Service Bulletin 747-53A2367, Revision 5, Dated July 8, 2014

Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014, specifies a compliance time "after the Revision 5 date of this service bulletin," this AD requires compliance within the specified compliance time "after the effective date of this AD."

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (o) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(o) Related Information

For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: nathan.p.weigand@faa.gov.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-53A2367, Revision 5, dated July 8, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 4, 2015.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-12 ATR–GIE Avions de Transport Régional: Amendment 39-18329. Docket No. FAA-2015-0682; Directorate Identifier 2014-NM-074-AD.

(a) Effective Date

This AD becomes effective December 29, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to ATR–GIE Avions de Transport Régional Model ATR42-200, -300, -320, and -500 airplanes; and Model ATR72-101, -201, -102, -202, -211, -212, and -212A airplanes; certificated in any category; all certified models; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Reason

This AD was prompted by new occurrences of certain cracked main landing gear (MLG) rear hinge pins. We are issuing this AD to detect and correct cracked rear hinge pins, which could lead to MLG structural failure, possibly resulting in collapse of the MLG and consequent injury to the occupants of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Hinge Pin Identification and Replacement for Model ATR72 Airplanes

For Model ATR72 airplanes: Within 12 months after the effective date of this AD, inspect for the serial number of the left-hand (LH) and right-hand (RH) MLG rear hinge pins having part number (P/N) D61000. A review of airplane maintenance records is acceptable in lieu of this identification if the part number and serial number of the LH and RH MLG rear hinge pins can be conclusively determined from that review. If a rear hinge pin having P/N D61000 has a serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable: Within 12 months after the effective date of this AD, replace the pin with a serviceable part as identified in paragraph (h) of this AD, in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable.

(h) Definition of Serviceable Hinge Pin for Model ATR72 Airplanes

For Model ATR72 airplanes: For purposes of paragraph (g) of this AD, a serviceable MLG rear hinge pin is a pin that is specified in paragraph (h)(1) or (h)(2) of this AD.

(1) A hinge pin that is not identified in Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable.

(2) A hinge pin that has been inspected and reconditioned, in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable.

(i) MLG Pin Identification and Replacement for Model ATR72 Airplanes

For Model ATR72 airplanes: At the earlier of the times specified in paragraphs (i)(1) and (i)(2) of this AD, inspect all LH and RH MLG pins for a part number and serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014; as applicable. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number and serial number of the LH and RH MLG pin can be conclusively determined from that review. If any affected MLG pin is found: At the earlier of the compliance times specified in paragraphs (i)(1) and (i)(2) of this AD, replace the MLG with a serviceable MLG as identified in paragraph (j) of this AD, using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or ATR-GIE Avions de Transport Régional's EASA Design Organization Approval (DOA).

(1) No later than the next MLG overhaul scheduled after the effective date of this AD.

(2) Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since installation of the MLG on an airplane since new or since last overhaul, as applicable.

(j) Definition of Serviceable MLG for Model ATR72 Airplanes

For Model ATR72 airplanes: For purposes of paragraph (i) of this AD, a serviceable MLG is one that incorporates pins specified in paragraph (j)(1) or (j)(2) of this AD.

(1) Pins that are not identified in Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014; as applicable.

(2) Pins that have been inspected and reconditioned in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014; as applicable.

(k) MLG Pin Identification and Replacement for Model ATR42 Airplanes

(1) For Model ATR42 airplanes: Within the compliance time identified in paragraph (k)(1)(i) or (k)(1)(ii) of this AD, whichever occurs first, inspect for any LH and RH MLG pins having a part number and serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable. A review of airplane maintenance records is acceptable in lieu of this identification if the part number and serial number of the LH and RH MLG pin can be conclusively determined from that review.

(i) No later than the next MLG overhaul scheduled after the effective date of this AD.

(ii) Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since installation of the MLG on an airplane since new or since last overhaul, as applicable.

(2) If the MLG pin having a part number and serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable; is found to be installed during the identification required by paragraph (k)(1) of this AD, within the compliance time identified in paragraph (k)(1) of this AD, replace the MLG with a serviceable MLG, using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or ATR-GIE Avions de Transport Régional's EASA DOA. A serviceable MLG is a part that has pins as identified in paragraph (k)(2)(i) or (k)(2)(ii) of this AD.

(i) Pins that are not listed in Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable.

(ii) Pins that have been inspected and reconditioned, in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable.

(l) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Messier-Bugatti-Dowty Service Bulletin 631-32-216, dated October 30, 2013, which is not incorporated by reference in this AD.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or ATR-GIE Avions de Transport Régional's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0074, dated March 21, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0682-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (o)(4) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013.

(ii) Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014.

(iii) Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014.

(iv) Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013. Pages 4, 5, and 8 of this service bulletin are the original issue and are dated October 30, 2013.

(v) Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014.

(vi) Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014.

(3) For service information identified in this AD, contact ATR–GIE Avions de Transport Régional, 1, Allée Pierre Nadot, 31712 Blagnac Cedex, France; telephone +33 (0) 5 62 21 62 21; fax +33 (0) 5 62 21 67 18; email continued.airworthiness@atr.fr; Internet <http://www.aerochain.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 12, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-13 Airbus: Amendment 39-18330. Docket No. FAA-2015-0251; Directorate Identifier 2014-NM-200-AD.

(a) Effective Date

This AD becomes effective December 29, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1) through (c)(4) of this AD, certificated in any category, all manufacturer serial numbers.

- (1) Airbus Model A318-111, -112, -121, and -122 airplanes.
- (2) Airbus Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.
- (3) Airbus Model A320-211, -212, -214, -231, -232, and -233 airplanes.
- (4) Airbus Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto Flight; 31, Instruments.

(e) Reason

This AD was prompted by a determination that, in specific flight conditions, the allowable load limits on the vertical tail plane could be reached and possibly exceeded. Exceeding allowable load could result in detachment of the vertical tail plane. We are issuing this AD to prevent detachment of the vertical tail plane and consequent loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Pin Programming Modification

Within 48 months after the effective date of this AD, modify the pin programming to activate the stop rudder input warning (SRIW) logic, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-22-1480, Revision 02, dated March 30, 2015.

(h) Inspection To Determine Part Numbers (P/Ns), Flight Warning Computer (FWC) and Flight Augmentation Computer (FAC) Replacement

Prior to or concurrently with the actions required by paragraph (g) of this AD: Inspect the part numbers of the FWC and the FAC installed on the airplane. If any FWC or FAC having a part number identified in paragraph (h)(1) or (h)(2) of this AD, as applicable, is installed on an airplane, prior to or concurrently with the actions required by paragraph (g) of this AD, replace all affected FWCs and FACs with a unit having a part number identified in paragraph (h)(3) of this AD, in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraph (i) of this AD.

(1) Paragraphs (h)(1)(i) through (h)(1)(xvii) of this AD identify FWCs having part numbers that are non-compatible with the SRIW activation required by paragraph (g) of this AD.

- (i) 350E017238484 (H1D1).
- (ii) 350E053020303 (H2E3).
- (iii) 350E016187171 (C5).
- (iv) 350E053020404 (H2E4).
- (v) 350E017248685 (H1D2).
- (vi) 350E053020606 (H2F2).
- (vii) 350E017251414 (H1E1).
- (viii) 350E053020707 (H2F3).
- (ix) 350E017271616 (H1E2).
- (x) 350E053021010 (H2F3P).
- (xi) 350E018291818 (H1E3CJ).
- (xii) 350E053020808 (H2F4).
- (xiii) 350E018301919 (H1E3P).
- (xiv) 350E053020909 (H2-F5).
- (xv) 350E018312020 (H1E3Q).
- (xvi) 350E053021111 (H2-F6).
- (xvii) 350E053020202 (H2E2).

(2) Paragraphs (h)(2)(i) through (h)(2)(xxxiv) of this AD identify FACs having part numbers that are non-compatible with the SRIW activation required by paragraph (g) of this AD.

- (i) B397AAM0202.
- (ii) B397BAM0101.
- (iii) B397BAM0512.
- (iv) B397AAM0301.
- (v) B397BAM0202.
- (vi) B397BAM0513.
- (vii) B397AAM0302.
- (viii) B397BAM0203.
- (ix) B397BAM0514.
- (x) B397AAM0303.
- (xi) B397BAM0305.
- (xii) B397BAM0515.
- (xiii) B397AAM0404.
- (xiv) B397BAM0406.
- (xv) B397BAM0616.
- (xvi) B397AAM0405.
- (xvii) B397BAM0407.
- (xviii) B397BAM0617.
- (xix) B397AAM0506.
- (xx) B397BAM0507.
- (xxi) B397BAM0618.

- (xxii) B397AAM0507.
- (xxiii) B397BAM0508.
- (xxiv) B397BAM0619.
- (xxv) B397AAM0508.
- (xxvi) B397BAM0509.
- (xxvii) B397BAM0620.
- (xxviii) B397AAM0509.
- (xxix) B397BAM0510.
- (xxx) B397CAM0101.
- (xxxi) B397AAM0510.
- (xxxii) B397BAM0511.
- (xxxiii) B397CAM0102.
- (xxxiv) Soft P/N G2856AAA01 installed on hard P/N C13206AA00.

(3) Paragraphs (h)(3)(i) through (h)(3)(v) of this AD identify the FWCs and FACs having the part numbers that are compatible with SRIW activation required by paragraph (g) of this AD.

(i) For airplane configurations with no sharklet, an FAC having P/N B397BAM0621 (621 hard B).

(ii) For airplanes configured with sharklet A320 and A319, an FAC having P/N B397BAM0622 (622 hard B).

(iii) For airplanes configured with sharklet A321, an FAC having P/N B397BAM0623 (623 hard B).

(iv) For all airplanes configured with an FAC standard CAA01, an FAC having soft P/N G2856AAA02 installed on hard P/N C13206AA00 (CAA02 hard C).

(v) For all airplane configurations, an FWC having P/N 350E053021212 (H2-F7).

(i) Service Information for Actions Required by Paragraph (h) of This AD

Do the actions required by paragraph (h) of this AD in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraphs (i)(1) through (i)(7) of this AD.

(1) Airbus Service Bulletin A320-22-1375, dated January 15, 2014 (FAC 621 hard B).

(2) Airbus Service Bulletin A320-22-1427, Revision 05, including Appendix 01, dated November 24, 2014 (FAC 622 hard B).

(3) Airbus Service Bulletin A320-22-1447, Revision 03, dated April 21, 2015 (FAC CAA02 hard C).

(4) Airbus Service Bulletin A320-22-1454, dated February 12, 2014 (FAC CAA02).

(5) Airbus Service Bulletin A320-22-1461, Revision 07, including Appendix 01, dated March 23, 2015 (FAC 623 hard B).

(6) Airbus Service Bulletin A320-22-1502, dated November 14, 2014 (FAC CAA02).

(7) Airbus Service Bulletin A320-31-1414, Revision 03, dated September 15, 2014 (FWC H-F7).

(j) Exclusion From Actions Required by Paragraphs (g) and (h) of This AD

An airplane on which Airbus Modification 154473 has been embodied in production is excluded from the requirements of paragraphs (g) and (h) of this AD, provided that within 30 days after the effective date of this AD, an inspection of the part numbers of the FWC and the FAC installed on the airplane is done to determine that no FWC having a part number listed in paragraph (h)(1) of this AD, and no FAC having a part number listed in paragraph (h)(2) of this AD, has been installed on that airplane since date of manufacture. A review of airplane maintenance records is acceptable in lieu of this inspection if the part numbers of the FWC and FAC can be conclusively determined from that review. If any FWC or FAC having a part number identified in paragraph (h)(1) or (h)(2) of this AD,

as applicable, is installed on a post-Airbus Modification 154473 airplane: Within 30 days after the effective date of this AD, do the replacement required by paragraph (h) of this AD.

(k) Parts Installation Prohibitions

After modification of an airplane as required by paragraphs (g), (h), and (j) of this AD: Do not install on that airplane any FWC having a part number listed in paragraph (h)(1) of this AD or any FAC having a part number listed in paragraph (h)(2) of this AD.

(l) Later Approved Parts

Installation of a version (part number) of the FWC or FAC approved after the effective date of this AD is an approved method of compliance with the requirements of paragraph (h) or (j) of this AD, provided the requirements specified in paragraphs (l)(1) and (l)(2) of this AD are met.

(1) The version (part number) must be approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(2) The installation must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA.

(m) Credit for Previous Actions

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-22-1480, dated July 9, 2014; or Airbus Service Bulletin A320-22-1480, Revision 01, dated February 6, 2015. This service information is not incorporated by reference in this AD.

(2) This paragraph provides credit for actions required by paragraph (i) of this AD, if those actions were performed before the effective date of this AD using the applicable Airbus service information identified in paragraphs (m)(2)(i) through (m)(2)(xviii) of this AD. This service information is not incorporated by reference in this AD.

(i) Airbus Service Bulletin A320-22-1427, dated January 25, 2013.

(ii) Airbus Service Bulletin A320-22-1427, Revision 01, dated July 30, 2013.

(iii) Airbus Service Bulletin A320-22-1427, Revision 02, dated October 14, 2013.

(iv) Airbus Service Bulletin A320-22-1427, Revision 03, dated November 8, 2013.

(v) Airbus Service Bulletin A320-22-1427, Revision 04, dated February 11, 2014.

(vi) Airbus Service Bulletin A320-22-1447, dated October 18, 2013.

(vii) Airbus Service Bulletin A320-22-1447, Revision 01, dated September 18, 2014.

(viii) Airbus Service Bulletin A320-22-1447, Revision 02, dated December 2, 2014.

(ix) Airbus Service Bulletin A320-22-1461, dated October 31, 2013.

(x) Airbus Service Bulletin A320-22-1461, Revision 01, dated February 25, 2014.

(xi) Airbus Service Bulletin A320-22-1461, Revision 02, dated April 30, 2014.

(xii) Airbus Service Bulletin A320-22-1461, Revision 03, dated July 17, 2014.

(xiii) Airbus Service Bulletin A320-22-1461, Revision 04, dated September 15, 2014.

(xiv) Airbus Service Bulletin A320-22-1461, Revision 05, dated November 13, 2014.

(xv) Airbus Service Bulletin A320-22-1461, Revision 06, dated January 21, 2015.

(xvi) Airbus Service Bulletin A320-31-1414, dated December 19, 2012.

(xvii) Airbus Service Bulletin A320-31-1414, Revision 01, dated March 21, 2013.

(xviii) Airbus Service Bulletin A320-31-1414, Revision 02, dated July 30, 2013.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(3) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0217R1, dated February 26, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0251-0003>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320-22-1375, dated January 15, 2014.

(ii) Airbus Service Bulletin A320-22-1427, Revision 05, including Appendix 01, dated November 24, 2014.

(iii) Airbus Service Bulletin A320-22-1447, Revision 03, dated April 21, 2015.

(iv) Airbus Service Bulletin A320-22-1454, dated February 12, 2014.

(v) Airbus Service Bulletin A320-22-1461, Revision 07, including Appendix 01, dated March 23, 2015.

(vi) Airbus Service Bulletin A320-22-1480, Revision 02, dated March 30, 2015.

(vii) Airbus Service Bulletin A320-22-1502, dated November 14, 2014.

(viii) Airbus Service Bulletin A320-31-1414, Revision 03, dated September 15, 2014.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 9, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-23-14 Fokker Services B.V.: Amendment 39-18332. Docket No. FAA-2014-1048; Directorate Identifier 2014-NM-055-AD.

(a) Effective Date

This AD becomes effective January 4, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports that cracks can occur in the oblique frame 67-2 in the tail section on certain airplanes. We are issuing this AD to detect and correct such cracking, which could lead to failure of the oblique frame 67-2, and consequent loss of the structural integrity of the tail section.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Repair

For airplanes that have accumulated more than 29,000 total flight cycles since the airplane's first flight as of the effective date of this AD: Within 500 flight cycles or 12 months after the effective date of this AD, whichever occurs first, do a one-time detailed inspection of the oblique frame 67-2 for any cracking, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-124, dated January 23, 2014. For the purposes of this AD, a detailed inspection is an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.

(h) Corrective Action

If any cracking is found during the inspection required by paragraph (g) of this AD, before further flight, repair the oblique frame 67-2, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-125, Revision 1, dated February 13, 2014.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington WA 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0039, dated February 20, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-1048-0002>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-53-124, dated January 23, 2014.

(ii) Fokker Service Bulletin SBF100-53-125, Revision 1, dated February 13, 2014.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 11, 2015.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-24-01 Airbus: Amendment 39-18333. Docket No. FAA-2014-0928; Directorate Identifier 2014-NM-040-AD.

(a) Effective Date

This AD becomes effective January 4, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Airbus Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes, all manufacturer serial numbers.

(2) Airbus Model A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 55, Stabilizers.

(e) Reason

This AD was prompted by a report of skin disbonding on a composite side panel of a rudder installed on an A310 airplane. We are issuing this AD to detect and correct the rudder skin disbonding, which could affect the structural integrity of the rudder, and could result in reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Review the Maintenance Records

Within 24 months after the effective date of this AD: Review the maintenance records of the rudder to determine if any composite side shell panel repair has been accomplished on the rudder since first installation on an airplane.

(1) If, based on the maintenance record review, any repair identified in Figure A-GBBAA (Sheet 01 and 02) or Figure A-GBCAA (Sheet 02) of the service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD is found: Within 24 months after the effective date of this AD, do a thermography inspection for repair, damages, and fluid ingress, limited to the repaired areas, in

accordance with the Accomplishment Instructions of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD:

(i) Airbus Service Bulletin A330-55-3043, Revision 1, dated August 20, 2014 (for Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes).

(ii) Airbus Service Bulletin A340-55-4039, Revision 1, dated August 20, 2014 (for Model A340-211, -212, -213, -311, -312, and -313 airplanes).

(iii) Airbus Service Bulletin A340-55-5007, Revision 1, dated August 20, 2014 (for Model A340-541 and -642 airplanes).

(2) For a rudder for which maintenance records are unavailable or incomplete, do the actions specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD:

(i) No later than 3 months before accomplishment of the thermography inspection, as required by paragraph (g)(2)(ii) of this AD, contact Airbus to request related rudder manufacturing data by submitting the serial number of the rudder to Airbus.

(ii) Within 24 months after the effective date of this AD: Do a thermography inspection for any repair on complete side shells to identify and mark any repair, in accordance with the Accomplishment Instructions of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD.

(h) Related Investigative Actions, Corrective Actions, and Repetitive Inspections

After the inspection as required by paragraph (g)(1) or (g)(2) of this AD: At the applicable compliance times specified in paragraph 1.E., "Compliance," of Tables 3, 4A, 4B, 4C, 4D, and 5 of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD, accomplish all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD; except as provided by paragraphs (i)(1) and (i)(2) of this AD. Options provided in the service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD for accomplishing the actions are acceptable for the corresponding requirements of this paragraph provided that the related investigative and corrective actions are done at the applicable times specified in paragraph 1.E., "Compliance," of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD, including applicable repetitive inspection intervals, except as required by paragraphs (i)(1) and (i)(2) of this AD. Thereafter repeat the inspections of the restored and repaired areas at the applicable compliance time specified in paragraph 1.E., "Compliance," of Tables 3, 4A, 4B, 4C, 4D, and 5 of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD.

(i) Exceptions to the Service Information

(1) Where the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD specifies a compliance time relative to the date of the service information, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) If the service information in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD specifies to contact Airbus: At the applicable compliance times specified in paragraph 1.E., "Compliance," of the applicable service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(j) Provisions for Certain Airplanes

Airplanes fitted with a rudder having a serial number (S/N) that is not in the range of S/N TS-1001 through S/N TS-1043 inclusive, S/N TS-2001 through S/N TS-2074 inclusive, S/N TS-3000 through S/N TS-3525 inclusive, S/N TS-4001 through S/N TS-4170 inclusive, S/N TS-6001 through S/N TS-6246 inclusive, or S/N TS-5001 through S/N TS-5138 inclusive, are not affected by the requirements of paragraphs (g) and (h) of this AD provided that it is determined that no repair has been accomplished as described in the procedures identified in Figure A-GBBAA (Sheet 01 and 02) or Figure A-GBCAA (Sheet 02) of the service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD, as applicable, on the composite side shell panel of that rudder since first installation on an airplane.

(k) Parts Installation Limitations

As of the effective date of this AD, no person may install, on any airplane, a rudder, unless the record review and thermography inspection specified in paragraph (g) of this AD has been done on that rudder and thereafter all applicable related investigative actions, repetitive inspections, and corrective actions are done as required by paragraph (h) of this AD, except as provided in paragraph (j) of this AD.

(l) Repair Prohibition

As of the effective date of this AD, no person may accomplish a side shell repair on any rudder using a structure repair manual procedure identified in Figure A-GBBAA (Sheet 01 and 02) or Figure A-GBCAA (Sheet 02) of the service information specified in paragraphs (g)(1)(i) through (g)(1)(iii) of this AD, as applicable, on any airplane.

(m) Credit for Previous Actions

This paragraph provides credit for the actions specified in this AD, if those actions were performed before the effective date of this AD using the service information in paragraphs (m)(1), (m)(2), and (m)(3) of this AD.

- (1) Airbus Service Bulletin A330-55-3043, dated February 7, 2013.
- (2) Airbus Service Bulletin A340-55-4039, dated February 7, 2013.
- (3) Airbus Service Bulletin A340-55-5007, dated February 7, 2013.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager,

International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0033, dated February 4, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0928.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-55-3043, Revision 1, dated August 20, 2014.

(ii) Airbus Service Bulletin A340-55-4039, Revision 1, dated August 20, 2014.

(iii) Airbus Service Bulletin A340-55-5007, Revision 1, dated August 20, 2014.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 9, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.