

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2016-18**

8/22/2016 - 9/4/2016



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2016-01			
2015-25-03	COR	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes
2015-25-06	R 2010-06-04	Airbus	A300 B2-1C, B2-203, B2K-3C, B4-103, B4-203, and B4-2C; A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-605R, B4-620, B-622, and B4-622R airplanes
2015-26-02		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2015-26-03	R 2011-07-10	Bombardier, Inc.	BD-100-1A10 (Challenger 300) airplanes
2015-26-07		The Boeing Company	767-200, -300, -300F series airplanes
Biweekly 2016-02			
2015-25-10	R 2011-24-05	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2015-26-05		Fokker Services B.V.	F.28 Mark 1000, 2000, 3000, and 4000
2015-26-06	R 2004-14-09	Airbus	A320-211, -212, and -231
2015-26-09		ATR-GIE Avions de Transport Régional (ATR)	ATR42-200, -300, -320, and -500
2015-27-01		General Electric Company (GE)	GE90-76B, -77B, -85B, -90B, and -94B
2016-01-02		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2016-01-03		Airbus	A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343; A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313
2016-01-04	R 2005-01-09	The Boeing Company	747-100, -100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series
2016-01-05		The Boeing Company	737-400 series
2016-01-07		Airbus	A319-113 and A319-114; A320-211 and A320-212
2016-01-08	R 2013-13-04	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-01-09		Bombardier, Inc.	DHC-8-400, -401, and -402
2016-01-11	R 98-18-26	Airbus	A320-211, -212, and -231
2016-01-12		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11
2016-01-13		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; and A300 F4-605R, F4-622R, and A300 C4-605R Variant F
2016-01-16	R 2002-23-20	Dassault Aviation	Mystere-Falcon 900
2016-01-17		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702)
Biweekly 2016-03			
2015-25-08	COR	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series airplanes
2015-28-01		Engine Alliance	GP7270 turbofan engines
2016-01-10	R 2004-20-14	Airbus	A300 airplanes
2016-01-18	R 98-20-27	Airbus	A300 airplanes
2016-02-01	R 96-18-06	Airbus	A320-211, -212, and -231 airplanes
2016-02-02		Airbus	A318-111 and -112; A319-111, -112, and -115; A320-214; A321-111, -112, -211, -212, and -213 airplanes
2016-02-03		Airbus	A319-113 and -114; A320-211 and -212 airplanes
2016-02-04		CFM International S.A.	CFM56-5B engines
2016-02-05		Bombardier, Inc.	BD-100-1A10 (Challenger 300) airplanes
2016-03-01		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2016-04			
2016-03-04		Rolls-Royce plc	(RR) RB211-535E4-37, RB211-535E4-B-37, and RB211-535E4-C-37 turbofan engines
2016-03-06	R 2012-18-05	The Boeing Company	DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC 9 34F, DC 9 32F (C-9A, C 9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, MD-90-30 airplanes.
2016-04-01	R 2015-26-02	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2016-04-02	R 2010-26-10	The Boeing Company	747-200C, -200F, -400, -400D, and -400F series airplanes
2016-04-03		The Boeing Company	747-400F series airplanes
Biweekly 2016-05			
2016-04-06		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2016-04-07		The Boeing Company	767-200, -300, -300F, and -400ER series
2016-04-08		The Boeing Company	787-8
2016-04-09		Dassault Aviation	FALCON 900EX and FALCON 2000EX
2016-04-10		ATR-GIE Avions de Transport Régional	ATR42-500 and ATR72-102, -202, -212, and -212A
2016-04-11		General Electric Company	GEEx-1B54, -1B58, -1B64, -1B67, and -1B70
2016-04-17		The Boeing Company	777-200 series
2016-04-18		The Boeing Company	747-100, -200B, -200C, -200F, -300, -400, -400D, and -400F series
2016-04-19		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295
2016-04-20		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series; 757-200, -200PF, -200CB, and -300 series; 767-200, -300, -300F, and -400ER series; 777-200, -200LR, -300, -300ER, and -777F series
2016-04-21	R 2008-26-07	The Boeing Company	DC-8-11, DC-8-12, DC-8-21, DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, DC-8-43, DC-8-51, DC-8-52, DC-8-53, DC-8-55, DC-8F-54, DC-8F-55, DC-8-61, DC-8-62, DC-8-63, DC-8-61F, DC-8-62F, DC-8-63F, DC-8-71, DC-8-72, DC-8-73, DC-8-71F, DC-8-72F, and DC-8-73F
2016-04-22		Fokker Services B.V.	F.27 Mark 200, 300, 400, 500, 600, and 700
2016-04-23		The Boeing Company	787-8
2016-04-24		The Boeing Company	757-200 series
Biweekly 2016-06			
2016-03-03	S 2013-11-13	Rolls-Royce plc	Viper Mk. 521, Viper Mk. 522, and Viper Mk. 601-22 turbojet engines
2016-03-07		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-04-13	S 2015-04-03	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2016-04-16	R 2013-08-23	The Boeing Company	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F
2016-05-02	R 2011-13-11 & R 2013-16-09	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-05-04		Dowty Propellers	R352/6-123-F/1, R352/6-123-F/2, and R410/6-123-F/35
2016-05-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-05-07		Engine Alliance	GP7270 turbofan engine
2016-05-12	R 2012-15-13	The Boeing Company	747-100B SUD, 747-300, 747-400, and 747-400D series, 747-200B series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-06-02		The Boeing Company	737-300, -400, and -500 series
2016-06-03		Airbus	A319-131, -132, and -133, A320-232 and -233, A321-131, -231, and -232
2016-06-04		The Boeing Company	737-300, -400, and -500 series
2016-06-05		The Boeing Company	777-200, -200LR, -300, -300ER, and -777F series
2016-06-06		Quest Aircraft Design, LLC	KODIAK 100
2016-06-07	R 2006-22-15	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2016-06-08		The Boeing Company	787-8 and 787-9
Biweekly 2016-07			
2016-06-10		The Boeing Company	787-8
2016-06-11		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, and CN-235-300
2016-06-12		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-06-13		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-07-03		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747SR, and 747SP series
2016-07-05		The Boeing Company	747-8 series
2016-07-06		BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2016-07-10		The Boeing Company	787-8 and 787-9
Biweekly 2016-08			
2016-06-14		General Electric Company	CF6-80E1
2016-07-02		Honeywell International Inc.	TFE731-4, -4R, -5AR, -5BR, and -5R
2016-07-04		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-07-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2016-07-08		The Boeing Company	DC-9-83 (MD-83)
2016-07-09	R 2011-21-06	BAE SYSTEMS (Operations) Limited	4101
2016-07-12		Airbus	A318-111 and -112, A319-111, -112, -113, -114, and -115; A320-211, -212, and -214; A321-111, -112, -211, -212, and -213
2016-07-14		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-07-15		Dassault Aviation	FALCON 7X
2016-07-16	R 2013-26-08	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2016-07-17	R 97-20-07	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2016-07-18		Airbus Defense and Space S.A.	CN-235-200 and CN-235-300
2016-07-20	R 95-18-08	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2016-07-22		Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-07-25		The Boeing Company	787-8
2016-07-28		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87); and MD-88
2016-07-30		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-07-31	R 2013-22-11	The Boeing Company	747-400 and -400D series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-08-03		The Boeing Company	777-200, -200LR, -300, and -300ER series
2016-08-04		Airbus	A330-223F and -243F
2016-08-05		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000)
2016-08-06		Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2016-08-07		Rolls-Royce plc	RB211-22B-02, RB211-22B (MOD 72-8700), RB211-524B-02, RB211-524B-B-02, RB211-524B2-19, RB211-524B2-B-19, RB211-524B3-02, RB211-524B4-02, RB211-524B4-D-02, RB211-524C2-19, RB211-524C2-B-19, RB211-524D4-19, RB211-524D4-B-19, RB211-524D4X-19, RB211-524D4X-B-19, RB211-524D4-39, RB211-524D4-B-39, RB211-524G2-19, RB211-524G3-19, RB211-524G2-T-19, RB211-524G3-T-19, RB211-524H-36, RB211-524H2-19, RB211-524H-T-36, and RB211-524H2-T-19
Biweekly 2016-09			
2016-08-01		Dassault Aviation	FALCON 7X airplanes
2016-08-09		Pratt & Whitney Division	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650 turbofan engines
2016-08-10		General Electric Company	CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B1F1, CF6-80C2B1F2, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B3F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6-80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80C2L1F, CF6-80C2K1F, CF6-80E1A1, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, and CF6-80E1A4/B turbofan engines
2016-08-11	R 2012-17-13	The Boeing Company	707 airplanes; 720 and 720B series airplanes
2016-08-12		The Boeing Company	787-8 and 787-9 airplanes
2016-08-14	R 2014-03-14	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
Biweekly 2016-10			
2016-07-23		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2016-08-02		Airbus	A320-214, -232, and -233, A321-211 and -231 airplanes
2016-08-13	R 2004-19-11	Airbus	A320-211, -212, -214, -231, -232, and -233
2016-08-15	R 2014-17-51	Bombardier, Inc	CL-600-2B16
2016-09-01		The Boeing Company	777-200 and -300 series
2016-09-03		Dassault Aviation	FALCON 2000, FALCON 2000EX, MYSTERE-FALCON 900 and FALCON 900EX
2016-09-04		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2016-09-05		The Boeing Company	717-200 airplanes
2016-09-06		Airbus	A318-111 and -112, A319-111, -112, -113, -114, and -115, A320-211, -212, and -214, A321-111, -112, -211, -212, and -213
2016-09-07		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-09-08		The Boeing Company	747-8 series airplanes
2016-09-10	R 2007-10-10 R1	Airbus	A300 B4-600, B4-600R, and F4-600R series, A300 C4-605R Variant F airplanes (collectively called A300-600 series airplanes)

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-09-11		Airbus	A330-201, -202, -203, -223, -223F, -243 -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2016-09-12		The Boeing Company	787-8 and 787-9 airplanes
2016-09-13		The Boeing Company	737-300, -400, and -500 series
2016-10-02		The Boeing Company	777-200 and -300 series
Biweekly 2016-11			
2016-10-04		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2016-10-05		The Boeing Company	757-200, -200CB, -200PF, and -300
2016-10-06		Bombardier, Inc.	BD-700-1A10, BD-700-1A11
2016-10-07		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2016-10-08		Airbus	A330-201, -202, -203, -223, and -243, A330-223F and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, and -213, A340-311, -312, and -313, A340-541, A340-642
2016-10-09		The Boeing Company	787-8 and 787-9
2016-10-10	R 2014-20-01	Bombardier, Inc.	CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants)
2016-10-11	R 2015-03-06	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213 -311, -312, -313, -541, and -642
2016-10-12		Fokker Services B.V.	F.28 Mark 0070 and 0100
2016-10-13		Airbus	A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-10-14		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900)
2016-10-16		Dassault Aviation	MYSTERE-FALCON 900, FALCON 900EX, FALCON 2000EX
2016-11-02		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
Biweekly 2016-12			
2016-10-15		Fokker Services B.V.	F.28 Mark 0070 and 0100
2016-11-01		Airbus	A330-201, -202, -203, -223, and -243; A330-223F and -243F; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-541; and A340-642
2016-11-03		The Boeing Company	777-200, -200LR, -300, -300ER, and -777F series
2016-11-04	R 2011-23-05	The Boeing Company	737-300, -400, and -500 series
2016-11-05	R 99-16-01	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R; and A300 C4-605R Variant F
2016-11-06	R 2005-18-18	The Boeing Company	757-200, -200PF, -200CB, and -300 series
2016-11-07		The Boeing Company	777-200 and -300 series
2016-11-08	R 2001-12-18	Airbus Defense and Space S.A.	CN-235; CN-235-100 and -200
2016-11-15		Fokker Services B.V.	F28 Mark 0070 and 0100
2016-11-17		The Boeing Company	787-8
2016-11-18		The Boeing Company	787
2016-11-20		B/E Aerospace	Protective Breathing Equipment (PBE)
2016-11-22		Fokker Services B.V.	F.28 Mark 0070 and 0100
2016-12-03	R 2011-17-10	Fokker Services B.V.	F.28 Mark 1000
Biweekly 2016-13			
2016-11-14		Fokker Services B.V.	F.28 Mark 1000, 2000, 3000, and 4000 airplanes
2016-11-16		The Boeing Company	777-200 and -300 series airplanes
2016-11-19		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-12-04		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2016-12-05	R 2014-15-04	Saab AB, Saab Aeronautics	SAAB 2000 airplanes
2016-12-09	R 2016-09-11	Airbus	A330-201, -202, -203, -223, -223F, -243 -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313 airplanes
2016-12-10	R 2016-09-07	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2016-12-11	R 2008-05-18 R1	The Boeing Company	787-8 airplanes
2016-12-12		Fokker Services B.V.	F.27 Mark 050, 200, 300, 400, 500, 600, and 700 airplanes
2016-12-14		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., and -100 SU; ERJ 170-200 LR, -200 SU, and -200 STD; ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes
2016-12-15	R 2016-07-30	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2016-13-01	R 2016-08-05	Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705); CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000) airplanes
2016-13-02	R 2016-09-04	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2016-13-05		General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, and GE90-94B turbofan engines
Biweekly 2016-14			
2016-13-03	COR	The Boeing Company	767-200, -300, -300F, and -400ER series airplanes
2016-13-05		General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, and GE90-94B turbofan engines
2016-13-06		Saab AB, Saab Aeronautics	340A (SAAB/SF340A), SAAB 340B airplanes
2016-13-08		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes
2016-13-10	R 2012-12-04	The Boeing Company	737-300, -400, and -500 series
2016-13-11	R 2008-05-06	The Boeing Company	737-100, -200, -300, -400, and -500 series
2016-13-12		Rolls-Royce Deutschland GmbH	BR700-710A1-10, BR700-710A2-20, BR700-710C4-11 engines
2016-13-13		Beechcraft Corporation	BAe.125 series 1000A and 1000B, and Hawker 1000 airplanes
2016-13-14		Bombardier, Inc.	DHC-8-400, -401 and -402 airplanes
2016-13-16		The Boeing Company	737-600, -700, -700C, -800, -900, and 900ER series airplanes
2016-14-02	R 2012-18-12	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, 320-211, -212, -214, -231, -232, and -233 airplanes
2016-14-03		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2016-14-04		The Boeing Company	787-8 series
Biweekly 2016-15			
2016-13-09		Bombardier, Inc	CL-600-2B16 (CL-604 Variant)
2016-13-15		Dassault Aviation	FALCON 7X
2016-14-01		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; A340-642
2016-14-07		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440); CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-14-08	R 2015-10-03	Airbus	(Regional Jet Series 705); CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000) A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313; A340-541 and -642
2016-14-09	R 2014-14-06	Airbus	A318-111 and -112; A319-111, -112, -113, -114, and -115; A320-211, -212, and -214; A321-111, -112, -211, -212, and -213
2016-15-01		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
Biweekly 2016-16			
2016-14-01	COR	Airbus	A330-223F and -243F, A330-201, -202, -203, -223, and -243, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, and -213, A340-311, -312, and -313, A340-541, A340-642 airplanes
2016-14-10	S 2013-02-02	CFM International, S.A.	CFM56-3, CFM56-3B, and CFM56-3C turbofan engines
2016-15-03		Bombardier Inc.	BD-700-1A10 and BD-700-1A11
2016-15-04		The Boeing Company	757-200 and -200CB series
2016-15-05		Dassault Aviation	FALCON 900EX and FALCON 2000EX
2016-15-06		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11
2016-15-07		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2016-16-01		Airbus	A330-223F and -243F, A330-201, -202, -203, -223, and -243, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343
2016-16-04		Fokker Services B.V.	F.28 Mark 1000, 2000, 3000, and 4000
2016-16-05		Fokker Services B.V.	F.28 Mark 1000, 2000, 3000, and 4000
2016-16-06		Airbus	A300 B4-603, A300 B4-605R, A300 B4-622R, A310-304, A310-324, and A310-325
Biweekly 2016-17			
2016-16-02		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-16-07	R 2007-21-14 R1	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-16-08		Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2016-16-09	R 2011-10-01	Dassault Aviation	FALCON 7X
2016-16-10		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2016-16-11	R 2010-10-13	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A series; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2016-16-13	R 2016-13-10	The Boeing Company	737-300, -400, and -500 series
2016-16-14	R 2013-20-11	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-16-15		Bombardier, Inc.	DHC-8-400, -401, and -402
2016-17-02		Dassault Aviation	FALCON 900EX; FALCON 2000EX
2016-17-03`	R 2003-25-07 R 2005-13-39	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2016-18			
2016-17-01	S 2006-18-14	Rolls-Royce Deutschland Ltd & Co	Tay 650-15 and Tay 651-54
2016-17-06		The Boeing Company	767-200 and -300 series
2016-17-09		Bombardier, Inc.	CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2016-17-10		The Boeing Company	777-200, 777-200LR, 777-300, 777-300ER, and 777F series
2016-17-11		The Boeing Company	787-8
2016-17-12		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-17-13		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702)
2016-17-15		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2016-17-16		Bombardier, Inc	BD-700-1A10 and BD-700-1A11
2016-17-17		Airbus Defense and Space S.A.	CN-235, CN 235-200, and CN 235-300
2016-18-01		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2016-18-02		The Boeing Company	777-200 and -300ER series
2016-18-03		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2016-18-04	R 2013-24-12	The Boeing Company	747-8 and 747-8F
2016-18-10		International Aero Engines AG (IAE)	V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5
2016-16-01	COR	Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343



2016-17-01 Rolls-Royce Deutschland Ltd & Co KG (formerly Rolls-Royce plc): Amendment 39-18614; Docket No. FAA-2006-25513; Directorate Identifier 99-NE-61-AD.

(a) Effective Date

This AD is effective September 27, 2016.

(b) Affected ADs

This AD supersedes AD 2006-18-14.

(c) Applicability

This AD applies to Rolls-Royce Deutschland Ltd & Co (RRD) KG Tay 650-15 and Tay 651-54 turbofan engines with stage 1 high-pressure turbine (HPT) disks, part number (P/N) JR32013 or P/N JR33838, or stage 1 low-pressure turbine (LPT) disks, P/N JR32318A, installed.

(d) Unsafe Condition

This AD was prompted by RRD review of the cyclic life limit of parts affected by AD 2006-18-14 and the RRD conclusion that the stage 1 HPT disk, P/N JR32013, requires further cyclic life limit reduction. We are issuing this AD to prevent failure of stage 1 HPT disks, P/N JR32013 and P/N JR33838, and stage 1 LPT disk, P/N JR32318A, which could result in an uncontained engine failure and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Re-calculate the cyclic life of stage 1 HPT disks, P/N JR32013, as follows:

(i) If a stage 1 HPT disk, P/N JR32013, was ever operated under a different engine flight plan profile than the engine flight plan profile operated on the last flight, or was ever installed and operated in a different engine model, do the following:

(A) Within 30 days after the effective date of this AD, re-calculate the cyclic life for each stage 1 HPT disk, P/N JR32013. Use the RRD Time Limits Manual (TLM) T-TAY-3RR, Chapter 05, Time Limits, Subject 05-10-01, Task 05-10-01-800-000, Subtask 05-10-01-860-036, paragraph 1(E) or (1)(F), dated September 15, 2014 to re-calculate the cyclic life.

(B) Reserved.

(ii) If you change your flight plan profile or install a stage 1 HPT disk, P/N JR32013 or P/N JR33838, or stage 1 LPT disk, P/N JR32318A, into a different engine model after the effective date of this AD, re-calculate the cyclic life within 30 days of making the change. Use the RRD TLM T-TAY-3RR, Chapter 05, Time Limits, Subject 05-10-01, Task 05-10-01-800-000, Subtask 05-10-01-860-036, paragraph 1(E) or (1)(F), dated September 15, 2014 to re-calculate the cyclic life.

(2) For engines with a stage 1 HPT disk, P/N JR32013, installed, do the following:

(i) Remove from service any stage 1 HPT disk, P/N JR32013, within 100 flight cycles after the effective date of this AD or before exceeding the new, reduced cyclic life limits specified in paragraphs (e)(2)(i)(A) through (e)(2)(i)(E) of this AD, whichever occurs later, as follows:

(A) For RRD Tay 650-15 engines operated under engine flight plan profile A, the new, reduced cyclic life limit is 18,900 flight cycles-since-new (FCSN).

(B) For RRD Tay 650-15 engines operated under engine flight plan profile B, the new, reduced cyclic life limit is 15,500 FCSN.

(C) For RRD Tay 650-15 engines operated under engine flight plan profile C, the new, reduced cyclic life limit is 11,500 FCSN.

(D) For RRD Tay 650-15 engines operated under engine flight plan profile D, the new, reduced cyclic life limit is 9,300 FCSN.

(E) For RRD Tay 651-54 engines operated under any engine flight plan profile, the new, reduced cyclic life limit is 10,873 FCSN.

(ii) Reserved.

(3) For engines with a stage 1 HPT disk, P/N JR33838, or stage 1 LPT disk, P/N JR32318A, installed, do the following:

(i) Remove from service any stage 1 HPT disk, P/N JR33838, or stage 1 LPT disk, P/N JR32318A, before exceeding the cyclic life limits specified in paragraphs (e)(3)(i)(A) through (e)(3)(i)(E) of this AD, as follows:

(A) For RRD Tay 650-15 engines operated under engine flight plan profile A, the cyclic life limit for stage 1 HPT disk, P/N JR33838, and stage 1 LPT disk, P/N JR32318A, is 23,000 FCSN.

(B) For RRD Tay 650-15 engines operated under engine flight plan profile B, the cyclic life limit for stage 1 HPT disk, P/N JR33838, and stage 1 LPT disk, P/N JR32318A, is 21,000 FCSN.

(C) For RRD Tay 650-15 engines operated under engine flight plan profile C, the cyclic life limit for stage 1 HPT disk, P/N JR33838, and stage 1 LPT disk, P/N JR32318A, is 18,000 FCSN.

(D) For RRD Tay 650-15 engines operated under engine flight plan profile D, the cyclic life limit for stage 1 HPT disk, P/N JR33838, and stage 1 LPT disk, P/N JR32318A, is 14,250 FCSN.

(E) For RRD Tay 651-54 engines operated under any engine flight plan profile, the cyclic life limit for stage 1 HPT disk, P/N JR33838, is 14,250 FCSN and the cyclic life limit for stage 1 LPT disk, P/N JR32318A, is 20,000 FCSN.

(ii) Reserved.

(f) Installation Prohibition

After the effective date of this AD, do not install any part identified in paragraph (e) of this AD into any engine, or return any engine to service with any part identified in paragraph (e) of this AD, installed, if the part exceeds the cyclic life limit specified in paragraphs (e)(2) and (e)(3) of this AD.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Philip Haberlen, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7770; fax: 781-238-7199; email: philip.haberlen@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency, AD 2015-0056, dated March 31, 2015, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2006-25513.

(3) Rolls-Royce Deutschland Ltd & Co KG Alert Non-Modification Service Bulletin No. TAY-72-A1821, Revision 1, dated March 26, 2015, which is not incorporated by reference in this AD, can be obtained from Rolls-Royce Deutschland Ltd & Co KG, using the contact information in paragraph (i)(3) of this AD.

(4) RRD TLM T-TAY-5RR, Chapter 05-10-01, dated September 15, 2014.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce Deutschland Ltd & Co KG, Time Limits Manual T-TAY-3RR, Chapter 05, Time Limits, Subject 05-10-01, dated September 15, 2014.

(ii) Reserved.

(3) For Rolls-Royce Deutschland Ltd & Co KG service information identified in this AD, contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, Dahlewitz, 15827 Blankenfelde-Mahlow, Germany; phone: 49-0-33-7086-1064; fax: 49-0-33-7086-3276.

(4) You may view this service information at FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 16, 2016.
Colleen M. D'Alessandro,
Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2016-17-06 The Boeing Company: Amendment 39-18619; Docket No. FAA-2016-4221; Directorate Identifier 2015-NM-167-AD.

(a) Effective Date

This AD is effective September 30, 2016.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 767-200 and -300 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01920SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/59027f43b9a7486e86257b1d006591ee/\\$FILE/ST01920SE_AML.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/59027f43b9a7486e86257b1d006591ee/$FILE/ST01920SE_AML.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01920SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder indicating that the aft pressure bulkhead web to pressure chord joint is subject to widespread fatigue damage. We are issuing this AD to detect and correct cracks in the aft pressure bulkhead web. Such cracking could result in the loss of structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Except as required by paragraph (h) of this AD, at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-53A0268, dated April 1, 2015, perform a surface high frequency eddy current (HFEC) inspection for cracking of the aft pressure bulkhead web at fasteners common to the bulkhead web and pressure chord, around the entire circumference of the pressure chord, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 767-53A0268, dated April 1, 2015. For this AD, Group 2, Configuration 2, as specified in Boeing

Alert Service Bulletin 767-53A0268, dated April 1, 2015, includes airplanes with the aft pressure bulkhead replaced as specified in Boeing Alert Service Bulletin 767-53A0267. Repeat the inspection thereafter at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-53A0268, dated April 1, 2015.

(h) Service Information Exception

Where Boeing Alert Service Bulletin 767-53A0268, dated April 1, 2015, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Crack Repair

If any crack is found during any inspection required by paragraph (g) of this AD, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (j) of this AD. Although Boeing Alert Service Bulletin 767-53A0268, dated April 1, 2015, specifies to contact Boeing for repair instructions, and specifies that action as "RC" (Required for Compliance), this AD requires repair as specified in this paragraph. Installation of a repair terminates the inspections required by paragraph (g) of this AD in the area covered by the repair only.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6447; fax: 425-917-6590; email: wayne.lockett@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 767-53A0268, dated April 1, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 16, 2016.

Dorr M. Anderson,

Acting Manager, Transport Airplane Directorate Aircraft Certification Service.

[FR Doc. 2016-20075 Filed 8-25-16; 8:45 am]



2016-17-09 Bombardier, Inc.: Amendment 39-18622; Docket No. FAA-2016-3990; Directorate Identifier 2015-NM-153-AD.

(a) Effective Date

This AD is effective September 30, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Bombardier, Inc. Model CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by reports of two in-service incidents on Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes regarding a loss of all air data information in the flight deck. We are issuing this AD to prevent air data information loss that may affect continued safe flight.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual (AFM) Revision

Within 30 days after the effective date of this AD, revise the Emergency Procedures section of the AFM to include the information in Emergency Procedure 1., Unreliable Airspeed, of Section 03-19, Emergency Procedures–Unreliable Airspeed, of Chapter 3, Emergency Procedures, in Volume 1 of the Bombardier CRJ Series Regional Jet CL-600-2D15 and CL-600-2D24 AFM CSP C-012, Revision 11A, dated May 25, 2015.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your

request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Assata Dessaline, Aerospace Engineer, Avionics and Services Branch, ANE 172, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7301; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2015-08, dated 28 April, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-3990.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 03-19, Emergency Procedures—Unreliable Airspeed, of Chapter 3, Emergency Procedures, in Volume 1 of the Bombardier CRJ Series Regional Jet CL-600-2D15 and CL-600-2D24 Airplane Flight Manual CSP C-012, Revision 11A, dated May 25, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone: 1-866-538-1247 or direct-dial telephone: 1-514-855-2999; fax 514-855-7401; email: ac.yul@aero.bombardier.com; Internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 17, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-10 The Boeing Company: Amendment 39-18623; Docket No. FAA-2016-0463; Directorate Identifier 2015-NM-155-AD.

(a) Effective Date

This AD is effective September 30, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 777-200, 777-200LR, 777-300, 777-300ER, and 777F series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Unsafe Condition

This AD was prompted by a report of an incident involving a landing in which the pilots needed to input corrections due to airplane yaw and roll to the right; the main landing gear (MLG) aft trunnion pin was later found to be fractured. We are issuing this AD to prevent a fractured MLG aft trunnion pin, which could result in collapse of the MLG and consequent loss of control of the airplane during landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Aft Trunnion Pin Identification

For airplanes on which the original airworthiness certificate or the original export certificate of airworthiness was issued on or before the effective date of this AD: Within 36 months after the effective date of this AD, identify the serial number and marking of the MLG aft trunnion pins, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 777-32A0103, Revision 1, dated December 10, 2015.

(h) MLG Aft Trunnion Pin Replacement

For any MLG aft trunnion pin that begins with serial number "EGL" or "MAL," on which no "BASE METAL INSPECTED" marking is found, replace with a new or serviceable MLG aft trunnion pin within 36 months after the effective date of this AD, in accordance with Part 2 of the

Accomplishment Instructions of Boeing Alert Service Bulletin 777-32A0103, Revision 1, dated December 10, 2015.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install, on any airplane, any MLG aft trunnion pin that begins with serial number "EGL" or "MAL" and is not marked "BASE METAL INSPECTED."

(j) Credit for Previous Actions

(1) This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Multi-Operator Message (MOM) MOM-MOM-15-0303-01B, dated May 13, 2015, which is not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions specified in paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777-32A0103, dated September 11, 2015, which is not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6412; fax: 415-917-6590; email: eric.lin@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777-32A0103, Revision 1, dated December 10, 2015.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone: 206-544-5000, extension 1; fax: 206-766-5680; Internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 17, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-11 The Boeing Company: Amendment 39-18624; Docket No. FAA-2016-8846; Directorate Identifier 2016-NM-046-AD.

(a) Effective Date

This AD is effective September 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787-8 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin B787-81205-SB570012-00, Issue 001, dated March 14, 2013.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report indicating that the engine pylon wiring bracket on certain airplanes was missing a corner relief fillet, which could lead to stress concentration and cracking in the engine pylon wiring bracket. We are issuing this AD to detect and correct cracking in the engine pylon wiring bracket. Such cracking could result in damage to adjacent power feeders, subsequent electrical arcing in a flammable leakage zone, and consequent uncontrollable fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One-Time Inspection and Corrective Actions

Within 88 months after the effective date of this AD: Do a one-time general visual inspection of the engine pylon wiring bracket on the left wing for the presence of an existing corner relief fillet, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB570012-00, Issue 001, dated March 14, 2013. Within 88 months after the effective date of this AD, do all applicable corrective actions specified in paragraph (g)(1) or (g)(2) of this AD.

(1) For airplanes on which the engine pylon wiring bracket has a corner relief fillet, re-identify the part number of the engine pylon wiring bracket, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB570012-00, Issue 001, dated March 14, 2013.

(2) For airplanes on which the engine pylon wiring bracket does not have a corner relief fillet, replace the engine pylon wiring bracket with a new bracket, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB570012-00, Issue 001, dated March 14, 2013.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(i) Related Information

For more information about this AD, contact Fnu Winarto, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6659; fax: 425-917-6590; email: fnu.winarto@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin B787-81205-SB570012-00, Issue 001, dated March 14, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 16, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-12 Airbus: Amendment 39-18625; Docket No. FAA-2016-3696; Directorate Identifier 2015-NM-113-AD.

(a) Effective Date

This AD is effective September 30, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), (c)(3), and (c)(4) of this AD, all manufacturer serial numbers.

- (1) Model A318-111, -112, -121, and -122 airplanes.
- (2) Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.
- (3) Model A320-211, -212, -214, -231, -232, and -233 airplanes.
- (4) Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Reason

This AD was prompted by a report of a partial loss of the no-back brake (NBB) efficiency during endurance qualification tests on the trimmable horizontal stabilizer actuator (THSA). We are issuing this AD to prevent premature wear of the carbon friction disks on the NBB of the THSA, which could lead to reduced braking efficiency in certain load conditions, and, in conjunction with the inability of the power gear train to keep the ball screw in its last commanded position, could result in uncommanded movements of the trimmable horizontal stabilizer and loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection To Determine THSA Part Number and Accumulated Total Flight Cycles

No later than each date specified in paragraphs (g)(1) through (g)(5) of this AD: Inspect the THSA to determine if it has a part number (P/N) 47145-(XXX), and, if any THSA P/N 47145-(XXX) is found, determine the total number of flight cycles accumulated since the THSA's first installation on an airplane, or since the most recent NBB replacement, whichever is later. A review of airplane delivery or maintenance records is acceptable in lieu of this inspection if the part number of the THSA can be conclusively determined from that review. In case maintenance records concerning the

most recent NBB disk replacement are unavailable or incomplete, the total flight cycles accumulated since first installation of the THSA on an airplane apply.

(1) As of the effective date of this AD: The THSA flight-cycle limit (since first installation on an airplane, or since the most recent NBB replacement, whichever is later) is 40,000 total flight cycles.

(2) As of December 31, 2016: The THSA flight-cycle limit (since first installation on an airplane, or since the most recent NBB replacement, whichever is later) is 36,000 total flight cycles.

(3) As of December 31, 2017: The THSA flight-cycle limit (since first installation on an airplane, or since the most recent NBB replacement, whichever is later) is 33,600 total flight cycles.

(4) As of December 31, 2018: The THSA flight-cycle limit (since first installation on an airplane, or since the most recent NBB replacement, whichever is later) is 31,600 total flight cycles.

(5) As of December 31, 2019: The THSA flight-cycle limit (since first installation on an airplane, or since the most recent NBB replacement, whichever is later) is 30,000 total flight cycles.

(h) Replacements

For airplanes with any THSA P/N 47145-(XXX): Do the replacements required by paragraphs (h)(1) and (h)(2) of this AD.

(1) No later than each date specified in paragraphs (g)(1) through (g)(5) of this AD, replace all THSA that have reached or exceeded on each date the corresponding number of flight cycles specified in paragraphs (g)(1) through (g)(5) of this AD. Do the replacement in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1242, Revision 01, dated February 4, 2016. Affected THSAs must be replaced with serviceable THSAs.

(2) As of each date specified in paragraphs (g)(1) through (g)(5) of this AD, and before exceeding the flight cycle limit corresponding to each date, as applicable: Replace each THSA with a serviceable THSA, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1242, Revision 01, dated February 4, 2016.

(i) Definition of Serviceable THSA

For the purposes of this AD: A serviceable THSA is a THSA that has not exceeded the applicable flight-cycle limits, as specified paragraphs (g)(1) through (g)(5) of this AD, since first installation of the THSA on an airplane or since last NBB replacement, whichever is later.

Note 1 to paragraph (i) of this AD: Guidance for NBB disc replacement can be found in UTC Aerospace Systems Service Bulletin 47145-27-17, Revision 1, dated July 21, 2015.

(j) Parts Installation Limitation

As of each date specified in paragraphs (g)(1) through (g)(5) of this AD, as applicable, only installation of a serviceable THSA P/N 47145-(XXX) is allowed on an airplane.

(k) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-27-1242, dated February 9, 2015.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if

requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Special Flight Permits

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0080, dated May 7, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-3696.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (o)(4) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320-27-1242, Revision 01, dated February 4, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-13 Bombardier, Inc.: Amendment 39-18626; Docket No. FAA-2016-6415; Directorate Identifier 2015-NM-178-AD.

(a) Effective Date

This AD is effective October 5, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, certificated in any category, serial numbers 10002 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by two in-service incidents of a loss of all air data information in the flight deck. We are issuing this AD to prevent loss of control when a loss of all air data information has occurred in the flight deck.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual (AFM) Revision

Within 30 days after the effective date of this AD, revise the emergency procedures section of the AFM by incorporating Section 03-19, "Unreliable Airspeed," of Chapter 3, "Emergency Procedures," in the Bombardier CRJ Series Regional Jet Model CL-600-2C10 Airplane Flight Manual CSP B-012, Revision 16A, dated November 6, 2015.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety,

FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2015-20, dated July 21, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6415.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 03-19, "Unreliable Airspeed," of Chapter 3, "Emergency Procedures," in the Bombardier CRJ Series Regional Jet Model CL-600-2C10 Airplane Flight Manual CSP B-012, Revision 16A, dated November 6, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-15 Bombardier, Inc: Amendment 39-18628. Docket No. FAA-2012-1075; Directorate Identifier 2012-NM-111-AD.

(a) Effective Date

This AD is effective October 5, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers 7003 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 05, Periodic inspections.

(e) Reason

This AD was prompted by the need for more stringent inspection requirements for certain affected components. We are issuing this AD to detect and correct fatigue cracking in the affected components, which could result in loss of structural integrity.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance Program or Inspection Program Revision

Within 60 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate the revised inspection requirements specified in the AWLs identified in paragraphs (g)(1) through (g)(12) of this AD. These AWLs are identified in Appendix B–Airworthiness Limitations, of Part 2, Airworthiness Requirements, Revision 10, dated May 10, 2015, of the Bombardier CL-600-2B19 Maintenance Requirements Manual (MRM) CSP A-053.

(1) AWL 52-11-131, "Passenger door–piano hinge half on door side."

(2) AWL 53-11-122, "Windshield center post and bulkhead aft post at FS202.75."

(3) AWL 53-21-118, "Potable water servicing door cut-out and internal structure."

(4) AWL 53-21-129, "Passenger door–piano hinge half on fuselage side."

(5) AWL 53-41-199, "FS409.0+128 vertical posts at BL0.0 and BL18.0 left and right local to WL69.0."

(6) AWL 53-41-200, "FS409.0+128 frame cap aft and fwd splice angles at STR21 left and right."

- (7) AWL 53-41-201, "FS559.0 pressure bulkhead web and cap angle local to BL9.0 and BL18.0 left and right."
- (8) AWL 53-61-156, "Rear pressure bulkhead forward face below floor."
- (9) AWL 54-10-105, "Pylon track and support fitting."
- (10) AWL 54-10-106, "Pylon track and support fitting."
- (11) AWL 57-21-105, "Lower wing skin, between BL0.0 to WS314.0."
- (12) AWL 57-21-112, "Lower wing plank splice joints at BL45.0, WS65.75, and WS148.0."

(h) Initial Compliance Times for AWL Tasks

(1) For tasks with phase-in schedules specified in the AWLs identified in paragraphs (g)(1) through (g)(12) of this AD: The initial compliance times are at the applicable times specified in the applicable AWL, or within 60 days after the effective date of this AD, whichever occurs later, except as specified in paragraph (h)(2) of this AD.

(2) For tasks with no phase-in schedules specified in the AWLs identified in paragraphs (g)(1) through (g)(12) of this AD: The initial compliance times are at the applicable times specified in Appendix B–Airworthiness Limitations, of Part 2, Airworthiness Requirements, Revision 10, dated May 10, 2015, of the Bombardier CL-600-2B19 MRM CSP A-053; or within 1,000 flight cycles after the effective date of this AD; whichever occurs later.

(i) Corrective Action

If any damage (including, but not limited to, cracking, corrosion, and wear) is found during any inspection required by any AWL specified in paragraph (g) of this AD: Before further flight, repair using a method approved by the Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO).

(j) No Alternative Actions or Intervals

After accomplishing the revisions required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used other than those specified in the AWLs identified in paragraphs (g)(1) through (g)(12) of this AD; unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (k) of this AD, or the actions and intervals are approved as part of a repair specified in paragraph (i) of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Previously Approved Repairs: Repairs approved before the effective date of this AD that meet the conditions specified in paragraphs (k)(2)(i), (k)(2)(ii), and (k)(2)(iii) of this AD are acceptable methods of compliance for the repaired area.

(i) The repairs were approved by the Manager, New York ACO, ANE-170, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO.

(ii) The repair approval refers to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2012-13, dated April 10, 2012, and provides an inspection program (inspection threshold, method, and repetitive interval).

(iii) The operator has revised its maintenance or inspection program, as applicable, to include the inspection program (inspection threshold, method, and repetitive interval) for the repair.

(3) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

Refer to MCAI Canadian AD CF-2012-13, dated April 10, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2012-1075.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Appendix B—Airworthiness Limitations, of Part 2, Airworthiness Requirements, of the Bombardier CL-600-2B19 Maintenance Requirements Manual, Revision 10, dated May 10, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; Internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-16 Bombardier, Inc.: Amendment 39-18629. Docket No. FAA-2016-3989; Directorate Identifier 2014-NM-220-AD.

(a) Effective Date

This AD is effective October 5, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category, serial numbers 9002 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by in-service reports of passenger door tensator spring failures, and qualification testing indicating that non-conforming tensator springs could be susceptible to failure prior to reaching their safe-life limit. We are issuing this AD to prevent tensator spring failure, resulting in the inability to open the main passenger door, which could impede evacuation in the event of an emergency.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 30 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate task number 52-11-41-101 as specified in the Temporary Revisions (TRs) identified in paragraphs (g)(1) through (g)(5) of this AD. The compliance time for doing the initial replacement of the passenger door tensator springs with new springs is at the times specified in the applicable TR specified in paragraphs (g)(1) through (g)(5) of this AD, or within 30 days after the effective date of this AD, whichever occurs later. The revision required by this paragraph may be done by inserting copies of the TRs identified in paragraphs (g)(1) through (g)(5) of this AD into the applicable Time Limits/Maintenance Checks manual. When the information in a TR has been included in general revisions of the applicable Time Limits/Maintenance Checks manual, the general revisions may be inserted in the Time Limits/Maintenance Checks manual, and the TR may be removed.

(1) TR 5-2-7, dated June 4, 2014, to Part 2, Section 5-10-11, of Bombardier Global Express XRS BD-700 Time Limits/Maintenance Checks (for Model BD-700-1A10 airplanes).

(2) TR 5-2-10, dated September 9, 2014, to Part 2, Section 5-10-11, of Bombardier Global 5000 GL 5000 Featuring Global Vision Flight Deck–Time Limits/Maintenance Checks (for Model BD-700-1A11 airplanes).

(3) TR 5-2-10, dated September 9, 2014, to Part 2, Section 5-10-11, of Bombardier Global 6000 GL 6000 Time Limits/Maintenance Checks (for Model BD-700-1A10 airplanes).

(4) TR 5-2-13, dated June 4, 2014, to Part 2, Section 5-10-11, of Bombardier Global 5000 BD-700 Time Limits/Maintenance Checks (for Model BD-700-1A11 airplanes).

(5) TR 5-2-44, dated June 4, 2014, to Part 2, Section 5-10-11, of Bombardier Global Express BD-700 Time Limits/Maintenance Checks (for Model BD-700-1A10 airplanes).

(h) No Alternative Actions and Intervals

After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) and intervals may be used unless the actions and intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k)(1) of this AD.

(i) Replacement

For airplanes identified in section 1.A., "Effectivity," of Bombardier Global 5000 Service Bulletin 700-1A11-52-023, dated October 4, 2013; or Bombardier Global Express/Global Express XRS Service Bulletin 700-52-046, dated October 4, 2013; except as provided by paragraph (j)(1) or (j)(2) of this AD: Within 15 months after the effective date of this AD, but not exceeding the applicable life limit of the passenger tensator spring identified in the applicable TR specified in paragraphs (g)(1) through (g)(5) of this AD, replace the passenger door tensator springs having part number (P/N) GS321-0580-1, with new springs, in accordance with the Accomplishment Instructions of Bombardier Global 5000 Service Bulletin 700-1A11-52-023, dated October 4, 2013; or Bombardier Global Express/Global Express XRS Service Bulletin 700-52-046, dated October 4, 2013; as applicable.

(j) Acceptable Alternative Actions for Paragraph (i) of This AD

(1) For airplanes having serial numbers (S/N) 9278 through 9360 inclusive: Replacement of the passenger door tensator springs having P/N GS321-0580-1 with new springs before the effective date of this AD is acceptable for compliance with the requirements of paragraph (i) of this AD. Refer to the task specified in the applicable TRs identified in paragraphs (g)(1) through (g)(5) of this AD for subsequent spring replacements.

(2) For airplanes with serial numbers other than those identified in paragraph (j)(1) of this AD: Accomplishment after the effective date of this AD of the "Time Limits/Maintenance Checks" discard task identified in the applicable service information specified in paragraphs (g)(1) through (g)(5) of this AD is acceptable for compliance with the requirements of paragraph (i) of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing

Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2014-39, dated November 4, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-3989.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Temporary Revision 5-2-7, dated June 4, 2014, to Part 2, Section 5-10-11, of Bombardier Global Express XRS BD-700 Time Limits/Maintenance Checks.

(ii) Temporary Revision 5-2-10, dated September 9, 2014, to Part 2, Section 5-10-11, of Bombardier Global 5000 GL 5000 Featuring Global Vision Flight Deck—Time Limits/Maintenance Checks.

(iii) Temporary Revision 5-2-10, dated September 9, 2014, to Part 2, Section 5-10-11, of Bombardier Global 6000 GL 6000 Time Limits/Maintenance Checks.

(iv) Temporary Revision 5-2-13, dated June 4, 2014, to Part 2, Section 5-10-11, of Bombardier Global 5000 BD-700 Time Limits/Maintenance Checks.

(v) Temporary Revision 5-2-44, dated June 4, 2014, to Part 2, Section 5-10-11, of Bombardier Global Express BD-700 Time Limits/Maintenance Checks.

(vi) Bombardier Global Express/Global Express XRS Service Bulletin 700-52-046, dated October 4, 2013.

(vii) Bombardier Global 5000 Service Bulletin 700-1A11-52-023, dated October 4, 2013.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-17-17 Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.): Amendment 39-18630; Docket No. FAA-2016-5467; Directorate Identifier 2015-NM-186-AD.

(a) Effective Date

This AD is effective October 5, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Defense and Space S.A. (formerly known as Construcciones Aeronauticas, S.A.) Model CN-235, CN 235-200, and CN 235-300 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by reports of main landing gear (MLG) access doors detaching from the airplane as a result of excessive vibration and metal fatigue in the attach fittings. We are issuing this AD to prevent a fracture in the MLG access door associated with excessive vibration and metal fatigue in the attach fittings. This condition could lead to MLG access door detachment and consequent impact of flight controls, resulting in reduced control of an airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modifications

(1) For all airplanes: Within 12 months after the effective date of this AD, modify each MLG access door by installing an improved fairing seal, in accordance with the Accomplishment Instructions of EADS CASA Service Bulletin SB-235-52-0068, Revision 2, dated January 9, 2015.

(2) For all Model CN-235-200 airplanes: Concurrently with the action required in paragraph (g)(1) of this AD, modify each affected MLG access door by installing an additional bolt, in accordance with the Accomplishment Instructions of EADS CASA Service Bulletin SB-235-52-0061, Revision 1, dated October 24, 2014.

(h) Credit for Previous Actions

(1) This paragraph provides credit for actions required by paragraph (g)(1) of this AD, if those actions were performed before the effective date of this AD, using EADS CASA Service Bulletin SB-235-52-0068, Revision 1, dated October 24, 2014; or SB-235-52-0068, dated July 15, 2002.

(2) This paragraph provides credit for actions required by paragraph (g)(2) of this AD, if those actions were performed before the effective date of this AD using EADS CASA Service Bulletin SB-235-52-0061, dated October 31, 1996.

(i) Parts Installation Prohibition and Limitation

(1) For airplanes modified as specified in paragraphs (g)(1) and (g)(2) of this AD, as applicable, before the effective date of this AD: As of the effective date of this AD, no person may install a seal having part number CAN36032R on any MLG access door.

(2) For airplanes not modified as specified in paragraphs (g)(1) and (g)(2) of this AD, as applicable, before the effective date of this AD: After accomplishing the actions required by paragraphs (g)(1) and (g)(2) of this AD, as applicable, no person may install a seal having part number CAN36032R on any MLG access door.

(3) As of the effective date of this AD, installation of an MLG access door on an airplane is allowed, provided the MLG access door is modified as required by paragraphs (g)(1) and (g)(2) of this AD, as applicable.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus Defense and Space S.A.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015-0225, dated November 18, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5467.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) EADS CASA Service Bulletin SB-235-52-0061, Revision 1, Dated October 24, 2014.

(ii) EADS CASA Service Bulletin SB-235-52-0068, Revision 2, dated January 9, 2015.

(3) For service information identified in this AD, contact EADS-CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain; telephone +34 91 585 55 84; fax +34 91 585 55 05; email MTA.TechnicalService@casa.eads.net; Internet <http://www.eads.net>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-18-01 The Boeing Company: Amendment 39-18631; Docket No. FAA-2015-8133; Directorate Identifier 2015-NM-101-AD.

(a) Effective Date

This AD is effective October 5, 2016.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015.

(2) Installation of Supplemental Type Certificate (STC) ST00830SE (http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/184DE9A71EC3FA5586257EAE00707DA6?OpenDocument&Highlight=st00830se) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST00830SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Unsafe Condition

This AD was prompted by reports of heavy corrosion and chrome damage of the forward and aft trunnion pin assemblies of the right and left main landing gears (MLGs). We are issuing this AD to detect and correct heavy corrosion and chrome damage of the forward and aft trunnion pin assemblies of the right and left MLGs, which could result in cracking of these assemblies and collapse of the MLGs.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Lubrication of MLG Trunnion Pin Assemblies

For airplanes in Groups 1 and 2, Configuration 1, and airplanes in Group 3, as identified in Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015: Except as required by paragraph (k) of this AD, at the applicable time specified in Table 1 or Table 2 of paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1,

dated May 29, 2015, lubricate the forward and aft trunnion pin assemblies of the left and right MLGs, in accordance with Work Package 1 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015. Repeat the lubrication thereafter at intervals not to exceed those specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015. Accomplishment of the actions specified in paragraph (i) of this AD terminates the repetitive lubrication required by this paragraph.

(h) Repetitive Inspections, Corrective Actions, and Lubrication

For airplanes in Groups 1 and 2, Configuration 1, and airplanes in Group 3, as identified in Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015: Except as required by paragraph (k) of this AD, at the applicable time specified in Table 1 or Table 2 of paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015, do a general visual inspection of the left and right MLGs at the forward and aft trunnion pin locations and the visible surfaces of the forward and aft trunnion pin assemblies for signs of corrosion or chrome plating damage and lubricate the forward and aft trunnion pin assemblies, in accordance with Work Package 2 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015. Repeat the general visual inspection thereafter at intervals not to exceed those specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015. If any discrepancy is found during any inspection required by this paragraph, before further flight, do all applicable related investigative and corrective actions in accordance with Work Package 2 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737 32-1448, Revision 1, dated May 29, 2015. Accomplishment of the actions required by paragraph (i) of this AD terminates the repetitive inspections required by this paragraph.

(i) Modification of MLG Trunnion Pin Assemblies

For airplanes in Groups 1 and 2, Configuration 1, and airplanes in Group 3, as identified in Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015: Except as required by paragraph (k) of this AD, at the applicable time specified in Table 1 or Table 2 of paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015, modify and lubricate the left and right MLG trunnion pin assemblies, and do all applicable related investigative and corrective actions, in accordance with Work Package 3 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015. Accomplishment of the actions in Work Package 3 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015, terminates the repetitive lubrication required by paragraph (g) of this AD and the repetitive inspections required by paragraph (h) of this AD.

(j) Replacement of MLG Forward Trunnion Pin Housing Assembly, Seal, and Retainer

For airplanes in Groups 1 and 2, Configuration 2, as identified in Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015: At the applicable time specified in Table 3 of paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015, replace the seal, retainer, and support ring assembly with a new seal and retainer configuration; install the forward trunnion pin assembly into the housing assembly; and lubricate the forward and aft trunnion pin assemblies for the left and right MLGs; in accordance with Work Package 4 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015.

(k) Exception to Service Information Specification

Where paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015, specifies a compliance time "from the original issue date on this service bulletin," this AD requires compliance within the specified compliance time "after the effective date of this AD."

(l) Credit for Previous Actions

This paragraph provides credit for the requirements of paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 737-32-1448, dated May 19, 2011, which is not incorporated by reference in this AD.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (n)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(n) Related Information

(1) For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Branch, ANM-120S, FAA Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6450; fax: 425-917-6590; email: alan.pohl@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (o)(4) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 737-32-1448, Revision 1, dated May 29, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-18-02 The Boeing Company: Amendment 39-18632; Docket No. FAA-2016-9047; Directorate Identifier 2016-NM-092-AD.

(a) Effective Date

This AD is effective September 15, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777-200 and -300ER series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 777-35-0041, dated April 8, 2016.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Unsafe Condition

This AD was prompted by a determination that the low-pressure oxygen flex hoses in the gaseous passenger oxygen system in airplanes equipped with therapeutic oxygen can potentially be conductive. We are issuing this AD to prevent electrical current from passing through the low-pressure oxygen flex hoses in the gaseous passenger oxygen system, which can cause the flex hoses to melt or burn, and a consequent oxygen-fed fire in the passenger cabin.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 72 months after the effective date of this AD: Replace the low-pressure oxygen flex hoses with new non-conductive low-pressure oxygen flex hoses in the gaseous passenger oxygen system in airplanes equipped with therapeutic oxygen, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-35-0041, dated April 8, 2016.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane a low-pressure oxygen flex hose having a part number that is specified to be removed from an airplane in the

Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-35-0041, dated April 8, 2016.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or sub-step is labeled "RC Exempt," then the RC requirement is removed from that step or sub-step. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Susan Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA; phone: 425-917-6457; fax: 425-917-6590; email: susan.l.monroe@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 777-35-0041, dated April 8, 2016.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-18-03 Bombardier, Inc.: Amendment 39-18633; Docket No. FAA-2016-6414; Directorate Identifier 2015-NM-175-AD.

(a) Effective Date

This AD is effective October 6, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category, serial numbers 7003 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by two in-service incidents of a loss of all air data information in the flight deck. We are issuing this AD to prevent loss of control when a loss of all air data information has occurred in the flight deck.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual (AFM) Revision

Within 30 days after the effective date of this AD, revise the emergency procedures section of the AFM by incorporating Section 03-19, "Unreliable Airspeed", of Chapter 3, "Emergency Procedures," in the Bombardier CRJ Series Regional Jet Model CL-600-2B19 Airplane Flight Manual CSP A-012, Revision 64B, dated December 8, 2015.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety,

FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2015-12, dated June 23, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6414.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 03-19, "Unreliable Airspeed," of Chapter 3, "Emergency Procedures," in the Bombardier CRJ Series Regional Jet Model CL-600-2B19 Airplane Flight Manual CSP A-012, Revision 64B, dated December 8, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 19, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-18-04 The Boeing Company: Amendment 39-18634; Docket No. FAA-2016-3702; Directorate Identifier 2015-NM-103-AD.

(a) Effective Date

This AD is effective October 6, 2016.

(b) Affected ADs

This AD replaces AD 2013-24-12, Amendment 39-17686 (78 FR 71989, December 2, 2013) ("AD 2013-24-12").

(c) Applicability

This AD applies to The Boeing Company Model 747-8 and 747-8F airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Unsafe Condition

This AD was prompted by a report of cracked barrel nuts found on a forward engine mount, and by the determination that additional actions are necessary to address the unsafe condition. We are issuing this AD to detect and correct cracked barrel nuts on a forward engine mount, which could result in reduced load capacity of the forward engine mount, separation of an engine under power from the airplane, and consequent loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Repetitive Inspections and Corrective Actions, With Revised Service Information

This paragraph restates the actions required by paragraph (g) of AD 2013-24-12, with revised service information. For airplanes identified in Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015: Except as required by paragraph (h)(1) of this AD, at the time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013, do the inspection specified in paragraph (g)(1) or (g)(2) of this AD, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013; or Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015. Do all applicable related investigative and corrective actions before further flight. Repeat the inspection thereafter at the times specified in paragraph 1.E.,

"Compliance," of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013. As of the effective date of this AD, use only Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015.

(1) Ultrasonic inspection for cracking of the barrel nuts on each forward engine mount, except as required by paragraph (h)(2) of this AD.

(2) Dye penetrant inspection for cracking of the bolts and barrel nuts. Whenever a dye penetrant inspection is done, all the bolts and barrel nuts on that engine mount must be removed and replaced with new or serviceable parts.

(h) Retained Exceptions to Service Information Specifications, With Revised Service Information References

(1) Where Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013; or Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015; specify a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after December 17, 2013 (the effective date of AD 2013-24-12).

(2) Where Appendix B of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013, and Appendix B of Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015, state that alternate instruments and transducers can be used, this AD requires that only equivalent instruments and transducers can be used.

(3) Where Appendix A of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013, and Appendix A of Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015, state to record flight hours and flight cycles, record the flight hours and flight cycles on the airplane and the flight hours and flight cycles for each engine since change or removal.

(i) Retained Reporting and Sending Parts, With Revised Service Information

After any inspection required by paragraph (g) of this AD: Submit a report of the inspection results (both positive and negative), and return all cracked bolts and barrel nuts, at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the information requested in Appendix A of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013, or Appendix A of Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015, except as required by paragraph (h)(3) of this AD. Both the report and all cracked bolts and barrel nuts must be sent to the address specified in Appendix A of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013, or Appendix A of Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015.

(1) For airplanes on which an ultrasonic inspection was done and no cracking was found, do the required actions at the time specified in paragraph (i)(1)(i) or (i)(1)(ii) of this AD, as applicable.

(i) If the inspection was done on or after December 17, 2013 (the effective date of AD 2013-24-12): Submit the report within 10 days after the inspection.

(ii) If the inspection was done before December 17, 2013 (the effective date of AD 2013-24-12): Submit the report within 10 days after December 17, 2013 (the effective date of AD 2013-24-12).

(2) For airplanes on which a dye penetrant inspection was done, do the required actions at the time specified in paragraph (i)(2)(i) or (i)(2)(ii) of this AD, as applicable.

(i) If the inspection was done on or after December 17, 2013 (the effective date of AD 2013-24-12): Submit the report and return all cracked bolts and barrel nuts within 10 days after replacing the bolts and barrel nuts with new or serviceable bolts and barrel nuts in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013; or Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015.

(ii) If the inspection was done before December 17, 2013 (the effective date of AD 2013-24-12): Submit the report and return all cracked bolts and barrel nuts within 10 days after December 17, 2013 (the effective date of AD 2013-24-12).

(j) Retained Paperwork Reduction Act Burden Statement, With No Changes

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid Office of Management and Budget (OMB) Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(k) New Installation or Inspections

At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015, except as required by paragraph (o)(1) of this AD: Do the actions specified in paragraph (k)(1) or (k)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015, except as required by paragraph (o)(2) of this AD.

(1) Install new barrel nuts using the bootstrap installation method identified in Part 1 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015.

(2) Do a general visual inspection to determine the part number (P/N) of the barrel nuts at the forward engine mount. If any barrel nut P/N SL4081C14SP1 is installed, before further flight, do a general visual inspection for gaps of the strut bulkhead and forward engine mount to determine if the nut-by-nut method identified in Part 4 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015, can be used, and do all applicable related investigative and corrective actions. Do all applicable related investigative and corrective actions before further flight, including the nut-by-nut replacement identified in Part 4 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015. If the nut-by-nut replacement identified in Part 4 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015, cannot be accomplished, install new nuts, in accordance with paragraph (k)(1) of this AD.

(l) Maintenance or Inspection Program Revision

Within 30 days after accomplishment of the actions required by paragraph (k) of this AD, or within 30 days after the effective date of this AD, whichever occurs later: Revise the maintenance or inspection program, as applicable, to incorporate Structurally Significant Item (SSI) 54-50-003c specified in Boeing 747-8/-8F Airworthiness Limitations (AWLs), Document Number D011U721-02-01, dated September 2015.

(m) Terminating Action

Accomplishment of the actions required by paragraphs (k) and (l) of this AD terminate the requirements of paragraphs (g) and (i) of this AD.

(n) Parts Installation Prohibition

As of the effective date of this AD, no person may install or reinstall any barrel nut P/N SL4081C14SP1 at the forward engine mount assembly on any airplane; and only P/N SL4750NA may be installed.

(o) New Exceptions to Service Information Specifications

(1) Where Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015, specifies to contact Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (r) of this AD.

(p) No Alternative Actions or Intervals

After the maintenance or inspection program has been revised as required by paragraph (l) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (r) of this AD.

(q) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (k) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 747-71-2332, dated May 30, 2014, which is not incorporated by reference in this AD.

(r) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (s)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2013-24-12 are approved as AMOCs for the corresponding provisions of this AD.

(5) Except as required by paragraph (o)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (r)(5)(i) and (r)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(s) Related Information

(1) For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: Nathan.P.Weigand@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (t)(5) and (t)(6) of this AD.

(t) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on October 6, 2016.

(i) Boeing Service Bulletin 747-71A2329, Revision 1, dated May 28, 2015.

(ii) Boeing Special Attention Service Bulletin 747-71-2332, Revision 1, dated May 28, 2015.

(iii) Boeing 747-8/-8F Airworthiness Limitation (AWL), Document Number D011U721-02-01, dated September 2015.

(4) The following service information was approved for IBR on December 17, 2013 (78 FR 71989, December 2, 2013).

(i) Boeing Alert Service Bulletin 747-71A2329, dated September 27, 2013.

(ii) Reserved.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 19, 2016.

Dorr M. Anderson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-18-10 International Aero Engines AG: Amendment 39-18640; Docket No. FAA-2016-4123; Directorate Identifier 2016-NE-06-AD.

(a) Effective Date

This AD is effective October 7, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to International Aero Engines AG (IAE) V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 engines with either of the following installed:

(1) High-pressure turbine (HPT) stage 1 hub, part number (P/N) 2A5001, with a serial number (S/N) listed in Table 1, Appendix A, of IAE Non-Modification Service Bulletin (NMSB) V2500-ENG-72-0661, Revision 2, dated May 27, 2016; or

(2) HPT stage 2 hub, P/N 2A4802, with an S/N listed in Table 2, Appendix A, of IAE NMSB V2500-ENG-72-0661, Revision 2, dated May 27, 2016.

(d) Unsafe Condition

This AD was prompted by the fracture of the HPT stage 2 hub during flight, which resulted in an in-flight shutdown, undercowl fire, and smoke in the cabin. We are issuing this AD to prevent failure of the HPT stage 1 or HPT stage 2 hubs, which could result in uncontained HPT blade release, damage to the engine, and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Inspect the HPT stage 1 hub, P/N 2A5001, and HPT stage 2 hub, P/N 2A4802, at the next shop visit or as follows, whichever comes first:

(i) For hubs with 0 to 7,000 CSN on the effective date of this AD, before accumulating 13,000 CSN;

(ii) For hubs with 7,001 to 11,000 CSN on the effective date of this AD, within 6,000 cycles from the effective date of this AD or before accumulating 15,000 CSN, whichever occurs first;

(iii) For hubs with 11,001 to 15,500 CSN on the effective date of this AD, within 4,000 cycles from the effective date of this AD or before accumulating 17,000 CSN, whichever occurs first;

(iv) For hubs with 15,501 CSN or more on the effective date of this AD, within 1,500 cycles from the effective date of this AD.

(2) Use Accomplishment Instructions, paragraphs 2.A., 2.C., and 2.D., of IAE NMSB V2500-ENG-72-0661, Revision 2, dated May 27, 2016, to inspect the HPT stage 1 hub, P/N 2A5001.

(3) Use Accomplishment Instructions, paragraphs 2.E., 2.G., and 2H., of IAE NMSB V2500-ENG-72-0661, Revision 2, dated May 27, 2016 to inspect the HPT stage 2 hub, P/N 2A4802.

(4) Remove from service any HPT stage 1 hub, P/N 2A5001, or HPT stage 2 hub, P/N 2A4802, that fails the inspections required by paragraphs (e)(2) and (e)(3) of this AD, and replace with a part that is eligible for installation.

(f) Definition

For the purpose of this AD, a "shop visit" is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(g) Credit for Previous Actions

If you performed inspection and or replacement using IAE NMSB V2500-ENG-72-0661, original issue, dated November 10, 2015 or NMSB V2500-ENG-72-0661, Revision 1, dated February 5, 2016, you met the requirements of paragraphs (e)(2) and (e)(3) of this AD.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(i) Related Information

For more information about this AD, contact Brian Kierstead, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: brian.kierstead@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) International Aero Engines AG Non-Modification Service Bulletin V2500-ENG-72-0661, Revision 2, dated May 27, 2016.

(ii) Reserved.

(3) For International Aero Engines AG service information identified in this AD, contact International Aero Engines AG, 400 Main Street, East Hartford, CT 06118; phone: 800-565-0140; email: help24@pw.utc.com; Internet: <http://fleetcare.pw.utc.com>.

(4) You may view this service information at FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 26, 2016.
Colleen M. D'Alessandro,
Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2016-16-01 Airbus: Amendment 39-18599; Docket No. FAA-2016-5460; Directorate Identifier 2015-NM-188-AD.

(a) Effective Date

This AD becomes effective on September 8, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category, manufacturer serial numbers 1175, 1180, 1287 through 1475 inclusive, 1478, 1480, 1483, and 1506.

(1) Model A330-223F and -243F airplanes.

(2) Model A330-201, -202, -203, -223, and -243 airplanes.

(3) Model A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of a manufacturing defect (i.e., improperly heat-treated materials) that affects the durability of affected parts in the cargo and cabin compartments. We are issuing this AD to prevent crack initiation and propagation, which could result in reduced structural integrity of the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of Affected Structure in the Cargo Compartment

Within 72 months since first flight of the airplane, do an eddy current inspection (i.e., conductivity measurement) of affected structural parts in the cargo compartment to determine if proper heat treatment has been done as identified in, and in accordance with, the Accomplishment Instructions of Airbus Service Bulletin A330-53-3227, dated August 18, 2015.

(h) Replacement of Non-Conforming Parts in the Cargo Compartment

If, during the inspection required by paragraph (g) of this AD, an affected structural part in the cargo compartment is identified to have a measured value greater than 26 megasiemens per meter (MS/m), or greater than 44.8% International Annealed Copper Standard (IACS), before further flight, replace the affected structural part with a serviceable part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3227, dated August 18, 2015.

(i) Repair of Non-Conforming Parts in the Cargo Compartment

If, during the inspection required by paragraph (g) of this AD, an affected structural part in the cargo compartment is identified to have a measured value other than those specified in Figure A-GFAAA, Sheet 01, "Inspection Flowchart," of Airbus Service Bulletin A330-53-3227, dated August 18, 2015, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(j) Inspection of Affected Structure in the Cabin Compartment

Within 72 months since first flight of the airplane, do an eddy current inspection of affected structural parts in the cabin compartment to determine if proper heat treatment has been done as identified in, and in accordance with, the Accomplishment Instructions of Airbus Service Bulletin A330-53-3228, dated August 18, 2015.

(k) Replacement of Non-Conforming Parts in the Cabin Compartment

If, during the inspection required by paragraph (j) of this AD, an affected structural part in the cabin compartment is identified to have a measured value greater than 26 MS/m or greater than 44.8% IACS, before further flight, replace the affected structural part with a serviceable part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3228, dated August 18, 2015.

(l) Repair of Non-Conforming Parts in the Cabin Compartment

If, during the inspection required by paragraph (j) of this AD, an affected structural part in the cabin compartment is identified to have a measured value other than those specified in Figure A-GFAAA, Sheet 01, "Inspection Flowchart," of Airbus Service Bulletin A330-53-3228, dated August 18, 2015, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1138; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight

standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) **Contacting the Manufacturer:** For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) **Required for Compliance (RC):** If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(n) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015-0212, dated November 4, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5460.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on September 8, 2016 (81 FR 51325, August 4, 2016).

(i) Airbus Service Bulletin A330-53-3227, dated August 18, 2015.

(ii) Airbus Service Bulletin A330-53-3228, dated August 18, 2015.

(4) For service information identified in this AD, contact Airbus SAS, Airworthiness Office-EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: airworthiness.A330-A340@airbus.com; Internet: <http://www.airbus.com>.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 24, 2016.

John P. Piccola, Jr.,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.