

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

LARGE AIRCRAFT

BIWEEKLY 2017-17

8/7/2017 - 8/20/2017



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2017-01			
2016-25-01		The Boeing Company	747-400, 747-400D, and 747-400F series; 757-200, -200PF, -200CB, and -300 series; 767-200, -300, -300F, and -400ER series; 767-300 and -300F series; and 767-300 and -300F series
2016-25-07	R 2012-11-15	The Boeing Company	767-200 and -300 series
2016-25-25		BAE (Operations) Limited	4101
2016-25-26		The Boeing Company	MD-90-30
2016-25-27		Airbus	A300 B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R variant F
2016-25-29		The Boeing Company	767-200 and -300 series
2016-25-30		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; A340-642
2016-25-31		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313; A340-541; and A340-642
2016-26-02		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705); and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000)
2016-26-03	R 2013-23-02	Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295
2016-26-05	R 2014-26-08	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2017-01-07		Dassault Aviation	FAN JET FALCON; FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON
2017-01-08		Airbus	20-C5, 20-D5, 20-E5, and 20-F5; MYSTERE-FALCON 50
2016-25-02		The Boeing Company	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342 and -343 airplanes; and Model A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-25-02		The Boeing Company	787-8 series
Biweekly 2017-02			
2016-26-06		The Boeing Company	787-8 airplanes
2016-26-07		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes
2017-01-01	R 2014-05-25	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2017-01-02		The Boeing Company	787-8 and 787-9 airplanes
2017-01-04		Fokker Services B.V.	F28 Mark 0100 airplanes
2017-01-05		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, and CN-235-300 airplanes
2017-01-06		Airbus	A319-115, A319-132, A320-214, A320-232, A321-211, A321-213, and A321-231 airplanes
2017-01-09		The Boeing Company	767-300 and 767-300F series airplanes
2017-01-10		Airbus Defense and Space S.A.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, C-212-CF, C-212-DF, and C-212-DE airplanes
2017-01-11		Airbus	A318, A319, A320, A321 airplanes
Biweekly 2017-03			
No ADs			
Biweekly 2017-04			
2017-01-03	R 2007-11-13	The Boeing Company	717-200 airplanes
2017-01-09	COR	The Boeing Company	767-300 and 767-300F series airplanes
2017-01-11		Airbus	A318, A319, A320, A321 airplanes
2017-02-02	2005-13-30	The Boeing Company	737-100, -200, and -200C series airplanes
2017-02-03		The Boeing Company	767-200, -300, and -400ER series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-02-04		The Boeing Company	747-200B, 747-300, 747-400, 747-400D, and 747-400F series airplanes
2017-02-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-02-08		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes
2017-02-09		The Boeing Company	747-400, -400D, and -400F series airplanes
2017-02-10	R 2013-19-04	The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-03-02	S 2014-16-10	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
Biweekly 2017-05			
2017-02-01		Rolls-Royce plc	Trent 1000-A, Trent 1000-C, Trent 1000-D, Trent 1000-E, Trent 1000-G, and Trent 1000-H turbofan engines
2017-02-12		The Boeing Company	737-300, -400, and -500 series airplanes
2017-03-03	S 2013-05-18	Rolls-Royce plc	RB211 Trent 553-61, RB211 Trent 553A2-61, RB211 Trent 556-61, RB211 Trent 556A2-61, RB211 Trent 556B-61, RB211 Trent 556B2-61, RB211 Trent 560-61, and RB211 Trent 560A2-61 turbofan engines
2017-03-04	R 2012-16-07	The Boeing Company	737-500 series airplanes
2017-04-01		Gulfstream Aerospace Corporation	GVI airplanes
2017-04-02	R 2014-23-06	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2017-04-04	R 2012-16-08	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes
2017-04-05	R 2011-10-17	Airbus	A300 B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, and B4-203 airplanes
2017-04-06		United Instruments, Inc.	5934 series altimeters
2017-04-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2017-04-08	R 2008-13-12 R1	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-04-09	R 2012-22-12	Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-04-10		Airbus	A318, A319, A320, A321 airplanes
2017-04-11		The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-04-12		Embraer	EMB-135, EMB-145 airplanes
2017-04-13		The Boeing Company	747-8 and 747-8F series airplanes
2017-04-15		Learjet Inc.	36A airplanes
2017-05-01		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2017-05-02		Airbus	A318, A319, A320, A321 airplanes
2017-05-06		The Boeing Company	767-200 and -300 series airplanes
2017-05-07		The Boeing Company	777-200 and -300 series airplanes
Biweekly 2017-06			
2017-05-09		CFM International S.A.	CFM56-5B, CFM56-5B/P, CFM56-5B/3, CFM56-5B/2P, CFM56-5B/P1, CFM56-5B/2P1, and CFM56-5B/3B1 engines
2017-05-11	R 2012-08-11	Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-05-10	R 2015-16-02	Airbus	A330-201, A330-202, A330-203, A330-223, A330-243, A330-223F, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes
2017-05-05		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
2017-05-12		Airbus	A318-112; A319-111, -112, -115, -132, and -133; A320-214, -232, and -233; A321-211, -212, -213, -231, and -232 airplanes
Biweekly 2017-07			
2017-06-05		The Boeing Company	DC-6, DC-6A, DC-6B, C-118A, R6D-1, and R6D-1Z airplanes
2017-07-03		Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-06-04		Airbus	A300 B4-603, B4-620, and B4-622; A300 B4-605R and A300 B4-622R; and A300 C4-605R Variant F airplanes
2017-06-02		Fokker Services B.V.	F28 Mark 0100 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-06-10		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-06-09		The Boeing Company	787-8 airplanes
2017-06-01	R 2017-03-04	The Boeing Company	737-500 series airplanes
2017-06-14		The Boeing Company	737-300, -400, and -500 series airplanes
2017-06-13		Textron Aviation Inc.	680 airplanes
2016-25-25	COR	BAE Systems (Operations) Limited	4101 airplanes
2017-06-12		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233 airplanes
Biweekly 2017-08			
2017-08-04	R 2015-03-01	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2017-07-06		Gulfstream Aerospace Corporation	G-1159B airplanes
2017-08-05	R 2016-13-05	General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, and GE90-94B turbofan engines
2017-06-07		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; and A340-642 airplanes
2017-07-03	COR	Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-08-01	R 2013-22-19	Gulfstream Aerospace Corporation	GV and GV-SP airplanes
2017-06-08	R 2006-06-09 R 2012-05-08 R 2012-07-08	Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU; ERJ 170-200 LR, -200 SU, and -200 STD airplanes
2017-07-04	R 2013-24-17	General Electric Company	GE90-110B1 and GE90-115B engines
2017-08-02		Bombardier, Inc.	DHC-8-102, -103, and -106; DHC-8-201 and -202; DHC-8-301, -311, and -315 airplanes
2017-07-05		Airbus	A300 airplanes
Biweekly 2017-09			
2017-07-07		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2017-08-03		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-08-06		General Electric Company	GE90-76B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, and GE90-115B
2017-08-07		Learjet, Inc.	60
2017-08-08		CFE Company	CFE738-1-1B
2017-08-10	R 2017-01-01	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84
2017-08-11	R 2012-04-01	Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17
2017-08-13		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R, and A300 C4-605R Variant F; and A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 F4-605R and F4-622R
2017-09-01		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000)
2016-05-02	R 2011-13-11 R 2011-13-11	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
Biweekly 2017-10			
2017-09-03	R 2013-03-12	Dassault Aviation	MYSTERE-FALCON 50 airplanes
2017-09-04		The Boeing Company	707-100 Long Body, -200, -100B Long Body, and -100B Short Body series; 707-300, -300B, -300C, and -400 series; 720 and 720B series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-09-06 2017-10-01	R 2015-15-03	General Electric Company Dassault Aviation	GENx-1B and GENx-2B turbofan engines FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
Biweekly 2017-11			
2017-09-08		The Boeing Company	787-8 airplanes
2017-09-09		Zodiac Seats California LLC	4157, 4170, and 4184 seating systems
2017-09-10		The Boeing Company	747-400, 747-400D, and 747-400F airplanes
2017-09-11		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-09-12		ATR-GIE Avions de Transport Régional	ATR42-500; ATR72-102, -202, -212, and -212A airplanes
2017-10-04		Embraer S.A.	EMB-120, EMB-120ER, EMB-120FC, EMB-120QC, and EMB-120RT airplanes
2017-10-05		Airbus	A300 airlines
2017-10-06		Rolls-Royce plc	RB211 Trent 768-60, RB211 Trent 772-60, and RB211 Trent 772B-60 turbofan engines
2017-10-07		The Boeing Company	737-400 series airplanes
2017-10-08	R 2009-21-01	The Boeing Company	737-300 series airplanes
2017-10-14	S 2014-07-07	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Series 3101 airplanes
2017-10-15		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes
2017-10-16		The Boeing Company	787-8 and 787-9 airplanes
2017-10-17	R 2014-16-19	Airbus	A330 airplanes
2017-10-18		Airbus	A330-223F, -223, -321, -322, and -323 airplanes
2017-10-21		The Boeing Company	737-300, -400, and -500 series airplanes
2017-10-22		The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-10-23		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-10-24	R 2011-17-09 R 2012-25-12	Airbus	A330 airplanes
2017-10-25		Rolls-Royce Deutschland Ltd & Co KG	Spey 506-14A, Spey 555-15, Spey 555-15H, Spey 555-15N, and Spey 555-15P turbofan engines
2017-11-01		The Boeing Company	737-100, -200, and -200C series airplanes
2017-11-02		The Boeing Company	MD-90-30 airplanes
2017-11-09	R 2017-08-07	Learjet, Inc.	Model 60 airplanes
Biweekly 2017-12			
2017-10-07		The Boeing Company	737-400 series airplanes
2017-10-08	R 2009-21-01	The Boeing Company	737-300 series airplanes
2017-10-13	S 2015-17-19	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2017-10-14	S 2014-07-07	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Series 3101 airplanes
2017-11-04		The Boeing Company	767-200, -300, and -400ER series airplanes
2017-11-07		Airbus	A318, A319, A320, A321 airplanes
2017-11-09	R 2017-08-07	Learjet, Inc.	60 airplanes
2017-11-11		NavWorx, Inc.	ADS600-B and ADS600-EXP ADS-B Universal Access Transceiver units
2017-11-12		Bombardier, Inc.	BD-100-1A10 airplanes
2017-11-13	R 98-13-14	Airbus	A320-211, -212, and -231 airplanes
2017-11-14	R 2011-26-03	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F airplanes
2017-11-15		General Electric Company	CF6-80C2L1F turbofan engines
2017-12-01		The Boeing Company	767-200 series airplanes
2017-12-02		General Electric Company	GENx-1B64, -1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, 1B70/P1, -1B70/P2, -1B70/75/P1, -1B70/75/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76A/P2 engines
Biweekly 2017-13			
2017-11-05		Roll-Royce Corporation	AE 3007C and 3007C1 turbofan engines
2017-11-06	R 2014-05-32	Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-12-03		Pratt & Whitney Division	PW2037, PW2037M, and PW2040 turbofan engines
2017-12-05	R 2007-26-04	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-12-06		Airbus	A300, A310 airplanes
2017-12-07		The Boeing Company	737-800, -900, and -900ER series airplanes
2017-12-08	R 2011-24-06	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes
2017-12-09		Embraer	EMB-135ER, -135BJ, -135KE, -135KL, and -135LR; and EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes
2017-12-10		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-12-11		Bombardier, Inc.	BD-100-1A10 airplanes
2017-12-12		The Boeing Company	757-200, -200PF, and -200CB series airplanes
2017-12-13		Airbus	A320-212, A320-214, A320-232 airplanes
2017-12-14		The Boeing Company	757-200 and -200PF series airplanes
2017-12-15		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000) airplanes
2017-13-01		The Boeing Company	737-300, -400, and -500 series airplanes
2017-13-02		Dassault Aviation	FALCON 7X airplanes
Biweekly 2017-14			
2017-10-19		Rolls-Royce plc	Trent 1000-A2, Trent 1000-C2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2
2017-13-07		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-13-08	R 2015-23-13	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-13-09	R 2014-16-02	Bombardier, Inc.	CL-600-1A11 (CL-600)
2017-13-10	R 2003-18-06	Airbus	A319-131 and -132; A320-231, -232, and -233; A321-131 and -231
2017-13-11		Gulfstream Aerospace Corporation	G-IV
2017-13-12		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-13-13		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2017-13-14		The Boeing Company	777-300ER series
2017-14-01	R 2013-10-03	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2017-14-02		Bombardier, Inc.	DHC-8-401 and DHC-8-402
Biweekly 2017-15			
2017-14-07		International Aero Engines AG	V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5, V2525-D5, V2528-D5, and V2531-E5 turbofan engines
2017-14-08		CFM International S.A.	CFM56-3, -3B, and -3C turbofan engines
2017-14-09		Fokker Services B.V.	F28 Mark 0100 airplanes
2017-14-10		The Boeing Company	MD-11 and MD-11F airplanes
2017-14-11	R 2007-13-08	Airbus	A318, A319, A320, A321 airplanes
2017-14-13		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2017-14-14		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-14-16		Bombardier, Inc.	BD-100-1A10 airplanes
2017-15-01		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series airplanes
2017-15-03	R 2014-08-02	Airbus	A300-B4-601, B4-603, B4-620, and B4-622 airplanes, and A300-B4-605R and B4-622R airplanes
2017-15-04		The Boeing Company	787-8 and 787-9 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2017-16

2017-13-05	R 2013-13-16	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2017-14-15		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2017-15-06	R 97-10-05	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200 and 3101, and Jetstream Model 3201 airplanes
2017-15-10		The Boeing Company	787-9 airplanes
2017-15-11		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2017-15-12		The Boeing Company	737-300, -400, and -500 series airplanes
2017-15-14		Bombardier, Inc.	CL-215-6B11 (CL-415 Variant) airplanes
2017-15-16		Embraer	EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes
2017-15-17		Airbus	A300 B4-605R and B4-622R; A300 C4-605R Variant F; A300 F4-605R and F4-622R airplanes

Biweekly 2017-17

2017-14-12	R 2015-22-06	Airbus	318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-15-08		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000)
2017-16-05		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2017-16-06		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325



2017-14-12 Airbus: Amendment 39-18956; Docket No. FAA-2016-9508; Directorate Identifier 2016-NM-065-AD.

(a) Effective Date

This AD is effective September 22, 2017.

(b) Affected ADs

This AD replaces AD 2015-22-06, Amendment 39-18311 (80 FR 68429, November 5, 2015) (“AD 2015-22-06”).

(c) Applicability

This AD applies to the airplanes, certificated in any category, identified in paragraphs (c)(1) through (c)(4) of this AD, all manufacturer serial numbers.

- (1) Airbus Model A318-111, -112, -121, and -122 airplanes.
- (2) Airbus Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.
- (3) Airbus Model A320-211, -212, -214, -231, -232, and -233 airplanes.
- (4) Airbus Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports that certain maintenance messages were recorded within the post flight report (PFR) that indicated the loss of elevator servo control monitoring performed by spoiler and elevator computer (SEC) 1, SEC 2, or both, during the engine start. We are issuing this AD to prevent an undetected loss of redundancy during flight if an affected SEC cannot control the related elevator servo control(s), possibly resulting in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Airplane Flight Manual (AFM) Revision, With Revised Compliance Language

(1) This paragraph restates the requirements of paragraph (g) of AD 2015-22-06, with revised compliance language. For airplanes equipped with SEC hardware C part number (P/N) B372CAM0100 with software standards 122 (P/N B372CAM0101), 124 (P/N B372CAM0102), or 125 (P/N B372CAM0103), on SEC position 1 or 2, or both: Within 30 days after November 20, 2015 (the effective date of AD 2015-22-06), revise the After Start Normal Procedures section of the AFM to include the statement specified in figure 1 to paragraph (g) of this AD. This may be done by

inserting a copy of this AD or Airbus A318/A319/A320/A321 Temporary Revision TR572, Issue 1.0, dated August 13, 2015, to the Airbus A318/A319/A320/A321 AFM, into the applicable AFM. When a statement identical to that in figure 1 to paragraph (g) of this AD has been included in the After Start Normal Procedures section of the general revisions of the AFM, the general revisions may be inserted into the AFM, and this AD or Airbus A318/A319/A320/A321 Temporary Revision TR572, Issue 1.0, dated August 13, 2015, to the Airbus A318/A319/A320/A321 AFM, may be removed from the AFM.

(2) Inserting a copy of AD 2015-22-06 into the applicable AFM is acceptable for compliance with the requirement of paragraph (g)(1) of this AD. When a statement identical to that in figure 1 to paragraph (g) of this AD has been included in the After Start Normal Procedures section of the general revisions of the AFM, the general revisions may be inserted into the AFM, and AD 2015-22-06 may be removed from the AFM.

Figure 1 to Paragraph (g) of This AD—AFM Temporary Revision

<p>AFTER START NORMAL PROCEDURE</p> <p>After both engines start:</p> <p>Turn OFF then ON SEC 1 and SEC 2 one after the other.</p>

Note 1 to paragraph (g) of this AD: Airbus Operations Engineering Bulletin OEB-50 provides additional information on the subject addressed by this AD.

(h) Retained Parts Installation Limitation, With No Change

This paragraph restates the requirements of paragraph (i) of AD 2015-22-06, with no change. For all airplanes: As of November 20, 2015 (the effective date of AD 2015-22-06), do not install SEC hardware C P/N B372CAM0100 with software standard 122 (P/N B372CAM0101), 124 (P/N B372CAM0102), or 125 (P/N B372CAM0103), on SEC position 1 or 2, or both, on any airplane, unless the AFM of the airplane is revised concurrently with that installation, as required by paragraph (g) of this AD.

(i) New Requirement of This AD: Replacement of Software

Within 3 months after the effective date of this AD, comply with the actions in paragraph (i)(1) or (i)(2) of this AD, as applicable.

(1) For an airplane that has received Airbus modification 39429 (installation of SEC hardware C P/N B372CAM0100) in production: Install SEC software standard 126, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1252, Revision 01, dated February 18, 2016.

(2) For an airplane that has not received Airbus modification 39429 in production: Inspect to determine whether an affected SEC software standard is installed. Do the inspection in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1257, Revision 01, dated January 1, 2017, except as required by paragraph (n) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the SEC C can be conclusively determined from that review. If an affected SEC software standard is found installed, replace the affected software standard using an installation method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(j) New Requirement of This AD: Compliance for Airplanes Having Airbus Modification 161208 Embodied in Production

An airplane on which Airbus modification 161208 has been embodied in production is compliant with the requirements of paragraph (i) of this AD, provided it is determined that no affected SEC software standard, as identified in paragraph (g) of this AD, is installed on that airplane.

(k) New Requirement of This AD: Disposition of AFM After Airplane Modification

After modification of an airplane as required by paragraph (i) of this AD, remove the information specified in Airbus A318/A319/A320/A321 TR572, Issue 1.0, dated August 13, 2015, to the Airbus A318/A319/A320/A321 AFM from the AFM of that airplane.

(l) New Requirement of This AD: Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane an affected SEC software standard, or a SEC hardware C hosting an affected SEC software standard.

(m) New Provision of This AD: Installation of Equivalent Software and Hardware

Installation on an airplane of a SEC software standard, or of a SEC hardware standard, approved after April 1, 2016 (the effective date of EASA AD 2016-0056), is acceptable for compliance with the requirements of paragraph (i) of this AD for that airplane, provided the conditions specified in paragraphs (m)(1) and (m)(2) of this AD are met.

(1) The software and hardware standard, as applicable, is approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA.

(2) Replacement of the affected software standard is done using an installation method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA.

(n) Exceptions to Service Information Specifications

Subtask 271257-832-006-001 of Airbus Service Bulletin A320-27-1257, Revision 01, dated January 1, 2017, includes incorrect instructions. This AD requires that those instructions be followed as specified in paragraphs (n)(1) and (n)(2) of this AD.

(1) For Subtask 271257-832-006-001, instruction “(b)”: If SEC C 126 software P/N B372CAM0104 is found, no further action is required by this AD.

(2) For Subtask 271257-832-006-001, instruction “(c)”: If SEC C 122 software P/N B372CAM0101, SEC C 124 software P/N B372CAM0102, or SEC C 125 software P/N B372CAM0103 is found, do corrective actions using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA.

(o) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (i) of this AD, if those actions were performed before the effective date of this AD using the applicable service information specified in paragraph (o)(1) or (o)(2) of this AD.

(1) For airplanes that have received Airbus modification 39429 (installation of SEC hardware C P/N B372CAM0100) in production: Airbus Service Bulletin A320-27-1252, dated November 6, 2015.

(2) For airplanes that have not received Airbus modification 39429 in production: Airbus Service Bulletin A320-27-1257, dated December 18, 2015.

(p) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (r)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as required by paragraph (n) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(q) Special Flight Permits

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(r) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0056, dated March 18, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9508.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (s)(5) and (s)(6) of this AD.

(s) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on September 22, 2017.

(i) Airbus Service Bulletin A320-27-1252, Revision 01, dated February 18, 2016.

(ii) Airbus Service Bulletin A320-27-1257, Revision 01, dated January 1, 2017.

(4) The following service information was approved for IBR on November 20, 2015 (80 FR 68429, November 5, 2015).

(i) Airbus A318/A319/A320/A321 Temporary Revision TR572, Issue 1.0, dated August 13, 2015, to the Airbus A318/A319/A320/A321 Airplane Flight Manual.

(ii) Reserved.

(5) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 29, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-15-08 Bombardier, Inc.: Amendment 39-18968; Docket No. FAA-2017-0699; Directorate Identifier 2017-NM-004-AD.

(a) Effective Date

This AD becomes effective September 5, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model CL-600-2E25 (Regional Jet Series 1000) airplanes, certificated in any category, serial numbers 19001 through 19048 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 36, Pneumatic.

(e) Reason

This AD was prompted by a report of a possibility that the shrouds of the high pressure bleed air ducts could deteriorate and their maximum permitted leakage rate could be exceeded. We are issuing this AD to prevent a bleed air leak from exceeding the maximum permitted leakage rate, which if not sensed by the detection system, could cause hot air impingement to damage the adjacent structure and system components or create a fire hazard.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

At the earlier of the times specified in paragraphs (g)(1) and (g)(2) of this AD: Modify the bleed-air duct and detection system, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-36-022, Revision B, dated December 20, 2016.

(1) Within 6,600 flight hours or 32 months, whichever occurs first after the effective date of this AD.

(2) Within the next 10,000-flight-hours scheduled maintenance check after the effective date of this AD.

(h) Maintenance or Inspection Program Revision

Within 30 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, by incorporating the service information specified in figure 1 to paragraph (h) of this AD. The initial compliance time for tasks 28-12-00-601 and 28-12-00-602 is at the later of the applicable times specified in the service information specified in figure 1 to paragraph (h) of this AD, or within 30 days after the effective date of this AD, whichever occurs later. The initial compliance times for tasks 25-85-00-101, 36-20-00-101, and 36-20-00-102 are specified in Figure 2 to paragraph (h) of this AD. When these temporary revisions (TRs) have been included in general revisions of the maintenance requirement manual (MRM), the general revisions may be inserted in the MRM, provided the relevant information in the general revision is identical to the TRs specified in figure 1 to paragraph (h) of this AD.

Figure 1 to Paragraph (h) of This AD—Temporary Revisions Maintenance Requirements

Temporary revision	Task No.	Maintenance requirements manual (MRM) part 2 section	Revision date
ALI-0553	25-85-00-101	1-25	August 19, 2016.
ALI-0554	36-20-00-101	1-36	August 19, 2016.
ALI-0555	36-20-00-102	1-36	August 19, 2016.
ALI-0556	28-12-00-601	4-28	August 19, 2016.
ALI-0557	28-12-00-602	4-28	August 19, 2016.

- **Figure 2 to Paragraph (h) of This AD—Initial Compliance Times**

Task No.	Initial compliance time (whichever occurs later)	
25-85-00-101	Before the accumulation of 8,000 total flight hours	Within 30 days after the effective date of this AD.
36-20-00-101	Before the accumulation of 10,000 total flight hours	Within 30 days after the effective date of this AD.
36-20-00-102	Before the accumulation of 10,000 total flight hours	Within 30 days after the effective date of this AD.

(i) No Alternative Actions or Intervals

After the maintenance or inspection program has been revised, as required by paragraph (h) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k)(1) of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA-36-022, dated May 30, 2016; or Bombardier Service Bulletin 670BA-36-022, Revision A, dated September 16, 2016.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2016-35, dated November 16, 2016, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0699.

(2) For more information about this AD, contact Joseph Catanzaro, Aerospace Engineer, Propulsion and Services Branch, ANE-173, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7366; fax 516-794-5531.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 670BA-36-022, Revision B, dated December 20, 2016.

(ii) Bombardier CRJ Series Regional Jet Airworthiness Limitations Temporary Revision ALI-0553, dated August 19, 2016.

(iii) Bombardier CRJ Series Regional Jet Airworthiness Limitations Temporary Revision ALI-0554, dated August 19, 2016.

(iv) Bombardier CRJ Series Regional Jet Airworthiness Limitations Temporary Revision ALI-0555, dated August 19, 2016.

(v) Bombardier CRJ Series Regional Jet Airworthiness Limitations Temporary Revision ALI-0556, dated August 19, 2016.

(vi) Bombardier CRJ Series Regional Jet Airworthiness Limitations Temporary Revision ALI-0557, dated August 19, 2016.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 13, 2017.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-16-05 The Boeing Company: Amendment 39-18982; Docket No. FAA-2016-9112; Product Identifier 2016-NM-091-AD.

(a) Effective Date

This AD is effective September 22, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-57A1327, Revision 1, dated September 28, 2016.

(2) Installation of Supplemental Type Certificate (STC) ST00830SE (http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/354588EE63741A068625807D006726F6?OpenDocument&Highlight=st00830se) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST00830SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of a Krueger flap bullnose departing an airplane during taxi, which caused damage to the wing structure and thrust reverser. We are issuing this AD to detect and correct missing Krueger flap bullnose hardware. Such missing hardware could result in the Krueger flap bullnose departing the airplane during flight, which could damage empennage structure and lead to the inability to maintain continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of the Krueger Flap Bullnose

Within 6 months after the effective date of this AD, do a detailed inspection for discrepancies of the Krueger flap bullnose attachment hardware, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service

Bulletin 737-57A1327, Revision 1, dated September 28, 2016. Do all applicable related investigative and corrective actions before further flight.

(h) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737-57A1327, dated May 20, 2016.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO) Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or sub-step is labeled "RC Exempt," then the RC requirement is removed from that step or sub-step. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

(1) For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6450; fax: 425-917-6590; email: alan.pohl@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-57A1327, Revision 1, dated September 28, 2016.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Standards Branch, 1601 Lind Ave SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 26, 2017.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.



2017-16-06 Airbus: Amendment 39-18983; Docket No. FAA-2016-9052; Product Identifier 2016-NM-080-AD.

(a) Effective Date

This AD is effective September 22, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus airplanes identified in paragraphs (c)(1) through (c)(6) of this AD, certificated in any category, all manufacturer serial numbers.

- (1) Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.
- (2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.
- (3) Model A300 B4-605R and B4-622R airplanes.
- (4) Model A300 F4-605R and F4-622R airplanes.
- (5) Model A300 C4-605R Variant F airplanes.
- (6) Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of failure of an aft hinge bolt assembly in the nose landing gear (NLG) aft doors. We are issuing this AD to prevent failure of an aft hinge bolt assembly in an NLG aft door while the airplane is in flight, which could lead to an in-flight loss of an NLG aft door, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement of Aft Hinge Bolt Assemblies Having Part Number (P/N) A53612600000

Before the accumulation of 10,000 total flight cycles since first flight of the airplane, or within 2,000 flight cycles after the effective date of this AD, whichever occurs later: Replace each aft hinge bolt assembly having P/N A53612600000 on the left and right NLG aft doors, with a new hinge bolt assembly having P/N A53612713000, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

- (1) Airbus Service Bulletin A300-53-0396, dated November 25, 2015.

(2) Airbus Service Bulletin A310-53-2142, dated November 17, 2015.

(3) Airbus Service Bulletin A300-53-6182, dated November 17, 2015.

(h) Replacement of Aft Hinge Bolt Assemblies Having P/N A53612713000

Within 10,000 flight cycles after modification of an airplane as required by paragraph (g) of this AD: Replace each aft hinge bolt assembly having P/N A53612713000 on the left and right NLG aft doors, with a new aft hinge bolt assembly having P/N A53612713000 on the left and right NLG aft doors, in accordance with the Accomplishment Instructions of the applicable service information specified in paragraph (h)(1), (h)(2), or (h)(3) of this AD, except where the service information specified in paragraph (h)(1), (h)(2), or (h)(3) of this AD specifies to contact Airbus for instructions, before further flight repair using the procedure in paragraph (k)(2) of this AD. Repeat the replacement thereafter at intervals not to exceed 10,000 flight cycles.

(1) Airbus Service Bulletin A300-53-0397, dated January 18, 2016.

(2) Airbus Service Bulletin A310-53-2144, dated January 18, 2016.

(3) Airbus Service Bulletin A300-53-6186, dated January 18, 2016.

(i) Parts Installation Prohibition (P/N A53612600000)

After modification of an airplane NLG aft door as required by paragraph (g) of this AD, do not install an aft hinge bolt assembly having P/N A53612600000 on any NLG aft door of that airplane.

(j) Parts Installation Limitation (P/N A53612713000)

After removal of an aft hinge bolt assembly having P/N A53612713000 from an airplane NLG aft door, as required by paragraph (h) of this AD, do not install an aft hinge bolt assembly having that part number on that airplane unless it is a new aft hinge bolt assembly.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy

condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0100, dated May 24, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9052.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A300-53-0396, dated November 25, 2015.

(ii) Airbus Service Bulletin A300-53-0397, dated January 18, 2016.

(iii) Airbus Service Bulletin A300-53-6182, dated November 17, 2015.

(iv) Airbus Service Bulletin A300-53-6186, dated January 18, 2016.

(v) Airbus Service Bulletin A310-53-2142, dated November 17, 2015.

(vi) Airbus Service Bulletin A310-53-2144, dated January 18, 2016.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 26, 2017.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.