

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT**

**BIWEEKLY 2014-13**

*6/16/2014 - 6/29/2014*



Federal Aviation Administration  
Engineering Procedures Office, AIR-110  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

### MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250

# LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
<b>Biweekly 2014-01</b>			
2013-25-04		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2013-25-06		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-01 2013-26-02		CFM International S.A. Bombardier, Inc.	CFM56-3 series and CFM56-7B series turbofan engines CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2013-26-03	S 2011-24-09	Airbus	A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, and A340-642
2013-26-04 2013-26-06	S 2010-19-01	The Boeing Company Rolls-Royce Corporation	747-400, -400D, and -400F series AE 3007A, A1, A1/1, A1/2, A1/3, A1P, A1E, and A3 turbofan engines
2013-26-07		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-08 2013-26-10		The Boeing Company Rolls-Royce plc	737-600, -700, -700C, -800, -900, and -900ER series RB211-524G2-19, RB211-524G3-19, RB211-524H-36, and RB211-524H2-19 turbofan engines
2013-26-12	S 2009-14-02	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
<b>Biweekly 2014-02</b>			
There were no AD's published in this Large Bi-weekly period			
<b>Biweekly 2014-03</b>			
2013-24-04	S 2003-19-11	Learjet Inc.	60
2013-25-03	S 2000-17-05 S 2001-04-09	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-01-04		Bae Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2014-01-05 2014-02-01	S 2011-03-13	The Boeing Company Bombardier, Inc.	737-100, -200, -200C, -300, -400, and -500 series CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
<b>Biweekly 2014-04</b>			
2014-03-07 2014-03-08	S 2009-26-16	The Boeing Company Airbus	MD-11 and MD-11F A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-03-09		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, -500, ATR72-101, -201, -102, -202, -211, -212, and -212A
2014-03-14		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2014-03-16		Rolls-Royce Deutschland Ltd & Co. KG	Tay 620-15, 650-15, and 651-54 turbofan engines
2014-03-17		Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, & CL-604 Variants)
<b>Biweekly 2014-05</b>			
2014-01-03 2014-03-04 2014-03-05 2014-03-06		Saab AB, Saab Aerosystems Bombardier, Inc. Bombardier, Inc. Boeing	340A (SAAB/SF340A) and SAAB 340B DHC-8-400, -401, and -402 BD-700-1A10 737-100, -200, -200C, -300, -400, and -500 series

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2014-03-12	S 2002-23-19	Dassault Aviation	FALCON 2000
2014-03-13		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-03-15	S 2008-14-16	328 Support Services GmbH	328-100, 328-300
2014-03-19		Boeing	737-600, -700, -800, -900, and -900ER series
2014-03-21		Boeing	727-200 and 727-200F series
2014-04-05		Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-04-08		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2014-05-02	S 2002-10-11	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-03		Boeing	777-200, -200LR, -300, -300ER, and -777F series
2014-05-05		Boeing	777-200, -200LR, -300, -300ER, and 777F series
<b>Biweekly 2014-06</b>			
2014-05-09	S 2012-12-08	Boeing	777-200 and -300 series
2014-05-12	S 2010-15-08	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-13	S 2004-12-07	Boeing	757-200, -200PF, and -200CB series
2014-05-16		Boeing	747-200B, 747-300, 747-400, 747-400D, 747-400F, 767-200, -300, -300F, and -400ER series
2014-05-18		Bombardier	DHC-8-400, -401, and -402
2014-05-19		Boeing	747-200B, 747-200F, 747-300, 747SP, 747-400, 747-400F, 767-300 series
2014-05-20		Boeing	757-200, -200PF, -200CB, and -300 series
2014-05-21	S 2008-11-04	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-22		Boeing	717-200
2014-05-23		Bombardier	BD-100-1A10 (Challenger 300)
2014-05-24	S 84-19-01	Boeing	747-100, 747-200B, and 747-200F series
2014-05-25		Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2014-05-30	S 2013-07-07	Boeing	737-600, -700, -700C, -800, -900, and -900ER series
2014-06-02		Boeing	747-400 series
<b>Biweekly 2014-07</b>			
2013-26-14	S 2008-08-04	Airbus	A318, A319, A320, A321
2014-04-09		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-04-10		Airbus	A330, A340 airplanes
2014-05-14		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-05-17		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2014-05-27		Rockwell Collins	Mode S transponders
2014-05-28		Bombardier	DHC-8-400, -401, and -402
2014-05-31	S 2008-08-25	Boeing	747-400F, 747-400 series
2014-05-32		Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2240, PW2337, PW2643, and F117-PW-100 turbofan engines
2014-06-04		Boeing	747-8 and 747-8F series
2014-06-05	S 2007-03-02	Rolls-Royce Deutschland	Tay 620-15, Tay 650-15 and Tay 651-54 turbofan engines
2014-06-08		Bombardier	DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315
2014-06-09	S 2009-18-18	ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, -500 ; ATR72-101, -201, -102, -202, -211, -212, and -212A
2014-06-10	S 2014-06-10	Airbus	A330, A340
2014-07-02		Rolls-Royce Deutschland	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines

# LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
<b>Biweekly 2014-08</b>			
2014-05-32	COR	Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2240, PW2337, PW2643, and F117-PW-100 turbofan engines
2014-07-03		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-07-05		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-08-02		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R
2014-08-03		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2014-08-05		Rolls-Royce Deutschland Ltd & Co KG	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines
<b>Biweekly 2014-09</b>			
2013-25-02	S 2000-11-06	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-07-01		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2014-08-01	S 2014-03-08	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-08-04	S 2012-03-04	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-08-08		The Boeing Company	737-200, -200C, -300, -400, and -500 series
2014-08-09		The Boeing Company	767-200, -300, -300F, and -400ER series
2014-08-11	S 2009-24-07	The Boeing Company	737-600, -700, -700C, -800 and -900 series
2014-09-05		Airbus	A330-201, A330-202, A330-203, A330-223, A330-243, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313
2014-09-06		The Boeing Company	777F series
<b>Biweekly 2014-10</b>			
2014-09-08	S 2007-16-19	The Boeing Company	747-200B, 747-300, and 747-400 series
2014-09-10		The Boeing Company	767-200, -300, -300F, and -400ER series
<b>Biweekly 2014-11</b>			
2014-09-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2014-09-09		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series
<b>Biweekly 2014-12</b>			
2008-21-07R1		Dowty Propellers	R408/6-123-F/17 propellers
2014-11-01		The Boeing Company	777-200 and -300 series
2014-11-04		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343 A340-211, -212, -213, -311, -312, -313, -541, and -642
2014-11-06		Lockheed	P-3A or P3A
2014-12-03		Rolls-Royce Deutschland	BR700-725A1-12 turbofan engines
2014-12-52	E	Honeywell International	TFE731-4, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, 40AR, -40R, -40BR, -50R, and -60 turbofan engines
<b>Biweekly 2014-13</b>			
2014-12-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-12-10		The Boeing Company	727-100 series
2014-13-03		Rolls-Royce plc	RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61 turbofan engines



---

**2014-12-06 Airbus:** Amendment 39-17867. Docket No. FAA-2014-0340; Directorate Identifier 2014-NM-084-AD.

**(a) Effective Date**

This AD becomes effective July 2, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to the airplanes identified in paragraphs (c)(1), (c)(2), (c)(3), (c)(4), and (c)(5) of this AD, certificated in any category, all certified models, all manufacturer serial numbers on which Airbus Modification 05438 has been embodied in production, except those on which Modification 12046 has been embodied in production.

- (1) Airbus Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.
- (2) Airbus Model A300 B4-605R and B4-622R airplanes.
- (3) Airbus Model A300 F4-605R and F4-622R airplanes.
- (4) Airbus Model A300 C4-605R Variant F airplanes.
- (5) Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Reason**

This AD was prompted by reports of fatigue cracks on the cargo door sill beam, lock fitting, and torsion box plate. We are issuing this AD to detect and correct fatigue cracking of the cargo door sill beam, lock fitting, and torsion box plate, which could result in the loss of the door locking function and subsequently, complete loss of the cargo door in flight with the risk of rapid decompression.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspection and Repair**

(1) Within the compliance time identified in paragraph (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD, as applicable, do an ultrasonic inspection or detailed inspection of the aft cargo door sill beam external area for cracking, in accordance with Airbus Alert Operators Transmission (AOT) A53W005-14, dated April 22, 2014. Repeat the inspection thereafter at intervals not to exceed 275 flight cycles.

(i) For airplanes that have accumulated 30,000 flight cycles or more since the airplane's first flight as of the effective date of this AD: Within 50 flight cycles after the effective date of this AD.

(ii) For airplanes that have accumulated 18,000 flight cycles or more, but less than 30,000 flight cycles since the airplane's first flight as of the effective date of this AD: Within 275 flight cycles after the effective date of this AD.

(iii) For airplanes that have accumulated less than 18,000 flight cycles since the airplane's first flight as of the effective date of this AD: Before exceeding 18,275 flight cycles since the airplane's first flight.

(2) If any crack is found during any inspection required by paragraph (g)(1) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent, or the Design Approval Holder (DAH) with EASA design organization approval).

#### **(h) Optional Terminating Action**

Accomplishment of the high frequency eddy current (HFEC) inspection for cracking in accordance with Airbus AOT A53W005-14, dated April 22, 2014, terminates the repetitive inspections required by paragraph (g)(1) of this AD for that airplane. If any cracking is found during the HFEC inspection, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA (or its delegated agent, or the DAH with EASA design organization approval).

#### **(i) Reporting Requirement**

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g)(1) of this AD to Airbus as specified in paragraph 7., "Reporting" of the Airbus AOT A53W005-14, dated April 22, 2014, at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include inspection results, including no findings.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

#### **(j) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or the DAH with a State of Design Authority's design organization approval, as applicable). You are required to ensure the product is airworthy before it is returned to service.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

#### **(k) Related Information**

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Emergency Airworthiness Directive 2014-0097-E, dated April 23, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0340.

#### **(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A53W005-14, dated April 22, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on: June 4, 2014.

Jeffrey E. Duven,  
Manager, Transport Airplane Directorate,  
Aircraft Certification Service.



---

**2014-12-10 The Boeing Company:** Amendment 39-17871; Docket No. FAA-2014-0141; Directorate Identifier 2013-NM-024-AD.

**(a) Effective Date**

This AD is effective July 28, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 727-100 series airplanes, certificated in any category, as identified in Boeing Service Bulletin 727-53-0041, Revision 6, dated September 5, 1991, unless previously modified using the service information specified in paragraphs (c)(1), (c)(2), or (c)(3) of this AD.

- (1) Boeing Service Bulletin 727-53-0041, Revision 4, dated July 27, 1973.
- (2) Boeing Service Bulletin 727-53-0041, Revision 5, dated January 25, 1990.
- (3) Boeing Service Bulletin 727-53-0041, Revision 6, dated September 5, 1991.

Note 1 to paragraph (c) of this AD: Boeing Service Bulletin 727-53-0041, Revision 4, dated July 27, 1973, is specified in Boeing Document D6-54860 "Aging Airplane Service Bulletin Structural Modification Program—Model 727," Revision C, dated December 11, 1989, as mandated by AD 90-06-09, Amendment 39-6488 (55 FR 8370, March 7, 1990).

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. We are issuing this AD to detect and correct cracking in stringers or frames originating at or near stringer-to-frame attachment fastener holes, which could result in reduced structural integrity of the airplane, and decompression of the cabin.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspections**

Before the accumulation of 16,000 total flight cycles, or within 3,000 flight cycles after the effective date of this AD, whichever occurs later, do a high frequency eddy current inspection and a general visual inspection for cracking in stringers and frames originating at or near stringer-to-frame attachment fastener holes, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 727-53-0041, Revision 6, dated September 5, 1991. Repeat the inspections thereafter at intervals not to exceed 6,000 flight cycles until the modification specified by paragraph (h) of this AD is accomplished. If any crack is found during any inspection required by this paragraph: Before further flight, repair or modify the affected stringer-to-frame attachment locations, in accordance with Part V, "Repair Data," of the Accomplishment Instructions of Boeing Service Bulletin 727-53-0041, Revision 6, dated September 5, 1991.

**(h) Modification**

Modifying the affected stringer-to-frame attachment locations, in accordance with Part IV, "Preventive Modification Data," of the Accomplishment Instructions of Boeing Service Bulletin 727-53-0041, Revision 6, dated September 5, 1991, terminates the repetitive inspections required by paragraph (g) of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

For more information about this AD, contact Chandra Ramdoss, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5239; fax: 562-627-5210; email: chandraduth.ramdoss@faa.gov.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 727-53-0041, Revision 6, dated September 5, 1991.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 4, 2014.

Jeffrey E. Duven,  
Manager, Transport Airplane Directorate,  
Aircraft Certification Service.



---

**2014-13-03 Rolls-Royce plc:** Amendment 39-17878; Docket No. FAA-2014-0281; Directorate Identifier 2014-NE-05-AD.

**(a) Effective Date**

This AD is effective July 14, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Rolls-Royce plc (RR) RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61 turbofan engines.

**(d) Reason**

This AD was prompted by the risk of fan flutter occurring during ground maintenance running, and the risk of intermediate-pressure (IP) shaft failure which may result in IP turbine overspeed and disk burst. We are issuing this AD to address, through an update to the electronic engine control (EEC) software, multiple risks of uncontained engine failure and damage to the airplane.

**(e) Actions and Compliance**

Comply with this AD within the compliance times specified, unless already done.

- (1) After the effective date of this AD, within 3 months or 200 flight cycles, whichever occurs first, modify the engine by removing EEC software, Version L5.6.1 or earlier.
- (2) Install EEC software eligible for installation.

**(f) Installation Prohibition**

After modification of an engine as required by paragraph (e) of this AD, do not install any EEC with a software Version L5.6.1 or earlier into any engine.

**(g) Alternative Methods of Compliance (AMOCs)**

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request.

**(h) Related Information**

- (1) For more information about this AD, contact Mark Riley, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7758; fax: (781) 238-7199; email: [mark.riley@faa.gov](mailto:mark.riley@faa.gov).

(2) Refer to MCAI European Aviation Safety Agency AD 2014-0086, dated April 11, 2014, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2014-0281.

(3) RR Alert Service Bulletin No. RB.211-73-AH531, Revision 1, dated March 7, 2014, which is not incorporated by reference in this AD, can be obtained from RR using the contact information in paragraph (h)(4) of this AD.

(4) Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE248BJ; phone: 011-44-1332-242424; fax: 011-44-1332-249936; email: [http://www.rolls-royce.com/contact/civil\\_team.jsp](http://www.rolls-royce.com/contact/civil_team.jsp); Internet: <https://www.aeromanager.com>.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

**(i) Material Incorporated by Reference**

None.

Issued in Burlington, Massachusetts, on June 13, 2014.

Ann C. Mollica,  
Acting Assistant Directorate Manager, Engine & Propeller Directorate,  
Aircraft Certification Service.