

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2013-23**

11/4/2013 - 11/17/2013



Federal Aviation Administration
Engineering Procedures Office, AIR-110
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2013-01			
2012-25-09		Rolls-Royce plc	RB211-524G2-19; RB211-524G2-T-19; RB211-524G3-19; RB211-524G3-T-19; RB211-524H2-19; RB211-524H2-T-19; RB211-524H-36; RB211-524H-T-36; RB211-535E4-37; RB211-535E4-B-37; RB211-535E4-B-75; and RB211-535E4-C-37 turbofan engines
2012-26-01	S 2005-13-27	Saab AB, Saab Aerosystems	SAAB 2000
2012-26-02		Boeing	737-300, -400, and -500 series
2012-26-03		Airbus	A330-202, -203, -223, -243, -302, -323, -342, -343, and A340-313
2012-26-05		Airbus	A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313
2012-26-08		Pratt & Whitney Canada Corp	PW118, PW118A, PW118B, PW119B, PW119C, PW120, PW120A, PW121, PW121A, PW123, PW123B, PW123C, PW123D, PW123E, PW123AF, PW124B, PW125B, PW126A, PW127, PW127E, PW127F, PW127G, and PW127M turboprop engines
2012-26-14		Rolls-Royce Deutschland Ltd & Co KG	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines
2012-26-15		Honeywell International Inc	See AD
2012-26-51		Airbus	A318-111, -112, -121, -122; A319-111, -112, -113, -114, -115, -131, -132, -133; A320-111, -211, -212, -214, -231, -232, -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2012-27-01		Rolls-Royce Deutschland Ltd & Co KG	Tay 620-15 turbofan engines
Biweekly 2013-02			
2012-25-13		The Boeing Company	747-100, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400F, and 747SR series
2012-26-04	S 2008-05-10	The Boeing Company	757-200, -200PF, and -200CB series
2013-01-02	S 2009-22-08	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP; and Model 757-200, -200PF, and -300 series
2013-01-03		The Boeing Company	737-300, -400, and -500; and Model 757-200 series
2013-02-03		Rolls-Royce plc	RB211-Trent 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84 turbofan engines
2013-02-51		The Boeing Company	787-8
Biweekly 2013-03			
2013-02-02		CFM International, S.A.	CFM56-3, CFM56-3B, and CFM56-3C turbofan engines
2013-02-04		Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 engines
2013-02-05		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-02-06		Engine Alliance	GP7270 and GP7277 turbofan engines
2013-02-07		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-02-08		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2013-02-09		BAE SYSTEMS (OPERATIONS) LIMITED	BAe 146-100A, -200A, -300A; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2013-02-10		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2013-02-11		Airbus	A310-203
2013-02-12		EADS CASA	CN-235, CN-235-100, CN-235-200, and CN-235-300

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2013-04			
2013-02-51		The Boeing Company	787-8
2013-03-05		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2013-03-07		Hawker Beechcraft Corporation	400A
2013-03-08		Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R Variants), and CL-600-2B16 (CL-604 Variants)
2013-03-11		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2013-03-12		Dassault Aviation	Mystere-Falcon 50
2013-03-13		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2013-03-17		Rolls-Royce Deutschland Ltd & Co KG	RRD BR700-710A1-10, BR700-710A2-20, and BR700-710C4-11 engines
2013-03-19	S 2001-17-20	The Boeing Company	707-100 long body, -200, -100B long body, -100B short body series, 707-300, -300B, -300C, -400 series, 720 and 720B series
2013-03-20		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2013-03-23		Gulfstream Aerospace LP	G150
2013-04-01	S 2011-13-01	Rolls-Royce plc	RB211-524D4-19, -524D4-B-19, -524D4-39, -524D4-B-39, -524D4X-19, -524D4X-B-19, -524H-36, -524H2-19, -524H-T-36, -524H2-T-19, -524G2-19, -524G3-19, -524G2-T-19, and -524G3-T-19 turbofan engines
2013-04-05		The Boeing Company	737-200, -200C, -300, -400, and -500 series
Biweekly 2013-05			
2012-25-03	Cor	The Boeing Company	757-200, -200PF, -200CB series, and 757-300
2013-03-06		Airbus	A330-223F, -243F, A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2013-04-03		Cessna Aircraft Company	750
2013-04-07		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2013-04-10		Airbus	A310-203, -204, -222, -304, -322, and -324
2013-04-11		The Boeing Company	737-600, -700, -800, and -900ER series
2013-04-12		Airbus	A310-204, -222, -304, -322, and -324
2013-04-13		BAE SYSTEMS (OPERATIONS) LIMITED	BAe 146-100A, -200A, and -300A airplanes; and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2013-05-02		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88
Biweekly 2013-06			
2013-03-06		Airbus	A330-223F, -243F, A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2013-03-22		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2013-04-14		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2013-05-02		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88
2013-05-03		The Boeing Company	777-200, -200LR, -300, and -300ER series
2013-05-05		The Boeing Company	777-200, -200LR, -300, and -300ER series
2013-05-06		Bombardier, Inc.	CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants)
2013-05-07		The Boeing Company	767-200, -300, -300F, and -400ER series
2013-05-09		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A330-223F, -243F, A340-211, -212, -213, -311, -312, and -313
2013-05-13		Rolls-Royce Deutschland Ltd & Co KG	BR700-710A1-10, BR700-710A2-20, and BR700-710C4-11 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2013-05-18	S 2012-02-04	Rolls-Royce plc	RB211 Trent 553-61, RB211 Trent 553A2-61, RB211 Trent 556-61, RB211 Trent 556A2-61, RB211 Trent 556B-61, RB211 Trent 556B2-61, RB211 Trent 560-61, and RB211 Trent 560A2-61 turbofan engine
2013-05-19		Rolls-Royce Deutschland Ltd & Co KG	Tay 611-8 turbofan engines
2013-05-20		Rolls-Royce Deutschland Ltd & Co KG	Spey 511-8 turbojet engines
2013-06-01		Rolls-Royce Deutschland Ltd & Co KG	Tay 620-15 and Tay 650-15 turbofan engines
Biweekly 2013-07			
2013-05-10		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series
2013-05-12		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 IGW, ERJ 190-200 STD, -200 LR, -200 IGW, and ERJ 190-100 ECJ
2013-06-03		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-06-05		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-06-06		General Electric Company	CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5A2, CF34-8C5A3, CF34-8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6, and CF34-8E6A1 turbofan engines
Biweekly 2013-08			
2013-04-04	S 2008-13-20	The Boeing Company	757-200, -200CB, -200PF, and -300 series
2013-05-04		Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2013-07-02		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, and -233
2013-07-03		Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and A340-642
2013-07-04	S 2007-05-13	Airbus	A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-07-07		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-07-08		The Boeing Company	757-200, 757-200PF, 757-200CB, 757-300 series
2013-07-09		The Boeing Company	737-700, -700C, -800, -900ER, 747-400F, 767-200 and -300 series
2013-07-10		International Aero Engines	V2525-D5 and V2528-D5 turbofan engines
2013-07-11	S 2009-24-08	The Boeing Company	777-200, -200LR, -300, and -300ER series
2013-07-13		Dassault Aviation	Falcon 7X
2013-08-02	S 2007-26-05	The Boeing Company	777-200, -200LR, -300, and -300ER series
2013-08-03		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2013-08-08		The Boeing Company	737-600 series
2013-08-09		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2013-09			
2013-08-10		Kelowna Flightcraft R & D Ltd.	340 and 440
2013-08-11		The Boeing Company	737-900 and -900ER series
2013-08-12		The Boeing Company	787-8
2013-08-13		The Boeing Company	767-300 series
2013-08-15		The Boeing Company	737-800 series
2013-08-16		The Boeing Company	737-700 and -700C series
2013-08-18		The Boeing Company	737-600, -700, -700C, -800, -900 and -900ER series
2013-08-20	S 2000-04-14	General Electric Company	CF6-80C2 A1/A2/A3/A5/A8/A5F/B1/B2/B4/B5F/B6/B1F/B2F/B4F/B6F/B7F/D1F turbofan engines
2013-08-23		The Boeing Company	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F
Biweekly 2013-10			
2012-18-13 R1		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2013-05-08		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -, A340-211, -212, -213, -311, -312, and -313
2013-08-01		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-09-01	S 2003-08-15	The Boeing Company	737-200, -200C, -300, -400, and -500 series
2013-09-02	S 2000-25-07 S 2002-05-07	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2013-09-07		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2013-09-08		The Boeing Company	737-300, -400, and -500 series
2013-10-02	S 2003-18-05	The Boeing Company	757-200 and -200PF series
2013-10-52	E	General Electric Company	GE90-110B1 and GE90-115B turbofan engines
Biweekly 2013-11			
2013-09-08	COR	The Boeing Company	737-300, -400, and -500 series
2013-09-10	S 2000-07-06	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2013-09-11		Cessna Aircraft Company	500, 501, 550, 551, S550, 560, 560XL, and 650
2013-10-03	S 2010-02-10	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and -642
2013-10-06		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2013-10-07		Airbus	A300 B4-601, B4-603, B4-620, B4-605R, and B4-622R
2013-11-03		Bombardier, Inc.	CL-215-1A10 and CL-215-6B11 (CL-215T Variant)
Biweekly 2013-12			
2013-11-04		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, 747SP, 767-200, -300, -300F, -400ER, 777-200, -200LR, -300, and -300ER series
2013-11-06		Dassault Aviation	Mystere-Falcon 900 and Falcon 900EX
2013-11-07		Embraer S.A.	ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2013-11-12		Bombardier, Inc.	BD-100-1A10 (Challenger 300)
2013-11-13		Rolls-Royce plc	Viper Mk. 601-22 turbojet engines
2013-11-14		The Boeing Company	777-200 and -300 series
2013-12-02		Engine Alliance	GP7270 and GP7277 turbofan engines
2013-12-03		Rolls-Royce Deutschland Ltd & Co KG	BR700-725A1-12 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
Biweekly 2013-13			
2013-01-01	S 2011-23-08	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2013-05-11	S 2010-23-07	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-09-04		Bombardier, Inc	DHC-8-400, -401, and -402
2013-10-52		General Electric Company	GE90-110B1 and GE90-115B turbofan engines
2013-11-16		Hawker Beechcraft Corporation	BAe.125 Series 800A (including C-29A and U-125), 800B, Hawker 800 (including variant U-125A) and 800XP
2013-12-01		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2013-13-05		The Boeing Company	747SP, 747-100B SUD, and 747-300
Biweekly 2013-14			
2010-17-11R1		Dowty Propellers	R408/6-123-F/17 model propellers
2013-09-03		Dassault Aviation	Falcon 2000, Falcon 2000EX, Mystere-Falcon 50, Mystere-Falcon 900 and Falcon 900EX
2013-11-17	S 2010-14-14	Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2013-13-03		Airbus	A319-112, -113, -132, A320-211, -212, -214, -231, -232, A321-111 and -131
2013-13-04		Airbus	A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, and A321-232
2013-13-09		Learjet Inc.	60
2013-13-11		The Boeing Company	747-400, -400D, and -400F series
2013-14-51		General Electric Company	GE90-110B1 and GE90-115B turbofan engines
Biweekly 2013-15			
2013-13-08	S 2009-18-02	The Boeing Company	767-200, -300, -300F, and -400ER series
2013-13-15	S 87-02-07	The Boeing Company	737-100, -200, -200C, and -300 series
2013-13-17	S 2011-13-08	Bombardier, Inc.	DHC-8-400, -401, and -402
2013-14-02		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2013-14-03		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2013-14-05		The Boeing Company	747-400 and 747-400F series
2013-14-07		Learjet	45
2013-14-11		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
2013-15-04		Hartzell Propeller, Inc.	HC-(1,D)2(X,V,MV)20-7, HC-(1,D)2(X,V,MV)20-8, and HC-(1,D)3(X,V,MV)20-8 propellers
2013-15-07		The Boeing Company	787-8
Biweekly 2013-16			
2013-13-12	S 2000-06-13 R1	The Boeing Company	737-200, -200C, -300, -400, and -500 series
2013-13-16	S 2005-07-04	Airbus	330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2013-14-06		CFM International S.A.	CFM56-5 and CFM56-5B series turbofan engines
2013-14-09	S 2012-14-04	Bombardier, Inc.	DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315
2013-14-10	S 2010-11-02	Gulfstream Aerospace LP	100, Astra SPX and 1125 Westwind Astra
2013-15-05		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2013-15-20	S 2013-14-51	General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, GE90-113B and GE90-115B turbofan engines
2013-16-02		Dassault Aviation	FALCON 7X

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2013-16-09		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
Biweekly 2013-17			
2013-15-08		Pratt & Whitney Canada Corp.	W118A, PW118B, PW119B, PW119C, PW123, PW123B, PW123C, PW123D, PW123E, PW123AF, PW124B, PW125B, PW126A, PW127, PW127E, PW127F, PW127G, and PW127M turboprop engines
2013-15-09		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
2013-15-11		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2013-15-12	S 2004-15-07	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2013-15-14	S 2008-06-29	The Boeing Company	737-300, -400, and -500 series
2013-15-15		The Boeing Company	27, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2013-15-16		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-15-21	S 2004-13-06	Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; and Model A320-111, -211, -212, -214, -231, -232, and -233
2013-16-08		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2013-16-10		Hamilton Standard Division and Hamilton Sundstrand Corporation	See AD
2013-16-11		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313
2013-16-12		Bombardier, Inc.	DHC-8-102, -103, and DHC-8-106
2013-16-15		General Electric Company	GENx-2B67B turbofan engines
2013-16-17		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2013-16-18		Airbus	A320-214, -232, -233, A321-211, -213, and -231
2013-16-22		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
Biweekly 2013-18			
2013-05-08		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, and -313
2013-15-10	S 2012-10-12	Rolls-Royce plc	RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61, 768-60, 772-60, 772B-60, 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, 895-17, 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84 turbofan engines
2013-15-13		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2013-15-17		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2013-15-18	S 2005-15-01	Lockheed Martin	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2013-16-23		Rolls-Royce plc	RB211-524G2-19; -524G3-19; -524H2-19; -524H-36; RB211-524B-02; -524B2-19; -524B3-02; -524B4-02; -524C2-19; -524D4-19; -524D4-B-19; and -524D4-39; RB211-535C-37; -535E4-37; -535E4-B-37, and -535E4-B-75 turbofan engines
2013-16-24	S 90-23-14	The Boeing Company	747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series
2013-16-25		Bombardier, Inc.	DHC-8-400, -401, and -402
2013-16-26		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, and -313
2013-17-03		Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2013-17-05 2013-17-09		Bombardier, Inc. Airbus	-303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313; A340-541, A340-642 CL-600-2C10, CL-600-2D15, and CL-600-2E25 A318-111, -112, -121, -122; A319-111, -112, -113, -114, -115, -131, -132, -133; A320-111, -211, -212, -214, -231, -232, -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
Biweekly 2013-19			
2013-17-06 2013-17-07		Fokker Services B.V. General Electric Company	F.27 Mark 050, F.28 Mark 0070 and 0100 GE90-76B, -85B, -90B, -94B, GE90-110B1 and -115B turbofan engines
2013-17-08	S 2010-20-08	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series
2013-18-02 2013-18-09 2013-19-02		The Boeing Company Honeywell ASCa Inc. Airbus	767-200, 767-300, 767-300F, and 767-400ER series See AD A330-201, -202, -203, -223, -223F, -243 -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
Biweekly 2013-20			
2013-18-08 2013-19-03	S 2004-18-06	Boeing Boeing	737-200, -200C, -300, -400, and -500 series airplanes 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2013-19-04 2013-19-08		Boeing Boeing	737-600, -700, -700C, -800, and -900 series airplanes 727, 727C, -100, -100C, -200, and -200F series; 737-100, -200, and -200C series; 747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, -400F, 747SR, and 747SP series airplanes
2013-19-09	S 2012-26-51	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-19-13		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SP series airplanes
2013-19-15		Boeing	Model 747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, -400F, and 747SR series airplanes
2013-19-17 2013-19-18		Rolls-Royce plc Rolls-Royce plc	RB211-535E4-B-37 series turbofan engines RB211-535E4-37, RB211-535E4-B-37, RB211-535E4-C-37, and RB211-535E4-B-75 turbofan engines
2013-19-20 2013-19-21	S 2012-04-13	Boeing Rolls Royce plc	DC-10-10 and MD-10-10F airplanes RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61; and RB211 Trent 768-60, 772-60, and 772B-60; and RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17; and RB211-524G2-T-19, -524G3-T-19, -524H-T-36, and -524H2-T-19
2013-19-22 2013-19-23		Boeing Boeing	717-200 airplanes 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2013-20-09 2013-20-12		Bombardier Boeing	CL-215-6B11 (CL-415 Variant) airplanes 767-200, -300, -300F, and -400ER series airplanes

Biweekly 2013-21

Due to the partial shutdown of the US Government, there were no AD's published in this Bi-weekly period.

Biweekly 2013-22

2013-16-10	COR	Hamilton Standard Division and Hamilton Sundstrand Corporation	6/5500/F and 24PF, 14RF, 14SF, 247F, and 568F series propellers
2013-20-04		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S - Supersedes			
2013-20-06		Airbus	A340-211, -212, -213, -311, -312, -313, -541, and -642
2013-20-10	S 2000-12-11	Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, and B4-622R
2013-20-11		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-20-14		The Boeing Company	747-400 and -400F series
2013-21-03		The Boeing Company	747-8F and 747-8 series
2013-21-07		The Boeing Company	727, 727C, 727-100, 727 -100C, 727-200, and 727-200F series
2013-21-08		ATR-GIE Avions de Transport Régional	ATR72-101, -201, -102, -202, -211, -212, and -212A
2013-22-02		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes; and Model A340-211, -212, -213, -311, -312, and -313
2013-22-03		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2013-22-04		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, -315, DHC-8-400, -401, and -402
2013-22-05		Bombardier, Inc.	CL-600-2B16 (CL-601-3A and CL-601-3R Variants), and CL-600-2B16 (CL-604 Variant)
2013-22-06		The Boeing Company	747-100, 747-200B, and 747-200F series
2013-22-07		The Boeing Company	747-400 series
2013-22-08		BAE Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2013-22-09		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2013-23			
2013-14-04		Airbus	A330-223F, -223, -321, -322, and -323
2013-19-14	S 2009-04-07 S 2011-02-09	Airbus	A330-223F, -243F, -201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and 642
2013-19-17		Rolls-Royce plc	RB211-535E4-B-37 series turbofan engines
2013-22-10		Dassault Aviation	Fan Jet Falcon, Mystere-Falcon 200, Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5
2013-22-11	S 2009-10-06	The Boeing Company	747-400 and -400D series
2013-22-18		EMBRAER	EMB-135ER, -135KE, -135KL, -135LR, EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2013-23-02		EADS CASA	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295
2013-23-03		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series
2013-23-04		The Boeing Company	737-600, -700, -800, -900, and -900ER series
2013-23-05		Fokker Services B.V.	F.28 Mark 0070 and 0100



2013-14-04 Airbus: Amendment 39-17509. Docket No. FAA-2013-0212; Directorate Identifier 2012-NM-116-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective December 19, 2013.

(b) Affected ADs

This AD affects AD 2006-16-05, Amendment 39-14705 (71 FR 44185, August 4, 2006).

(c) Applicability

This AD applies to Airbus Model A330-223F, -223, -321, -322, and -323 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Reason

This AD was prompted by fatigue load analysis that determined that certain pylon bolts inspection interval must be reduced. We are issuing this AD to detect and correct loose or broken bolts, which could lead to engine detachment in-flight, and damage to the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Torque Check and Replacement

(1) Within the compliance times specified in table 1 to paragraph (g) of this AD, as applicable to airplane model and utilization, do a torque check to determine if there are any loose or broken forward engine mount bolts (4 positions/engine) on both engines, and repeat that torque check at intervals not to exceed the values defined in table 1 to paragraph (g) of this AD, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-71-3028, Revision 01, dated February 20, 2012. For the purposes of table 1 to paragraph (g) of this AD, the average flight time (AFT) is defined as a computation of the number of flight hours divided by the number of flight cycles accumulated since last torque check or since the airplane's first flight, as applicable.

Table 1 to Paragraph (g) of This AD

Airplane models	Flight cycles accumulated on the effective date of this AD since last torque check performed as specified in Pratt & Whitney Alert Service Bulletin PW4G-100-A71-32, or since airplane first flight, as applicable	Compliance time	Torque check interval (not to exceed)
For Model A330-223,-321, -322, and -323 airplanes with AFT more than 132 minutes	0-1,850	Within 2,350 flight cycles since the last torque check as specified in Pratt & Whitney Alert Service Bulletin PW4G-100-A71-32, or since airplane first flight, as applicable	2,350 flight cycles or 24,320 flight hours, whichever occurs first.
For Model A330-223, -321, -322, and -323 airplanes with AFT more than 132 minutes	1,851-2,700	Within 500 flight cycles after the effective date of this AD without exceeding 2,700 flight cycles since last torque check as specified in Pratt & Whitney Alert Service Bulletin PW4G-100-A71-32, or since airplane first flight, as applicable; or within 3 months after the effective date of this AD; whichever occurs later	2,350 flight cycles or 24,320 flight hours, whichever occurs first.
For Model A330-321,-322, and -323 airplanes with AFT equal or less than 132 minutes; and for Model A330-321, -322, and -323 airplanes on which the AFT is not calculated on a regular basis	0-1,450	Within 1,950 flight cycles since the last torque check performed as specified in Pratt & Whitney Alert Service Bulletin PW4G-100-A71-32, or since airplane first flight, as applicable	1,950 flight cycles or 20,210 flight hours, whichever occurs first.

For Model A330-321, -322, and -323 airplanes with AFT equal or less than 132 minutes; and for Model A330-321, -322, and -323 airplanes on which the AFT is not calculated on a regular basis	1,451-2,700	Within 500 flight cycles after the effective date of this AD without exceeding 2,700 flight cycles since last torque check performed as specified in Pratt & Whitney Alert Service Bulletin PW4G-100-A71-32, or since airplane first flight, as applicable; or within 3 months after the effective date of this AD; whichever occurs later	1,950 flight cycles or 20,210 flight hours, whichever occurs first.
For Model A330-223F airplanes	Not applicable	Within 2,140 flight cycles or 6,600 flight hours, whichever occurs first since the last torque check performed as specified in Pratt & Whitney Alert Service Bulletin PW4G-100-A71-32, or since airplane first flight, as applicable	2,140 flight cycles or 6,600 flight hours, whichever occurs first.

(2) If any loose or broken bolt is detected during the check required by paragraph (g)(1) of this AD, before further flight, replace all four forward engine mount bolts and associated nuts, on the engine where the loose or broken bolt was detected, with new bolts and nuts, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-71-3028, Revision 01, dated February 20, 2012.

(3) Replacement of bolts and nuts as required by paragraph (g)(2) of this AD is not terminating action for the repetitive torque checks required by paragraph (g)(1) of this AD.

(h) Compliance With AD 2006-16-05, Amendment 39-14705 (71 FR 44185, August 4, 2006)

Doing the actions required by paragraph (g) of this AD constitutes compliance with the requirements specified in paragraph (g) of AD 2006-16-05, Amendment 39-14705 (71 FR 44185, August 4, 2006).

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install any INCO718 material, forward mount pylon bolt having Pratt & Whitney part number 54T670 on any airplane.

(j) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g)(1) and (g)(2) of this AD, if those actions were performed before the effective date of this AD using Airbus Mandatory Service Bulletin A330-71-3028, dated December 16, 2011, which is not incorporated by reference in this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(l) Related Information

(1) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2012-0094, dated May 31, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0212-0002>.

(2) Service information identified in this AD that is not incorporated by reference may be viewed at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Mandatory Service Bulletin A330-71-3028, Revision 01, dated February 20, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 21, 2013.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-19-14 Airbus: Amendment 39-17596. Docket No. FAA-2013-0329; Directorate Identifier 2012-NM-032-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective December 19, 2013.

(b) Affected ADs

This AD supersedes AD 2009-04-07, Amendment 39-15813 (74 FR 7549, February 18, 2009); and AD 2011-02-09, Amendment 39-16583 (76 FR 4219, January 25, 2011).

(c) Applicability

This AD applies to the Airbus airplanes, certificated in any category, as identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model A330-223F, -243F, -201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes; except those on which Airbus Modification 201654 has been embodied in production, or Airbus Service Bulletin A330-27-3156 has been incorporated in service.

(2) All Model A340-211, -212, -213, -311, -312, -313, -541, and 642 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by the possibility that, due to significant differences among all airspeed sources, the flight controls will revert to alternate law, the autopilot (AP) and the auto-thrust (A/THR) automatically disconnect, and the flight director (FD) bars are automatically removed. Then, if two airspeed sources become similar while still erroneous, the flight guidance computers will display the FD bars again, and enable the re-engagement of the AP and A/THR. In some cases, however, the AP orders may be inappropriate, such as possible abrupt pitch command. We are issuing this AD to prevent autopilot engagement under unreliable airspeed conditions, which could result in reduced controllability of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Airplane Flight Manual (AFM) Revision: Certain NAV Faults or ATT Flag on PFD

This paragraph restates the actions required by paragraph (f) of AD 2009-04-07, Amendment 39-15813 (74 FR 7549, February 18, 2009). For all airplanes except Model A330-223F and -243F airplanes: Within 14 days after March 5, 2009 (the effective date of AD 2009-04-07), revise the applicable section of the A330 or A340 (Airbus) Flight Manual (FM) by inserting a copy of A330 (Airbus) Temporary Revision (TR) 4.02.00/46, or A340 (Airbus) TR 4.02.00/54, both Issue 3, both dated January 13, 2009, as applicable. Thereafter, operate the airplane according to the limitations and procedures in the TRs. When information identical to that in the TR has been included in the general revisions of the FM, the general revisions may be inserted in the FM, and the TR may be removed.

(h) Retained AFM Revision: Alternate Law Associated With AP and A/THR Disconnection

This paragraph restates the actions required by paragraph (g) of AD 2011-02-09, Amendment 39-16583 (76 FR 4219, January 25, 2011). Within 15 days after February 9, 2011 (the effective date of AD 2011-02-09), do the actions in paragraph (h)(1) or (h)(2) of this AD.

(1) Revise the Limitations and Abnormal Sections of the Airbus A330/A340 AFM to include the following statement and operate the airplane according to these limitations and procedures. This may be done by inserting a copy of this AD in the AFM. When a statement identical to that in figure 1 to paragraph (h)(1) of this AD has been included in the general revisions of the Limitations and Abnormal Sections of the AFM, the general revisions may be inserted into the AFM, and the copy of this AD may be removed from the AFM.

Figure 1 to Paragraph (h)(1) of this AD: *Procedure*

PROCEDURE:

When autopilot and auto-thrust are automatically disconnected and flight controls have reverted to alternate law:

- Do not engage the AP and the A/THR, even if FD bars have reappeared

- Do not follow the FD orders

- ALL SPEED INDICATIONSX-CHECK

- If unreliable speed indication is suspected:

- UNRELIABLE SPEED INDIC/ADR CHECK
PROC APPLY

- If at least two ADRs provide reliable speed indication for at least 30 seconds, and the aircraft is stabilised on the intended path:

AP/FD and A/THR As required

(2) Revise the Limitations and Abnormal Sections of the Airbus A330/A340 AFM to include the information in Airbus A330/A340 TR TR149 (for Model A330 airplanes) or TR TR150 (for Model A340-200 and -300 series airplanes), both Issue 1.0, both dated December 20, 2010. These TRs introduce procedures for operation of the auto pilot and auto-thrust disconnect. Operate the airplane according to the limitations and procedures in the TRs. This may be done by inserting copies of Airbus A330/A340 TR TR149 or TR150, both Issue 1.0, both dated December 20, 2010; as applicable; into the Airbus A330/A340 AFM. When these TRs have been included in general revisions of the AFM, the general revisions may be inserted in the AFM, and the TRs may be removed.

(i) New Software Standard Upgrade for Model A330 Series Airplanes, and Model A340-200 and -300 Series Airplanes

Within 10 months after the effective date of this AD, upgrade (by modification or replacement, as applicable) the three flight control primary computers (FCPCs), as specified in paragraphs (i)(1), (i)(2), (i)(3), and (i)(4) of this AD, as applicable. Accomplishment of the applicable requirements of this paragraph terminates the requirements of paragraphs (g) and (h) of this AD. Accomplishing the actions specified in paragraphs (i)(1) through (i)(4) of this AD are compliant with the optional actions specified in paragraphs (l) and (o)(1) through (o)(4) of AD 2013-05-08, Amendment 39-17380 (78 FR 27015, May 9, 2013).

(1) For Model A330 series airplanes: Upgrade to software standard P11A/M20A on FCPC 2K2 hardware, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-27-3176, Revision 02, dated April 24, 2012.

(2) For Model A330 series airplanes: Upgrade to software standard P12A/M21A on FCPC 2K1 hardware, and software standard M21A on FCPC 2K0 hardware, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330-27-3177, dated December 21, 2011.

(3) For Model A340-200 and -300 series airplanes: Upgrade to software standard L22A on FCPC 2K1 hardware, and software standard L22A on FCPC 2K0 hardware, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-27-4174, dated November 21, 2011.

(4) For Model A340-200 and -300 series airplanes: Upgrade to software standard L21A on FCPC 2K2 hardware, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-27-4162, Revision 01, dated September 17, 2012.

(j) New Software Standard Upgrade for Model A340-541 and -642 Series Airplanes

(1) Within 10 months after the effective date of this AD, modify or replace the three FCPCs to integrate software standard W12 on FCPC 2K2 hardware, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340-27-5051, dated July 16, 2012. Accomplishment of the applicable requirements of this paragraph terminates the requirements of paragraphs (g) and (h) of this AD.

(2) After accomplishing the modification in accordance with paragraph (j)(1) of this AD, do not install an FCPC on the airplane unless the FCPC is 2K2 hardware with integrating software standard W12.

(k) Credit for Previous Actions

(1) This paragraph provides credit for the actions specified in paragraph (i)(1) of this AD, if those actions were performed before the effective date of this AD using Airbus Mandatory Service Bulletin A330-27-3176, dated July 26, 2011; or Airbus Mandatory Service Bulletin A330-27-3176, Revision 01, dated March 27, 2012; which are not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions specified in paragraph (i)(4) of this AD, if those actions were performed before the effective date of this AD using Airbus Mandatory Service Bulletin A340-27-4162, dated January 10, 2012, which is not incorporated by reference in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directives 2011-0199R1, dated February 17, 2012; and 2013-0107, dated May 17, 2013; for related information. The MCAI can be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0329-0003>.

(2) Service information that is referenced in this AD that is not incorporated by reference in this AD may be viewed at the addresses identified in paragraphs (n)(6) and (n)(7) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on December 19, 2013.

(i) Airbus Mandatory Service Bulletin A330-27-3176, Revision 02, dated April 24, 2012.

(ii) Airbus Mandatory Service Bulletin A330-27-3177, dated December 21, 2011.

(iii) Airbus Mandatory Service Bulletin A340-27-4162, Revision 01, dated September 17, 2012.

(iv) Airbus Mandatory Service Bulletin A340-27-4174, dated November 21, 2011.

(v) Airbus Mandatory Service Bulletin A340-27-5051, dated July 16, 2012.

(4) The following service information was approved for IBR on February 9, 2011 (76 FR 4219, January 25, 2011).

(i) Airbus A330/A340 Temporary Revision TR149, Issue 1.0, dated December 20, 2010, to the Airbus A330/A340 Airplane Flight Manual.

(ii) Airbus A330/A340 Temporary Revision TR150, Issue 1.0, dated December 20, 2010, to the Airbus A330/A340 Airplane Flight Manual.

(5) The following service information was approved for IBR on March 5, 2009 (74 FR 7549, February 18, 2009).

(i) Airbus A330 Temporary Revision 4.02.00/46, Issue 3, dated January 13, 2009, to the Airbus A330 Airplane Flight Manual.

(ii) Airbus A340 Temporary Revision 4.02.00/54, Issue 3, dated January 13, 2009, to the Airbus A340 Airplane Flight Manual.

(6) For service information identified in this AD, contact Airbus SAS–Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(7) You may view copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 13, 2013.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



CORRECTION: Federal Register Volume 78, Number 220 (Thursday, November 14, 2013); Page 68360.

2013-19-17 Rolls-Royce plc: Amendment 39-17599; Docket No. FAA-2013-0029; Directorate Identifier 2013-NE-01-AD.

(a) Effective Date

This AD becomes effective November 7, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Rolls-Royce plc (RR) RB211-535E4-B-37 series turbofan engines.

(d) Unsafe Condition

This AD was prompted by recalculating the lives of certain rotating life limited parts (LLPs) operated to certain flight profiles. We are issuing this AD to prevent the failure of rotating LLPs, which could result in uncontained failure of the engine and damage to the airplane.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Within 30 days after the effective date of this AD, for engines that have operated to Flight Profile D or E, recalculate the life of the low-pressure (LP) turbine disc stage 2, intermediate-pressure (IP) compressor rotor shaft (stage 1 to 6), high-pressure (HP) compressor rear rotor shaft assembly, and HP turbine disc installed on that engine. Use the part lives, prorated life formulas, and flight profiles in Appendices 2, 4, and 5 of RR Alert Non-Modification Service Bulletin (NMSB) No. RB.211-72-AG875, dated December 13, 2012, to make that calculation.

(2) Within 30 days after the effective date of this AD, for engines that will operate to Flight Profile D or E, assign the maximum approved lives defined in Appendix 2 of RR Alert NMSB No. RB.211-72-AG875, dated December 13, 2012, to the LP turbine disc stage 2, IP compressor rotor shaft (stage 1 to 6), HP compressor rear rotor shaft assembly, and HP turbine disc based on the flight profile that will be flown.

(3) For engines that have only operated to, and will continue to operate to, Flight Profile C, as defined in Appendix 5 of RR Alert NMSB No. RB.211-72-AG875, dated December 13, 2012, no further action is required by this AD.

(4) After the effective date of this AD, for engines that incorporate an LP turbine disc stage 2, IP compressor rotor shaft (stage 1 to 6), HP compressor rear rotor shaft assembly, or HP turbine disc whose part life is defined by paragraph (e)(1) of this AD, that have an engine shop visit (ESV) before

reaching the part life assigned in paragraph (e)(2) of this AD, remove each part from service before the part exceeds the part life assigned in paragraph (e)(2).

(5) For those engines that incorporate an LP turbine disc stage 2, IP compressor rotor shaft (stage 1 to 6), HP compressor rear rotor shaft assembly, or HP turbine disc whose part life is defined by paragraph (e)(1) of this AD, that do not have an ESV after the effective date of this AD before the part exceeds the part life assigned in paragraph (e)(2) of this AD, remove the part from service at the next ESV.

(f) Installation Prohibition

Any LP turbine disc stage 2, IP compressor rotor shaft (stage 1 to 6), HP compressor rear rotor shaft assembly, or HP turbine disc whose part life is defined by paragraph (e)(1) of this AD that is re-installed in any engine after the effective date of this AD must be removed from service before the part exceeds the part life assigned in paragraph (e)(2) of this AD.

(g) Definition

For the purpose of this AD, ESV is whenever engine maintenance performed prior to reinstallation requires the separation of a pair of major mating engine module flanges. Separation of flanges solely for the purpose of shipment without subsequent internal maintenance is not an ESV. Separation of the external gearbox engine mating flanges or removal of the external gearbox is also not classified as a shop visit.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(i) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

(2) Refer to European Aviation Safety Agency AD 2012-0265, dated December 18, 2012, for related information. You may examine the AD on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0029-0007>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce plc Alert Non-Modification Service Bulletin No. RB.211-72-AG875, dated December 13, 2012.

(ii) Reserved.

(3) For Rolls-Royce plc service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE248BJ; phone: 011-44-1332-242424; fax: 011-44-1332-249936; email: http://www.rolls-royce.com/contact/civil_team.jsp; or download from <https://www.aeromanager.com>.

(4) You may view this service information at FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on September 16, 2013.

Carlos A. Pestana,
Acting Directorate Assistant Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2013-22-10 Dassault Aviation: Amendment 39-17642. Docket No. FAA-2013-0626; Directorate Identifier 2012-NM-180-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective December 19, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Dassault Aviation airplanes identified in paragraphs (c)(1) through (c)(3) of this AD, certificated in any category, all serial numbers.

- (1) Model Fan Jet Falcon airplanes.
- (2) Model Mystere-Falcon 200 airplanes.
- (3) Model Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire Protection.

(e) Reason

This AD was prompted by reports of defective fire extinguisher bottle cartridges. We are issuing this AD to detect and correct defective fire bottle cartridges, which could impact the capability to extinguish a fire in an engine, auxiliary power unit, or rear compartment, which could result in damage to the airplane and injury to the occupants.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Checks of References of Cartridges

For airplanes equipped with fire extinguisher bottle cartridges having a part number (P/N), batch number, and manufacturing date as listed in paragraph (g)(1), (g)(2), or (g)(3) of this AD: Within 30 days or 100 flight hours, whichever occurs first after the effective date of this AD, check the manufacturing references of pyrotechnical cartridges for batch number and date, and check the cartridges for electrical continuity and resistance, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F20-783, Revision 1 (also referred to as 783-R1), dated June 11, 2012 (for Model Fan Jet Falcon and Mystere-Falcon 20-C5, 20-D5, 20-E5, and

20-F5 airplanes); or Dassault Mandatory Service Bulletin F200-128, Revision 1 (also referred to as 128-R1), dated June 11, 2012 (for Model Mystere-Falcon 200 airplanes).

- (1) P/N 12-12-11707S1-4, with batch up to 44 inclusive, manufactured before May 2012.
- (2) P/N 12-12-11707S2-4, with batch up to 33 inclusive, manufactured before May 2012.
- (3) P/N 12-12-11707S3-4, with batch up to 44 inclusive, manufactured before May 2012.

(h) Replacement

If, during any check as required by paragraphs (g) and (i) of this AD, a discrepancy [excessive resistance] is identified, before next flight, replace the discrepant fire extinguisher bottle cartridge(s) with a serviceable part, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F20-783, Revision 1 (also referred to as 783-R1), dated June 11, 2012 (for Model Fan Jet Falcon and Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5 airplanes); or Dassault Mandatory Service Bulletin F200-128, Revision 1 (also referred to as 128-R1), dated June 11, 2012 (for Model Mystere-Falcon 200 airplanes). Replacement of discrepant fire extinguisher bottle cartridges with a serviceable part terminates the repetitive actions required by paragraph (i) of this AD for that cartridge.

(i) Repetitive Checks

At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, repeat the checks required by paragraph (g) of this AD.

(1) For airplanes equipped with fire extinguisher bottle cartridges having P/N 12-12-11707S3-4, having a batch number, and manufacturing date, as listed in paragraph (g)(3) of this AD, at intervals not to exceed 65 days.

(2) For airplanes equipped with fire extinguisher bottle cartridges having P/N 12-12-11707S1-4 or P/N 12-12-11707S2-4, having a batch number, and manufacturing date, as listed in paragraph (g)(1) or (g)(2) of this AD, at intervals not to exceed 12 months.

(j) Replacement

Except as required by paragraph (h) of this AD: Within 30 months after installation of an affected fire extinguisher bottle cartridge on an airplane, or within 36 months since cartridge manufacturing date, whichever occurs first after the effective date of this AD, replace each affected fire extinguisher bottle cartridge listed in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, with a serviceable part, in accordance with the Accomplishment Instructions of Dassault Mandatory Service Bulletin F20-783, Revision 1 (also referred to as 783-R1), dated June 11, 2012 (for Model Fan Jet Falcon and Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5 airplanes); or Dassault Mandatory Service Bulletin F200-128, Revision 1 (also referred to as 128-R1), dated June 11, 2012 (for Model Mystere-Falcon 200 airplanes). Replacing the affected fire extinguisher bottle cartridge with a serviceable part as required by paragraph (h) or (j) of this AD, terminates the repetitive actions required by paragraph (i) of this AD for that cartridge.

(k) Parts Installation Prohibition

As of the effective date of this AD, no person may install any fire extinguisher bottle cartridge having a part number, batch number, and manufacturing date as specified in paragraph (g)(1), (g)(2), or (g)(3) of this AD, on any airplane.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(m) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency (EASA) Airworthiness Directive 2012-0190, dated September 24, 2012, for related information. You may examine this AD on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0626-0002>.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Mandatory Service Bulletin F20-783, Revision 1 (also referred to as 783-R1), dated June 11, 2012.

(ii) Dassault Mandatory Service Bulletin F200-128, Revision 1 (also referred to as 128-R1), dated June 11, 2012.

(3) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(4) You may review this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 18, 2013.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-22-11 The Boeing Company: Amendment 39-17643; Docket No. FAA-2013-0328; Directorate Identifier 2012-NM-184-AD.

(a) Effective Date

This AD is effective December 10, 2013.

(b) Affected ADs

This AD supersedes AD 2009-10-06, Amendment 39-15901 (74 FR 22424, May 13, 2009).

(c) Applicability

This AD applies to The Boeing Company Model 747-400 and -400D series airplanes; certificated in any category; as identified in Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that certain upper chords of the upper deck floor beam are subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking in certain upper chords of the upper deck floor beam, which could become large and cause the floor beams to become severed and result in rapid decompression or reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspections and Corrective Actions With Revised Service Information and Compliance Times

This paragraph restates the actions required by paragraph (g) of AD 2009-10-06, Amendment 39-15901 (74 FR 22424, May 13, 2009), with revised service information and compliance times. Except as required by paragraphs (h)(1) and (h)(2) of this AD: At the applicable times in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008, do an inspection (open-hole or surface high frequency eddy current (HFEC)) to detect cracks in the floor panel attachment fastener holes of the Section 41 upper deck floor beam upper chords, and do applicable corrective actions, by accomplishing all the applicable actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008;

or Revision 1, dated September 19, 2012. Repeat the inspections thereafter at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008, except as required by paragraphs (i) and (m) of this AD. As of the effective date of this AD, use only Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, to accomplish the actions in this paragraph.

(h) Retained Exceptions

(1) This paragraph restates the exception stated in paragraph (h) of AD 2009-10-06, Amendment 39-15901 (74 FR 22424, May 13, 2009). If any crack is found during any inspection required by paragraph (g) of this AD, and Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008; or Revision 1, dated September 19, 2012; specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

(2) This paragraph restates the exception stated in paragraph (i) of AD 2009-10-06, Amendment 39-15901 (74 FR 22424, May 13, 2009). Where Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008, specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after June 17, 2009 (the effective date of AD 2009-10-06).

(i) Inspections and Corrective Actions for Airplanes on Which a Repair or Modification Is Done (for Section 41)

For airplanes on which a repair or modification identified in Table 2 of 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, has been done: At the times specified in Table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, except as required by paragraph (n)(3) of this AD, do open-hole and surface HFEC inspections, as applicable, for cracking, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012. Repeat at the applicable intervals specified in Table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012. If any cracking is found in the repaired or modified locations, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

(j) New Inspections and Repair

For Group 1 airplanes identified in Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, except as specified in paragraph (n)(2) of this AD, do an open-hole or surface HFEC inspection to detect cracking in the floor panel attachment fastener holes of the Section 44 upper deck floor beam upper chords, and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, except as required by paragraph (n)(1) of this AD. Repeat the inspections thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, except as provided by paragraph (m) of this AD. Do all applicable corrective actions before further flight.

(k) New Terminating Action for Certain Conditions

(1) For Section 41: Doing a hole modification or repair as a hole modification, in accordance with "Part 2–Section 41–Repair," of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, terminates the repetitive inspections specified in paragraph (g) of this AD. However, the repetitive inspections specified in paragraph (i) of this AD must be done.

(2) For Section 44: Doing a hole modification or repair as a hole modification, in accordance with "Part 5–Section 44–Repair," of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, terminates the repetitive inspections specified in paragraph (j) of this AD. However, the repetitive inspections specified in paragraph (l) of this AD must be done.

(l) New Inspections and Corrective Actions for Airplanes on Which a Repair or Modification Is Done (for Section 44)

For airplanes on which a repair or modification specified in the "Condition" column of Table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, has been done: At the times specified in Table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, except as required by paragraph (n)(3) of this AD, do open hole and surface HFEC inspections, as applicable, for cracking, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012. Repeat at the applicable intervals specified in Table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012. If any cracking is found in the repaired or modified locations, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

(m) New Replacement and Post-Replacement Inspections

At the time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012: Replace Section 41 and 44 upper deck floor beam upper chords, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012. Repeat the inspections required by paragraphs (g) and (j) of this AD within 20,000 flight cycles after doing the replacement. Thereafter, repeat the inspection required by paragraphs (g) and (j) of this AD at the times specified in paragraphs (g) and (j) of this AD.

(n) New Exceptions

(1) If any crack is found during any inspection required by paragraph (i), (j), or (l) of this AD, and Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

(2) Where Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, specifies a compliance time "after the Revision 1 date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(3) Where Table 2 or Table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012, specifies to contact Boeing for inspections and compliance times: Before further flight, contact the Manager, FAA, Seattle Aircraft Certification Office (ACO), for inspections and compliance times and accomplish the inspections at the given times.

(o) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008.

(p) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (q)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2009-10-06, Amendment 39-15901 (74 FR 22424, May 13, 2009), are approved as AMOCs for the corresponding actions of this AD.

(q) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: bill.ashforth@faa.gov.

(2) Service information that is not incorporated by reference in this AD may be obtained at the addresses identified in paragraph (r)(5) of this AD.

(r) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on December 10, 2013.

(i) Boeing Alert Service Bulletin 747-53A2688, Revision 1, dated September 19, 2012.

(ii) Reserved.

(4) The following service information was approved for IBR on June 17, 2009 (74 FR 22424, May 13, 2009).

(i) Boeing Alert Service Bulletin 747-53A2688, dated August 21, 2008.

(ii) Reserved.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at FAA, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 17, 2013.
Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-22-18 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-17650.
Docket No. FAA-2013-0868; Directorate Identifier 2013-NM-194-AD.

(a) Effective Date

This AD becomes effective November 20, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135ER, -135KE, -135KL, and -135LR airplanes, and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes, certificated in any category, as identified in EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of failure of the bolts that connect the lower eyelet fitting of the cockpit windshield center-post to the forward fuselage. We are issuing this AD to detect and correct failed bolts and attaching parts of the lower eyelet fitting of the cockpit windshield center-post, which could lead to loss of structural integrity of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Repetitive Inspections

(1) For Group 1 airplanes, as identified in EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013: At the applicable compliance time specified in paragraph (g)(1)(i), (g)(1)(ii), (g)(1)(iii), or (g)(1)(iv) of this AD, do a detailed inspection to detect discrepancies on the attaching parts of the lower eyelet fitting of the cockpit windshield center-post, and if no discrepancy is found, before further flight, do a check to make sure the bolts are tight, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013. Repeat the actions required by this paragraph thereafter at intervals not to exceed 500 flight cycles until the accomplishment of the replacement required by paragraph (h) of this AD or the optional terminating action specified in paragraph (i) of this AD.

(i) For airplanes with 11,000 total flight cycles or more as of the effective date of this AD: Do the inspection within 50 flight cycles after the effective date of this AD.

(ii) For airplanes with 10,000 total flight cycles or more but fewer than 11,000 total flight cycles as of the effective date of this AD: Do the inspection before the accumulation of 11,050 total flight cycles, or within 150 flight cycles after the effective date of this AD, whichever occurs first.

(iii) For airplanes with 7,500 total flight cycles or more but fewer than 10,000 total flight cycles as of the effective date of this AD: Do the inspection before the accumulation of 10,150 total flight cycles, or within 500 flight cycles after the effective date of this AD, whichever occurs first.

(iv) For airplanes with fewer than 7,500 total flight cycles as of the effective date of this AD: Do the inspection before the accumulation of 8,000 total flight cycles, or within 5,000 flight cycles after the effective date of this AD, whichever occurs first.

(2) For Group 2 airplanes, as identified in EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013 (airplanes on which the actions specified in EMBRAER Service Bulletin 145-53-0058, dated December 23, 2004; or Revision 01, dated March 30, 2007; have been done): At the applicable compliance time specified in paragraph (g)(2)(i), (g)(2)(ii), (g)(2)(iii), or (g)(2)(iv) of this AD, do a detailed inspection to detect discrepancies on the attaching parts of the lower eyelet fitting of the cockpit windshield center-post, and if no discrepancy is found, before further flight, do a check to make sure the bolts are tight, in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013. Repeat the actions required by this paragraph thereafter at intervals not to exceed 500 flight cycles until the accomplishment of the requirements of paragraph (h) of this AD or the optional terminating action specified in paragraph (i) of this AD.

(i) For airplanes that, as of the effective date of this AD, have accumulated 11,000 flight cycles or more since the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058: Do the inspection within 50 flight cycles after the effective date of this AD.

(ii) For airplanes that, as of the effective date of this AD, have accumulated 10,000 flight cycles or more but fewer than 11,000 flight cycles since the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058: Do the inspection within 11,050 flight cycles after the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058, or within 150 flight cycles after the effective date of this AD, whichever occurs first.

(iii) For airplanes that, as of the effective date of this AD, have accumulated 7,500 flight cycles or more but fewer than 10,000 flight cycles since the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058: Do the inspection within 10,150 flight cycles after the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058, or within 500 flight cycles after the effective date of this AD, whichever occurs first.

(iv) For airplanes that, as of the effective date of this AD, accumulated fewer than 7,500 flight cycles since the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058: Do the inspection within 8,000 flight cycles after the incorporation of the actions specified in EMBRAER Service Bulletin 145-53-0058, or within 5,000 flight cycles after the effective date of this AD, whichever occurs first.

(h) Corrective Actions

If, during any inspection required by paragraph (g) of this AD, any discrepancy is found or if, during any check required by paragraph (g) of this AD, any bolt is found that is not tight, before further flight, do the replacement of the attaching parts of the lower eyelet fitting of the cockpit windshield center-post, including doing a general visual inspection for damage on the eyelet fitting; in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013. If any damage to the eyelet fitting is found, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or Agência Nacional de Aviação Civil (ANAC) (or its delegated agent, or by the Design Approval Holder (DAH) with ANAC design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD.

(i) Optional Terminating Action

For Group 1 airplanes, and Group 2 airplanes (airplanes on which the actions specified in EMBRAER Service Bulletin 145-53-0058, dated December 23, 2004; or Revision 01, dated March 30, 2007; have been done), as identified in EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013: Doing the replacement of the attaching parts of the lower eyelet fitting of the cockpit windshield center-post, including doing a general visual inspection for damage on the eyelet fitting if any discrepancy is found in any bolts, terminates the inspections required by paragraph (g) of this AD. The replacement specified in this paragraph must be done in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013, except as required by paragraph (j) of this AD.

(j) Service Information Exception

Where EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013, specifies to contact Embraer if there are signs of damage on the eyelet fitting, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or ANAC (or its delegated agent, or by the DAH with ANAC design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD.

(k) Credit for Previous Actions

This paragraph provides credit for actions specified in paragraphs (g), (h), and (i) of this AD, if those actions were performed before the effective date of this AD using EMBRAER Alert Service Bulletin 145-53-A082, dated September 22, 2013; or EMBRAER Alert Service Bulletin 145-53-A082, Revision 01, dated September 26, 2013; which are not incorporated by reference in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or the Design Approval Holder with a State of Design Authority's design organization approval, as applicable). For a repair method to be approved, the repair approval must specifically refer to this AD. You are required to ensure the product is airworthy before it is returned to service.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Brazilian Emergency Airworthiness Directive 2013-10-01, effective October 3, 2013, for related information. You may

examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-0868.

(2) Service information identified in this AD that is not incorporated by reference may be obtained at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) EMBRAER Service Bulletin 145-53-0082, dated October 18, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170–Putim–12227-901 São Jose dos Campos–SP–BRASIL; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 25, 2013.

Stephen P. Boyd,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-23-02 EADS CASA (Type Certificate Previously Held by Construcciones Aeronauticas, S.A.): Amendment 39-17657. Docket No. FAA-2013-0870; Directorate Identifier 2013-NM-166-AD.

(a) Effective Date

This AD becomes effective December 2, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to EADS CASA (Type Certificate previously held by Construcciones Aeronauticas, S.A.) Model CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a report of an in-flight problem with the fuel transfer system. We are issuing this AD to detect and correct damage to certain fuel booster pumps, which could create an ignition source in the fuel tank vapor space, and result in a fuel tank explosion and consequent loss of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection of the Feeder Cables of Certain Fuel Booster Pumps

Within the times specified in paragraph (g)(1) or (g)(2) of this AD, as applicable: Perform a detailed visual inspection for damage (including, but not limited to, signs of electrical arcing and fuel leaks) of the electrical feeder cables of each fuel booster pump having part number (P/N) 1C12-34 or 1C12-46, in accordance with the instructions of Airbus Military All Operator Letter 235-025, dated July 29, 2013 (for Model CN-235 airplanes); or Airbus Military All Operator Letter 295-025, Revision 01, dated August 1, 2013 (for Model C-295 airplanes).

(1) For each fuel booster pump that has not been replaced as of the effective date of this AD: Prior to the accumulation of 300 total flight hours or within 5 cycles after the effective date of this AD, whichever occurs later.

(2) For each fuel booster pump that has been replaced as of the effective date of this AD: Within 300 flight hours since the most recent fuel booster pump replacement, or within 5 flight cycles after the effective date of this AD, whichever occurs later.

(h) Replacement of Affected Fuel Boost Pumps

If any damage (including, but not limited to, signs of electrical arcing and fuel leaks) is found during the inspection required by paragraph (g) of this AD: Within the time specified in paragraph (h)(1) or (h)(2) of this AD, replace the affected fuel booster pump with a serviceable pump, in accordance with Airbus Military All Operator Letter 235-025, dated July 29, 2013 (for Model CN-235 airplanes); or Airbus Military All Operator Letter 295-025, Revision 01, dated August 1, 2013 (for Model C-295 airplanes).

(1) Before further flight.

(2) Within 10 days following the inspection, provided that the airplane is operated under the conditions specified in Airbus Military All Operator Letter 235-025, dated July 29, 2013 (for Model CN-235 airplanes); or Airbus Military All Operator Letter 295-025, Revision 01, dated August 1, 2013 (for Model C-295 airplanes).

(i) Report of Inspection Findings

At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, submit an inspection report to EADS CASA (Airbus Military), in accordance with Airbus Military All Operator Letter 235-025, dated July 29, 2013 (for Model CN-235 airplanes); or Airbus Military All Operator Letter 295-025, Revision 01, dated August 1, 2013 (for Model C-295 airplanes).

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 10 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: (425) 227-1112; fax: (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or by the Design Approval Holder (DAH) with a State of Design Authority's design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD. You are required to ensure the product is airworthy before it is returned to service.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that

collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing, and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directive 2013-0186, dated August 16, 2013, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-0870.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Military All Operator Letter 235-025, dated July 29, 2013.

(ii) Airbus Military All Operator Letter 295-025, Revision 01, dated August 1, 2013.

(3) For service information identified in this AD, contact EADS-CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain; telephone +34 91 585 55 84; fax +34 91 585 55 05; email MTA.TechnicalService@casa.eads.net; Internet <http://www.eads.net>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 31, 2013.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-23-03 The Boeing Company: Amendment 39-17658; Docket No. FAA-2013-0871; Directorate Identifier 2013-NM-187-AD.

(a) Effective Date

This AD is effective November 29, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of the fracture of an inboard actuator attach fitting of the outboard flap. An inspection of the attach fitting revealed that it was incorrectly machined with a cylindrical profile instead of a conical profile, resulting in reduced wall thickness. We are issuing this AD to detect and correct defective inboard actuator attach fittings which, combined with loss of the outboard actuator load path, could result in uncontrolled retraction of the outboard flap, damage to flight control systems, and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Part Number Inspection

Within 90 days after the effective date of this AD: Inspect to determine the part number of the inboard actuator attach fittings of the outboard flaps, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013.

(h) Actions for Certain Attach Fittings

If, during the inspection required by paragraph (g) of this AD, any inboard actuator attach fitting having part number (P/N) 65B08564-7 is found, before further flight, do the actions specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Do a detailed inspection of the inboard actuator attach fitting for a cylindrical defect, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013. If any cylindrical defect is found, before further flight, do the actions specified in paragraph (h)(1)(i) or (h)(1)(ii) of this AD.

(i) Do a minimum thickness inspection of the inboard actuator attach fitting to determine minimum wall thickness of the actuator fitting assembly, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013. If the minimum thickness of the wall is less than 0.130 inch: Before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747 57A2343, dated September 12, 2013.

(ii) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013.

(2) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) If the service information contains steps that are labeled as RC (Required for Compliance), those steps must be done to comply with this AD; any steps that are not labeled as RC are recommended. Those steps that are not labeled as RC may be deviated from, done as part of other actions, or done using accepted methods different from those identified in the specified service information without obtaining approval of an AMOC, provided the steps labeled as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to steps labeled as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: nathan.p.weigand@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-57A2343, dated September 12, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 31, 2013.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-23-04 The Boeing Company: Amendment 39-17659; Docket No. FAA-2012-0426; Directorate Identifier 2011-NM-087-AD.

(a) Effective Date

This AD is effective December 20, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-600, -700, -800, -900, and -900ER series airplanes, with passenger seats installed; certificated in any category; as identified in Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 53: Fuselage.

(e) Unsafe Condition

This AD was prompted by reports that certain seat track bolts were found with severed bolt heads due to fatigue. We are issuing this AD to detect and correct missing or severed bolt heads, which, if not corrected, could result in the inability of the seat track to carry passenger loads, which could cause the seats to detach from the seat track, resulting in possible injury to passengers during an emergency landing or survivable crash.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Seat Track Bolt Replacement and Splice Strap Installation

Before the accumulation of 7,000 total flight cycles, or within 24 months after the effective date of this AD, whichever occurs later: Replace titanium seat track bolts with corrosion resistant steel (CRES) bolts at both the left and right sides of buttock lines 24.75 and 45.50, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011. If a titanium seat track bolt is found missing from the structure during the accomplishment of the tasks required by paragraph (g) of this AD: Before further flight, do a high frequency eddy current (HFEC) inspection for cracking in the fastener holes and a general visual inspection of the area, including the splice strap and forward seat track for damage, and replace missing bolts with new or serviceable CRES bolts, in accordance with the Accomplishment

Instructions of Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011. If cracking or damage is found: Before further flight, repair the seat track using a method approved in accordance with the procedures specified in paragraph (j) of this AD. If it is necessary to remove more parts for access, those parts may be removed. If access can be obtained without removing identified parts, it is not necessary to remove all identified parts. Jacking and shoring limitations should be observed.

(h) Detailed and HFEC Inspections

Before the accumulation of 7,000 total flight cycles, or within 24 months after the effective date of this AD, whichever occurs later: Do a detailed inspection and an HFEC inspection for cracking in the holes common to the splice strap and forward seat track at both the left and right sides of buttock lines 24.75 and 45.50, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011. Repeat the inspections thereafter at intervals not to exceed 7,000 flight cycles, until the actions specified in paragraph (i) of this AD have been done.

(1) If a crack is found in the splice strap during any inspection required by paragraph (h) of this AD: Before further flight, replace the seat track bolts and install a new splice strap part number (P/N) 146A5342-26 and retained angle at the affected location, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011.

(2) If a crack is found in the seat track during any inspection required by paragraph (h) of this AD, and Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011, specifies to contact Boeing for appropriate action: Before further flight, repair the seat track using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Optional Terminating Action

Replacing the titanium seat track bolts with CRES bolts on both the left and right sides of buttock lines 24.75 and 45.50 at station 727B, and installing a new splice strap P/N 146A5342-26, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011, terminates the repetitive inspections required by paragraph (h) of this AD.

Note 1 to paragraph (i) of this AD: Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011, contains an error in Step 1, "Move," of Figure 10, Sheet 5 of 7; and in Step 1, "Move," of Figure 12, Sheet 5 of 7. The splice strap needs to be centered with left buttock line 45.50 and right buttock line 45.50, respectively— not left buttock line 24.75, as stated in that service bulletin.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by Boeing Commercial Airplanes Organization Designation Authorization

(ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact Sarah Piccola, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6483; fax: 425-917-6590; email: sarah.piccola@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 737-53-1296, dated January 11, 2011.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 4, 2013.

Stephen P. Boyd,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2013-23-05 Fokker Services B.V.: Amendment 39-17660. Docket No. FAA-2013-0630; Directorate Identifier 2012-NM-213-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective December 20, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a design review, which revealed that, under certain failure conditions, wiring in the main fuel tank could develop a short circuit that might cause a hot spot on the wiring conduit or puncture the wiring conduit wall. We are issuing this AD to prevent an ignition source in the main fuel tank vapor space, which could result in a fuel tank explosion and consequent loss of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Installation of Fuses

Within 24 months after the effective date of this AD: Install fuses in the power supply wiring and return wiring, as applicable, for the reed-switches in the main fuel tank overflow valve, level control pilot valve solenoid, re/de-fuel shut off valve solenoid, and the collector-tank low level float switch, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-28-068, dated August 10, 2012, including the drawings specified in paragraphs (g)(1) through (g)(3) of this AD and the manual change notification specified in paragraph (g)(4) of this AD.

(1) Fokker Drawing W41192, Sheet 051, Issue AS (the issue date is not specified on the drawing).

(2) Fokker Drawing W41208, Sheet 002, Issue B (the issue date is not specified on the drawing).

(3) Fokker Drawing W59520, Sheet 002, Issue E, dated March 18, 2011.

(4) Fokker Manual Change Notification MCNM F100-143, dated August 10, 2012.

(h) Revision of Maintenance or Inspection Program

After installing the fuses as required by paragraph (g) of this AD, before further flight, revise the maintenance or inspection program, as applicable, by incorporating the critical design configuration control limitations (CDCCLs) specified in paragraph 1.L.(1)(c) of Fokker Service Bulletin SBF100-28-068, dated August 10, 2012, including the drawings specified in paragraphs (h)(1) through (h)(3) of this AD and the manual change notification specified in paragraph (h)(4) of this AD.

- (1) Fokker Drawing W41192, Sheet 051, Issue AS (the issue date is not specified on the drawing).
- (2) Fokker Drawing W41208, Sheet 002, Issue B (the issue date is not specified on the drawing).
- (3) Fokker Drawing W59520, Sheet 002, Issue E, dated March 18, 2011.
- (4) Fokker Manual Change Notification MCNM F100-143, dated August 10, 2012.

(i) No Alternative Intervals or CDCCLs

After the CDCCLs have been incorporated, as required by paragraph (h) of this AD, no alternative CDCCLs may be used unless the CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directive 2012-0241, dated November 12, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0630-0002>.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-28-068, dated August 10, 2012, including the drawings specified in paragraphs (1)(2)(i)(A) through (1)(2)(i)(C) of this AD and the manual change notification specified in paragraph (1)(2)(i)(D) of this AD.

(A) Fokker Drawing W41192, Sheet 051, Issue AS (the issue date is not specified on the drawing).

(B) Fokker Drawing W41208, Sheet 002, Issue B (the issue date is not specified on the drawing).

(C) Fokker Drawing W59520, Sheet 002, Issue E, dated March 18, 2011.

(D) Fokker Manual Change Notification MCNM F100-143, dated August 10, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 6, 2013.

Jeffrey E. Duven,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.