

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

LARGE AIRCRAFT

BIWEEKLY 2019-13

6/10/2019 - 6/23/2019



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
Biweekly 2019-01			
2018-22-07		Engine Alliance	GP7270, GP7272, and GP7277 model turbofan engines
2018-23-12	COR	Zodiac Aero Evacuation Systems	Fusible plugs installed on emergency evacuation equipment
2018-25-08	R 2017-22-07	Airbus SAS	A319, A320, A321 airplanes
2018-26-01	R 2018-18-01	CFM International S.A.	CFM56-7B turbofan engines
2018-26-03		The Boeing Company	757-200 series airplanes
2018-26-04		Airbus SAS	A350-941 and -1041 airplanes
2018-26-05	A 2015-19-01	The Boeing Company	777-200, 777-200LR, 777-300, 777-300ER, and 777F series airplanes
2018-26-06		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
Biweekly 2019-02			
2019-01-01		The Boeing Company	787-8 airplanes
Biweekly 2019-03			
2019-01-01	COR	The Boeing Company	787-8 airplanes
Biweekly 2019-04			
2018-23-04		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2018-24-01		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-01-03	R 2016-18-01	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-01-04		The Boeing Company	787 series airplanes
2019-01-05	A 2017-05-10	Airbus SAS	A330-201, A330-202, A330-223, A330-243, A330-223F, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes
2019-01-06		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-01-07		Airbus SAS	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2019-01-08		The Boeing Company	777-200, -200LR, -300, and -300ER series airplanes
2019-02-01	R 2018-16-07	General Electric Company	GEnx-1B54, -1B58, -1B64, -1B67, -1B70, -1B54/P1, -1B58/P1, -1B64/P1, -1B67/P1, -1B70/P1, -1B54/P2, -1B58/P2, -1B64/P2, -1B67/P2, -1B70/P2, -1B70C/P1, -1B70/P2, -1B70/P2, -1B70/P2, -1B74/P1, -1B75/P1, -1B70C/P2, -1B70/P2, -1B70/P2, -1B74/P2, -1B75/P2, -1B76/P2, -1B76A/P2, -1B78/P2, -2B67, -2B67B, and -2B67/P turbofan engines
2019-02-03		The Boeing Company	787-8, 787-9, and 787-10 airplane
2019-02-04	R 2018-22-05	Engine Alliance	GP7270, GP7272, and GP7277 turbofan engines
2019-03-01		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
Biweekly 2019-05			
2018-21-14		Zodiac Aerotechnics	MC10 series crew oxygen mask regulators
2018-26-07		Airbus SAS	A350-941 and -1041 airplanes
2018-26-08		Airbus SAS	Note: Was missing from BW2019-01 A320-214, A320-232, A320-233, A321-211, and A321-231 airplanes
2019-03-03	A 2016-17-03	Airbus SAS	Note: Was missing from BW2019-01 A318, A319, A320, A321 airplanes
2019-03-04	R 2018-11-16	Engine Alliance	GP7270 and GP7277 model turbofan engines
2019-03-06		The Boeing Company	737-300, -400, and -500 series airplanes
2019-03-07	R 2017-16-05	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-03-08		Airbus SAS	A350-941 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-03-09		Airbus SAS	A310-304, -322, -324, and -325 airplanes
2019-03-10	R 2017-07-05	Airbus SAS	A300 airplanes
2019-03-11		Airbus SAS	A350-941 and -1041 airplanes
2019-03-15		Airbus SAS	A330-201, -202, and -203; A330-301, -302, and -303 airplanes
2019-03-17	A 2017-25-04	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-19		Saab AB, Saab Aeronautics	SAAB 2000 airplanes
2019-03-20	A 2014-16-23 A 2016-16-09	Dassault Aviation	FALCON 7X airplanes
2019-03-21		Embraer S.A.	ERJ 190-100 STD, -100 LR, and -100 IGW; ERJ 190-200 STD, -200 LR, and -200 IGW airplanes
2019-03-23		Airbus SAS	A330, A340 airplanes
Biweekly 2019-06			
2019-03-13		Gulfstream Aerospace LP	Gulfstream G150 airplanes
2019-03-14		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes
2019-03-16	A 2006-25-06 A 97-04-08	Fokker Services B.V.	F.27 Mark 100, 200, 300, 400, 500, 600, and 700 airplanes
2019-03-18		Airbus SAS	A318, A319, A320 airplanes
2019-03-22		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2019-03-24		The Boeing Company	737-400 series airplanes
2019-03-25	A 2008-02-15	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-26		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-03-27		Dassault Aviation	Falcon 10 airplanes
2019-03-28	R 2016-07-23	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-30		Empresa Brasileira de Aeronautica S.A.	EMB-135, EMB-145 airplanes
2019-05-01	R 2017-11-06	Pratt & Whitney Division	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines
2019-05-02	R 2017-22-13	Rolls-Royce plc	RB211-Trent 970-84 and RB211-Trent 972-84 turbofan engines
2019-05-08	R 2015-12-08	Airbus SAS	A318, A319, A320, A321 airplanes
Biweekly 2019-07			
2019-05-07	R 2017-20-01	Honeywell International Inc.	TFE731-20R, -20AR, -20BR, and TFE731-40, -40AR, -40BR, and -40R turbofan engines
2019-05-09		Airbus SAS	A320-251N and -271N, and A321-253N airplanes
2019-05-10		Airbus SAS	A350-941 airplanes
2019-05-12		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2019-05-13	R 2007-22-05	Airbus SAS	A300-600 and A310 series airplanes
2019-05-14	R 2012-02-18	Dassault Aviation	MYSTERE-FALCON 50 airplanes
2019-06-01	R 2018-24-01	International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-06-02		Pratt & Whitney Division	PW4158 turbofan engines
2019-06-06		International Aero Engines AG	V2500-A1, V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2533-A5 turbofan engines
2019-06-07	R 2016-22-05	Pratt & Whitney Division	Certain PW4000 engines (see AD)
Biweekly 2019-08			
2019-06-01	R 2018-24-01	International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-06-02	COR	Pratt & Whitney Division	PW4158 turbofan engines
2019-06-03	A 2017-01-08	Airbus SAS	A330 and A340 airplanes
2019-06-08		Airbus SAS	A330-223, A330-223F, A330-321, A330-322, and A330-323 airplanes
2019-06-09		Airbus SAS	A350-941 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-06-12		Airbus SAS	A330-201, -202, and -203; A330-301, -302, and -303 airplanes
2019-07-03		Zodiac Seats France	536-Series Cabin Attendant Seats
Biweekly 2019-09			
2019-07-01	A 2014-26-07	Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes
2019-07-04	COR	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2019-07-05	R 2016-19-04	Airbus SAS	A318, A319, A320 and A321 airplanes
2019-07-06		Bombardier, Inc	Model BD-100-1A10 airplanes
2019-07-09		Rolls-Royce plc	Trent 1000-A2, Trent 1000-AE2, Trent 1000-C2, Trent 1000-CE2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 model turbofan engines
Biweekly 2019-10			
2019-03-29		Bombardier, Inc	Model BD-100-1A10 airplanes
2019-06-13		The Boeing Company	Model 787 series airplanes
2019-07-05	COR, A 2016-19-04	Airbus SAS	A318, A319, A320 airplanes
2019-08-01		RECARO Aircraft Seating GmbH & Co. KG	Passenger Compartment Equipment
2019-08-02		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-08-05		The Boeing Company	Model 787-8 and 787-9 airplanes
2019-08-06	R 2016-16-01	Airbus SAS	A330-223F and -243F, A330-201, -202, -203, -223, -243 A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2019-08-09	A 2017-04-13	The Boeing Company	Model 747-8 and 747-8F series airplanes
2019-08-12		Viking Air Limited	Model CL-215-6B11 (CL-215T Variant) and CL-215-6B11 (CL-415 Variant)
Biweekly 2019-11			
2019-08-03		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-08-07	R 2014-20-04	Airbus SAS	A318, A319, A320 and A321 airplanes
2019-08-08	R 2010-14-05	Bombardier, Inc.	Model CL-600-1A11 (600), Model CL-600-2A12 (601), Model CL-600-2B16 airplanes
2019-09-01		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
Biweekly 2019-12			
2019-08-04	R 2012-25-02	Bombardier, Inc.	Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2019-08-11	R 2008-24-14	Bombardier, Inc.	Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2019-10-03		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-10-04		BRP-Rotax GmbH & Co KG	BRP-Rotax GmbH & Co KG (Rotax) 912 F2, 912 F3, and 912 F4 engines, Rotax 912 S2, 912 S3, and 912 S4 engines, Rotax 914 F2, 914 F3, and 914 F4 engines, and Rotax 912 F2, 912 F3, 912 F4, 912 S2, 912 S3, 912 S4, 914 F2, 914 F3, and 914 F4 engines
2019-10-05		Viking Air Limited	Models DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2019-13

2019-10-01		Bombardier, Inc	Model CL-600-2A12 (601) airplanes
2019-11-01		Airbus SAS	Model A350-941 airplanes
2019-11-02	R 2017-16-10	The Boeing Company	Model 777-200, -200LR, -300, -300ER, and 777F series airplanes
2019-11-03		The Boeing Company	Model 737-700C, -800, and -900ER series airplanes
2019-11-06	A 2013-19-23	The Boeing Company	Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-11-07		Rolls-Royce plc	RB211-524G2-19, RB211-524G2-T-19, RB211-524G3-19, RB211-524G3-T-19, RB211-524H2-19, RB211-524H2-T-19, RB211-524H-36 and RB211-524H-T-36 engines
2019-11-08		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines
2019-11-09		Airbus SAS	Model A319-113 and -114 airplanes, and Model A320-211 and -212 airplanes
2019-12-01		CFM International S.A	LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B3, -1B28B2C, -1B28BBJ1, and -1B28BBJ2 model turbofan engines
2019-12-05		CFM International S.A	CFM56-5B1, -5B2, -5B4, -5B5, -5B6, -5B7, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B7/P, -5B8/P, -5B9/P, -5B3/P1, -5B4/P1, -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P, -5B9/2P, -5B3/2P1, -5B4/2P1, -7B20, -7B22, -7B24, -7B26, -7B27, -7B22/B1, -7B24/B1, -7B26/B1, -7B26/B2, -7B27/B1, -7B27/B3, -7B20/2, -7B22/2, -7B24/2, -7B26/2, -7B27/2, -7B27A model turbofan engines



2019-10-01 Bombardier, Inc.: Amendment 39-19640; Docket No. FAA-2019-0024; Product Identifier 2018-NM-138-AD.

(a) Effective Date

This AD is effective July 18, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model CL-600-2A12 (601) airplanes, certificated in any category, serial numbers (S/N) 3001 through 3009 inclusive and 3011 through 3029 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by a report of damage to the anti-rotation tab on a main landing gear (MLG) side brace fitting due to the installation of an incorrect side brace fitting shaft. We are issuing this AD to address premature cracking of the MLG side brace fitting. This condition, if not corrected, could lead to the collapse of the MLG, resulting in structural damage to the wing spar and fuel tank.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection for Damage and Identification of the Side Brace Fitting Shaft Part Number

Within 400 flight cycles or 12 months, whichever occurs first, after the effective date of this AD, do the actions specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) Identify the part number of the installed side brace fitting shaft.

(2) Do a detailed visual inspection (DVI) of the side brace fitting for signs of damage, including cracking and gouges, in accordance with paragraph 2.B. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(h) Installation of Anti-Rotation Bracket

(1) For airplanes on which a side brace fitting shaft having P/N 600-10237-3 is installed and the actions required by paragraph (g) of this AD are done on or after the effective date of this AD: Before

further flight, modify the MLG side brace fitting by installing the anti-rotation bracket in accordance with paragraph 2.C. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(2) For airplanes on which a side brace fitting shaft having P/N 600-10237-3 is installed and the actions required by paragraph (g) of this AD were done before the effective date of this AD: Within 6 months after the effective date of this AD, modify the MLG side brace fitting by installing the anti-rotation bracket in accordance with paragraph 2.C. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(i) Replacement of the Side Brace Fitting Shaft and Installation of the Anti-Rotation Bracket

(1) For airplanes on which a side brace fitting shaft having P/N 600-10237-1 or 600-10237-5 is installed and damage is found during the DVI of the side brace fitting: Before further flight, do a DVI of the anti-rotation tab and side brace fitting aft bushing for cracking, scratches, gouges, corrosion, and inner diameter tolerance, and a special detailed inspection (SDI) of the side brace fitting aft bore for cracks and defects; perform applicable repairs; replace the side brace fitting shaft with a side brace fitting shaft having P/N 600-10237-3; and install the anti-rotation bracket in accordance with paragraph 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(2) For airplanes on which a side brace fitting shaft having P/N 600-10237-1 or 600-10237-5 is installed and no damage is found during the DVI of the side brace fitting: Within 300 flight cycles or 12 months, whichever occurs first, after the inspection required by paragraph (g)(2) of this AD, do a DVI of the anti-rotation tab and side brace fitting aft bushing for cracking, scratches, gouges, corrosion, and inner diameter tolerance, and an SDI of the side brace fitting aft bore for cracks and defects; perform applicable repairs; replace the side brace fitting shaft with a side brace fitting shaft having P/N 600-10237-3; and install the anti-rotation bracket in accordance with paragraph 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(j) Exceptions to Service Information

Where Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018, specifies contacting Bombardier's Customer Support Engineering for repair instructions: This AD requires doing the repair before further flight using a method approved in accordance with the procedures specified in paragraph (l)(2) of this AD.

(k) Credit for Previous Actions

(1) For an airplane on which a side brace fitting shaft having P/N 600-10237-3 is installed: This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 601-0624, dated October 1, 2012; or Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017.

(2) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 601-0624, dated October 1, 2012; or Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017, provided that the side brace fitting shaft was identified as having P/N 600-10237-3 and within 6 months after the effective date of this AD, the MLG side brace fitting is modified by installing the anti-rotation bracket in accordance with paragraph 2.C. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(3) This paragraph provides credit for actions required by paragraphs (g) and (i) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin

601-0624, Revision 01, dated March 29, 2017, provided that any side brace fitting shaft having P/N 600-10237-1 or P/N 600-10237-5 was identified and replaced with a side brace fitting shaft having P/N 600-10237-3, and the anti-rotation bracket was installed in accordance with paragraph 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-19, dated July 20, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0024.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516-287-7329; fax: 516-794-5531; email: Aziz.Ahmed@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone: 1-866-538-1247 or direct-dial telephone: 1-514-855-2999; email: ac.yul@aero.bombardier.com; internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 29, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-11-01 Airbus SAS: Amendment 39-19647; Docket No. FAA-2019-0405; Product Identifier 2019-NM-003-AD.

(a) Effective Date

This AD becomes effective June 28, 2019.

(b) Affected ADs

This AD replaces AD 2018-25-12, Amendment 39-19523 (83 FR 64230, December 14, 2018) (“AD 2018-25-12”).

(c) Applicability

This AD applies to Airbus SAS Model A350-941 airplanes, certificated in any category, as identified in European Aviation Safety Agency (EASA) AD 2018-0290, dated December 21, 2018 (“EASA AD 2018-0290”).

(d) Subject

Air Transport Association (ATA) of America Code 55, Stabilizers.

(e) Reason

This AD was prompted by a determination that certain holes for the vertical tail plane (VTP) tension bolts connection are not properly protected against corrosion. We are issuing this AD to address corrosion of the VTP tension bolts connection, which could reduce the structural integrity of the VTP, and could ultimately lead to reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2018-0290.

(h) Exceptions to EASA AD 2018-0290

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2018-0290 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2018-0290 refers to a compliance time after March 1, 2018, this AD requires using January 18, 2019 (the effective date of AD 2018-25-12).

(3) The “Remarks” section of EASA AD 2018-0290 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2018-0290 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018-0290, dated December 21, 2018.

(ii) [Reserved]

(3) For EASA AD 2018-0290, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2018-0290 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0405.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 29, 2019.
Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-11-02 The Boeing Company: Amendment 39-19648; Docket No. FAA-2019-0407; Product Identifier 2019-NM-075-AD.

(a) Effective Date

This AD is effective July 5, 2019.

(b) Affected ADs

This AD replaces AD 2017-16-10, Amendment 39-18987 (82 FR 39513, August 21, 2017) (“AD 2017-16-10”).

(c) Applicability

This AD applies to The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks on the underwing longerons. The FAA is issuing this AD to address cracks in the underwing longerons, which could result in fuel leakage into the forward cargo area and consequent increased risk of a fire or, in a more severe case, could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019. Replacing an underwing longeron, including doing all applicable on-condition actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, except as required by paragraph (h)(2) of this AD, terminates the repetitive inspections specified in tables 1 through 6 and table 15 of paragraph 1.E.,

“Compliance,” of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, for that longeron only.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, uses the phrase “the Revision 2 date of this service bulletin,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016, or Boeing Alert Service Bulletin 777-53A0081, Revision 1, dated May 1, 2017.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2017-16-10 are approved as AMOCs for the corresponding provisions of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, that are required by paragraph (g) of this AD.

(5) Except as specified by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(5)(i) and (j)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3523; email: eric.lin@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 5, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-11-03 The Boeing Company: Amendment 39-19649; Docket No. FAA-2019-0409; Product Identifier 2019-NM-092-AD.

(a) Effective Date

This AD is effective June 10, 2019.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-700C, -800, and -900ER series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019.

(2) Installation of Supplemental Type Certificate (STC) ST00830SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST00830SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by a report that certain main slat track assemblies were manufactured incorrectly and are affected by hydrogen embrittlement. The FAA is issuing this AD to address main slat track assemblies that have reduced strength due to hydrogen embrittlement. This condition, if not addressed, could result in failure of main slat track assemblies, which could cause the slat to depart and potentially strike the airplane, resulting in injury to airplane occupants and/or preventing continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-27A1312, dated June 4, 2019, which is referred to in Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, uses the phrase “the original issue date of Requirements Bulletin 737-27A1312 RB,” this AD requires using “the effective date of this AD.”

(2) Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, specifies to report inspection results to Boeing within a certain compliance time. For this AD, the compliance time to report inspection results is at the applicable time specified in paragraph (h)(2)(i) or (h)(2)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 3 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 3 days after the effective date of this AD.

(3) Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, specifies to ship affected parts to Boeing within a certain compliance time if, during the inspection, it has been determined that any main slat track assembly has a suspect lot number or has a lot number that cannot be determined. For this AD, the compliance time for shipping affected parts to Boeing is at the applicable time specified in paragraph (h)(3)(i) or (h)(3)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Ship the affected part to Boeing within 30 days after removing the affected part.

(ii) If the inspection was done before the effective date of this AD: Ship the affected part to Boeing within 30 days after the effective date of this AD.

(4) Where “CONDITION 5” of Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, uses the phrase “suspect lot number cannot be determined,” or “suspect lot number that cannot be determined,” this AD requires using, “lot number cannot be determined,” or “lot number that cannot be determined;” respectively.

(5) Where flag note (a) of Figure 5, Figure 6, Figure 7, and Figure 8, of Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019, specifies “Only required if the main slat track assembly has a suspect lot number,” this AD requires using, “Only required if the main slat track assembly has a suspect lot number or a lot number that cannot be determined.”

(i) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact Greg Rutar, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3529; email: Greg.Rutar@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-27A1312 RB, dated June 4, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 5, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-11-06 The Boeing Company: Amendment 39-19652; Docket No. FAA-2018-0708; Product Identifier 2018-NM-072-AD.

(a) Effective Date

This AD is effective July 17, 2019.

(b) Affected ADs

This AD affects AD 2013-19-23, Amendment 39-17605 (78 FR 61173, October 3, 2013) (“AD 2013-19-23”).

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018.

(2) Installation of Supplemental Type Certificate (STC) ST00830SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST00830SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks in the skin and the station (STA) 540 bulkhead chord at the three fastener locations common to the drag link assembly at the STA 540 bulkhead chord. The FAA is issuing this AD to address cracking in the STA 540 bulkhead chord or skin, which could result in the inability of a primary structural element to sustain limit load. This condition, if not addressed, could result in possible rapid decompression and loss of structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as required by paragraphs (h)(1) through (h)(5) of this AD: At the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, do all applicable actions identified as “RC” (required for compliance) in, and in

accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, specifies contacting Boeing: This AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(3) If any action(s) identified as RC in Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, cannot be accomplished as specified therein, those action(s) must be accomplished using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(4) Parts 8, 9, 10, and 11 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, specify post-repair/modification airworthiness limitation inspections in compliance with 14 CFR 25.571(a)(3) at the repaired/modified locations to support compliance with 14 CFR 121.1109(c)(2) or 129.109(b)(2). Although Parts 8, 9, 10, and 11 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, are identified as RC, this AD does not require accomplishment of Parts 8, 9, 10, and 11 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018. As airworthiness limitations, these inspections are required by maintenance and operational rules. It is therefore unnecessary to mandate them in this AD. Deviations from these inspections require FAA approval, but do not require approval of an AMOC.

(5) For airplanes on which any crack is found during any Part 2 inspection specified in Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, and no crack is found during the Part 3 inspection specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018: Before further flight, do the preventative modification specified in Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, on each side of the airplane on which no crack was found during the Part 3 inspection.

(i) Optional Terminating Action for Repetitive Inspections

(1) Accomplishment of the repair in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, terminates the repetitive inspections specified in Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, on the side of the airplane on which the repair was done, as required by paragraph (g) of this AD.

(2) Accomplishment of the preventive modification in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, terminates the repetitive inspections specified in Part 2 or Part 6, as applicable, of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, on the side of the airplane on which the preventive modification was done, as required by paragraph (g) of this AD.

(j) Optional Terminating Action for Certain Requirements of AD 2013-19-23

Accomplishment of the repair specified in Part 4 or the modification specified in Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018, terminates the repetitive inspections specified in the airworthiness limitations required by

paragraph (g) of AD 2013-19-23 for Principal Structural Element (PSE) 53-30-02-4 on the side of the airplane on which the repair or modification was done.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified in paragraphs (h)(2) through (h)(5) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3527; email: alan.pohl@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1368, dated February 27, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. (5) You may view this service information that is incorporated by reference at the National

Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 29, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-12322 Filed 6-11-19; 8:45 am]



2019-11-07 Rolls-Royce plc: Amendment 39-19653; Docket No. FAA-2019-0338; Product Identifier 2019-NE-10-AD.

(a) Effective Date

This AD is effective June 28, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Rolls-Royce plc (RR) RB211-524G2-19, RB211-524G2-T-19, RB211-524G3-19, RB211-524G3-T-19, RB211-524H2-19, RB211-524H2-T-19, RB211-524H-36 and RB211-524H-T-36 engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by unauthorized repairs to the affected low-pressure compressor (LPC) shafts that reduced their expected life. The FAA is issuing this AD to prevent failure of the LPC shaft. The unsafe condition, if not addressed, could result in uncontained release of the LPC shaft, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 30 days from the effective date of this AD or before exceeding 10,500 flight cycles (FCs) since new, whichever occurs later, remove LPC shaft, part number (P/N) UL24833, with serial numbers (S/Ns) PATH3113; PATH3121; PAVN1765, PAVN1853, PAVN2152, PAVN2157, PAVN2259, PAVN2636, PAVN2991, or PAVN2992.

(h) Installation Prohibition

After the effective date of this AD, do not install an LPC shaft, P/N UL24833 and with S/Ns PATH3113; PATH3121; PAVN1765, PAVN1853, PAVN2152, PAVN2157, PAVN2259, PAVN2636, PAVN2991, or PAVN2992, with 10,500 FCs since new, or greater, on any engine.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Eugene Triozzi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7148; fax: 781-238-7199; email: Eugene.triozzi@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2018-0157, dated July 24, 2018, for more information. You may examine the EASA AD in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2019-0338.

(k) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 6, 2019.
Robert J. Ganley,
Manager, Engine and Propeller Standards Branch,
Aircraft Certification Service.



2019-11-08 International Aero Engines: Amendment 39-19654; Docket No. FAA-2019-0393; Product Identifier 2019-NE-14-AD.

(a) Effective Date

This AD is effective June 28, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all International Aero Engines, LLC (IAE) PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7260, Turbine Engine Accessory Drive.

(e) Unsafe Condition

This AD was prompted by multiple reports of in-flight engine shutdowns as the result of high-cycle fatigue causing fracture of certain parts of the main gearbox (MGB) assembly. The FAA is issuing this AD to prevent failure of the MGB assembly. The unsafe condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Remove the MGB assembly, part number (P/N) 5322505, and install a part eligible for installation as follows:

(i) For engines that operate on 180-minute extended operations (ETOPS) flights, within 90 days from the effective date of this AD;

(ii) For engines that operate on 120-minute ETOPS flights, within 120 days from the effective date of this AD.

(2) For engines with MGB assembly P/N 5322505, within 120 days from the effective date of this AD, remove electronic engine control (EEC) software earlier than FCS 5.0 from the engine and load EEC software that is eligible for installation.

(h) Installation Prohibition

(1) After the effective date of this AD, do not install integrated drive generator (IDG) oil pump drive gearshaft assembly, P/N 5322630-01, into an MGB assembly.

(2) After the effective date of this AD, do not load EEC software earlier than FCS 5.0 on any engine identified in paragraph (c) of this AD with an MGB assembly, P/N 5322505.

(i) Definitions

(1) For the purpose of this AD, a “part eligible for installation” is an MGB assembly with an IDG oil pump drive gearshaft assembly other than P/N 5322630-01.

(2) For the purpose of this AD, “EEC software that is eligible for installation” is EEC software FCS 5.0 and later.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Kevin M. Clark, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7088; fax: 781-238-7199; email: kevin.m.clark@faa.gov.

(l) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 6, 2019.

Robert J. Ganley,
Manager, Engine & Propeller Standards Branch,
Aircraft Certification Service.



2019-11-09 Airbus SAS: Amendment 39-19655; Docket No. FAA-2018-1068; Product Identifier 2018-NM-140-AD.

(a) Effective Date

This AD is effective July 25, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A319-113 and -114 airplanes, and Model A320-211 and -212 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Reason

This AD was prompted by a report that a life-limit of 64,000 flight cycles has been established for certain titanium crossbeams of the forward engine mount. The FAA is issuing this AD to address failure of a crossbeam of the forward engine mount, which could result in detachment of the engine and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with European Aviation Safety Agency (EASA) AD 2018-0212, dated September 28, 2018 (“EASA AD 2018-0212”), or EASA AD 2018-0212R1, dated March 28, 2019 (“EASA AD 2018-0212R1”).

(h) Exceptions to EASA ADs 2018-0212 and 2018-0212R1

(1) For purposes of determining compliance with the requirements of this AD: Where EASA ADs 2018-0212 and 2018-0212R1 refer to the effective date of EASA AD 2018-0212 (October 12, 2018), this AD requires using the effective date of this AD.

(2) Where paragraph (2) of EASA ADs 2018-0212 and 2018-0212R1 specifies replacing “with instructions provided by Airbus,” for this AD, the replacement must be done using a method approved in accordance with the procedures specified in paragraph (i)(2) of this AD.

(3) Where paragraphs (1) and (3) of EASA ADs 2018-0212 and 2018-0212R1 specify flight cycles (FC), this AD requires using “total flight cycles.”

(4) The “Remarks” sections of EASA ADs 2018-0212 and 2018-0212R1 do not apply.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2018-0212 or EASA AD 2018-0212R1 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018-0212, dated September 28, 2018.

(ii) European Aviation Safety Agency (EASA) AD 2018-0212R1, dated March 28, 2019.

(3) For EASA AD 2018-0212 and EASA AD 2018-0212R1, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find these EASA ADs on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view these EASA ADs at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2018-0212 and EASA AD 2018-0212R1 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1068.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 10, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-12-01 CFM International S.A.: Amendment 39-19656; Docket No. FAA-2019-0414; Product Identifier 2019-NE-15-AD.

(a) Effective Date

This AD is effective July 3, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all CFM International S.A. (CFM) LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B3, -1B28B2C, -1B28BBJ1, and -1B28BBJ2 model turbofan engines with radial drive shaft (RDS) bearing, part number (P/N) 92D08200 or P/N 92D08201, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7260, Turbine Engine Accessory Drive.

(e) Unsafe Condition

This AD was prompted by multiple reports of in-flight shutdowns (IFSDs) due to RDS bearing cage failure. The FAA is issuing this AD to prevent failure of the RDS bearing. The unsafe condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Inspect the transfer gearbox (TGB) 1 and TGB2 scavenge screens in accordance with the Accomplishment Instructions, paragraph 5.A.(1), of CFM Service Bulletin (SB) LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019, as follows:

(i) For affected engines with engine serial number (ESN) 602499 and lower:

(A) After the RDS bearing accumulates 50 flight hours (FHs) since new but before accumulating 250 FHs since new, or within 50 FHs after the effective date of this AD, whichever occurs later, perform an initial inspection of the TGB1 and TGB2 scavenge screens.

(B) Thereafter, perform repetitive inspections of the TGB1 and TGB2 scavenge screens at intervals not exceeding 250 FHs since the last inspection.

(ii) For affected engines with ESN 602500 and higher:

(A) After the RDS accumulates 50 FHs since new but before accumulating 100 FHs since new, or within 50 FHs after the effective date of this AD, whichever occurs later, perform an initial inspection of the TGB1 and TGB2 scavenge screens.

(B) Thereafter, perform repetitive inspections of the TGB1 and TGB2 scavenge screens at intervals not exceeding 100 FHs since the last inspection.

(iii) Based on the results of these inspections, remove the engine from service or return the engine to service using the criteria in the Accomplishment Instructions, Paragraphs 5.A.(2) through 5.A.(5), of CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019.

(2) [Reserved]

(h) Optional Borescope Inspection (BSI)

(1) Once the RDS bearing has accumulated 1,000 FHs since new, you may perform a BSI of the RDS bearing in accordance with the Accomplishment Instructions, paragraphs 5.B.(1) through 5.B.(8), of CFM SB LEAP-1B-72-00-0222-01A-930A-D dated May 17, 2019. If the results of this BSI are “satisfactory” according to the criteria in the Accomplishment Instructions, paragraphs 5.B.(6)(g), of CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019, then you are not required to perform the repetitive inspections in paragraphs (g)(1)(i)(B) or (g)(1)(ii)(B) of this AD until the RDS bearing accumulates 4,250 FHs since new.

(2) [Reserved]

(i) Optional Terminating Action

(1) As an optional terminating action to the repetitive inspections required by paragraphs (g)(1)(i)(B) and (g)(1)(ii)(B) of this AD, you may perform a BSI of the RDS bearing in accordance with the Accomplishment Instructions, Paragraphs 5.B.(1) through 5.B.(8), of CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019 after the RDS bearing accumulates 3,750 FHs since new.

(i) If the results of the BSI are “satisfactory” using the criteria in Accomplishment Instructions, paragraph 5.B.(6)(g), of CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019, then you have met the repetitive inspection requirements of this AD and no further action is required.

(ii) If the results of the BSI are “unsatisfactory” using the criteria in Accomplishment Instructions, paragraph 5.B.(6)(g), of CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019, then you must continue the repetitive inspections required by paragraphs (g)(1)(i)(B) or (g)(1)(ii)(B) of this AD.

(2) [Reserved]

(j) Definition

For the purpose of this AD, “flight hours (FHs) since new” are the FHs accumulated on the RDS bearings on new engines delivered from production and on engines that have had the RDS bearing replaced during an engine shop visit.

(k) No Reporting Requirement

The reporting requirement in paragraph 5.A.(6) in CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019, is not required by this AD.

(l) Credit for Previous Actions

You may take credit for the inspections that are required by paragraph (g)(1) of this AD, if you performed those actions before the effective date of this AD using CFM SB LEAP-1B-72-00-0222-01A-930A-D, Issue 006, dated March 22, 2019, or an earlier revision. You may also take credit for the optional BSI in paragraphs (h)(1) or the optional terminating inspection in paragraph (i)(1) of this AD, if you performed that action before the effective date of this AD using CFM SB LEAP-1B-72-00-0256-01A-930A-D, Issue 002, dated May 6, 2019, or an earlier revision.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (n) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(n) Related Information

For more information about this AD, contact Christopher McGuire, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7120; fax: 781-238-7199; email: chris.mcguire@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) CFM Service Bulletin LEAP-1B-72-00-0222-01A-930A-D, Issue 007, dated May 17, 2019.

(ii) [Reserved]

(3) For CFM service information identified in this AD, contact CFM International Inc., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH, 45125; phone: 877-432-3272; fax: 877-432-3329; email: aviation.fleetsupport@ge.com.

(4) You may view this service information at FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on June 14, 2019.

Karen M. Grant,

Acting Manager, Engine & Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2019-13022 Filed 6-17-19; 8:45 am]



2019-12-05 CFM International S.A.: Amendment 39-19660; Docket No. FAA-2019-0212; Product Identifier 2019-NE-05-AD.

(a) Effective Date

This AD is effective July 5, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to:

(1) CFM International S.A. (CFM) CFM56-5B1, -5B2, -5B4, -5B5, -5B6, -5B7, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B7/P, -5B8/P, -5B9/P, -5B3/P1, -5B4/P1, -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P, -5B9/2P, -5B3/2P1, -5B4/2P1, -7B20, -7B22, -7B24, -7B26, -7B27, -7B22/B1, -7B24/B1, -7B26/B1, -7B26/B2, -7B27/B1, -7B27/B3, -7B20/2, -7B22/2, -7B24/2, -7B26/2, -7B27/2, -7B27A model turbofan engines with a:

(i) rotating air high-pressure turbine (HPT) front seal:

(A) with part number (P/N) 1795M36P01 or P/N 1795M36P02 and serial numbers (S/Ns) GWNDN949 through GWNSE969 or S/Ns GWN000CE through GWN0990L, not including S/Ns GWN08ND7, GWN0923A, GWN0971E, GWN098A1, GWN098W6, GWN098W8, GWN098WA, and GWN0990G, installed;

(B) that has been removed from the original HPT disk and re-assembled to a different HPT disk; and

(C) that has 6,001 or more cycles since being reconfigured.

(ii) [Reserved]

(2) CFM CFM56-5C2, -5C2/4, -5C2/F, -5C2/F4, -5C2/G, -5C2/G4, -5C2/P, -5C3/F, -5C3/F4, -5C3/G, -5C3/G4, -5C3/P, -5C4, -5C4/1, -5C4/P, -5C4/1P model turbofan engines with a:

(i) rotating air HPT front seal:

(A) with P/N 1795M36P01 or P/N 1795M36P02 and S/Ns GWNDN949 through GWNSE969 or S/Ns GWN000CE through GWN0990L, not including S/Ns GWN08ND7, GWN0923A, GWN0971E, GWN098A1, GWN098W6, GWN098W8, GWN098WA, and GWN0990G, installed;

(B) that has been removed from the original HPT disk and re-assembled to a different HPT disk; and

(C) that has 3,751 or more cycles since being reconfigured.

(ii) [Reserved]

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by cracks found in the rotating air HPT front seal. The FAA is issuing this AD to prevent failure of the rotating air HPT front seal. The unsafe condition, if not addressed, could result in the uncontained release of the rotating air HPT front seal, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For all affected CFM CFM56-5B and CFM56-7B model turbofan engines:

(i) If, on the effective date of this AD, the rotating air HPT front seal has 7,000 cycles or greater since being reconfigured, remove the part from service within 50 cycles after the effective date of this AD and replace with a part eligible for installation.

(ii) If, on the effective date of this AD, the rotating air HPT front seal has between 6,001 and 6,999 cycles, inclusive, since being reconfigured, remove the part from service within 500 cycles after the effective date of this AD, but not to exceed 7,050 cycles since being reconfigured, and replace with a part eligible for installation.

(2) For all affected CFM CFM56-5C model turbofan engines:

(i) If, on the effective date of this AD, the rotating air HPT front seal has 4,250 cycles or greater since being reconfigured, remove the part from service within 25 cycles after the effective date of this AD, or within 1,500 cycles since the last fluorescent penetrant inspection (FPI) of the rotating air HPT front seal, whichever occurs later, and replace with a part eligible for installation.

(ii) If, on the effective date of this AD, the rotating air HPT front seal has between 3,751 and 4,249 cycles, inclusive, since being reconfigured, remove the part from service within 250 cycles after the effective date of this AD, before accumulating 4,275 cycles since being reconfigured, or within 1,500 cycles since the last FPI of the rotating air HPT front seal, whichever occurs later, and replace with a part eligible for installation.

(h) Definition

For the purpose of this AD, reconfigured is when a rotating air HPT front seal has been removed from the original HPT disk and re-assembled to a different HPT disk.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Christopher McGuire, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7120; fax: 781-238-7199; email: chris.mcguire@faa.gov.

(k) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 14, 2019.

Karen M. Grant,
Acting Manager, Engine and Propeller Standards Branch,
Aircraft Certification Service.