

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

LARGE AIRCRAFT

BIWEEKLY 2017-13

6/12/2017 - 6/25/2017



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2017-01			
2016-25-01		The Boeing Company	747-400, 747-400D, and 747-400F series; 757-200, -200PF, -200CB, and -300 series; 767-200, -300, -300F, and -400ER series; 767-300 and -300F series; and 767-300 and -300F series
2016-25-07	R 2012-11-15	The Boeing Company	767-200 and -300 series
2016-25-25		BAE (Operations) Limited	4101
2016-25-26		The Boeing Company	MD-90-30
2016-25-27		Airbus	A300 B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R variant F
2016-25-29		The Boeing Company	767-200 and -300 series
2016-25-30		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; A340-642
2016-25-31		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313; A340-541; and A340-642
2016-26-02		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705); and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000)
2016-26-03	R 2013-23-02	Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295
2016-26-05	R 2014-26-08	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2017-01-07		Dassault Aviation	FAN JET FALCON; FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON
2017-01-08		Airbus	20-C5, 20-D5, 20-E5, and 20-F5; MYSTERE-FALCON 50
2016-25-02		The Boeing Company	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342 and -343 airplanes; and Model A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-25-02		The Boeing Company	787-8 series
Biweekly 2017-02			
2016-26-06		The Boeing Company	787-8 airplanes
2016-26-07		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes
2017-01-01	R 2014-05-25	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2017-01-02		The Boeing Company	787-8 and 787-9 airplanes
2017-01-04		Fokker Services B.V.	F28 Mark 0100 airplanes
2017-01-05		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, and CN-235-300 airplanes
2017-01-06		Airbus	A319-115, A319-132, A320-214, A320-232, A321-211, A321-213, and A321-231 airplanes
2017-01-09		The Boeing Company	767-300 and 767-300F series airplanes
2017-01-10		Airbus Defense and Space S.A.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, C-212-CF, C-212-DF, and C-212-DE airplanes
2017-01-11		Airbus	A318, A319, A320, A321 airplanes
Biweekly 2017-03			
No ADs			
Biweekly 2017-04			
2017-01-03	R 2007-11-13	The Boeing Company	717-200 airplanes
2017-01-09	COR	The Boeing Company	767-300 and 767-300F series airplanes
2017-01-11		Airbus	A318, A319, A320, A321 airplanes
2017-02-02	2005-13-30	The Boeing Company	737-100, -200, and -200C series airplanes
2017-02-03		The Boeing Company	767-200, -300, and -400ER series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-02-04		The Boeing Company	747-200B, 747-300, 747-400, 747-400D, and 747-400F series airplanes
2017-02-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-02-08		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes
2017-02-09		The Boeing Company	747-400, -400D, and -400F series airplanes
2017-02-10	R 2013-19-04	The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-03-02	S 2014-16-10	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
Biweekly 2017-05			
2017-02-01		Rolls-Royce plc	Trent 1000-A, Trent 1000-C, Trent 1000-D, Trent 1000-E, Trent 1000-G, and Trent 1000-H turbofan engines
2017-02-12		The Boeing Company	737-300, -400, and -500 series airplanes
2017-03-03	S 2013-05-18	Rolls-Royce plc	RB211 Trent 553-61, RB211 Trent 553A2-61, RB211 Trent 556-61, RB211 Trent 556A2-61, RB211 Trent 556B-61, RB211 Trent 556B2-61, RB211 Trent 560-61, and RB211 Trent 560A2-61 turbofan engines
2017-03-04	R 2012-16-07	The Boeing Company	737-500 series airplanes
2017-04-01		Gulfstream Aerospace Corporation	GVI airplanes
2017-04-02	R 2014-23-06	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2017-04-04	R 2012-16-08	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes
2017-04-05	R 2011-10-17	Airbus	A300 B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, and B4-203 airplanes
2017-04-06		United Instruments, Inc.	5934 series altimeters
2017-04-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2017-04-08	R 2008-13-12 R1	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-04-09	R 2012-22-12	Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-04-10		Airbus	A318, A319, A320, A321 airplanes
2017-04-11		The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-04-12		Embraer	EMB-135, EMB-145 airplanes
2017-04-13		The Boeing Company	747-8 and 747-8F series airplanes
2017-04-15		Learjet Inc.	36A airplanes
2017-05-01		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2017-05-02		Airbus	A318, A319, A320, A321 airplanes
2017-05-06		The Boeing Company	767-200 and -300 series airplanes
2017-05-07		The Boeing Company	777-200 and -300 series airplanes
Biweekly 2017-06			
2017-05-09		CFM International S.A.	CFM56-5B, CFM56-5B/P, CFM56-5B/3, CFM56-5B/2P, CFM56-5B/P1, CFM56-5B/2P1, and CFM56-5B/3B1 engines
2017-05-11	R 2012-08-11	Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-05-10	R 2015-16-02	Airbus	A330-201, A330-202, A330-203, A330-223, A330-243, A330-223F, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes
2017-05-05		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
2017-05-12		Airbus	A318-112; A319-111, -112, -115, -132, and -133; A320-214, -232, and -233; A321-211, -212, -213, -231, and -232 airplanes
Biweekly 2017-07			
2017-06-05		The Boeing Company	DC-6, DC-6A, DC-6B, C-118A, R6D-1, and R6D-1Z airplanes
2017-07-03		Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-06-04		Airbus	A300 B4-603, B4-620, and B4-622; A300 B4-605R and A300 B4-622R; and A300 C4-605R Variant F airplanes
2017-06-02		Fokker Services B.V.	F28 Mark 0100 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-06-10		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-06-09		The Boeing Company	787-8 airplanes
2017-06-01	R 2017-03-04	The Boeing Company	737-500 series airplanes
2017-06-14		The Boeing Company	737-300, -400, and -500 series airplanes
2017-06-13		Textron Aviation Inc.	680 airplanes
2016-25-25	COR	BAE Systems (Operations) Limited	4101 airplanes
2017-06-12		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233 airplanes
Biweekly 2017-08			
2017-08-04	R 2015-03-01	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2017-07-06		Gulfstream Aerospace Corporation	G-1159B airplanes
2017-08-05	R 2016-13-05	General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, and GE90-94B turbofan engines
2017-06-07		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; and A340-642 airplanes
2017-07-03	COR	Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-08-01	R 2013-22-19	Gulfstream Aerospace Corporation	GV and GV-SP airplanes
2017-06-08	R 2006-06-09 R 2012-05-08 R 2012-07-08	Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU; ERJ 170-200 LR, -200 SU, and -200 STD airplanes
2017-07-04	R 2013-24-17	General Electric Company	GE90-110B1 and GE90-115B engines
2017-08-02		Bombardier, Inc.	DHC-8-102, -103, and -106; DHC-8-201 and -202; DHC-8-301, -311, and -315 airplanes
2017-07-05		Airbus	A300 airplanes
Biweekly 2017-09			
2017-07-07		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2017-08-03		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-08-06		General Electric Company	GE90-76B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, and GE90-115B
2017-08-07		Learjet, Inc.	60
2017-08-08		CFE Company	CFE738-1-1B
2017-08-10	R 2017-01-01	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84
2017-08-11	R 2012-04-01	Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17
2017-08-13		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R, and A300 C4-605R Variant F; and A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 F4-605R and F4-622R
2017-09-01		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000)
2016-05-02	R 2011-13-11 R 2011-13-11	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
Biweekly 2017-10			
2017-09-03	R 2013-03-12	Dassault Aviation	MYSTERE-FALCON 50 airplanes
2017-09-04		The Boeing Company	707-100 Long Body, -200, -100B Long Body, and -100B Short Body series; 707-300, -300B, -300C, and -400 series; 720 and 720B series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-09-06 2017-10-01	R 2015-15-03	General Electric Company Dassault Aviation	GENx-1B and GENx-2B turbofan engines FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
Biweekly 2017-11			
2017-09-08		The Boeing Company	787-8 airplanes
2017-09-09		Zodiac Seats California LLC	4157, 4170, and 4184 seating systems
2017-09-10		The Boeing Company	747-400, 747-400D, and 747-400F airplanes
2017-09-11		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-09-12		ATR-GIE Avions de Transport Régional	ATR42-500; ATR72-102, -202, -212, and -212A airplanes
2017-10-04		Embraer S.A.	EMB-120, EMB-120ER, EMB-120FC, EMB-120QC, and EMB-120RT airplanes
2017-10-05		Airbus	A300 airlines
2017-10-06		Rolls-Royce plc	RB211 Trent 768-60, RB211 Trent 772-60, and RB211 Trent 772B-60 turbofan engines
2017-10-07		The Boeing Company	737-400 series airplanes
2017-10-08	R 2009-21-01	The Boeing Company	737-300 series airplanes
2017-10-14	S 2014-07-07	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Series 3101 airplanes
2017-10-15		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes
2017-10-16		The Boeing Company	787-8 and 787-9 airplanes
2017-10-17	R 2014-16-19	Airbus	A330 airplanes
2017-10-18		Airbus	A330-223F, -223, -321, -322, and -323 airplanes
2017-10-21		The Boeing Company	737-300, -400, and -500 series airplanes
2017-10-22		The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-10-23		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-10-24	R 2011-17-09 R 2012-25-12	Airbus	A330 airplanes
2017-10-25		Rolls-Royce Deutschland Ltd & Co KG	Spey 506-14A, Spey 555-15, Spey 555-15H, Spey 555-15N, and Spey 555-15P turbofan engines
2017-11-01		The Boeing Company	737-100, -200, and -200C series airplanes
2017-11-02		The Boeing Company	MD-90-30 airplanes
2017-11-09	R 2017-08-07	Learjet, Inc.	Model 60 airplanes
Biweekly 2017-12			
2017-10-07		The Boeing Company	737-400 series airplanes
2017-10-08	R 2009-21-01	The Boeing Company	737-300 series airplanes
2017-10-13	S 2015-17-19	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2017-10-14	S 2014-07-07	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Series 3101 airplanes
2017-11-04		The Boeing Company	767-200, -300, and -400ER series airplanes
2017-11-07		Airbus	A318, A319, A320, A321 airplanes
2017-11-09	R 2017-08-07	Learjet, Inc.	60 airplanes
2017-11-11		NavWorx, Inc.	ADS600-B and ADS600-EXP ADS-B Universal Access Transceiver units
2017-11-12		Bombardier, Inc.	BD-100-1A10 airplanes
2017-11-13	R 98-13-14	Airbus	A320-211, -212, and -231 airplanes
2017-11-14	R 2011-26-03	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F airplanes
2017-11-15		General Electric Company	CF6-80C2L1F turbofan engines
2017-12-01		The Boeing Company	767-200 series airplanes
2017-12-02		General Electric Company	GENx-1B64, -1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, 1B70/P1, -1B70/P2, -1B70/75/P1, -1B70/75/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76A/P2 engines
Biweekly 2017-13			
2017-11-05		Roll-Royce Corporation	AE 3007C and 3007C1 turbofan engines
2017-11-06	R 2014-05-32	Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-12-03		Pratt & Whitney Division	PW2037, PW2037M, and PW2040 turbofan engines
2017-12-05	R 2007-26-04	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-12-06		Airbus	A300, A310 airplanes
2017-12-07		The Boeing Company	737-800, -900, and -900ER series airplanes
2017-12-08	R 2011-24-06	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes
2017-12-09		Embraer	EMB-135ER, -135BJ, -135KE, -135KL, and -135LR; and EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes
2017-12-10		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-12-11		Bombardier, Inc.	BD-100-1A10 airplanes
2017-12-12		The Boeing Company	757-200, -200PF, and -200CB series airplanes
2017-12-13		Airbus	A320-212, A320-214, A320-232 airplanes
2017-12-14		The Boeing Company	757-200 and -200PF series airplanes
2017-12-15		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000) airplanes
2017-13-01		The Boeing Company	737-300, -400, and -500 series airplanes
2017-13-02		Dassault Aviation	FALCON 7X airplanes



2017-11-05 Roll-Royce Corporation (Type Certificate previously held by Allison Engine Company): Amendment 39-18904; Docket No. FAA-2016-9553; Directorate Identifier 2016-NE-29-AD.

(a) Effective Date

This AD is effective July 18, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to Rolls-Royce Corporation (RRC) AE 3007C and 3007C1 turbofan engines with 1st stage high-pressure turbine (HPT) wheels, part number (P/N) 23062373, 23065891, or 23070664; or with 2nd stage HPT wheels, P/N 23063462, 23065892, 23069116, 23069592 (except those serial numbers (S/Ns) noted in paragraph (c)(2) of this AD), or 23074643, installed.

(2) This AD does not apply to RRC AE 3007C and 3007C1 turbofan engines with 2nd stage HPT wheels, P/N 23069592, with S/Ns listed in Table 6 of RRC Alert Service Bulletin (ASB) AE 3007C-A-72-318, Revision 2, dated September 23, 2016, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine/turboprop Engine, Turbine Section.

(e) Unsafe Condition

This AD was prompted by analysis and by cracks found in the HPT wheel during an inspection. We are issuing this AD to prevent uncontained failure of the HPT wheels, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) For all RRC AE 3007C or C1 engines with an installed 1st stage HPT wheel, P/N 23062373, 23065891, or 23070664, or 2nd stage HPT wheel, P/N 23063462, 23065892, 23069116, 23069592 (except those S/Ns excluded by paragraph (c)(2) of this AD) or 23074643, after the effective date of this AD, remove the affected wheels before exceeding the new life limits identified in paragraph C., Table 1 of RRC ASB AE 3007C-A-72-318, Revision 2, dated September 23, 2016.

(2) After the effective date of this AD, do not return to service any engine with an HPT turbine wheel, with an affected P/N and an S/N, with a wheel life that exceeds the new life limits identified in paragraph C., Table 1 of RRC ASB AE 3007C-A-72-318, Revision 2, dated September 23, 2016.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Chicago Aircraft Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(h) Related Information

For more information about this AD, contact Kyri Zaroyiannis, Aerospace Engineer, Chicago Aircraft Certification Office, Small Airplane Directorate, FAA, 2300 E. Devon Ave., Des Plaines, IL 60018; phone: 847-294-7836; fax: 847-294-7834; email: kyri.zaroyiannis@faa.gov.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce Corporation (RRC) Alert Service Bulletin AE 3007C-A-72-318, Revision 2, dated September 23, 2016.

(ii) Reserved.

(3) For RRC service information identified in this AD, contact Rolls-Royce Corporation, 450 South Meridian Street, Mail Code NB-01-06, Indianapolis, IN 46225; phone: 317-230-3774; email: royce.com">indy.pubs.services@rolls-royce.com; Internet: www.rolls-royce.com.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on May 17, 2017.

Robert J. Ganley,
Acting Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2017-11-06 Pratt & Whitney: Amendment 39-18905; Docket No. FAA-2013-0740; Directorate Identifier 2013-NE-24-AD.

(a) Effective Date

This AD is effective July 18, 2017.

(b) Affected ADs

This AD replaces AD 2014-05-32, Amendment 39-17804 (79 FR 17856, March 31, 2014).

(c) Applicability

This AD applies to all Pratt & Whitney (PW) PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 72, Turbine/Turboprop Engine.

(e) Unsafe Condition

This AD was prompted by a rupture of the diffuser-to-high-pressure turbine (HPT) case flange. We are issuing this AD to prevent failure of the diffuser-to-HPT case flange, which could lead to uncontained engine failure and damage to the airplane.

(f) Compliance

Unless already done, comply with this AD within the compliance times specified.

(1) For diffuser case, part number (P/N) 1B7461, serial numbers (S/Ns) DGGUAK1306 and DGGUAK1308, and HPT case, P/N 1B2440, S/N DKLBCS1032:

(i) Within 100 flight cycles or 30 days after May 5, 2014, whichever is later, eddy current inspect the diffuser case and the HPT case M-flange. Use PW Service Bulletin (SB) No. PW2000 72-763, Revision No. 1, dated August 30, 2013, to do the inspection.

(ii) Reserved.

(2) For all diffuser and HPT cases, at the next piece-part opportunity and every piece-part opportunity thereafter, perform a high sensitivity fluorescent-penetrant inspection (FPI) of the entire diffuser case rear flange (M-flange) and boltholes, and the entire HPT case forward flange (M-flange) and boltholes.

(3) For diffuser cases that have not incorporated PW SB PW2000-72-364 or have incorporated either PW SB PW2000-72-700 or PW2000 Series Engine Manual, Repair-28, Task 72-41-01-300-028 (M-flange replacement), perform initial and repetitive eddy current inspections (ECIs) of the M-flange of the diffuser case in accordance with paragraph (f)(4) of this AD.

(4) Use, as applicable, either the Accomplishment Instructions, "For Engines Installed on the Aircraft," paragraphs 3.(I) through 3.(J), or the Accomplishment Instructions, "For Engines Removed

from the Aircraft,” paragraphs 3.(D) through 3.(E), of PW Alert Service Bulletin (ASB) No. PW2000 A72-765, Revision No. 2, dated August 12, 2016 to do the ECI as follows:

- (i) Perform an initial inspection within the following period, whichever occurs later:
 - (A) Within 5,500 cycles since new or since M-flange replacement, or
 - (B) Within 2,500 cycles since last piece-part FPI inspection, or
 - (C) Within 1,000 cycles from the effective date of this AD.
- (ii) If no crack indications are found, re-inspect within 2,500 cycles since last ECI or last piece-part FPI inspection, whichever occurs later.
- (iii) If bolthole ID crack indications are found, measure the length and determine the re-inspect interval in accordance with:
 - (A) Paragraphs 5.(C) through 5.(D) of PW ASB No. PW2000 A72-765, Revision No. 2, dated August 12, 2016 “For Engines Installed on the Aircraft”; or
 - (B) Paragraphs 4.(C) through 4.(D) of PW ASB No. PW2000 A72-765, Revision No. 2, dated August 12, 2016, “For Engines Removed from the Aircraft.”
- (iv) Remove from service diffuser cases with bolthole ID cracks exceeding 0.170 inches.

(g) Definition

For the purpose of this AD, piece-part opportunity is defined as when the part is completely disassembled.

(h) Credit for Previous Actions

(1) You may take credit for the diffuser case and HPT case inspections required by paragraphs (f)(1) and (3) of this AD if you performed:

- (i) An ECI of the diffuser case and the HPT case M-flange using the Accomplishment Instructions of PW SB No. PW2000 72-763, Revision No. 1, dated August 30, 2013, or an earlier version; or
- (ii) a high sensitivity FPI of the diffuser case and the HPT case at a piece-part opportunity after January 1, 2010.

(2) You may take credit for only the diffuser case inspections required by paragraphs (f)(1) and (3) of this AD if you performed an ECI of the M-flange using the Accomplishment Instructions of PW SB No. PW2000 A72-765, Revision No. 1, dated July 13, 2016, or an earlier version.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(j) Related Information

For more information about this AD, contact Brian Kierstead, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7772; fax: 781-238-7199; email: brian.kierstead@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pratt & Whitney (PW) Service Bulletin No. PW2000 72-763, Revision No. 1, dated August 30, 2013.

(ii) PW Alert Service Bulletin No. PW2000 A72-765, Revision No. 2, dated August 12, 2016.

(3) For PW service information identified in this AD, contact Pratt & Whitney, 400 Main St., East Hartford, CT 06118; phone: 860-565-0140; fax: 860-565-5442; email: HELP24@pw.utc.com.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on May 17, 2017.

Robert J. Ganley,
Acting Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2017-12-03 Pratt & Whitney Division: Amendment 39-18918; Docket No. FAA-2016-9405; Directorate Identifier 2016-NE-22-AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Pratt & Whitney Division (PW) PW2037, PW2037M, and PW2040 turbofan engines with electronic engine control (EEC), model number EEC104-40 or EEC104-60, installed, with an EEC software standard earlier than SCN 5B/I.

(d) Subject

Joint Aircraft System Component (JASC) of America Code 7321, Fuel Control Turbine Engines.

(e) Unsafe Condition

This AD was prompted by an unrecoverable engine in-flight shutdown (IFSD) after an ice crystal icing event. We are issuing this AD to prevent failure of the high-pressure turbine (HPT), rotor seizure, failure of one or more engines, loss of thrust control, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Action

(1) For an engine with a serial number (S/N) listed in Figure 1 to paragraph (g) of this AD, upgrade any EEC software standards earlier than SCN 5B/I at the next engine shop visit, or before December 1, 2018, whichever occurs first, or, replace the EEC with a part eligible for installation.

(2) For an engine with an S/N not listed in Figure 1 to paragraph (g) of this AD, upgrade any EEC software standards earlier than SCN 5B/I at the next engine shop visit, or before July 1, 2024, whichever occurs first, or replace the EEC with a part eligible for installation.

Figure 1 to Paragraph (g)–Engine S/Ns

716402	727272	728741
727103	727280	728743

727134	727281	728748
727152	727282	728779
727158	727286	728785
727189	727287	728795
727202	727288	728806
727204	728709	728811
727231	728715	728812
727239	728716	728820
727240	728719	728824
727251	728720	728826
727252	728725	728827
727253	728726	728840
727257	728729	728864
727269	728730	728870

(h) Installation Prohibition

After the effective date of this AD, do not install any software standard earlier than SCN 5B/I into any EEC model number EEC104-40 or EEC104-60.

(i) Definition

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

(1) For more information about this AD, contact Kevin Clark, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7088; fax: 781-238-7199; email: kevin.m.clark@faa.gov.

(2) PW Alert Service Bulletin PW2000 A73-170, dated July 14, 2016, which is not incorporated by reference in this AD, can be obtained from PW, using the contact information in paragraph (k)(3) of this AD.

(3) For service information identified in this AD, contact Pratt & Whitney Division, 400 Main St., East Hartford, CT 06118; phone: 800-565-0140; fax: 860-565-5442.

(4) You may view this service information at FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(I) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 2, 2017.

Robert J. Ganley,
Acting Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2017-12-05 The Boeing Company: Amendment 39-18920; Docket No. FAA-2016-9188; Directorate Identifier 2016-NM-102-AD.

(a) Effective Date

This AD is effective July 25, 2017.

(b) Affected ADs

This AD replaces AD 2007-26-04, Amendment 39-15306 (72 FR 71216, December 17, 2007) (“AD 2007-26-04”).

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1267, Revision 1, dated March 8, 2016 (“ASB 737-53A1267, R1”).

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder indicating that the forward skin panel at the station (STA) 259.5 circumferential butt splice between stringers 19L and 24L is subject to widespread fatigue damage. We are issuing this AD to prevent cracking of the STA 259.5 circumferential butt splice, which could result in loss of structural integrity of the fuselage skin and possible loss of cabin pressure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Actions for Group 2 Airplanes

For airplanes identified as Group 2 in ASB 737-53A1267, R1: Within 120 days after the effective date of this AD, inspect the airplane and do all applicable corrective actions using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(h) Inspections for Group 1 Airplanes

For airplanes identified as Group 1 in ASB 737-53A1267, R1: Except as specified in paragraph (j)(1) of this AD, at the applicable time specified in paragraph 1.E. “Compliance” of ASB 737-53A1267, R1, do the applicable actions specified in paragraphs (h)(1) and (h)(2) of this AD; and do all applicable corrective actions; in accordance with the Accomplishment Instructions of ASB 737-53A1267, R1, except as specified in paragraph (j)(2) of this AD and as provided by paragraph (i) of this AD. Do all applicable corrective actions before further flight. Repeat the applicable inspections specified in paragraph (h)(1) of this AD thereafter at the applicable intervals specified paragraph 1.E., “Compliance,” of ASB 737-53A1267, R1, except as provided by paragraph (i) of this AD.

(1) Do detailed inspections and high frequency eddy current (HFEC) surface inspections of the skin around the fastener heads for any crack on the forward and aft fastener columns, left and right sides, at STA 259.5 circumferential butt splice, in accordance with Parts 1, 2, 6, 7, 8, and 9 of the Accomplishment Instructions of ASB 737-53A1267, R1, as applicable.

(2) Do a one-time detailed inspection for any defect of the production countersunk rivet heads on both forward and aft fastener columns, left and right sides, at STA 259.5 circumferential butt splice, in accordance with Part 3 of the Accomplishment Instructions of ASB 737-53A1267, R1.

(i) Repairs That Terminate Inspections in Repair Areas

(1) For airplanes identified as Group 1, Configuration 1, in ASB 737-53A1267, R1: Doing the skin trim-out repair specified in Part 5 of the Accomplishment Instructions of ASB 737-53A1267, R1, terminates the initial and repetitive inspections required by paragraph (h) of this AD that are specified in Part 1 of the Accomplishment Instructions of ASB 737-53A1267, R1, only; all other inspections required by paragraph (h) of this AD must be done, except as provided by paragraph (i)(2) of this AD.

(2) For airplanes identified as Group 1, Configuration 1 in ASB 737-53A1267, R1: Doing the skin repair specified in Part 4 of the Accomplishment Instructions of ASB 737-53A1267, R1, terminates the initial and repetitive inspections required by paragraph (h) of this AD that are specified in Part 1 and Part 2 of the Accomplishment Instructions of ASB 737-53A1267, R1, for the repaired area only; all other inspections required by paragraph (h) of this AD must be done, except as provided by paragraph (i)(1) of this AD.

(j) Exceptions to Service Information

(1) Where paragraph 1.E., “Compliance,” of ASB 737-53A1267, R1, specifies a compliance time “after the Revision 1 date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Although ASB 737-53A1267, R1, specifies to contact Boeing for appropriate action, and specifies that action as “RC” (Required for Compliance), this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-LAACO-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2007-26-04 are approved as AMOCs for the corresponding provisions of this AD.

(5) Except as required by paragraph (j)(2) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (k)(5)(i) and (k)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

For more information about this AD, contact Jennifer Tsakoumakis, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5264; fax: 562-627-5210; email: jennifer.tsakoumakis@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1267, Revision 1, dated March 8, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-06 Airbus: Amendment 39-18921; Docket No. FAA-2016-9574; Directorate Identifier 2016-NM-063-AD.

(a) Effective Date

This AD is effective July 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus airplanes identified in paragraphs (c)(1) through (c)(6) of this AD, certificated in any category, all manufacturer serial numbers.

- (1) Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.
- (2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.
- (3) Model A300 B4-605R and B4-622R airplanes.
- (4) Model A300 F4-605R and F4-622R airplanes.
- (5) Model A300 C4-605R Variant F airplanes.
- (6) Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. We are issuing this AD to detect and correct widespread fatigue damage of the forward passenger doors, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Parts Identification

Within 36 months after the effective date of this AD, or before exceeding the applicable airplane design service goal specified in table 1 to paragraph (g) of this AD, whichever occurs later: Identify the part number on the forward passenger doors on the left-hand and right-hand sides, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

(1) Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014 (for Model A300 airplanes).

(2) Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014 (for Model A300-600 series airplanes).

(3) Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014.

Table 1 to Paragraph (g) of This AD—Design Service Goal

Airplane model/series	Design service goal flight cycles or flight hours
A300 B2-100, B2-200, B2-320	Before the accumulation of 48,000 total flight cycles.
A300 B4-100	Before the accumulation of 40,000 total flight cycles.
A300 B4-200	Before the accumulation of 34,000 total flight cycles.
A300 B4-600, B4-600R, F4-600R, C4-600R	Before the accumulation of 30,000 total flight cycles or 67,500 total flight hours, whichever occurs first.
A310-200	Before the accumulation of 40,000 total flight cycles or 60,000 total flight hours, whichever occurs first.
A310-300	Before the accumulation of 35,000 total flight cycles or 60,000 total flight hours, whichever occurs first.

(h) Corrective Actions

(1) For airplanes on which no forward passenger door having part number (P/N) A521-71851-000 or P/N A521-71851-001 is found to be installed, after identifying the part number as specified in paragraph (g) of this AD: No further action is required for these airplanes.

(2) For airplanes on which any forward passenger door having P/N A521-71851-000 or P/N A521-71851-001 is found to be installed, after identifying the part number as specified in paragraph (g) of this AD: Before further flight, do a detailed inspection of all frame segment inner flanges of the forward passenger doors with the affected part numbers for installed repairs, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

(i) For Airbus Model A300 airplanes: Before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014. Where Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014, specifies to contact Airbus for appropriate action, and specifies that action as “RC” (Required for Compliance): Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (1)(2) of this AD.

(ii) For Airbus Model A310 and A300-600 series airplanes on which the repair principle A310 Structural Repair Manual (SRM) 52-10-00, page block (PB) 201, Figure 209, or A300-600 SRM 52-10-00, PB 201, Figure 206, as applicable, is not embodied on any inner flange, no further action is required for these airplanes.

(iii) For Airbus Model A310 and A300-600 series airplanes on which the repair principle A310 SRM 52-10-00, PB 201, Figure 209, or A300-600 SRM 52-10-00, PB 201, Figure 206, as applicable, is embodied on at least one inner flange: Before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014; or Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014; as applicable. Where Airbus Service Bulletins A300-52-6084, Revision 01, dated October 16, 2014; and A310-52-2076, Revision 01, dated October 14, 2014; specify to contact Airbus for appropriate action, and specify that action as “RC”: Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (1)(2) of this AD.

(i) Reporting Requirement

At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, report the results of the inspection required by paragraph (h)(2) of this AD to Airbus Service Bulletin Reporting Online Application on Airbus World (<https://w3.airbus.com/>), or submit the results to Airbus using the reporting sheet provided in the service information identified in paragraphs (g)(2) or (g)(3) of this AD, as applicable.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Parts Installation Limitations

As of the effective date of this AD, no person may replace a forward passenger door on any airplane, unless the replacement door has been inspected in accordance with the requirements of this AD.

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using the applicable service information identified in paragraph (k)(1), (k)(2), or (k)(3) of this AD.

(1) Airbus Service Bulletin A300-52-0180, dated September 23, 2014.

(2) Airbus Service Bulletin A300-52-6084, dated September 23, 2014.

(3) Airbus Service Bulletin A310-52-2076, dated September 23, 2014.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Branch, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of

information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(4) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0079, dated April 21, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9574.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A300-52-0180, Revision 01, dated October 14, 2014.

(ii) Airbus Service Bulletin A300-52-6084, Revision 01, dated October 16, 2014.

(iii) Airbus Service Bulletin A310-52-2076, Revision 01, dated October 14, 2014.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-07 The Boeing Company: Amendment 39-18922; Docket No. FAA-2016-9432; Directorate Identifier 2016-NM-116-AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-800, -900, and -900ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-21A1203, dated June 8, 2016.

(d) Subject

Air Transport Association (ATA) of America Code 21, Air conditioning.

(e) Unsafe Condition

This AD was prompted by reports of in-flight failure of the left temperature control valve and control cabin trim air modulating valve. We are issuing this AD to prevent temperatures in excess of 100 degrees Fahrenheit in the flight deck or the passenger cabin during cruise, which could lead to the impairment of the flight crew and prevent continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement of the Left Temperature Control Valve and Control Cabin Trim Air Modulating Valve

Within 60 months after the effective date of this AD, replace the left temperature control valve and control cabin trim air modulating valve, as applicable, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-21A1203, dated June 8, 2016.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install a temperature control valve, part number 398908-4, in either the left temperature control valve location or the control cabin trim air modulating valve location on any Model 737-800, -900, or -900ER airplane.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Stanley Chen, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6585; fax: 425-917-6590; email: stanley.chen@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-21A1203, dated June 8, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-08 BAE Systems (Operations) Limited: Amendment 39-18923; Docket No. FAA-2016-4220; Directorate Identifier 2015-NM-076-AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

This AD replaces AD 2011-24-06, Amendment 39-16870 (76 FR 73477, November 29, 2011) (“AD 2011-24-06”).

(c) Applicability

This AD applies to BAE Systems (Operations) Limited Model BAe 146-100A, -200A, and -300A airplanes; and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes; certificated in any category; all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 05, Periodic Inspections.

(e) Reason

This AD was prompted by a determination that new or revised structural inspection requirements are necessary. We are issuing this AD to detect and correct fatigue cracking of certain structural elements, which could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Airworthiness Limitations Revisions of the Shock Absorber Assemblies, With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2011-24-06, with no changes. Within 90 days after January 3, 2012 (the effective date of AD 2011-24-06), revise the maintenance program, by incorporating Subject 05-10-15, “Aircraft Equipment Airworthiness Limitations” of Chapter 05, “Time Limits/Maintenance Checks,” of the BAE Systems (Operations) Limited BAe 146 Series/Avro 146-RJ Series Aircraft Maintenance Manual (AMM), Revision 104, dated April 15, 2011, to remove life limits on shock absorber assemblies, but not the individual shock absorber components, amend life limits on main landing gear (MLG) up-locks and door up-locks, and to introduce and amend life limits on MLG components. Accomplishing the actions required by paragraph (i) of this AD terminates the actions required by this paragraph.

(h) Retained No Alternative Actions, Intervals, and/or Critical Design Configuration Control Limitations (CDCCLs), With No Changes

This paragraph restates the requirements of paragraph (k) of AD 2011-24-06, with no changes. Except as specified in paragraph (i) of this AD: After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used, unless the actions, intervals, and/or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k)(1) of this AD.

(i) New Revision to the Maintenance or Inspection Program

Within 90 days after the effective date of this AD: Revise the maintenance or inspection program, as applicable, to incorporate new and revised limitations, tasks, thresholds, and intervals using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Accomplishing the actions required by this paragraph terminates the actions required by paragraph (g) of this AD.

Note 1 to paragraph (i) of this AD: An additional source of guidance for the actions specified in paragraph (i) of this AD can be found in BAe 146/AVRO 146-RJ Airplane Maintenance Manual, Revision 112, dated October 15, 2013.

Note 2 to paragraph (i) of this AD: An additional source of guidance for the actions specified in paragraph (i) of this AD can be found in Corrosion Prevention Control Program (CPCP) Document No. CPCP-146-01, Revision 4, dated September 15, 2010.

Note 3 to paragraph (i) of this AD: An additional source of guidance for the actions specified in paragraph (i) of this AD can be found in Supplemental Structural Inspections Document (SSID) Document No. SSID-146-01, Revision 2, dated August 15, 2012.

Note 4 to paragraph (i) of this AD: An additional source of guidance for the actions specified in paragraph (i) of this AD can be found in Maintenance Review Board Report Document No. MRB 146-01, Issue 2, Revision 19, dated August 2012.

Note 5 to paragraph (i) of this AD: An additional source of guidance for the actions specified in paragraph (i) of this AD can be found in BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-237, Revision 1, dated April 2, 2013.

(j) New No Alternative Actions, Intervals, and/or CDCCLs

After accomplishment of the revision required by paragraph (i) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used, unless the actions, intervals, and/or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (k)(1) of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or BAE Systems (Operations) Limited's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0071, dated March 19, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4220.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on January 3, 2012 (76 FR 73477, November 29, 2011).

(i) Subject 05-10-15, "Aircraft Equipment Airworthiness Limitations" of Chapter 05, "Time Limits/Maintenance Checks," of the BAE Systems (Operations) Limited BAe 146 Series/Avro 146-RJ Series Aircraft Maintenance Manual, Revision 104, dated April 15, 2011.

(ii) Reserved.

(4) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-09 Empresa Brasileira de Aeronautica S.A. (Embraer): Amendment 39-18924; Docket No. FAA-2015-3143; Directorate Identifier 2015-NM-047-AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes specified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes, certificated in any category, as identified in Embraer Service Bulletin 145-28-0030, Revision 01, dated October 22, 2010.

(2) Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135BJ airplanes, certificated in any category, as identified in Embraer Service Bulletin 145LEG-28-0032, Revision 01, dated November 20, 2012.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a report of chafing found between the fuel pump electrical harness and the fuel pump tubing during scheduled maintenance. We are issuing this AD to detect and correct chafing of the fuel pump harnesses with other parts inside the fuel tank, which could present a potential ignition source that could result in a fire or fuel tank explosion.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Detailed Inspection and Corrective Action

Do the actions specified in paragraphs (g)(1) and (g)(2) of this AD at the applicable times specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Do a detailed inspection for chafing on the electrical harness of each electrical fuel pump in the fuel tanks, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145-28-0030, Revision 01, dated October 22, 2010 (for Model EMB-135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR

airplanes); or Embraer Service Bulletin 145LEG-28-0032, Revision 01, dated November 20, 2012 (for Model EMB-135BJ airplanes). If any chafing is found, before further flight, replace the affected electrical fuel pump with a new or serviceable pump having the same part number, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145-28-0030, Revision 01, dated October 22, 2010; or Embraer Service Bulletin 145LEG-28-0032, Revision 01, dated November 20, 2012; as applicable.

(2) Install clamps on the fuel pump electrical harnesses, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145-28-0030, Revision 01, dated October 22, 2010 (for Model EMB-135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes); or Embraer Service Bulletin 145LEG-28-0032, Revision 01, dated November 20, 2012 (for Model EMB-135BJ airplanes).

(h) Compliance Times

(1) For Model EMB-135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes: Do the actions specified in paragraph (g) of this AD within 5,000 flight hours or 24 months after the effective date of this AD, whichever occurs first.

(2) For Model EMB-135BJ airplanes: Do the actions specified in paragraph (g) of this AD within 4,800 flight hours or 48 months after the effective date of this AD, whichever occurs first.

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Embraer Service Bulletin 145-28-0030, dated September 1, 2010 (for Model EMB-135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes); or Embraer Service Bulletin 145LEG-28-0032, dated September 15, 2011 (for Model EMB-135BJ airplanes), as applicable.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Agência Nacional de Aviação Civil (ANAC); or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Brazilian Airworthiness Directive 2015-03-01, effective March 23, 2015, for related information. This MCAI may be found in

the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3143.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (1)(3) and (1)(4) of this AD.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Embraer Service Bulletin 145-28-0030, Revision 01, dated October 22, 2010.

(ii) Embraer Service Bulletin 145LEG-28-0032, Revision 01, dated November 20, 2012.

(3) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170-Putim-12227-901 São Jose dos Campos-SP-Brasil; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-10 Airbus: Amendment 39-18925; Docket No. FAA-2016-9571; Directorate Identifier 2016-NM-139-AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a full scale fatigue test campaign on Airbus Model A321 series airplanes in the context of the extended service goal. It was determined that cracks could develop on the fastener holes of certain frames on the left-hand (LH) and right-hand (RH) sides of the affected airplanes. We are issuing this AD to detect and correct cracking of the fastener holes at certain frame locations, which could result in reduced structural integrity of the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections of the Frames, Stringers, and Slidebox Junctions

At the applicable time specified in table 1 to the introductory text of paragraph (g) of this AD, do a rototest inspection for cracking at frame (FR) 35.1, FR 35.2, and FR 35.3 on the LH and RH sides, in accordance with the Accomplishment Instructions of the Airbus service information specified in paragraphs (g)(1), (g)(2), (g)(3), (g)(4), (g)(5), and (g)(6) of this AD. Repeat the inspection thereafter at intervals not to exceed 5,300 flight cycles.

Table 1 to the Introductory Text of Paragraph (g) of This AD–Inspection Threshold

Airplane accumulated total flight cycles at the effective date of this AD	Compliance time
For airplanes with 18,300 total flight cycles or less	Before exceeding 18,300 total flight cycles, or within 5,300 flight cycles after the effective date of this AD, whichever occurs later.
For airplanes with more than 18,300 total flight cycles	Before exceeding 23,600 total flight cycles, or within 2,100 flight cycles after the effective date of this AD, whichever occurs later.

- (1) Airbus Service Bulletin A320-53-1308, dated November 4, 2015 (FR 35.1 LH side).
- (2) Airbus Service Bulletin A320-53-1309, dated November 4, 2015 (FR 35.1 RH side).
- (3) Airbus Service Bulletin A320-53-1310, dated November 4, 2015 (FR 35.2 LH side).
- (4) Airbus Service Bulletin A320-53-1311, dated November 4, 2015 (FR 35.2 RH side).
- (5) Airbus Service Bulletin A320-53-1312, dated November 4, 2015 (FR 35.3 LH side).
- (6) Airbus Service Bulletin A320-53-1313, dated November 4, 2015 (FR 35.3 RH side).

(h) Corrective Action

If any crack is found during any inspection required by the introductory text to paragraph (g) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). Although the service information specified in paragraph (g) of this AD specifies to contact Airbus for repair instructions, and specifies that action as "RC" (Required for Compliance), this AD requires repair as specified in this paragraph. Repair of an airplane as required by this paragraph does not constitute terminating action for the repetitive inspections required by the introductory text to paragraph (g) of this AD for that airplane, unless specified otherwise in the repair instructions approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as required by paragraph (h) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using

accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0146, dated July 20, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9571.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320-53-1308, dated November 4, 2015.

(ii) Airbus Service Bulletin A320-53-1309, dated November 4, 2015.

(iii) Airbus Service Bulletin A320-53-1310, dated November 4, 2015.

(iv) Airbus Service Bulletin A320-53-1311, dated November 4, 2015.

(v) Airbus Service Bulletin A320-53-1312, dated November 4, 2015.

(vi) Airbus Service Bulletin A320-53-1313, dated November 4, 2015.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 2, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-11 Bombardier, Inc.: Amendment 39-18926; Docket No. FAA-2016-9387; Directorate Identifier 2016-NM-182-AD.

(a) Effective Date

This AD is effective July 20, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD-100-1A10 airplanes, certificated in any category, serial numbers (S/Ns) 20003 through 20532 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Reason

This AD was prompted by a report that the left-hand side (LHS) and right-hand side (RHS) equipment racks were not designed to support the actual weight of all the equipment and the secondary direct current power centers under all loading conditions. We are issuing this AD to prevent structural failure of the LHS or RHS equipment racks in the event of a high energy emergency landing or runway excursion, which could result in blockage of the emergency exit for the flightcrew.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification of the Equipment Racks

Within 90 months after the effective date of this AD, do the modification required by paragraph (g)(1) or (g)(2) of this AD, as applicable.

(1) For airplanes having S/Ns 20003 through 20500 inclusive: Modify the equipment racks having part numbers (P/Ns) K1000070316-003 (LHS) and K1000070316-004 (RHS), in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100-25-39, dated October 26, 2015.

(2) For airplanes having S/Ns 20501 through 20532 inclusive: Modify the equipment rack having P/N K1000070316-004 (RHS only), in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 350-25-002, dated October 26, 2015.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2016-26, dated September 14, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9387.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7329; fax 516-794-5531.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 100-25-39, dated October 26, 2015.

(ii) Bombardier Service Bulletin 350-25-002, dated October 26, 2015.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 5, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-12 The Boeing Company: Amendment 39-18927; Docket No. FAA-2016-9566; Directorate Identifier 2016-NM-191-AD.

(a) Effective Date

This AD is effective July 25, 2017.

(b) Affected ADs

This AD affects AD 2006-11-11, Amendment 39-14615 (71 FR 30278, May 26, 2006) (“AD 2006-11-11”).

(c) Applicability

(1) This AD applies to all The Boeing Company Model 757-200, -200PF, and -200CB series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01518SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/48e13cdfbbc32cf4862576a4005d308b/\\$FILE/ST01518SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/48e13cdfbbc32cf4862576a4005d308b/$FILE/ST01518SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01518SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the fuselage circumferential splice plates along the center fastener rows, forward and aft of station 900 and station 1180 splice centerlines, are subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct cracks of certain circumferential splice plates, which could lead to the failure of a principal structural element and could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Low Frequency Eddy Current (LFEC) Inspections and Corrective Actions

At the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 757-53A0105, dated June 10, 2016, except as required by paragraph (h)(1) of this AD: Do an LFEC inspection for cracking of the circumferential splice plates at station 900 and station 1180,

from stringer S-6L to stringer S-6R, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-53A0105, dated June 10, 2016, except as required by paragraph (h)(2) of this AD. Do all applicable corrective actions before further flight. Repeat the inspections thereafter at the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 757-53A0105, dated June 10, 2016. Accomplishing these inspections terminates the requirements of paragraph (h) of AD 2006-11-11 for the inspections of structurally significant item (SSI) 53-40-05, circumferential skin splice body station BS900 stringer S-6L to stringer S-6R and circumferential skin splice body station BS1180 stringer S-6L to stringer S-6R, as specified in Section 9 of Boeing Maintenance Planning Data (MPD) Document D622N001-9, May 2003 or June 2005 revisions. All other requirements of AD 2006-11-11 remain fully applicable and must be complied with.

(h) Service Information Exceptions

(1) Where Boeing Alert Service Bulletin 757-53A0105, dated June 10, 2016, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 757-53A0105, dated June 10, 2016, specifies to contact Boeing for repair instructions, and specifies that action as Required for Compliance (RC), this AD requires repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Eric Schrieber, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5348; fax: 562-627-5210; email: eric.schrieber@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 757-53A0105, dated June 10, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 6, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-13 Airbus: Amendment 39-18928; Docket No. FAA-2015-3148; Directorate Identifier 2014-NM-254-AD.

(a) Effective Date

This AD becomes effective July 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus Model A320-212 airplane having manufacturer serial number (MSN) 1011; Airbus Model A320-214 airplanes having MSNs 1009, 1026 and 1030; the Airbus Model A320-232 airplane having MSN 0977; and Airbus Model A320-233 airplanes having MSNs 1007 and 1013; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of a crack found during an inspection of the pocket radius of the fuselage frame. We are issuing this AD to detect and correct any cracking of the pocket radius, which could lead to in-flight decompression of the airplane and possible injury to the passengers.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Within 750 flight cycles or 4 months, whichever occurs first after the effective date of this AD: Do a low frequency eddy current (LFEC) inspection or a high frequency eddy current (HFEC) inspection for cracking of the pocket radii located between fuselage frames 35 and 40, above stringer 6 on both the left- and right-hand sides, in accordance with the instructions of Airbus Alert Operators Transmission (AOT) A53N009-14, Rev 00, dated December 17, 2014. Repeat the inspection, thereafter, at intervals not to exceed the times specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) For the LFEC inspection performed on the outside: Repeat the inspection at intervals not to exceed 1,000 flight cycles.

(2) For the HFEC inspection performed on the inside: Repeat the inspection at intervals not to exceed 2,000 flight cycles.

(h) Corrective Action

If, during any inspection required by paragraph (g) of this AD, any crack is found, before further flight, accomplish the repair in accordance with the instructions of Airbus AOT A53N009-14, Rev 00, dated December 17, 2014; except if the crack is beyond the structural repair manual limits as specified in Airbus AOT A53N009-14, Rev 00, dated December 17, 2014, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(i) Terminating Action

Repair of an airplane as required by paragraph (h) of this AD terminates the repetitive inspections required by paragraph (g) of this AD for the repaired area only.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0278, dated December 19, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3148.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A53N009-14, Rev 00, dated December 17, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 6, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-14 The Boeing Company: Amendment 39-18929; Docket No. FAA-2016-9502; Directorate Identifier 2016-NM-128-AD.

(a) Effective Date

This AD is effective July 25, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 757-200 and -200PF series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 757-53A0103, dated June 22, 2016.

(2) Installation of Supplemental Type Certificate (STC) ST01518SE (http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgSTC.nsf/0/38B606833BBD98B386257FAA00602538?OpenDocument&Highlight=st01518se) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01518SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the frame webs between stringers S-20 and S-25 on the left side and right side, from station (STA) 440 to STA 820 and from STA 1300 to STA 1701, are subject to widespread fatigue damage (WFD). We are issuing this AD to prevent fatigue cracking that could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive High Frequency Eddy Current (HFEC) Inspections of the Frame Webs

Before the accumulation of 28,000 total flight cycles, or within 3,000 flight cycles after the effective date of this AD, whichever occurs later, do an HFEC inspection of the frame webs for any crack in any open coordinating holes, tooling holes, and insulation blanket attachment holes, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-53A0103,

dated June 22, 2016. If any cracking is found, repair before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD. Repeat the inspection at intervals not to exceed 12,000 flight cycles.

(h) Modification of the Frame Webs

Before the accumulation of 59,000 total flight cycles, modify the frame webs at all open hole locations, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-53A0103, dated June 22, 2016. Accomplishment of this modification terminates the repetitive inspection requirements of paragraph (g) of this AD at the modified locations only.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (g) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Muoi Vuong, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5205; fax: 562-627-5210; email: muoi.vuong@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 757-53A0103, dated June 22, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 7, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-12-15 Bombardier, Inc.: Amendment 39-18930; Docket No. FAA-2017-0558; Directorate Identifier 2015-NM-133-AD.

(a) Effective Date

This AD becomes effective July 5, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Bombardier, Inc., Model CL-600-2E25 (Regional Jet Series 1000) airplanes, serial numbers 19001 and subsequent, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by reports of two in-service incidents of loss of all air data information in the flight deck. We are issuing this AD to advise the flight crew of procedures to stabilize the airplane's airspeed and attitude in the event of loss of air data information. Loss of air data information may result in loss of continued flight safety.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual Revision

Within 30 days after the effective date of this AD, revise the Emergency Procedures section of the airplane flight manual (AFM) to include the information in Section 03-19, "Unreliable Airspeed," of Chapter 3, "Emergency Procedures," in the Bombardier CRJ Series Regional Jet Model CL-600-2E25 (Series 1000) AFM, Revision 9, dated February 13, 2015.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending

information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2015-11, dated June 9, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0558.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 03-19, "Unreliable Airspeed," of Chapter 3, "Emergency Procedures," in the Bombardier CRJ Series Regional Jet Model CL-600-2E25 (Series 1000) AFM, Revision 9, dated February 13, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 7, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-13-01 The Boeing Company: Amendment 39-18931; Docket No. FAA-2016-9391; Directorate Identifier 2016-NM-129-AD.

(a) Effective Date

This AD is effective July 27, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE (http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/EBD1CEC7B301293E86257CB30045557A?OpenDocument&Highlight=st01219se) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

a

(e) Unsafe Condition

This AD was prompted by a report of a crack in the body station (BS) 616 frame inboard chord during supplemental structural inspection document (SSID) inspections; the crack was located at the lowest fastener hole of the inboard chord inboard strap below stringer S-11R. We are issuing this AD to detect and correct any crack in the inboard chord of the BS 578 (737-400 series airplanes) and BS 616 (737-300 and -500 series airplanes) frame below stringers S-11L or S-11R, which could result in structural failure of the frame and possible rapid decompression.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Detailed and High Frequency Eddy Current (HFEC) Inspections

Except as required by paragraph (i) of this AD, at the applicable times specified in table 1 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016: Do detailed and HFEC inspections for any crack at the frame inboard chords, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016.

Repeat the inspections thereafter at the time specified in table 1 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016.

(h) Repair

If any crack is found during any inspection required by paragraph (g) of this AD, repair before further flight using a method approved in accordance with the procedures specified in paragraph (j) of this AD. Although Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016, specifies to contact Boeing for repair instructions, and specifies that action as “RC” (Required for Compliance), this AD requires repair as specified in this paragraph.

(i) Service Information Exceptions

Where Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or sub-step is labeled “RC Exempt,” then the RC requirement is removed from that step or sub-step. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1366, dated May 17, 2016.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 9, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-13-02 Dassault Aviation: Amendment 39-18932; Docket No. FAA-2016-9504; Directorate Identifier 2016-NM-107-AD.

(a) Effective Date

This AD is effective July 27, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, serial numbers (S/Ns) 2, 5, and 8 through 182 inclusive; except S/Ns 141, 148, 149, 157, 159, 166, 170, 171, 174, 175, and 177 through 180 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports that during the assembly of structural elements on some airplanes, lack of established procedures and tools caused boring and torqueing defects to be present at some locations on the foot of frame (FR) 36 and FR39. We are issuing this AD to detect and correct defects in the bore holes at FR36 and FR39 that could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of Bore Holes

At the applicable time identified in paragraphs (g)(1) or (g)(2) of this AD, remove the sheer bolts at FR36 and FR39, left hand and right hand, as identified in Dassault Service Bulletin 7X-379, dated February 29, 2016, and do a detailed visual inspection of the bore holes for defects, in accordance with Dassault Service Bulletin 7X-379, dated February 29, 2016.

(1) For airplanes with S/Ns 2 and 5: Before exceeding 4,100 flight cycles after the date of release to service after the first C-Check or within 3 months from the effective date of this AD, whichever occurs later.

(2) For airplanes other than those identified in paragraph (g)(1) of this AD: Before exceeding 4,100 flight cycles since the date of issuance of the original certificate of airworthiness or the original

export certificate of airworthiness or within 3 months from the effective date of this AD, whichever occurs later.

(h) Repair of Bore Holes and Bolt Replacement

(1) If, during any inspection required by paragraph (g) of this AD, any defect is found, before further flight, repair the affected areas, and replace the bolts at FR36 and FR39, in accordance with Dassault Service Bulletin 7X-379, dated February 29, 2016; except where Dassault Service Bulletin 7X-379, dated February 29, 2016, specifies to contact Dassault Aviation for instructions, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA).

(2) If, during any inspection required by paragraph (g) of this AD, no defect is found, before further flight, replace the bolts at FR36 and FR39, in accordance with Dassault Service Bulletin 7X-379, dated February 29, 2016.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0116, dated June 16, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9504.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Service Bulletin 7X-379, dated February 29, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 12, 2017.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.

