

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2017-18**

8/21/2017 - 9/3/2017



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2017-01

2016-25-01		The Boeing Company	747-400, 747-400D, and 747-400F series; 757-200, -200PF, -200CB, and -300 series; 767-200, -300, -300F, and -400ER series; 767-300 and -300F series; and 767-300 and -300F series
2016-25-07	R 2012-11-15	The Boeing Company	767-200 and -300 series
2016-25-25		BAE (Operations) Limited	4101
2016-25-26		The Boeing Company	MD-90-30
2016-25-27		Airbus	A300 B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R variant F
2016-25-29		The Boeing Company	767-200 and -300 series
2016-25-30		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; A340-642
2016-25-31		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313; A340-541; and A340-642
2016-26-02		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705); and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000)
2016-26-03	R 2013-23-02	Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295
2016-26-05	R 2014-26-08	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2017-01-07		Dassault Aviation	FAN JET FALCON; FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON
2017-01-08		Airbus	20-C5, 20-D5, 20-E5, and 20-F5; MYSTERE-FALCON 50
2016-25-02		The Boeing Company	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342 and -343 airplanes; and Model A340-211, -212, -213, -311, -312, -313, -541, and -642
			787-8 series

Biweekly 2017-02

2016-26-06		The Boeing Company	787-8 airplanes
2016-26-07		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes
2017-01-01	R 2014-05-25	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2017-01-02		The Boeing Company	787-8 and 787-9 airplanes
2017-01-04		Fokker Services B.V.	F28 Mark 0100 airplanes
2017-01-05		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, and CN-235-300 airplanes
2017-01-06		Airbus	A319-115, A319-132, A320-214, A320-232, A321-211, A321-213, and A321-231 airplanes
2017-01-09		The Boeing Company	767-300 and 767-300F series airplanes
2017-01-10		Airbus Defense and Space S.A.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, C-212-CF, C-212-DF, and C-212-DE airplanes
2017-01-11		Airbus	A318, A319, A320, A321 airplanes

Biweekly 2017-03

No ADs

Biweekly 2017-04

2017-01-03	R 2007-11-13	The Boeing Company	717-200 airplanes
2017-01-09	COR	The Boeing Company	767-300 and 767-300F series airplanes
2017-01-11		Airbus	A318, A319, A320, A321 airplanes
2017-02-02	2005-13-30	The Boeing Company	737-100, -200, and -200C series airplanes
2017-02-03		The Boeing Company	767-200, -300, and -400ER series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-02-04		The Boeing Company	747-200B, 747-300, 747-400, 747-400D, and 747-400F series airplanes
2017-02-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-02-08		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes
2017-02-09		The Boeing Company	747-400, -400D, and -400F series airplanes
2017-02-10	R 2013-19-04	The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-03-02	S 2014-16-10	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
Biweekly 2017-05			
2017-02-01		Rolls-Royce plc	Trent 1000-A, Trent 1000-C, Trent 1000-D, Trent 1000-E, Trent 1000-G, and Trent 1000-H turbofan engines
2017-02-12		The Boeing Company	737-300, -400, and -500 series airplanes
2017-03-03	S 2013-05-18	Rolls-Royce plc	RB211 Trent 553-61, RB211 Trent 553A2-61, RB211 Trent 556-61, RB211 Trent 556A2-61, RB211 Trent 556B-61, RB211 Trent 556B2-61, RB211 Trent 560-61, and RB211 Trent 560A2-61 turbofan engines
2017-03-04	R 2012-16-07	The Boeing Company	737-500 series airplanes
2017-04-01		Gulfstream Aerospace Corporation	GVI airplanes
2017-04-02	R 2014-23-06	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2017-04-04	R 2012-16-08	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes
2017-04-05	R 2011-10-17	Airbus	A300 B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, and B4-203 airplanes
2017-04-06		United Instruments, Inc.	5934 series altimeters
2017-04-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2017-04-08	R 2008-13-12 R1	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-04-09	R 2012-22-12	Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-04-10		Airbus	A318, A319, A320, A321 airplanes
2017-04-11		The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-04-12		Embraer	EMB-135, EMB-145 airplanes
2017-04-13		The Boeing Company	747-8 and 747-8F series airplanes
2017-04-15		Learjet Inc.	36A airplanes
2017-05-01		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2017-05-02		Airbus	A318, A319, A320, A321 airplanes
2017-05-06		The Boeing Company	767-200 and -300 series airplanes
2017-05-07		The Boeing Company	777-200 and -300 series airplanes
Biweekly 2017-06			
2017-05-09		CFM International S.A.	CFM56-5B, CFM56-5B/P, CFM56-5B/3, CFM56-5B/2P, CFM56-5B/P1, CFM56-5B/2P1, and CFM56-5B/3B1 engines
2017-05-11	R 2012-08-11	Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-05-10	R 2015-16-02	Airbus	A330-201, A330-202, A330-203, A330-223, A330-243, A330-223F, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes
2017-05-05		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
2017-05-12		Airbus	A318-112; A319-111, -112, -115, -132, and -133; A320-214, -232, and -233; A321-211, -212, -213, -231, and -232 airplanes
Biweekly 2017-07			
2017-06-05		The Boeing Company	DC-6, DC-6A, DC-6B, C-118A, R6D-1, and R6D-1Z airplanes
2017-07-03		Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-06-04		Airbus	A300 B4-603, B4-620, and B4-622; A300 B4-605R and A300 B4-622R; and A300 C4-605R Variant F airplanes
2017-06-02		Fokker Services B.V.	F28 Mark 0100 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-06-10		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-06-09		The Boeing Company	787-8 airplanes
2017-06-01	R 2017-03-04	The Boeing Company	737-500 series airplanes
2017-06-14		The Boeing Company	737-300, -400, and -500 series airplanes
2017-06-13		Textron Aviation Inc.	680 airplanes
2016-25-25	COR	BAE Systems (Operations) Limited	4101 airplanes
2017-06-12		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233 airplanes
Biweekly 2017-08			
2017-08-04	R 2015-03-01	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2017-07-06		Gulfstream Aerospace Corporation	G-1159B airplanes
2017-08-05	R 2016-13-05	General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, and GE90-94B turbofan engines
2017-06-07		Airbus	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; and A340-642 airplanes
2017-07-03	COR	Airbus	A330-243, -243F, -341, -342, and -343 airplanes
2017-08-01	R 2013-22-19	Gulfstream Aerospace Corporation	GV and GV-SP airplanes
2017-06-08	R 2006-06-09 R 2012-05-08 R 2012-07-08	Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU; ERJ 170-200 LR, -200 SU, and -200 STD airplanes
2017-07-04	R 2013-24-17	General Electric Company	GE90-110B1 and GE90-115B engines
2017-08-02		Bombardier, Inc.	DHC-8-102, -103, and -106; DHC-8-201 and -202; DHC-8-301, -311, and -315 airplanes
2017-07-05		Airbus	A300 airplanes
Biweekly 2017-09			
2017-07-07		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2017-08-03		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-08-06		General Electric Company	GE90-76B, GE90-85B, GE90-90B, GE90-94B, GE90-110B1, and GE90-115B
2017-08-07		Learjet, Inc.	60
2017-08-08		CFE Company	CFE738-1-1B
2017-08-10	R 2017-01-01	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84
2017-08-11	R 2012-04-01	Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17
2017-08-13		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R, and A300 C4-605R Variant F; and A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 F4-605R and F4-622R
2017-09-01		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000)
2016-05-02	R 2011-13-11 R 2011-13-11	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
Biweekly 2017-10			
2017-09-03	R 2013-03-12	Dassault Aviation	MYSTERE-FALCON 50 airplanes
2017-09-04		The Boeing Company	707-100 Long Body, -200, -100B Long Body, and -100B Short Body series; 707-300, -300B, -300C, and -400 series; 720 and 720B series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-09-06 2017-10-01	R 2015-15-03	General Electric Company Dassault Aviation	GENx-1B and GENx-2B turbofan engines FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
Biweekly 2017-11			
2017-09-08		The Boeing Company	787-8 airplanes
2017-09-09		Zodiac Seats California LLC	4157, 4170, and 4184 seating systems
2017-09-10		The Boeing Company	747-400, 747-400D, and 747-400F airplanes
2017-09-11		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2017-09-12		ATR-GIE Avions de Transport Régional	ATR42-500; ATR72-102, -202, -212, and -212A airplanes
2017-10-04		Embraer S.A.	EMB-120, EMB-120ER, EMB-120FC, EMB-120QC, and EMB-120RT airplanes
2017-10-05		Airbus	A300 airlines
2017-10-06		Rolls-Royce plc	RB211 Trent 768-60, RB211 Trent 772-60, and RB211 Trent 772B-60 turbofan engines
2017-10-07		The Boeing Company	737-400 series airplanes
2017-10-08	R 2009-21-01	The Boeing Company	737-300 series airplanes
2017-10-14	S 2014-07-07	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Series 3101 airplanes
2017-10-15		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes
2017-10-16		The Boeing Company	787-8 and 787-9 airplanes
2017-10-17	R 2014-16-19	Airbus	A330 airplanes
2017-10-18		Airbus	A330-223F, -223, -321, -322, and -323 airplanes
2017-10-21		The Boeing Company	737-300, -400, and -500 series airplanes
2017-10-22		The Boeing Company	737-600, -700, -700C, -800, and -900 series airplanes
2017-10-23		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-10-24	R 2011-17-09 R 2012-25-12	Airbus	A330 airplanes
2017-10-25		Rolls-Royce Deutschland Ltd & Co KG	Spey 506-14A, Spey 555-15, Spey 555-15H, Spey 555-15N, and Spey 555-15P turbofan engines
2017-11-01		The Boeing Company	737-100, -200, and -200C series airplanes
2017-11-02		The Boeing Company	MD-90-30 airplanes
2017-11-09	R 2017-08-07	Learjet, Inc.	Model 60 airplanes
Biweekly 2017-12			
2017-10-07		The Boeing Company	737-400 series airplanes
2017-10-08	R 2009-21-01	The Boeing Company	737-300 series airplanes
2017-10-13	S 2015-17-19	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2017-10-14	S 2014-07-07	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200, and Jetstream Series 3101 airplanes
2017-11-04		The Boeing Company	767-200, -300, and -400ER series airplanes
2017-11-07		Airbus	A318, A319, A320, A321 airplanes
2017-11-09	R 2017-08-07	Learjet, Inc.	60 airplanes
2017-11-11		NavWorx, Inc.	ADS600-B and ADS600-EXP ADS-B Universal Access Transceiver units
2017-11-12		Bombardier, Inc.	BD-100-1A10 airplanes
2017-11-13	R 98-13-14	Airbus	A320-211, -212, and -231 airplanes
2017-11-14	R 2011-26-03	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F airplanes
2017-11-15		General Electric Company	CF6-80C2L1F turbofan engines
2017-12-01		The Boeing Company	767-200 series airplanes
2017-12-02		General Electric Company	GENx-1B64, -1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, 1B70/P1, -1B70/P2, -1B70/75/P1, -1B70/75/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76A/P2 engines
Biweekly 2017-13			
2017-11-05		Roll-Royce Corporation	AE 3007C and 3007C1 turbofan engines
2017-11-06	R 2014-05-32	Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-12-03		Pratt & Whitney Division	PW2037, PW2037M, and PW2040 turbofan engines
2017-12-05	R 2007-26-04	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2017-12-06		Airbus	A300, A310 airplanes
2017-12-07		The Boeing Company	737-800, -900, and -900ER series airplanes
2017-12-08	R 2011-24-06	BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes
2017-12-09		Embraer	EMB-135ER, -135BJ, -135KE, -135KL, and -135LR; and EMB-145, -145ER, -145MR, -145LR, -145MP, -145EP, and -145XR airplanes
2017-12-10		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-12-11		Bombardier, Inc.	BD-100-1A10 airplanes
2017-12-12		The Boeing Company	757-200, -200PF, and -200CB series airplanes
2017-12-13		Airbus	A320-212, A320-214, A320-232 airplanes
2017-12-14		The Boeing Company	757-200 and -200PF series airplanes
2017-12-15		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000) airplanes
2017-13-01		The Boeing Company	737-300, -400, and -500 series airplanes
2017-13-02		Dassault Aviation	FALCON 7X airplanes
Biweekly 2017-14			
2017-10-19		Rolls-Royce plc	Trent 1000-A2, Trent 1000-C2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2
2017-13-07		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-13-08	R 2015-23-13	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-13-09	R 2014-16-02	Bombardier, Inc.	CL-600-1A11 (CL-600)
2017-13-10	R 2003-18-06	Airbus	A319-131 and -132; A320-231, -232, and -233; A321-131 and -231
2017-13-11		Gulfstream Aerospace Corporation	G-IV
2017-13-12		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-13-13		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2017-13-14		The Boeing Company	777-300ER series
2017-14-01	R 2013-10-03	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2017-14-02		Bombardier, Inc.	DHC-8-401 and DHC-8-402
Biweekly 2017-15			
2017-14-07		International Aero Engines AG	V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5, V2525-D5, V2528-D5, and V2531-E5 turbofan engines
2017-14-08		CFM International S.A.	CFM56-3, -3B, and -3C turbofan engines
2017-14-09		Fokker Services B.V.	F28 Mark 0100 airplanes
2017-14-10		The Boeing Company	MD-11 and MD-11F airplanes
2017-14-11	R 2007-13-08	Airbus	A318, A319, A320, A321 airplanes
2017-14-13		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2017-14-14		Airbus	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2017-14-16		Bombardier, Inc.	BD-100-1A10 airplanes
2017-15-01		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series airplanes
2017-15-03	R 2014-08-02	Airbus	A300-B4-601, B4-603, B4-620, and B4-622 airplanes, and A300-B4-605R and B4-622R airplanes
2017-15-04		The Boeing Company	787-8 and 787-9 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2017-16			
2017-13-05	R 2013-13-16	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2017-14-15		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2017-15-06	R 97-10-05	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200 and 3101, and Jetstream Model 3201 airplanes
2017-15-10		The Boeing Company	787-9 airplanes
2017-15-11		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2017-15-12		The Boeing Company	737-300, -400, and -500 series airplanes
2017-15-14		Bombardier, Inc.	CL-215-6B11 (CL-415 Variant) airplanes
2017-15-16		Embraer	EMB-135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes
2017-15-17		Airbus	A300 B4-605R and B4-622R; A300 C4-605R Variant F; A300 F4-605R and F4-622R airplanes
Biweekly 2017-17			
2017-14-12	R 2015-22-06	Airbus	318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-15-08		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000)
2017-16-05		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2017-16-06		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
Biweekly 2017-18			
2017-16-09		Dassault Aviation	MYSTERE-FALCON 50 and FALCON 2000
2017-16-10		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series
2017-16-12	R 2013-19-09 R 2014-25-51	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2017-16-13		Bombardier, Inc.	CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants)
2017-17-02	R 2014-20-09	Bombardier, Inc.	DHC-8-400, -401, and -402
2017-17-04		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2017-17-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2017-17-06		The Boeing Company	737-300, -400, and -500 series
2017-17-07		Rolls-Royce plc	Trent XWB-75, Trent XWB-79, Trent XWB-79B, and Trent XWB-84 turbofan engines
2017-17-08		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-541 and -642
2017-17-09		The Boeing Company	737-300, -400, and -500 series
2017-17-10	R 2015-23-12	ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500; and ATR72-101, -201, -102, -202, -211, -212, and -212A
2017-17-11		Dassault Aviation	FALCON 7X
2017-17-12		Airbus	A310-203, -221, -222, -304, -322, -324, and -325
2017-17-13		Bombardier, Inc.	BD-100-1A10
2017-17-14		Saab AB, Saab Aeronautics	340A (SAAB/SF340A)
2017-17-15		Bombardier, Inc.	CL-600-2E25 (Regional Jet Series 1000)
2017-17-16		The Boeing Company	767-200, -300, -300F, and -400ER series
2017-17-18		General Electric Company	CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5B1, CF34-8C5A2, CF34-8C5A3, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6 and CF34-8E6A1; CF34-8C5B1/B, CF34-8C5/B, CF34-8C5A1/B, CF34-

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2017-17-19		The Boeing Company	8C5A2/B, CF34-8C5/M, CF34-8C5A1/M, CF34-C8C5A2/M, CF34-8C5A3/B, or CF34-8C5B1/M
2017-18-05		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) and MD-88
2017-18-06	R 2012-05-03	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2017-18-07		Dassault Aviation	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2017-18-08		Dassault Aviation	FALCON 7X
			FALCON 2000 and FALCON 2000EX



2017-16-09 Dassault Aviation: Amendment 39-18986; FAA-2017-0130; Product Identifier 2016-NM-058-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model MYSTERE-FALCON 50 airplanes and FALCON 2000 airplanes, certificated in any category, all serial numbers.

Note 1 to paragraph (c) of this AD: Model MYSTERE-FALCON 50 airplanes include all commercial variants, including F50EX airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by a report indicating that during ground maintenance, a Model FALCON 2000 airplane experienced a loss of hydraulic pressure affecting both hydraulic systems due to damage to both brake hoses on the main landing gear (MLG). We are issuing this AD to detect and correct unprotected brake hoses, which could lead to loss of braking during landing or a rejected take-off, and result in a runway excursion and a risk of fire if the leaking brake hydraulic fluid reaches hot parts.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 9 months after the effective date of this AD, inspect the brake hoses to identify whether any brake hose having part number (P/N) AE705317-1 or P/N 00-200-1268 is installed. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the brake hose can be conclusively determined from that review.

(h) Installation

If, during the inspection required by paragraph (g) of this AD, it is determined that any brake hose having P/N AE705317-1 or P/N 00-200-1268 is installed, within 9 months after the effective date of this AD, do the actions specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Install protective wraps on the brake hoses, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F50-510, Revision 2, dated December 20, 2012; or Dassault Service Bulletin F2000-382, Revision 2, dated May 12, 2011; as applicable.

(2) Install brake hoses having P/N 00-200-1534 that are fitted with Dacron sleeves, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F50-518, dated April 14, 2011; or Dassault Service Bulletin F2000-368, dated May 29, 2009; as applicable.

Note 2 to paragraphs (h)(2) and (i) of this AD: Dassault Service Bulletin F50-518, dated April 14, 2011, refers to Messier-Dowty Service Bulletin C23791-32-062, dated February 22, 2011; and Dassault Service Bulletin F2000-368, dated May 29, 2009, refers to Messier-Dowty Service Bulletin D23345-32-020, dated May 14, 2009; as additional sources of guidance for doing the replacement.

(i) Replacement

Within 6,000 flight cycles, or within 149 months, whichever occurs first after the effective date of this AD: Replace brake hoses having P/N AE705317-1 and P/N 00-200-1268 with brake hoses having P/N 00-200-1534 that are fitted with Dacron sleeves, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F50-518, dated April 14, 2011; or Dassault Service Bulletin F2000-368, dated May 29, 2009; as applicable. Once brake hoses having P/N 00-200-1534 are fitted in an MLG leg, no further action is required for that MLG leg, as specified in paragraph (j) of this AD.

(j) Provisions for Unaffected MLG Leg Assemblies

If, during the inspection required by paragraph (g) of this AD, it is determined that the airplane is equipped with an MLG leg assembly with a part number specified in table 1 to paragraph (j) of this AD, the requirement of paragraph (h) of this AD is not applicable, provided that the MLG leg assembly has not been modified in service after its installation on an airplane.

Table 1 to Paragraph (j) of This AD—MLG Leg Assembly Not Affected

Model	MLG leg position	Part No.
MYSTERE-FALCON 50 airplanes	Left Hand (LH)	C23791-1009 amdt F.
MYSTERE-FALCON 50 airplanes	Right Hand (RH)	C23792-1009 amdt F.
FALCON 2000	LH	D23345000-7 amdt B.
FALCON 2000	RH	D23346000-7 amdt B.

Note 3 to paragraph (j) of this AD: The parts specified in table 1 to paragraph (j) of this AD are known to be delivered with brake hoses having P/N 00-200-1534 that are fitted with Dacron sleeves.

(k) Parts Installation Limitation

As of the effective date of this AD, no person may install a brake hose having P/N AE705317-1 or P/N 00-200-1268 on any airplane, unless the brake hose has been inspected to verify that protective wraps are installed on the hose, in accordance with the Accomplishment Instructions of

Dassault Service Bulletin F50-510, Revision 2, dated December 20, 2012; or Dassault Service Bulletin F2000-382, Revision 2, dated May 12, 2011; as applicable.

(l) Parts Installation Prohibition

As of the effective date of this AD, no person may install, on any airplane, a brake hose having P/N AE705317-1 or P/N 00-200-1268, or an MLG leg or shock absorber equipped with a brake hose having P/N AE705317-1 or P/N 00-200-1268, after the actions in paragraphs (h)(2) or (i) of this AD are done.

(m) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (h)(1) and (k) of this AD, if those actions were performed before the effective date of this AD using Dassault Service Bulletin F50-510, Revision 1, dated December 15, 2010; or Dassault Service Bulletin F2000-382, Revision 1, dated December 15, 2010.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2013-0255, dated October 23, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0130.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1137; fax: 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Service Bulletin F50-510, Revision 2, dated December 20, 2012.

(ii) Dassault Service Bulletin F50-518, dated April 14, 2011.

(iii) Dassault Service Bulletin F2000-368, dated May 29, 2009.

(iv) Dassault Service Bulletin F2000-382, Revision 2, dated May 12, 2011.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone: 201-440-6700; Internet: <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 28, 2017.

John P. Piccola, Jr.,

Acting Director, System Oversight Division,

Aircraft Certification Service.



2017-16-10 The Boeing Company: Amendment 39-18987; Docket No. FAA-2016-9520; Product Identifier 2016-NM-163-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage and 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of cracks on the underwing longerons. We are issuing this AD to detect and correct cracks in the underwing longerons, which could result in fuel leakage into the forward cargo area and consequent increased risk of a fire or, in a more severe case, could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections

Except as specified in paragraph (i)(1) of this AD, at the applicable times specified in tables 1 through 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016: Do detailed inspections for any crack of the left and right side underwing longerons; or do detailed inspections, and high frequency eddy current (HFEC) or ultrasonic inspections, as applicable, for any crack of the left and right side underwing longerons; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016, or Boeing Alert Service Bulletin 777-53A0081, Revision 1, dated May 1, 2017, except as required by paragraph (i)(2) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections thereafter at the times specified in tables 1 through 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016, as applicable. Replacing an underwing longeron, including doing all applicable related investigative and

corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016; or Boeing Alert Service Bulletin 777-53A0081, Revision 1, dated May 1, 2017; except as required by paragraph (i)(2) of this AD, terminates the repetitive inspections required by this paragraph for that longeron only.

(h) Repetitive Post-Replacement Inspections and Corrective Actions

For airplanes on which any longeron replacement has been done as specified in Boeing Alert Service Bulletin 777-53A0081: At the applicable times specified in tables 7 through 14 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016, do detailed inspections of all replaced longerons for any crack, or do detailed inspections and ultrasonic inspections of all replaced longerons for any crack, and do all applicable corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016; or Boeing Alert Service Bulletin 777-53A0081, Revision 1, dated May 1, 2017; except as required by paragraph (i)(2) of this AD. Do all applicable corrective actions before further flight. Repeat the inspections thereafter at intervals not to exceed the applicable time specified in tables 7 through 14 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016.

(i) Service Information Exceptions

(1) Where Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016, specifies a compliance time "after the issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016; or Boeing Alert Service Bulletin 777-53A0081, Revision 1, dated May 1, 2017; specifies to contact Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or sub-step is labeled "RC Exempt," then the

RC requirement is removed from that step or sub-step. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6412; fax: 425-917-6590; email: eric.lin@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777-53A0081, dated September 8, 2016.

(ii) Boeing Alert Service Bulletin 777-53A0081, Revision 1, dated May 1, 2017.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 2, 2017.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.



2017-16-12 Airbus: Amendment 39-18989; Docket No. FAA-2016-9518; Product Identifier 2015-NM-091-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

(1) This AD replaces AD 2013-19-09, Amendment 39-17591 (78 FR 60667, October 2, 2013) (“AD 2013-19-09”); and AD 2014-25-51, Amendment 39-18067 (80 FR 3153, January 22, 2015) (“AD 2014-25-51”).

(2) This AD affects AD 2013-06-03, Amendment 39-17399 (78 FR 19085, March 29, 2013) (“AD 2013-06-03”).

(c) Applicability

This AD applies to the Airbus airplanes listed in paragraphs (c)(1) through (c)(4) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Airbus Model A318-111, -112, -121, and -122 airplanes.

(2) Airbus Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.

(3) Airbus Model A320-211, -212, -214, -231, -232, and -233 airplanes.

(4) Airbus Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Reason

This AD was prompted by a report indicating that an Airbus Model A321 airplane encountered a blockage of two Angle of Attack (AOA) probes during climb, leading to activation of the Alpha Protection (Alpha Prot) while the Mach number increased. We are issuing this AD to prevent a pitch down order due to abnormal activation of the Alpha Prot. An abnormal Alpha Prot, if not corrected, could result in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained New Flat Plate Installation, With Removed Post-Installation Requirement, Specific Delegation Approval Language, and New Service Information

This paragraph restates the requirements of paragraph (j) of AD 2013-19-09, with a removed post-installation requirement, specific delegation approval language, and revised service information.

Within 5 months after November 6, 2013 (the effective date of AD 2013-19-09), remove all AOA sensor conic plates having part number (P/N) F3411060200000 or P/N F3411060900000, and install AOA sensor flat plates having P/Ns specified in paragraph (g)(1) or (g)(2) of this AD, except as specified in paragraph (h) of this AD. Install the AOA sensor plates in accordance with the applicable method specified in paragraph (g)(1) or (g)(2) of this AD.

(1) Install P/N D3411013520200 in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A320-34-1564, including Appendix 01, dated January 25, 2013, or Airbus Service Bulletin A320-34-1564, Revision 01, dated August 26, 2013. As of the effective date of this AD, only Airbus Service Bulletin A320-34-1564, Revision 01, dated August 26, 2013, may be used for accomplishment of the actions required by this paragraph.

(2) Install P/N D3411007620000 or P/N D3411013520000, using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(h) Retained Exception, With No Changes

This paragraph restates the exception provided by paragraph (k) of AD 2013-19-09, with no changes. An airplane on which Airbus modification 154863 (installation of AOA sensor flat plate) and modification 154864 (coating protection) have been embodied in production is not affected by the requirements of paragraph (g) of this AD, provided that, since first flight, no AOA sensor conic plate having P/N F3411060200000 or P/N F3411060900000 has been installed on that airplane.

(i) Retained Parts Installation Prohibition, With No Changes

This paragraph restates the requirements of paragraph (m) of AD 2013-19-09, with no changes.

(1) For any airplane that has AOA sensor flat plates installed: As of November 6, 2013 (the effective date of AD 2013-19-09), do not install any AOA sensor conic plate having P/N F3411060200000 or P/N F3411060900000, and do not use any AOA protection cover having P/N 98D34203003000.

(2) For any airplane that has AOA sensor conic plates installed: As of November 6, 2013 (the effective date of AD 2013-19-09), after modification of the airplane as required by paragraph (g) of this AD, do not install any AOA sensor conic plate having P/N F3411060200000 or P/N F3411060900000, and do not use any AOA protection cover having P/N 98D34203003000.

(j) Retained Revision of Airplane Flight Manual (AFM), With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2014-25-51, with no changes. Within 2 days after February 6, 2015 (the effective date of AD 2014-25-51), revise the AFM to incorporate procedures to address undue activation of Alpha Prot by inserting the text specified in figure 1 to paragraph (j) of this AD into the Emergency Procedures section of the applicable AFM, to advise the flight crew of emergency procedures for abnormal Alpha Prot. This may be accomplished by inserting a copy of this AD into the AFM. When a statement identical to the text specified in figure 1 to paragraph (j) of this AD is included in the general revisions of the AFM, the general revisions may be inserted in the AFM, and the text specified in figure 1 to paragraph (j) of this AD may be removed.

Figure 1 to paragraph (j) of this AD - AFM Procedure

- At any time, with a speed above VLS, if the aircraft goes to a continuous nose down pitch rate that cannot be stopped with backward sidestick inputs, immediately:
Keep on one ADR.
Turn off two ADRs.
 - If the Alpha Max strip (red) hides completely the Alpha Prot strip (black and amber) in a stabilized wings-level flight path (without an increase in load factor):
Keep on one ADR.
Turn off two ADRs.
In case of dispatch with one ADR inoperative, switch only one ADR to OFF.
- CAUTION** RISK OF ERRONEOUS DISPLAY OF THE VSW STRIP (RED AND BLACK)
- Consider using the Flight Path Vector (FPV).
- If the Alpha Prot strip (black and amber) rapidly moves by more than 30 kt during flight maneuvers (with an increase in load factor), with AP ON and speed brakes retracted:
Keep on one ADR.
Turn off two ADRs.
In case of dispatch with one ADR inoperative, switch only one ADR to OFF.
- CAUTION** RISK OF ERRONEOUS DISPLAY OF THE VSW STRIP (RED AND BLACK)
- Consider using the Flight Path Vector (FPV).

(k) New Requirement of This AD: Replacement of Certain UTAS (Formerly Goodrich) AOA Sensors

For airplanes on which any UTAS AOA sensor, P/N 0861ED or P/N 0861ED2, is installed: Within the applicable compliance times specified in paragraphs (k)(1), (k)(2), (k)(3), and (k)(4) of this AD, replace the affected Captain and First Officer AOA sensors with Thales AOA sensors, P/N C16291AB, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-34-1610, Revision 01, dated July 30, 2015.

(1) For Model A318 and A321 series airplanes on which any UTAS AOA sensor, P/N 0861ED, is installed: Replace within 7 months after the effective date of this AD.

(2) For Model A319 and A320 series airplanes on which any UTAS AOA sensor, P/N 0861ED, is installed: Replace within 22 months after the effective date of this AD.

(3) For Model A318 and A321 series airplanes on which any UTAS AOA sensor, P/N 0861ED2, is installed: Replace within 4 months after the effective date of this AD.

(4) For Model A319 and A320 series airplanes on which any UTAS AOA sensor, P/N 0861ED2, is installed: Replace within 7 months after the effective date of this AD.

(l) New Requirement of This AD: Replacement of Certain SEXTANT/THOMSON AOA Sensors

(1) For airplanes on which any SEXTANT/THOMSON AOA sensor, P/N 45150320 or P/N 16990568, is installed: Within the applicable compliance time specified in paragraphs (l)(1)(i) or (l)(1)(ii) of this AD, replace each SEXTANT/THOMSON AOA sensor, P/N 45150320 and P/N 16990568, with a Thales AOA sensor, P/N C16291AB, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-34-1444, Revision 01, dated March 17, 2011; except AOA sensor probes P/N C16291AB having a serial number specified in Thales Service Bulletin C16291A-34-007, Revision 04, dated October 11, 2012, may not be installed unless the AOA probe

sensors have been inspected and re-identified, and have passed a functional test, in accordance with the Thales service information specified in paragraphs (l)(2)(i), (l)(2)(ii), (l)(2)(iii), or (l)(2)(iv) of this AD.

(i) For Model A318 and A321 series airplanes on which any SEXTANT/THOMSON AOA sensor, P/N 45150320 or P/N 16990568, is installed: Replace within 7 months after the effective date of this AD.

(ii) For Model A319 and A320 series airplanes on which any SEXTANT/THOMSON AOA sensor, P/N 45150320 or P/N 16990568, is installed: Replace within 22 months after the effective date of this AD.

(2) As specified in paragraph (l)(1) of this AD, use the following Thales service information specified in paragraphs (l)(2)(i), (l)(2)(ii), (l)(2)(iii), or (l)(2)(iv) of this AD.

(i) Thales Service Bulletin C16291A-34-007, Revision 04, dated October 11, 2012.

(ii) Thales Service Bulletin C16291A-34-007, Revision 03, dated April 10, 2012.

(iii) Thales Service Bulletin C16291A-34-007, Revision 02, dated December 16, 2011.

(iv) Thales Service Bulletin C16291A-34-007, Revision 01, dated December 03, 2009.

(m) New Requirement of This AD: Functional Heating Test, and Corrective Action for Certain AOA Sensors

For an airplane on which any Thales AOA sensor, P/N C16291AA, is installed: Before exceeding 5,200 flight hours accumulated by each affected Thales AOA sensor since its first installation on an airplane, or within 6 months after the effective date of this AD, whichever occurs later, do a functional heating test of each AOA sensor, P/N C16291AA, to determine the maximum current (Imax) value, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-34-1415, Revision 04, dated July 30, 2015. If, during any functional heating test, any Imax value is below the flow chart value as specified in Airbus Service Bulletin A320-34-1415, Revision 04, dated July 30, 2015, before further flight, replace each discrepant AOA sensor with a sensor identified in paragraph (m)(1) or (m)(2) of this AD, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-34-1415, Revision 04, dated July 30, 2015. Repeat the functional heating test thereafter at intervals not to exceed 2,000 flight hours.

(1) Replace with a Thales AOA sensor, P/N C16291AA, that has passed a functional heating test as specified in the Accomplishment Instructions of Airbus Service Bulletin A320-34-1415, Revision 04, dated July 30, 2015.

(2) Replace with a Thales AOA sensor, P/N C16291AB, except AOA sensor probes P/N C16291AB having a serial number specified in Thales Service Bulletin C16291A-34-007, Revision 04, dated October 11, 2012, may not be installed unless the AOA probe sensors have been inspected and re-identified, and have passed a functional test, in accordance with the Thales service information specified in paragraphs (l)(2)(i), (l)(2)(ii), (l)(2)(iii), or (l)(2)(iv) of this AD.

(n) Optional Terminating Action

Modification of an airplane by replacing each Thales P/N C16291AA AOA sensor with a Thales P/N C16291AB AOA sensor, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-34-1444, Revision 01, dated March 17, 2011, terminates the repetitive functional heating tests required in paragraph (m) of this AD for that airplane; except AOA sensor probes P/N C16291AB having a serial number specified in Thales Service Bulletin C16291A-34-007, Revision 04, dated October 11, 2012, may not be installed, unless the AOA probe sensors have been inspected and re-identified, and have passed a functional test, in accordance with the Thales service information specified in paragraphs (l)(2)(i), (l)(2)(ii), (l)(2)(iii), or (l)(2)(iv) of this AD.

(o) New Provisions of This AD: Airplanes Not Affected

An airplane with Airbus modification 150006 (installation of Thales P/N C16291AB AOA sensors), but without modification 26934 (installation of UTAS P/N 0861ED AOA sensors) embodied in production, is not affected by the requirements of paragraphs (k), (l), and (m) of this AD, provided it is determined that no AOA sensor having SEXTANT/THOMSON P/N 45150320 or 16990568, or UTAS P/N 0861ED or 0861ED2, has been installed on that airplane since its date of manufacture.

(p) New Requirement of This AD: Parts Installation Prohibitions

(1) As of the effective date of this AD: For an airplane on which only Thales AOA sensors, P/N C16291AB, are installed, do not install a Thales AOA sensor, P/N C16291AA, on that airplane. This parts installation prohibition terminates the requirements of paragraph (i)(1) of AD 2013-06-03 for the airplanes identified in this paragraph.

(2) As of the effective date of this AD: For an airplane on which any combination of Thales AOA sensors, P/N C16291AA and Thales P/N C16291AB, is installed, do not install any SEXTANT/THOMSON AOA sensor, P/N 45150320 or 16990568, or UTAS AOA sensor, P/N 0861ED or 0861ED2, on that airplane.

(3) After modification of an airplane as required by paragraph (k) of this AD, do not install any AOA sensor with a part number specified in paragraphs (p)(3)(i) and (p)(3)(ii) of this AD on that airplane, with the exception that installation of a UTAS P/N 0861ED AOA sensor is allowed in the standby position of that airplane.

(i) SEXTANT/THOMSON AOA sensors, P/N 45150320 and P/N 16990568.

(ii) UTAS AOA sensors, P/N 0861ED and P/N 0861ED2.

(q) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (k) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-34-1610, dated March 31, 2015.

(2) This paragraph provides credit for the actions required by paragraph (l) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-34-1444, dated October 7, 2009; except AOA sensor probes P/N C16291AB having a serial number specified in Thales Service Bulletin C16291A-34-007, Revision 04, dated October 11, 2012, may not be installed unless the AOA probe sensors have been inspected and re-identified, and have passed a functional test, using the Thales service information specified in paragraphs (l)(2)(i), (l)(2)(ii), (l)(2)(iii), or (l)(2)(iv) of this AD.

(3) This paragraph provides credit for the actions required by paragraph (m) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-34-1415, Revision 03, July 8, 2010.

(r) Acceptable Parts

Installation of a version (part number) of an AOA sensor approved after the effective date of this AD is an approved method of compliance with the requirements of paragraph (k), (l), or (m) of this AD, as applicable, provided the requirements specified in paragraphs (r)(1) and (r)(2) of this AD are met.

(1) The version (part number) must be approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA.

(2) The installation must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA.

(s) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to the attention of the person identified in paragraph (u)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2013-19-09 are approved as AMOCs for the corresponding provisions of paragraphs (g), (h), (i), and (t)(1) of this AD.

(iii) AMOCs approved previously for AD 2014-25-51 are approved as AMOCs for the corresponding provisions of paragraph (j) of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(t) Retained Provisions for Special Flight Permits

(1) For the requirements of paragraphs (g), (h), and (i) of this AD: Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be modified (if the operator elects to do so), provided Airbus A318/A319/A320/A321 TR TR286, Issue 1.0, dated December 17, 2012, has been inserted into the Emergency Procedures of the Airbus A318/A319/A320/A321 AFM.

(2) For the requirements of paragraphs (j) of this AD: Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be modified (if the operator elects to do so), provided the revision required by paragraph (j) of this AD has been done.

(u) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0135, dated July 8, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9518.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (v)(5) and (v)(6) of this AD.

(v) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on October 2, 2017.

(i) Airbus Service Bulletin A320-34-1415, Revision 04, dated July 30, 2015.

(ii) Airbus Service Bulletin A320-34-1444, Revision 01, dated March 17, 2011.

(iii) Airbus Service Bulletin A320-34-1564, Revision 01, dated August 26, 2013.

(iv) Airbus Service Bulletin A320-34-1610, Revision 01, dated July 30, 2015.

(v) Thales Service Bulletin C16291A-34-007, Revision 04, dated October 11, 2012.

(vi) Thales Service Bulletin C16291A-34-007, Revision 03, dated April 10, 2012.

(vii) Thales Service Bulletin C16291A-34-007, Revision 02, dated December 16, 2011.

(viii) Thales Service Bulletin C16291A-34-007, Revision 01, dated December 03, 2009.

(4) The following service information was approved for IBR on November 6, 2013, Amendment 39-17591 (78 FR 60667, October 2, 2013).

(i) Airbus Mandatory Service Bulletin A320-34-1564, including Appendix 01, dated January 25, 2013.

(ii) Reserved.

(5) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 2, 2017.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.



2017-16-13 Bombardier, Inc.: Amendment 39-18990; Docket No. FAA-2017-0477; Product Identifier 2016-NM-112-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants) airplanes, certificated in any category, serial numbers 5702 through 5705 inclusive, 5707, 5709, 5710, 5712, 5714, 5715, 5718, 5719, 5722, 5723, 5725, 5727, 5728, 5731 through 5733 inclusive, 5735, 5736, 5740, 5742, 5743, 5745, 5746, 5748 through 5750 inclusive, 5752 through 5754 inclusive, 5756 through 5758 inclusive, 5760 through 5762 inclusive, 5764 through 5766 inclusive, 5768 through 5770 inclusive, 5772 through 5774 inclusive, 5776 through 5780 inclusive, 5782 through 5787 inclusive, 5790, 5791, 5793, 5794, 5796, 5797, 5799, 5800, 5802, 5803, 5805 through 5814 inclusive, 5816, 5818 through 5820 inclusive, 5823 through 5829 inclusive, 5831 through 5853 inclusive, 5856, 5857, 5859 through 5863 inclusive, 5865 through 5874 inclusive, 5876 through 5881 inclusive, 5883 through 5888 inclusive, 5890 through 5894 inclusive, 5896 through 5898 inclusive, 5900 through 5906 inclusive, 5908 through 5911 inclusive, 5913 through 5938 inclusive, 5940 through 5947 inclusive, 5949 through 5980 inclusive, 5982 through 5985 inclusive, 5987, and 5988.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by a report indicating that the lanyard length of the passenger drop down oxygen masks is too long. The length of the oxygen mask lanyard might cause the safety pin tethered to the opposite end of the lanyard to remain engaged in the oxygen flow mechanism when the mask is pulled to the passenger's face. We are issuing this AD to prevent improper oxygen flow functionality to the passenger oxygen masks in the event of an emergency.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement of Oxygen Mask Lanyards

Within 2,400 flight hours or 60 months, whichever occurs first after the effective date of this AD, replace the existing lanyards in the passenger oxygen box assemblies with lanyards of the correct length, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 605-35-003, Revision 02, dated April 18, 2016.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 605-35-003, dated January 28, 2016; or Bombardier Service Bulletin 605-35-003, Revision 01, dated February 10, 2016.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2016-15, dated May 18, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0477.

(2) For more information about this AD, contact Cesar A. Gomez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 605-35-003, Revision 02, dated April 18, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 4, 2017.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.



2017-17-02 Bombardier, Inc.: Amendment 39-18992; Docket No. FAA-2016-9575; Product Identifier 2016-NM-168-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

This AD replaces AD 2014-20-09, Amendment 39-17982 (79 FR 59630, October 3, 2014) (“AD 2014-20-09”).

(c) Applicability

This AD applies to Bombardier, Inc., Model DHC-8-400, -401, and -402 airplanes, certificated in any category, serial numbers 4035 through 4347 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Reason

This AD was prompted by reports of missing clamps that are required to provide positive separation between the alternating current (AC) feeder cables and the hydraulic line of the landing gear alternate extension. We are issuing this AD to detect and correct chafing of the AC feeder cable. A chafed and arcing AC feeder cable could puncture the adjacent hydraulic line, which, in combination with the use of the alternate extension, could result in an in-flight fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Clamp Inspection, Related Investigative Actions, and Corrective Actions, With Revised Service Information Having a Reduced Effectivity

This paragraph restates the requirements of paragraph (g) of AD 2014-20-09, with revised service information having a reduced Effectivity. Within 6,000 flight hours or 36 months after November 7, 2014 (the effective date of AD 2014-20-09), whichever occurs earlier: Do a general visual inspection for correctly installed clamps between the AC feeder cables and hydraulic line, and do all applicable related investigative and corrective actions, in accordance with paragraph 3.B., “Procedure,” of the Accomplishment Instructions of Bombardier Service Bulletin 84-24-53, Revision B, dated September 10, 2015. Do all applicable related investigative and corrective actions before further flight.

(h) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before November 7, 2014 (the effective date of AD 2014-20-09), using Bombardier Service Bulletin 84-24-53, dated May 11, 2012. This service bulletin is not incorporated by reference in this AD.

(2) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD, using Bombardier Service Bulletin 84-24-53, Revision A, dated May 16, 2013. This service bulletin was incorporated by reference in AD 2014-20-09.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2013-16R1, effective July 26, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9575.

(2) For more information about this AD, contact Assata Dessaline, Aerospace Engineer, Avionics and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7301; fax 516-794-5531.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 84-24-53, Revision B, dated September 10, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 7, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-04 The Boeing Company: Amendment 39-18994; Docket No. FAA-2017-0335; Product Identifier 2017-NM-025-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/312bc296830a925c86257c85006d1b1f/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/312bc296830a925c86257c85006d1b1f/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 57; Wings.

(e) Unsafe Condition

This AD was prompted by a report of cracks in the upper aft skin of the right wing at certain fastener holes along the rear spar upper chord. We are issuing this AD to detect and correct cracks in the upper aft skin of the wings, which could result in the inability of a principle structural element to sustain limit load, and consequent reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Group 2 Airplanes: Detailed Inspections and Repair

For Group 2 airplanes identified in Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017: At the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017, except as required by paragraph (i) of this AD, do a detailed inspection for cracking of the upper aft skin of the wings from wing buttock line (WBL) 80 to WBL 155, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017. If any cracking is found, repair before further flight in

accordance with the procedures specified in paragraph (j) of this AD. Although Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017, specifies to contact Boeing for repair instructions, and specifies that action as “RC” (Required for Compliance), this AD requires repair as specified in this paragraph. Repeat the inspection thereafter at the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017.

(h) Group 1 Airplanes: Inspection and Corrective Action

For Group 1 airplanes identified in Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017: Within 120 days after the effective date of this AD, inspect for cracking of the upper aft skin of the wings, and do all applicable corrective actions, using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Exception to the Service Information

Where Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017, specifies a compliance time “after the original issue date of this Service Bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (g) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Payman Soltani, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5313; fax: 562-627-5210; email: payman.soltani@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-57A1332, dated January 3, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 8, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-05 Airbus: Amendment 39-18995; Docket No. FAA-2017-0520; Product Identifier 2016-NM-143-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

This AD affects AD 2007-26-14, Amendment 39-15316 (73 FR 2803, January 16, 2008) (“AD 2007-26-14”).

(c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1) through (c)(5) of this AD, certificated in any category, except airplanes that have been repaired as specified in Airbus Service Bulletin A300-53-0370; or Airbus Service Bulletin A300-53-6144, as applicable.

- (1) Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.
- (2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.
- (3) Model A300 B4-605R and B4-622R airplanes.
- (4) Model A300 F4-605R and F4-622R airplanes.
- (5) Model A300 C4-605R Variant F airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of cracks initiating at the upper radius of frame (FR) 47 and a determination that the current inspection procedure is not reliable in detecting certain cracking of the forward fitting of FR 47. We are issuing this AD to detect and correct fatigue cracking of the FR 47 forward fitting upper radius on the left-hand and right-hand sides of the fuselage, which could propagate and result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Except as required by paragraph (h) of this AD: Before exceeding 10,000 flight cycles since first flight of the airplane or within 30 days after the effective date of this AD, whichever occurs later, do a special detailed inspection (SDI) for cracking of the FR 47 forward fitting upper radius on the left-hand and right-hand sides of the fuselage, in accordance with the Accomplishment Instructions of the

applicable Airbus service information specified in paragraphs (g)(1) and (g)(2) of this AD. Repeat the inspection thereafter at intervals not to exceed 4,150 flight cycles, except as required by paragraph (j) of this AD.

(1) Airbus Service Bulletin A300-53-0246, Revision 08, including Appendix 1, dated April 13, 2016.

(2) Airbus Service Bulletin A300-53-6029, Revision 12, including Appendix 1, dated April 13, 2016.

(h) Initial Inspection for Airplanes Previously Inspected

For airplanes previously inspected as specified in the applicable Airbus service information specified in paragraphs (h)(1) through (h)(6) of this AD and on which no cracking was found: Within 4,150 flight cycles after the most recent inspection, do the inspection for cracking of the FR 47 forward fitting upper radius required by paragraph (g) of this AD.

(1) Airbus Service Bulletin A300-53-0246, Revision 06, dated October 19, 2005.

(2) Airbus Service Bulletin A300-53-0246, Revision 07, dated September 9, 2008.

(3) Airbus Service Bulletin A300-53-6029, Revision 08, dated October 19, 2005.

(4) Airbus Service Bulletin A300-53-6029, Revision 09, dated September 9, 2008.

(5) Airbus Service Bulletin A300-53-6029, Revision 10, dated July 9, 2009.

(6) Airbus Service Bulletin A300-53-6029, Revision 11, dated September 28, 2009.

(i) Inspections for Airplanes With Abnormal Load Events

For airplanes on which any crack was found during any inspection done as specified in Airbus Service Bulletin A300-53-0246 or Airbus Service Bulletin A300-53-6029, as applicable, and on which any abnormal load event, such as hard landing or flight in excessive turbulence, occurred within 3 months before the effective date of this AD or occurs on or after the effective date of this AD: Within 3 months after each event, accomplish an SDI for cracking of the FR 47 forward fitting upper radius, left-hand and right-hand sides of the fuselage, in accordance with the applicable Accomplishment Instructions of the Airbus service information specified in paragraphs (g)(1) or (g)(2) of this AD. If, during this 3-month period, another abnormal load event occurs, and if no SDI has yet been accomplished, before further flight after the second event, obtain corrective action instructions from the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA), and accomplish those instructions accordingly.

(j) Corrective Actions for Airplanes With Cracks

If, during any SDI as required by paragraph (g), (h), or (i) of this AD, any crack is found: Before further flight, do the applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraph (g)(1) or (g)(2) of this AD, and obtain additional corrective action instructions from the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA, and accomplish those instructions accordingly before further flight.

(k) Reporting

Submit a report of the findings (both positive and negative) of each SDI inspection required by paragraphs (g), (h), and (i) of this AD to Airbus Service Bulletin Reporting Online Application on Airbus World (<https://w3.airbus.com/>), at the applicable time specified in paragraph (k)(1) or (k)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(l) Terminating Action for AD 2007-26-14

Accomplishing any inspection required by paragraph (g) or (h) of this AD terminates all requirements of AD 2007-26-14 for the inspected airplane.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (n)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016-0150, dated July 25, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0520.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A300-53-0246, Revision 08, including Appendix 1, dated April 13, 2016.

(ii) Airbus Service Bulletin A300-53-6029, Revision 12, including Appendix 1, dated April 13, 2016.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 8, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-06 The Boeing Company: Amendment 39-18996; Docket No. FAA-2017-0131; Product Identifier 2016-NM-186-AD.

(a) Effective Date

This AD is effective September 25, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-300, -400, and -500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1357, dated August 9, 2016.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53; Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of fatigue cracking found in a certain fuselage frame common to the water tank support intercostal clip located between certain stringers. We are issuing this AD to detect and correct cracking, which could grow in size and result in a severed frame. Multiple adjacent severed frames would result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Before the accumulation of 34,000 total flight cycles or within 6,000 flight cycles after the effective date of this AD, whichever occurs later, do a high frequency eddy current (HFEC) inspection for any cracking in the fuselage frame at station (STA) 947.5 common to the water tank support intercostal clip located between stringers S-24R and S-25R, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1357, dated August 9, 2016.

(1) If no cracking is found, repeat the inspection thereafter at intervals not to exceed 12,000 flight cycles.

(2) If any cracking is found: Before further flight, repair in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1357, dated August 9, 2016.

(h) Terminating Action

Accomplishing the repair in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1357, dated August 9, 2016, terminates the inspection requirements of paragraph (g) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1357, dated August 9, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 8, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-07 Rolls-Royce plc: Amendment 39-18997; Docket No. FAA-2017-0652; Product Identifier 2017-NE-18-AD.

(a) Effective Date

This AD is effective September 12, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Rolls-Royce plc (RR) Trent XWB-75, Trent XWB-79, Trent XWB-79B, and Trent XWB-84 turbofan engines with an engine serial number (S/N) listed in Appendix 1 of RR Alert Non-Modification Service Bulletin (NMSB) Trent XWB 72-AJ738, dated April 11, 2017, and with intermediate-pressure (IP) turbine stage 2 locking plates, part number (P/N) KH12922 or KH16183, installed.

(d) Subject

Joint Aircraft System Component (JASC) 7250, Turbine/Turboprop Engine/Turbine Section.

(e) Reason

This AD was prompted by a report of several IP turbine stage 2 locking plates cracked during module assembly. We are issuing this AD to prevent failure of the IP turbine stage 2 locking plates, uncontained release of the IP turbine stage 2 blades, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Inspect the IP turbine stage 2 locking plates on-wing before exceeding 750 engine flight cycles (FCs) since new, or within 100 engine FCs after the effective date of this AD, whichever occurs later. Use the Accomplishment Instructions, paragraph 3.A., of RR Alert NMSB Trent XWB 72-AJ738, dated April 11, 2017, to do the inspection.

(2) Thereafter, re-inspect the IP turbine stage 2 locking plates at intervals not to exceed 750 engine FCs since the last locking plate inspection. Use the Accomplishment Instructions, paragraph 3.A., of RR Alert NMSB Trent XWB 72-AJ738, dated April 11, 2017, to do the inspection.

(i) If all IP turbine stage 2 locking plates installed on the engine have an S/N beginning with 20452, or are not marked with an S/N, the repetitive inspection required by paragraph (f)(2) of this AD is not required.

(ii) If one or more IP turbine stage 2 locking plates are missing, remove the engine from service within the compliance times specified in the Accomplishment Instructions, paragraph 3.A.(3), of RR Alert NMSB Trent XWB 72-AJ738, dated April 11, 2017.

(3) Inspect the IP turbine stage 2 locking plates during the next engine shop visit (ESV) after the effective date of this AD.

(i) Use the Accomplishment Instructions, paragraph 3.B., of RR Alert NMSB Trent XWB 72-AJ738, dated April 11, 2017, to do this inspection. This in-shop inspection may be substituted for the on-wing inspection required by paragraphs (f)(1) and (2) of this AD.

(ii) If one or more IP turbine stage 2 locking plates are missing, use the acceptance criteria in the Accomplishment Instructions, paragraph 3.B.(3), of RR Alert NMSB Trent XWB 72-AJ738 dated April 11, 2017, to disposition the engine.

(g) Installation Prohibition

After the effective date of this AD, do not install an engine unless the IP turbine stage 2 locking plates were inspected using the Accomplishment Instructions, paragraph 3.A. or 3.B., of RR Alert NMSB Trent XWB 72-AJ738, dated April 11, 2017.

(h) Definition

For the purpose of this AD, an ESV is when the engine is subject to a serviceability check and repair, rebuild, or overhaul.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, FAA, ECO Branch, Compliance and Airworthiness Division, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Robert Green, Aerospace Engineer, FAA, ECO Branch, Compliance and Airworthiness Division, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7754; fax: 781-238-7199; email: robert.green@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2017-0088, dated May 16, 2017, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-0642.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce plc (RR) Alert Non-Modification Service Bulletin Trent XWB 72-AJ738, dated April 11, 2017.

(ii) Reserved.

(3) For RR service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE24 8BJ; phone: 011-44-1332-242424; fax: 011-

44-1332-249936; email: http://www.rolls-royce.com/contact/civil_team.jsp; Internet: <https://customers.rolls-royce.com/public/rollsroycecare>.

(4) You may view this service information at FAA, Engine and Propeller Standards Branch, Policy and Innovation Division, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 16, 2017.

Robert J. Ganley,
Manager, Engine and Propeller Standards Branch,
Aircraft Certification Service.



2017-17-08 Airbus: Amendment 39-18998; Docket No. FAA-2016-7264; Product Identifier 2015-NM-185-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Airbus Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes, manufacturer serial numbers identified in Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016; and/or Airbus Service Bulletin A330-53-3262, including Appendixes 01 and 02, dated June 23, 2015.

(2) Airbus Model A340-541 and -642 airplanes, manufacturer serial numbers 1030, 1040, 1079, 1091, 1102, and 1122.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a quality control review on the final assembly line, which determined that the wrong aluminum alloy was used to manufacture several structural parts. We are issuing this AD to detect and replace structural parts made of an incorrect aluminum alloy. This condition could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One-Time Measurement

Except as provided by paragraph (i) of this AD: Within 6 years after the effective date of this AD, but not exceeding 12 years since the date of issuance of the original certificate of airworthiness or the date of issuance of the original export certificate of airworthiness; do a one-time eddy current conductivity measurement of the cabin and cargo compartment structural parts identified in the "Affected Part Number" column of table 1 to paragraphs (g) and (h) of this AD to determine if an

incorrect aluminum alloy was used, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

(1) For cargo compartment structural parts for Model A330 airplanes: Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016.

(2) For cabin structural parts for Model A330 airplanes: Airbus Service Bulletin A330-53-3262, including Appendixes 01 and 02, dated June 23, 2015; except part number F5377004320300, which is located in the “cabin” area, but must be inspected in accordance with Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016.

(3) For cargo compartment structural parts for Model A340 airplanes: Airbus Service Bulletin A340-53-5072, including Appendixes 01 and 02, dated June 23, 2015.

Table 1 to Paragraphs (g) and (h) of This AD—Parts To Be Inspected/Installed

Affected part No.	Acceptable replacement part No.	Area
F5347126620600	F5347126620000	Cabin.
F5347126621000	F5347126620400	Cabin.
F5377004320300	F5377004320351	Cabin.
F5347170420400	F5347170420400	Cargo.
F5347170420600	F5347170420600	Cargo.
G5367131300000	G5367131300000	Cargo.
G5367173700000	G5367173700000	Cargo.
G5367173800000	G5367173800000	Cargo.

(h) Replacement

If during the inspection required by paragraph (g) of this AD, any affected part having a part number specified in table 1 to paragraphs (g) and (h) of this AD is found to have a measured value greater than that specified in Figure A-GFAAA, Sheet 02, “Inspection Flowchart,” of the applicable service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, except as provided by paragraph (i) of this AD: Within 6 years after the effective date of this AD, but not exceeding 12 years since the date of issuance of the original certificate of airworthiness or the date of issuance of the original export certificate of airworthiness, replace the affected part with an acceptable replacement part having a part number specified in table 1 to paragraphs (g) and (h) of this AD, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g)(1), (g)(2), or (g)(3) of this AD.

(i) Exception to Certain Service Information

Where Figure A-GFAAA, Sheet 02, “Inspection Flowchart,” of the service information identified in paragraphs (g)(2) and (g)(3) of this AD specifies to “do the conductivity (σ) measurement with 60kHz (refer to Appendix 01) $\sigma_{480} = \text{___ MS/m}$,” the correct conductivity measurement is “ $\sigma_{60} = \text{___ MS/m}$.”

(j) Additional Inspection for Certain Airplanes

For Model A330 airplanes on which the inspection and replacement, as applicable, specified in paragraphs (g) and (h) of this AD were done before the effective date of this AD, in accordance with

Airbus Service Bulletin A330-53-3261, dated June 23, 2015: Within 6 years after the effective date of this AD, but not exceeding 12 years since the date of issuance of the original certificate of airworthiness or the date of issuance of the original export certificate of airworthiness, do a one-time eddy current conductivity measurement of structural parts having part number (P/N) G5367131300000, P/N G5367173700000, and P/N G5367173800000, located in fuselage section 15, in accordance with the “Additional Work” section of the Accomplishment Instructions of Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016.

(k) Replacement

If during the inspection required by paragraph (j) of this AD, any affected part having a part number specified in paragraph (j) of this AD is found to have a measured value greater than that specified in Figure A-GFAAA, Sheet 02, “Inspection Flowchart,” of Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016: Within 6 years after the effective date of this AD, but not exceeding 12 years since the date of issuance of the original certificate of airworthiness or the date of issuance of the original export certificate of airworthiness, replace the affected part with an acceptable replacement part having a part number specified in table 1 to paragraphs (g) and (h) of this AD, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017-0021, dated February 8, 2017, for related information. This MCAI may be found in

the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7264.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-53-3261, Revision 01, including Appendixes 01, 02, and 03, dated November 10, 2016.

(ii) Airbus Service Bulletin A330-53-3262, including Appendixes 01 and 02, dated June 23, 2015.

(iii) Airbus Service Bulletin A340-53-5072, including Appendixes 01 and 02, dated June 23, 2015.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 9, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-09 The Boeing Company: Amendment 39-18999; Docket No. FAA-2017-0128; Product Identifier 2016-NM-194-AD.

(a) Effective Date

This AD is effective September 29, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 737-300, -400, and -500 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a manufacturer's review that showed that the fuel tank access door at wing buttock line 191.00 did not have an engineered ground path with the mating wing structure. We are issuing this AD to prevent an ungrounded path that could result in an increased risk of ignition and subsequent fuel tank explosion in the event of a lightning strike.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) New Door Assembly, Electrical Bond Check, and Related Corrective Actions

Within 36 months after the effective date of this AD: Install a new door assembly, do a check of the electrical bond, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 737-57-1320, dated October 7, 2016, except as required by paragraph (i) of this AD. Do all applicable related investigative and corrective actions before further flight.

(h) Revise the Maintenance or Inspection Program

Prior to or concurrently with accomplishment of the actions required by paragraph (g) of this AD, or within 30 days after the effective date of this AD, whichever occurs later: Revise the maintenance or inspection program, as applicable, to incorporate Airworthiness Limitation 28-AWL-30, "Upper Wing Fuel Tank Access Panel–Lightning Protection Electrical Design Features," as

specified in Boeing 737-100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) D6-38278-CMR, dated May 2016.

(i) Service Information Exception

Where Boeing Service Bulletin 737-57-1320, dated October 7, 2016, specifies to contact Boeing for repair instructions, and specifies that action as Required for Compliance (RC), this AD requires repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Serj Harutunian, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5254; fax: 562-627-5210; email: serj.harutunian@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 737-57-1320, dated October 7, 2016.

(ii) Boeing 737-100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs) D6-38278-CMR, dated May 2016.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 9, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-10 ATR-GIE Avions de Transport Régional: Amendment 39-19000; Docket No. FAA-2017-0516; Product Identifier 2016-NM-125-AD.

(a) Effective Date

This AD is effective September 29, 2017.

(b) Affected ADs

This AD replaces AD 2015-23-12, Amendment 39-18329 (80 FR 73096, November 24, 2015) (“AD 2015-23-12”).

(c) Applicability

This AD applies to ATR-GIE Avions de Transport Régional Model ATR42-200, -300, -320, and -500 airplanes; and ATR72-101, -201, -102, -202, -211, -212, and -212A airplanes; certificated in any category; all certified models; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Reason

This AD was prompted by a new occurrence of a cracked main landing gear (MLG) rear hinge pin. We are issuing this AD to detect and correct cracked rear hinge pins, which could lead to MLG structural failure, possibly resulting in collapse of the MLG and consequent injury to the occupants of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Hinge Pin Identification and Replacement for Model ATR72 Airplanes, With Terminating Action

This paragraph restates the requirements of paragraph (g) of AD 2015-23-12, with terminating action. For Model ATR72 airplanes: Within 12 months after December 29, 2015 (the effective date of AD 2015-23-12), inspect for the serial number of the left-hand (LH) and right-hand (RH) MLG rear hinge pins having part number (P/N) D61000. A review of airplane maintenance records is acceptable in lieu of this identification if the part number and serial number of the LH and RH MLG rear hinge pins can be conclusively determined from that review. If a rear hinge pin having P/N D61000 has a serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable: Within 12 months after December 29, 2015, replace the pin with a serviceable part as

identified in paragraph (h) of this AD, in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable. Accomplishment of the actions required by paragraph (l) of this AD terminates the inspection required by this paragraph. Accomplishing the actions required by paragraph (m) or (o) of this AD terminates the actions required by this paragraph.

(h) Retained Definition of Serviceable Hinge Pin for Model ATR72 Airplanes for Paragraph (g) of This AD, With No Changes

This paragraph restates the definition in paragraph (h) of AD 2015-23-12, with no changes. For Model ATR72 airplanes: For purposes of paragraph (g) of this AD, a serviceable MLG rear hinge pin is a pin that is specified in paragraph (h)(1) or (h)(2) of this AD.

(1) A hinge pin that is not identified in Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable.

(2) A hinge pin that has been inspected and reconditioned, in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013; or Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013; as applicable.

(i) Retained MLG Pin Identification and Replacement for Model ATR72 Airplanes, With Terminating Action

This paragraph restates the requirements of paragraph (i) of AD 2015-23-12, with terminating action. For Model ATR72 airplanes: At the earlier of the times specified in paragraphs (i)(1) and (i)(2) of this AD, inspect all LH and RH MLG pins for a part number and serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014; as applicable. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number and serial number of the LH and RH MLG pin can be conclusively determined from that review. If any affected MLG pin is found: At the earlier of the compliance times specified in paragraphs (i)(1) and (i)(2) of this AD, replace the MLG with a serviceable MLG as identified in paragraph (j) of this AD, using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or ATR-GIE Avions de Transport Régional's EASA Design Organization Approval (DOA). Accomplishment of the actions required by paragraph (l) of this AD terminates the inspection for the part number and serial number of the LH and RH MLG rear hinge pins required by this paragraph. Accomplishment of the actions required by paragraph (m) or (o) of this AD terminates the actions required by this paragraph.

(1) No later than the next MLG overhaul scheduled after December 29, 2015 (the effective date of AD 2015-23-12).

(2) Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since installation of the MLG on an airplane since new or since last overhaul, as applicable.

(j) Retained Definition of Serviceable MLG for Model ATR72 Airplanes for Paragraph (i) of This AD, With No Changes

This paragraph restates the definition in paragraph (j) of AD 2015-23-12, with no changes. For Model ATR72 airplanes: For purposes of paragraph (i) of this AD, a serviceable MLG is one that incorporates pins specified in paragraph (j)(1) or (j)(2) of this AD.

(1) Pins that are not identified in Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014; as applicable.

(2) Pins that have been inspected and reconditioned in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014; as applicable.

(k) Retained MLG Pin Identification and Replacement for Model ATR42 Airplanes, With Terminating Action

This paragraph restates the requirements of paragraph (k) of AD 2015-23-12, with terminating action. Accomplishment of the actions required by paragraph (l) of this AD terminates the actions required by paragraph (k)(1) of this AD. Accomplishment of the actions required by paragraph (m) or (o) of this AD terminates the actions required by paragraph (k)(2) of this AD.

(1) For Model ATR42 airplanes: Within the compliance time identified in paragraph (k)(1)(i) or (k)(1)(ii) of this AD, whichever occurs first, inspect for any LH and RH MLG pins having a part number and serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable. A review of airplane maintenance records is acceptable in lieu of this identification if the part number and serial number of the LH and RH MLG pin can be conclusively determined from that review.

(i) No later than the next MLG overhaul scheduled after December 29, 2015 (the effective date of AD 2015-23-12).

(ii) Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since installation of the MLG on an airplane since new or since last overhaul, as applicable.

(2) If the MLG pin having a part number and serial number listed in Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable; is found to be installed during the identification required by paragraph (k)(1) of this AD, within the compliance time identified in paragraph (k)(1) of this AD, replace the MLG with a serviceable MLG, using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or ATR-GIE Avions de Transport Régional's EASA DOA. For the purposes of this paragraph, a serviceable MLG is a part that has pins identified in paragraph (k)(2)(i) or (k)(2)(ii) of this AD.

(i) Pins that are not listed in Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable.

(ii) Pins that have been inspected and reconditioned, in accordance with the Accomplishment Instructions of Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014; or Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014; as applicable.

(l) New Requirement of This AD: Hinge Pin Identification

Within the applicable compliance time specified in, and in accordance with the Accomplishment Instructions of, the applicable Messier-Bugatti-Dowty Service Bulletin specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, as applicable to the airplane model and MLG hinge part number, identify the serial number (S/N) of the LH and RH MLG hinge pins. A review of airplane maintenance records is acceptable in lieu of this identification if the part number and serial number of the LH and RH MLG hinge pins can be conclusively determined from that review. Accomplishment of the actions required by this paragraph terminates the inspections required by paragraphs (g), (i), and (k)(1) of this AD.

Figure 1 to Paragraphs (l) Through (p) of This AD—Model ATR72 Airplanes

MLG hinge part Nos.	Applicable Messier-Bugatti-Dowty service bulletins	Compliance time
D60955, D60968, D60999, D61032, D61061	Messier-Bugatti-Dowty Service Bulletin 631-32-214, Revision 1, dated March 15, 2016, Messier-Bugatti-Dowty Service Bulletin 631-32-219, Revision 1, dated March 15, 2016, or Messier-Bugatti-Dowty Service Bulletin 631-32-233, dated March 15, 2016.	A or B, whichever occurs first: A: Not later than the next scheduled MLG overhaul after the effective date of this AD. B: Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since first installation of a MLG on an airplane since new, or since last overhaul, as applicable.
D61000	Messier-Bugatti-Dowty Service Bulletin 631-32-213, Revision 2, dated March 15, 2016,	Within 12 months after the effective date of this AD.
	Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 3, dated March 15, 2016, or	
	Messier-Bugatti-Dowty Service Bulletin 631-32-232, Revision 1, dated March 15, 2016.	

Figure 2 to Paragraphs (l) Through (p) of This AD—Model ATR42 Airplanes

MLG hinge part Nos.	Airplane model(s)	Applicable Messier-Bugatti-Dowty service bulletins	Compliance time
D62054, D63823, D63825	All	Messier-Bugatti-Dowty Service Bulletin 631-32-215, Revision 1, dated March 15, 2016,	A or B, whichever occurs first: A: Not later than the next scheduled MLG overhaul after the effective date of this AD.
		Messier-Bugatti-Dowty Service Bulletin 631-32-220, Revision 1, dated March 15, 2016, or Messier-Bugatti-Dowty Service Bulletin 631-32-235, dated March 15, 2016.	B: Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since first installation of a MLG on an airplane since new, or since last overhaul, as applicable.
D56800, D56800-1, D56809, D56841, D57261, D57401, D57407, D58807, D62079	ATR42-300	Messier-Bugatti-Dowty Service Bulletin 631-32-215, Revision 1, dated March 15, 2016, Messier-Bugatti-Dowty Service Bulletin 631-32-220, Revision 1, dated March 15, 2016, or Messier-Bugatti-Dowty Service Bulletin 631-32-235, dated March 15, 2016.	A or B, whichever occurs first: A: Not later than the next scheduled MLG overhaul after the effective date of this AD. B: Within 20,000 flight cycles or 9 years, whichever occurs first, accumulated since first installation of a MLG on an airplane since new, or since last overhaul, as applicable.

D62055	All	Messier-Bugatti-Dowty Service Bulletin 631-32-224, dated March 15, 2016,	Within 24 months after the effective date of this AD.
		Messier-Bugatti-Dowty Service Bulletin 631-32-231, dated March 15, 2016, or	
		Messier-Bugatti-Dowty Service Bulletin 631-32-234, dated March 15, 2016.	

(m) New MLG Hinge Pin Replacement

If, during the identification required by paragraph (l) of this AD, an MLG hinge pin with a serial number listed in the applicable Messier-Bugatti-Dowty Service Bulletin is found to be installed: Within the compliance time specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, as applicable to airplane model and MLG hinge pin part number, replace each affected MLG hinge pin with a serviceable MLG hinge pin. The replacement must be done in accordance with the Accomplishment Instructions of the applicable Messier-Bugatti-Dowty Service Bulletin specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, as applicable to the airplane model and MLG hinge part number, except as required by paragraph (o) of this AD. Accomplishment of the actions required by this paragraph terminates the actions required by paragraphs (g) and (i) of this AD. Accomplishment of the actions required by this paragraph terminates the replacement required by paragraph (k)(2) of this AD.

(n) New Definition of Serviceable Hinge Pins for Paragraph (m) of This AD

For the purpose of paragraph (m) of this AD, a serviceable MLG hinge pin is a pin that is specified in paragraph (n)(1) or (n)(2) of this AD.

(1) A hinge pin that does not belong to the identified batch as listed in the applicable Messier-Bugatti-Dowty Service Bulletin specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, as applicable to the airplane model and MLG hinge part number.

(2) A hinge pin that can be identified, through the MLG maintenance records, as having been inspected and reconditioned in accordance with the Accomplishment Instructions of the applicable Messier-Bugatti-Dowty Service Bulletin specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, as applicable to the airplane model and MLG hinge part number.

(o) New MLG Hinge Pin Replacement Procedures

If, during accomplishment of the MLG hinge pin replacement required by paragraph (m) of this AD, the applicable Messier-Bugatti-Dowty Service Bulletin specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, does not specify the MLG hinge pin replacement procedure, do the MLG hinge pin replacement using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or ATR-GIE Avions de Transport Régional's EASA DOA. Do the MLG hinge pin replacement at the applicable compliance time specified in paragraph (m) of this AD. Accomplishment of the actions required by this paragraph terminates the hinge pin replacement required by paragraphs (g), (i), and (k)(2) of this AD.

(p) New Parts Installation Limitation

As of the effective date of this AD, no person may install on any airplane an MLG hinge pin having a part number identified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, and having a serial number defined in the applicable Messier-Bugatti-Dowty Service Bulletin specified in figure 1 to paragraphs (l) through (p) of this AD, or figure 2 to paragraphs (l) through (p) of this AD, as applicable to the airplane model and MLG hinge part number, unless the part can be conclusively identified, through the MLG maintenance records, as having been inspected and reconditioned in accordance with the Accomplishment Instructions of the applicable Messier-Bugatti-Dowty Service Bulletin.

(q) Credit for Previous Actions

(1) This paragraph restates the credit provided in paragraph (l) of AD 2015-23-12, with no changes. This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before December 29, 2015 (the effective date of AD 2105-23-12), using Messier-Bugatti-Dowty Service Bulletin 631-32-216, dated October 30, 2013, which is not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions required by paragraphs (l) and (m) of this AD, if those actions were done before the effective date of this AD using the applicable service information specified in paragraph (q)(2)(i) through (q)(2)(x) of this AD.

(i) Messier-Bugatti-Dowty Service Bulletin 631-32-213, December 16, 2013, which was incorporated by reference on December 29, 2015 (80 FR 73096, November 24, 2015).

(ii) Messier-Bugatti-Dowty Service Bulletin 631-32-213, Revision 1, dated December 8, 2014, which is not incorporated by reference in this AD.

(iii) Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014, which was incorporated by reference on December 29, 2015 (80 FR 73096, November 24, 2015).

(iv) Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014, which was incorporated by reference on December 29, 2015 (80 FR 73096, November 24, 2015).

(v) Messier-Bugatti-Dowty Service Bulletin 631-32-216, dated October 30, 2013, which is not incorporated by reference in this AD.

(vi) Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 201, which was incorporated by reference on December 29, 2015 (80 FR 73096, November 24, 2015).

(vii) Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 2, dated December 8, 2014, which is not incorporated by reference in this AD.

(viii) Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014, which was incorporated by reference on December 29, 2015 (80 FR 73096, November 24, 2015).

(ix) Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014, which was incorporated by reference on December 29, 2015 (80 FR 73096, November 24, 2015).

(x) Messier-Bugatti-Dowty Service Bulletin 631-32-232, dated December 8, 2014, which is not incorporated by reference in this AD.

(r) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Branch, send it to the attention of the person

identified in paragraph (s)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2015-23-12 are approved as AMOCs for the corresponding provisions of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or ATR-GIE Avions de Transport Régional's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(s) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0135, dated July 8, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0516.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (t)(5) and (t)(6) of this AD.

(t) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on September 29, 2017.

(i) Messier-Bugatti-Dowty Service Bulletin 631-32-213, Revision 2, dated March 15, 2016.

(ii) Messier-Bugatti-Dowty Service Bulletin 631-32-214, Revision 1, dated March 15, 2016.

(iii) Messier-Bugatti-Dowty Service Bulletin 631-32-215, Revision 1, dated March 15, 2016.

(iv) Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 3, dated March 15, 2016.

(v) Messier-Bugatti-Dowty Service Bulletin 631-32-219, Revision 1, dated March 15, 2016.

(vi) Messier-Bugatti-Dowty Service Bulletin 631-32-220, Revision 1, dated March 15, 2016.

(vii) Messier-Bugatti-Dowty Service Bulletin 631-32-224, dated March 15, 2016.

(viii) Messier-Bugatti-Dowty Service Bulletin 631-32-231, dated March 15, 2016.

(ix) Messier-Bugatti-Dowty Service Bulletin 631-32-232, Revision 1, dated March 15, 2016.

(x) Messier-Bugatti-Dowty Service Bulletin 631-32-233, dated March 15, 2016.

(xi) Messier-Bugatti-Dowty Service Bulletin 631-32-234, dated March 15, 2016.

(xii) Messier-Bugatti-Dowty Service Bulletin 631-32-235, dated March 15, 2016.

(4) The following service information was approved for IBR on December 29, 2015 (80 FR 73096, November 24, 2015).

(i) Messier-Bugatti-Dowty Service Bulletin 631-32-213, dated December 16, 2013.

(ii) Messier-Bugatti-Dowty Service Bulletin 631-32-214, dated January 13, 2014.

(iii) Messier-Bugatti-Dowty Service Bulletin 631-32-215, dated January 13, 2014.

(iv) Messier-Bugatti-Dowty Service Bulletin 631-32-216, Revision 1, dated December 17, 2013.

Pages 4, 5, and 8 of this service bulletin are the original issue and are dated October 30, 2013.

(v) Messier-Bugatti-Dowty Service Bulletin 631-32-219, dated March 3, 2014.

(vi) Messier-Bugatti-Dowty Service Bulletin 631-32-220, dated March 3, 2014.

(5) For service information identified in this AD, contact ATR-GIE Avions de Transport Régional, 1, Allée Pierre Nadot, 31712 Blagnac Cedex, France; telephone +33 (0) 5 62 21 62 21; fax +33 (0) 5 62 21 67 18; email continued.airworthiness@atr.fr; Internet <http://www.aerochain.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 8, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-11 Dassault Aviation Airplanes: Amendment 39-19001; Docket No. FAA-2017-0496; Product Identifier 2016-NM-103-AD.

(a) Effective Date

This AD is effective September 29, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, all serial numbers, except airplanes modified with Dassault Aviation modification (Mod) M1389.

(d) Subject

Air Transport Association (ATA) of America Code 76, Engine Controls.

(e) Reason

This AD was prompted by a report indicating that, under certain operational takeoff conditions, the available thrust in relation with the N1 indication is less than a certified value, which could affect the safety margins with an engine failure during takeoff. We are issuing this AD to prevent a reduction in available engine thrust during certain operational takeoff conditions, which could affect the safety margins with an engine failure during takeoff and could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification–Software Update

Within 12 months after the effective date of this AD, modify each engine installed on the airplane by updating the electronic engine control (EEC) (installation of software EEC version 307A0514), in accordance with the Accomplishment Instructions of Dassault Service Bulletin 7X-287, also referred to as 287, dated January 4, 2016; and Pratt & Whitney Canada Service Bulletin PW300-72-47216, also referred to as 47216, dated January 13, 2016.

(h) Airplane Flight Manual (AFM) Revision

Concurrently with the modification of an airplane required by paragraph (g) of this AD, revise the applicable AFM of that airplane by inserting a copy of Dassault FALCON 7X AFM DGT105608, Revision 21, dated November 20, 2015 (incorporating AFM CP098).

(i) Modification—N1 Detrim

Prior to or concurrently with the modification of an airplane required by paragraph (g) of this AD, modify each engine installed on the airplane by adjusting the engine N1 trim value, in accordance with the Accomplishment Instructions of Pratt & Whitney Canada Service Bulletin PW300-72-47202, Revision 3, also referred to as 47202R3, dated March 10, 2016.

(j) Replacement Limitation

After modification of an airplane as required by paragraph (g) of this AD, installation of a replacement engine on that airplane is allowed, provided that, prior to installation, it is positively established that the engine embodies software EEC version 307A0514. Modification of a pre-modified engine to embody this software can be accomplished in accordance with the Accomplishment Instructions of Pratt & Whitney Canada Service Bulletin PW300-72-47216, also referred to as 47216, dated January 13, 2016.

(k) Alternative Replacements

Installation of a replacement engine or replacement EEC unit on an airplane after the effective date of this AD, which embodies a later software EEC version, is acceptable for compliance with paragraph (g) of this AD, provided the conditions specified in paragraphs (k)(1) and (k)(2) of this AD are met.

(1) The software EEC version must be approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA).

(2) The installation must be accomplished in accordance with airplane modification instructions approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA DOA.

(l) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (i) of this AD, if those actions were performed before the effective date of this AD using service information in paragraph (l)(1), (l)(2), or (l)(3) of this AD.

(1) Pratt & Whitney Canada Service Bulletin PW300-72-47202, also referred to as 47202, dated June 17, 2014.

(2) Pratt & Whitney Canada Service Bulletin PW300-72-47202, Revision 1, also referred to as 47202R1, dated November 18, 2014.

(3) Pratt & Whitney Canada Service Bulletin PW300-72-47202, Revision 2, also referred to as 47202R2, dated January 5, 2016.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested

using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (n)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0063, dated March 31, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0496.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(4) and (o)(5) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault FALCON 7X Airplane Flight Manual DGT105608, Revision 21, dated November 20, 2015.

(ii) Dassault Service Bulletin 7X-287, also referred to as 287, dated January 4, 2016.

(iii) Pratt & Whitney Canada Service Bulletin PW300-72-47202, Revision 3, also referred to as 47202R3, dated March 10, 2016.

(iv) Pratt & Whitney Canada Service Bulletin PW300-72-47216, also referred to as 47216, dated January 13, 2016.

(3) For Dassault service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(4) For Pratt & Whitney Canada service information identified in this AD, contact Pratt & Whitney Canada Corp., 1000 Marie-Victorin, Longueuil, Quebec, Canada, J4G 1A1; telephone 800-268-8000; fax 450-647-2888; Internet <http://www.pwc.ca>.

(5) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 9, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-12 Airbus: Amendment 39-19002; Docket No. FAA-2017-0472; Product Identifier 2016-NM-148-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A310-203, -221, -222, -304, -322, -324, and -325 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by an evaluation by the design approval holder indicating that the wing bottom skin at the main landing gear (MLG) reinforcing plate is subject to widespread fatigue damage. We are issuing this AD to prevent multi-site damage in the bottom skin at the MLG reinforcing plate, which could result in reduced structural integrity of the wing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within the compliance times defined in table 1 to paragraph (g) of this AD, table 2 to paragraph (g) of this AD, or table 3 to paragraph (g) of this AD, as applicable to airplane type and utilization: Do a modification of the left-hand and right-hand wing bottom skin at the MLG reinforcing plate, including all related investigative actions and applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-57-2104, dated December 15, 2015, except as required by paragraph (h) of this AD. Do all related investigative and applicable corrective actions before further flight. For the purpose of this AD, the term “short range” applies to airplanes with an average flight time (AFT) lower than 1.5 flight hours per flight cycle, and the term “long range” applies to airplanes with an average flight time equal to or higher than 1.5 flight hours per flight cycle. For determining the “short range” and “long range” airplanes, the AFT is the total accumulated flight hours, counted from take-off to touch-down, divided by the total accumulated flight cycles at the effective date of this AD.

Table 1 to Paragraph (g) of This AD—Model A310-200 Series Airplanes**Compliance time (whichever occurs later, A or B)**

A Before exceeding 28,800 flight cycles (FC) or 57,600 flight hours (FH), whichever occurs first since first flight of the airplane.

B Within 960 FC, or 1,920 FH, or 12 months, whichever occurs first after the effective date of this AD.

Table 2 to Paragraph (g) of This AD—Model A310-300 “Short-Range” Airplanes**Compliance time (whichever occurs later, A or B)**

A Before exceeding 27,700 FC or 77,700 FH, whichever occurs first since first flight of the airplane.

B Within 920 FC, or 2,580 FH, or 12 months, whichever occurs first after the effective date of this AD.

Table 3 to Paragraph (g) of This AD—Model A310-300 “Long-Range” Airplanes**Compliance time (whichever occurs later, A or B)**

A Before exceeding 20,500 FC or 102,500 FH, whichever occurs first since first flight of the airplane.

B Within 680 FC, or 3,420 FH, or 12 months, whichever occurs first after the effective date of this AD.

(h) Exception to Service Information Specifications

Where Airbus Service Bulletin A310-57-2104, dated December 15, 2015, specifies to contact Airbus for appropriate action, and specifies that action as “RC” (Required for Compliance): Before further flight, accomplish corrective actions in accordance with the procedures specified in paragraph (i)(2) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as required by paragraph (h) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0170, dated August 19, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0472.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A310-57-2104, dated December 15, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 9, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-13 Bombardier, Inc.: Amendment 39-19003; Docket No. FAA-2017-0481; Product Identifier 2016-NM-196-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD-100-1A10 airplanes, certificated in any category, serial numbers 20003 through 20635 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Reason

This AD was prompted by reports of low clearance in the aft equipment bay between auxiliary power unit (APU) generator power cables and a hydraulic line, which can cause damage to wire insulation. We are issuing this AD to prevent electrical arcing from power cables, which could cause a fire in the aft equipment bay.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of APU Generator Power Cables and Hydraulic Line, Repairs, and Modification

Within 24 months after the effective date of this AD, do the applicable actions required by paragraph (g)(1) or (g)(2) of this AD.

(1) For airplanes having serial numbers 20003 through 20500 inclusive: Do a general visual inspection of the APU generator power cables and the adjacent hydraulic line for damage, and do all applicable repairs; and modify the APU generator power cable installation; in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100-24-28, dated July 27, 2016, except as required by paragraph (h) of this AD. Do all applicable repairs before further flight.

(2) For airplanes having serial numbers 20501 through 20635 inclusive: Do a general visual inspection of the APU generator power cables and the adjacent hydraulic line for damage, and do all applicable repairs; and modify the APU generator power cable installation; in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 350-24-003, dated July 27, 2016, except as required by paragraph (h) of this AD. Do all applicable repairs before further flight.

(h) Exception to the Service Information

Where Bombardier Service Bulletin 100-24-28, dated July 27, 2016; and Bombardier Service Bulletin 350-24-003, dated July 27, 2016, specify to contact the manufacturer for repair, before further flight, repair using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO).

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2016-28, dated September 15, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0481.

(2) For more information about this AD, contact Assata Dessaline, Aerospace Engineer, Avionics and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7301; fax 516-794-5531.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 100-24-28, dated July 27, 2016.

(ii) Bombardier Service Bulletin 350-24-003, dated July 27, 2016.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 9, 2017.
Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-14 Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems):
Amendment 39-19004; Docket No. FAA-2017-0479; Product Identifier 2016-NM-202-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes, certificated in any category, serial numbers 004 through 138 inclusive; except those on which Saab Service Bulletin 340-33-053 (modification/removal for cargo/freighter configuration) has been embodied.

(d) Subject

Air Transport Association (ATA) of America Code 33, Lights.

(e) Reason

This AD was prompted by the discovery of circuit breakers of unsuitable strength that fail to protect the system from an overcurrent. We are issuing this AD to prevent such conditions, which could lead to overheating of the wires and possibly result in smoke or fire in the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 6 months after the effective date of this AD: Replace any circuit breaker having part number (P/N) MS3320-10 installed at position 2LJ (L25) and position 4LJ (L26) with a circuit breaker having P/N MS3320-7-5, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-33-058, Revision 01, dated October 21, 2016.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install a circuit breaker having P/N MS3320-10 on any passenger reading light system at position 2LJ (L25) or position 4LJ (L26), on any airplane.

(i) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Saab Service Bulletin 340-33-058, dated May 30, 2016.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0234, dated November 24, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0479.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Saab Service Bulletin 340-33-058, Revision 01, dated October 21, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab340techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 9, 2017.
Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-15 Bombardier, Inc.: Amendment 39-19005; Docket No. FAA-2017-0512; Product Identifier 2017-NM-031-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model CL-600-2E25 (Regional Jet Series 1000) airplanes, certificated in any category, serial numbers 19001 through 19039 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by failures of the landing gear alternate-extension system (AES). We are issuing this AD to prevent failure of the landing gear AES and consequent landing with some or all of the landing gear not extended.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 1,200 flight hours or 12 months after the effective date of this AD, whichever occurs first: Replace the nose landing gear (NLG) and main landing gear (MLG) electro-mechanical actuators (EMAs) having part numbers (P/Ns) BA698-85006-1 and BA698-85007-1 with P/Ns BA698-85006-3 and BA698-85007-3, as applicable, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-32-047, Revision A, dated December 5, 2016 ("670BA-32-047, Revision A"). Where 670BA-32-047, Revision A, instructs operators to contact Bombardier if it is not possible to complete all the instructions in 670BA-32-047, Revision A, because of the configuration of the airplane, this AD requires that any deviation from the instructions provided in 670BA-32-047, Revision A, must be approved as an alternative method of compliance (AMOC) under the provisions of paragraph (j)(1) of this AD.

(h) Parts Installation Prohibition

As of the effective date of this AD, no person may install an NLG or MLG EMA having P/N BA698-85006-1 or BA698-85007-1, on any airplane.

(i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 670BA-32-047, dated February 28, 2014.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2017-08, dated February 22, 2017, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0512.

(2) For more information about this AD, contact Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7318; fax: 516-794-5531.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 670BA-32-047, Revision A, dated December 5, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-

free telephone 1-866-538-1247 or direct-dial telephone: 1-514-855-2999; fax: 514-855-7401; email: ac.yul@aero.bombardier.com; Internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 10, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-16 The Boeing Company: Amendment 39-19006; Docket No. FAA-2017-0337; Product Identifier 2017-NM-006-AD.

(a) Effective Date

This AD is effective October 2, 2017.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017.

(2) Installation of Supplemental Type Certificate (STC) ST01920SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01920SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53; Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of cracking in the vertical stiffener in the nose wheel well. We are issuing this AD to detect and correct such cracking, which could adversely affect the structural integrity of the airplane and possibly lead to cabin depressurization or a nose landing gear collapse.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections

At the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017, except as specified in paragraph (h)(1) of this AD: Do a detailed inspection and a medium frequency eddy current inspection of the nose wheel well bulkhead stiffener for any cracking, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017; except as specified in paragraph (h)(2) of this AD. Do all corrective actions before further flight.

Repeat the inspections thereafter at the times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017.

(h) Exceptions to the Service Information

(1) Where Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) If any cracking is found and Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017, specifies to contact Boeing for appropriate action and specifies that action as “RC” (Required for Compliance): Before further flight repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6447; fax: 425-917-6590; email: wayne.lockett@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 767-53A0275, dated January 5, 2017.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 11, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-17-18 General Electric Company: Amendment 39-19008; Docket No. FAA-2017-0164; Product Identifier 2017-NE-06-AD.

(a) Effective Date

This AD is effective October 6, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5B1, CF34-8C5A2, CF34-8C5A3, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6 and CF34-8E6A1 engines, including engines marked on the engine data plate as CF34-8C5B1/B, CF34-8C5/B, CF34-8C5A1/B, CF34-8C5A2/B, CF34-8C5/M, CF34-8C5A1/M, CF34-8C5A2/M, CF34-8C5A3/B, or CF34-8C5B1/M, with a fan blade, part number (P/N) 4114T15P02 or P/N 4114T31G01, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by analysis that resulted in the reduction of the life of the affected fan blades. We are issuing this AD to prevent failure of the fan blade, uncontained blade release, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Eddy Current Inspections (ECIs)

(1) For CF34-8C1, CF34-8C5B1, CF34-8C5B1/B and CF34-8E2 engines with fan blade, P/N 4114T15P02, installed:

(i) Perform an initial ECI of the fan blade pinhole prior to the fan blade accumulating 25,000 cycles-since-new (CSN); and

(ii) Repeat this inspection within every 3,000 cycles thereafter.

(2) For CF34-8C5, CF34-8C5/B, CF34-8C5A1, CF34-8C5A1/B, CF34-8C5A2, CF34-8C5A2/B, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E6 and CF34-8E6A1 engines with fan blade, P/N 4114T15P02, installed:

(i) Perform an initial ECI of the fan blade pinhole prior to the fan blade accumulating 19,500 CSN; and

(ii) Repeat this inspection within every 3,000 cycles thereafter, until the fan blade has accumulated 25,000 CSN, then repeat the inspection every 1,500 cycles thereafter.

(3) For CF34-8C5/M, CF34-8C5A1/M, CF34-8C5A2/M, CF34-8C5A3, CF34-8C5A3/B, CF34-8C5B1/M, and CF34-8E5A2 engines with fan blade, P/N 4114T15P02, installed:

(i) Perform an initial ECI of the fan blade pinhole prior to the fan blade accumulating 19,000 CSN; and

(ii) Repeat this inspection within every 3,000 cycles thereafter, until the fan blade has accumulated 25,000 CSN, then repeat the inspection every 1,500 cycles thereafter.

(4) For any affected engine with a fan blade, P/N 4114T15P02, installed, where the CSN of the fan blade is unknown on the effective date of this AD:

(i) Assume the blade has accumulated 25,000 CSN on the effective date of this AD; and

(ii) Inspect the blade prior to installation or within 500 cycles after the effective date of this AD, whichever is earlier.

(iii) Repeat this inspection based on the intervals of the new engine installation, as specified in paragraph (g) of this AD.

(5) If a fan blade is moved from one affected engine model to another affected model after the initial ECI:

(i) Perform an additional ECI of the blade prior to installation in the new model; and

(ii) Repeat this inspection based on the intervals of the new engine installation, as specified in paragraph (g) of this AD.

(6) If a fan blade, P/N 4114T15P02, has been used on more than one engine model prior to the initial ECI, use Appendix A of GE Alert Service Bulletin (ASB) CF34-8C SB 72-A0137, R05, dated June 15, 2016, or Appendix A of GE ASB CF34-8E SB 72-A0060, R05, dated June 15, 2016, to calculate the new cycle limit for the initial inspection of that fan blade.

(7) Guidance on performing the ECI can be found in GE Service Bulletins GE ASB CF34-8C SB 72-A0137, R05, dated June 15, 2016, or GE ASB CF34-8E SB 72-A0060, R05, dated June 15, 2016.

(h) Fan Blade Removal

(1) For any affected engine with a fan blade, P/N 4114T15P02, installed, remove the blade from service or repair to P/N 4114T31G01 prior to the blade accumulating 41,000 CSN.

(2) For any affected engine with a fan blade, P/N 4114T31G01, installed, remove the blade from service prior to the blade accumulating 28,000 cycles since installation of the pinhole bushing.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, FAA, ECO Branch, Compliance and Airworthiness Division, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (i)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact John Frost, Aerospace Engineer, FAA, ECO Branch, Compliance and Airworthiness Division, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7756; fax: 781-238-7199; email: john.frost@faa.gov.

(2) GE ASB CF34-8E SB 72-A0115, R04, dated December 9, 2016, and GE ASB CF34-8C SB 72-A0225, R03, dated December 9, 2016, can be obtained from GE using the contact information in paragraph (k)(3) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) General Electric Company (GE) Alert Service Bulletin (ASB) CF34-8C SB 72-A0137, Revision 5 (R05), dated June 15, 2016.

(ii) GE ASB CF34-8E SB 72-A0060, Revision 5 (R05), dated June 15, 2016.

(3) For General Electric Company service information identified in this AD, contact General Electric Company, GE-Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215, phone: 513-552-3272; fax: 513-552-3329; email: geae.aoc@ge.com.

(4) You may view this service information at FAA, Engine and Propeller Standards Branch, Policy and Innovation Division, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 29, 2017.

Robert J. Ganley,
Manager, Engine and Propeller Standards Branch,
Aircraft Certification Service.



2017-17-19 The Boeing Company: Amendment 39-19009; Docket No. FAA-2017-0503; Product Identifier 2017-NM-032-AD.

(a) Effective Date

This AD is effective October 4, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes, and Model MD-88 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53; Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracking of various structures at the cant station 1463 bulkhead and at the cant station 1254 bulkhead. We are issuing this AD to detect and correct cracking at the cant station 1463 bulkhead and cant station 1254 bulkhead, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Action

Within 700 flight cycles or 6 months after the effective date of this AD, whichever occurs first, do a detailed inspection for cracking on the left and right sides of the forward and aft surfaces of the cant station 1463 bulkhead (for Model DC-9-81 (MD-81), DC-9-82 (MD-82), and DC-9-83 (MD-83) airplanes, and Model MD-88 airplanes) and cant station 1254 bulkhead (for Model DC-9-87 (MD-87) airplanes); and do all applicable corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-53A316, dated December 15, 2016, except as required in paragraph (h) of this AD. Do all applicable corrective actions before further flight.

(h) Exception to Service Information

Where Boeing Alert Service Bulletin MD80-53A316, dated December 15, 2016, specifies to contact Boeing for appropriate action and specifies that action as “RC” (Required for Compliance): Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Multi Operator Message MOM-MOM-16-0684-01B, dated October 7, 2016.

(j) Special Flight Permit

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), may be issued to operate the airplane to a location where the requirements of this AD can be accomplished, but concurrence by the Manager, Los Angeles ACO Branch, FAA, is required before issuance of the special flight permit.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email: george.garrido@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD80-53A316, dated December 15, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 17, 2017.

Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.



2017-18-05 The Boeing Company: Amendment 39-19014; Docket No. FAA-2017-0559; Product Identifier 2017-NM-013-AD.

(a) Effective Date

This AD is effective October 5, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of damage found at the lower trailing edge panels of the left wing and a broken fuse pin of the landing gear beam end fitting. We are issuing this AD to detect and correct cracking in the fuse pin of the wing landing gear beam end fitting. A broken fuse pin will not support the wing landing gear beam, causing damage to the surrounding structure, including flight control cables and hydraulic systems, which could result in loss of controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Actions Required for Compliance

Except as required by paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-57A2360, dated January 20, 2017, do all applicable actions identified as required for compliance ("RC") in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2360, dated January 20, 2017.

(h) Exception to the Service Information

Where Boeing Alert Service Bulletin 747-57A2360, dated January 20, 2017, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: bill.ashforth@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-57A2360, dated January 20, 2017.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 21, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-18-06 The Boeing Company: Amendment 39-19015; Docket No. FAA-2017-0247; Product Identifier 2016-NM-180-AD.

(a) Effective Date

This AD is effective October 5, 2017.

(b) Affected ADs

This AD replaces AD 2012-05-03, Amendment 39-16975 (77 FR 16143, March 20, 2012) (“AD 2012-05-03”).

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 747-57-2332, Revision 2, dated February 22, 2016.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a design review following a ground fire incident and reports of flammable fluid leaks from the wing leading edge area onto the engine exhaust area. We are issuing this AD to prevent flammable fluid from leaking onto the engine exhaust nozzle, which could result in a fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Leading Edge Installation, With Revised Service Information

This paragraph restates the requirements of paragraph (g) of AD 2012-05-03, with revised service information. Within 60 months after April 24, 2012 (the effective date of AD 2012-05-03), modify the fluid drain path in the leading edge area of the wing, in accordance with all applicable parts of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-57-2332, Revision 1, dated July 25, 2011; or Revision 2, dated February 22, 2016.

(h) Retained Credit for Previous Actions, With No Changes

This paragraph restates the provisions of paragraph (h) of AD 2012-05-03, with no changes. This paragraph provides credit for modification of the fluid drain path required by paragraph (g) of this AD, if the modification was performed before April 24, 2012, using Boeing Special Attention Service Bulletin 747-57-2332, dated November 9, 2010.

(i) New Requirement to Seal Drainage Holes

For airplanes on which the actions specified in Boeing Special Attention Service Bulletin 747-57-2332, dated November 9, 2010; or Revision 1, dated July 25, 2011; were done: Within 2 years after the effective date of this AD, fill the drainage holes in wing panels 521EB and 621EB with sealant, in accordance with Part 5 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-57-2332, Revision 2, dated February 22, 2016.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2012-05-03 are approved as AMOCs for the corresponding provisions of paragraph (g) of this AD.

(k) Related Information

(1) For more information about this AD, contact Tung Tran, Aerospace Engineer, Propulsion, Seattle ACO Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6505; fax: 425-917-6590; email: Tung.Tran@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(5) and (l)(6) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on October 5, 2017.

(i) Boeing Special Attention Service Bulletin 747-57-2332, Revision 2, dated February 22, 2016.

(ii) Reserved.

(4) The following service information was approved for IBR on April 24, 2012 (77 FR 16143, March 20, 2012).

(i) Boeing Special Attention Service Bulletin 747-57-2332, Revision 1, dated July 25, 2011.

(ii) Reserved.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 21, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-18-07 Dassault Aviation: Amendment 39-19016; Docket No. FAA-2017-0502; Product Identifier 2016-NM-120-AD.

(a) Effective Date

This AD is effective October 5, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, manufacturer serial numbers 15 through 89 inclusive, 92 through 94 inclusive, 97 through 101 inclusive, 105, and 106.

(d) Subject

Air Transport Association (ATA) of America Code 51, Standard practices/structures.

(e) Reason

This AD was prompted by a discovery of noncompliant rivets in the flight deck upper skin. We are issuing this AD to prevent interference between the rivet shank and the flight deck mounted overhead panel when the flight deck upper skin deforms due to impact (e.g., bird strike), which could affect the functioning of essential flight control systems and result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Before exceeding 99 months or 4,100 flight cycles, whichever occurs first, since the date of issuance of the original certificate of airworthiness or the date of issuance of the original export certificate of airworthiness, modify the airplane by replacing certain MGPL-type rivets installed on the flight deck skin panel with solid type-rivets, in accordance with the Accomplishment Instructions of Dassault Service Bulletin 7X-176, dated February 3, 2016.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested

using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (i)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2016-0124, dated June 22, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0502.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Service Bulletin 7X-176, dated February 3, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 21, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2017-18-08 Dassault Aviation: Amendment 39-19017; Docket No. FAA-2017-0475; Product Identifier 2016-NM-142-AD.

(a) Effective Date

This AD is effective October 5, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 2000 and FALCON 2000EX airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 30, Ice and Rain Protection.

(e) Reason

This AD was prompted by reports of ice accretion on the airplane wing due to the failure of certain anti-ice piccolo tubes in the wing outboard slats. We are issuing this AD to detect and correct manufacturing defects in the anti-ice piccolo tubes in the wing outboard slats. This condition could lead to undetected significant ice accretion on a wing, resulting in loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Affected Anti-ice Piccolo Tubes

(1) For the purpose of this AD, an affected anti-ice piccolo tube meets at least one of the conditions specified in paragraphs (g)(1)(i) and (g)(1)(ii) of this AD.

(i) Has part number (P/N) FGFB725102 (left-hand side (LH)) or P/N FGFB726102 (right-hand side (RH)).

(ii) Is installed on a wing outboard slat having a part number identified in table 1 to paragraph (g)(1)(ii) of this AD.

Table 1 to Paragraph (g)(1)(ii) of This AD–Affected Outboard Slats Part Numbers

LH	RH
FGFB134	FGFB144.
FGFB134A1 to FGFB134A9 inclusive	FGFB144A1 to FGFB144A9 inclusive.
FGFB134B1	FGFB144B1.
FFGFB134C1 to FGFB134C4 inclusive	FGFB144C1 to FGFB144C4 inclusive.
From FGFB134D1 to FGFB134D4 inclusive	FGFB144D1 to FGFB144D4 inclusive.
FGFB135 and FGFB135M	FGFB145 and FGFB145M.
FGFB135A1 to FGFB135A4 inclusive	FGFB145A1 to FGFB145A4 inclusive.
From FGFB135A1M to FGFB135A4M inclusive	FGFB145A1M to FGFB145A4M inclusive.
From FGFB135B1 to FGFB135B3 inclusive	FGFB145B1 to FGFB145B3 inclusive.
FGFB135B1M to FGFB135B3M inclusive	FGFB145B1M to FGFB145B3M inclusive.
F2MB135	F2MB145.
F2MB135A1	F2MB145A1.
F2MB135L1 to F2MB135L5 inclusive	F2MB145L1 to F2MB145L5 inclusive.

(2) If the outboard slat part number is identified in table 2 to paragraph (g)(2) of this AD, the anti-ice piccolo tube is not affected because the outboard slat has already been retrofitted with a new stiffened anti-ice piccolo tube, and no action is required by this AD for that piccolo tube.

Table 2 to Paragraph (g)(2) of This AD–Serviceable Outboard Slats Part Numbers

LH	RH
FGFB134P	FGFB144P.
FGFB134A1P through FGFB134A9P inclusive	FGFB144A1P through FGFB144A9P inclusive.
FGFB134B1P	FGFB144B1P.
FFGFB134C1P to FGFB134C4P inclusive	FGFB144C1P to FGFB144C4P inclusive.
From FGFB134D1P to FGFB134D4P inclusive	FGFB144D1P to FGFB144D4P inclusive.
FGFB135P and FGFB135MP	FGFB145P and FGFB145MP.
FGFB135A1P to FGFB135A4P inclusive	FGFB145A1P to FGFB145A4P inclusive.
From FGFB135A1MP to FGFB135A4MP inclusive	FGFB145A1MP to FGFB145A4MP inclusive.
From FGFB135B1P to FGFB135B3P inclusive	FGFB145B1P to FGFB145B3P inclusive.
FGFB135B1MP to FGFB135B3MP inclusive	FGFB145B1MP to FGFB145B3MP inclusive.
F2MB135P	F2MB145P.
F2MB135A1P	F2MB145A1P.
F2MB135L1P to F2MB135L5P inclusive	F2MB145L1P to F2MB145L5P inclusive.
F2MB135L6 to F2MB135L7 inclusive	F2MB145L6 to F2MB145L7 inclusive.

(h) Inspections

If an anti-ice piccolo tube has been determined to be affected, as specified in paragraph (g) of this AD: At the applicable time specified in table 3 to paragraph (h) of this AD, do an endoscopic inspection for discrepancies, i.e., manufacturing defects, cracking, and loss of material in the welded parts of each affected anti-ice piccolo tube, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F2000-431, Revision 1, dated June 6, 2016; or Service Bulletin F2000EX-391, Revision 1, dated June 6, 2016; as applicable. Repeat the endoscopic inspection thereafter at intervals not to exceed those specified in table 3 to paragraph (h) of this AD, until the modification specified in paragraph (k) of this AD is done.

Table 3 to Paragraph (h) of this AD—Compliance Times for Inspections

Airplane model	Initial inspection	Repetitive inspection intervals
FALCON 2000 airplanes	Prior to exceeding 2,000 flight cycles since the airplane's first flight, or within 1,000 flight cycles after the effective date of this AD, whichever occurs later	2,000 flight cycles.
FALCON 2000EX airplanes	Prior to exceeding 1,000 flight cycles since the airplane's first flight, or within 500 flight cycles after the effective date of this AD, whichever occurs later	1,000 flight cycles.

(i) Corrective Action

If any discrepancy is found during any inspection required by paragraph (h) of this AD: Before further flight, replace the affected anti-ice piccolo tube with a new or serviceable part, and replace or re-identify the affected wing outboard slat as applicable, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F2000-431, Revision 1, dated June 6, 2016; or Service Bulletin F2000EX-391, Revision 1, dated June 6, 2016; as applicable.

(j) Reporting Provisions

Although Dassault Service Bulletin F2000-431, Revision 1, dated June 6, 2016; and Service Bulletin F2000EX-391, Revision 1, dated June 6, 2016; specify to submit a report of crack findings to Dassault, this AD does not require a report.

(k) Optional Terminating Action

Modification of an airplane by installing a new or serviceable anti-ice piccolo tube, and replacing or re-identifying the affected wing outboard slat, terminates the repetitive inspections required by paragraph (h) of this AD, if done in accordance with the Accomplishment Instructions of Dassault Service Bulletin F2000-431, Revision 1, dated June 6, 2016; or Service Bulletin F2000EX-391, Revision 1, dated June 6, 2016; as applicable.

(l) Parts Installation Prohibition

As of the time specified in paragraph (l)(1) or (l)(2) of this AD, as applicable, no person may install on any airplane an affected anti-ice piccolo tube or an affected outboard slat.

(1) For an airplane that, on the effective date of this AD, has an affected anti-ice piccolo tube or an affected outboard slat installed: After modification of that airplane as required by paragraph (i) of this AD.

(2) For an airplane that, on the effective date of this AD, does not have an affected anti-ice piccolo tube or an affected outboard slat installed: As of the effective date of this AD.

(m) Later-Approved Parts

Installation on an airplane of an anti-ice piccolo tube having a part number approved after the effective date of this AD is acceptable for compliance with the requirements of paragraph (i) or paragraph (k) of this AD, as applicable, provided the conditions in paragraphs (m)(1) and (m)(2) of this AD are met.

(1) The anti-ice piccolo tube part number must be approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA).

(2) The installation of the anti-ice piccolo tube must be accomplished in accordance with a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or Dassault Aviation's EASA DOA.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016-0149, dated July 25, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0475.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Service Bulletin F2000-431, Revision 1, dated June 6, 2016.

(ii) Dassault Service Bulletin F2000EX-391, Revision 1, dated June 6, 2016.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 21, 2017.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service