

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2017-05

2/20/2017 - 3/5/2017



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes; R - Replaces			
Biweekly 2017-01			
2016-24-51		Sikorsky Aircraft Corporation	S-92A
2016-25-13	S 2016-04-12	Safran Helicopter Engines, S.A.	Arriel 2B, 2B1, 2C, 2C1, 2C2, 2D, 2E, 2S1, and 2S2
2016-25-14		Airbus Helicopters Deutschland GmbH	BO-105LS A-3
2016-25-19	S 2010-21-07	Airbus Helicopters	AS350B3 and EC130B4
2016-25-20		Airbus Helicopters	EC130B4, EC130T2, AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP
2016-25-28		Airbus Helicopters	AS355NP
2016-26-01		AGUSTAWESTLAND S.P.A.	AB139 and AW139
2016-26-04		Robinson Helicopter Company	R44 and R44 II; R66
2016-26-08	R 2014-22-01	PILATUS AIRCRAFT LTD.	PC-12, PC-12/45, PC-12/47, and PC-12/47E
2016-26-09	S 2016-06-01	B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T-4R, BN-2T, BN2A MK. III, BN2A MK. III-2, and BN2A MK. III-3
Biweekly 2017-02			
2017-01-12		Diamond Aircraft Industries GmbH	DA 42 airplanes
2017-02-51		Sikorsky Aircraft Corporation	S-92A helicopters
Biweekly 2017-03			
No ADs			
Biweekly 2017-04			
2016-26-08	COR	PILATUS AIRCRAFT LTD.	PC-12, PC-12/45, PC-12/47, and PC-12/47E airplanes
2017-02-06		Piper Aircraft, Inc.	PA-31T, PA-31T1, PA-31T2, PA-31T3, and PA-31P-350 airplanes
2017-02-07		Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2, and Model MBB-BK 117 D-2 helicopters
2017-02-11		Alexander Schleicher GmbH & Co.	ASK 21 gliders
2017-04-51		Safran Helicopter Engines, S.A.	Arriel 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S and 1S1 turboshaft engines
Biweekly 2017-05			
2017-02-51		Sikorsky Aircraft Corporation	S-92A helicopters
2017-03-01	S 2014-05-06	Airbus Helicopters Deutschland GmbH	EC135 P1, P2, P2+, T1, T2, and T2+ helicopters
2017-04-03		Pilatus Aircraft Limited	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2 airplanes
2017-04-06		United Instruments, Inc.	5934 series altimeters
2017-04-14		Textron Aviation Inc.	560XL airplanes
2017-04-15		Learjet Inc.	36A airplanes
2017-05-03		Airbus Helicopters Deutschland GmbH	BO-105C, BO-105LS A-3, and BO-105S helicopters
2017-05-04		Bell Helicopter Textron Canada Limited	206A, 206B, 206L, 206L1, 206L3, and 206L4 helicopters
2017-05-51		Bell Helicopter Textron Canada	429 helicopters



2017-02-51 Sikorsky Aircraft Corporation: Amendment 39-18818; Docket No. FAA-2017-FAA-2017-0169; Directorate Identifier 2017-SW-003-AD.

(a) Applicability

This AD applies to Sikorsky Aircraft Corporation (Sikorsky) Model S-92A helicopters, certificated in any category, with a tail rotor pitch change shaft (TRPCS) assembly part number (P/N) 92358-06303-041 or P/N 92358-06303-042 installed.

(b) Unsafe Condition

This AD defines the unsafe condition as a binding TRPCS bearing. This condition could result in loss of tail rotor (TR) control and possible loss of control of the helicopter.

(c) Effective Date

This AD becomes effective March 20, 2017 to all persons except those persons to whom it was made immediately effective by Emergency AD 2017-02-51, issued on January 13, 2017, which contains the requirements of this AD.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Before further flight, unless already done, remove the TRPCS assembly and inspect the SB2310 angular contact bearing for free rotation, purged grease with metal particles, a nick or a dent, and any cut, tear, or distortion on the bearing seal. If the bearing does not rotate freely; the bearing sounds rough or chatters; there is any purged grease with metal particles; a nick or dent; or if there is a cut, tear, or distortion in the bearing seal, before further flight, replace the TRPCS assembly.

(2) Within 10 hours time-in-service (TIS), unless already done within the last 10 hours TIS, and thereafter at intervals not to exceed 10 hours TIS, on the TR side of the TRPCS bearing, remove the plug from the end of the TRPCS, insert the borescope into the TRPCS, and determine whether the white Teflon seal and snap ring are installed. If the white Teflon seal or snap ring is missing, or if there is a rip, tear, or heat damage on the seal or if there is no gap in the snap ring, before further flight replace the TRPCS assembly.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Boston Aircraft Certification Office, FAA, may approve AMOCs for this Emergency AD. Send your proposal to: Blaine Williams, Aerospace Engineer, Boston Aircraft Certification Office, Engine & Propeller Directorate, 1200 District Avenue, Burlington, Massachusetts 01803; telephone (781) 238-7161; email blaine.williams@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

Sikorsky Alert Service Bulletin 92-64-011, Basic Issue, dated January 10, 2017, which is not incorporated by reference, contains additional information about the subject of this final rule. For service information identified in this final rule, contact Sikorsky Aircraft Corporation, Customer Service Engineering, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S or 203-416-4299; email: wcs_cust_service_eng.gr-sik@lmco.com. You may review this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6720 Tail Rotor Control System.

Issued in Fort Worth, Texas, on February 23, 2017.

Lance T. Gant,
Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2017-03-01 Airbus Helicopters Deutschland GmbH (Previously Eurocopter Deutschland GmbH): Amendment 39-18792; Docket No. FAA-2015-0674; Directorate Identifier 2014-SW-019-AD.

(a) Applicability

This AD applies to the following helicopters, certificated in any category:

(1) Model EC135 P1, P2, P2+, T1, T2, and T2+ helicopters, serial number (S/N) 0005 through 00829, with a tail rotor control lever, part number (P/N) L672M2802205 or L672M1012212; cyclic control lever, P/N L671M1005250; collective control lever assembly, P/N L671M2020108; or collective control plate, P/N L671M5040207; installed; and

(2) Model MBB-BK 117 C-2 helicopters, S/N 9004 through 9310, with a tail rotor control lever assembly, P/N B672M1007101 or B672M1807101; tail rotor control lever, P/N B672M1002202 or L672M2802205; or lateral control lever assembly, P/N B670M1008101, installed.

(b) Unsafe Condition

This AD defines the unsafe condition as incorrectly installed flight control bearings. This condition could cause the affected control lever to shift and contact the helicopter structure, resulting in reduced control of the helicopter.

(c) Affected ADs

This AD supersedes AD 2014-05-06, Amendment 39-17779 (79 FR 13196, March 10, 2014).

(d) Effective Date

This AD becomes effective March 31, 2017.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) For Model EC135 P1, P2, P2+, T1, T2, and T2+ helicopters:

(i) Within the next 100 hours time-in-service (TIS) or at the next annual inspection, whichever occurs first, modify the left-hand (LH) and right-hand (RH) guidance units and the cyclic shaft by installing bushings and washers to prevent shifting of the bearings in the axial direction as follows:

(A) Remove and disassemble the LH guidance unit and install a bushing, P/N L672M1012260, between the bearing block and the lever of the LH guidance unit as depicted in Detail A of Figure 5 of Eurocopter Alert Service Bulletin EC135-67A-019, Revision 3, dated December 16, 2009 (EC135 ASB).

(B) For helicopters without a yaw brake, remove and disassemble the RH guidance unit and install a bushing, P/N L672M1012260, between the bearing block and the lever as depicted in Detail B of Figure 5 of EC135 ASB.

(C) Remove and disassemble the cyclic shaft and install a washer, P/N L671M1005260, between the bearing block and the lever as depicted in Detail C of Figure 6 of EC135 ASB.

(D) Remove the collective control rod from the bellcrank and install a washer, P/N L221M1042208, on each side of the collective control rod and bellcrank as depicted in Detail D of Figure 6 of EC135 ASB.

(E) At intervals not to exceed 800 hours TIS or 36 months, whichever occurs first, inspect the bearings in the LH guidance unit, RH guidance unit, cyclic control, upper guidance unit, and linear voltage differential transducer plate for play. If any bearing is loose, replace the affected bearing with an airworthy bearing.

(2) For Model MBB-BK 117 C-2 helicopters:

(i) Within the next 100 hours TIS or at the next annual inspection, whichever occurs first, modify the LH and RH guidance units and the lateral control lever by installing bushings and washers to prevent shifting of the bearings in the axial direction as follows:

(A) Remove and disassemble the RH guidance unit and install a bushing, P/N L672M1012260, between the lever and the bracket as depicted in Detail B of Figure 4 of Eurocopter Alert Service Bulletin MBB BK117 C-2-67A-010, Revision 3, dated February 8, 2010 (BK117 ASB). Remove and disassemble the LH guidance unit and install a bushing, P/N L672M1012260, between the lever and the bracket as depicted in Detail C of Figure 4 of BK117 ASB.

(B) Remove the lateral control lever and install new bushings in accordance with the Accomplishment Instructions, paragraphs 3.C(9)(a) through 3.C(9)(g), of BK 117 ASB.

(C) Identify the modified lever assembly by writing "MBB BK117 C-2-67A-010" on the lever with permanent marking pen and protect with a single layer of lacquer (CM 421 or equivalent).

(D) Apply corrosion preventive paste (CM 518 or equivalent) on the shank of the screws and install airworthy parts as depicted in Figure 5 of BK117 ASB.

(E) At intervals not to exceed 600 hours TIS or 24 months, whichever occurs first, inspect the bearings in the RH guidance unit, LH guidance unit, and lateral control guidance unit for play. If any bearing is loose, replace the affected bearing with an airworthy bearing.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2010-0058, dated March 30, 2010. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2015-0674.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6710, Main Rotor Control.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(3) The Director of the Federal Register previously approved the incorporation by reference of the service information listed in this paragraph on April 14, 2014 (79 FR 13196, March 10, 2014).

(i) Eurocopter Alert Service Bulletin EC135-67A-019, Revision 3, dated December 16, 2009.

(ii) Eurocopter Alert Service Bulletin MBB BK117 C-2-67A-010, Revision 3, dated February 8, 2010.

(4) For service information identified in this final rule, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(5) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on January 25, 2017.

Lance T. Gant,
Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2017-04-03 Pilatus Aircraft Limited: Amendment 39-18798; Docket No. FAA-2016-9357; Directorate Identifier 2016-CE-030-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective April 7, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to PILATUS Models PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2 airplanes, all manufacturer serial numbers (MSN), including MSN 2001 through 2092, certificated in any category.

Note 1 of paragraph (c) of this AD: For MSN 2001-2092, these airplanes are also identified as Fairchild Republic Company PC-6 airplanes, Fairchild Industries PC-6 airplanes, Fairchild Heli Porter PC-6 airplanes, or Fairchild-Hiller Corporation PC-6 airplanes.

(d) Subject

Air Transport Association of America (ATA) Code 57: Wings.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as certain combinations of the aileron counterweight and the attaching parts possibly resulting in reduced thread engagement and leading to disconnection of the aileron counterweight from the aileron. We are issuing this AD to prevent disconnection of the aileron counterweight from the aileron, which could result in loss of control.

(f) Actions and Compliance

Unless already done, do the following actions as specified in paragraphs (f)(1) and (2) of this AD:

(1) Within the next 12 months after April 7, 2017 (the effective date of this AD) or the next time the ailerons or aileron counterweights are removed or installed, whichever occurs first, and thereafter anytime the ailerons or aileron counterweights are removed or installed, remove each aileron counterweight to inspect the type and number of washers required for the installation of a counterweight on each aileron following the accomplishment instructions of paragraphs 3.B.(2) and 3.B.(3) of Pilatus PC-6 Service Bulletin (SB) No. 57-006, dated May 13, 2016.

(2) Before further flight after the inspection required by paragraph (f)(1) of this AD, reinstall each aileron counterweight on the airplane following the accomplishment instructions of paragraph 3.B.(3) of Pilatus PC-6 SB No. 57-006, dated May 13, 2016.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI EASA AD No.: 2016-0183, dated September 13, 2016, for related information. The MCAI can be found in the AD docket on the Internet at: <https://www.regulations.gov/document?D=FAA-2016-9357-0002>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Pilatus PC-6 Service Bulletin (SB) No. 57-006, dated May 13, 2016.

(ii) Reserved.

(3) For Pilatus Aircraft Ltd. service information identified in this AD, contact Pilatus Aircraft Ltd., Customer Technical Support (MCC), P.O. Box 992, CH-6371 Stans, Switzerland; phone: +41 (0)41 619 3333; fax: +41 (0)41 619 7311; email: supportPC12@pilatus-aircraft.com; Internet: <http://www.pilatus-aircraft.com>.

(4) You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9357.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri on February 8, 2016.

Robert Busto,
Acting Manager, Small Airplane Directorate, Aircraft Certification Service.



2017-04-06 United Instruments, Inc.: Amendment 39-18801; Docket No. FAA-2016-9345; Directorate Identifier 2016-CE-028-AD.

(a) Effective Date

This AD is effective April 7, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to United Instruments, Inc. 5934 series altimeters that were manufactured between January 2015 and February 2016 and installed in airplanes and helicopters.

(1) The specific affected serial number altimeters can be found in United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016. Paragraph (j)(3) of this AD contains addresses for obtaining the service bulletin.

(2) Altimeters that have been corrected by United Instruments, Inc. following Service Bulletin No. 13, dated March 25, 2016, are not affected by this AD and no further action is necessary.

(3) Altimeters that have been corrected by United Instruments, Inc. can be identified by a yellow dot, approximately 1/4 inch (6 mm) in diameter, located approximately 1 inch (25 mm) to the left side of the nameplate. The corrected altimeters will also have a letter "M," approximately 1/8 inch (3mm) high, metal stamped on the nameplate after the name "ALTIMETER."

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 44, Cabin Systems.

(e) Unsafe Condition

This AD was prompted by reports of certain altimeters displaying higher than actual altitude due to a slow diaphragm leak. We are issuing this AD to prevent display of misleading altitude data, which could result in inadvertent flight into terrain.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within the next 12 months after April 7, 2017 (the effective date of this AD), replace any affected altimeter with a serviceable part following United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Les Lyne, Aerospace Engineer, FAA, Wichita ACO, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4190; fax: (316) 946-4107; email: leslie.lyne@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.

(ii) Reserved.

(3) For United Instruments, Inc. service information identified in this AD, contact United Instruments, Inc., 3625 Comotara Avenue, Wichita, KS 67226; telephone (316) 636-9203; fax: (316) 636-9243; email: customerservice@unitedinst.com; Internet: www.unitedinst.com or <http://www.unitedinst.com/Products/SpecificationsSheets/d132811.aspx>.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9345.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on February 6, 2017.

Kelly A. Broadway,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.



2017-04-14 Textron Aviation Inc. (Type Certificate Previously Held by Cessna Aircraft Company): Amendment 39-18809; Docket No. FAA-2017-0122; Directorate Identifier 2017-NM-010-AD.

(a) Effective Date

This AD is effective March 9, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Textron Aviation Inc. (Type Certificate previously held by Cessna Aircraft Company) Model 560XL airplanes, certificated in any category, as identified in Textron Aviation Service Letter SL560XL-24-07, dated January 13, 2017.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Unsafe Condition

This AD was prompted by reports of inadequate separation between the electrical wire bundle and fuel tube. We are issuing this AD to detect and correct inadequate separation and consequent chafing, which could result in electrical arcing and a fuel leak, leading to a fuel ignition source and possible uncontrolled fire in the tail cone of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections, Adjustments, and Corrective Actions

Within 25 flight hours or 180 days after the effective date of this AD, whichever occurs first, do general visual inspections of the fuel tube and right alternating current (AC) generator wires for evidence of damage, do all applicable adjustments, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Textron Aviation Service Letter SL560XL-24-07, including Attachment, dated January 13, 2017. All applicable adjustments and corrective actions must be done before further flight.

(h) Reporting

Submit a report of the findings (both positive and negative) of the inspections required by paragraph (g) of this AD to Textron Aviation Inc. as specified in Textron Aviation Service Letter SL560XL-24-07, including Attachment, dated January 13, 2017, at the applicable time specified in paragraph (h)(1) or (h)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 10 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

(i) Special Flight Permit

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(j) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Craig Henrichsen, Aerospace Engineer, Electrical Systems and Avionics, ACE-119W, FAA, Wichita ACO, 1801 Airport Road, Room 100, Dwight D. Eisenhower Airport, Wichita, KS 67209; phone: 316-946-4110; fax: 316-946-4107; email: Wichita-COS@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Textron Aviation Service Letter SL560XL-24-07, including Attachment, dated January 13, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Textron Aviation Inc., P.O. Box 7706, Wichita, KS 67277; telephone 316-517-6215; fax 316-517-5802; email citationpubs@txtav.com; Internet <https://support.cessna.com/custsupt/csupt/newlogin.jsp>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 9, 2017.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-04-15 Learjet Inc.: Amendment 39-18810; Docket No. FAA-2016-9388; Directorate Identifier 2016-NM-145-AD.

(a) Effective Date

This AD is effective April 4, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Learjet Inc. Model 36A airplanes, certificated in any category, as identified in Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Unsafe Condition

This AD was prompted by a report indicating that an aileron cable failed on an airplane during a tension check. We are issuing this AD to prevent severe weakening of the aileron cable, and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 100 flight hours or 90 days after the effective date of this AD, whichever occurs first, do a detailed inspection of the center ball of the aileron control cables for a defective swage, and before further flight, replace any damaged or defective cable with a new cable, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002. For the purposes of this AD, a detailed inspection is an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirrors, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.

(h) Parts Installation Limitation

As of the effective date of this AD, no person may install on any airplane an aileron control cable unless it has been inspected in accordance with paragraph (g) of this AD.

(i) No Reporting or Parts Return Requirement

Although Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002, has procedures for submitting a report showing compliance and for returning any discrepant parts to the manufacturer, this AD does not include those requirements.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Donald Ristow, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Dwight D. Eisenhower National Airport, Wichita, KS 67209; phone: 316-946-4120; fax: 316-946-4107; email: donald.ristow@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on August 9, 2005 (70 FR 38578, July 5, 2005).

(i) Bombardier Alert Service Bulletin A35/36-27-42, dated December 23, 2002.

(ii) Reserved.

(4) For Learjet Inc. service information identified in this AD, contact Learjet Inc., One Learjet Way, Wichita, KS 67209-2942; telephone 316-946-2000; fax 316-946-2220; email ac.ict@aero.bombardier.com; Internet <http://www.bombardier.com>.

(5) You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 15, 2017.
Thomas Groves,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2017-05-03 Airbus Helicopters Deutschland GmbH (Previously Eurocopter Deutschland GmbH): Amendment 39-18813; Docket No. FAA-2017-0155; Directorate Identifier 2016-SW-051-AD.

(a) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH Model BO-105C, BO-105LS A-3, and BO-105S helicopters, certificated in any category, with a main rotor blade (MRB) part number 105-15103, 105-15141, 105-15141V001, 105-15143, 105-15150, 105-15150V001, 105-15152, 105-81013, 105-87214, 1120-15101, or 1120-15103 that has less than 200 hours time-in-service (TIS) since the MRB erosion protective shell (shell) was last replaced, and where the shell was last replaced between December 1, 2010, and February 28, 2015, inclusive or where the most recent date of replacement of the shell is unknown.

(b) Unsafe Condition

This AD defines the unsafe condition as debonding of the shell of an MRB. This condition could result in loss of the shell in-flight, which could strike the tailboom or tail rotor, resulting in loss of tail rotor control, high main rotor vibration, and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective March 17, 2017.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 10 hours TIS, and thereafter at intervals not to exceed 50 hours TIS:

- (1) Inspect by tap test each MRB for debonding of the shell.
- (2) If the shell has debonded in any area, before further flight, repair any debonding that does not exceed the maximum repair damage limits, or replace the MRB.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector,

the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Airbus Helicopters Emergency Alert Service Bulletin (EASB) BO105-10A-128 for Model BO105C, D, and S helicopters and EASB BO105 LS-10A-016 for Model BO105 LS A-3 helicopters, both Revision 0, and dated June 16, 2016, which are not incorporated by reference, contain additional information about the subject of this final rule. For service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) Emergency AD No. 2016-0118-E, dated June 17, 2016. You may view the EASA AD on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-0155.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6210 Main Rotor Blade.

Issued in Fort Worth, Texas, on February 21, 2017.

Lance T. Gant,
Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2017-05-04 Bell Helicopter Textron Canada Limited: Amendment 39-18814; Docket No. FAA-2017-0154; Directorate Identifier 2016-SW-069-AD.

(a) Applicability

This AD applies to Bell Helicopter Textron Canada Limited Model 206A, 206B, 206L, 206L1, 206L3, and 206L4 helicopters, certificated in any category, with a tension-torsion strap (TT strap) part number (P/N) 206-011-147-005 with a serial number BTFS-23868 through BTFS-24277 or P/N 206-011-147-007 with a serial number BT-22719 through BT-23437 installed.

(b) Unsafe Condition

This AD defines the unsafe condition as corrosion of a TT strap. This condition could result in failure of the TT strap and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective March 17, 2017.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 25 hours time-in-service (TIS), remove from service any TT strap that has 1,000 or more hours TIS or 18 or more months since installation. Thereafter, remove from service any TT strap before accumulating 1,000 hours TIS or 18 months since installation, whichever occurs first.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Bell Helicopter Alert Service Bulletin (ASB) No. 206-13-130, Revision A, dated October 14, 2013 for model 206A, 206B, and TH67 helicopters and ASB 206L-13-171, Revision A, dated

October 14, 2013 for model 206L series helicopters, which are not incorporated by reference, contain additional information about the subject of this final rule. For service information identified in this final rule, contact Bell Helicopter Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; telephone (450) 437-2862 or (800) 363-8023; fax (450) 433-0272; or at <http://www.bellcustomer.com/files/>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in Transport Canada AD No. CF-2016-09, dated March 21, 2016. You may view the Transport Canada AD on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2017-0154.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6220 Tension Torsion Strap.

Issued in Fort Worth, Texas, on February 17, 2017.

Lance T. Gant,
Manager, Rotorcraft Directorate,
Aircraft Certification Service.



DATE: March 3, 2017

AD #: 2017-05-51

This Emergency Airworthiness Directive (Emergency AD) 2017-05-51 is being sent to owners and operators of Bell Helicopter Textron Canada (Bell) Model 429 helicopters. This Emergency AD applies to those helicopters that have an Air Comm Corporation (Air Comm) air conditioning system part number (P/N) 429EC-200 or 429EC-202 installed.

Background

This Emergency AD is prompted by a report that the condenser blower motor (motor) detached from the condenser blower (blower). The motor is secured to the blower support (shroud) by three screw fasteners with thread locker applied. The report states that the detached motor was resting on the flight controls.

An initial investigation indicates that the motor mount fasteners may not have had the thread locker adhesive applied during production. However, the root cause is under investigation. The motor fell on the collective control tube, causing wear damage to the control tube. The motor's power wiring also was on the collective control tube near hydraulic and fuel lines.

This Emergency AD requires inspecting the motor and blower to determine if the motor is securely attached to the shroud. The actions in this Emergency AD are intended to prevent the motor from detaching, causing failure of the primary flight controls and subsequent loss of helicopter control.

FAA's Determination

We are issuing this Emergency AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of this same type design.

Related Service Information

We reviewed Air Comm Service Bulletin 429-201-1, Revision NC, dated February 17, 2017 (SB 429-201-1), which advises inspecting the motor for to determine whether it is attached to the blower assembly within 20 flight hours. If the motor is not attached to the blower assembly, SB 429-201-1 advises reporting the detachment to Air Comm and inspecting the surrounding area for damage. If any surrounding parts are damaged, SB 429-201-1 specifies replacing or repairing the damaged parts. SB 429-201-1 then specifies replacing the blower assembly if parts are available and deactivating the air conditioning system if parts are not available. SB 429-201-1 also provides instructions if any P/N MS27039-1-15 fasteners are missing or loose or if the motor is not secured firmly to the blower assembly. These instructions include rotating the fan blades by hand and verifying the clearance between the blades and the shroud. If the fan blades are scraping or rubbing against the shroud or if the blades cause visible damage to the shroud, SB 429-201-1 advises replacing the blower assembly if parts are available. If parts are not available, SB 429-201-1 advises deactivating the air conditioning system. If the motor is secure, SB 429-201-1 provides instructions

for replacing any missing fasteners and removing and reinstalling any existing fasteners with thread locker.

Emergency AD Requirements

This Emergency AD requires, before further flight and at intervals not to exceed 25 hours time-in-service (TIS), inspecting the air conditioner condenser blower for motor attachment and for missing or loose fasteners. If the motor is not attached or if a fastener is missing or loose, this Emergency AD requires deactivating the air conditioning system. If the motor is not attached, this Emergency AD also requires inspecting the collective flight control tube, the area under the forward transmission cowling, and each wiring harness, and depending on the findings, repairing or replacing the affected parts. Additionally, if the motor is not attached or if the motor is attached but any fasteners are missing, this Emergency AD requires inspecting for and removing any found detached hardware. Deactivating the air conditioning system constitutes terminating action for the repetitive inspections required by this Emergency AD. This Emergency AD also requires reporting certain information to the FAA within 10 days.

Differences Between this Emergency AD and the Service Information

SB 429-201-1 advises performing the initial inspection within 20 hours TIS. This Emergency AD requires the initial inspection before further flight. SB 429-201-1 advises reporting certain incidents to Air Comm, whereas this Emergency AD requires reporting certain information to the FAA. SB 429-201-1 does not specify inspecting for and removing missing hardware, whereas this Emergency AD requires inspecting for and removing missing hardware. If replacement parts are available, SB 429-201-1 advises replacing the blower, while this Emergency AD makes no allowance for replacing the blower except by alternate means of compliance. If fasteners are missing or loose but the motor is secure, SB 429-201-1 advises replacing missing fasteners and removing and reinstalling existing fasteners with thread locker and a torque stripe. This Emergency AD requires removing the blower assembly if fasteners are missing or loose but the motor is still secure. SB 429-201-1 does not require repetitive inspections, while this Emergency AD requires the inspection every 25 hours time-in-service until the air conditioning system is deactivated.

Interim Action

We consider this Emergency AD to be an interim action. The inspection report that is required by this Emergency AD will enable us to obtain better insight into the cause of the motor's detachment, and help us develop final action to address this unsafe condition. Once final action has been identified, we might consider further rulemaking.

Costs of Compliance

We estimate that this AD affects 78 helicopters of U.S. Registry and that labor costs average \$85 per work-hour. Based on these estimates, we expect the following costs:

- Inspecting the motor attachment requires 1 work-hour and no parts for a total cost of \$85 per helicopter, and \$6,630 for the U.S. fleet, per inspection cycle.
- Removing the motor and deactivating the air conditioning requires 2 work-hours and no parts for a total cost of \$170 per helicopter.
- Removing the blower assembly and deactivating the air conditioning requires 13 work-hours and no parts for a total cost of \$1,105 per helicopter.

- Reporting the findings to the FAA requires 1 work-hour and no parts for a total cost of \$85 per helicopter.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this Emergency AD is 2120-0056. The paperwork cost associated with this Emergency AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting required by this Emergency AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave., SW, Washington, DC 20591; ATTN: Information Collection Clearance Officer, AES-200.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. "Subtitle VII, Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701, General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Adoption of the Emergency Airworthiness Directive (AD)

We are issuing this Emergency AD under 49 U.S.C. Sections 106(g), 40113, and 44701 according to the authority delegated to me by the Administrator.
2017-05-51 **Bell Helicopter Textron Canada:** Directorate Identifier 2017-SW-008-AD.

(a) Applicability

This Emergency AD applies to Bell Helicopter Textron Canada (Bell) Model 429 helicopters with an Air Comm Corporation air conditioning system part number (P/N) 429EC-200 or 429EC-202 installed, certificated in any category.

Note 1 to paragraph (a) of this Emergency AD: air conditioning system P/N 429EC-200 and 429EC-202 are identifiable by a three-screw installation as depicted in Figure 1 of Air Comm Corporation Service Bulletin 429-201-1, Revision NC, dated February 17, 2017 (SB 429-201-1).

(b) Unsafe Condition

This Emergency AD defines the unsafe condition as a condenser blower motor (motor) detaching from the condenser blower support (shroud). This condition could lead to failure of the primary flight controls and subsequent loss of helicopter control.

(c) Effective Date

This Emergency AD is effective upon receipt.

(d) Compliance

You are responsible for performing each action required by this Emergency AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Before further flight, and thereafter at intervals not to exceed 25 hours time-in-service:

(1) Inspect the motor and condenser blower to determine whether the motor is attached to the shroud.

(i) If the motor is not attached, before further flight:

(A) Inspect the collective flight control tube for loss of protective primer, a scratch, any gouging, and a dent. If there is any loss of protective primer, a scratch, any gouging, or a dent, repair or replace the control tube.

(B) Inspect the area under the forward transmission cowling for loss of protective primer, a scratch, any gouging, and a dent. Inspect each wiring harness for any cuts, chafing, and exposed wires. If there is any loss of protective primer, a scratch, any gouging, a dent, or if any wiring harness has a cut, chafing, or an exposed wire, repair or replace the affected parts.

(C) Inspect the area under the forward transmission cowling for the three fasteners as depicted in Figure 1 of SB 429-201-1. Also inspect for the crimp-on external fan retaining ring (crimp ring) and the slotted fan drive spring (commonly known as a roll pin), which may have fallen loose with the motor. Remove any fasteners, the crimp ring, and the roll pin if found detached.

(D) Deactivate the air conditioning system by following the instructions in Procedure, paragraphs B.2.d.i. through B.2.d.v., of SB 429-201-1.

(ii) If the motor is attached to the shroud but a fastener is missing or loose, before further flight:

(A) Remove any detached fasteners found in the area under the forward transmission cowling.

(B) Deactivate the air conditioning system as follows:

- (1) Pull and red collar the air conditioning COND circuit breaker.
- (2) Pull and red collar the air-conditioning COMP circuit breaker.
- (3) Remove the compressor drive belt.
- (4) Remove the condenser blower assembly.

(2) Deactivating the air conditioning system as required by paragraph (e)(1) of this Emergency AD constitutes terminating action for the repetitive inspections required by paragraph (e)(1) of this Emergency AD.

(3) If the air conditioning system is deactivated as required by paragraph (e)(1) of this Emergency AD, within 10 days after completing the inspection, report the information requested in

Appendix 1 to this Emergency AD by mail to the Manager, Denver Aircraft Certification Office, FAA, Technical Operations Center, 26805 East 68th Avenue, Room 214, Denver CO 80249, ATTN: Matthew Bryant; by fax to (303) 342-1088; or by email to Matthew.Bryant@faa.gov.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Denver Aircraft Certification Office, FAA, may approve AMOCs for this Emergency AD. Send your proposal to: Matthew Bryant, Aerospace Engineer, Denver Aircraft Certification Office, FAA, Technical Operations Center, 26805 East 68th Avenue, Room 214, Denver CO 80249; fax (303) 342-1088; email Matthew.Bryant@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this Emergency AD through an AMOC.

(g) Additional Information

(1) For further information contact: Matthew Bryant, Aerospace Engineer, Denver Aircraft Certification Office, FAA, Technical Operations Center, 26805 East 68th Avenue, Room 214, Denver CO 80249; phone (303) 342-1092; fax (303) 342-1088; email Matthew.Bryant@faa.gov.

(2) For a copy of the service information referenced in this Emergency AD, contact: Air Comm Corporation, 1575 West 124th Avenue, Westminster, CO 80234, telephone: (303) 440-4075 (during business hours) or (720) 233-8330 (after hours); email: service@aircommcorp.com, website: <http://www.aircommcorp.com/contact>.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 2150, Cabin Cooling System.

Issued in Fort Worth, Texas, on March 3, 2017.

Lance T. Gant,

Manager, Rotorcraft Directorate,
Aircraft Certification Service.

Appendix 1 to Emergency AD 2017-05-51

Provide the following information by mail to the Manager, Denver Aircraft Certification Office, FAA, Technical Operations Center, 26805 East 68th Avenue, Room 214, Denver CO 80249, ATTN: Matthew Bryant; by fax to (303) 342-1088; or by email to Matthew.Bryant@faa.gov:

For inspection being accomplished (Initial or Repetitive), record inspection findings below and provide photos if possible.

AD 2017-05-51	Inspection Findings		
Aircraft S/N or N-Number		Aircraft hours time-in-service (TIS)	
Air Conditioner Installation S/N (Laser etched on compressor mount)		Aircraft TIS when air conditioning system was installed	
		Estimated percent air conditioner operating time	
Aircraft Location		Operator and maintenance facility contact information	
Condition		Findings	
Is this a single evaporator installation or a dual evaporator installation?			
Was the motor still attached?			
Were there any missing or loose fasteners?			
Were any of the loose fasteners found in the surrounding area?			
Did the found fasteners show evidence of thread locker being applied?			
Has the condenser blower (blower) been replaced following the initial installation of the air conditioning system?			
What was the reason for the blower replacement?			
Aircraft TIS when blower was replaced.			