

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2019-26**

12/09/2019 - 12/22/2019



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
Biweekly 2019-01			
2018-22-07		Engine Alliance	GP7270, GP7272, and GP7277 model turbofan engines
2018-23-12	COR	Zodiac Aero Evacuation Systems	Fusible plugs installed on emergency evacuation equipment
2018-25-08	R 2017-22-07	Airbus SAS	A319, A320, A321 airplanes
2018-26-01	R 2018-18-01	CFM International S.A.	CFM56-7B turbofan engines
2018-26-03		The Boeing Company	757-200 series airplanes
2018-26-04		Airbus SAS	A350-941 and -1041 airplanes
2018-26-05	A 2015-19-01	The Boeing Company	777-200, 777-200LR, 777-300, 777-300ER, and 777F series airplanes
2018-26-06		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
Biweekly 2019-02			
2019-01-01		The Boeing Company	787-8 airplanes
Biweekly 2019-03			
2019-01-01	COR	The Boeing Company	787-8 airplanes
Biweekly 2019-04			
2018-23-04		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2018-24-01		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-01-03	R 2016-18-01	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-01-04		The Boeing Company	787 series airplanes
2019-01-05	A 2017-05-10	Airbus SAS	A330-201, A330-202, A330-203, A330-223, A330-243, A330-223F, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes
2019-01-06		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-01-07		Airbus SAS	A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2019-01-08		The Boeing Company	777-200, -200LR, -300, and -300ER series airplanes
2019-02-01	R 2018-16-07	General Electric Company	GEnx-1B54, -1B58, -1B64, -1B67, -1B70, -1B54/P1, -1B58/P1, -1B64/P1, -1B67/P1, -1B70/P1, -1B54/P2, -1B58/P2, -1B64/P2, -1B67/P2, -1B70/P2, -1B70C/P1, -1B70/72/P1, -1B70/75/P1, -1B74/75/P1, -1B75/P1, -1B70C/P2, -1B70/72/P2, -1B70/75/P2, -1B74/75/P2, -1B75/P2, -1B76/P2, -1B76A/P2, -1B78/P2, -2B67, -2B67B, and -2B67/P turbofan engines
2019-02-03		The Boeing Company	787-8, 787-9, and 787-10 airplane
2019-02-04	R 2018-22-05	Engine Alliance	GP7270, GP7272, and GP7277 turbofan engines
2019-03-01		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
Biweekly 2019-05			
2018-21-14		Zodiac Aerotechnics	MC10 series crew oxygen mask regulators
2018-26-07		Airbus SAS	A350-941 and -1041 airplanes
2018-26-08		Airbus SAS	Note: Was missing from BW2019-01 A320-214, A320-232, A320-233, A321-211, and A321-231 airplanes
2019-03-03	A 2016-17-03	Airbus SAS	Note: Was missing from BW2019-01 A318, A319, A320, A321 airplanes
2019-03-04	R 2018-11-16	Engine Alliance	GP7270 and GP7277 model turbofan engines
2019-03-06		The Boeing Company	737-300, -400, and -500 series airplanes
2019-03-07	R 2017-16-05	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-03-08		Airbus SAS	A350-941 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-03-09		Airbus SAS	A310-304, -322, -324, and -325 airplanes
2019-03-10	R 2017-07-05	Airbus SAS	A300 airplanes
2019-03-11		Airbus SAS	A350-941 and -1041 airplanes
2019-03-15		Airbus SAS	A330-201, -202, and -203; A330-301, -302, and -303 airplanes
2019-03-17	A 2017-25-04	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-19		Saab AB, Saab Aeronautics	SAAB 2000 airplanes
2019-03-20	A 2014-16-23 A 2016-16-09	Dassault Aviation	FALCON 7X airplanes
2019-03-21		Embraer S.A.	ERJ 190-100 STD, -100 LR, and -100 IGW; ERJ 190-200 STD, -200 LR, and -200 IGW airplanes
2019-03-23		Airbus SAS	A330, A340 airplanes
Biweekly 2019-06			
2019-03-13		Gulfstream Aerospace LP	Gulfstream G150 airplanes
2019-03-14		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes
2019-03-16	A 2006-25-06 A 97-04-08	Fokker Services B.V.	F.27 Mark 100, 200, 300, 400, 500, 600, and 700 airplanes
2019-03-18		Airbus SAS	A318, A319, A320 airplanes
2019-03-22		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2019-03-24		The Boeing Company	737-400 series airplanes
2019-03-25	A 2008-02-15	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-26		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-03-27		Dassault Aviation	Falcon 10 airplanes
2019-03-28	R 2016-07-23	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-30		Empresa Brasileira de Aeronautica S.A.	EMB-135, EMB-145 airplanes
2019-05-01	R 2017-11-06	Pratt & Whitney Division	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines
2019-05-02	R 2017-22-13	Rolls-Royce plc	RB211-Trent 970-84 and RB211-Trent 972-84 turbofan engines
2019-05-08	R 2015-12-08	Airbus SAS	A318, A319, A320, A321 airplanes
Biweekly 2019-07			
2019-05-07	R 2017-20-01	Honeywell International Inc.	TFE731-20R, -20AR, -20BR, and TFE731-40, -40AR, -40BR, and -40R turbofan engines
2019-05-09		Airbus SAS	A320-251N and -271N, and A321-253N airplanes
2019-05-10		Airbus SAS	A350-941 airplanes
2019-05-12		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2019-05-13	R 2007-22-05	Airbus SAS	A300-600 and A310 series airplanes
2019-05-14	R 2012-02-18	Dassault Aviation	MYSTERE-FALCON 50 airplanes
2019-06-01	R 2018-24-01	International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-06-02		Pratt & Whitney Division	PW4158 turbofan engines
2019-06-06		International Aero Engines AG	V2500-A1, V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2533-A5 turbofan engines
2019-06-07	R 2016-22-05	Pratt & Whitney Division	Certain PW4000 engines (see AD)
Biweekly 2019-08			
2019-06-01	R 2018-24-01	International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-06-02	COR	Pratt & Whitney Division	PW4158 turbofan engines
2019-06-03	A 2017-01-08	Airbus SAS	A330 and A340 airplanes
2019-06-08		Airbus SAS	A330-223, A330-223F, A330-321, A330-322, and A330-323 airplanes
2019-06-09		Airbus SAS	A350-941 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-06-12		Airbus SAS	A330-201, -202, and -203; A330-301, -302, and -303 airplanes
2019-07-03		Zodiac Seats France	536-Series Cabin Attendant Seats
Biweekly 2019-09			
2019-07-01	A 2014-26-07	Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes
2019-07-04	COR	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2019-07-05	R 2016-19-04	Airbus SAS	A318, A319, A320 and A321 airplanes
2019-07-06		Bombardier, Inc	Model BD-100-1A10 airplanes
2019-07-09		Rolls-Royce plc	Trent 1000-A2, Trent 1000-AE2, Trent 1000-C2, Trent 1000-CE2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 model turbofan engines
Biweekly 2019-10			
2019-03-29		Bombardier, Inc	Model BD-100-1A10 airplanes
2019-06-13		The Boeing Company	Model 787 series airplanes
2019-07-05	COR, A 2016-19-04	Airbus SAS	A318, A319, A320 airplanes
2019-08-01		RECARO Aircraft Seating GmbH & Co. KG	Passenger Compartment Equipment
2019-08-02		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-08-05		The Boeing Company	Model 787-8 and 787-9 airplanes
2019-08-06	R 2016-16-01	Airbus SAS	A330-223F and -243F, A330-201, -202, -203, -223, -243 A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2019-08-09	A 2017-04-13	The Boeing Company	Model 747-8 and 747-8F series airplanes
2019-08-12		Viking Air Limited	Model CL-215-6B11 (CL-215T Variant) and CL-215-6B11 (CL-415 Variant)
Biweekly 2019-11			
2019-08-03		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-08-07	R 2014-20-04	Airbus SAS	A318, A319, A320 and A321 airplanes
2019-08-08	R 2010-14-05	Bombardier, Inc.	Model CL-600-1A11 (600), Model CL-600-2A12 (601), Model CL-600-2B16 airplanes
2019-09-01		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
Biweekly 2019-12			
2019-08-04	R 2012-25-02	Bombardier, Inc.	Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2019-08-11	R 2008-24-14	Bombardier, Inc.	Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2019-10-03		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-10-04		BRP-Rotax GmbH & Co KG	BRP-Rotax GmbH & Co KG (Rotax) 912 F2, 912 F3, and 912 F4 engines, Rotax 912 S2, 912 S3, and 912 S4 engines, Rotax 914 F2, 914 F3, and 914 F4 engines, and Rotax 912 F2, 912 F3, 912 F4, 912 S2, 912 S3, 912 S4, 914 F2, 914 F3, and 914 F4 engines
2019-10-05		Viking Air Limited	Models DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 airplanes
Biweekly 2019-13			
2019-10-01		Bombardier, Inc	Model CL-600-2A12 (601) airplanes
2019-11-01		Airbus SAS	Model A350-941 airplanes
2019-11-02	R 2017-16-10	The Boeing Company	Model 777-200, -200LR, -300, -300ER, and 777F series airplanes
2019-11-03		The Boeing Company	Model 737-700C, -800, and -900ER series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-11-06	A 2013-19-23	The Boeing Company	Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-11-07		Rolls-Royce plc	RB211-524G2-19, RB211-524G2-T-19, RB211-524G3-19, RB211-524G3-T-19, RB211-524H2-19, RB211-524H2-T-19, RB211-524H-36 and RB211-524H-T-36 engines
2019-11-08		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines
2019-11-09		Airbus SAS	Model A319-113 and -114 airplanes, and Model A320-211 and -212 airplanes
2019-12-01		CFM International S.A	LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B3, -1B28B2C, -1B28BBJ1, and -1B28BBJ2 model turbofan engines
2019-12-05		CFM International S.A	CFM56-5B1, -5B2, -5B4, -5B5, -5B6, -5B7, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B7/P, -5B8/P, -5B9/P, -5B3/P1, -5B4/P1, -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P, -5B9/2P, -5B3/2P1, -5B4/2P1, -7B20, -7B22, -7B24, -7B26, -7B27, -7B22/B1, -7B24/B1, -7B26/B1, -7B26/B2, -7B27/B1, -7B27/B3, -7B20/2, -7B22/2, -7B24/2, -7B26/2, -7B27/2, -7B27A model turbofan engines
Biweekly 2019-14			
2019-12-03		Bombardier, Inc.	Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes
2019-12-04	R 2018-19-18	Airbus SAS	Model A300 B4-603, B4-620, B4-622, B4-605R, B4-622R, C4-605R Variant F, F4-605R, and F4-622R airplanes
2019-12-07	A 2014-20-18 R 2007-11-11 R 2018-01-11	Airbus SAS	Model A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, A320-211, -212, -214, -216, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2019-12-10	A 2017-06-06 A 2012-12-07	Fokker Services B.V	Model F28 Mark 0070 and 0100 airplanes
2019-12-13		The Boeing Company	Model 757-200, -200PF, -200CB, and -300 series airplanes
Biweekly 2019-15			
2019-10-02		Saab AB, Saab Aeronautics	Model SAAB 2000 airplanes
2019-12-02		Bombardier Inc.	Model BD-700-1A10 and BD-700-1A11 airplanes
2019-12-08		Bombardier, Inc.	Model CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2019-12-09		Rockwell Collins, Inc.	Flight Display System Application FDSA-6500
2019-12-11		Bombardier, Inc	Model CL-600-2B19 (Regional Jet Series 100 & 440)
2019-12-16		Airbus SAS	Model A350-941 airplanes
2019-12-17		Bombardier, Inc.	Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2019-13-02		The Boeing Company	Model 737-200, -200C, -300, -400, and -500 airplanes
Biweekly 2019-16			
2019-07-10		Northrop Grumman LITEF GmbH LCR-100	Attitude and Heading Reference System (AHRS) Note: This AD was included in Small AD Biweekly 2019-09, but was inadvertently left off the Large AD Biweekly.
2019-13-03		Trig Avionics Limited	Mode S transponders
2019-13-04		ATR-GIE Avions de Transport Régional	Model ATR72-101, -102, -201, -202, -211, -212, and -212A
2019-14-01		Rolls-Royce Deutschland Ltd & Co KG	TAY 650-15 and TAY 651-54 turbofan
2019-14-02		The Boeing Company	Model 737 series
2019-14-04		Airbus SAS	Model A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -216, -231, -232, -233, -251N, -252N, and -271N,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-14-05 2019-15-05		B/E Aerospace Fischer GmbH Rolls-Royce Deutschland Ltd & Co KG	A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes Common Seats Trent 1000-AE3, Trent 1000-CE3, Trent 1000-D3, Trent 1000-G3, Trent 1000-H3, Trent 1000-J3, Trent 1000-K3, Trent 1000-L3, Trent 1000-M3, Trent 1000-N3, Trent 1000-P3, Trent 1000-Q3 and Trent 1000-R3 engines
Biweekly 2019-17			
2019-14-06		Airbus SAS	A319-111, -112, -115, and -131 airplanes, and Airbus SAS Model A320-214 and -232 airplanes
2019-14-07		Airbus SAS	A320-251N and -271N airplanes; and Model A321-251N, -253N, -271N, and -272N airplanes
2019-14-09 2019-14-10	R 2018-02-11	Airbus SAS Airbus SAS	A330-223F and -243F A330-223, -243, -301, -302, -321, -322, -323, -341, -342, and -343 airplanes; and Model A340-211, -212, -213, -311, -312, and -313
2019-14-12 2019-14-13 2019-14-14		The Boeing Company The Boeing Company Airbus SAS	737-8 and 737-9 Model 767-200, -300, -300F, and, -400ER series airplanes A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2019-14-15 2019-15-01	R 2017-25-12	The Boeing Company Bombardier, Inc.	737-100, -200, -200C, -300, -400, and -500 series Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes
2019-15-03 2019-15-04 2019-15-06 2019-15-07	R 2018-22-07	328 Support Services GmbH Bombardier, Inc. Engine Alliance The Boeing Company	Model 328-100 airplanes Model BD-100-1A10 airplanes GP7270, GP7272, and GP7277 model turbofan Model 737-100, 737-200, 737-200C, 737-300, 737-400, and 737-500 series
2019-15-08	R2002-07-05	Airbus SAS	Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 C4-605R Variant F, A300 F4-605R
2019-15-09 2019-15-10 2019-16-01 2019-16-02 2019-16-04	R 2019-03-04	Bombardier, Inc. Safran Aerosystems International Aero Engines AG GE Honda Aero Engines Engine Alliance	DHC-8-400, -401, and -402 airplanes life jackets V2525-D5 and V2528-D5 model turbofan engines HF120 model turbofan engines GP7270 and GP7277 model turbofan engines
Biweekly 2019-18			
2019-14-03	R 2016-07-12	Airbus SAS	A318-111, -112; Model A319-111, -112, -113, -114, -115; Model A320-211, -212, -214, -216; and Model A321-111, -112, -211, -212, -213
2019-14-08	R 2016-07-22	Airbus SAS	A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2019-15-02		Airbus SAS	A321-251N, A321-252N, A321-253N, A321-271N, A321-272N, A321-251NX, A321-252NX, A321-253NX, A321-271NX, and A321-272NX airplanes
2019-16-03 2019-16-06 2019-16-11 2019-16-14	R 2018-20-06 R 2018-25-01	Airbus SAS Airbus SAS Airbus SAS Rolls-Royce Deutschland Ltd & Co KG	A350-941 and -1041 airplanes A320-251N and A320-271N A300 F4-605R and F4-622R airplanes Trent 1000-A, Trent 1000-AE, Trent 1000-C, Trent 1000-CE, Trent 1000-D, Trent 1000-E, Trent 1000-G, and Trent 1000-H turbofan
2019-16-15		Pratt & Whitney	PW1519G, PW1521G, PW1521GA, PW1524G, PW1525G, PW1521G-3, PW1524G-3, PW1525G-3, PW1919G, PW1921G, PW1922G, PW1923G, and PW1923G-A model turbofan

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-17-01	R 2017-11-09	Learjet, Inc	Model 60 airplanes
Biweekly 2019-19			
2019-15-07	COR	The Boeing Company	737-100, 737-200, 737-200C, 737-300, 737-400, and 737-500 series
2019-16-05		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series
2019-16-09		Bombardier, Inc	DHC-8-400, -401, and -402 airplanes
2019-16-10		The Boeing Company	787-8 airplanes
2019-16-12	R 2005-20-01	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2019-17-03		Airbus SAS	A320-214 and -271N airplanes and Model A321-211 and -231 airplanes
2019-17-04	R 2019-06-09	Airbus SAS	A350-941 airplanes
2019-17-05		Airbus SAS	A330-223F and -243F, A330-201, -202, -203, -223, and -243, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, and -21, A340-311, -312, and -313, A340-541 and -642 airplanes
2019-17-07		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2019-18-01		International Aero Engines AG	AG V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, and V2533-A5 model turbofan
Biweekly 2019-20			
2019-16-07	R 2016-12-09	Airbus SAS	A330-201, -202, -203, -223, and -243, A330-223F and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, and -213, A340-311, -312, and -313 airplanes
2019-17-06		Fokker Services B.V	F28 Mark 0070 and 0100
2019-18-03		The Boeing Company	Model 737 series
2019-18-04	R 2005-17-14	Airbus SAS	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2019-18-05		De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402
2019-18-06		Airbus SAS	A318-112, -121, and -122; A319-111, -112, -115, -131, -132, and -133; A320-214, -216, -232, -233, -251N, and -271N; and A321-211, -212, -213, -231, -232, -251N, -253N, -271N, and -272N
2019-18-07	R 2015-17-14	Airbus SAS	A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-211, -212, -214, -216, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232
2019-18-08	R 2019-16-04	Engine Alliance	GP7270 and GP7277 model turbofan
2019-18-09		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G
2019-19-03		Embraer S.A	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU airplanes; and Model ERJ 170-200 LR, -200 SU, -200 STD, and -200 LL, ERJ 190-100 STD, -100 LR, and -100 IGW airplanes; and ERJ 190-200 STD, -200 LR, and -200 IGW, ERJ 190-100 ECJ
2019-19-04		Saab AB, Saab Aeronautics	SAAB 2000
2019-19-11		Pratt & Whitney	PW1519G, PW1521G, PW1521GA, PW1524G, PW1525G, PW1521G-3, PW1524G-3, PW1525G-3, PW1919G, PW1921G, PW1922G, PW1923G, and PW1923G-A turbofan

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

Biweekly 2019-21

2019-16-08	R 2018-22-13	Airbus SAS	Model A350-941 and -1041
2019-16-13		The Boeing Company	Model 777-200 and -300
2019-19-05		Airbus SAS	A350-941 and -1041 airplanes
2019-19-06		Airbus SAS	A330-202, -243, -243F, -302, -323, and -343 airplanes
2019-19-07		Airbus SAS	Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2019-19-09		Airbus SAS	A330-223F and -243F, A330-201, -202, -203, -223, and -243, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2019-19-14		Airbus SAS	A350-941 and -1041 airplanes
2019-19-15		Airbus SAS	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -216, -231, -232, -233, -251N, and -271N airplanes, A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes.
2019-19-16	R 2019-05-09	Airbus SAS	Model A320-251N and -271N, A321-253N
2019-19-17	R 2000-03-20 R1	Airbus SAS	A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R, A300 C4-605R Variant F airplanes
2019-20-02		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2019-20-07		The Boeing Company	787-8, 787-9, and 787-10 airplanes

Biweekly 2019-22

2019-19-02		The Boeing Company	747-400 and 747-400F series
2019-20-01	R 2018-26-07	Airbus SAS	A350-941 and -1041
2019-20-03		Transport Category Airplanes	See AD
2019-20-05	R 2018-15-01	Rolls-Royce Deutschland Ltd & Co KG	Trent 1000-A, Trent 1000-A2, Trent 1000-AE, Trent 1000-AE2, Trent 1000-AE3, Trent 1000-C, Trent 1000-C2, Trent 1000-CE, Trent 1000-CE2, Trent 1000-CE3, Trent 1000-D, Trent 1000-D2, Trent 1000-D3, Trent 1000-E, Trent 1000-E2, Trent 1000-G, Trent 1000-G2, Trent 1000-G3, Trent 1000-H, Trent 1000-H2, Trent 1000-H3, Trent 1000-J2, Trent 1000-J3, Trent 1000-K2, Trent 1000-K3, Trent 1000-L2, Trent 1000-L3, Trent 1000-M3, Trent 1000-N3, Trent 1000-P3, Trent 1000-Q3 and Trent 1000-R3 model turbofan
2019-20-06		Airbus SAS	A310-203, -204, -221, -222, -304, -322, -324, and -325
2019-20-09	R 2011-18-15	De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402
2019-20-12		Airbus SAS	A330-243, -243F, -341, -342, and -343
2019-20-13		Airbus SAS	A330-201, -202, -203, -223, and -243, A330-223F, -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343
2019-21-01		Airbus SAS	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F
2019-21-02		Airbus SAS	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2019-21-51	E	General Electric Company	GE90-115B model turbofan

Biweekly 2019-23

2019-19-01		Airbus SAS	A320-251N and -271N airplanes, and Model A321-251N, -253N, -271N, and -272N
2019-20-11		ATR-GIE Avions de Transport Régional	ATR72-101, -102, -201, -202, -211, -212, and -212A
2019-21-04		Saab AB, Saab Aeronautics	SAAB 2000
2019-21-05		Airbus SAS	A330-200, A330-200 Freighter, A330-300, A340-200, A340-300, A340-500, and A340-600
2019-21-06	R 2017-22-02	Ipeco Holdings Limited	Pilot and co-pilot seats

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-21-07 2019-21-11	R 2019-19-11	Airbus SAS Pratt & Whitney	A350-941 Model PW1519G, PW1521G, PW1521GA, PW1524G, PW1525G, PW1521G-3, PW1524G-3, PW1525G-3, PW1919G, PW1921G, PW1922G, PW1923G, and PW1923G-A model turbofan
Biweekly 2019-24			
2019-13-01		Airbus SAS	A330-201, -202, -203, -223, and -243, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A330-343, A340-211, -212, and -213, A340-311, -312, and -313
2019-19-08		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2019-20-04		Airbus SAS	A330-243, A330-243F, A330-341, A330-342, and A330-343
2019-20-10		Airbus SAS	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -216, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2019-21-03		Bombardier, Inc	CL-600-1A11 (600), CL-600-2A12 (601), CL-600-2B16 (601-3A and 601-3R Variants)
2019-21-09 2019-21-10		Aviointeriors S.p.A Airbus SAS	passenger seats A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, and A321-232
2019-21-13 2019-21-51 2019-22-01	R 2012-22-18	Airbus SAS General Electric Company The Boeing Company	A330-243, -243F, -341, -342, and -343 GE90-115B model turbofan 787-8
2019-22-04 2019-22-05	R 96-25-04 R 2017-23-06	Airbus SAS General Electric Company	A320-211, -212, and -231 CF34-8C1, CF34-8C5, CF34-8C5A1, CF34-8C5B1, CF34-8C5A2, and CF34-8C5A3
2019-22-10	R 2019-20-02	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER
Biweekly 2019-25			
2019-22-06 2019-22-11	2009-09-02	The Boeing Company De Havilland Aircraft of Canada Limited	Model 737-800 DHC-8-400, -401, and -402
2019-22-12 2019-22-13 2019-22-14 2019-23-01		Airbus SAS Fokker Services B.V Airbus SAS Airbus SAS	A320-214, -216, -232, and -233 F28 Mark 0070 and 0100 A350-941 A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -216, -231, -232, -233, -251N, -252N and -271N, A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX
2019-23-02		Airbus SAS	A330-223F and -243F, A330-201, -202, -203, -223, and -243, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343
2019-23-08 2019-25-01	R 2019-03-19	Saab AB, Saab Aeronautics International Aero Engines LLC	SAAB 2000 PW1122G-JM, PW1124G-JM, PW1124G1-JM, PW1127G1-JM, PW1127GA-JM, PW1127G-JM, PW1129G-JM, PW1130G-JM, PW1133GA-JM, PW1133G-JM
Biweekly 2019-26			
2019-19-10 2019-22-02	A 88-21-03 R1	The Boeing Company The Boeing Company	737, 757, 767, 777, 787 series airplanes 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes
2019-22-09 2019-23-03	R 2014-16-27 R 2017-19-14 A 2010-26-05	The Boeing Company Dassault Aviation	787-8 airplanes FALCON 900EX airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-23-05	R 2016-01-16 R 2018-19-05 A 2010-26-05	Dassault Aviation	MYSTERE-FALCON 900 airplanes
2019-23-06		The Boeing Company	757-200, -200CB, and -300 series airplanes
2019-23-07		The Boeing Company	787-8, 787-9, and 787-10 airplanes
2019-23-11		Gulfstream Aerospace Corporation	GVI airplanes
2019-23-12		The Boeing Company	737-300, -400, and -500 series airplanes
2019-23-13		Airbus SAS	A320-251N and A321-253N airplanes
2019-23-14	A 2008-10-09 R1 A 2011-12-09 A 2013-13-15 A 2013-25-05 A 2016-18-16 A 2017-17-09 A 2018-04-12	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-23-15		Airbus Canada Limited Partnership	BD-500-1A10 and BD-500-1A11 airplanes
2019-23-17		Dassault Aviation	FALCON 900EX and Model FALCON 2000EX airplanes
2019-23-18		Dassault Aviation	MYSTERE FALCON 50, MYSTERE FALCON 900, FALCON 900EX, FALCON 2000, and FALCON 2000EX airplanes
2019-24-10		Airbus SAS	A350-941 airplanes
2019-24-11	R 2014-16-26 R 2017-19-04 A 2010-26-05	Dassault Aviation	FALCON 900EX airplanes
2019-24-17		The Boeing Company	MD-90-30 airplanes
2019-25-55	E	The Boeing Company	737-300, -400, and -700 series airplanes



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2019-19-10 The Boeing Company: Amendment 39-19746; Docket No. FAA-2017-1024; Product Identifier 2017-NM-065-AD.

(a) Effective Date

This AD is effective January 16, 2020.

(b) Affected ADs

This AD affects AD 88-21-03 R1, Amendment 39-6077 (53 FR 46605, November 18, 1988) (“AD 88-21-03 R1”).

(c) Applicability

This AD applies to all The Boeing Company airplanes, certificated in any category, identified in paragraphs (c)(1) through (5) of this AD.

- (1) Model 737-300, -400, -500, -600, -700, -700C, -800, -900, and -900ER series airplanes.
- (2) Model 757-200, -200PF, -200CB, and -300 series airplanes.
- (3) Model 767-200, -300, -300F, and -400ER series airplanes.
- (4) Model 777-200, -200LR, -300, -300ER, and -777F series airplanes.
- (5) Model 787-8 and 787-9 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 28; Fuel.

(e) Unsafe Condition

This AD was prompted by reports of fuel crossfeed valves failing to open when activated during flight. The FAA is issuing this AD to prevent an airplane from being dispatched on an extended operations (ETOPS) flight with a single fuel crossfeed valve (due to design or due to minimum equipment list (MEL) dispatch of a dual crossfeed valve equipped airplane with one crossfeed valve inoperative) that cannot be opened or a fuel balancing system that cannot properly operate when activated. This condition could cause the fuel in the main tank associated with a failed engine to be unavailable to the remaining operative engine, potentially resulting in a forced off airport landing due to exhaustion of the remaining usable fuel and consequent loss of all engine thrust.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) AFM Revisions for Model 737 Airplanes Equipped With a Single Fuel Crossfeed Valve

For airplanes identified in paragraph (c)(1) of this AD: Within 120 days after the effective date of this AD, do the actions specified in paragraphs (g)(1) and (2) of this AD.

(1) Revise the “Extended Range Operations” subsection of the “Fuel System Limitations” section of the Section 1 Certificate Limitations of the existing airplane flight manual (AFM) by incorporating the information specified in figure 1 to paragraph (g)(1) of this AD. This may be done by inserting a copy of this AD into the existing AFM. When a statement identical to that in figure 1 to paragraph (g)(1) of this AD has been included in the “Extended Range Operations” subsection of the “Fuel System Limitations” section of the Section 1 Certificate Limitations of the general revisions of the existing AFM, the general revisions may be inserted into the existing AFM, and the copy of this AD may be removed from the existing AFM.

Figure 1 to paragraph (g)(1) – Model 737 AFM Section 1 Revision

Fuel Crossfeed Valve Operational Check for Airplanes with a Single Crossfeed Valve
(Required by AD 2019-19-10)

Prior to each extended operations (ETOPS) flight, an operational check of the fuel crossfeed valve must be performed. This check must be performed by the flight crew prior to each ETOPS flight as part of the pre-flight procedure for each specific extended range flight, or by the maintenance crew no earlier than one hour prior to the flight crew boarding the aircraft for the purpose of flight.

(2) Revise the “Extended Range Operations” section of the Section 3 Normal Procedures of the existing AFM by incorporating the information specified in figure 2 to paragraph (g)(2) of this AD. This may be done by inserting a copy of this AD into the existing AFM. When a statement identical to that in figure 2 to paragraph (g)(2) of this AD has been included in the “Extended Range Operations” section of Section 3 Normal Procedures of the existing AFM, the general revisions may be inserted into the existing AFM, and the copy of this AD may be removed from the existing AFM.

Figure 2 to paragraph (g)(2) – Model 737 AFM Section 3 Revision

Extended Range Operations (Required by AD 2019-19-10)

Fuel Crossfeed Valve Operational Check

Unless accomplished by maintenance personnel as part of preparing the airplane for the specific ETOPS flight, do the following steps on the ground prior to engine start.

Crossfeed selector.....Open
Verify that the VALVE OPEN light illuminates bright, then dim

Crossfeed selector.....Closed
Verify that the VALVE OPEN light illuminates bright, then extinguishes

(h) AFM Revisions for Model 757 Airplanes Equipped With a Single Fuel Crossfeed Valve

For airplanes identified in paragraph (c)(2) of this AD having line numbers 1 through 518 inclusive, on which the actions specified in Boeing Service Bulletin 757-28-0029 (second fuel crossfeed valve installation) have not been done: Within 120 days after the effective date of this AD, do the actions specified in paragraphs (h)(1) and (2) of this AD. For Model 757 airplanes identified in this paragraph, if the actions specified in Boeing Service Bulletin 757-28-0029 have been done, the actions specified in this paragraph are no longer required for that airplane and the actions specified in paragraph (j) of this AD must be done before further flight after the actions specified in Boeing Service Bulletin 757-28-0029 have been performed.

(1) Revise the “Extended Range Operations” section of the Section 1 Certificate Limitations of the existing AFM by incorporating the information specified in figure 3 to paragraph (h)(1). This may be done by inserting a copy of this AD into the existing AFM. When a statement identical to that in figure 3 to paragraph (h)(1) of this AD has been included in the “Extended Range Operations” section of the Section 1 Certificate Limitations of the general revisions of the existing AFM, the general revisions may be inserted into the existing AFM, and the copy of this AD may be removed from the existing AFM.

Figure 3 to paragraph (h)(1) – Model 757 AFM Section 1 Revision

Fuel Crossfeed Valve Operational Check for Airplanes with a Single Crossfeed Valve
(Required by AD 2019-19-10)

Prior to each extended operations (ETOPS) flight, an operational check of the fuel crossfeed valve must be performed. This check must be performed by the flight crew prior to each ETOPS flight as part of the pre-flight procedure for each specific extended range flight, or by the maintenance crew no earlier than one hour prior to the flight crew boarding the airplane for the purpose of flight.

(2) Revise the “Extended Range Operations” section of Section 3 Normal Procedures of the existing AFM by incorporating the information specified in figure 4 to paragraph (h)(2) of this AD. This may be done by inserting a copy of this AD into the existing AFM. When a statement identical to that in figure 4 to paragraph (h)(2) of this AD has been included in the “Extended Range Operations” section of Section 3 Normal Procedures of the existing AFM, the general revisions may be inserted into the existing AFM, and the copy of this AD may be removed from the existing AFM.

Figure 4 to paragraph (h)(2) – Model 757 AFM Section 3 Revision**Fuel Crossfeed Valve Operational Check (Required by AD 2019-19-10)**

Unless accomplished by maintenance personnel as part of preparing the airplane for the specific ETOPS flight, do the following steps on the ground prior to engine start.

Crossfeed selector.....ON

Verify that the VALVE light illuminates, then extinguishes

Crossfeed selector.....OFF

Verify that the VALVE light illuminates, then extinguishes

If the VALVE light is inoperative, it is acceptable to have ground personnel verify by direct observation the opening and closing of the crossfeed valve during this procedure.

(i) AFM Revisions for Model 767 Airplanes Equipped With a Single Fuel Crossfeed Valve

For airplanes identified in paragraph (c)(3) of this AD having line numbers 1 through 430 inclusive on which the actions specified in Boeing Service Bulletin 767-28-0034 (second fuel crossfeed valve installation) have not been done as of the effective date of this AD: Within 120 days after the effective date of this AD, do the actions specified in paragraphs (i)(1) and (2) of this AD. For airplanes on which the actions specified in Boeing Service Bulletin 767-28-0034 have been done, the actions specified in this paragraph are no longer required for that airplane and the actions specified in paragraph (k) of this AD must be done before further flight.

(1) Revise the “Extended Range Operations” section of the Section 1 Certificate Limitations of the existing AFM by incorporating the information specified in figure 5 to paragraph (i)(1) of this AD. This may be done by inserting a copy of this AD into the existing AFM. When a statement identical to that in figure 5 to paragraph (i)(1) of this AD has been included in the “Extended Range Operations” section of the Section 1 Certificate Limitations of the general revisions of the existing AFM, the general revisions may be inserted into the existing AFM, and the copy of this AD may be removed from the existing AFM.

Figure 5 to paragraph (i)(1) – Model 767 AFM Section 1 Revision**Fuel Crossfeed Valve Operational Check for Airplanes with a Single Crossfeed Valve (Required by AD 2019-19-10)**

Prior to each extended operations (ETOPS) flight, an operational check of the fuel crossfeed valve must be performed. This check must be performed by the flight crew prior to each ETOPS flight as part of the pre-flight procedure for each specific extended range flight, or by the maintenance crew no earlier than one hour prior to the flight crew boarding the airplane for the purpose of flight.

(2) Revise the “Extended Range Operations” section of Section 3.1 Normal Procedures of the existing AFM by incorporating the information specified in figure 6 to paragraph (i)(2) of this AD. This may be done by inserting a copy of this AD into the existing AFM. When a statement identical to that in figure 6 to paragraph (i)(2) of this AD has been included in the “Extended Range Operations” section of Section 3.1 Normal Procedures of the existing AFM, the general revisions

may be inserted into the existing AFM, and the copy of this AD may be removed from the existing AFM.

Figure 6 to paragraph (i)(2) – Model 767 AFM Section 3.1 Revision

Fuel Crossfeed Valve Operational Check (Required by AD 2019-19-10)

Unless accomplished by maintenance personnel as part of preparing the airplane for the specific ETOPS flight, do the following steps on the ground prior to engine start.

Crossfeed selector.....ON
 Verify that the VALVE light illuminates, then extinguishes

Crossfeed selector.....OFF
 Verify that the VALVE light illuminates, then extinguishes

If the VALVE light is inoperative, it is acceptable to have ground personnel verify by direct observation the opening and closing of the crossfeed valve during this procedure.

(j) MEL Revisions for Model 757 Airplanes Equipped With Dual Fuel Crossfeed Valves

For airplanes identified in paragraph (c)(2) of this AD having line numbers 519 and subsequent; and for airplanes identified in paragraph (c)(2) of this AD having line numbers 1 through 518 inclusive, on which a second fuel crossfeed valve has been installed, as specified in Boeing Service Bulletin 757-28-0029: Within 120 days after the effective date of this AD, revise the operator's existing FAA-approved MEL by incorporating the information specified in figure 7 to paragraph (j) of this AD as a required operations procedure when dispatching for ETOPS operation with an inoperative fuel crossfeed valve. Specific alternative MEL wording to accomplish the actions specified in figure 7 to paragraph (j) of this AD can be approved by the operator's principal operations inspector (POI).

Figure 7 to paragraph (j) – Model 757 MEL Revision

Fuel Crossfeed Valve Operational Check (Required by AD 2019-19-10)

Unless accomplished by maintenance personnel as part of preparing the airplane for the specific ETOPS flight, do the following steps on the ground prior to engine start.

Crossfeed selector.....ON
 Verify that the VALVE light illuminates, then extinguishes

Crossfeed selector.....OFF
 Verify that the VALVE light illuminates, then extinguishes

If the VALVE light is inoperative, it is acceptable to have ground personnel verify by direct observation the opening and closing of the crossfeed valve during this procedure.

(k) MEL Revisions for Model 767 Airplanes Equipped With Dual Fuel Crossfeed Valves

For airplanes identified in paragraph (c)(3) of this AD having line numbers 431 and subsequent; and for airplanes identified in paragraph (c)(3) of this AD having line numbers 1 through 430 inclusive on which a second fuel crossfeed valve has been installed, as specified in Boeing Service Bulletin 767-28-0034: Within 120 days after the effective date of this AD, revise the operator's existing FAA-approved MEL by incorporating the information specified in figure 8 to paragraph (k) of this AD as a required operations procedure when dispatching for ETOPS operation with an inoperative fuel crossfeed valve. Specific alternative MEL wording to accomplish the actions specified in figure 8 to paragraph (k) of this AD can be approved by the operator's POI.

Figure 8 to paragraph (k) – Model 767 MEL Revision**Fuel Crossfeed Valve Operational Check (Required by AD 2019-19-10)**

Unless accomplished by maintenance personnel as part of preparing the airplane for the specific ETOPS flight, do the following steps on the ground prior to engine start.

Crossfeed selector.....ON

Verify that the VALVE light illuminates, then extinguishes

Crossfeed selector.....OFF

Verify that the VALVE light illuminates, then extinguishes

If the VALVE light is inoperative, it is acceptable to have ground personnel verify by direct observation the opening and closing of the crossfeed valve during this procedure.

(l) MEL Revisions for Model 777 Airplanes

For airplanes identified in paragraph (c)(4) of this AD: Within 120 days after the effective date of this AD, revise the operator's existing FAA-approved MEL by incorporating the information specified in figure 9 to paragraph (l) of this AD as a required operations procedure when dispatching for ETOPS operation with an inoperative fuel crossfeed valve. Specific alternative MEL wording to accomplish the actions specified in figure 9 to paragraph (l) of this AD can be approved by the operator's POI.

Figure 9 to paragraph (l) – Model 777 MEL Revision**Fuel Crossfeed Valve Operational Check (Required by AD 2019-19-10)**

Before each departure, perform the following fuel crossfeed valve check:

1. Position operative crossfeed valve on and verify associated FUEL CROSSFEED AFT or FWD advisory message does not display.
2. Position operative crossfeed valve off and verify associated FUEL CROSSFEED AFT or FWD advisory message does not display.

(m) MEL Revisions for Model 787 Airplanes

For airplanes identified in paragraph (c)(5) of this AD: Within 120 days after the effective date of this AD, revise the operator's existing FAA-approved MEL by incorporating the information specified in figure 10 to paragraph (m) of this AD into the MEL requirements for each of the inoperative items specified in paragraphs (m)(1) through (4) of this AD. Specific alternative MEL wording to accomplish the actions specified in figure 10 to paragraph (m) of this AD can be approved by the operator's POI.

- (1) 28-21-01-01 Pressure Refueling System, Main Tank Inboard Refuel Valve.
- (2) 28-22-06 Fuel Balance Switch.
- (3) 28-26-01 Defuel/Isolation Valves.
- (4) 28-41-01-01 Main Tank Fuel Quantity Indication Systems.

Figure 10 to paragraph (m) – Model 787 MEL Revision

(Required by AD 2019-19-10)

Before the first ETOPS departure after the (insert the name of the applicable dispatch relief item identified in paragraphs (m)(1) through (m)(4) of AD 2019-19-10) is determined to be inoperative, perform the following maintenance (M) procedure prior to flight. If the item remains inoperative, this maintenance procedure is not required on subsequent ETOPS departures if the crossfeed valve operated normally on the operations (O) pre-flight check.

MAINTENANCE (M)

Verify crossfeed valve operates normally.

1. Gain access to the crossfeed valve in the main gear wheel well.
2. Set Fuel Control Panel (P5) CROSSFEED switch to ON and visually confirm the valve drive moves from the closed (C) position to the open (O) position.
3. Set Fuel Control Panel (P5) CROSSFEED switch to OFF and visually confirm the valve drive moves from the open (O) position to closed (C) position.

Before each ETOPS flight conducted with this item inoperative, perform the following operational check as part of the pre-flight check of the airplane. This check may be performed by either the flight crew or ground crew.

OPERATIONS (O)

1. Prior to each flight, verify crossfeed valve operates normally.
 - A. Set Fuel Control Panel (P5) CROSSFEED switch to ON and after 15 seconds confirm FUEL CROSSFEED advisory message does not display.
 - B. Set Fuel Control Panel (P5) CROSSFEED switch to OFF and after 15 seconds confirm FUEL CROSSFEED advisory message does not display.
2. For fuel balancing, do the FUEL BALANCE SYS Non-Normal Checklist.

(n) AD 88-21-03 R1 AFM Limitation Removal

After the applicable AFM limitations specified in paragraphs (g)(1), (h)(1), and (i)(1) of this AD are incorporated into an airplane's existing AFM, operators may remove the AFM limitation required by AD 88-21-03 R1, for that airplane.

(o) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the

person identified in paragraph (p) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(p) Related Information

For more information about this AD, contact Jon Regimbal, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3557; email: Jon.Regimbal@faa.gov.

(q) Material Incorporated by Reference

None.

Issued in Des Moines, Washington, on October 3, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-26736 Filed 12-11-19; 8:45 am]



2019-22-02 The Boeing Company: Amendment 39-19781; Docket No. FAA-2019-0188; Product Identifier 2018-NM-174-AD.

(a) Effective Date

This AD is effective January 16, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by reports of uncommanded fore and aft movement of the Captain's and First Officer's seats. The FAA is issuing this AD to address uncommanded fore and aft movement of the Captain's and First Officer's seats. An uncommanded fore or aft seat movement during a critical part of a flight, such as takeoff or landing, could cause a flight control obstruction or unintended flight control input, which could result in the loss of the ability to control the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Horizontal Actuator Identifications, Detailed Inspection, and Repetitive Checks of Horizontal Movement System and On-Condition Actions

Except as specified in paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018.

(h) Seat Identification and On-Condition Actions

Within 36 months after the effective date of this AD, do an inspection of the nameplate on the Captain's and First Officer's seats for the part number, and serial number as applicable, and do all applicable on-condition actions, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-25-3644, Revision 1, dated July 17, 2018. A review of the airplane maintenance records may be used for the seat inspection if the part number and serial number can be conclusively determined from that review.

(i) Exception to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018, uses the phrase "the original issue date of this service bulletin," this AD requires using "the effective date of this AD."

(j) Terminating Action for Repetitive Actions for Certain Seats

Installation of a serviceable Captain's or First Officer's seat as specified in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018, terminates the repetitive actions required by paragraph (g) of this AD, for that seat only.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (i) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3569; email: Brandon.Lucero@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 747-25-3644, Revision 1, dated July 17, 2018.

(ii) Boeing Special Attention Service Bulletin 747-25-3653, Revision 1, dated October 19, 2018.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 20, 2019.

Dorr Anderson,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-22-09 The Boeing Company: Amendment 39-19788; Docket No. FAA-2019-0671; Product Identifier 2019-NM-080-AD.

(a) Effective Date

This AD is effective January 13, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787-8 airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin B787-81205-SB530070-00 RB, Issue 001, dated August 31, 2018.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of fatigue cracking in the lug root radius of a main landing gear (MLG) aft hanger link lug fitting. The FAA is issuing this AD to address fatigue cracking in the left and right side MLG aft hanger link lug fittings. This condition, if not addressed, could result in undetected fatigue cracks that can grow and weaken the primary structure such that it cannot sustain limit load, which could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin B787-81205-SB530070-00 RB, Issue 001, dated August 31, 2018, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin B787-81205-SB530070-00 RB, Issue 001, dated August 31, 2018.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin B787-81205-SB530070-00, Issue 001, dated August 31, 2018,

which is referred to in Boeing Alert Requirements Bulletin B787-81205-SB530070-00 RB, Issue 001, dated August 31, 2018.

(h) Exceptions to Service Information Specifications

Where Boeing Alert Requirements Bulletin B787-81205-SB530070-00 RB, Issue 001, dated August 31, 2018, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Greg Rutar, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3529; email: greg.rutar@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin B787-81205-SB530070-00 RB, Issue 001, dated August 31, 2018

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at

NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 12, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-03 Dassault Aviation: Amendment 39-19796; Docket No. FAA-2019-0697; Product Identifier 2019-NM-110-AD.

(a) Effective Date

This AD is effective January 13, 2020.

(b) Affected ADs

(1) This AD replaces AD 2014-16-27, Amendment 39-17951 (79 FR 51071, August 27, 2014) (“AD 2014-16-27”); and AD 2017-19-14, Amendment 39-19044 (82 FR 43674, September 19, 2017) (“AD 2017-19-14”).

(2) This AD affects AD 2010-26-05, Amendment 39-16544 (75 FR 79952, December 21, 2010) (“AD 2010-26-05”).

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 900EX airplanes, serial number (S/N) 97 and S/Ns 120 and higher, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before September 1, 2018.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address, among other things, fatigue cracking and damage in principal structural elements; such fatigue cracking and damage could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision of Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2017-19-14, with no changes. Within 90 days after October 24, 2017 (the effective date of AD 2017-19-14), revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5-40, Airworthiness Limitations, Revision 9, dated November 2015, of the Dassault Falcon 900EX EASy, Falcon 900LX, and Falcon 900DX Maintenance Manual. The initial compliance times for accomplishing the actions specified in Chapter 5-40, Airworthiness Limitations, Revision 9, dated

November 2015, of the Dassault Falcon 900EX EASy, Falcon 900LX, and Falcon 900DX Maintenance Manual, is within the applicable times specified in the maintenance manual or 90 days after October 24, 2017, whichever occurs later, except as provided by paragraphs (g)(1) through (4) of this AD.

(1) The term “LDG” in the “First Inspection” column of any table in the service information means total airplane landings.

(2) The term “FH” in the “First Inspection” column of any table in the service information means total flight hours.

(3) The term “FC” in the “First Inspection” column of any table in the service information means total flight cycles.

(4) The term “M” in the “First Inspection” column of any table in the service information means months.

(h) Retained Requirement for No Alternative Actions and Intervals, With New Exception

This paragraph restates the requirements specified in paragraph (h) of AD 2017-19-14, with a new exception. Except as required by paragraph (i) of this AD, after accomplishing the revision required by paragraph (g) of this AD, no alternative actions (inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (l)(1) of this AD.

(i) New Requirement of This AD: Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5-40, Airworthiness Limitations, Revision 11, dated September 2018, of the Dassault Falcon 900EX EASy, Falcon 900LX, and Falcon 900DX Maintenance Manual. The initial compliance times for accomplishing the actions are at the times specified in Chapter 5-40, Airworthiness Limitations, Revision 11, dated September 2018, of the Dassault Falcon 900EX EASy, Falcon 900LX, and Falcon 900DX Maintenance Manual, or 90 days after the effective date of this AD, whichever occurs later, except as provided by paragraphs (i)(1) through (4) of this AD.

(1) The term “LDG” in the “First Inspection” column of any table in the service information means total airplane landings.

(2) The term “FH” in the “First Inspection” column of any table in the service information means total flight hours.

(3) The term “FC” in the “First Inspection” column of any table in the service information means total flight cycles.

(4) The term “M” in the “First Inspection” column of any table in the service information means months since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

(j) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (l)(1) of this AD.

(k) Terminating Actions for Certain Actions in AD 2010-26-05

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates the requirements of paragraph (g)(1) of AD 2010-26-05, for Dassault Aviation Model 900EX airplanes, S/N 97 and S/Ns 120 and higher.

(l) Other FAA AD Provisions

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2019-0134, dated June 11, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0697.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on January 13, 2020.

(i) Chapter 5-40, Airworthiness Limitations, Revision 11, dated September 2018, of the Dassault Falcon 900EX EASy, Falcon 900LX, and Falcon 900DX Maintenance Manual.

(ii) [Reserved]

(4) The following service information was approved for IBR on October 24, 2017 (82 FR 43674, September 19, 2017).

(i) Chapter 5-40, Airworthiness Limitations, Revision 9, dated November 2015, of the Dassault Falcon 900EX EASy, Falcon 900LX, and Falcon 900DX Maintenance Manual.

(ii) [Reserved]

(5) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <https://www.dassaultfalcon.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 14, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-05 Dassault Aviation: Amendment 39-19799; Docket No. FAA-2019-0668; Product Identifier 2019-NM-108-AD.

(a) Effective Date

This AD is effective January 13, 2020.

(b) Affected ADs

(1) This AD replaces AD 2016-01-16, Amendment 39-18376 (81 FR 3320, January 21, 2016); AD 2017-19-03, Amendment 39-19033 (82 FR 43166, September 14, 2017); and AD 2018-19-05, Amendment 39-19405 (83 FR 47813, September 21, 2018) (“AD 2018-19-05”).

(2) This AD affects AD 2010-26-05, Amendment 39-16544 (75 FR 79952, December 21, 2010).

(c) Applicability

This AD applies to all Dassault Aviation Model MYSTERE-FALCON 900 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision of Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2018-19-05, with no changes. Within 90 days after October 26, 2018 (the effective date of AD 2018-19-05), revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5-40, Airworthiness Limitations, Revision 23, dated September 2017, of the Dassault Aviation Falcon 900 Maintenance Manual. The initial compliance times for doing the tasks are at the times specified in Chapter 5-40, Airworthiness Limitations, Revision 23, dated September 2017, of the Dassault Aviation Falcon 900 Maintenance Manual, or within 90 days after October 26, 2018, whichever occurs later. The term “LDG” in the “First Inspection” column of any table in the service information specified in this paragraph means total airplane landings. The term “FH” in the “First Inspection” column of any table in the service information specified in this paragraph means total

flight hours. The term “FC” in the “First Inspection” column of any table in the service information specified in this paragraph means total flight cycles. The term “M” in the “First Inspection” column of any table in the service information specified in this paragraph means months.

(h) Retained Requirement for No Alternative Actions or Intervals, With a New Exception

This paragraph restates the requirements of paragraph (h) of AD 2018-19-05, with a new exception. Except as required by paragraph (i) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (l)(1) of this AD.

(i) New Requirement of This AD: Revision of Existing Maintenance or Inspection Program

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5-40, Airworthiness Limitations, Revision 24, dated September 2018, of the Dassault Aviation Falcon 900 Maintenance Manual. The initial compliance times for doing the tasks are at the times specified in Chapter 5-40, Airworthiness Limitations, Revision 24, dated September 2018, of the Dassault Aviation Falcon 900 Maintenance Manual, or within 90 days after the effective date of this AD, whichever occurs later. The term “LDG” in the “First Inspection” column of any table in the service information specified in this paragraph means total airplane landings. The term “FH” in the “First Inspection” column of any table in the service information specified in this paragraph means total flight hours. The term “FC” in the “First Inspection” column of any table in the service information specified in this paragraph means total flight cycles. The term “M” in the “First Inspection” column of any table in the service information specified in this paragraph means months since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness. Doing the revision required by this paragraph terminates the actions required by paragraph (g) of this AD.

(j) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an AMOC in accordance with the procedures specified in paragraph (l)(1) of this AD.

(k) Terminating Actions for Certain Requirements in AD 2010-26-05

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates the requirements of paragraph (g)(1) of AD 2010-26-05, for Dassault Aviation Model MYSTERE-FALCON 900 airplanes.

(l) Other FAA AD Provisions

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in

paragraph (m)(2) of this AD. Information may be emailed to 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2018-19-05 are approved as AMOCs for the corresponding provisions of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2019-0132, dated June 11, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0668.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on January 13, 2020.

(i) Chapter 5-40, Airworthiness Limitations, Revision 24, dated September 2018, of the Dassault Aviation Falcon 900 Maintenance Manual.

(ii) [Reserved]

(4) The following service information was approved for IBR on October 26, 2018 (83 FR 47813, September 21, 2018).

(i) Chapter 5-40, Airworthiness Limitations, Revision 23, dated September 2017, of the Dassault Aviation Falcon 900 Maintenance Manual.

(ii) [Reserved]

(5) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <https://www.dassaultfalcon.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 15, 2019.

Dionne Palermo,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-06 The Boeing Company: Amendment 39-19800; Docket No. FAA-2019-0437; Product Identifier 2019-NM-074-AD.

(a) Effective Date

This AD is effective January 13, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 757-200, -200CB, and -300 series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks initiating in the fuselage frame web at body station (STA) 1640. The FAA is issuing this AD to address cracks initiating in the fuselage frame web at STA 1640, which, if not detected and corrected, could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For all airplanes except those identified in paragraphs (g)(2) through (4) of this AD: Except as specified by paragraph (h) of this AD, at the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

Note 1 to paragraphs (g)(1) through (4): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757-53A0112, dated November 16, 2018, which is referred to in Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

Note 2 to paragraphs (g)(1) through (4): Accomplishing certain repairs required by this AD might affect AD 2018-06-07, Amendment 39-19227 (83 FR 13398, March 29, 2018) (“AD 2018-06-07”), and necessitate requesting an alternative method of compliance (AMOC) to AD 2018-06-07.

(2) For airplanes on which Aviation Partners Boeing (APB) blended or scimitar blended winglets are installed in accordance with Supplemental Type Certificate (STC) ST01518SE: Except as specified by paragraph (h) of this AD, at the applicable times specified in paragraph 1.E., “Compliance” of APB Alert Service Bulletin AP757-53-002, Revision 3, dated August 14, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

(3) Except as specified by paragraph (h) of this AD: For Group 1 airplanes that have been converted from a passenger to freighter configuration using VT Mobile Aerospace Engineering (MAE) Inc. STC ST03562AT, at the applicable times specified for Group 2 airplanes in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018, do all applicable Group 2 actions, as identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

(4) Except as specified by paragraph (h) of this AD: For Group 4 airplanes that have been converted from a passenger to freighter configuration using VT MAE Inc. STC ST03562AT, at the applicable times specified for Group 5 airplanes in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018, do all applicable Group 5 actions as identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

(h) Exceptions to Service Information Specifications

(1) Where Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018, uses the phrase “the original issue date of Requirements Bulletin 757-53A0112 RB,” this AD requires using “the effective date of this AD,” except where Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018, uses the phrase “the original issue date of Requirements Bulletin 757-53A0112 RB” in a note or flag note.

(2) Where Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(3) Where Aviation Partners Boeing Alert Service Bulletin AP757-53-002, Revision 3, dated August 14, 2019, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD,” except where Aviation Partners Boeing Alert Service Bulletin AP757-53-002, Revision 3, dated August 14, 2019, uses the phrase “the original issue date of this Service Bulletin” in a note or flag note.

(4) Where Aviation Partners Boeing Alert Service Bulletin AP757-53-002, Revision 3, dated August 14, 2019, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g)(2) of this AD, if those actions were performed before the effective date of this AD using Aviation Partners Boeing Alert Service Bulletin AP757-53-002, Revision 2, dated April 11, 2019.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5234; fax: 562-627-5210; email: peter.jarzomb@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) through (5) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Aviation Partners Boeing Alert Service Bulletin AP757-53-002, Revision 3 dated August 14, 2019.

(ii) Boeing Alert Requirements Bulletin 757-53A0112 RB, dated November 16, 2018.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>.

(4) For Aviation Partners Boeing service information identified in this AD, contact Aviation Partners Boeing, 2811 South 102nd St., Suite 200, Seattle, WA 98168; phone: 206-830-7699; fax: 206-767-0535; email: leng@aviationpartners.com; internet: <http://www.aviationpartnersboeing.com>.

(5) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 18, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-07 The Boeing Company: Amendment 39-19801; Docket No. FAA-2019-0494; Product Identifier 2019-NM-051-AD.

(a) Effective Date

This AD is effective January 16, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787-8, 787-9, and 787-10 airplanes, certificated in any category, as identified in Boeing Requirements Bulletin B787-81205-SB320040-00 RB, Issue 001, dated March 12, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Unsafe Condition

This AD was prompted by reports that the nose landing gear (NLG) retracted on the ground, with weight on the airplane's wheels, due to the incorrect installation of an NLG downlock pin in the apex pin inner bore of the NLG lock link assembly. The FAA is issuing this AD to address the NLG downlock pin being incorrectly installed in the apex pin inner bore of the NLG lock link assembly, which could result in the NLG retracting on the ground, possibly causing serious injuries to personnel and passengers and substantial damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Requirements Bulletin B787-81205-SB320040-00 RB, Issue 001, dated March 12, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Requirements Bulletin B787-81205-SB320040-00 RB, Issue 001, dated March 12, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Service Bulletin B787-81205-SB320040-00, Issue 001, dated March 12, 2019,

which is referred to in Boeing Requirements Bulletin B787-81205-SB320040-00 RB, Issue 001, dated March 12, 2019.

(h) Exceptions to Service Information Specifications

For purposes of determining compliance with the requirements of this AD: Where Boeing Requirements Bulletin B787-81205-SB320040-00 RB, Issue 001, dated March 12, 2019, uses the phrase “the Issue 001 date of Requirements Bulletin B787-81205-SB320040-00 RB,” this AD requires using “the effective date of this AD.”

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Allen Rauschendorfer, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3528; email: allen.rauschendorfer@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Requirements Bulletin B787-81205-SB320040-00 RB, Issue 001, dated March 12, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at

NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on December 2, 2019.

John Piccola,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-11 Gulfstream Aerospace Corporation: Amendment 39-19805; Docket No. FAA-2019-0960; Product Identifier 2019-CE-049-AD.

(a) Effective Date

This AD is effective December 30, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Gulfstream Aerospace Corporation Model GVI airplanes, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by a report of an inflight rudder surface shutdown that resulted in sustained lateral-directional oscillations of the airplane. The FAA is issuing this AD to provide operating limitations and flight crew procedures in the event of an inflight loss of rudder or yaw damper. The unsafe condition, if not addressed, could result in catastrophic structural damage or loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revise the Airplane Flight Manual

Within 15 days after December 30, 2019 (the effective date of this AD), revise the airplane flight manual for your airplane by adding the applicable airplane flight manual supplement specified below:

(1) Gulfstream Aerospace G650 Airplane Flight Manual Supplement No. G650-2019-03, dated November 4, 2019; or

(2) Gulfstream Aerospace G650ER Airplane Flight Manual Supplement No. G650ER-2019-03, dated November 4, 2019.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Alex Armas, Aerospace Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5538; fax: (404) 474-5605; email: alex.armas@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Gulfstream Aerospace G650 Airplane Flight Manual Supplement No. G650-2019-03, dated November 4, 2019.

(ii) Gulfstream Aerospace G650ER Airplane Flight Manual Supplement No. G650ER-2019-03, dated November 4, 2019.

(3) For service information identified in this AD, contact Gulfstream Aerospace Corporation, Technical Publications Dept., P.O. Box 2206, Savannah, GA 31402-2206; telephone: (800) 810-4853; fax: (912) 965-3520; email: pubs@gulfstream.com; internet: <https://www.gulfstream.com/customer-support>.

(4) You may view this service information at FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 4, 2019.

Patrick R. Mullen,

Aircraft Certification Service, Manager, Small Airplane Standards Branch, AIR-690.

[FR Doc. 2019-26849 Filed 12-12-19; 8:45 am]

BILLING CODE 4910-13-P



2019-23-12 The Boeing Company: Amendment 39-19806; Docket No. FAA-2019-0440; Product Identifier 2019-NM-032-AD.

(a) Effective Date

This AD is effective January 13, 2020.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by fuel system reviews conducted by the manufacturer to ensure their fuel tank systems can prevent potential ignition sources. The FAA is issuing this AD to address potential ignition sources inside the fuel tank, which, in combination with flammable vapors, could result in a fuel tank fire or explosion, and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Apply Sealant, Replace Clamps, and Install Teflon Sleeving

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., “Compliance,” of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-57A1321, dated February 8, 2019, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 737-57A1321, dated February 8, 2019.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 737-57A1321, dated February 8, 2019, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Service Bulletin 737-57A1321, dated February 8, 2019, specifies contacting Boeing: This AD requires doing actions using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Serj Harutunian, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5254; fax: 562-627-5210; email: serj.harutunian@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-57A1321, dated February 8, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 18, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-13 Airbus SAS: Amendment 39-19807; Docket No. FAA-2019-0443; Product Identifier 2019-NM-056-AD.

(a) Effective Date

This AD is effective January 16, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A320-251N and A321-253N airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019-0068, dated March 27, 2019 (“EASA AD 2019-0068”).

(d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

(e) Reason

This AD was prompted by reports of cracks on the pylon block seals during the final assembly line. The FAA is issuing this AD to address cracks on pylon block seals, which could reduce the firewall integrity between the pylon and the nacelle.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0068.

(h) Exceptions to EASA AD 2019-0068

(1) Where EASA AD 2019-0068 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2019-0068 specifies credit for actions “accomplished before the effective date of this AD in accordance with the instructions of the applicable Airplane Maintenance Manual,” this AD provides credit for actions “accomplished before the effective date of this AD in accordance with the instructions of an FAA-approved maintenance or inspection program.”

(3) The “Remarks” section of EASA AD 2019-0068 does not apply to this AD.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2019-0068 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3223.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0068, dated March 27, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0068, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 6017; email: ADs@easa.europa.eu; Internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0443.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 21, 2019.

Dorr Anderson,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-14 The Boeing Company: Amendment 39-19808; Docket No. FAA-2019-0326; Product Identifier 2018-NM-166-AD.

(a) Effective Date

This AD is effective January 21, 2020.

(b) Affected ADs

This AD affects the ADs specified in paragraphs (b)(1) through (7) of this AD.

- (1) AD 2008-10-09 R1, Amendment 39-16148 (74 FR 69264, December 31, 2009) (“AD 2008-10-09 R1”).
- (2) AD 2011-12-09, Amendment 39-16716 (76 FR 33988, June 10, 2011) (“AD 2011-12-09”).
- (3) AD 2013-13-15, Amendment 39-17503 (78 FR 42415, July 16, 2013) (“AD 2013-13-15”).
- (4) AD 2013-25-05, Amendment 39-17701 (78 FR 78701, December 27, 2013) (“AD 2013-25-05”).
- (5) AD 2016-18-16, Amendment 39-18647 (81 FR 65864, September 26, 2016) (“AD 2016-18-16”).
- (6) AD 2017-17-09, Amendment 39-18999 (82 FR 40477, August 25, 2017) (“AD 2017-17-09”).
- (7) AD 2018-04-12, Amendment 39-19208 (83 FR 9178, March 5, 2018) (“AD 2018-04-12”).

(c) Applicability

This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel; 47, Nitrogen Generation System.

(e) Unsafe Condition

This AD was prompted by a determination that new or revised airworthiness limitations (AWLs) are necessary related to fuel tank ignition prevention and the nitrogen generation system. The FAA is issuing this AD to address the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

(1) For The Boeing Company Model 737-100, -200, and -200C series airplanes: Within 60 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Section C, including Subsections C.1, C.2, and C.3 of Boeing 737-100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D6-38278-CMR, dated March 2019, except as provided in paragraph (h) of this AD. The initial compliance time for the ALI tasks are within the applicable compliance times specified in paragraphs (g)(1)(i) through (x) of this AD.

(i) For AWL No. 28-AWL-01, “External Wires Over Center Fuel Tank”: Within 120 months after the most recent inspection was performed as specified in AWL No. 28-AWL-01, or within 12 months after the effective date of this AD if no initial inspection has been performed.

(ii) For AWL No. 28-AWL-03, “Fuel Quantity Indicating System (FQIS)–Out Tank Wiring Lightning Shield to Ground Termination”: Within 120 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1178, or within 120 months after the most recent inspection was performed as specified in AWL No. 28-AWL-03, whichever is later.

(iii) For AWL No. 28-AWL-21, “Center Tank Fuel Boost Pump Automatic Shutoff System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1228, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-21, whichever is later.

(iv) For AWL No. 28-AWL-22, “Auxiliary Tank Fuel Boost Pump Automatic Shutoff System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1228, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-22, whichever is later.

(v) For AWL No. 28-AWL-23, “Over-Current and Arcing Protection Electrical Design Features Operation–Boost Pump Ground Fault Interrupter (GFI)”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1212, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-23, whichever is later.

(vi) For AWL No. 28-AWL-24, “Center Tank Fuel Boost Pump Power Failed On Protection System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1227, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-24, whichever is later.

(vii) For AWL No. 28-AWL-25, “Auxiliary Fuel Tank Boost Pump Power Failed On Protection System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1227, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-25, whichever is later.

(viii) For AWL No. 28-AWL-29, “AC Fuel Boost Pump Installation”: Within 72 months after the most recent inspection was performed as specified in AWL No. 28-AWL-29, or within 12 months after the effective date of this AD if no inspection has been performed in the last 72 months.

(ix) For AWL No. 47-AWL-04, “Nitrogen Generation System (NGS)–Thermal Switch”: Within 22,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1005; within 22,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1008; or within 22,500 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-04; whichever is latest.

(x) For AWL No. 47-AWL-05, “Nitrogen Generation System (NGS)–Nitrogen Enriched Air (NEA) Distribution Ducting Integrity”: Within 14,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1005; within 14,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1008; or within 14,500 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-05; whichever is latest.

(2) For The Boeing Company Model 737-300, -400, and -500 series airplanes: Within 60 days after the effective date of this AD, revise the existing maintenance or inspection program, as

applicable, to incorporate the information specified in Section C, including Subsections C.1, C.2, and C.3 of Boeing 737-100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D6-38278-CMR, dated March 2019; except as provided in paragraph (h) of this AD. The initial compliance time for the ALI tasks are within the applicable compliance times specified in paragraphs (g)(2)(i) through (xi) of this AD.

(i) For AWL No. 28-AWL-01, “External Wires Over Center Fuel Tank”: Within 120 months after the most recent inspection was performed as specified in AWL No. 28-AWL-01, or within 12 months after the effective date of this AD if no initial inspection has been performed.

(ii) For AWL No. 28-AWL-03, “Fuel Quantity Indicating System (FQIS)–Out Tank Wiring Lightning Shield to Ground Termination”: Within 120 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1175; within 120 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1183; within 120 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1186; or within 120 months after the most recent inspection was performed as specified in AWL No. 28-AWL-03; whichever is latest.

(iii) For AWL No. 28-AWL-20, “Center Tank Fuel Boost Pump Automatic Shutoff System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1216, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-20, whichever is later.

(iv) For AWL No. 28-AWL-21, “Auxiliary Tank Fuel Boost Pump Automatic Shutoff System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1216, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-21, whichever is later.

(v) For AWL No. 28-AWL-22, “Over-Current and Arcing Protection Electrical Design Features Operation–Boost Pump Ground Fault Interrupter (GFI)”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1212, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-22, whichever is later.

(vi) For AWL No. 28-AWL-23, “Center Tank Fuel Boost Pump Power Failed On Protection System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1227, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-23, whichever is later.

(vii) For AWL No. 28-AWL-24, “Auxiliary Fuel Tank Boost Pump Power Failed On Protection System”: Within 12 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1227, or within 12 months after the most recent inspection was performed as specified in AWL No. 28-AWL-24, whichever is later.

(viii) For AWL No. 28-AWL-27, “AC Fuel Boost Pump Installation”: Within 72 months after the most recent inspection was performed as specified in AWL No. 28-AWL-27, or within 12 months after the effective date of this AD if no inspection has been performed in the last 72 months.

(ix) For AWL No. 28-AWL-31, “Cushion Clamps and Teflon Sleeving Installed on Out-of-Tank Wire Bundles Installed on Brackets that are Mounted Directly on the Fuel Tanks”: Within 144 months after accomplishment of the actions specified in Boeing Service Bulletin 737-28A1228.

(x) For AWL No. 47-AWL-04, “Nitrogen Generation System (NGS)–Thermal Switch”: Within 22,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1005; within 22,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1008; or within 22,500 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-04; whichever is latest.

(xi) For AWL No. 47-AWL-05, “Nitrogen Generation System (NGS)–Nitrogen Enriched Air (NEA) Distribution Ducting Integrity”: Within 14,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1005; within 14,500 flight hours after accomplishment of the actions specified in Boeing Service Bulletin 737-47-1008; or within 14,500 flight hours after the most recent inspection was performed as specified in AWL No. 47-AWL-05; whichever is latest.

(h) Additional Acceptable Wire Types and Sleeving

As an option to accomplishing the actions required by paragraph (g) of this AD, the changes specified in paragraphs (h)(1) and (2) of this AD are acceptable.

(1) Where AWL No. 28-AWL-05 identifies wire types BMS 13-48, BMS 13-58, and BMS 13-60, the following wire types are acceptable: MIL-W-22759/16, SAE AS22759/16 (M22759/16), MIL-W-22759/32, SAE AS22759/32 (M22759/32), MIL-W-22759/34, SAE AS22759/34 (M22759/34), MIL-W-22759/41, SAE AS22759/41 (M22759/41), MIL-W-22759/86, SAE AS22759/86 (M22759/86), MIL-W-22759/87, SAE AS22759/87 (M22759/87), MIL-W-22759/92, and SAE AS22759/92 (M22759/92); and MIL-C-27500 and NEMA WC 27500 cables constructed from these military or SAE specification wire types, as applicable.

(2) Where AWL No. 28-AWL-05 identifies TFE-2X Standard wall for wire sleeving, the following sleeving materials are acceptable: Roundit 2000NX and Varglas Type HO, HP, or HM.

(i) No Alternative Actions, Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k) of this AD.

(j) Terminating Actions for Certain AD Requirements

Accomplishment of the revision required by paragraph (g) of this AD terminates the requirements specified in paragraphs (j)(1) through (7) of this AD for that airplane:

- (1) All requirements of AD 2008-10-09 R1.
- (2) The revision required by paragraph (l) of AD 2011-12-09.
- (3) The revision required by paragraph (h) of AD 2013-13-15.
- (4) The revision required by paragraph (j) of AD 2013-25-05.
- (5) The revisions required by paragraphs (l) and (n) of AD 2016-18-16.
- (6) The revision required by paragraph (h) of AD 2017-17-09.
- (7) The revision required by paragraph (h) of AD 2018-04-12.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs that were previously approved for the ADs specified in paragraph (j) of this AD are not approved as AMOCs for this AD.

(l) Related Information

For more information about this AD, contact Serj Harutunian, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5254; fax: 562-627-5210; email: serj.harutunian@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing 737-100/200/200C/300/400/500 Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D6-38278-CMR, dated March 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; phone: 562-797-1717; internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 20, 2019.

Dorr Anderson,
Acting Director, System Oversight Division,
Aircraft Certification Service.



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2019-23-15 Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39-19809; Docket No. FAA-2019-0584; Product Identifier 2019-NM-096-AD.

(a) Effective Date

This AD is effective January 16, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD-500-1A10 and BD-500-1A11 airplanes, certificated in any category, identified in paragraphs (c)(1) and (2) of this AD.

(1) Model BD-500-1A10 airplanes, serial numbers 50001 and subsequent with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 6, 2019.

(2) Model BD-500-1A11 airplanes, serial numbers 55001 and subsequent with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 6, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to prevent reduced structural integrity of the airplane or reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Bombardier C Series Airworthiness Limitations, BD500-3AB48-11400-02, Issue 009.00, dated June 6, 2019. The initial compliance time for doing the tasks is at the time specified in Bombardier C Series Airworthiness

Limitations, BD500-3AB48-11400-02, Issue 009.00, dated June 6, 2019, or within 90 days after the effective date of this AD, whichever occurs later.

(h) No Alternative Actions, Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Airbus Canada Limited Partnership's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-14R1, dated September 11, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0584.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7330; fax: 516-794-5531; email: 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier C Series Airworthiness Limitations, BD500-3AB48-11400-02, Issue 009.00, dated June 6, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; phone: 514-855-5000; fax: 514-855-7401; email: thd.crj@aero.bombardier.com; internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 26, 2019.

Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-17 Dassault Aviation: Amendment 39-19811; Docket No. FAA-2019-0973; Product Identifier 2019-NM-187-AD.

(a) Effective Date

This AD becomes effective December 27, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 900EX and Model FALCON 2000EX airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019-0273, dated November 4, 2019 (“EASA AD 2019-0273”).

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by reports of iced angle-of-attack (AoA) probes after take-off, with associated misleading airspeed indication and/or misleading stall warning. A slow or late positioning of thrust levers into the take-off position in certain conditions can lead to probes being heated too late during the take-off run, which increases the risk of icing on probes after take-off. The FAA is issuing this AD to address this condition, which could result in blocked AoA probes, possibly resulting in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0273.

(h) Exceptions to EASA AD 2019-0273

(1) Where EASA AD 2019-0273 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0273 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0273, dated November 4, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0273, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0973.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 21, 2019.

Dorr Anderson,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-23-18 Dassault Aviation: Amendment 39-19812; Docket No. FAA-2019-0604; Product Identifier 2019-NM-072-AD.

(a) Effective Date

This AD is effective January 17, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Dassault Aviation Model MYSTERE FALCON 50, MYSTERE FALCON 900, and FALCON 900EX airplanes; and Model FALCON 2000 and FALCON 2000EX airplanes; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire protection.

(e) Reason

This AD was prompted by a report that the Dassault maintenance planning document (MPD) of the related Dassault aircraft maintenance manual (AMM) mentions that the “combined service/storage life” of the fire extinguisher percussion cartridges is 12 years, whereas it should be 10 years, and could have a safety impact in case of fire. The FAA is issuing this AD to address the total life limit of the fire extinguisher percussion cartridges, which if not corrected, could prevent extinguishing a fire and possibly result in damage to the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purpose of this AD, the definitions specified in paragraphs (g)(1) through (4) apply to this AD.

(1) An affected part is a fire extinguisher percussion cartridge having part number (P/N) 862700-00 or P/N 862710-00.

(2) Total life is time since the manufacturing date, which includes both the time installed on an airplane and time in storage.

(3) A serviceable part is an affected part that has not exceeded 10 years of total life, or a fire extinguisher percussion cartridge that is not an affected part.

(4) Group 1 airplanes are those that have an affected part installed. Group 2 airplanes are those that do not have an affected part installed.

(h) Total Life Limit Implementation

For Group 1 airplanes, except as specified in paragraph (j) of this AD: Before a fire extinguisher percussion cartridge exceeds 10 years of total life, remove the affected part and replace it with a serviceable part in accordance with the procedures specified in paragraph (l)(2) of this AD.

(i) Guidance for Replacement Required by Paragraph (h) of This AD

Guidance for the replacement required by paragraph (h) of this AD can be found in the applicable Dassault AMM task specified in figure 1 to paragraph (i) of this AD.

Figure 1 to Paragraph (i)–AMM Tasks

Airplane model	Location	AMM task
MYSTERE FALCON 50 airplanes	Engine 1 first shoot	26-20-13-960-801-01
	Engine 2 first shoot	26-20-13-960-801-02
	Engine 3 first shoot	26-20-13-960-801-03
	Engine 1 second shoot	26-20-13-960-801-04
	Engine 2 second shoot	26-20-13-960-801-05
	Engine 3 second shoot	26-20-13-960-801-06
FALCON 2000 and FALCON 2000EX airplanes	Engine 1 first shoot	26-20-13-960-801-01
	Engine 1 second shoot	26-20-13-960-801-02
	Engine 2 second shoot	26-20-13-960-801-03
	Engine 2 first shoot	26-20-13-960-801-04
	Auxiliary Power Unit (APU)	26-20-13-960-801-05
MYSTERE FALCON 900 and FALCON 900EX airplanes	Engine 1 first shoot	26-20-13-960-801-01
	Engine 3 first shoot	26-20-13-960-801-02
	Engine 2 second shoot left-hand side	26-20-13-960-801-03
	Engine 2 second shoot right-hand side	26-20-13-960-801-04
	Engine 1 second shoot	26-20-13-960-801-05
	Engine 3 second shoot	26-20-13-960-801-06
	Engine 2 first shoot left-hand side	26-20-13-960-801-07
	Engine 2 first shoot right-hand side	26-20-13-960-801-08
	APU	26-20-13-960-801-09
	Baggage compartment	26-20-13-960-801-10
	Mechanic's Servicing Compartment	26-20-13-960-801-11

(j) Grace Period for Initial Replacement

For Group 1 airplanes: For a fire extinguisher percussion cartridge that, on the effective date of this AD, has a total life of 9 years 6 months or more, the replacement required by paragraph (h) of this AD can be deferred up to 6 months after the effective date of this AD.

(k) Parts Installation Limitations

For Group 1 and Group 2 airplanes: As of the effective date of this AD, no person may install, on any airplane, a fire extinguisher percussion cartridge, unless the part is a serviceable part as specified in this AD, and that, following installation, the affected part is replaced as required by paragraph (h) of this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2019-0084, dated April 17, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0604.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(3) For service information identified in this AD that is not incorporated by reference, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(n) Material Incorporated by Reference

None.

Issued in Des Moines, Washington, on November 27, 2019.
Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2019-24-10 Airbus SAS: Amendment 39-19813; Docket No. FAA-2019-0704;
Product Identifier 2019-NM-132-AD.

(a) Effective Date

This AD is effective January 24, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A350-941 airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019-0183, dated July 26, 2019 (“EASA AD 2019-0183”).

(d) Subject

Air Transport Association (ATA) of America Code 92, Electric and electronic common installation.

(e) Reason

This AD was prompted by an investigation that identified the cargo lining gutter assembly would be unable to drain a certain quantity of water in case of leakage or rupture of certain water pipes. The FAA is issuing this AD to address this condition, which, if not corrected, could lead to fluid contamination of certain electrical equipment and connectors, possibly resulting in the loss of several flight control functions, with consequent reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0183.

(h) Exception to EASA AD 2019-0183

The “Remarks” section of EASA AD 2019-0183 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019-0183 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0183, dated July 26, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0183, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0704.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 27, 2019.
Michael Kaszycki,
Acting Director, System Oversight Division, Aircraft Certification Service.
[FR Doc. 2019-27468 Filed 12-19-19; 8:45 am]



2019-24-11 Dassault Aviation: Amendment 39-19814; Docket No. FAA-2019-0698; Product Identifier 2019-NM-109-AD.

(a) Effective Date

This AD is effective January 24, 2020.

(b) Affected ADs

(1) This AD replaces AD 2014-16-26, Amendment 39-17950 (79 FR 51077, August 27, 2014) (“AD 2014-16-26”); and AD 2017-19-04, Amendment 39-19034 (82 FR 43163, September 14, 2017) (“AD 2017-19-04”).

(2) This AD affects AD 2010-26-05, Amendment 39-16544 (75 FR 79952, December 21, 2010) (“AD 2010-26-05”).

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 900EX airplanes, certificated in any category, serial numbers 1 through 96 inclusive, and serial numbers 98 through 119 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision of Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2017-19-04, with no changes. Within 90 days after October 19, 2017 (the effective date of AD 2017-19-04), revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5-40, Airworthiness Limitations, Revision 14, dated November 2015, of the FALCON 900EX Maintenance Manual. The initial compliance time for accomplishing the actions specified in Chapter 5-40, Airworthiness Limitations, Revision 14, dated November 2015, of the FALCON 900EX Maintenance Manual, is within the applicable times specified in the maintenance manual, or 90 days after October 19, 2017, whichever occurs later, except as provided by paragraphs (g)(1) through (4) of this AD.

(1) The term “LDG” in the “First Inspection” column of any table in the service information means total airplane landings.

(2) The term “FH” in the “First Inspection” column of any table in the service information means total flight hours.

(3) The term “FC” in the “First Inspection” column of any table in the service information means total flight cycles.

(4) The term “M” in the “First Inspection” column of any table in the service information means months.

(h) Retained Requirement for No Alternative Actions and Intervals, With New Exception

This paragraph restates the requirement specified in paragraph (h) of AD 2017-19-04, with a new exception. Except as required by paragraph (i) of this AD, after accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (l)(1) of this AD.

(i) New Requirement of This AD: Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5-40, Airworthiness Limitations, Revision 16, dated September 2018, of the Dassault FALCON 900EX Maintenance Manual. The initial compliance times for accomplishing the actions are at the times specified in Chapter 5-40, Airworthiness Limitations, Revision 16, dated September 2018, or 90 days after the effective date of this AD, whichever occurs later, except as provided by paragraphs (i)(1) through (4) of this AD.

(1) The term “LDG” in the “First Inspection” column of any table in the service information means total airplane landings.

(2) The term “FH” in the “First Inspection” column of any table in the service information means total flight hours.

(3) The term “FC” in the “First Inspection” column of any table in the service information means total flight cycles.

(4) The term “M” in the “First Inspection” column of any table in the service information means months since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

(j) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (l)(1) of this AD.

(k) Terminating Actions for Certain Actions in AD 2010-26-05

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates the requirements of paragraph (g)(1) of AD 2010-26-05, for Dassault Aviation Model FALCON 900EX airplanes, serial numbers 1 through 96 inclusive, and serial numbers 98 through 119 inclusive.

(l) Other FAA AD Provisions

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2019-0133, dated June 11, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0698.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on January 24, 2020.

(i) Chapter 5-40, Airworthiness Limitations, Revision 16, dated September 2018, of the Dassault FALCON 900EX Maintenance Manual.

(ii) [Reserved]

(4) The following service information was approved for IBR on October 19, 2017 (82 FR 43163, September 14, 2017).

(i) Chapter 5-40, Airworthiness Limitations, Revision 14, dated November 2015, of the FALCON 900EX Maintenance Manual.

(ii) [Reserved]

(5) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <https://www.dassaultfalcon.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 27, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-27467 Filed 12-19-19; 8:45 am]



2019-24-17 The Boeing Company: Amendment 39-21006; Docket No. FAA-2019-0406; Product Identifier 2019-NM-059-AD.

(a) Effective Date

This AD is effective January 24, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model MD-90-30 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports indicating that certain center wing stringers and skins are potentially susceptible to cracking. The FAA is issuing this AD to address cracking of the center wing stringers and skins, which could result in the inability of the structure to sustain limit loads, and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-57A031, dated March 19, 2019, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin MD90-57A031, dated March 19, 2019.

Note 1 to paragraph (g) of this AD: Boeing Alert Service Bulletin MD90-57A031, dated March 19, 2019, refers to Boeing Drawing SN09570007, as data supplied with this service bulletin. If the pages of Boeing Drawing SN09570007 are illegible, guidance can be found in Boeing Multi Operator Message MOM-MOM-19-0549-01B, dated October 4, 2019.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin MD90-57A031, dated March 19, 2019, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Service Bulletin MD90-57A031, dated March 19, 2019, specifies contacting Boeing for repair instructions and doing the repair: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

(1) For more information about this AD, contact David Truong, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5224; fax: 562-627-5210; email: david.truong@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD90-57A031, dated March 19, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740 5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on December 4, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-27465 Filed 12-19-19; 8:45 am]



DATE: December 13, 2019

AD #: 2019-25-55

Emergency Airworthiness Directive (AD) 2019-25-55 is sent to owners and operators of The Boeing Company Model 737-300, -400, and -700 series airplanes, certificated in any category, modified to a Bedek Division Special Freighter (BDSF) by supplemental type certificate (STC) ST01566LA, ST01961SE, or ST02556SE, with a 9G rigid barrier.

Background

This emergency AD was prompted by a review of the manufacturing process for the 9G rigid barrier installed on BDSF conversions that identified a manufacturing non-compliance. It has been found that the surface preparation before bonding was improperly done, which can affect the 9G rigid barrier's strength characteristics. This condition, if not addressed, could result in the potential failure of the 9G rigid barrier under certain emergency landing loads, which could injure occupants.

The Civil Aviation Authority of Israel (CAAI), which is the aviation authority for Israel, has issued Israeli AD ISR-I-53-2019-12-6, dated December 12, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for The Boeing Company Model 737-300, -400, and -700 series airplanes, modified to a BDSF by STC ST01566LA, ST01961SE, or ST02556SE, with a 9G rigid barrier.

Relevant Service Information

The FAA reviewed Israel Aerospace Industries Service Bulletin 365-00-054, dated December 2019. This service information describes loading restrictions and methods that include reducing the cargo weights for each loading configuration and using additional straps when necessary to address 9G rigid barrier manufacturing non-compliance.

FAA's Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. Due to the need to correct an urgent safety of flight situation, good cause exists to make this AD effective in less than 30 days.

AD Requirements

This AD requires complying with the loading restrictions and methods specified in the service information described previously, except as discussed under "Differences Between this AD and the Service Information."

Differences Between This AD and the Service Information

Where Israel Aerospace Industries Service Bulletin 365-00-054, dated December 2019, specifies using cargo restraint straps rated at a minimum of 7,500 pounds, this AD requires using technical standard order TSO-C172 cargo restraint straps; that TSO specifies a load rating of 5,000 pounds. This exception corrects the Israel Aerospace Industries service bulletin's reference to a TSO-C172 cargo strap load rating of 7,500 pounds; the cargo strap load capability specified in the TSO is 5,000 pounds.

This AD specifies that the provisions for restraining cargo directly to a pallet or the airplane as provided in the existing airplane flight manual (AFM) (reference section 1-68-XX of the Israel Aerospace Industries Weight and Balance Manual (WBM)) can only be used if that cargo and all cargo aft of that location are restrained to a forward load factor of 9G. This exception corrects an omission in the Israel Aerospace Industries' service bulletin.

Interim Action

The FAA considers this AD interim action.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Presentation of the Actual AD

The FAA is issuing this AD under 49 U.S.C. Section 44701 according to the authority delegated to me by the Administrator.

2019-25-55 The Boeing Company: Product Identifier 2019-NM-201-AD.

(a) Effective Date

This Emergency Airworthiness Directive (AD) is effective upon receipt.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-300, -400, and -700 series airplanes, certificated in any category, modified to a Bedek Division Special Freighter (BDSF) by supplemental type certificate (STC) ST01566LA, ST01961SE, or ST02556SE, with a 9G rigid barrier.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by a review of the manufacturing process for the 9G rigid barrier installed on BDSF conversions that identified a manufacturing non-compliance. It has been found that the surface preparation before bonding was improperly done, which can affect the 9G rigid barrier's strength characteristics. The FAA is issuing this AD to address potential failure of the 9G rigid barrier under certain emergency landing loads, which could injure occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Loading Restrictions and Methods

- Before further flight, comply with the loading restrictions and methods specified in the Accomplishment Instructions of Israel Aerospace Industries Service Bulletin 365-00-054, dated December 2019, except as specified in paragraph (h) of this AD. The loading restrictions include reducing the cargo weights for each loading configuration and using additional straps as applicable.

(h) Exceptions to Service Information

(1) Where Israel Aerospace Industries Service Bulletin 365-00-054, dated December 2019, specifies using cargo restraint straps rated at a minimum of 7,500 pounds, for this AD use technical standard order TSO-C172 cargo restraint straps; that TSO specifies a load rating of 5,000 pounds.

(2) The provisions for restraining cargo directly to a pallet or the airplane as provided in the existing airplane flight manual (AFM) can only be used if that cargo and all cargo aft of that location are restrained to a forward load factor of 9G.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Israeli AD ISR-I-53-2019-12-6, dated December 12, 2019, for related information.

(2) For further information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3523; email: eric.lin@faa.gov.

(3) For service information referenced in this AD, contact Israel Aerospace Industries, LTD., Ben-Gurion International Airport, 70100 Israel; telephone 972-3-935-3090; email aviation_group@iai.co.il; Internet <https://www.iai.co.il/about/groups/aviation-group>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on December 13, 2019.

Original signed by
Jeffrey E. Duven,
Director,
System Oversight Division,
Aircraft Certification Service.