

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2013-19

9/9/2013 - 9/22/2013



Federal Aviation Administration
Engineering Procedures Office, AIR-110
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes

Biweekly 2013-01

2012-26-07		Eurocopter France	AS350BA helicopters
2012-26-09		Burkhart GROB Luft-und Raumfahrt GmbH	GROB G 109 and GROB G 109B sailplanes
2012-26-10		Eurocopter France	SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, EC155B1, SA-366G1, SA-365C, SA-365C1, and SA-365C2 helicopters
2012-26-11		Bell Helicopter Textron Inc	205A, 205A-1, and 205B helicopters
2012-26-12		Thielert Aircraft Engines	TAE 125-02-99 and TAE 125-02-114 reciprocating engines
2012-26-13	S 2011-07-09	Thielert Aircraft Engines GmbH	TAE 125-01, TAE 125-02-99, and TAE 125-02-114 reciprocating engines
2012-26-15		Honeywell International Inc	See AD
2012-27-02		Turbomeca S.A.	ARRIEL 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S, and 1S1 turboshaft engines

Biweekly 2013-02

2012-17-08		Bell Helicopter Textron Inc	204B, 205A, 205A-1, 205B, and 212 helicopters
2012-24-09	COR	Lycoming Engines and Continental Motors, Inc.	TIO-540-AK1A, TSIO-360-MB, TSIO-360-SB, and TSIO-360-RB reciprocating engines
2013-01-06		Pilatus Aircraft Ltd	PC-7
2013-02-01		Bell Helicopter Textron Inc	206L, 206L-1, and 206L-3 helicopters, and Model 206L-4 helicopters

Biweekly 2013-03

2013-01-04		Bell Helicopter Textron, Inc	412 and 412EP helicopters
2013-01-05		Eurocopter France	AS350B3 and EC130B4 helicopters
2013-01-07		Turbomeca S.A.	Arriel 2D turboshaft engines
2013-02-13		Piper Aircraft, Inc	PA-28-236, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28R-201, PA-28-235, PA-28R-201T, PA-28S-160, PA-28S-180, PA-28R-180, PA-28R-200, PA-28RT-201, PA-28RT-201T, PA-32-260, PA-32-301, PA-32-301T, PA-32-300, PA-32R-300, PA-32R-301T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32RT-300, PA-32RT-300T, PA-32S-300, PA-32-301FT, PA-32-301XTC, PA-34-200, PA-34-200T, PA-34-220T, PA-44-180, and PA-44-180T
2013-03-03		MD Helicopters, Inc.	500N, 600N, and MD900 helicopters

Biweekly 2013-04

2012-26-16	S 2009-14-13	Pilatus Aircraft Ltd.	PC-12, PC-12/45, PC-12/47, and PC-12/47E
2013-03-01	S 2010-20-18	Pacific Aerospace Limited	FU24-954 and FU24A-954
2013-03-02	S 2012-19-09	Eurocopter France	EC 155B, EC155B1, SA-365N1, AS-365N2 AS 365 N, and AS 365 N3 helicopters
2013-03-04		Sikorsky Aircraft Corporation	269D and Model 269D
2013-03-09		DG Flugzeugbau GmbH	DG-1000T gliders
2013-03-10		Lindstrand Hot Air Balloons Ltd	Appliance: Female ACME threaded hose connectors
2013-03-14		Pratt & Whitney Canada Corp.	PT6C-67C turboshaft engines
2013-03-15		Cessna Aircraft Company	172R and 172S
2013-03-16	S 2011-08-01	Bell Helicopter Textron	204B, 205A, 205A-1, 205B, 210 and 212 helicopters
2013-03-21		Pratt & Whitney Canada Corp.	PW206B, PW206B2, PW206C, PW207C, PW207D, PW207D1, PW207D2, and PW207E turboshaft engines
2013-04-02		Reims Aviation S.A.	F406

Biweekly 2013-05

2013-04-06		Eurocopter France	AS332C, AS332L, and AS332L1 helicopters
2013-04-08		Diamond Aircraft Industries GmbH	H-36, HK 36 R, HK 36 TS, and HK 36 TTS
2013-04-09		Costruzioni Aeronautiche Tecnam srl	P2006T
2013-05-01	S 2011-24-08	Turbomeca S.A.	Makila 1A2 turboshaft engines

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes

Biweekly 2013-06

2012-26-06	S 97-10-15	Erickson Air-Crane Incorporated	S-64F helicopters
2013-04-06		Eurocopter France	AS332C, AS332L, and AS332L1 helicopters
2013-05-14		Bell Helicopter Textron, Inc.	412 and 412EP helicopters
2013-05-17		Sikorsky Aircraft Corporation	S-61A, D, E, L, N, NM, R, and V helicopters
2013-05-23		Eurocopter France	AS332C, L, and L1 helicopters
2013-06-02		Diamond Aircraft Industries GmbH	DA 42 M-NG and DA 42 NG

Biweekly 2013-07

2004-21-08 R1		Cessna Aircraft Company	190, 195 (L-126A,B,C), 195A, and 195B
2008-07-11 R1		Pilatus Aircraft Ltd.	PC-12, PC-12/45, and PC-12/47
2013-03-10		Lindstrand Hot Air Balloons Ltd	Appliance: female ACME threaded hose connectors
2013-05-15		Robinson Helicopter Company	R44 and R44 II helicopters
2013-05-16		MD Helicopters, Inc.	369D, E, F, and FF helicopters
2013-05-21		Eurocopter France	EC130 B4 helicopters
2013-05-22		Agusta S.p.A.	A109, A109A, A109A II, A109C, A109K2, A109E, A109S, and A119 helicopters
2013-06-04		Reims Aviation S.A.	F406
2013-06-07		Eurocopter France	SA-365N1, AS-365N2, and AS 365 N3 helicopters
2013-06-51		See AD	See Ad

Biweekly 2013-08

2013-07-01		Diamond Aircraft Industries GmbH	DA 42, DA 42 M-NG, and DA 42 NG
2013-07-05		Eurocopter France	EC130B4 helicopters
2013-07-06		Eurocopter France	AS332C, AS332L, AS332L1, AS332L2, and EC225LP helicopters
2013-07-12		BRP Powertrain GmbH & Co KG Rotax	912 F2; 912 F3, 912 F4, 912 S2; 912 S3, 912 S4, 914 F2; 914 F3; and 914 F4 engines
2013-08-04		Grob-Werke	G115EG
2013-08-06		Bell Helicopter Textron Canada	430 helicopters
2013-08-07		Eurocopter France	AS332C, L, and L1 helicopters

Biweekly 2013-09

2004-21-08 R1		Cessna Aircraft Company	190, 195 (L-126A,B,C), 195A, and 195B
2012-25-01		Eurocopter France	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters
2012-25-04		Eurocopter France	AS350B3 helicopters
2013-03-18		Eurocopter Deutschland GmbH	MBB-BK 117 C-2 helicopters
2013-08-05		Cessna Aircraft Company	525
2013-08-17		Eurocopter France	SA-365N, SA-365N1, AS-365N2, AS 365 N3, and SA-366G1 helicopters
2013-08-19		Eurocopter France	AS350B, BA, B1, B2, B3, C, D, D1, AS355E, F, F1, F2, and N helicopters
2013-08-21		Diamond Aircraft Industries GmbH	DA 40 NG
2013-08-22		Turbomeca S.A.	1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S, and 1S1 turboshaft engines

Biweekly 2013-10

2013-04-08 R1		Diamond Aircraft Industries GmbH	HK 36 R, HK 36 TS, and HK 36 TTS powered gliders
2013-08-14	S 2005-12-02	Revo, Incorporated	COLONIAL C-1, COLONIAL C-2, LAKE LA-4, LAKE LA-4A, LAKE LA-4P, and LAKE LA-4-200
2013-09-05		Twin Commander Aircraft LLC	690, 690A, and 690B
2013-09-06		Agusta	A119 and AW119 MKII helicopters
2013-09-09	S 98-22-15	Slingsby Sailplanes Ltd.	Dart T.51, Dart T.51/17, and Dart T.51/17R sailplanes
2013-10-01		Spectrolab Nightsun XP Searchlight	Appliance: See AD
2013-10-51	E	Eurocopter France	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes

Biweekly 2013-11

2013-10-05		Eurocopter Deutschland GmbH	MBB-BK 117 C-2 helicopters
2013-11-02		Aircraft Industries a.s.	L-420
2013-11-09	S 2001-08-14R1	Turbomeca S.A.	Arrius 2B1 and 2F turboshaft engines

Biweekly 2013-12

2013-10-04	S 82-16-05 R1	Piper Aircraft, Inc.	PA-31, PA-31-325, and PA-31-350
2013-11-01		Iniziativa Industriali Italiane S.p.A.	Sky Arrow 650 TC, Sky Arrow 650 TCN, Sky Arrow 650TCS, and Sky Arrow 650TCNS
2013-11-05		Bell	214B, 214B-1, and 214ST helicopters
2013-11-13		Rolls-Royce plc	Viper Mk. 601-22 turbojet engines

Biweekly 2013-13

2013-06-51		Goodrich	Appliance: See AD
2013-11-08	S 2011-01-14	Pilatus Aircraft Ltd.	PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2
2013-11-10		Cessna Aircraft Company	LC40-550FG, LC41-550FG, and LC42-550FG
2013-11-11	S 2000-04-01	Cessna Aircraft Company	172R, 172S, 182S, 182T, T182T, 206H and T206H
2013-11-15		Eurocopter Deutschland GmbH	BO-105A, BO-105C, BO-105S, BO-105LS A-1, BO 105 LS A-3, EC135 P1, EC135 P2, EC135 P2+, EC135 T1, EC135 T2, EC135 T2+, MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, and MBB-BK117 C-1, MBB-BK117 C-2 helicopters
2013-12-04		Eurocopter France	EC 155B, EC155B1, SA-366G1, SA-365N, SA-365N1, AS-365N2, and AS 365 N3 helicopters
2013-12-07		Bell Helicopter Textron Canada	407 helicopters
2013-13-02		B-N Group Ltd.	BN-2, BN-2A, BN2A MK. III, BN2A MK. III-2, BN2A MK. III-3, BN-2A-2, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, and BN-2T-4R

Biweekly 2013-14

2012-23-13	COR	Sikorsky Aircraft Corporation	S-70, S-70A, and S-70C helicopters
2013-12-06		Eurocopter Deutschland	MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, and MBB-BK 117 C-2 helicopters
2013-13-01		Piper Aircraft, Inc.	PA-46-310P (Malibu), PA-46-350P (Mirage), PA-46R-350T (Matrix), and PA-46-500TP (Meridian)
2013-13-10		Pilatus Aircraft Ltd.	PC-7
2013-13-14		See AD	See AD

Biweekly 2013-15

2013-10-51		Eurocopter France	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters
2013-12-05		Eurocopter Deutschland GmbH	MBB-BK 117 C-2 helicopters
2013-14-01		Pilatus Aircraft Ltd.	PC-6/B2-H4
2013-14-08		Austro Engine GmbH	E4 engines
2013-15-03		Eurocopter France	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D and AS350D1 helicopters
2013-15-04		Hartzell Propeller, Inc.	HC-(1,D)2(X,V,MV)20-7, HC-(1,D)2(X,V,MV)20-8, and HC-(1,D)3(X,V,MV)20-8 propellers

Biweekly 2013-16

2013-13-06		See AD	See AD
2013-15-02	S 2008-10-03	Bell Helicopter Textron	205A, 205A-1, 205B, 210, 212, 412, 412CF, and 412EP helicopters
2013-16-06		Eurocopter Deutschland GmbH	BO-105A, BO-105C, BO-105LS A-1, BO-105LS A-3, and BO-105S helicopters

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes

Biweekly 2013-17

2011-22-05	COR, S 2003-22-06	EUROCOPTER FRANCE	AS350B, B1, B2, B3, BA, C, D, D1, AS355E, F, F1, F2, N, and NP helicopters
2012-11-02	COR, S 2008-22-51	Eurocopter Deutschland GmbH	EC135 helicopters
2012-25-04	COR, S 2012-21-51	Eurocopter France	AS350B3 helicopters
2013-15-19	S 2013-07-12	BRP Powertrain GmbH & Co KG Rotax	Rotax 912F, Rotax 912S, Rotax 914F, Rotax 912F, 912S, and 914F engines
2013-16-01		Beechcraft Corporation and Hawker Beechcraft Corporation	See AD
2013-16-04		Eclipse Aerospace, Inc.	EA500
2013-16-07		Eurocopter France	AS332C, AS332L, AS332L1, AS332L2, and EC225LP helicopters
2013-16-10		Hamilton Standard Division and Hamilton Sundstrand Corporation	See AD
2013-16-13		Eurocopter Deutschland GmbH	O-105A, BO-105C, BO-105S, BO-105LS A-1, BO-105LS A-3, MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK117 B-1, MBB-BK 117 B-2, and MBB-BK 117 C-1 helicopters
2013-16-16		Agusta S.p.A. and Bell Helicopter Textron Helicopters	See AD
2013-16-19		Eurocopter France	EC120B and EC130B4 helicopters
2013-16-20		Eurocopter Deutschland GmbH	MBB-BK 117 C-2 helicopters
99-07-10 R1		PIAGGIO AERO INDUSTRIES S.p.A	P-180

Biweekly 2013-18

2013-10-04	COR	Piper Aircraft, Inc.	PA-31, PA-31-325, and PA-31-350 airplanes
2013-16-05	S 64-07-05	Alexander Schleicher	AS -K13, Ka2B, Ka 6, Ka 6 B, Ka 6 BR, Ka 6 C, Ka 6 CR, K7, K8, and K 8 B sailplanes
2013-16-14		Eurocopter Deutschland	EC135 P1, P2, P2+, T1, T2, and T2+ helicopters
2013-17-01		Eurocopter France	AS350B, AS350BA, AS350B1, AS350B2, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, and AS355F2; AS350B3; AS355N and AS355NP helicopters
2013-17-04		Various Aircraft	Equipped with a Rotax Aircraft Engines 912 A series engine (See AD)
2013-18-03		Bell Helicopter Textron Canada	206A and 206B; 206L helicopters

Biweekly 2013-19

2013-13-01	COR	Piper Aircraft, Inc.	PA-46-310P (Malibu), PA-46-350P (Mirage), PA-46R-350T (Matrix), PA-46-500TP (Meridian)
2013-16-03		Eurocopter France	AS350C, D, D1, B, BA, B1, B2, and B3; and AS355E, F, F1, F2, N, and NP helicopters
2013-18-01		Eurocopter France	C 155B, EC155B1, SA-365N, SA-365N1, AS-365N2, AS 365 N3, and SA-366G1 helicopters
2013-18-04		Piaggio Aero Industries S.p.A	P-180
2013-18-05		Eurocopter Deutschland GmbH	EC135P1, EC135P2, EC135P2+, EC135T1, EC135T2, and EC135T2+ helicopters
2013-18-06		Bell Helicopter Textron Canada Limited	206A, 206B, 206L, 206L-1, 206L-3, 206L-4, 222, 222B, 222U, 230, 407, 427, and 430 helicopters
2013-18-07	S 76-12-07	Bell Helicopter Textron	204B and 205A-1 helicopters
2013-19-01		AgustaWestland S.p.A.	A119 and AW119 MKII helicopters



CORRECTION: Federal Register Volume 78, Number 177 (Thursday, September 12, 2013); Pages 56150-56151.

2013-13-01 Piper Aircraft, Inc.: Amendment 39-17489; Docket No. FAA-2013-0535; Directorate Identifier 2013-CE-018-AD.

(a) Effective Date

This AD is effective July 10, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the following Piper Aircraft, Inc. airplanes, listed in table 1 of paragraph (c) of this AD, certificated in any category:

Table 1 of Paragraph (c) of This AD—Applicable Airplanes

Model	Serial Nos.
PA-46-310P (Malibu)	46-8408001 through 46-8408087; 46-8508001 through 46-8508109; 46-8608001 through 46-8608067; and 4608001 through 4608140.
PA-46-350P (Mirage)	4622001 through 4622200; 4636001 through 4636591; and 4636593.
PA-46R-350T (Matrix)	4692001 through 4692190 and 4692192.
PA-46-500TP (Meridian)	4697001 through 4697520.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 2810, Fuel Storage.

(e) Unsafe Condition

This AD was prompted by certain fuel vent valves not providing the correct ventilation. If not corrected, this unsafe condition may lead to structural damage of the wings, which could result in loss of control. We are issuing this AD to correct the unsafe condition on these products.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Modification

(1) Within the next 10 hours time-in-service (TIS) after July 10, 2013 (the effective date of this AD), inspect the left and right fuel vent valves of the main fuel tank vent assemblies to identify if they are the nitrile (black) valves following Part I of Piper Aircraft Inc. Mandatory Service Bulletin No. 1258, dated June 5, 2013.

(2) If during the inspection required in paragraph (g)(1) of this AD, you find that a nitrile (black) fuel vent valve is not installed, except for the requirement of paragraph (h)(3) of this AD, no further action is required by this AD.

(3) If during the inspection required in paragraph (g)(1) of this AD, you find that a nitrile (black) fuel vent valve is installed, before further flight, modify the fuel vent valve following Part II of Piper Aircraft, Inc. Mandatory Service Bulletin No. 1258, dated June 5, 2013. A copy of the limitations from paragraph 4 of Part II of Piper Aircraft, Inc. Mandatory Service Bulletin No. 1258, dated June 15, 2013, must be inserted in the pilot's operating handbook.

(4) In lieu of doing the modification required in paragraph (g)(3) of this AD, you may within the next 10 hours TIS after July 10, 2013 (the effective date of this AD), do the fuel vent valve replacement required in paragraph (h)(1) of this AD following Part III of Piper Aircraft, Inc. Mandatory Service Bulletin No. 1258, dated June 5, 2013.

(h) Replacement

(1) If during the inspection required in paragraph (g)(1) of this AD, you find that a nitrile (black) fuel vent valve is installed, within the next 90 days after July 10, 2013 (the effective date of this AD) if not already done before further flight as specified in paragraph (g)(4) of this AD, replace the nitril (black) fuel vent valve with the fluorosilicone (orange) fuel vent valve following Part III of Piper Aircraft, Inc. Mandatory Service Bulletin No. 1258, dated June 5, 2013. This would include removing the limitations requirement in paragraph 4 of Part II of the service bulletin.

(2) You may at any time before 90 days after July 10, 2013 (the effective date of this AD), replace the nitrile (black) fuel vent valve with the flourosilicone (orange) fuel vent valve. This would include removing the limitations requirement in paragraph 4 of Part II of the service bulletin.

(3) After July 10, 2013 (the effective date of this AD), do not install the nitrile (black) fuel vent valve on any of the affected airplanes.

(i) Positioning Flight

For the purpose of complying with paragraph (g)(1) of this AD, a single-positioning flight is allowed to a location where the inspection required in paragraph (g)(1) can be done provided the actions and limitations specified in paragraphs (i)(1) through (i)(4) of this AD are followed, and the flight is done within the initial 10-hour TIS inspection compliance time. A copy of the limitations from paragraph 4 of Part II of Piper Aircraft, Inc. Mandatory Service Bulletin No. 1258, dated June 5, 2013, must be inserted in the pilot's operating handbook before the positioning flight and removed after the flight. An owner/operator (pilot) holding at least a private pilot certificate is allowed to insert these limitations and do the action of paragraph (i)(1) of this AD.

(1) During normal procedures checklist of every preflight inspection, check condition of wing surface for buckling, skin wrinkling, distortion or other damage. If any damage is found during the preflight inspection, before further flight, repairs must be done. Contact Piper Aircraft, Inc. at contact information found in paragraph (l)(3) of this AD for an FAA-approved repair and incorporate the

repair. At the operator's discretion, this preflight inspection may be delegated to an appropriately certified mechanic.

(2) Flights must be limited to the minimum required crew. No passenger flights are allowed.

(3) Outside air temperature must not be lower than -34 degrees Celsius (-30 degrees Fahrenheit) during all phases of flight.

(4) Avoid unnecessary rapid decent maneuvers.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Gary Wechsler, Aerospace Engineer, Atlanta ACO, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; telephone: (404) 474-5575; fax: (404) 474-5606; email: gary.wechsler@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Piper Aircraft, Inc. Mandatory Service Bulletin No. 1258, dated June 5, 2013.

(ii) Reserved.

(3) For Piper Aircraft, Inc. service information identified in this AD, contact Piper Aircraft, Inc., 2926 Piper Drive, Vero Beach, FL 32960; telephone: 1-877-879-0275; fax: (772) 978-6573; email: customer.service@piper.com; Internet: <http://www.piper.com/pages/publications.cfm>.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on June 18, 2013.

James E. Jackson,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.



2013-16-03 EUROCOPTER FRANCE HELICOPTERS (EUROCOPTER): Amendment 39-17541; Docket No. FAA-2013-0119; Directorate Identifier 2011-SW-034-AD.

(a) Applicability

This AD applies to Eurocopter AS350C, D, D1, B, BA, B1, B2, and B3; and AS355E, F, F1, F2, N, and NP helicopters, with a tailrotor gearbox (TGB) casing assembly, part number (P/N) 350A33-1090-02 and serial number (S/N) MA47577, MA47585, MA47587 through MA47593, MA47597 through MA47600, MA47602, MA47604, MA47606, MA47610, MA47613, MA47615, MA47617, MA47619 through MA47624, MA47626, MA47628, or MA47631 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in the control lever attachment yoke of the TGB casing assembly, which could result in loss of tail rotor pitch control and loss of helicopter control.

(c) Effective Date

This AD becomes effective October 22, 2013.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 100 hours time-in-service:

- (1) Remove the control lever, as depicted in Figure 1, item (b), of Eurocopter Alert Service Bulletin (ASB) No. AS350-65.00.46 or No. AS355-65.00.22, both Revision 0 and both dated May 18, 2011, as applicable for your model helicopter.
- (2) Strip the paint from the TGB control lever attachment yokes, as depicted in Figure 2, item (z), of the ASB No. AS350-65.00.46 or No. AS355-65.00.22, as applicable to your model helicopter.
- (3) Perform a Fluorescent Penetrant Inspection (FPI) in accordance with paragraph 3.B.2 of ASB No. AS350-65.00.46 or No. AS355-65.00.22, as applicable to your model helicopter, on the TGB control lever attachment yokes for a crack. You are only required to follow the actions defined in this ASB paragraph pertaining to the FPI.
- (4) If a crack exists, before further flight, replace the TGB with an airworthy TGB.
- (5) If there is no crack, clean the inspected area and apply chemical conversion coating (Alodine 1200 or equivalent), Epoxy primer, and top coat paint.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone 817-222-5328; email robert.grant@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency AD No. 2011-0104, dated May 27, 2011. You may view the EASA AD at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-0119.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6520, Tail Rotor Gearbox.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Alert Service Bulletin No. AS350-65.00.46, Revision 0, dated May 18, 2011.

(ii) Eurocopter Alert Service Bulletin No. AS355-65.00.22, Revision 0, May 18, 2011.

(3) For Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on July 26, 2013.

Kim Smith,
Directorate Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2013-18-01 EUROCOPTER FRANCE: Amendment 39-17574; Docket No. FAA-2013-0399; Directorate Identifier 2011-SW-064-AD.

(a) Applicability

This AD applies to Model EC 155B, EC155B1, SA-365N, SA-365N1, AS-365N2, AS 365 N3, and SA-366G1 helicopters, except helicopters with modification (MOD) 0767B5 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as inadvertent locking and unlocking of the collective pitch lever, which could result in subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective October 18, 2013.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 50 hours time-in-service:

(1) For Model EC155B and EC155B1 helicopters:

(i) Lock the collective pitch lever, and using a spring scale, measure the load (G) required to unlock the pilot's collective pitch lever as depicted in Figure 1, Detail B of Eurocopter Alert Service Bulletin (ASB) No. 67A007, Revision 1, dated February 25, 2009 (ASB 67A007).

(ii) If the collective pitch lever unlocks at a load less than 11 deca Newtons (daN) (24.7 lbs) or greater than 14 daN (31.5 lbs), before further flight, adjust the collective pitch lever restraining tab (F) using the oblong holes.

(iii) Set the collective pitch lever to the "low pitch" position and hold it in this position, without forcing it downwards.

(iv) Measure the clearance (J1) between the locking pin of the collective pitch lever (C) and the L-section of the restraining tab (F) as depicted in Figure 1, Detail A of ASB 67A007.

(v) If the clearance between the locking pin of the collective pitch lever and the L-section of the restraining tab is less than 3 millimeters (mm), before further flight, remove the restraining tab, clamp the restraining tab (F) in a vice with soft jaws, and gradually apply a load (H) to ensure a clearance of 3 mm or more, as depicted in Figure 1, Detail K of ASB 67A007.

(2) For Model SA-365N, SA-365N1, AS-365N2, and AS 365 N3 helicopters:

(i) Completely loosen the friction, lock the collective pitch lever, and using a spring scale, measure the load (G) required to unlock the pilot's collective pitch lever as depicted in Figure 1, Detail B of Eurocopter ASB No. 67.00.10, Revision 1, dated February 25, 2009 (ASB 67.00.10).

(ii) If the collective pitch lever unlocks at a load less than 5 daN (11.3 lbs) or greater than 14 daN (31.5 lbs), before further flight, adjust the collective pitch lever restraining tab (F) using the oblong holes and adjust the collective link rods as described in the Accomplishment Instructions, paragraph 2.B.4., of ASB 67.00.10.

(iii) Set the collective pitch lever to the "low pitch" position and hold it in this position, without forcing it downwards.

(iv) Tighten the friction lock and measure the clearance (J1) between the locking pin of the collective pitch lever (C) and the L-section of the restraining tab (F) as depicted in Figure 1, Detail A of ASB 67.00.10.

(v) If the clearance between the locking pin of the collective pitch lever and the L-section of the restraining tab is less than 3 mm, before further flight, remove the restraining tab, clamp the restraining tab (F) in a vice with soft jaws, and gradually apply a load (H) to ensure a clearance of 3 mm or more, as depicted in Figure 1, Detail K, of ASB 67.00.10.

(3) For Model SA-366G1 helicopters:

(i) Completely loosen the friction, lock the collective pitch lever, and using a spring scale, measure the load (G) required to unlock the pilot's collective pitch lever as depicted in Figure 1, Detail B of Eurocopter ASB No. 67.05, Revision 1, dated February 25, 2009 (ASB 67.05).

(ii) If the collective pitch lever unlocks at a load less than 5 daN (11.3 lbs) or greater than 14 daN (31.5 lbs), before further flight, adjust the collective pitch lever restraining tab (F) using the oblong holes and adjust the collective link rods as described in the Accomplishment Instructions, paragraph 2.B.4., of ASB 67.05.

(iii) Set the collective pitch lever to the "low pitch" position and hold it in this position, without forcing it downwards.

(iv) Tighten the friction lock and measure the clearance (J1) between the locking pin of the collective pitch lever (C) and the L-section of the restraining tab (F) as depicted in Figure 1, Detail A, of ASB 67.05.

(v) If the clearance between the locking pin of the collective pitch lever and the L-section of the restraining tab is less than 3 mm, before further flight, remove the restraining tab, clamp the restraining tab (F) in a vice with soft jaws, and gradually apply a load (H) to ensure a clearance of 3 mm or more, as depicted in Figure 1, Detail K, of ASB 67.05.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Wilbanks, Aviation Safety Engineer, Rotorcraft Certification Office, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email matt.wilbanks@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Eurocopter Alert Service Bulletin (ASB) No. 67.00.12, Revision 0, dated February 25, 2009; ASB No. 67.07, Revision 0, dated February 25, 2009; and ASB No. 67-009, Revision 1, dated July 19, 2010, which are not incorporated by reference, contain additional information about this AD. For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2011-0154, dated August 22, 2011. You may view the EASA AD in the AD Docket on the internet at <http://www.regulations.gov>.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6710: Main Rotor Control

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Alert Service Bulletin No. 67.00.10, Revision 1, dated February 25, 2009.

(ii) Eurocopter Alert Service Bulletin No. 67.05, Revision 1, dated February 25, 2009.

(iii) Eurocopter Alert Service Bulletin No. 67A007, Revision 1, dated February 25, 2009.

(3) For Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may also view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on August 21, 2013.

Kim Smith,
Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2013-18-04 PIAGGIO AERO INDUSTRIES S.p.A: Amendment 39-17577; Docket No. FAA-2012-0962; Directorate Identifier 2012-CE-033-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 18, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to PIAGGIO AERO INDUSTRIES S.p.A Model P-180 airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 32: Landing Gear.

(e) Reason

This AD was prompted by results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as cracks at the joint between the hinge pin sub-assembly and the lock pin of the main landing gear (MLG) lever hinge fitting (LHF). We are issuing this AD to prevent structural failure of the MLG LHF, which could result in loss of control during take-off or landing runs.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) through (f)(8), including all subparagraphs, of this AD:

(1) Within the next 200 landings after October 18, 2013 (the effective date of this AD), or within the next 3 months after October 18, 2013 (the effective date of this AD), whichever occurs first, and before further flight after each MLG replacement, visually inspect each MLG LHF for cracks and verify freedom of rotation of the MLG wheel lever subassemblies. Do the inspection following Part 1 of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012; and Paragraph A of the Accomplishment Instructions in Appendix A of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012, which includes Messier-Dowty Service Bulletin No. P180-32-32, dated September 10, 2012. The compliance times for the entire AD are presented in landings; however, it is not mandatory to track landings for this class of airplane. If an operator does not track landings, 1 hour time-in-service (TIS) corresponds to 1 landing for compliance with this AD.

(2) If, during the inspection required in paragraph (f)(1) of this AD, freedom of rotation of the MLG wheel lever subassembly is not assured, before further flight, mark the LHF on the affected MLG as "inspect as per SB-80-0345" with an indelible pen, and replace the MLG with a serviceable part as defined in paragraph (f)(7) of this AD. Do the replacement following Part 1 of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012. The newly installed MLG is subject to the inspection requirement specified in paragraph (f)(1) of this AD and all repetitive inspection requirements specified in paragraphs (f)(3) and (f)(4) of this AD.

(3) Within the compliance times specified in paragraphs (f)(3)(i), (f)(3)(ii), and (f)(3)(iii) of this AD, and repetitively thereafter at intervals not to exceed 200 landings, do a detailed visual inspection of each MLG LHF for cracks. Do the inspection following Part 2 of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012; and Paragraph B of the Accomplishment Instructions in Appendix A of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012, which includes Messier-Dowty Service Bulletin No. P180-32-32, dated September 10, 2012.

(i) As of October 18, 2013 (the effective date of this AD), if the MLG LHF has accumulated 2,300 landings or less since new, inspect before exceeding 2,500 landings since new.

(ii) As of October 18, 2013 (the effective date of this AD), if the MLG LHF has accumulated more than 2,300 landings since new, but less than 2,500 landings since new, inspect within the next 200 landings after October 18, 2013 (the effective date of this AD).

(iii) As of October 18, 2013 (the effective date of this AD), if the MLG LHF has accumulated 2,500 landings or more since new, inspect within the next 200 landings after October 18, 2013 (the effective date of this AD), or within the next 3 months after October 18, 2013 (the effective date of this AD), whichever occurs first.

(4) Within the compliance times specified in paragraphs (f)(3)(i), (f)(3)(ii), and (f)(3)(iii) of this AD and repetitively thereafter at intervals not to exceed 750 landings, do a fluorescent penetrant inspection on each MLG LHF for cracks. Do the inspection following Part 3 of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012; and Paragraph C in Appendix A of PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012, which includes Messier-Dowty Service Bulletin No. P180-32-32, dated September 10, 2012.

(5) If, during any inspection required by paragraphs (f)(1), (f)(3), (f)(4), (f)(7), and (f)(8) of this AD, including all subparagraphs, any crack is found, before further flight, replace the MLG with a serviceable part as defined in paragraph (f)(7) of this AD. Do the replacement following the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012. The newly installed MLG is subject to the inspection requirement specified in paragraph (f)(1) of this AD and all repetitive inspection requirements specified in paragraphs (f)(3) and (f)(4) of this AD.

(6) Within 30 days after each MLG replacement, submit an inspection result report to PIAGGIO AERO INDUSTRIES S.p.A at the address specified in paragraph (h) of this AD using the Confirmation Slip attached to PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012.

(7) For the purpose of this AD, a "serviceable" MLG is defined as an airworthy MLG that has had the freedom of rotation verified before installation and that has been inspected following paragraphs (f)(3), (f)(4), and (f)(8) (paragraph (f)(8) only applies if the LHF on the MLG has been marked "inspect as per SB-80-0345" as specified in paragraph (f)(2) of this AD) of this AD, including all subparagraphs, and is found free of cracks. If status of detailed visual inspections intervals, fluorescent penetrant inspections intervals, or landings since new cannot be determined from the Authorized Release Certificate of the MLG to be installed, before next flight after installation, inspect the MLG LHF as specified in paragraphs (f)(1), (f)(3), and (f)(4) of this AD. For the purpose of this AD, a serviceable MLG replacement is defined in paragraphs (f)(7)(i), (f)(7)(ii), and (f)(7)(iii) of this

AD. All newly installed MLG LHF is subject to the inspections required in paragraphs (f)(1), (f)(3), and (f)(4) of this AD.

(i) Remove the unserviceable MLG and replace it with a different serviceable MLG.

(ii) Rework the unserviceable MLG following Part 2 and Part 3 of the Accomplishment Instructions in PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012, until it passes the check for freedom of rotation and no cracks are found.

(iii) Replace the cracked LHF in the unserviceable MLG with a new LHF and, after LHF replacement, check the MLG for freedom of rotation.

(8) As of October 18, 2013 (the effective date of this AD), any MLG with LHF marked "inspect as per SB 80-0345" that was removed as specified in paragraph (f)(2) of this AD may be reinstalled provided that before installation, freedom of rotation has been restored. Before further flight after installation, the MLG LHF must be inspected as specified in paragraphs (f)(1), (f)(3), and (f)(4) of this AD. Continue thereafter with the repetitive inspections at the intervals specified in paragraphs (f)(3) and (f)(4) of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2013-0084, dated April 5, 2013, which can be found in the AD docket on the Internet at <http://www.regulations.gov>; Messier-Dowty PCS-2700 Paint Stripping document, dated January 2011; Messier-Dowty PCS-2622 Cold Degreasing (Solvent) document, Issue 2, dated May 12, 2008; and Messier-Dowty Ltd 201034005 and 201034006 Component Maintenance Manual, page 2, dated May 1, 2004, and page 1020, dated March 17, 2006, which can be found on the Internet at: <http://www.safranmbd.com>, for related information.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, dated September 20, 2012.

(ii) PIAGGIO AERO INDUSTRIES S.p.A. Mandatory Service Bulletin No. 80-0345, Appendix A, dated September 20, 2012, which includes Messier-Dowty Service Bulletin No. P180-32-32, dated September 10, 2012.

(3) For PIAGGIO AERO INDUSTRIES S.p.A. service information identified in this AD, contact Piaggio Aero Industries S.p.A— Airworthiness Office, Via Luigi Cibrario, 4-16154 Genova-Italy; phone: +39 010 6481353; fax: +39 010 6481881; email: airworthiness@piaggioaero.it; Internet: <http://www.piaggioaero.com/#/en/aftersales/service-support>; and Messier-Dowty Limited, Cheltenham Road, Gloucester, GL2 9QH, England; phone: +44(0)1452 712424; fax: +44(0)1452 713821; email: americatasc@safranmbd.com; Internet: www.safranmbd.com.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on August 29, 2013.
Earl Lawrence,
Manager, Small Airplane Directorate,
Aircraft Certification Service.



2013-18-05 Eurocopter Deutschland GmbH: Amendment 39-17578; Docket No. FAA-2013-0398; Directorate Identifier 2011-SW-065-AD.

(a) Applicability

This AD applies to Eurocopter Deutschland GmbH (ECD) Model EC135P1, EC135P2, EC135P2+, EC135T1, EC135T2, and EC135T2+ helicopters with a fire extinguishing system part number (P/N) L262M1808101, P/N L262M1812101, or P/N L262M1812102 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as deformation of the fire extinguishing system injection tubes during an engine fire, which could result in impaired distribution of the fire extinguishing agent, failure of the fire extinguishing system to contain a fire, and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective October 18, 2013.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 30 days, modify each fire extinguishing system injection tube by removing and replacing a section of the tubing in accordance with the Accomplishment Instructions, paragraph 3.B., of Eurocopter EC135 Alert Service Bulletin No. EC135-26A-003, Revision 2, dated December 19, 2011.

(2) Do not install an injection tube, P/N L262M1810101, P/N L262M1811801, or P/N L262M1809101, on any helicopter unless it has been modified as required by this AD.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Wilbanks, Aviation Safety Engineer, Rotorcraft Certification Office, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email matt.wilbanks@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2011-0172, dated September 7, 2011. You may view the EASA AD in the AD Docket on the internet at <http://www.regulations.gov>.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 2620: Extinguishing System.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter EC135 Alert Service Bulletin No. EC135-26A-003, Revision 2, dated December 19, 2011.

(ii) Reserved.

(3) For Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may also view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on August 27, 2013.

Kim Smith,
Directorate Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2013-18-06 Bell Helicopter Textron Canada Limited: Amendment 39-17579; Docket No. FAA-2013-0400; Directorate Identifier 2009-SW-48-AD.

(a) Applicability

This AD applies to Model 206A, 206B, 206L, 206L-1, 206L-3, 206L-4, 222, 222B, 222U, 230, 407, 427, and 430 helicopters as follows, certificated in any category.

(1) Model 206A, Model 206B helicopters converted from Model 206A, and Model 206B with Bellcrank Assembly, part-number (P/N) 206-001-526-001 or 206-001-538-009; Idler Link Assembly, P/N 206-010-336-109; or Link Assembly, P/N 206-031-589-001, installed.

(2) Model 206L, Model 206L-1, Model 206L-3, and Model 206L-4 with Idler Assembly, P/N 206-001-549-101; Bellcrank Assembly, P/N 206-001-552-001; or Link Assembly, P/N 206-010-336-109, installed.

(3) Model 222 and Model 222B with

(i) Cyclic Link Assembly, P/N 222-010-419-110; or

(ii) Bellcrank Assembly Directional Controls, P/N 222-001-734-001 or 222-001-736-005, installed.

(4) Model 222U with

(i) Cyclic Link Assembly, P/N 222-010-419-110; or

(ii) Bellcrank Assembly Directional Controls, P/N 222-001-734-001 or 222-001-736-005, installed.

(5) Model 230 with

(i) Fitting Assembly Engine Bipod Mount, P/N 230-060-113-101, 230-060-113-102, 230-060-114-101, or 230-060-114-102; Cyclic Link Assembly P/N 222-010-419-110; or

(ii) Bellcrank Assembly Directional Controls, P/N 222-001-734-001, or 222-001-736-005, installed.

(6) Model 407 with

(i) Bearing and Liner Assembly, P/N 406-010-417-101; Cyclic Mixer Follower Assembly, P/N 407-001-325-101; Bellcrank Assembly, P/N 407-001-524-105, 407-001-524-109, 407-001-526-105, 407-001-526-109, 407-001-528-101, or 407-001-528-105; or

(ii) Beam Assembly, P/N 407-001-723-101, installed.

(7) Model 427 with Swashplate Lateral Link Assembly (upper and lower bearing), P/N 427-001-021-101; Swashplate Longitudinal Link Assembly (upper and lower bearing), P/N 427-001-022-101; Transmission Mounted Longitudinal Bellcrank Assembly (pivot bearing), P/N 427-001-521-105/-109; Transmission Mounted Lateral Bellcrank Assembly (pivot bearing), P/N 427-001-520-109/-113; or Bearing and Liner (lower drive link bearing), P/N 406-010-417-109, installed.

(8) Model 427 with Tail Rotor Actuator Output Idler, P/N 427-001-723-101, installed.

(9) Model 430 with

(i) Fitting Assembly Engine Bipod Mount, P/N 230-060-113-101, 230-060-113-102, 230-060-114-101, or 230-060-114-102; Bearing Assembly M/R Rotating Controls, P/N 430-010-449-101; Rod End Assembly Lift link, P/N 430-010-204-101 or 430-010-204-103, or

(ii) Bellcrank Assembly Directional Controls, P/N 222-001-734-001, or 222-001-736-005, installed.

(b) Unsafe Condition

This AD defines the unsafe condition as bearings that may not have been staked as required and may migrate out of their proper position and limit the functionality of the affected part. This condition could result in failure of a bearing and the lever assembly in which it is installed and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective October 17, 2013.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Perform each action required by this AD within the compliance time for each part listed in the applicability paragraph of this AD as follows: (a)(1), (a)(2), (a)(6)(i), (a)(7), and (a)(8), within 10 hours time-in-service (TIS) or 30 days, whichever occurs first; (a)(3)(i), (a)(4)(i), (a)(5)(i), and (a)(9)(i), within 5 hours TIS or 30 days, whichever occurs first; (a)(3)(ii), (a)(4)(ii), (a)(5)(ii), and (a)(9)(ii) within 150 hours TIS or 12 months, whichever occurs first; and (a)(6)(ii) within 300 hours TIS or 12 months, whichever occurs first.

(2) Using a 10X or higher power magnifying glass or using a boroscope, inspect each bearing and determine if the bearing has been properly staked for each part that contains a part serial number with a prefix of either "TI" or "TIFS."

(i) If a part does not contain a serial number, inspect the bearing of that part even if that part contains a supplier marking.

(ii) If you cannot access the bearing while the part is installed on the helicopter to make a determination as to whether the bearing in the part is properly staked, remove the part and inspect the bearing using a 10X or higher power magnifying glass or using a boroscope.

(iii) If you find a part that is not properly staked, replace the bearing or the assembly with an airworthy bearing or assembly before further flight.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to Sharon Miles, ASW-111, Aviation Safety Engineer, Rotorcraft Directorate, Regulations and Guidance Group, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5110, email sharon.y.miles@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Bell Alert Service Bulletin (ASB) No. 206-09-122 for Models 206A and 206B; No. 206L-09-156 for Models 206L, 206L-1, 206L-3, and 206L-4; No. 222-09-107 for Models 222 and 222B; No. 222U-09-78 for Model 222U; No. 230-09-39 for Model 230; No. 407-09-88 for Model 407; No. 427-09-25 for Model 427; and No. 430-09-42 for Model 430, all dated April 7, 2009, which are not

incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Bell Helicopter Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4, telephone (450) 437-2862 or (800) 363-8023, fax (450) 433-0272, or at <http://www.bellcustomer.com/files/>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in Transport Canada Civil Aviation AD No. CF-2009-32, dated July 24, 2009, which may be reviewed in the AD docket on the Internet at <http://www.regulations.gov>.

(h) Subject

Joint Aircraft System/Component (JASC) Code: 6700 Rotorcraft Flight Controls and 6710 Main Rotor Control.

Issued in Fort Worth, Texas, on August 27, 2013.

Kim Smith,
Directorate Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2013-18-07 BELL HELICOPTER TEXTRON (BELL): Amendment 39-17580; Docket No. FAA-2013-0379; Directorate Identifier 2009-SW-26-AD.

(a) Applicability

This AD applies to Model 204B helicopters with a tail rotor pitch control chain (chain), part number (P/N) 204-001-739-003 or -105, installed, and Model 205A-1 helicopters with a serial number (S/N) 30001 through 30228, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in a chain, which can grow quickly because of oscillatory loads and lead to premature failure of the chain, loss of the tail rotor blade pitch control, and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 76-12-07, Amendment 39-2640 (41 FR 23939, June 14, 1976) as revised by Amendment 39-3569 (44 FR 55555, September 27, 1979).

(d) Effective Date

This AD becomes effective October 18, 2013.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) For Model 205A-1 helicopters, before further flight, replace the tail rotor chain and cable control system with an airworthy tail rotor push-pull control system by installing an improved tail rotor hub and blade assembly kit, P/N 205-704-040-001 or 205-704-040-103, and then installing a push/pull anti-torque retrofit kit, P/N 205-704-057-001 or 205-704-057-101.

(2) For Model 204B helicopters:

(i) Within 10 hours time-in-service (TIS) and thereafter at intervals not to exceed 10 hours TIS, using a 10-power or higher magnifying glass and a light, visually inspect each of the link segments in the chain for a crack. Also, slowly operate the cockpit anti-torque control pedals during the inspection so that the entire surface area of the chain in contact with the control quill sprocket (sprocket) is visibly accessible and can be inspected. Pay particular attention to the portion of the chain that travels over the sprocket and extends 6 inches to each side of the sprocket.

(A) If there is no cracked or broken link segment, lubricate the chain with a light preservative oil (C-125) or wipe with a cloth dampened in lubricating oil (C-010).

(B) If there is a cracked or broken link segment, before further flight, replace the chain with an airworthy chain.

(ii) Within 50 hours TIS, install a tail rotor cable and chain damper kit, P/N 204-706-130-101, as depicted in Figures 1 through 3, and by following the Accomplishment Instructions, paragraphs 2. through 9., of Bell Alert Service Bulletin (ASB) No. 204-79-7, dated August 21, 1979.

(g) Alternative Methods of Compliance (AMOC)

(1) The Manager, Rotorcraft Certification Office, FAA, may approve AMOCs for this AD. Send your proposal to Michael Kohner, ASW-170, Aviation Safety Engineer, Rotorcraft Directorate, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5170, fax (817) 222-5783, email mike.kohner@faa.gov.

(2) For operations conducted under 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

(1) Bell ASB No. 204-75-4, dated December 16, 1975; Bell ASB No. 205-78-5, dated May 16, 1978; Service Instructions (SI) No. 205-38, "changed" March 28, 1990; and SI No. 205-46, revised March 7, 1980, which are not incorporated by reference, contain additional information about the subject of this AD. For this service information, contact Bell Helicopter Textron, Inc., P.O. Box 482, Fort Worth, TX 76101, telephone (817) 280-3391, fax (817) 280-6466, or at <http://www.bellcustomer.com/files/>. You may review a copy of the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in Transport Canada Civil Aviation (TCCA) AD CF-1990-06R1, issued January 7, 2008. You may view the TCAA AD in the AD docket on the Internet at <http://www.regulations.gov>.

(i) Subject

The Joint Aircraft System Component Code is 6720: Tail Rotor Control System.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Bell Alert Service Bulletin No. 204-79-7, dated August 21, 1979.

(ii) Reserved.

(3) For Bell Helicopter Textron, Inc. service information identified in this AD, contact Bell Helicopter Textron, Inc., P.O. Box 482, Fort Worth, TX 76101; telephone (817) 280-3391; fax (817) 280-6466; or at <http://www.bellcustomer.com/files/>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on August 27, 2013.
Kim Smith,
Directorate Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2013-19-01 AgustaWestland S.p.A.: Amendment 39-17583; Docket No. FAA-2013-0350; Directorate Identifier 2012-SW-050-AD.

(a) Applicability

This AD applies to AgustaWestland S.p.A. (AgustaWestland) Model A119 and AW119 MKII helicopters, serial numbers up to and including 14781, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a window detaching from the pilot or co-pilot doors, which could result in damage to the helicopter and injury to persons on the ground.

(c) Effective Date

This AD becomes effective October 25, 2013.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within the next 50 hours time-in-service (TIS) or within the next five months, whichever comes first:

(1) Visually inspect the pilot and co-pilot doors by referencing Figure 1 of AugustWestland Bollettino Tecnico 119-47, dated March 29, 2012 (BT), to determine whether there is bonding between the seal (3) and the window (4) in the internal and external side of the seal's junction area.

(2) If there is no bonding, before further flight, apply bonding to the windows, seals, and window frames in accordance with the Compliance Instructions, paragraphs 5 through 20, of the BT.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Sharon Miles, Aviation Safety Engineer, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email sharon.y.miles@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2012-0058, dated April 3, 2012. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2013-0350.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 5610, Flight Compartment Windows.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) AgustaWestland Bollettino Tecnico 119-47, dated March 29, 2012.

(ii) Reserved.

(3) For AgustaWestland service information identified in this AD, contact AgustaWestland, Customer Support & Services, Via Per Tornaento 15, 21019 Somma Lombardo (VA) Italy, ATTN: Giovanni Cecchelli; telephone 39- 0331-711133; fax 39 0331 711180; or at <http://www.agustawestland.com/technical-bullettins>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on September 9, 2013.

Kim Smith,
Directorate Manager, Rotorcraft Directorate,
Aircraft Certification Service.