

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

LARGE AIRCRAFT

BIWEEKLY 2015-15

7/13/2015 - 7/26/2015



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2015-01			
2014-26-03		Saab AB, Saab Aerosystems	340B
Biweekly 2015-02			
2014-25-51		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-25-52		Airbus	A330-223F, -243F, A330-201, -202, -203, -223, -243, A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, -313, A340-541 and A340-642
2014-26-06		ATR–GIE Avions de Transport Régional	ATR42-500 and ATR72-212A
2014-26-07		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G
2014-26-09	R 2014-03-05	Bombardier, Inc.	BD-700-1A10
2014-26-10		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-53		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-01-01	R 2011-09-11	The Boeing Company	777-200 and -300 series
Biweekly 2015-03			
2014-23-15	R 2011-14-06	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-08	R 2011-13-09	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2015-02-02		Bombardier, Inc	CL-215-6B11 (CL-215T Variant), CL-215-6B11 (CL-415 Variant)
2015-02-03		Airbus	A300 B4-601, B4-603, B4-605R, F4-605R, and C4-605R Variant F
2015-02-04		Dassault Aviation	MYSTERE-FALCON 50
2015-02-05		The Boeing Company	717-200, DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F, MD-10-10F and MD-10-30F, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87), MD-88, MD-90-30
2015-02-06		Bombardier, Inc	CL-600-2B16 (CL-604 Variant)
2015-02-08		Rolls-Royce Corporation (RRC)	AE 2100D2, 2100D2A, 2100D3, 2100P and AE 3007A1, A1/1, A1/3, A1E, A1P, A2, A3, C, C1, and C2
2015-02-11		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-02-12		Bombardier, Inc	DHC-8-400, -401 and -402
2015-02-13		Empresa Brasileira de Aeronautica S.A. (Embraer)	EMB -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2015-02-16	R 2009-06-06	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-02-17		Airbus	A330-201, -202, -203, -223, -223F, -243, and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2015-02-18		Airbus	A330-201, -202, -203, -301, -302, and -303
2015-02-19	R 95-24-04	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R, A300 C4-605R Variant F

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-02-20	S 2013-15-10	Rolls-Royce plc (RR)	RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61, 768-60, 772-60, 772B-60, 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, 895-17, 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84
2015-02-23		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants)
2015-02-26	R 2013-24-13	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series, 737-600, -700, -700C, -800, and -900 series
Biweekly 2015-04			
2015-02-24	R 2007-03-18 R2008-17-02 R2012-08-03 R2012-15-14	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, A300 B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-02-25		Bombardier, Inc.	DHC-8-400, -401, and -402
2015-03-01		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2015-03-02		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-03-04		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2015-03-05	R 2012-09-07	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-03-06	R 2007-22-10	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213 -311, -312, -313, -541, and -642
Biweekly 2015-05			
2015-02-14	R 2009-20-05	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, -232.
2015-03-03		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R. A300 C4-605R Variant F.
2015-04-02		CFM International S.A.	CFM56-7B series
2015-04-03		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60
2015-04-06		Rolls-Royce plc	RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17.
Biweekly 2015-06			
2015-04-07		Boeing	767-200 and -300 series airplanes
2015-05-01		Boeing	757-200, -200PF, -200CB, and -300 series airplanes; and 767-200, -300, -300F, and -400ER series airplanes
2015-05-03		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2015-05-07	R 2015-02-06	Bombardier	CL-600-2B16 (CL-604 Variant) airplanes
2015-05-08		Lockheed Martin	382, 382B, 382E, 382F, and 382G airplanes
2015-06-01	S 2014-06-03	British Aerospace	Jetstream Series 3101 and Jetstream 3201 airplanes
Biweekly 2015-07			
2015-04-08	R 2014-06-08	Bombardier, Inc	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2015-05-02	R 2014-23-15	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2015-06-04	R 2011-13-07	Dassault	FALCON 7X
2015-06-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-06-06 2015-06-07 2015-07-01		BAE Systems The Boeing Company Rolls-Royce plc	A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes. 4101 airplanes 737-100, -200, -200C, -300, -400, and -500 series airplanes RB211-524B-02, RB211-524B-B-02, RB211-524B2-19, RB211-524B2-B-19, RB211-524B3-02, RB211-524C2-19, and RB211-524C2-B-19 turbofan engines
Biweekly 2015-08			
2015-06-08	R 2011-09-03	Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G
2015-07-05		BAE Systems (Operations) Limited	146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2015-07-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-07-07 2015-08-02	R 2015-02-04	The Boeing Company Dassault Aviation	777-200, -200LR, -300ER, and 777F series MYSTERE-FALCON 50
Biweekly 2015-09			
2015-06-10		ATR-GIE Avions de Transport Régional	ATR72-212A
2015-07-02		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), CL-600-2B16 (CL-604 Variants)
2015-08-01 2015-08-03 2015-08-05	R 2013-26-05	The Boeing Company Bombardier, Inc. Dassault Aviation	757-200, -200PF, -200CB, and -300 series DHC-8-400, -401, and -402 FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2015-08-06	R 2007-14-05	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-08-08	R 2014-26-53 and 2015-03-02	Airbus	A319-115, A319-132, A319-133, A320-214, A320-232, and A320-233
2015-08-09 2015-09-02 2015-09-03		The Boeing Company Bombardier, Inc. Airbus	737-600 and -700 series CL-600-2E25 (Regional Jet Series 1000)
2015-09-07		The Boeing Company	A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 787
Biweekly 2015-10			
2015-08-07 2015-09-05 2015-09-08		Zodiac Aerotechnics The Boeing Company Airbus	See AD 747-400 and 747-400F A300 B4-601, B4-603, and B4-605R; and A300 F4-605R; and A300 C4-605R Variant F; and A310-204 and -304
2015-09-09	R 2004-07-11	The Boeing Company	767-200, -300, and -400ER series
Biweekly 2015-11			
2015-10-02	R 2014-20-11	Zodiac Seats France	9140, 9166, 9173, 9174, 9184, 9188, 9196, 91B7, 91B8, 91C0, 91C2, 91C4, 91C5, 91C9, 9301, and 9501 series passenger seat assemblies
2015-10-03	R 2014-09-05	Airbus Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-10-04	R 2012-09-09	International Aero Engines AG	IAE V2500-A1, IAE V2525-D5, IAE V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, and V2533-A5
2015-11-04		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body; 707-300, -300B, -300C, -400; 720 and 720B series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2015-12			
2015-10-01		Bombardier, Inc.	DHC-8-401, -402, and -403
2015-11-02	R 95-26-11	Lockheed Martin Corporation	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2015-11-03		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A; ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A
2015-11-05		The Boeing Company	747-400, 747-400D, 747-400F, 747-8F, and 747-8 series
Biweekly 2015-13			
2015-10-51		Avidyne Corporation	Integrated Flight Displays (IFDs)
2015-12-03	COR R 2007-13-05	The Boeing Company	777-200, -200LR, -300, and -300ER series
2015-12-05	R 2008-06-18	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-12-06		Learjet Inc.	45
2015-12-07		The Boeing Company	747-8F and 747-8 series
2015-12-08		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-12-10		Pratt & Whitney Division	PW6122A and PW6124A
2015-12-11	COR	The Boeing Company	767-200, -300, -300F, and -400ER series, 777-200, -200LR, -300, -300ER, and 777F
2015-12-12		Fokker Services B.V.	F.28 Mark 0070 and 0100
2015-13-01		ATR-GIE Avions de Transport Régional	ATR42-500, ATR72-212A
2015-13-02		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2015-14			
2015-13-08		Dassault Aviation	FALCON 2000EX
2015-14-01		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2015-15			
2015-13-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-13-07	R 98-13-23	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; and A300 C4-605R Variant F
2015-14-03		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2015-14-05		Pratt & Whitney	JT8D-217C and JT8D-219
2015-14-06		The Boeing Company	747-8 and 747-8F series
2015-14-07		The Boeing Company	787-8
2015-14-08		Airbus	A310-203
2015-14-09		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, 747SP, 747-8F, and 747-8 series
2015-15-01	R 2004-13-02	The Boeing Company	747-100, -200B, and -200F series
2015-15-02	R 2012-13-06	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R; and A300 C4-605R Variant F
2015-15-03		General Electric Company	GENx-1B and GENx-2B
2015-15-05	R 98-22-10 R 90-06-02	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-15-08		Bombardier, Inc.	BD-100-1A10 (Challenger 300)
2015-15-09		BAE Systems (Operations) Limited	4101
2015-15-10		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232



2015-13-05 The Boeing Company: Amendment 39-18192; Docket No. FAA-2014-0339; Directorate Identifier 2014-NM-025-AD.

(a) Effective Date

This AD is effective August 18, 2015.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes; certificated in any category; as identified in Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf) http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/%24FILE/ST01219SE.pdf) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of fatigue cracks found in the upper corners of the forward entry door skin cutout. We are issuing this AD to detect and correct cracking in the doorway upper corners, which could result in cabin depressurization.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

(1) For airplanes identified in Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, as Groups 1 and 2, Configuration 2, and Group 3: Before the accumulation of 27,000 total flight cycles, or within 4,500 flight cycles after the effective date of this AD, whichever occurs later, do an external detailed inspection for cracking of the skin assembly, and a low frequency

eddy current (LFEC) inspection for cracking of the skin assembly and bear strap, and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, except as required by paragraph (j) of this AD. Repeat the inspections thereafter at intervals not to exceed 4,500 flight cycles. Do all applicable corrective actions before further flight.

(2) For airplanes identified as Group 4 in Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014: Within 120 days after the effective date of this AD, do inspections of the skin assembly and bear strap and all applicable corrective actions using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(h) Terminating Actions

(1) Accomplishment of the preventive change specified in Part II of the Accomplishment Instructions of Boeing Service Bulletin 737-53-1163, dated December 21, 1993; or the preventive modification specified in Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014; terminates the inspection requirements specified in paragraph (g)(1) of this AD.

(2) Accomplishment of the repair specified in Part III of the Accomplishment Instructions of Boeing Service Bulletin 737-53-1163, dated December 21, 1993; or Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014; terminates the inspection requirements specified in paragraph (g)(1) of this AD.

(3) For door corners that have a repair installed, as provided by Boeing, which inhibits the inspections required by paragraph (g)(1) of this AD, and approved before the effective date of this AD using FAA Form 8100-9, the inspection in paragraph (g)(1) of this AD is not required. Refer to the repair approval for any supplemental inspection of the repair area.

(i) Post-Modification and Post-Repair Inspections

(1) For airplanes identified in Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, as Groups 1 and 2, on which a repair or preventive modification has been installed in accordance with Boeing Service Bulletin 737-53-1163, dated December 21, 1993; or Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014: At the applicable time specified in table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, or within 4,500 flight cycles after the effective date of this AD, whichever occurs later, inspect the fuselage skin assembly, bear strap, and frame and sill outer chords, as applicable, for cracking, in accordance with table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014. Repeat the inspection thereafter at the times specified in table 3 of paragraph 1.E., "Compliance" of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014. If any crack is found during any inspection required by this paragraph, repair before further flight using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(2) The inspection requirement in paragraph (i)(1) of this AD does not apply to operators who have added the inspection program for this area specified in table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, in accordance with 14 CFR 121.1109(c)(2) or § 129.109(b)(2) to their FAA-approved maintenance program. These inspections may be used in support of compliance with 14 CFR 121.1109(c)(2) or § 129.109(b)(2).

(j) Exception to Service Information Specifications

If any cracking is found during any inspection required by this AD, and Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, specifies to contact Boeing for appropriate

action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(k) Explanation of Service Information and AD: Repair/Preventative Modification Required

The Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014, state that Group 1 and 2, Configuration 1 airplanes on which the repair or preventive modification has been installed as specified in Boeing Service Bulletin 737-53-1163, dated December 21, 1993, are not required to be inspected. However, this AD requires inspections of Group 1 and 2 airplanes, as identified in and in accordance with paragraph (i) of this AD, which correspond with table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014.

(l) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 737-53-1163, dated December 21, 1993.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (n)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(n) Related Information

(1) For more information about this AD, contact Nenita Odesa, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; telephone: 562-627-5234; fax: 562-627-5210; email: nenita.odesa@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (o)(4) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 737-53-1163, dated December 21, 1993.

(ii) Boeing Alert Service Bulletin 737-53A1163, Revision 1, dated January 8, 2014.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 19, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-13-07 Airbus: Amendment 39-18194. Docket No. FAA-2014-0011; Directorate Identifier 2013-NM-046-AD.

(a) Effective Date

This AD becomes effective August 28, 2015.

(b) Affected ADs

This AD replaces AD 98-13-23, Amendment 39-10614 (63 FR 34576, June 25, 1998).

(c) Applicability

This AD applies to Airbus Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes; Model A300 B4-605R and B4-622R airplanes; Model A300 F4-605R and F4-622R airplanes; and Model A300 C4-605R Variant F airplanes; certificated in any category; on which Airbus Modification 6146 has not been installed.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of cracking found at the lower corner of the horizontal stabilizer cutout longeron during a full scale fatigue test, and a determination that the risk of cracking is higher than initially determined. We are issuing this AD to prevent cracking of the lower horizontal stabilizer cutout longeron, the corner fitting, the skin strap, and the outer skin, which could result in reduced structural integrity of the horizontal-stabilizer cutout longeron.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspections and Corrective Actions

This paragraph restates the requirements of paragraphs (a), (b), (c), (d), and (e) of AD 98-13-23, Amendment 39-10614 (63 FR 34576, June 25, 1998), with revised service information.

(1) Prior to the accumulation of 18,000 total landings, or within 2,000 landings after July 30, 1998 (the effective date of AD 98-13-23, Amendment 39-10614 (63 FR 34576, June 25, 1998), whichever occurs later: Perform a visual and eddy current inspection to detect cracks and/or corrosion of Areas 1 and 2 of the lower horizontal stabilizer cutout longeron, in accordance with Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. As of the

effective date of this AD, use only Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, to do the actions required by this paragraph.

(2) At the later of the times specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD: Perform a visual and an eddy current inspection to detect cracks and corrosion of Area 3 of the lower horizontal stabilizer cutout longeron, in accordance with Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. As of the effective date of this AD, use only Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, to do the actions required by this paragraph.

(i) Prior to the accumulation of 24,000 total landings, but not before the accumulation of 18,000 total landings; or

(ii) Prior to the accumulation of 2,000 landings after July 30, 1998 (the effective date of AD 98-13-23, Amendment 39-10614 (63 FR 34576, June 25, 1998)).

(3) If no cracking is detected during any inspection required by paragraph (g)(1) or (g)(2) of this AD: Before further flight, cold work and ream the vacated fastener holes, in accordance with Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012; and perform the requirements of paragraph (g)(3)(i) or (g)(3)(ii) of this AD, as applicable. As of the effective date of this AD, use only Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, to do the actions required by this paragraph.

(i) For airplanes on which no cracking is found in Area 1 or 2: Repeat the inspections required by paragraph (g)(1) of this AD thereafter at intervals not to exceed 6,000 flight cycles.

(ii) For airplanes on which no cracking is found in Area 3: Perform the various follow-on actions in accordance with Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. (The follow-on actions include installing a new corner fitting, installing a new longeron, and performing a cold working procedure.) After accomplishment of these follow-on actions, no further action is required by this AD. After the effective date of this AD, use only Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, to do the actions required by this paragraph.

(4) If any cracking is detected during any inspection required by paragraph (g)(1) or (g)(2) of this AD, perform the requirements of paragraph (g)(4)(i) or (g)(4)(ii) of this AD, as applicable.

(i) If any cracking is found in Area 1 or 3 that is within the limits specified in Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012: Before further flight, repair in accordance with Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. As of the effective date of this AD, use only Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, to do the actions required by this paragraph.

(ii) If any cracking is found in Area 2, or if any cracking is found in any area and that cracking is beyond the limits described in Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA), or Airbus's EASA Design Organization Approval (DOA).

(5) If any corrosion is detected during any inspection required by paragraph (g) of this AD, prior to further flight, repair the corrosion, in accordance with Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995; or the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. As of the effective date of this AD, use only Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, to do the actions required by this paragraph.

(h) New Inspections

At the applicable times specified in paragraph 1.E., "Compliance," of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, except as provided by paragraphs (j)(1) and (j)(2) of this AD: Do the actions specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. Repeat the inspections, thereafter, at the applicable intervals specified in paragraph 1.E., "Compliance," of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012. Doing the initial inspections required by paragraph (h) of this AD and applicable corrective actions required by paragraph (i) of this AD terminates the requirements of paragraph (g) of this AD.

(1) Do a general visual inspection for cracking and corrosion of the lower horizontal stabilizer cut-out longeron, the corner fitting, the skin strap, and the skin between frame (FR)87 and FR89 and between stringers (STGR)24 and STGR27, left- and right-hand sides.

(2) Do a high frequency eddy current (HFEC) inspection for cracking of the flanges of the lower corner fittings and the edges of the outer skin and the edges of the longeron, the skin strap, and the skin at the run-out of the corner fitting above the last eight fasteners.

(3) Do a rotating probe inspection for cracking of the fastener holes. If no cracking is found during the rotating probe inspection, before further flight, do a cold expansion of the fastener holes, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012.

(i) New Corrective Actions

(1) If any corrosion is found during any inspection required by paragraph (h) of this AD, before further flight, repair, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012.

(2) If any cracking is found during any inspection required by paragraph (h) of this AD, before further flight, repair in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, except where Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, specifies to contact Airbus, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA, or Airbus's EASA DOA.

(j) Exception

(1) Where Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, specifies a grace period of 1950 flight cycles or 4100 flight hours, this AD specifies the grace period after the effective date of this AD.

(2) Where Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012, specifies a compliance time "after receipt of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(k) Credit for Previous Actions

(1) This paragraph provides credit for the corresponding actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A300-53-6042, Revision 02, dated April 28, 1998, which is not incorporated by reference in this AD.

(2) This paragraph provides credit for the corresponding actions required by paragraph (h)(3) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995, which was incorporated by reference in

AD 98-13-23, Amendment 39-10614 (63 FR 34576, June 25, 1998), and continues to be incorporated by reference in this AD; or Airbus Service Bulletin A300-53-6042, Revision 02, dated April 28, 1998, which is not incorporated by reference in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(ii) AMOCs approved for AD 98-13-23, Amendment 39-10614 (63 FR 34576, June 25, 1998), are approved as AMOCs for the corresponding requirements of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0048, dated March 4, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0011.

(2) Service information identified in this AD that is not incorporated by reference in this AD is available at the addresses specified in paragraphs (n)(5) and (n)(6) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on August 28, 2015.

(i) Airbus Service Bulletin A300-53-6042, Revision 03, dated August 30, 2012.

(ii) Reserved.

(4) The following service information was approved for IBR on July 30, 1998 (63 FR 34576, June 25, 1998).

(i) Airbus Service Bulletin A300-53-6042, Revision 1, dated February 20, 1995.

(ii) Reserved.

(5) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 17, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-14-03 Bombardier, Inc.: Amendment 39-18201. Docket No. FAA-2014-0570; Directorate Identifier 2013-NM-094-AD.

(a) Effective Date

This AD becomes effective August 21, 2015.

(b) Affected ADs

This AD affects AD 2008-13-09, Amendment 39-15572 (73 FR 47029, August 13, 2008).

(c) Applicability

This AD applies to Bombardier, Inc. Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes, certificated in any category, serial numbers (S/N) 003 through 624 inclusive, and 626.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent potential ignition sources within the fuel system, which could result in a fuel tank explosion.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 30 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, to include fuel system limitation (FSL) Task Numbers FSL-02, "Detailed Inspection of the Fuel Tank Bonding Jumpers"; and FSL-17, "Functional Check of the Fuel Tank Components and the Plumbing Lines Electrical Bonding"; as specified in the applicable service information identified in paragraphs (g)(1) through (g)(5) of this AD. The initial compliance times for accomplishing the tasks are specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD. Doing this revision terminates the requirements of paragraph (f) of AD 2008-13-09, Amendment 39-15572 (73 FR 47029, August 13, 2008), for Task Numbers FSL-02 and FSL-17 only.

(1) Bombardier Temporary Revision AWL 2-43, dated August 31, 2007, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1-82-7.

(2) Bombardier Temporary Revision AWL 2-47, dated February 16, 2011, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1-82-7.

(3) Bombardier Temporary Revision AWL 3-109, dated August 31, 2007, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1-83-7.

(4) Bombardier Temporary Revision AWL 3-117, dated February 16, 2011, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1-83-7.

(5) Subject 5-FSL of Section 5, "Fuel System Limitations," of the "Airworthiness Limitations List," of the Bombardier Dash 8 Series 100 Maintenance Program Manual, PSM 1-8-7, Revision 18, dated February 23, 2012.

(h) Phase-in Compliance Times

For airplanes having S/Ns 003 through 624 inclusive, and S/N 626, the initial compliance times are specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD, as applicable.

(1) For airplanes having S/Ns 003 through 624 inclusive on which the applicable modification summaries (ModSums) specified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD have been incorporated before the effective date of this AD: The compliance time for the initial inspection in FSL Task Number FSL-02, "Detailed Inspection of the Fuel Tank Bonding Jumpers"; and the initial functional check in FSL Task Number FSL-17, "Functional Check of the Fuel Tank Components and the Plumbing Lines Electrical Bonding"; is within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first. Airplane configurations can be a combination of the configurations specified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD.

(i) For airplanes having S/Ns 003 through 624 inclusive: Bombardier ModSum Package 8Q101512, Revision G, dated June 10, 2009; and Bombardier ModSum Package 8Q101865, Revision B, dated May 26, 2008.

(ii) For airplanes having S/Ns 003 through 624 inclusive with auxiliary power unit (APU) option: Bombardier ModSum Package 8Q902144, Revision E, dated June 17, 2009.

(iii) For airplanes having S/Ns 003 through 624 inclusive with a long-range fuel system installed: Bombardier ModSum Package 8Q902091, Revision C, dated December 22, 2006.

(2) For airplanes having S/Ns 003 through 624 inclusive on which the applicable ModSum packages specified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD have not been incorporated before the effective date of this AD: The compliance time for the initial inspection in FSL Task Number FSL-02, "Detailed Inspection of the Fuel Tank Bonding Jumpers"; and the initial functional check in FSL Task Number FSL-17, "Functional Check of the Fuel Tank Components and the Plumbing Lines Electrical Bonding"; is before further flight after incorporation of all applicable ModSum packages specified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD. Airplane configurations can be a combination of the configurations specified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD.

(3) For the airplane having serial number 626: The initial compliance time is at the applicable time specified in paragraph (h)(3)(i) or (h)(3)(ii) of this AD.

(i) If Bombardier ModSum Package 8Q902091, Revision C, dated December 22, 2006, has been accomplished before the effective date of this AD: The compliance time for doing the initial inspection specified in FSL Task Number FSL-02, "Detailed Inspection of the Fuel Tank Bonding Jumpers"; and the initial functional check specified in FSL Task Number FSL-17, "Functional Check of the Fuel Tank Components and the Plumbing Lines Electrical Bonding"; is within 6,000 flight hours or within 36 months after the effective date of this AD, whichever occurs first.

(ii) If Bombardier ModSum Package 8Q902091 Revision C, dated December 22, 2006, has not been accomplished before the effective date of this AD: The compliance time for doing the initial

inspection in FSL Task Number FSL-02, "Detailed Inspection of the Fuel Tank Bonding Jumpers"; and the initial functional check in FSL Task Number FSL-17, "Functional Check of the Fuel Tank Components and the Plumbing Lines Electrical Bonding"; is before further flight after accomplishment of Bombardier ModSum Package 8Q901091.

(i) No Alternative Actions, Intervals, and/or Critical Design Configuration Control Limitations (CDCCLs)

After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used unless the actions, intervals, and/or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k) of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier TR AWL-110, dated August 31, 2007, to Part 2, "Airworthiness Limitations List," of the Bombardier Dash 8 Series 100 Maintenance Program Manual, Product Support Manual PSM 1-8-7, which is not incorporated by reference in this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2007-32R2, dated June 27, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0570-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Temporary Revision AWL 2-43, dated August 31, 2007, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1-82-7.

(ii) Bombardier Temporary Revision AWL 2-47, dated February 16, 2011, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 200 Maintenance Program Manual, PSM 1-82-7.

(iii) Bombardier Temporary Revision AWL 3-109, dated August 31, 2007, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1-83-7.

(iv) Bombardier Temporary Revision AWL 3-117, dated February 16, 2011, to Part 2, "Airworthiness Limitations," of the Bombardier Dash 8 Series 300 Maintenance Program Manual, PSM 1-83-7.

(v) Subject 5-FSL of Section 5, "Fuel System Limitations," of the "Airworthiness Limitations List," of the Bombardier Dash 8 Series 100 Maintenance Program Manual, PSM 1-8-7, Revision 18, dated February 23, 2012.

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 29, 2015.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-14-05 Pratt & Whitney: Amendment 39-18203; Docket No. FAA-2014-1127; Directorate Identifier 2014-NE-16-AD.

(a) Effective Date

This AD is effective August 25, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Pratt & Whitney (PW) JT8D-217C and JT8D-219 turbofan engines with low-pressure turbine (LPT) shaft part numbers 783319, 783319-001, 783319-003, 783319-004, 783320, 783320-001, 783320-003, 783320-004, 820514-001, 820514-003, 820514-004, or 820514-005, installed.

(d) Unsafe Condition

This AD was prompted by reports of cracking in the LPT shaft. We are issuing this AD to prevent failure of the LPT shaft, which could lead to an uncontained engine failure and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) If the LPT shaft has 15,000 or fewer cycles-since-new (CSN) on the effective date of this AD, remove it from service before it accumulates 20,000 CSN.

(2) If the LPT shaft has more than 15,000 CSN on the effective date of this AD, remove it from service before it accumulates 5,000 additional cycles in service, or at the next piece-part exposure after accumulating 20,000 CSN, whichever occurs first.

(3) After the effective date of this AD, do not install any LPT shaft listed in paragraph (c) of this AD that is at piece-part exposure and exceeds the new life limit of 20,000 CSN, into any engine.

(f) Definition

For the purpose of this AD, piece-part exposure is when the LPT shaft is completely disassembled from the engine.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Jo-Ann Theriault, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7105; fax: 781-238-7199; email: jo-ann.theriault@faa.gov.

(2) PW Service Bulletin No. JT8D 6504, dated November 5, 2014, which is not incorporated by reference in this AD, can be obtained from PW using the contact information in paragraph (h)(3) of this AD.

(3) For service information identified in this AD, contact Pratt & Whitney, 400 Main St., East Hartford, CT 06108; phone: 860-565-8770; fax: 860-565-4503.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(i) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 26, 2015.

Ann C. Mollica,
Acting Directorate Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2015-14-06 The Boeing Company: Amendment 39-18204; Docket No. FAA-2014-0926; Directorate Identifier 2014-NM-085-AD.

(a) Effective Date

This AD is effective August 20, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD.

(1) Model 747-8 and 747-8F series airplanes, as identified in Boeing Alert Service Bulletin 747-27A2506, dated February 3, 2014.

(2) Model 747-8 and 747-8F series airplanes, as identified in Boeing Service Bulletin 747-27A2513, Revision 1, dated July 18, 2014.

(3) Model 747-8 series airplanes that are operated less than 1,200 flight hours per calendar year.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by an analysis, which indicated that in a limited flight envelope with specific conditions, divergent flutter could occur during a high g-load maneuver in combination with certain system failures. We are issuing this AD to prevent certain system failures from resulting in divergent flutter, and subsequent loss of continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement of Lateral Control Electronic (LCE) Modules

For airplanes identified in paragraph (c)(1) of this AD: Within 12 months after the effective date of this AD, replace the LCE modules with new LCE modules having revised software, and do an operational test of the LCE modules, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-27A2506, dated February 3, 2014. If the operational test fails, before further flight, do corrective actions and repeat the operational test and applicable corrective actions until the operational test passes.

(h) Replacement of Inboard Elevator Power Control Packages (PCPs) and Installation of External Inboard Elevator Compensators

For airplanes identified in paragraph (c)(2) of this AD: Within 60 months after the effective date of this AD, replace both inboard elevator PCPs with new PCPs that have the internal compensators removed, install two larger external compensators for each PCP, and do an operational test of each inboard elevator PCP, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 747-27A2513, Revision 1, dated July 18, 2014. If the operational test fails, before further flight, do corrective actions and repeat the operational test and applicable corrective actions until the operational test passes.

(i) Revision to the Maintenance or Inspection Program

For all airplanes: Within 90 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate Item Numbers 27-CMR-10, "Lubricate inboard elevator hinge bearings," and 27-CMR-11, "Functional check of inboard elevator hinge bearing and power control unit rod end bearing free play," of Section G., "CMR Tasks," of the Boeing 747-8/8F Certification Maintenance Requirements (CMRs) Document D011U721-02-03, Revision December 2013. The initial compliance times and repetitive intervals for the lubrication and functional check are specified in paragraphs (i)(1) and (i)(2) of this AD.

(1) For airplanes identified in paragraphs (c)(1) and (c)(2) of this AD that are not identified in paragraph (c)(3) of this AD:

(i) The initial compliance time for the lubrication of the inboard elevator hinge bearings is within 18 months after the most recent lubrication. The repetitive lubrication intervals are specified in Item Number 27-CMR-10, "Lubricate inboard elevator hinge bearings," of Section G., "CMR Tasks," of the Boeing 747-8/8F Certification Maintenance Requirements (CMRs) Document D011U721-02-03, Revision December 2013.

(ii) The initial compliance time for the functional check of the inboard elevator hinge bearing and power control unit rod end bearing freeplay is within 12 months after the effective date of this AD. The repetitive functional check intervals are specified in Item Number 27-CMR-11, "Functional check of inboard elevator hinge bearing and power control unit rod end bearing free play," of Section G., "CMR Tasks," of the Boeing 747-8/8F Certification Maintenance Requirements, D011U721-02-03, Revision December 2013.

(2) For airplanes identified in paragraph (c)(3) of this AD:

(i) The initial compliance time for the lubrication of the inboard elevator hinge bearings is within 24 months after the most recent lubrication. Repeat the lubrication thereafter at intervals not to exceed 24 months.

(ii) The initial compliance time for the functional check of the inboard elevator hinge bearing and power control unit rod end bearing freeplay is within 36 months after the effective date of this AD. Repeat the functional check thereafter at intervals not to exceed 36 months.

(j) Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane an LCE having part number (P/N) CA49253-001 or CA49253-002, or an inboard elevator PCP having P/N 327400-1009.

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747-27A2513, dated February 4, 2014, which is not incorporated by reference in this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (l)(4)(i) and (l)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(m) Related Information

(1) For more information about this AD, contact Douglas Tsuji, Senior Aerospace Engineer, Systems and Equipment Branch, ANM-130S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6546; fax: 425-917-6590; email: douglas.tsuji@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-27A2506, dated February 3, 2014.

(ii) Boeing Service Bulletin 747-27A2513, Revision 1, dated July 18, 2014.

(iii) Boeing 747-8/8F Certification Maintenance Requirements (CMRs) Document D011U721-02-03, Revision December 2013.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 1, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-14-07 The Boeing Company: Amendment 39-18205; Docket No. FAA-2014-0428; Directorate Identifier 2014-NM-067-AD.

(a) Effective Date

This AD is effective August 20, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787-8 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin B787-81205-SB270020-00, Issue 002, dated February 12, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by reports of deficiencies in the flight control module (FCM) software. We are issuing this AD to correct deficiencies in the FCM software, which, if not corrected, could prevent continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) FCM Software Installation

Within 6 months after the effective date of this AD: Do the actions specified in paragraph (g)(1), (g)(2), (g)(3), or (g)(4) of this AD.

(1) Use the onboard data load function (ODLF) to install FCM Block Point 3 software (including FCM operational program software (OPS), FCM loadable diagnostic information (LDI) database (DB) software, and FCM air data reference function (ADRF) DB software), in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB270020-00, Issue 002, dated February 12, 2015.

(2) Use the ODLF to install FCM Block Point 4 software (including FCM OPS, FCM LDI DB software, FCM ADRF DB software, and central maintenance computer function (CMCF) LDI DB software), in accordance with the Accomplishment Instructions of Boeing Service Bulletin B787-81205-SB270023-00, Issue 001, dated July 24, 2014.

(3) Use the ODLF to install FCM Common Block Point 1 software (including FMC OPS, FCM LDI DB software, FCM Compatibility DB software, and CMCF LDI DB software), in accordance with the Accomplishment Instructions of Boeing Service Bulletin B787-81205-SB270027-00, Issue 002, dated March 9, 2015.

(4) Install any later FAA-approved FCM software version using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(h) Concurrent Requirements

For Group 1 airplanes, as identified in Boeing Alert Service Bulletin B787-81205-SB270020-00, Issue 002, dated February 12, 2015: Prior to or concurrently with accomplishing the actions required by paragraph (g) of this AD, use the ODLF to install FCM OPS, FCM LDI DB, and CMCF LDI DB software, or at a minimum install the FCM LDI DB and CMCF LDI DB software, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB270017-00, Issue 001, dated September 18, 2013.

(i) Parts Installation Prohibition

After installation of the software specified in paragraphs (g) and (h) of this AD, no person may install any previous versions of the FCM OPS, FCM LDI DB, FCM ADRF DB, or CMCF LDI DB software, on any airplane.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin B787-81205-SB270020-00, Issue 001, dated February 6, 2014; or Boeing Service Bulletin B787-81205-SB270027-00, Issue 001, dated September 26, 2014; which are not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) If the service information contains steps that are labeled as RC (Required for Compliance), those steps must be done to comply with this AD; any steps that are not labeled as RC are recommended. Those steps that are not labeled as RC may be deviated from using accepted methods different from those identified in the specified service information without obtaining approval of an AMOC, provided the steps labeled as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to steps labeled as RC require approval of an AMOC.

(l) Related Information

(1) For more information about this AD, contact Douglas Tsuji, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6546; fax: 425-917-6590; email: douglas.tsuji@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S. C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin B787-81205-SB270020-00, Issue 002, dated February 12, 2015.

(ii) Boeing Service Bulletin B787-81205-SB270023-00, Issue 001, dated July 24, 2014.

(iii) Boeing Service Bulletin B787-81205-SB270027-00, Issue 002, dated March 9, 2015.

(iv) Boeing Alert Service Bulletin B787-81205-SB270017-00, Issue 001, dated September 18, 2013.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 2, 2015.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-14-08 Airbus: Amendment 39-18206. Docket No. FAA-2015-0086; Directorate Identifier 2014-NM-191-AD.

(a) Effective Date

This AD becomes effective August 20, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A310-203 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Reason

This AD was prompted by reports that side link clevis bolts of the front engine mount do not meet the Design Service Goal (DSG) requirements on airplanes equipped with General Electric Company CF6-80A3 engines. We are issuing this AD to prevent failure of the front engine mount, and consequent possible departure of the engine.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Bolt Replacement

Within 18 months after the effective date of this AD, replace the side link clevis bolts, nuts, and bushings of the front engine mount on both engines, and re-identify the new installed bolts with a cross (to differentiate them from the old ones), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-71-2038, including Appendices 01 and 02, dated April 8, 2014. Repeat the replacement thereafter at intervals not to exceed 29 years.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your

request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0191, dated August 29, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0086-0003>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A310-71-2038, including Appendices 01 and 02, dated April 8, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 2, 2015.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-14-09 The Boeing Company: Amendment 39-18207; Docket No. FAA-2014-0780; Directorate Identifier 2014-NM-168-AD.

(a) Effective Date

This AD is effective August 17, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, 747SP, 747-8F, and 747-8 series airplanes, certificated in any category, equipped with a main deck side cargo door (MDSCD).

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by recent testing that indicates that intermodal containers, when loaded as cargo, under certain flight-load conditions, can shift and impact the adjacent fuselage frames. We are issuing this AD to prevent intermodal containers loaded in the offset method from shifting during flight gust loads and damaging fuselage frames, which could lead to the structural failure of the aft fuselage in flight, and subsequent in-flight breakup of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Airplane Flight Manual (AFM)

Within 14 days after the effective date of this AD, revise the Operating Limitations section of the FAA-approved AFM to include the information in figure 1 to paragraph (g) of this AD. This may be accomplished by inserting a copy of this AD into the Limitations section of the AFM.

Figure 1 to Paragraph (g) of This AD–AFM Revision

Unless approved by the Manager of the Seattle Aircraft Certification Office, the carriage of the following payloads is prohibited:

(1) Intermodal containers nominally sized at 20 feet long, 8 feet wide, and 8.5 feet tall that are not concentrically loaded on a pallet and restrained to the aircraft in accordance with the FAA-approved Boeing type certificate Weight and Balance Manual or a supplemental type certificate Weight and Balance Supplement.

(2) ISO 668-1CC containers that are not concentrically loaded on a pallet and restrained to the aircraft in accordance with the FAA-approved Boeing type certificate Weight and Balance Manual or a supplemental type certificate Weight and Balance Supplement.

Note: Both payloads 1 and 2 may be concentrically loaded on a pallet and netted in accordance with the FAA-approved Weight and Balance Manual and then loaded in the center of the airplane and restrained to the airplane by the approved center loaded cargo restraint system or restrained directly to the airplane, both as defined in the FAA-approved Weight and Balance Manual.

(h) Special Flight Permits

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed if any intermodal container prohibited as specified in figure 1 to paragraph (g) of this AD is on board. For special flight permits, carriage of freight is not allowed.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Steven C. Fox, Senior Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6425; fax: 425-917-6590; email: steven.fox@faa.gov.

(k) Material Incorporated by Reference

None.

Issued in Renton, Washington, on July 7, 2015.
 Jeffrey E. Duven,
 Manager, Transport Airplane Directorate,
 Aircraft Certification Service.



2015-15-01 The Boeing Company: Amendment 39-18210; Docket No. FAA-2014-1052; Directorate Identifier 2014-NM-140-AD.

(a) Effective Date

This AD is effective August 28, 2015.

(b) Affected ADs

This AD replaces AD 2004-13-02, Amendment 39-13682 (69 FR 35237, June 24, 2004).

(c) Applicability

This AD applies to The Boeing Company Model 747-100, -200B, and -200F series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) that indicates the longitudinal lap joints are subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking in the upper and lower skins of the fuselage lap joints, which could result in sudden fracture and failure of a lap joint and rapid in-flight decompression of the airplane fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections for Corrosion, and Corrective Actions

For airplanes identified as Groups 2 through 14 in Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014: Except as provided by paragraph (1)(3) of this AD, at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, do an external low frequency eddy current inspection for corrosion at the upper row of fasteners in the lap joint, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (1)(1) of this AD. Do all applicable corrective actions before further flight. Repeat the inspection at the upper row of fasteners in the lap joint thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph

(l)(3) of this AD. Accomplishment of a structural modification in accordance with Part 5 of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(1) of this AD, terminates the inspection requirements of this paragraph in the area of the modification only. The actions required by paragraph (j) of this AD are still applicable in the area of the modification.

(h) Inspections for Cracking, and Corrective Actions

For airplanes identified as Groups 2 through 14 in Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014: Except as provided by paragraph (l)(3) of this AD, at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, do an internal medium frequency eddy current inspection for skin cracks at the lower row of fasteners in the lap joint, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(1) of this AD. Do all applicable corrective actions before further flight. Repeat the inspection at the lower row of fasteners in the lap joint thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(3) of this AD. Accomplishment of a structural modification in accordance with Part 5 of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(1) of this AD, terminates the inspection requirements of this paragraph in the area of the modification only. The actions required by paragraph (j) of this AD are still applicable in the area of the modification.

(i) Structural Modification

For airplanes identified as Groups 2 through 14 in Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014: At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(2) of this AD, do a structural modification at the lap joints, and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(1) of this AD. Do all applicable corrective actions before further flight. Accomplishment of the structural modification required by this paragraph terminates the inspections required by paragraphs (g), (h), and (k) of this AD in the area of the modification only. The actions required by paragraph (j) of this AD are still applicable in the area of the modification.

(j) Post-Modification Inspections and Corrective Actions

For airplanes on which the actions required by paragraph (i) of this AD have been done: At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(2) of this AD, do an internal high frequency eddy current (HFEC) inspection for cracks of the skin or existing internal doublers, and an open-hole HFEC inspection for splice strap cracks, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014. If any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD. Repeat the inspections of the skin, internal doublers, and splice straps thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014.

(k) Post-Repair Inspections and Corrective Actions

For airplanes with any new or existing external doubler repair accomplished at a lap joint and the repair doubler length is 40 inches or longer: At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(2) of this AD, do an internal HFEC inspection for cracking or corrosion of the repairs, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(1) of this AD. Do all applicable corrective actions before further flight. Repeat the inspection of external doubler repairs accomplished at lap joints thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014. Accomplishment of a structural modification in accordance with Part 5 of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, except as provided by paragraph (l)(1) of this AD, terminates the inspection requirements of this paragraph in the area of the modification only. The actions required by paragraph (j) of this AD are still applicable in the area of the modification.

(l) Exceptions

(1) If, during any action required by this AD, Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, specifies to contact Boeing for an inspection or modification procedure, or repair instructions: Before further flight, do the inspection, or modification, or repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(2) Where Paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014, specifies a compliance time "after the Revision 2 date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(3) For the compliance threshold and repetitive interval calculations for inspections required by paragraphs (g) and (h) of this AD, the provisions specified in paragraphs (l)(3)(i) and (l)(3)(ii) of this AD apply regarding differential pressure.

(i) For inspections done before the effective date of this AD: Flight cycles in which the cabin differential pressure was at 2.0 pounds-per-square-inch (psi) or less need not be counted in the flight-cycle determination, provided that flight cycles with momentary spikes in cabin differential pressure above 2.0 psi were included as full pressure flight cycles. For this provision to apply, all cabin pressure records must have been maintained for each airplane. No fleet-averaging of cabin pressure is allowed.

(ii) For inspections done on or after the effective date of this AD: All flight cycles must be counted, regardless of differential pressure.

(m) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (m)(1) or (m)(2) of this AD.

(1) Boeing Alert Service Bulletin 747-53A2463, dated March 7, 2002, including Appendices A, B, and C, dated March 7, 2002, which was incorporated by reference in AD 2004-13-02, Amendment 39-13682 (69 FR 35237, June 24, 2004).

(2) Boeing Alert Service Bulletin 747-53A2463, Revision 1, dated April 16, 2009, which is not incorporated by reference in this AD.

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (o)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2004-13-02, Amendment 39-13682 (69 FR 35237, June 24, 2004), are approved as AMOCs for the corresponding provisions of paragraphs (g) and (h) of this AD.

(o) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: Bill.Ashforth@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-53A2463, Revision 2, dated June 16, 2014.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 10, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-15-02 Airbus: Amendment 39-18211. Docket No. FAA-2015-0679; Directorate Identifier 2013-NM-182-AD.

(a) Effective Date

This AD becomes effective August 28, 2015.

(b) Affected ADs

This AD replaces AD 2012-13-06, Amendment 39-17108 (77 FR 40485, July 10, 2012).

(c) Applicability

This AD applies to the airplanes specified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Airbus Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.

(2) Airbus Model A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R airplanes.

(3) Airbus Model A300 C4-605R Variant F airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Reason

This AD was prompted by a determination that the description of the inspection area specified in the service information was misleading; therefore, some operators might have inspected incorrect bonding leads. We are issuing this AD to detect and correct contact or chafing of wires and the bonding leads, which, if not detected, could be a source of sparks in the wing trailing edge, and could lead to an uncontrolled engine fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of the Fire Shut-Off Valve (FSOV) Bonding Leads

At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD: Do a one-time detailed inspection to determine the length of the FSOV bonding leads, and to detect contact or chafing of the wires located on the left-hand (LH) and right-hand (RH) sides of the wing rear spar, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-24-0106, Revision 01, dated March 26, 2013 (for Model A300 series airplanes); or Airbus Service Bulletin A300-24-6108, Revision 01, dated March 26, 2013 (for Model A300-600 series airplanes); as applicable.

(1) For airplanes on which the inspection required by paragraph (g) of AD 2012-13-06, Amendment 39-17108 (77 FR 40485, July 10, 2012), has not been done as of the effective date of this AD: Inspect within 4,500 flight hours or 30 months after August 14, 2012 (the effective date of AD 2012-13-06), whichever occurs first.

(2) For airplanes on which the inspection required by paragraph (g) of AD 2012-13-06, Amendment 39-17108 (77 FR 40485, July 10, 2012), has been done as of the effective date of this AD: Inspect within 4,500 flight hours or 30 months after the effective date of this AD, whichever occurs first.

(h) Corrective Action for FSOV Bonding Leads

If, during the inspection required by paragraph (g) of this AD, the length of the bonding lead(s) is more than 80 millimeters (mm) (3.15 inches): Before further flight, replace the bonding lead(s) with a new bonding lead having a length equal to 80 mm 2 mm (3.15 inches) 0.08 inch, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g) of this AD.

(i) Repair of the Wires of the LH and RH Sides

If, during the inspection required by paragraph (g) of this AD, any contact or chafing of the wires is found, repair the wires before further flight, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraph (g) of this AD.

(j) Parts Installation Prohibition

As of August 14, 2012 (the effective date of AD 2012-13-06, Amendment 39-17108 (77 FR 40485, July 10, 2012)), no person may install any bonding lead longer than 80 mm 2 mm (3.15 inches) 0.08 inch, located between the LH/RH engine hydraulic FSOV and wing rear spar in zones 575/675 on any airplane.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0204, dated September 6, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0679.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on August 28, 2015.

(i) Airbus Service Bulletin A300-24-0106, Revision 01, dated March 26, 2013.

(ii) Airbus Service Bulletin A300-24-6108, Revision 01, dated March 26, 2013.

(4) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 10, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-15-03 General Electric Company: Amendment 39-18212; Docket No. FAA-2015-0165; Directorate Identifier 2015-NE-02-AD.

(a) Effective Date

This AD is effective August 24, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all General Electric Company (GE) GENx-1B model turbofan engines with full authority digital engine control (FADEC) software version B175 or earlier, installed, and GENx-2B model turbofan engines with FADEC software version C065 or earlier, installed.

(d) Unsafe Condition

This AD was prompted by reports of GENx-1B and GENx-2B engines experiencing power loss in ice crystal icing (ICI) conditions. We are issuing this AD to prevent engine failure, loss of thrust control, and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Thirty days after the effective date of this AD, do not operate any GE GENx-1B engine with FADEC software version B175 or earlier, installed in the electronic engine control (EEC).

(2) Thirty days after the effective date of this AD, do not operate any GE GENx-2B engine with FADEC software version C065 or earlier, installed in the EEC.

(f) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(g) Related Information

(1) For more information about this AD, contact Christopher McGuire, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7120; fax: 781-238-7199; email: chris.mcguire@faa.gov.

(2) GE GENx-1B Service Bulletin (SB) No. 73-0036 R00, dated January 6, 2015, and GE GENx-2B SB No. 73-0035 R00, dated September 16, 2014, which are not incorporated by reference in this AD, can be obtained from GE using the contact information in paragraph (g)(3) of this AD.

(3) For service information identified in this proposed AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: geae.aoc@ge.com.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(h) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on July 13, 2015.

Carlos A. Pestana,
Acting Directorate Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2015-15-05 The Boeing Company: Amendment 39-18214; Docket No. FAA-2014-0572; Directorate Identifier 2014-NM-027-AD.

(a) Effective Date

This AD is effective August 28, 2015.

(b) Affected ADs

- (1) This AD replaces AD 98-22-10, Amendment 39-10858 (63 FR 57240, October 27, 1998).
- (2) This AD affects AD 90-06-02, Amendment 39-6489 (55 FR 8372, March 7, 1990).

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of fatigue cracking of the aft frame and frame support structure of the forward service doorway around the six doorstop fittings, and a determination that inspections are needed in additional locations and that additional airplanes might be subject to the identified unsafe condition. We are issuing this AD to detect and correct fatigue cracking of the aft frame and frame support structure of the forward service doorway around the six doorstop fittings, which could result in door deflection and loss of pressurization.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections and Corrective Actions

At the applicable times specified in tables 1 through 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, except as required by

paragraph (k)(1) of this AD: Do detailed inspections of the frame web between body station (STA) 332.1 and STA 344, intercostal T-brackets, intercostal T-chords, intercostals, and stringers, as applicable; do high frequency eddy current (HFEC) inspections for cracking of door stop intercostal T-brackets, intercostal web, door stop intercostal T-chords, intercostals, and stringers, as applicable; and do all applicable related investigative and corrective actions; in accordance with Parts 2 and 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, except as required by paragraphs (k)(2) through (k)(4) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections at the applicable times specified in tables 1 through 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, until the terminating action specified in paragraph (h) of this AD is done.

(h) Optional Terminating Action

For Group 1, Configuration 1; Group 1, Configuration 2; Group 2; Group 3; Group 4, Configuration 1; and Group 4, Configuration 2 airplanes identified in Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014: Accomplishment of a preventive modification in accordance with Part 5 of Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, terminates the repetitive inspections required by paragraph (g) of this AD.

(i) Inspections and Corrective Actions for Group 5 Airplanes

For Group 5 airplanes identified in Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014: Within 120 days after the effective date of this AD, inspect and repair any cracking using a method approved in accordance with the procedures specified in paragraph (m) of this AD. Repair any cracking, before further flight.

(j) Post Preventive Modification Inspections Not Required

The post preventive modification inspections specified in tables 9 through 12 in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1108, Revision 6, dated January 9, 2014; and Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014; are not required by this AD.

Note 1 to paragraph (j) of this AD: Tables 9 through 12 in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1108, Revision 6, dated January 9, 2014; and Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014; specify that post preventive modification inspections may be used in support of compliance with section 121.1109(c)(2) or 129.109(b)(2) of the Federal Aviation Regulations (14 CFR 121.1109(c)(2) or 14 CFR 129.109(b)(2)). The corresponding actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1108, Revision 6, dated January 9, 2014; and Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014; are not required by this AD.

(k) Exceptions to the Service Information

(1) Where Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, specifies a compliance time "after the issue date of Revision 6 of this service bulletin," this AD requires compliance within the specified time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, specifies to contact Boeing for repair instructions: Before further flight, repair the cracking using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(3) Where Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, specifies accomplishment of a preventative modification in accordance with "Revision 6 of this service bulletin," this AD requires accomplishment of those actions to be done in accordance with Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014.

(4) Where table 4 in paragraph 1.E, "Compliance," of Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, specifies repairing a condition identified as any crack found in "an intercostal," this AD requires repairing a condition identified as any crack found in "an intercostal or attaching stringers."

(l) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737-53A1108, Revision 6, dated January 9, 2014. This service information is not incorporated by reference in this AD.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (n)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 98-22-10, Amendment 39-10858 (63 FR 57240, October 27, 1998), are approved as AMOCs for the corresponding provisions of this AD.

(5) Accomplishment of the preventive modification in accordance with Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014, as required by paragraph (h) of this AD, is an AMOC for the structural modification specified in Boeing Alert Service Bulletin 737-53A1108 that is required by paragraph A. of AD 90-06-02, Amendment 39-6489, (55 FR 8372, March 7, 1990), for the airplanes identified in paragraph (h) of this AD.

(n) Related Information

(1) For more information about this AD, contact Nenita Odesa, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5234; fax: 562-627-5210; email: nenita.odesa@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraph (o)(3) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1108, Revision 7, dated July 7, 2014. (ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 10, 2015.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



AD 2015-15-08 Bombardier, Inc.: Amendment 39-18217. Docket No. FAA-2015-0088; Directorate Identifier 2014-NM-179-AD.

(a) Effective Date

This AD becomes effective August 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-100-1A10 (Challenger 300) airplanes, equipped with a spoiler electronic control unit (SECU) having part number (P/N) C47330-006, C47330-007, or C47330-008; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Reason

This AD was prompted by testing of the spoiler electronic control unit (SECU) software for an upgrade, which revealed a timing error between the command and monitor channels. We are issuing this AD to prevent a timing error in the SECU software, which, in combination with failure of the roll disconnect switch, could result in complete loss of spoiler functionality and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Maintenance or Inspection Program

Within 600 flight hours since the most recent operational test of the aileron disconnect system for spoiler functionality as of the effective date of this AD, or within 400 flight hours after the effective date of this AD, whichever occurs first: Revise the maintenance or inspection program, as applicable, to incorporate repetitive operational tests of the aileron disconnect system for spoiler functionality, and all applicable corrective actions, using a method approved by the Manager, New York ACO, ANE-170, FAA.

Note 1 to paragraph (g) of this AD: Guidance on operational tests of the aileron disconnect system can be found in the Bombardier Inc., BD-100-1A10 Time Limits/Maintenance Checks (TLMC) Manual.

(h) Modification of the SECU

Within 1,600 flight hours or 48 months after the effective date of this AD, whichever occurs first: Modify and re-identify the SECU, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 100-27-16, dated October 31, 2013. Doing the actions required by this paragraph terminates the actions required by paragraph (g) of this AD.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install an SECU, P/N C47330-006, C47330-007, or C47330-008, on any airplane.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-24, dated August 5, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2015-0088-0002.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 100-27-16, dated October 31, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 15, 2015.
Suzanne Masterson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-15-09 BAE Systems (Operations) Limited: Amendment 39-18218. Docket No. FAA-2015-2957; Directorate Identifier 2015-NM-089-AD.

(a) Effective Date

This AD becomes effective August 10, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to BAE Systems (Operations) Limited Model 4101 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by a report that the pitch trim jammed in the fully down position due to incorrectly adjusted travel stops of the pitch trim servo motor, causing parts of the stop plates to break off and allowing the servo motor to force contact of the swaged stop on the trim cable with the stop plates. We are issuing this AD to detect and correct broken stop arms of the stop plates, which could lead to the pitch trim jamming, loss of control of the elevator trim, and possible reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One-Time Inspection

Within 30 days after the effective date of this AD: Do a one-time detailed inspection for damage of the stop arms of the stop plates, and an adjustment of the electric trim limit switches, in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin J41-27-068, dated January 21, 2014. If any damage is found, before further flight, replace the stop plate with a newly manufactured stop plate made of tufnol, in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin J41-27-068, dated January 21, 2014.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1175; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or BAE Systems (Operations) Limited's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015-0099, dated June 3, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-2957.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) BAE Systems (Operations) Limited Inspection Service Bulletin J41-27-068, dated January 21, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone: +44 1292 675207; fax: +44 1292 675704; email: RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 15, 2015.

Suzanne Masterson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-15-10 Airbus: Amendment 39-18219. Docket No. FAA-2014-0748; Directorate Identifier 2014-NM-013-AD.

(a) Effective Date

This AD becomes effective August 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), (c)(3), and (c)(4) of this AD, all manufacturer serial numbers.

- (1) Model A318-111, -112, -121, and -122 airplanes.
- (2) Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.
- (3) Model A320-211, -212, -214, -231, -232, and -233 airplanes.
- (4) Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Reason

This AD was prompted by reports of wear of the trimmable horizontal stabilizer actuator (THSA). We are issuing this AD to detect and correct wear on the THSA, which would reduce the remaining life of the THSA, possibly resulting in premature failure and consequent reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Initial Inspections

At the later of the times specified in paragraphs (g)(1) and (g)(2) of this AD: Do a detailed inspection of the magnetic chip detector for metal particles, a spectrometric analysis of the oil drained from the THSA gearbox, a detailed inspection of the ballscrew and nut for damage (including, but not limited to, cracks, dents, corrosion, and unsatisfactory surface protection), and a detailed inspection of the upper and the lower attachments for damage (including, but not limited to, cracks, dents, corrosion, and unsatisfactory surface protection), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013.

(1) Before the THSA accumulates 48,000 total flight hours or 30,000 total flight cycles, whichever occurs first since first installation on an airplane.

(2) Within 4 months after the effective date of this AD.

(h) Repetitive Inspections

Repeat the inspections required by paragraph (g) of this AD thereafter at intervals not to exceed the applicable time specified in paragraphs (h)(1) and (h)(2) of this AD.

(1) For a THSA that, as of the date of the most recent inspection required by paragraph (g) or (h) of this AD, has accumulated less than 67,500 total flight hours since first installation on an airplane: The repetitive inspection interval is 24 months.

(2) For a THSA that, as of the date of the most recent inspection required by paragraph (g) or (h) of this AD, has accumulated 67,500 total flight hours or more since first installation on an airplane: The repetitive inspection interval is 4 months.

(i) THSA Corrective Action

If, during any inspection required by paragraphs (g) and (h) of this AD, any finding as described in the Accomplishment Instructions of Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013, is found: At the applicable compliance time (depending on the applicable findings) specified in paragraph 1.E., "Compliance," of Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013, replace the THSA with a serviceable THSA, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013. For the purposes of this AD, a serviceable THSA is a THSA that has accumulated less than 67,500 total flight hours since first installation on an airplane.

(j) THSA Replacement

Before a THSA accumulates 67,500 total flight hours since first installation on an airplane, or within 12 months after the effective date of this AD, whichever occurs later: Replace the THSA with a serviceable THSA, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013. Thereafter, before the accumulation of 67,500 total flight hours on any THSA since first installation on an airplane, replace it with a serviceable THSA.

(k) Replacement THSA: No Terminating Action

Replacement of a THSA on an airplane, as required by paragraph (i) or (j) of this AD, does not constitute terminating action for the repetitive inspections required by paragraphs (g) and (h) of this AD for that airplane. After THSA replacement: At the applicable compliance time specified in paragraphs (g)(1), (g)(2), (h)(1), and (h)(2) of this AD, do the inspections required by paragraphs (g) and (h) of this AD.

(l) Replacement THSA Equivalency

A THSA that has been repaired in shop as specified in United Technologies Corporation Aerospace Systems Component Maintenance Manual 27-44-51 is considered equivalent to having passed an inspection in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013. Depending on the flight hours or flight cycles accumulated by the repaired THSA: At the applicable compliance time specified in paragraphs (g)(1), (g)(2), (h)(1), and (h)(2) of this AD, do the inspections required by paragraphs (g) and (h) of this AD.

(m) Parts Installation Limitation

As of the effective date of this AD, installation on an airplane of a THSA that has accumulated 67,500 or more total flight hours is allowed, provided that, prior to installation, the THSA has been modified or inspected using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(n) Credit for Previous Actions

This paragraph provides credit for inspections required by paragraphs (g), (h), and (l) of this AD, if those inspections were performed before the effective date of this AD using Airbus Service Bulletin A320-27-1227, dated July 1, 2013, which is not incorporated by reference in this AD.

(o) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(p) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0011R1, dated January 17, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0748-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (q)(3) and (q)(4) of this AD.

(q) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320-27-1227, Revision 01, dated October 7, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 12, 2015.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.