

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT**

**BIWEEKLY 2020-11**

*5/11/2020 - 5/24/2020*



Federal Aviation Administration  
Continued Operational Safety Policy Section, AIR-141  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

### MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
<b>Biweekly 2020-01</b>			
2019-23-04		The Boeing Company	727, 727-100, 727C, 727-100C, 727-200, and 727-200F
2019-23-16		The Boeing Company	737-100, -200, -200C, -300, -400, and -500
2019-24-12		De Havilland Aircraft of Canada Limited	DHC-8-401 and -402
2019-24-13		Airbus SAS	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -216, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2019-24-14		328 Support Services GmbH	328-100
2019-24-15		The Boeing Company	737-900ER
2019-24-16	R 2017-16-08	Embraer S.A	ERJ 190-100 STD, -100 LR, -100 ECJ, and -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2019-24-18		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F, 757-200, -200PF, -200CB, and -300, 767-200, -300, -300F, and -400ER
2019-25-13		Engine Alliance	GP7270 and GP7277
2019-25-17		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER
<b>Biweekly 2020-02</b>			
2019-22-07		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), Model CL-600-2D24 (Regional Jet Series 900), Model CL-600-2E25 (Regional Jet Series 1000)
2019-23-14		The Boeing Company	37-100, -200, -200C, -300, -400, and -500
2019-24-01		Airbus SAS	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -231, -212, -213, and -232, A330-201, -202, -203, -223, -223F, -243, and -243F, A340-211, -212, -213, -311, -312, -313, -541, and -642
2019-25-10		Fokker Services B.V	F28 Mark 0070 and 0100
2019-25-11		Viking Air Limited	CL-215-1A10, CL-215-6B11 (CL-215T Variant)
2019-25-12	R 2016-18-02	The Boeing Company	777-200 and -300ER
2019-25-14		The Boeing Company	777-300ER and 777F
2019-25-15		Fokker Services B.V	F28 Mark 0100
2019-25-16	R 2017-06-08	Embraer S.A	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU airplanes; and Model ERJ 170-200 LR, -200 SU, -200 STD, and -200 LL
2019-25-18		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2019-25-19		Airbus SAS	A350-941
2020-01-11	R 2017-12-07	The Boeing Company	737-800, -900, and -900ER
2020-01-55	E	General Electric Company	GE90-110B1 and GE90-115B
<b>Biweekly 2020-03</b>			
2019-25-20		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G; C-130A, C-130B, C-130BL, C-130E, C-130H, C-130H-30, C-130J, C-130J-30, EC-130Q, HC-130H, KC-130H, NC-130B, NC-130, and WC-130H airplanes
2019-25-55		The Boeing Company	737-300, -400, and -700 series airplanes
2019-26-01		Airbus SAS	A350-941 and -1041 airplanes
2020-01-12	A 2017-16-12	Airbus SAS	A318, A319, A320, A321 airplanes
2020-01-13	R 2018-19-26	Dassault Aviation	MYSTERE-FALCON 200 airplanes
2020-01-14	A 2010-26-05	Airbus SAS	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2020-01-17		Airbus SAS	A318, A319, A320, A321 airplanes
2020-01-18	R 2006-11-11	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

### Biweekly 2020-04

2019-26-10		Bombardier, Inc.	CL-600-2C10, -2D15, -2D25, -2E25 airplanes
2019-26-11		Airbus SAS	A319, A320, A321 airplanes
2020-01-10		Airbus SAS	A350-941 airplanes
2020-01-15		Airbus SAS	A300, A310 airplanes
2020-01-16	A 2014-25-52	Airbus SAS	A330, A340 airplanes
2020-01-55		General Electric Company	GE90-110B1 and GE90-115B model turbofan engines
2020-02-10		De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402 airplanes
2020-02-12	R 2017-15-04	The Boeing Company	787 series airplanes
2020-02-13	R 2019-03-14 A 2010-26-05	Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G airplanes
2020-02-14		Airbus SAS	A350-941 and -1041 airplanes
2020-02-15		Bombardier, Inc.	BD-700-1A10, BD-700-1A11 airplanes
2020-02-16		The Boeing Company	737-200, -200C, -300, -400, and -500 series airplanes
2020-02-18		Gulfstream Aerospace Corporation	GVI, GVII-G500, and GVII-G600 airplanes
2020-02-19	R 2003-09-04 R1	Bombardier, Inc.	CL-600-2B19 airplanes
2020-02-20	R 2014-24-07	Airbus SAS	A318, A319, A320, A321 airplanes
2020-02-21	R 2014-03-12 R 2018-19-25 A 2010-26-05	Dassault Aviation	FALCON 2000 airplanes
2020-02-22		Airbus SAS	A300, A310 airplanes
2020-03-11		The Boeing Company	707-100 long body, -200, -100B long body, -100B short body, -300, -300B, -300C, and -400 series; and 720 and 720B series airplanes
2020-03-12		Airbus SAS	A350-941 and -1041 airplanes

### Biweekly 2020-05

2020-01-18	COR R 2006-11-11	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2020-02-19	COR R 2003-09-04 R1	Bombardier, Inc.	CL-600-2B19 (Regional Jet series 100 & 440) airplanes
2020-03-10		The Boeing Company	737 series, except for 737-100, -200, -200C, -300, -400, and -500 series airplanes
2020-03-14		Airbus SAS	A350-941 and -1041 airplanes
2020-03-15		Airbus SAS	A321-211, -212, -213, -231, and -232 airplanes
2020-03-17	R 2015-24-04	Bombardier, Inc.	CL-600-2B19, -2C10, -2D15, -2D25, -2E25 airplanes
2020-03-18	R 2017-19-08	Airbus Defense and Space S.A.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes
2020-03-19	A 2010-26-05	Dassault Aviation	MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
2020-03-20		The Boeing Company	MD-11, MD-11F, 717-200, 737-8, 737-9, 737-600, -700, -700C, -800, -900, and -900ER; 747-400 and 747-400F; 757-200, -200PF, -200CB, and -300; 767-200, -300, -300F, -400ER, and -2C; 777-200, -200LR, -300, and -300ER; 777F series airplanes
2020-03-21		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2020-03-22		The Boeing Company	787-8 airplanes
2020-03-23		Bombardier, Inc.	CL-600-2B19
2020-03-24	A 2010-26-05	Dassault Aviation	MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
2020-04-01		Pratt & Whitney	PW1519G, PW1521G, PW1521GA, PW1524G, PW1525G, PW1521G-3, PW1524G-3, PW1525G-3, PW1919G, PW1921G, PW1922G, PW1923G, and PW1923G-A model turbofan engines

### Biweekly 2020-06

2020-04-10	A 2011-03-10	Airbus SAS	A330 airplanes
2020-04-11		The Boeing Company	747-400 series airplanes
2020-04-12	R 2012-22-05 R 2018-19-03	Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes
2020-04-18		Airbus SAS	A330-941 airplanes

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2020-05-01		Rolls-Royce Deutschland Ltd & Co KG	Trent 1000-AE3, Trent 1000-CE3, Trent 1000-D3, Trent 1000-G3, Trent 1000-H3, Trent 1000-J3, Trent 1000-K3, Trent 1000-L3, Trent 1000-M3, Trent 1000-N3, Trent 1000-P3, Trent 1000-Q3, and Trent 1000-R3 model turbofan engines
2020-05-10		Dassault Aviation	FALCON 7X airplanes
2020-05-12		Gulfstream Aerospace Corporation	GVII-G500 and GVII-G600 airplanes
2020-05-13		Airbus Canada Limited Partnership	BD-500-1A11 airplanes
2020-05-14		Airbus SAS	A320-214, -232, -271N; A321-231 airplanes
2020-05-18		Airbus SAS	A350-941 and -1041 airplanes
2020-06-01	R 2018-25-09 R 2019-12-01	CFM International, S.A.	LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B3, -1B28B2C, -1B28BBJ1, and -1B28BBJ2 model turbofan engines
<b>Biweekly 2020-07</b>			
2020-04-19	R 2017-15-01	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series airplanes
2020-05-13		Airbus Canada Limited Partnership	BD-500-1A11 airplanes
2020-05-14		Airbus SAS	A320-214, -232, -271N; A321-231 airplanes
2020-05-15		Airbus SAS	A319-131, -132, -133; A320-231, -232, -233; and A321-131, -231, -232 airplanes
2020-05-16		Airbus SAS	A319-115; A320-214, -216, -232, -251N, -271N; and A321-211, -231, -251N, -251NX, -253N, -271N, -271NX, -272N airplanes
2020-05-17		Airbus SAS	A318-112, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-216, A320-231, A320-232, A320-233, A320-251N, and A320-271N airplanes
2020-05-18		Airbus SAS	A350-941 and -1041 airplanes
2020-05-19		Airbus SAS	A319-112, -115, -132; and A320-214, -216, -232 -233 airplanes
2020-05-21		Yaborã Indústria Aeronáutica S.A.	ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes
2020-05-22		Yaborã Indústria Aeronáutica S.A.	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU; and ERJ 170-200 LR, -200 SU, -200 STD, -200 LL airplanes
2020-05-24	R 2010-26-01	The Boeing Company	777-200 series airplanes
2020-05-28	R 2019-11-08	International Aero Engines LLC	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2020-06-02		International Aero Engines LLC	PW1122G-JM, PW1124G1-JM, PW1124G-JM, PW1127GA-JM, PW1127G1-JM, PW1127G-JM, PW1133G-JM, PW1133GA-JM, PW1130G-JM, and PW1129G-JM turbofan engines
2020-06-14		The Boeing Company	787-8, 787-9, and 787-10 airplanes
2020-07-51	E	International Aero Engines AG	V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5 turbofan engines
<b>Biweekly 2020-08</b>			
2020-04-15		The Boeing Company	757-200, -200PF, -200CB, and -300 series; 767-200, -300, and -300F series airplanes
2020-04-16		Yaborã Indústria Aeronáutica S.A.	ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes
2020-04-17		Airbus SAS Model	A350-941 and -1041 airplanes
2020-04-20		De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402 airplanes
2020-04-22	R 2018-19-27 R 2014-16-12 A 2010-26-05	Dassault Aviation	FALCON 2000EX airplanes
2020-05-25		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2020-05-26		The Boeing Company	787-8 airplanes

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2020-05-27 2020-06-10		Bombardier, Inc. Airbus SAS	BD-700-1A10 and BD-700-1A11 airplanes A318-111, -112, -121, and -122; A319-111, -112, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -216, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2020-06-15 2020-06-16	R 2017-03-02	Fokker Services B.V. Rolls-Royce Deutschland Ltd. & Co. KG	F28 Mark 0100 airplanes RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2020-06-17	R 2011-09-06	Airbus SAS	A330-223F and -243F; A330-201, -202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A330-941; A340-211, -212, and -213; A340-311, -312, and -313; A340-541 and -642 airplanes
2020-06-18		Airbus SAS	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, -133, -151N, -153N, and -171N; A320-211, -212, -214, -216, -231, -232, -233, -251N, -252N, -253N, -271N, -272N, and -273N; A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes
2020-07-02		Pratt & Whitney	PW1519G, PW1521G, PW1521G-3, PW1521GA, PW1524G, PW1524G-3, PW1525G, and PW1525G-3 turbofan engines
2020-07-10 2020-08-01		Airbus SAS General Electric Company	A320-271N; A321-271N, -271NX, and -272N airplanes CF34-1A, CF34-3A, CF34-3A1, CF34-3A2, CF34-3B, and CF34-3B1 turbofan engines
<b>Biweekly 2020-09</b>			
2020-07-11		ATR–GIE Avions de Transport Regional	ATR42-200, -300, -320, and -500; ATR72-101, -102, -201, -202, -211, -212, and -212A
2020-07-12		ATR–GIE Avions de Transport Regional	ATR42-500
2020-07-13 2020-07-14		Bombardier, Inc The Boeing Company	BD-100-1A10 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2020-07-16	R 2016-16-09 R 2019-03-20 A 2014-16-23	Dassault Aviation	FALCON 7X
2020-07-17 2020-07-18	R 2017-05-12	Saab AB, Support and Services Airbus SAS	SAAB 2000 A318-112; A319-111, -112, -115, -132, and -133; A320-214, -216, -232, and -233; A321-211, -212, -213, -231, and -232
2020-07-19		ATR–GIE Avions de Transport Regional	ATR72-101, -102, -201, -202, -211, -212, and -212A
2020-07-20	R 2004-06-01 R 2009-06-09 A 2008-17-01 R1 A 2012-01-08	Support Services GmbH	328-100
2020-07-21		Yabora Industria Aeronautica S.A.	ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU; ERJ 170-200 LR, -200 SU, -200 STD, and -200 LL; ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, -200 STD, -200 LR, and -200 IGW
2020-07-51		International Aero Engines AG	V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, and V2533-A5
2020-08-02		Thales AVS France SAS	Global Positioning System/Satellite Based Augmentation System receivers
2020-08-03	R 2008-22-24	Rolls-Royce Deutschland Ltd & Co KG	RB211-535E4-37, RB211-535E4-B-37, RB211-535E4-C-37, and RB-211-535E4-B-75
2020-08-04		International Aero Engines LLC	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM
2020-09-03		International Aero Engines AG	V2500-A1, V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2531-E5, and V2533-A5

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects

### Biweekly 2020-10

2020-08-11		Yabora Industria Aeronautica S.A.	ERJ 190-300 and ERJ 190-400
2020-08-12		The Boeing Company	747-8 and 747-8F series
2020-08-13		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440); CL-600-2C10 (Regional Jet Series 700, 701 & 702); CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)

### Biweekly 2020-11

2020-06-19		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2020-09-10	R 2018-25-04	Airbus Canada Limited Partnership	BD-500-1A10; BD-500-1A11
2020-09-11	R 2017-06-06 R 2019-12-10 A 2012-12-07	Fokker Services B.V.	F28 Mark 0070 and 0100
2020-09-12		De Havilland Aircraft of Canada Limited	DHC-8-400, -401, and -402 series
2020-09-13	A 2009-01-06 R1 A 2012-01-08	328 Support Services GmbH	328-300
2020-09-14	R 2020-03-12	Airbus SAS	A350-941 and -1041
2020-09-16	R 2000-17-09 R 2008-04-19 R1 R 2015-26-09 A 2018-18-05	ATR-GIE Avions de Transport Regional	ATR42-200, -300, and -320
2020-10-04		General Electric Company	GE90-110B1 and GE90-115B
2020-10-05		Rockwell Collins, Inc.	Flight Management Systems
2020-10-10	R 2016-07-28	The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87)
2020-11-04		Learjet Inc.	60



**2020-06-19 The Boeing Company:** Amendment 39-19888; Docket No. FAA-2019-1072; Product Identifier 2019-NM-181-AD.

**(a) Effective Date**

This AD is effective June 22, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes, certificated in any category, variable numbers QB065, QD191, QD192, QD402, QD403, QD407, and QD410.

**(d) Subject**

Air Transport Association (ATA) of America Code 34, Navigation.

**(e) Unsafe Condition**

This AD was prompted by reports of nuisance stick shaker activation while the airplane accelerated to cruise speed at the top of climb. This AD was also prompted by an investigation of those reports that revealed that the angle of attack (AOA) (also known as angle of airflow) sensor vanes could not prevent the build-up of ice, causing the AOA sensor vanes to become immobilized, which resulted in nuisance stick shaker activation. The FAA is issuing this AD to address ice buildup in the AOA sensor faceplate and vane, which may immobilize the AOA sensor vanes, and could result in inaccurate or unreliable AOA sensor data being transmitted to airplane systems and consequent loss of controllability of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified in paragraph (h) of this AD: Within 36 months after the effective date of this AD or at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 727-34A0247, Revision 1, dated October 1, 2019, whichever occurs first, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 727-34A0247, Revision 1, dated October 1, 2019.

## **(h) Exceptions to Service Information Specifications**

Where Boeing Alert Service Bulletin 727-34A0247, Revision 1, dated October 1, 2019, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD.”

## **(i) Credit for Previous Actions**

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 727-34A0247, dated January 2, 2019.

## **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

## **(k) Related Information**

(1) For more information about this AD, contact Jeffrey W. Palmer, Aerospace Engineer, Systems and Equipment Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5351; fax: 562-627-5210; email: Jeffrey.W.Palmer@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(4) and (5) of this AD.

**(I) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on February 3, 2020 (84 FR 71778, December 30, 2019).

(i) Boeing Alert Service Bulletin 727-34A0247, Revision 1, dated October 1, 2019.

(ii) [Reserved]

(4) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(5) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 27, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10604 Filed 5-15-20; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2020-09-10 Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.):** Amendment 39-19906; Docket No. FAA-2020-0349; Product Identifier 2020-NM-027-AD.

### **(a) Effective Date**

This AD is effective May 26, 2020.

### **(b) Affected ADs**

This AD replaces AD 2018-25-04, Amendment 39-19515 (83 FR 63397, December 10, 2018) (“AD 2018-25-04”).

### **(c) Applicability**

This AD applies to Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) airplanes, certificated in any category, identified in paragraphs (c)(1) and (2) of this AD.

(1) Model BD-500-1A10 airplanes, serial numbers 50001 through 50017 inclusive, equipped with blow-out panel part number D762213-503, D762216-505, or D762209-503.

(2) Model BD-500-1A11 airplanes, serial numbers 55001 through 55044 inclusive, equipped with blow-out panel part number D762213-503, D762216-505, or D762209-503.

### **(d) Subject**

Air Transport Association (ATA) of America Code 50, Cargo and accessory compartment.

### **(e) Reason**

This AD was prompted by reports of dislodged cargo compartment blow-out panels. This AD was also prompted by a panel redesign that decreases the likelihood of dislodgement due to baggage impact, and by the determination that the repetitive inspection interval may be extended, based on in-service findings. The FAA is issuing this AD to address dislodged cargo compartment blow-out panels, which could result in openings in the forward and aft cargo compartments. In the event of a cargo compartment fire, these unintended openings in the forward and aft cargo compartments would provide a path for smoke, fire, and Halon to enter the adjacent equipment bays, flight deck, and passenger cabin, which could delay smoke detection in the forward and aft cargo compartments and result in the forward and aft cargo compartments not being able to maintain the Halon concentration required for fire suppression. The cargo compartment fire may become uncontrollable if this condition is not addressed, which could result in the loss of controllability of the airplane.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Repetitive Inspections of the Forward and Aft Cargo Compartment Blow-Out Panels and Re-Installation, With Revised Repetitive Inspection Interval**

This paragraph restates the requirements of paragraph (g) of AD 2018-25-04, with a revised repetitive inspection interval. Within 7 days or 50 flight cycles, whichever occurs first, after January 14, 2019 (the effective date of AD 2018-25-04): Do a detailed inspection for any dislodged blow-out panel in the forward and aft cargo compartments, in accordance with C Series (Bombardier) Data Module BD500-A-J50-10-01-01AAA-310B-A, "Forward and aft cargo compartment blow-out panels–Visual check," Issue 002, dated May 16, 2018. Re-install all dislodged forward and aft cargo compartment blow-out panels before further flight, in accordance with C Series (Bombardier) Data Module BD500-A-J50-10-01-00AAA-521A-A, "Decompression panels dislodging–Return to basic configuration," Issue 002, dated May 16, 2018. Thereafter, at intervals not to exceed 200 flight cycles, repeat the detailed inspection for any dislodged blow-out panel in the forward and aft cargo compartments.

**(h) New Requirement of This AD: Blow-Out Panel Replacement**

Within 9,350 flight hours or 56 months, whichever occurs first, after the date of issuance of the original airworthiness certificate or date of issuance of the original export certificate of airworthiness: Install new, redesigned sidewall and bulkhead panel assemblies in the forward and aft cargo compartments, in accordance with Airbus Canada Limited Partnership A220 Service Bulletin BD500-500001, Issue 002, dated October 28, 2019.

**(i) No Reporting Requirement**

Although reporting was required in AD 2018-25-04, this AD does not include that requirement.

**(j) New Terminating Action for Repetitive Inspections**

Modification of an airplane as required by paragraph (h) of this AD constitutes terminating action for the initial and repetitive inspections required by paragraph (g) of this AD for that airplane.

**(k) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier C Series Service Bulletin BD500-500001, Issue 001, dated February 18, 2019.

**(l) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Airbus Canada Limited Partnership's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(m) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-15R1, dated January 3, 2020, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0349.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Admin Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(5) and (6) of this AD.

**(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on May 26, 2020.

(i) Airbus Canada Limited Partnership A220 Service Bulletin BD500-500001, Issue 002, dated October 28, 2019.

(ii) [Reserved]

(4) The following service information was approved for IBR on January 14, 2019 (83 FR 63397, December 10, 2018).

(i) C Series (Bombardier) Data Module BD500-A-J50-10-01-00AAA-521A-A, "Decompression panels dislodging–Return to basic configuration," Issue 002, dated May 16, 2018.

(ii) C Series (Bombardier) Data Module BD500-A-J50-10-01-01AAA-310B-A, "Forward and aft cargo compartment blow-out panels–Visual check," Issue 002, dated May 16, 2018.

(5) For service information identified in this AD, contact Airbus Canada Limited Partnership, 13100 Henri-Fabre Boulevard, Mirabel, Québec, J7N 3C6, Canada; telephone 450-476-7676; email a220\_crc@abc.airbus; internet <http://a220world.airbus.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 28, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-09946 Filed 5-8-20; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2020-09-11 Fokker Services B.V.:** Amendment 39-19907; Docket No. FAA-2020-0450; Product Identifier 2020-NM-034-AD.

### **(a) Effective Date**

This AD becomes effective June 4, 2020.

### **(b) Affected ADs**

(1) This AD replaces AD 2017-06-06, Amendment 39-18830 (83 FR 8328, February 27, 2018) (“AD 2017-06-06”); and AD 2019-12-10, Amendment 39-19665 (84 FR 30588, June 27, 2019) (“AD 2019-12-10”).

(2) This AD affects AD 2012-12-07, Amendment 39-17087 (77 FR 37788, June 25, 2012) (“AD 2012-12-07”).

### **(c) Applicability**

This AD applies to all Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category.

### **(d) Subject**

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

### **(e) Reason**

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Retained Maintenance or Inspection Program Revision, With No Changes**

This paragraph restates the requirements of paragraph (g) of AD 2019-12-10, with no changes. Within 90 days after August 1, 2019 (the effective date of AD 2019-12-10), revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Fokker Engineering Report SE-623, Fokker 70/100 Airworthiness Limitations Section, Part 2—(Structure ALIs and Safe Life Items), Issue 18, dated June 14, 2018. Accomplishing the maintenance or inspection program revision required by paragraph (i) of this AD terminates the requirements of this paragraph.

(1) The initial compliance time for doing the tasks is at the time specified in Fokker Engineering Report SE-623, Fokker 70/100 Airworthiness Limitations Section, Part 2—(Structure ALIs and Safe

Life Items), Issue 18, dated June 14, 2018, or within 90 days after August 1, 2019, whichever occurs later.

(2) If any discrepancy is found, before further flight, repair using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### **(h) Retained Restrictions on Alternative Actions and Intervals, With a New Exception**

This paragraph restates the requirements of paragraph (h) of AD 2019-12-10, with a new exception. Except as required by paragraph (i) of this AD, after the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (m)(1) of this AD.

#### **(i) New Maintenance or Inspection Program Revision**

Except as specified in paragraph (j) of this AD: Comply with all required actions and compliance times specified in, and in accordance with EASA AD 2020-0024, dated February 13, 2020 ("EASA AD 2020-0024"). Accomplishing the maintenance or inspection program revision required by this paragraph terminates the requirements of paragraph (g) of this AD.

#### **(j) Exceptions to EASA AD 2020-0024**

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2020-0024 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2020-0024 specifies revising "the AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the "limitations, tasks and associated thresholds and intervals" specified in paragraph (3) of EASA AD 2020-0024 within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2020-0024 is at the applicable "associated thresholds" specified in paragraph (3) of EASA AD 2020-0024, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2020-0024 do not apply to this AD.

(5) The "Remarks" section of EASA AD 2020-0024 does not apply to this AD.

#### **(k) New Provisions for Alternative Actions or Intervals**

After the existing maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2020-0024.

#### **(l) Terminating Action for Certain Requirements of AD 2012-12-07**

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates the requirements of paragraph (g) of AD 2012-12-07.

#### **(m) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (n) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2019-12-10 are approved as AMOCs for the corresponding provisions of EASA AD 2020-0024 that are required by paragraph (i) of this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Fokker's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

#### **(n) Related Information**

For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3226; email: tom.rodriguez@faa.gov.

#### **(o) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on June 4, 2020.

(i) European Union Aviation Safety Agency (EASA) AD 2020-0024, dated February 13, 2020.

(ii) [Reserved]

(4) The following service information was approved for IBR on August 1, 2019 (84 FR 30588, June 27, 2019).

(i) Fokker Engineering Report SE-623, Fokker 70/100 Airworthiness Limitations Section, Part 2--(Structure ALIs and Safe Life Items), Issue 18, dated June 14, 2018.

(ii) [Reserved]

(5) For information about Fokker Services B.V. material, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; internet <http://www.myfokkerfleet.com>.

(6) For information about EASA AD 2020-0024, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(7) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0450.

(8) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 4, 2020.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10626 Filed 5-19-20; 8:45 am]



**2020-09-12 De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.):** Amendment 39-19908; Docket No. FAA-2020-0101; Product Identifier 2019-NM-190-AD.

**(a) Effective Date**

This AD is effective June 24, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to De Havilland Aircraft of Canada Limited Model DHC-8-400, -401, and -402 series airplanes, certificated in any category, serial numbers 4001 and subsequent.

**(d) Subject**

Air Transport Association (ATA) of America Code 55, Stabilizers.

**(e) Reason**

This AD was prompted by a report that certain elevator power control unit (PCU) arm fittings have nonconforming fillet radii. The FAA is issuing this AD to address elevator PCU assemblies with nonconforming fillet radii, which could lead to premature failure of the fitting and a jam in one elevator; if the fittings on both elevators fail, a complete loss of elevator control could occur.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Definition**

Affected elevator PCU assemblies are those having part number 85527021-005 or 85527021-006, and having serial number MMC4255 through MMC4276 inclusive.

**(h) Inspections**

For airplanes having serial numbers 4001 through 4620 inclusive, within 8,000 flight cycles on the elevator PCU assembly after the effective date of this AD, or before the accumulation of 30,000 total flight cycles on the elevator PCU assembly, whichever occurs first: Do the actions specified in paragraphs (h)(1) and (2) of this AD.

(1) Inspect to determine the part number and serial number of each elevator PCU assembly installed on the airplane. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number and serial number of the elevator PCU assembly can be conclusively determined from that review.

(2) If, during any inspection or records review required by paragraph (h)(1) of this AD, any affected elevator PCU assembly is found, do a detailed inspection of the elevator PCU arm fittings for undersized fillet radii and cracks of the fillet radii in accordance with Part A of the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, Revision A, dated July 25, 2019. If no undersized fillet radii or cracks of the fillet radii are found, before further flight, re-identify the affected elevator PCU assembly in accordance with the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, Revision A, dated July 25, 2019.

**(i) Corrective Actions**

If during any inspection of the elevator PCU arm fittings required by paragraph (h)(2) of this AD, any undersized fillet radii or cracks of the fillet radii are found, before further flight, replace the elevator PCU arm fittings and re-identify each affected elevator PCU assembly in accordance with Part B of the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, Revision A, dated July 25, 2019.

**(j) Parts Installation Limitation**

As of the effective date of this AD, no person may install an affected elevator PCU assembly on any airplane, unless it has been re-identified in accordance with the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, Revision A, dated July 25, 2019.

**(k) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraphs (h) and (i) of this AD, if those actions were performed before the effective date of this AD using De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, dated May 29, 2019.

**(l) No Reporting Requirement**

Although De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, Revision A, dated July 25, 2019, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(m) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7300; fax: 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or De Havilland Aircraft of Canada Limited's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(n) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-36, dated October 18, 2019, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0101.

(2) For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7330; fax: 516-794-5531; email: 9-avs-nyaco-cos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (4) of this AD.

**(o) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) De Havilland Aircraft of Canada Limited Service Bulletin 84-55-10, Revision A, dated July 25, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; phone: 416-375-4000; fax: 416-375-4539; email: thd@dehavilland.com; internet: <https://dehavilland.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 6, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10741 Filed 5-19-20; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2020-09-13 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH):** Amendment 39-19909; Docket No. FAA-2020-0090; Product Identifier 2019-NM-196-AD.

### **(a) Effective Date**

This AD is effective June 22, 2020.

### **(b) Affected ADs**

This AD affects the ADs identified in paragraphs (b)(1) and (2) of this AD:

(1) AD 2009-01-06 R1, Amendment 39-16082 (74 FR 57411, November 6, 2009) (“AD 2009-01-06 R1”).

(2) AD 2012-01-08, Amendment 39-16920 (77 FR 3583, January 25, 2012) (“AD 2012-01-08”).

### **(c) Applicability**

This AD applies to all 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328-300 airplanes, certificated in any category.

### **(d) Subject**

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

### **(e) Reason**

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address the potential failure of parts, which could lead to reduced control of the airplane; and to address the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0271, dated October 30, 2019 (“EASA AD 2019-0271”).

### **(h) Exceptions to EASA AD 2019-0271**

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2019-0271 do not apply to this AD.

(2) Where paragraph (3) of EASA AD 2019-0271 specifies a compliance time of “Within 12 months” after its effective date to “revise the approved AMP,” this AD requires “revising the existing maintenance or inspection program, as applicable,” to incorporate the “limitations, tasks and associated thresholds and intervals,” specified in paragraph (3) of EASA AD 2019-0271 within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2019-0271 is at the applicable “associated thresholds” specified in paragraph (3) of EASA AD 2019-0271, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2019-0271 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2019-0271 does not apply to this AD.

### **(i) Provisions for Alternative Actions, Intervals, and Critical Design Configuration Control Limitation (CDCCLs)**

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed except as specified in the provisions of the “Ref. Publications” section of EASA AD 2019-0271.

### **(j) Terminating Action for Other ADs**

(1) Accomplishing the maintenance or inspection program revision required by paragraph (g) of this AD terminates all requirements of AD 2009-01-06 R1.

(2) Accomplishing the maintenance or inspection program revision required by paragraph (g) of this AD terminates all requirements of AD 2012-01-08 for Model 328-300 airplanes only.

### **(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or 328 Support Services GmbH's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(l) Related Information**

For more information about this AD, contact Todd Thompson, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3228; email: todd.thompson@faa.gov.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0271, dated October 30, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0271, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 6017; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0090.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 6, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10631 Filed 5-15-20; 8:45 am]



**FAA**  
**Aviation Safety**

## **AIRWORTHINESS DIRECTIVE**

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

---

**2020-09-14 Airbus SAS:** Amendment 39-19910; Docket No. FAA-2020-0452; Product Identifier 2020-NM-062-AD.

### **(a) Effective Date**

This AD becomes effective June 4, 2020.

### **(b) Affected ADs**

This AD replaces AD 2020-03-12, Amendment 39-19837 (85 FR 7863, February 12, 2020) (“AD 2020-03-12”).

### **(c) Applicability**

This AD applies to Airbus SAS Model A350-941 and -1041 airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2020-0090, dated April 20, 2020 (“EASA AD 2020-0090”).

### **(d) Subject**

Air Transport Association (ATA) of America Code 31, Instruments.

### **(e) Reason**

This AD was prompted by two reports of abnormal operation of the components of the ENG START panel or Electronic Centralized Aircraft Monitoring (ECAM) Control Panel (ECP) due to liquid spillage in the system, and the subsequent uncommanded engine inflight shutdown (IFSD) of one engine in each case. This AD was also prompted by the FAA's determination that a removable integrated control panel (ICP) cover must be installed to prevent damage from spillage and the existing AFM must be revised. The FAA is issuing this AD to address the potential for dual-engine IFSD, possibly resulting in a forced landing with consequent damage to the airplane and injury to occupants.

### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

### **(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020-0090.

### **(h) Exceptions to EASA AD 2020-0090**

(1) Where EASA AD 2020-0090 refers to “the effective date of EASA AD 2020-0020-E,” this AD requires using February 14, 2020 (the effective date of AD 2020-03-12).

(2) Where EASA AD 2020-0090 refers to its effective date, this AD requires using the effective date of this AD.

(3) “Note 1” of EASA AD 2020-0090 does not apply to this AD. However, after the actions required by paragraph (g) of this AD have been accomplished on an airplane, that airplane may be operated with a damaged or missing ICP removable cover, provided provisions that address the ICP removable cover are included in the operator's approved minimum equipment list (MEL).

(4) The “Remarks” section of EASA AD 2020-0090 does not apply to this AD.

### **(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2020-03-12 are approved as AMOCs for the corresponding provisions of EASA AD 2020-0090 that are required by paragraph (g) of this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2020-0090 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

### **(j) Related Information**

For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020-0090, dated April 20, 2020.

(ii) [Reserved]

(3) For information about EASA AD 2020-0090, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0452.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 6, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10629 Filed 5-19-20; 8:45 am]



**2020-09-16 GIE Avions de Transport Regional:** Amendment 39-19912; Docket No. FAA-2020-0102; Product Identifier 2019-NM-184-AD.

**(a) Effective Date**

This AD is effective June 22, 2020.

**(b) Affected ADs**

(1) This AD replaces the ADs identified in paragraphs (b)(1)(i) through (iii) of this AD.

(i) AD 2000-17-09, Amendment 39-11883 (65 FR 53897, September 6, 2000) (“AD 2000-17-09”).

(ii) AD 2008-04-19 R1, Amendment 39-16069 (74 FR 56713, November 3, 2009) (“AD 2008-04-19 R1”).

(iii) AD 2015-26-09, Amendment 39-18357 (81 FR 1483, January 13, 2016) (“AD 2015-26-09”).

(2) This AD affects AD 2018-18-05, Amendment 39-19384 (83 FR 44463, August 31, 2018) (“AD 2018-18-05”).

**(c) Applicability**

This AD applies to all ATR-GIE Avions de Transport Regional Model ATR42-200, -300, and -320 airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

**(e) Reason**

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0256, dated October 17, 2019 (“EASA AD 2019-0256”).

### **(h) Exceptions to EASA AD 2019-0256**

(1) The requirements specified in paragraphs (1) and (3) of EASA AD 2019-0256 do not apply to this AD.

(2) Where paragraph (2) of EASA AD 2019-0256 refers to its effective date, this AD requires using the effective date of this AD.

(3) Paragraph (4) of EASA AD 2019-0256 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the “limitations, tasks and associated thresholds and intervals” specified in paragraph (4) of EASA AD 2019-0256 within 90 days after the effective date of this AD.

(4) The initial compliance time for doing the tasks specified in paragraph (4) of EASA AD 2019-0256 is at the applicable “associated thresholds” specified in paragraph (4) of EASA AD 2019-0256, or within 90 days after the effective date of this AD, whichever occurs later.

(5) The provisions specified in paragraphs (5) and (6) of EASA AD 2019-0256 do not apply to this AD.

(6) The “Remarks” section of EASA AD 2019-0256 does not apply to this AD.

### **(i) Provisions for Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs)**

After the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and CDCCLs are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2019-0256.

### **(j) Terminating Action for AD 2018-18-05**

Accomplishing the maintenance or inspection program revision required by paragraph (g) of this AD terminates the requirements of AD 2018-18-05.

### **(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or ATR-GIE Avions de Transport Regional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019-0256 that contains RC procedures and tests: Except as required by paragraph (k)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC

can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(l) Related Information**

For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220; email shahram.daneshmandi@faa.gov.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on June 22, 2020.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0256, dated October 17, 2019.

(ii) [Reserved]

(4) For information about EASA AD 2019-0256, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(5) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0102.

(6) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 8, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10627 Filed 5-15-20; 8:45 am]



**2020-10-04 General Electric Company:** Amendment 39-21122; Docket No. FAA-2020-0469; Project Identifier AD-2020-00258-E.

**(a) Effective Date**

This AD is effective May 27, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all General Electric Company (GE) GE90-110B1 and GE90-115B model turbofan engines with an interstage high-pressure turbine (HPT) rotor seal with a part number and serial number listed in Table 1 of GE GE90-100 Alert Service Bulletin (ASB) 72-A0841 R00, dated February 26, 2020 (“the ASB”).

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

**(e) Unsafe Condition**

This AD was prompted by investigative findings from an event involving an uncontained interstage HPT rotor seal failure, resulting in debris penetrating the fuselage and the other engine. The FAA is issuing this AD to prevent failure of the interstage HPT rotor seal. The unsafe condition, if not addressed, could result in uncontained interstage HPT rotor seal release, release of high-energy debris, damage to the engine, and damage to the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) Perform an ultrasonic inspection (USI) of the interstage HPT rotor seal in accordance with the Accomplishment Instructions, paragraph 3.B.(1), of the ASB, as follows:

(i) After the effective date of this AD, perform an initial USI of the interstage HPT rotor seal before reaching the additional cycles listed in Table 1 of the ASB. When computing the additional cycles, use the effective date of this AD instead of the issue date of the ASB.

(ii) Thereafter, repeat the USI of the interstage HPT rotor seal required by paragraph (g)(1)(i) within every 100 cycles since the last inspection.

(2) If, during any USI required by paragraph (g)(1)(i) or (ii) of this AD, a non-serviceable indication is found, as defined in paragraph 3.B.(2)(b) of the ASB, before further flight, remove the interstage HPT rotor seal from service.

#### **(h) Mandatory Terminating Action**

As a terminating action to the repetitive USI required by paragraph (g)(1)(ii) of this AD, at the next engine shop visit after the effective date of this AD, remove the affected interstage HPT rotor seal from service and replace with a part eligible for installation.

#### **(i) Definition**

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine case flanges, except separation of engine flanges solely for the purposes of transportation of the engine without subsequent maintenance does not constitute an engine shop visit.

#### **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### **(k) Related Information**

For more information about this AD, contact Stephen Elwin, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7236; fax: 781-238-7199; email: stephen.l.elwin@faa.gov.

#### **(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) General Electric Company (GE) GE90-100 Alert Service Bulletin 72-A0841 R00, dated February 26, 2020.

(ii) [Reserved]

(3) For GE service information identified in this AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: aviation.fleetsupport@ge.com.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 6, 2020.

Gaetano A. Sciortino,  
Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft  
Certification Service.

[FR Doc. 2020-10048 Filed 5-11-20; 8:45 am]



---

**2020-10-05 Rockwell Collins, Inc.:** Amendment 39-21123; Docket No. FAA-2018-0977; Product Identifier 2018-CE-041-AD.

**(a) Effective Date**

This AD is effective June 24, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Rockwell Collins, Inc. (Rockwell Collins) Pro Line 4 and Pro Line 21 Flight Management Systems installed on airplanes, certificated in any category, that has a flight management computer (FMC) with a Rockwell Collins part number (RCPN) listed in paragraph (c)(1) of this AD and with a configuration strapping unit (CSU) listed in paragraph (c)(2) of this AD.

(1) FMC-3000 RCPN 822-0883-031, -036, -038, -040, -041, -053, -054, -056, -057, -058, -059, -060, -081, -082, -083, -084; FMC-4200 RCPN 822-0783-022, -025, -028, -032, -036, -039, -040; FMC-5000 RCPN 822-0891-021, -027, -028, -034, -040; or FMC-6000 RCPN 822-0868-074, -075, -082, -083, -084, -085, -087, -089, -090, -109, -110, -111, -112, -113, -114, -116, -117, -122, -123, -127, -130, -132, -133, -134, -139.

(2) CSU-3100 RCPN 822-1363-002, CSU-4000 RCPN 822-0049-002, or CSU-4100 RCPN 822-1364-002.

Note 1 to paragraph (c) of this AD: To determine the CSU and FMC unit RCPN, refer to the aircraft manufacturer or applicable STC holder maintenance instructions for accessing them.

**(d) Subject**

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 3460, Flight Management Computing Hardware System.

**(e) Unsafe Condition**

This AD was prompted by reports of the FMC software issuing incorrect turn commands when the altitude climb field is edited or when the temperature compensation is activated. The FAA is issuing this AD to prevent the FMC from issuing an incorrect turn direction command. The unsafe condition, if not addressed, could result in a collision or controlled flight into terrain.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Disable Temperature Compensation**

Within the next 12 months after June 24, 2020 (the effective date of this AD), disable the automatic temperature compensation feature on the CSU by following steps (2) through (6) of the Instructions in Rockwell Collins Service Information Letter CSU-XX00-18-1, dated June 27, 2018.

**(h) Revise the Airplane Flight Manual Limitations**

Within the next 12 months after June 24, 2020 (the effective date of this AD), revise the airplane flight manual by adding the information from step 2 of the Aircraft Flight Manual Recommendation in Rockwell Collins Service Information Letter FMC-XX00-18-1, Revision 1, dated February 5, 2019, into the Limitations section of the AFM.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Wichita ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(j) Related Information**

For more information about this AD, contact Avi Acharya, Aerospace Engineer, Wichita ACO Branch, FAA, 1801 Airport Road, Room 100, Wichita, Kansas 67209; phone: 316-946-4192; fax: 316-946-4107; email: avishek.acharya@faa.gov.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rockwell Collins Service Information Letter CSU-XX00-18-1, dated June 27, 2018.

(ii) Rockwell Collins Service Information Letter FMC-XX00-18-1, Revision 1, dated February 5, 2019.

(3) For service information identified in this AD, contact Rockwell Collins, Inc., Collins Aviation Services, 400 Collins Road NE, M/S 164-100, Cedar Rapids, IA 52498-0001; telephone: 888-265-5467 (U.S.) or 319-265-5467; fax: 319-295-4941; email: techmanuals@rockwellcollins.com; internet: <https://portal.rockwellcollins.com/web/publications-and-training>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0977.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at

NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 14, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10744 Filed 5-19-20; 8:45 am]



**2020-10-10 The Boeing Company:** Amendment 39-19913; Docket No. FAA-2020-0096; Product Identifier 2019-NM-211-AD.

**(a) Effective Date**

This AD is effective June 26, 2020.

**(b) Affected ADs**

This AD replaces AD 2016-07-28, Amendment 39-18473 (81 FR 21253, April 11, 2016) (“AD 2016-07-28”).

**(c) Applicability**

This AD applies to all The Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes, and Model MD-88 airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 57, Wings.

**(e) Unsafe Condition**

This AD was prompted by a report of a crack at a certain stringer not addressed by AD 2016-07-28, and cracks at certain other stringers and associated end fittings, and skins in the center wing fuel tank where the stringers meet the end fittings addressed by AD 2016-07-28. The FAA is issuing this AD to detect and correct cracking in the center wing lower skin. Such cracking could cause structural failure of the wings.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin MD80-57A244, Revision 1, dated October 1, 2019, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-57A244, Revision 1, dated October 1, 2019.

Note 1 to paragraph (g) of this AD: Boeing Alert Service Bulletin MD80-57A244, Revision 1, dated October 1, 2019, refers to Drawing SN09570007 for certain inspection sequences. If the pages

of Drawing SN09570007 are illegible, guidance can be found in Boeing Multi Operator Message MOM-MOM-19-0549-01B, dated October 4, 2019.

### **(h) Exception to Service Information Specifications**

Where Boeing Alert Service Bulletin MD80-57A244, Revision 1, dated October 1, 2019, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2016-07-28 are not approved as AMOCs for this AD.

(5) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(5)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

### **(j) Related Information**

(1) For more information about this AD, contact Mohit Garg, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5264; fax: 562-627-5210; email: mohit.garg@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

### **(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD80-57A244, Revision 1, dated October 1, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 14, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-11034 Filed 5-21-20; 8:45 am]



**2020-11-04 Learjet Inc.:** Amendment 39-21129; Docket No. FAA-2019-0204; Project Identifier 2018-CE-042-AD.

**(a) Effective Date**

This AD is effective June 25, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Learjet Inc. Model 60 airplanes, serial numbers 60-001 through 60-430 inclusive, certificated in any category.

**(d) Subject**

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 78, Engine Exhaust.

**(e) Unsafe Condition**

This AD was prompted by a report of a reverse thrust command accelerating the airplane instead of decelerating the airplane because the thrust reverser doors were stowed instead of deployed. The FAA is issuing this AD to mitigate failure of the engine thrust reverser system. The unsafe condition, if not addressed, could result in the airplane overrunning the runway or a runway excursion.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Install a Thrust Reverser Voice Command Warning System**

Within the next 1,200 hours time-in-service or within the next 48 months after June 25, 2020 (the effective date of this AD), whichever occurs first, install a Thrust Reverser Voice Command Warning System and perform a functional test in accordance with sections 3.A. through 3.C. of the Accomplishment Instructions in Bombardier Learjet 60 Service Bulletin SB 60-78-9, dated June 25, 2018.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Wichita ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send

your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

For more information about this AD, contact James Galstad, Aerospace Engineer, Wichita ACO Branch, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4135; fax: (316) 946-4107; email: james.galstad@faa.gov or Wichita-COS@faa.gov.

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Learjet 60 Service Bulletin SB 60-78-9, dated June 25, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Learjet Inc., MS 53, P.O. Box 7707, Wichita, Kansas 67277-7707; telephone: (toll free) 1-866-538-1247; (514) 855-2999; internet: <https://my.businessaircraft.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 15, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10915 Filed 5-20-20; 8:45 am]