

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2014-23**

11/3/2014 - 11/16/2014



Federal Aviation Administration
Engineering Procedures Office, AIR-110
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2014-01

2013-25-04		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2013-25-06		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-01 2013-26-02		CFM International S.A. Bombardier, Inc.	CFM56-3 series and CFM56-7B series turbofan engines CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2013-26-03	S 2011-24-09	Airbus	A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, and A340-642
2013-26-04 2013-26-06	S 2010-19-01	The Boeing Company Rolls-Royce Corporation	747-400, -400D, and -400F series AE 3007A, A1, A1/1, A1/2, A1/3, A1P, A1E, and A3 turbofan engines
2013-26-07		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-08 2013-26-10		The Boeing Company Rolls-Royce plc	737-600, -700, -700C, -800, -900, and -900ER series RB211-524G2-19, RB211-524G3-19, RB211-524H-36, and RB211-524H2-19 turbofan engines
2013-26-12	S 2009-14-02	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series

Biweekly 2014-02

There were no AD's published in this Large Bi-weekly period

Biweekly 2014-03

2013-24-04	S 2003-19-11	Learjet Inc.	60
2013-25-03	S 2000-17-05 S 2001-04-09	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-01-04		Bae Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2014-01-05 2014-02-01	S 2011-03-13	The Boeing Company Bombardier, Inc.	737-100, -200, -200C, -300, -400, and -500 series CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)

Biweekly 2014-04

2014-03-07 2014-03-08	S 2009-26-16	The Boeing Company Airbus	MD-11 and MD-11F A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-03-09		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, -500, ATR72-101, -201, -102, -202, -211, -212, and -212A
2014-03-14		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2014-03-16		Rolls-Royce Deutschland Ltd & Co. KG	Tay 620-15, 650-15, and 651-54 turbofan engines
2014-03-17		Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, & CL-604 Variants)

Biweekly 2014-05

2014-01-03 2014-03-04 2014-03-05 2014-03-06		Saab AB, Saab Aerosystems Bombardier, Inc. Bombardier, Inc. Boeing	340A (SAAB/SF340A) and SAAB 340B DHC-8-400, -401, and -402 BD-700-1A10 737-100, -200, -200C, -300, -400, and -500 series
--	--	---	---

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-03-12	S 2002-23-19	Dassault Aviation	FALCON 2000
2014-03-13		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-03-15	S 2008-14-16	328 Support Services GmbH	328-100, 328-300
2014-03-19		Boeing	737-600, -700, -800, -900, and -900ER series
2014-03-21		Boeing	727-200 and 727-200F series
2014-04-05		Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-04-08		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2014-05-02	S 2002-10-11	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-03		Boeing	777-200, -200LR, -300, -300ER, and -777F series
2014-05-05		Boeing	777-200, -200LR, -300, -300ER, and 777F series
Biweekly 2014-06			
2014-05-09	S 2012-12-08	Boeing	777-200 and -300 series
2014-05-12	S 2010-15-08	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-13	S 2004-12-07	Boeing	757-200, -200PF, and -200CB series
2014-05-16		Boeing	747-200B, 747-300, 747-400, 747-400D, 747-400F, 767-200, -300, -300F, and -400ER series
2014-05-18		Bombardier	DHC-8-400, -401, and -402
2014-05-19		Boeing	747-200B, 747-200F, 747-300, 747SP, 747-400, 747-400F, 767-300 series
2014-05-20		Boeing	757-200, -200PF, -200CB, and -300 series
2014-05-21	S 2008-11-04	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-22		Boeing	717-200
2014-05-23		Bombardier	BD-100-1A10 (Challenger 300)
2014-05-24	S 84-19-01	Boeing	747-100, 747-200B, and 747-200F series
2014-05-25		Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2014-05-30	S 2013-07-07	Boeing	737-600, -700, -700C, -800, -900, and -900ER series
2014-06-02		Boeing	747-400 series
Biweekly 2014-07			
2013-26-14	S 2008-08-04	Airbus	A318, A319, A320, A321
2014-04-09		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-04-10		Airbus	A330, A340 airplanes
2014-05-14		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-05-17		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2014-05-27		Rockwell Collins	Mode S transponders
2014-05-28		Bombardier	DHC-8-400, -401, and -402
2014-05-31	S 2008-08-25	Boeing	747-400F, 747-400 series
2014-05-32		Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2240, PW2337, PW2643, and F117-PW-100 turbofan engines
2014-06-04		Boeing	747-8 and 747-8F series
2014-06-05	S 2007-03-02	Rolls-Royce Deutschland	Tay 620-15, Tay 650-15 and Tay 651-54 turbofan engines
2014-06-08		Bombardier	DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315
2014-06-09	S 2009-18-18	ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, -500 ; ATR72-101, -201, -102, -202, -211, -212, and -212A
2014-06-10	S 2014-06-10	Airbus	A330, A340
2014-07-02		Rolls-Royce Deutschland	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2014-08			
2014-05-32	COR	Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2240, PW2337, PW2643, and F117-PW-100 turbofan engines
2014-07-03		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-07-05		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-08-02		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R
2014-08-03		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2014-08-05		Rolls-Royce Deutschland Ltd & Co KG	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines
Biweekly 2014-09			
2013-25-02	S 2000-11-06	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-07-01		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2014-08-01	S 2014-03-08	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-08-04	S 2012-03-04	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-08-08		The Boeing Company	737-200, -200C, -300, -400, and -500 series
2014-08-09		The Boeing Company	767-200, -300, -300F, and -400ER series
2014-08-11	S 2009-24-07	The Boeing Company	737-600, -700, -700C, -800 and -900 series
2014-09-05		Airbus	A330-201, A330-202, A330-203, A330-223, A330-243, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313
2014-09-06		The Boeing Company	777F series
Biweekly 2014-10			
2014-09-08	S 2007-16-19	The Boeing Company	747-200B, 747-300, and 747-400 series
2014-09-10		The Boeing Company	767-200, -300, -300F, and -400ER series
Biweekly 2014-11			
2014-09-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2014-09-09		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series
Biweekly 2014-12			
2008-21-07R1		Dowty Propellers	R408/6-123-F/17 propellers
2014-11-01		The Boeing Company	777-200 and -300 series
2014-11-04		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343 A340-211, -212, -213, -311, -312, -313, -541, and -642
2014-11-06		Lockheed	P-3A or P3A
2014-12-03		Rolls-Royce Deutschland	BR700-725A1-12 turbofan engines
2014-12-52	E	Honeywell International	TFE731-4, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, 40AR, -40R, -40BR, -50R, and -60 turbofan engines
Biweekly 2014-13			
2014-12-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-12-10		The Boeing Company	727-100 series
2014-13-03		Rolls-Royce plc	RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2014-14

2014-12-02		Dassault Aviation	FALCON 2000 and FALCON 2000EX
2014-12-13		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2014-12-52	S 2014-12-52	Honeywell International Inc.	TFE731-4, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, -40AR, -40R, -40BR, -50R, and -60 turbofan engines
2014-13-02		Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan engines
2014-14-01		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2014-14-02		Pratt & Whitney Canada Corp.	PW120, PW121, PW121A, PW124B, PW127, PW127E, PW127F, PW127G and PW127M turboprop engines

Biweekly 2014-15 (AD 2014-15-01 was originally left off this Biweekly, but was added Oct. 23, 2014, and also will be included in Large AD Biweekly 2014-22)

2014-11-03		The Boeing Company	777-200, -200LR, -300, and -300ER series airplanes
2014-11-10	S 2008-08-09	Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2014-13-06		Learjet Inc.	45 airplanes
2014-13-07		The Boeing Company	737-300, -400, and -500 series airplanes; 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2014-13-10		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2014-13-11		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body series airplanes; 720 and 720B series airplanes
2014-13-14		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2014-13-15		EADS CASA	CN-235-300 airplanes
2014-13-16		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000) airplanes
2014-13-17		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2014-13-18		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2014-14-03	S 2014-07-01	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes
2014-14-05		Airbus	A320-211, -212, and -231 airplanes
2014-14-06		Airbus	A318-111 and -112; A319-111, -112, -113, -114, and -115; A320-111, -211, -212, and -214; A321-111, -112, -211, -212, and -213 airplanes
2014-15-01		M7 Aerospace LLC	SA227-AT, SA227-AC, SA227-BC, SA227-CC, SA227-DC airplanes
2014-15-03		Pratt & Whitney Canada Corporation	PW150A turboprop engines

Biweekly 2014-16

2014-13-12		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-13-13		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-14-04	S 2003-18-10	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-15-04		Saab AB, Saab Aerosystems	SAAB 2000
2014-15-05		Airbus	A310-304, -322, -324, and -325
2014-15-06		The Boeing Company	747-100B SUD, 747-200B, 747-300, 747-400, and 747-400D series
2014-15-07		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2014-15-08		Beechcraft Corporation	Hawker 800XP, 850XP, and 900XP
2014-15-09		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and -642

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-15-10 2014-15-11		Dassault Aviation Bombardier, Inc.	FALCON 7X CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2014-15-12 2014-15-14		The Boeing Company The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2014-15-15 2014-15-16		Beechcraft Corporation Airbus	MU-300, 400, 400A, 400T (T-1A), and 400T (TX) A319-111, -112, -115, -132, -133, A320-214, -232, -233, A321-211, -231, and -232
2014-15-17		Bombardier, Inc.	CL-600-2B16 (CL-604 Variant)
Biweekly 2014-17			
2013-13-13		Airbus	A310-203, -204, -221, -222, 304, -322, -324, -325, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F
2014-15-13	R 2005-15-04	Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), and CL-600-2B16 (CL-604 Variant)
2014-15-20 2014-15-21 2014-16-02	S 2006-26-06	Bombardier, Inc. The Boeing Company Bombardier, Inc.	DHC-8-400, -401, and -402 777-200 and -300 series CL-600-1A11 (CL-600)
2014-16-04 2014-16-06 2014-16-07 2014-16-08	R 2008-14-17 R 2011-15-09	Airbus Bombardier, Inc. Bombardier, Inc. Bombardier, Inc.	A330-201, -202, -203, -223, -243, A340-311, -312, and -313 CL-600-2B16 (CL-604 Variant) DHC-8-400, -401, and -402 CL-215-6B11 (CL-215T Variant) and CL-215-6B11 (CL-415 Variant)
2014-16-09		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body, 707-300, -300B, -300C, and -400 series, 720 and 720B series, 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series, 737-100, -200, and -200C series
2014-16-10 2014-16-11 2014-16-14 2014-16-16	S 2013-12-01	Rolls-Royce plc The Boeing Company The Boeing Company Embraer S.A.	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines 777-200 series 737-600, -700, -700C, -800, and -900 series ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, -200 STD, -200 LR, and -200 IGW
2014-16-19	See AD	Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2014-16-20		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203
2014-16-22		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and -642
2014-17-51	E	Bombardier, Inc.	CL-600-2B16
Biweekly 2014-18			
2014-16-05		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 170-200 LR, -200 SU, and -200 STD
2014-16-12 2014-16-13		Dassault Aviation Airbus	FALCON 2000EX A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203
2014-16-18		BAE Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2014-16-21 2014-16-23 2014-16-25	R 2011-16-01 R 2007-06-12	Dassault Aviation Dassault Aviation Airbus	FALCON 7X FALCON 7X A330-201, -202, -203, -223, -243, A330-301, -321, -322, -323, -341, -342, and -343
2014-16-26 2014-16-27 2014-16-28		Dassault Aviation Dassault Aviation Empresa Brasileira de Aeronautica S.A.	FALCON 900EX FALCON 900EX EMB-135BJ
2014-17-02	R 2013-18-09	Honeywell ASCa Inc	See AD

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-17-04		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2014-17-05		The Boeing Company	767-400ER series
2014-17-06	R 2011-17-08	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2014-17-07		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-17-10		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-18-02	R 2014-05-02	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
Biweekly 2014-19			
2013-15-06		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2013-25-07	R 2007-18-09	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-05		Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, G, MYSTERE-FALCON 200, MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2014-15-19	R 2013-03-23	Gulfstream Aerospace LP	G150
2014-19-02		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2014-20			
2014-18-01		Rockwell Collins, Inc.	Appliance: See AD
2014-19-03		The Boeing Company	747-8 and 747-8F series
2014-19-04	R 2004-03-19	Airbus	A320-111, -211, -212, and -231
2014-20-01		Bombardier, Inc.	CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants)
2014-20-02		The Boeing Company	767-200, -300, -300F, and -400ER series
2014-20-03		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11
2014-20-04	R 94-12-03	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-20-06		The Boeing Company	737-600, -700, -700C, -800, -900, -900ER series, 777-200, 777-200LR, 777-300, 777-300ER, and 777F series
2014-20-07	R 2010-03-05	The Boeing Company	747-200C and -200F series
2014-20-08		Lockheed Martin Corporation	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2014-20-09		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2014-21			
2014-20-10	R 2013-11-14	The Boeing Company	777-200 and -300 series airplanes
2014-20-11	R 2011-07-05	Zodiac Seats France	9140, 9166, 9173, 9174, 9184, 9188, 9196, 91B7, 91B8, 91C0, 91C2, 91C4, 91C5, 91C9, 9301, and 9501 series passenger seat assemblies
Biweekly 2014-22			
(AD 2014-15-01 should have been included in Large AD Biweekly 2014-15. We have corrected the online version, but have also included it here for the print subscribers.)			
2012-26-15 R1	R 2012-26-15	Honeywell International Inc.	Appliance: See AD
2014-15-01		M7 Aerospace LLC	SA227-AT, SA227-AC, SA227-BC, SA227-CC, and SA227-DC
2014-17-51		Bombardier, Inc.	CL-600-2B16
2014-21-01	S 90-26-01, S 91-20-02, S 2009-05-02	General Electric Company	CF6-80C2 and CF6-80E1 series turbofan engines
2014-21-04		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88
2014-21-05		The Boeing Company	DC-10-10, DC-10-10F, DC-10-30, DC-10-30F (KC-10A)

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-21-06 2014-21-07		Beechcraft Corporation Bombardier, Inc.	and KDC-10), DC-10-40, MD-10-10F, and MD-10-30F 400 Beechjet, 400A Beechjet, 400T Beechjet, and MU-300 CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL- 600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2014-21-08 2014-21-09	R 2005-14-07	Bombardier, Inc. The Boeing Company	BD-700-1A11 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-21-10		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, - 322, -323, -341, -342, -343, A340-211, -212, -213, -311, - 312, and -313
2014-22-02		Rolls-Royce plc	Trent 1000-A, 1000-C, 1000-D, 1000-E, 1000-G, and 1000- H turbofan engines
Biweekly 2014-23			
2014-20-18	R 2005-23-08	Airbus	B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, and Model A300 C4-605R Variant F
2014-20-19	S 2013-10-06	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, - 213, -311, -312, -313, -541, and -642
2014-22-04		The Boeing Company	DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9- 15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC- 9-32F, DC-9-33F, DC-9-34, DC-9-34F, and DC-9-32F (C- 9A, C-9B)
2014-22-05		The Boeing Company	DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9- 15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC- 9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41 and DC-9-51
2014-22-06 2014-22-07	R 2005-07-12 R 2013-16-08	The Boeing Company Bombardier, Inc.	737-100, -200, -200C, -300, -400, and -500 series CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL- 600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2014-22-08		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, - 115, -131, -132, -133, A320-111, -211, -212, -214, -231, - 232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-22-09 2014-22-11	R 2012-13-08	The Boeing Company The Boeing Company	767-200, -300, -300F, and -400ER series 747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747- 400F, 747SR, and 747SP series



2014-20-18 Airbus: Amendment 39-17991. Docket No. FAA-2013-1064; Directorate Identifier 2012-NM-101-AD.

(a) Effective Date

This AD becomes effective December 11, 2014.

(b) Affected ADs

This AD replaces AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005).

(c) Applicability

This AD applies to Airbus Model B4-603, B4-620, and B4-622 airplanes; Model A300 B4-605R and B4-622R airplanes; Model A300 F4-605R airplanes; and Model A300 C4-605R Variant F airplanes; certificated in any category; except airplanes on which Airbus Modification 12171 or 12249 has been embodied in production, or on which Airbus Service Bulletin A300-57-6069 has been embodied in service.

(d) Subject

Air Transport Association (ATA) of America Code 57: Wings.

(e) Reason

This AD was prompted by reports of cracks found on the horizontal flange of the Frame 47 internal corner angle fitting while accomplishing the modification required by AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005). We are issuing this AD to detect and correct fatigue cracking of the forward fitting of fuselage frame FR47, which could result in reduced structural integrity of the frame.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Inspections for Attachment Holes on the Internal Angles of the Wing Center Box, and Corrective Action

This paragraph restates the requirements of paragraphs (f), (g), and (h) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005), with revised service information. Perform a rotating probe inspection to detect cracking of the applicable attachment holes on the left and right internal angles of the wing center box in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6049, Revision 06, dated July 15, 2004; or Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006. Do the inspection at the applicable

time specified by paragraph 1.E.(2), Accomplishment Timescale, of Airbus Service Bulletin A300-57-6049, Revision 06, dated July 15, 2004; except as required by paragraph (j) of this AD. Repeat the rotating probe inspection specified in this paragraph thereafter at intervals not to exceed the applicable interval specified in Airbus Service Bulletin A300-57-6049, Revision 06, dated July 15, 2004, except that all touch-and-go landings must be counted in determining the total number of flight cycles between consecutive inspections. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006, may be used to accomplish the actions required by this paragraph.

(1) If no cracking is found during any inspection required by paragraph (g) of this AD: Prior to further flight, install new fasteners in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6049, Revision 06, dated July 15, 2004; or Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006, may be used to accomplish the actions required by this paragraph.

(2) If any cracking is found during any inspection required by paragraph (g) of this AD: Prior to further flight, perform applicable corrective actions (including reaming, drilling, drill-stopping holes, chamfering, performing follow-on inspections, and installing new or oversize fasteners), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6049, Revision 06, dated July 15, 2004; or Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006; except as required by paragraph (k) of this AD. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006, may be used to accomplish the actions required by this paragraph.

(h) Retained Inspections for Attachment Holes in the Horizontal Flange of the Internal Corner Angle Fitting of Fuselage Frame FR47, and Corrective Action

This paragraph restates the requirements of paragraphs (i), (j), and (k) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005), with revised service information. Perform a rotating probe inspection to detect cracking of the applicable attachment holes in the horizontal flange of the internal corner angle fitting of fuselage frame FR47, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6086, Revision 01, dated April 2, 2002; or Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012. Do the inspection at the applicable time specified in paragraph 1.E., Compliance, of Airbus Service Bulletin A300-57-6086, Revision 01, dated April 2, 2002, except as provided by paragraph (j) of this AD; or within 1,500 flight cycles after July 8, 2002 (the effective date of AD 2002-11-04, Amendment 39-12765 (67 FR 38193, June 3, 2002)); whichever occurs later. Repeat the rotating probe inspection specified in this paragraph thereafter at intervals not to exceed the applicable interval specified in Airbus Service Bulletin A300-57-6086, dated June 6, 2000, except that all touch-and-go landings must be counted in determining the total number of flight cycles between consecutive inspections. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012, may be used to accomplish the actions required by this paragraph.

(1) If no cracking is found during any inspection required by paragraph (h) of this AD: Prior to further flight, install new fasteners in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6086, Revision 01, dated April 2, 2002; or Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012, may be used to accomplish the actions required by this paragraph.

(2) If any cracking is found during any inspection required by paragraph (h) of this AD: Prior to further flight, perform applicable corrective actions (including inspecting hole T if any cracking is found at hole G, reaming the holes, and installing oversize fasteners), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6086, Revision 01, dated April 2, 2002; or Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012; except as

required by paragraph (k) of this AD. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012, may be used to accomplish the actions required by this paragraph.

(i) Retained Modification of Angle Fittings of the Wing Center Box

This paragraph restates the requirements of paragraph (l) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005). Modify the left and right internal angle fittings of the wing center box. The modification includes performing a rotating probe inspection to detect cracking, repairing cracks, cold expanding holes, and installing medium interference fitting bolts. Perform the modification in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6050, Revision 03, dated May 31, 2001; and at the applicable time specified by paragraph 1.B.(4), Accomplishment Timescale, of Airbus Service Bulletin A300-57-6050, Revision 03, dated May 31, 2001; except as required by paragraphs (j) and (k) of this AD.

(j) Retained Compliance Time Exception to Service Information Specified in Paragraphs (g), (h), and (i) of This AD

This paragraph restates the requirements of paragraph (m) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005). Where the service information specified in paragraphs (g), (h), and (i) of this AD specify a grace period relative to receipt of the service bulletin, this AD requires compliance within the applicable grace period following December 19, 2005 (the effective date of AD 2005-23-08), if the threshold has been exceeded.

(k) Retained Corrective Action Exception to Service Information Specified in Paragraphs (g), (h), and (i) of This AD

This paragraph restates the requirements of paragraph (n) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005). If any crack is detected during any inspection required by paragraph (g), (h), or (i) of this AD, and the applicable service information specifies to contact the manufacturer for disposition of certain corrective actions: Prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

(l) Credit for Previous Actions

(1) This paragraph restates the credit provided by paragraph (o) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005): This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before December 19, 2005 (the effective date of AD 2005-23-08), using Airbus Service Bulletin A300-57-6086, dated June 6, 2000.

(2) This paragraph restates the credit provided by paragraph (p) of AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005): This paragraph provides credit for the modification required by paragraph (i) of this AD, if the modification was performed before December 19, 2005 (the effective date of AD 2005-23-08), using Airbus Service Bulletin A300-57-6050, Revision 02, dated February 10, 2000.

(m) New Requirements of This AD: Repetitive Ultrasonic Inspections and Corrective Action

(1) For airplanes on which Airbus Service Bulletin A300-57-6050, Revision 03, dated May 31, 2001, has not been done, or on which Airbus Modification 10155 has been done: Perform an ultrasonic inspection for cracking of the left- and right-hand aft bottom panel of the center wing box (CWB), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-

6086, Revision 05, dated January 30, 2012. Do the inspection at the later of the times specified in paragraphs (m)(1)(i) and (m)(1)(ii) of this AD. If any cracking is found, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). Repeat the inspection thereafter at intervals not to exceed the applicable interval specified in paragraph 1.E.(2), Accomplishment Timescale, of Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012.

(i) Within 13,400 flight cycles or 34,600 flight hours after the first flight of the airplane, whichever occurs first.

(ii) Within 650 flight cycles or 8 months after the effective date of this AD, whichever occurs first.

(2) For airplanes on which Airbus Service Bulletin A300-57-6050, Revision 03, dated May 31, 2001, has been done: Perform an ultrasonic inspection for cracking of the left- and right-hand aft bottom panel of the center wing box (CWB), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012. Do the inspection at the later of the times specified in paragraphs (m)(2)(i) and (m)(2)(ii) of this AD. If any cracking is found, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). Repeat the inspection thereafter at intervals not to exceed the applicable interval specified in paragraph 1.E.(2), Accomplishment Timescale, of Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012.

(i) Within 13,400 flight cycles or 34,600 flight hours after accomplishing Airbus Service Bulletin A300-57-6050, whichever occurs first.

(ii) Within 650 flight cycles or 8 months after the effective date of this AD, whichever occurs first.

(n) New Reporting Requirement

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (m) of this AD to the Design Approval Holder, at the applicable time specified in paragraph (n)(1) or (n)(2) of this AD. The report must include the inspection results, a description of any discrepancies found, the airplane serial number, and the number of flight cycles and flight hours on the airplane. The inspection report form in Appendix 01 of Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012, may be used.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(o) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(ii) AMOCs approved previously in accordance with AD 2005-23-08, Amendment 39-14366 (70 FR 69056, November 14, 2005), are approved as AMOCs for the corresponding provision of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(p) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) 2012-0092, dated May 25, 2012; Correction dated June 4, 2012; for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-10640002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (q)(5) and (q)(6) of this AD.

(q) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on December 11, 2014.

(i) Airbus Service Bulletin A300-57-6049, Revision 07, dated December 22, 2006.

(ii) Airbus Service Bulletin A300-57-6086, Revision 05, dated January 30, 2012.

(4) The following service information was approved for IBR on December 19, 2005 (70 FR 69056, November 14, 2005).

(i) Airbus Service Bulletin A300-57-6049, excluding Appendix 01, Revision 06, dated July 15, 2004.

(ii) Airbus Service Bulletin A300-57-6050, Revision 03, dated May 31, 2001. This document contains the effective pages specified in paragraphs (q)(4)(ii)(A), (q)(4)(ii)(B), (q)(4)(ii)(C), and (q)(4)(ii)(D) of this AD.

(A) Pages 1, 4, 10A through 11, 75, and 76 are identified as Revision 03, dated May 31, 2001.

(B) Pages 2, 8, 9, 17 through 32, 41, 42, 57, 58, 61 through 63, and 77 are identified as Revision 02, dated February 10, 2000.

(C) Pages 3, 5 through 7, 10, 12, 33, 34, 37, 38, 47, 59, and 60 are identified as Revision 01, dated May 31, 1999.

(D) Pages 13 through 16, 35, 36, 39, 40, 43 through 46, 48 through 56, and 64 through 74 are identified as original, dated September 9, 1994.

(iii) Airbus Service Bulletin A300-57-6086, Revision 01, dated April 2, 2002.

(5) The following service information was approved for IBR on July 8, 2002 (67 FR 38193, June 3, 2002).

(i) Airbus Service Bulletin A300-57-6086, dated June 6, 2000.

(ii) Reserved.

(6) For service information identified in this AD, contact Airbus SAS–EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(7) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 24, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-20-19 Airbus: Amendment 39-17992. Docket No. FAA-2014-0192; Directorate Identifier 2013-NM-221-AD.

(a) Effective Date

This AD becomes effective December 11, 2014.

(b) Affected ADs

This AD supersedes AD 2013-10-06, Amendment 39-17459 (78 FR 32347, May 30, 2013).

(c) Applicability

This AD applies to all airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Airbus Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.

(2) Airbus Model A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 56, Windows.

(e) Reason

This AD was prompted by several reports of a burning smell and/or smoke in the cockpit during cruise phase, leading in some cases, to diversion to alternate airports. We are issuing this AD to prevent significantly increased workload for the flightcrew, which could, under some flight phases and/or circumstances, constitute an unsafe condition.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection With Revised Service Information

This paragraph restates the requirements of paragraph (g) of AD 2013-10-06, Amendment 39-17459 (78 FR 32347, May 30, 2013), with revised service information. Within 1,200 flight hours after July 5, 2013 (the effective date of AD 2013-10-06), inspect to identify the manufacturer, the part number, and the serial number of the left-hand (LH) and right-hand (RH) windshields installed on the airplane, in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraph (g)(1), (g)(2), or (g)(3) of this AD. A review of airplane delivery or maintenance records is acceptable in lieu of this inspection if the manufacturer, part number, and serial number of the installed windshields can be conclusively determined from that review.

(1) For Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes: Airbus Service Bulletin A330-56-3009, Revision 02, including Appendix 01, dated February 8, 2012; or Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013. As of the effective date of this AD, use only Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013, to do the actions required by paragraph (g) of this AD.

(2) For Model A340-211, -212, -213, -311, -312, and -313 airplanes: Airbus Service Bulletin A340-56-4008, Revision 01, including Appendix 01, dated February 8, 2012; or Airbus Service Bulletin A340-56-4008, Revision 02, including Appendixes 01 and 02, dated August 1, 2013. As of the effective date of this AD, use only Airbus Service Bulletin A340-56-4008, Revision 02, including Appendixes 01 and 02, dated August 1, 2013, to do the actions required by paragraph (g) of this AD.

(3) For Model A340-541 and -642 airplanes: Airbus Service Bulletin A340-56-5002, Revision 01, including Appendix 01, dated February 8, 2012; or Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013. As of the effective date of this AD, use only Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013, to do the actions required by paragraph (g) of this AD.

(h) Retained Replacement With Revised Service Information

This paragraph restates the requirements of paragraph (h) of AD 2013-10-06, Amendment 39-17459 (78 FR 32347, May 30, 2013), with revised service information. If it is found, during the inspection required by paragraph (g) of this AD, that any installed LH or RH windshield was manufactured by Saint-Gobain Sully (SGS) and the part number and serial number are specified in the applicable Airbus service information specified in paragraph (g)(1), (g)(2), or (g)(3) of this AD: Within 9 months or 1,200 flight hours after July 5, 2013 (the effective date of AD 2013-10-06), whichever occurs first, replace all affected LH and RH windshields, in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraph (h)(1), (h)(2), or (h)(3) of this AD.

(1) For Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes: Airbus Service Bulletin A330-56-3009, Revision 02, including Appendix 01, dated February 8, 2012; or Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013. As of the effective date of this AD, use only Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013, to do the actions required by paragraph (h) of this AD.

(2) For Model A340-211, -212, -213, -311, -312, and -313 airplanes: Airbus Service Bulletin A340-56-4008, Revision 01, including Appendix 01, dated February 8, 2012; or Airbus Service Bulletin A340-56-4008, Revision 02, including Appendixes 01 and 02, dated August 1, 2013. As of the effective date of this AD, use only Airbus Service Bulletin A340-56-4008, Revision 02, including Appendixes 01 and 02, dated August 1, 2013, to do the actions required by paragraph (h) of this AD.

(3) For Model A340-541 and -642 airplanes: Airbus Service Bulletin A340-56-5002, Revision 01, including Appendix 01, dated February 8, 2012; or Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013. As of the effective date of this AD, use only Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013, to do the actions required by paragraph (h) of this AD.

(i) New Requirement of This AD: Inspection

Within 6 months after the effective date of this AD, inspect to identify the manufacturer, the part number, and the serial number of the LH and RH windshields installed on the airplane, in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraph (i)(1), (i)(2), or (i)(3) of this AD. A review of airplane delivery or maintenance records is

acceptable in lieu of this inspection if the manufacturer, part number, and serial number of the installed windshields can be conclusively determined from that review.

(1) For Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes: Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013.

(2) For Model A340-211, -212, -213, -311, -312, and -313 airplanes: Airbus Service Bulletin A340-56-4008, Revision 02, including Appendixes 01 and 02, dated August 1, 2013.

(3) For Model A340-541 and -642 airplanes: Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013.

(j) New Requirement of This AD: Replacement

If it is found, during the inspection required by paragraph (i) of this AD, that any installed LH or RH windshield was manufactured by Saint-Gobain Sully (SGS) and the part number and serial number are specified in Appendix 02 of the applicable Airbus service information specified in paragraph (j)(1), (j)(2), or (j)(3) of this AD, or if the manufacturer or part number or serial number is not identifiable: Within 6 months after the effective date of this AD, replace the affected LH and/or RH windshield with a serviceable part, in accordance with the Accomplishment Instructions of the applicable Airbus service information specified in paragraph (j)(1), (j)(2), or (j)(3) of this AD.

(1) For Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes: Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013.

(2) For Model A340-211, -212, -213, -311, -312, and -313 airplanes: Airbus Service Bulletin A340-56-4008, Revision 02, including Appendixes 01 and 02, dated August 1, 2013.

(3) For Model A340-541 and -642 airplanes: Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013.

(k) Definition of Serviceable Windshield

For the purposes of this AD, a serviceable windshield is a windshield not identified in Appendix 01 of the applicable Airbus service information as specified in paragraphs (j)(1), (j)(2), or (j)(3) of this AD; or it is specified in Appendix 01 but has a suffix "U" added to the serial number on the identification plate.

(l) Parts Installation Limitations

As of the effective date of this AD, no person may install, on any airplane, an affected windshield from SGS having a part number and serial number identified in Appendix 01 of the applicable Airbus service information as specified in paragraph (l)(1), (l)(2), or (l)(3) of this AD, unless a suffix "U" has been added on the serial number identification plate.

(1) For Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes: Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013.

(2) For Model A340-211, -212, -213, -311, -312, and -313 airplanes: Airbus Service Bulletin A340-56-4008, Revision 02, including Appendix 01 and 02, dated August 1, 2013.

(3) For Model A340-541 and -642 airplanes: Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013.

(m) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using the applicable Airbus service

information specified in paragraphs (m)(1) through (m)(4) of this AD, provided that the actions were accomplished on the airplane, and no replacement windshield has been installed with a part number and serial number identified in Appendix 02 of the applicable Airbus service information as specified in paragraphs (j)(1) through (j)(3) of this AD.

(1) Airbus Service Bulletin A330-56-3009, dated May 4, 2010 (for Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes), which is not incorporated by reference in this AD.

(2) Airbus Service Bulletin A330-56-3009, Revision 01, dated January 27, 2011 (for Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes), which is not incorporated by reference in this AD.

(3) Airbus Service Bulletin A340-56-4008, dated May 4, 2010 (for Model A340-211, -212, -213, -311, -312, and -313 airplanes), which is not incorporated by reference in this AD.

(4) Airbus Service Bulletin A340-56-5002, dated May 4, 2010 (for Model A340-541 and -642 airplanes), which is not incorporated by reference in this AD.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM 116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0256, dated October 21, 2013, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0192-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-56-3009, Revision 03, including Appendixes 01 and 02, dated August 1, 2013.

(ii) Airbus Service Bulletin A340-56-4008, Revision 02, including Appendix 01 and 02, dated August 1, 2013.

(iii) Airbus Service Bulletin A340-56-5002, Revision 02, including Appendixes 01 and 02, dated August 1, 2013.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 24, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-04 The Boeing Company: Amendment 39-18009 ; Docket No. FAA-2014-0288;
Directorate Identifier 2013-NM-101-AD.

(a) Effective Date

This AD is effective December 11, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, and DC-9-15F airplanes; Model DC-9-21 airplanes; and Model DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, and DC-9-32F (C-9A, C-9B) airplanes; certificated in any category; equipped with a non-ventral aft pressure bulkhead.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the improved (shot-peened) non-ventral aft pressure bulkhead tee is subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking of the improved (shot-peened) non-ventral aft pressure bulkhead tees connecting the bulkhead web to the fuselage, which could result in reduced structural integrity and rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

(1) For the purposes of this AD, the term "original tee section" refers to the original (non-peened) non-ventral aft pressure bulkhead web to fuselage skin attach tee sections.

(2) For the purposes of this AD, the term "improved tee section" refers to improved (shot peened) non-ventral aft pressure bulkhead web to fuselage skin attach tee sections.

(h) Inspection

For airplanes on which an improved tee section having P/N 5910163-257, 5910163-259, 5910163-260, 5910163-261, 5910163-262, 5910163-263, SR09530001-3, SR09530001-5,

SR09530001-6, SR09530001-7, SR09530001-8, SR09530001-9, SR09530001-29, SR09530001-30, SR09530001-31, SR09530001-32, SR09530001-33, SR09530001-35, SR09530056-3, SR09530056-5, SR09530056-6, SR09530056-7, SR09530056-8, SR09530056-9, SR09530056-11, SR09530056-13, SR09530056-14, SR09530056-15, SR09530056-16, SR09530056-17, SR09530056-19, SR09530056-21, SR09530056-22, SR09530056-23, SR09530056-24, or SR09530056-25, is installed: At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, do a general visual and low frequency eddy current (LFEC) inspection (Option I), or a high and low frequency eddy current inspection (Option II), for cracking of the improved tee sections, in accordance with the Accomplishment Instructions of McDonnell Douglas DC-9 Alert Service Bulletin A53-231, Revision 2, dated June 25, 1993, including Service Sketch 3683D, Revision C, dated July 19, 1989.

(i) Compliance Times

(1) For Option I and Option II inspections specified in paragraph (h) of this AD: If the time of installation of an improved tee section having a part number listed in paragraph (h) of this AD is known, do the initial inspection required by paragraph (h) of this AD within 50,000 flight cycles after installation of the improved tee section, or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

(2) For Option I and Option II inspections specified in paragraph (h) of this AD: If the time of installation of an improved tee section having a part number identified in paragraph (h) of this AD is not known, do the initial inspection required by paragraph (h) of this AD before the accumulation of 75,000 total flight cycles, or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

(j) Repetitive Inspections

If no cracking is found during the inspection required by paragraph (h) of this AD: Do the actions specified in paragraph (j)(1) or (j)(2) of this AD, as applicable, in accordance with the Accomplishment Instructions of McDonnell Douglas DC-9 Alert Service Bulletin A53-231, Revision 2, dated June 25, 1993, including Service Sketch 3683D, Revision C, dated July 19, 1989.

(1) For Option I: If Option I was used for the inspection required by paragraph (h) of this AD, do the actions at the applicable intervals, as specified in paragraphs (j)(1)(i), (j)(1)(ii), and (j)(1)(iii) of this AD.

(i) Repeat the LFEC inspection for cracking of the side areas above the floor between longerons L7 and L17 on the fuselage left and right sides, at intervals not to exceed 2,000 flight cycles.

(ii) Repeat the general visual inspection for cracking of the top and lower areas from longeron L7 left side to L7 right side, and lower fuselage longeron L17 to L20 on the fuselage left and right sides, at intervals not to exceed 1,500 flight cycles.

(iii) Repeat the general visual inspection for cracking of the bottom areas from longeron L20 left side to L20 right side, at intervals not to exceed 3,500 flight cycles.

(2) For Option II: If Option II was used for the inspection required by paragraph (h) of this AD, repeat the high and low eddy frequency eddy current inspections for cracking around the entire periphery of the fuselage from the forward side of the bulkhead at intervals not to exceed 2,500 flight cycles.

(k) Corrective Action and Post-Replacement Inspections

If any cracking is found during any inspection required by paragraph (h) or (j) of this AD: Before further pressurized flight, replace each cracked tee section with an airworthy tee section having a part number identified in paragraph (h) of this AD, or with an original tee section having P/N 5910163-89, 5910163-91, 5910163-92, 5910163-93, 5910163-94, or 5910163-95, in accordance with the

Accomplishment Instructions of McDonnell Douglas DC-9 Alert Service Bulletin A53-231, Revision 2, dated June 25, 1993, including Service Sketch 3683D, Revision C, dated July 19, 1989.

(1) If the tee section is replaced with an improved tee section listed in paragraph (h) of this AD, prior to the accumulation of 50,000 flight cycles after installation, inspect the tee section in accordance with paragraph (h) of this AD and do all applicable corrective actions and repetitive inspections in accordance with and at the times specified in paragraphs (j) and (k) of this AD.

(2) If the tee section is replaced with an original tee section listed in paragraph (k) of this AD, prior to the accumulation of 25,000 flight cycles after installation, inspect the tee section in accordance with paragraph (h) of this AD and do all applicable corrective actions and repetitive inspections in accordance with and at the times specified in paragraphs (j) and (k) of this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

(m) Related Information

For more information about this AD, contact Eric Schrieber, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5348; fax: 562-627-5210; email: eric.schrieber@faa.gov.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) McDonnell Douglas DC-9 Alert Service Bulletin A53-231, Revision 2, dated June 25, 1993, including Service Sketch 3683D, Revision C, dated July 19, 1989.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.
Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-05 The Boeing Company: Amendment 39-18010; Docket No. FAA-2014-0232; Directorate Identifier 2013-NM-100-AD.

(a) Effective Date

This AD is effective December 11, 2014.

(b) Affected ADs

This AD affects certain requirements of AD 96-16-04, Amendment 39-9704 (61 FR 39860, July 31, 1996).

(c) Applicability

This AD applies to The Boeing Company Model DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, and DC-9-15F airplanes; Model DC-9-21 airplanes; Model DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, and DC-9-32F (C-9A, C-9B) airplanes; Model DC-9-41 airplanes; and Model DC-9-51 airplanes; certificated in any category; equipped with a ventral aft pressure bulkhead.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the improved (shot-peened) ventral aft pressure bulkhead dome tees, which connect the bulkhead web to the fuselage, are subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking of the improved (shot-peened) ventral aft pressure bulkhead dome tees connecting the bulkhead web to the fuselage, which could result in reduced structural integrity and rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

(1) For the purposes of this AD, the term "original tee section" refers to the original (non-peened) ventral aft pressure bulkhead web to fuselage skin attach tee sections.

(2) For the purposes of this AD, the term "improved tee section" refers to improved (shot peened) ventral aft pressure bulkhead web to fuselage skin attach tee sections.

(h) Inspections

For airplanes on which an improved tee section having P/N 5910130-389, 5910130-391, 5910130-392, 5910130-393, 5910130-394, 5910130-387, SR09530001-19, SR09530001-21, SR09530001-22, SR09530001-23, SR09530001-24, SR09530001-25, SR09530001-29, SR09530001-30, SR09530001-31, SR09530001-32, SR09530001-33, SR09530001-35, SR09530056-3, SR09530056-5, SR09530056-6, SR09530056-7, SR09530056-8, SR09530056-9, SR09530056-19, SR09530056-21, SR09530056-22, SR09530056-23, SR09530056-24, or SR09530056-25, is installed: At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, do general visual and low frequency eddy current inspections (Option I), or high and low frequency eddy current inspections (Option II), for cracking of the improved tee sections, in accordance with the Accomplishment Instructions of McDonnell Douglas Alert Service Bulletin A53-232, Revision 2, dated April 28, 1995.

(i) Compliance Times

(1) For Option I and Option II inspections specified in paragraph (h) of this AD: If the time of installation of an improved tee section having a part number listed in paragraph (h) of this AD, is known, do the initial inspection required by paragraph (h) of this AD within 70,000 flight cycles after installation of the improved tee section, or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

(2) For Option I and Option II inspections specified in paragraph (h) of this AD: If the time of installation of an improved tee section having a part number listed in paragraph (h) of this AD, is not known, do the initial inspection required by paragraph (h) of this AD before the accumulation of 105,000 total flight cycles on the airplane or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

(j) Repetitive Inspections

If no cracking is found during the inspection required by paragraph (h) of this AD: Do the actions specified in paragraph (j)(1) or (j)(2) of this AD, as applicable, in accordance with the Accomplishment Instructions of McDonnell Douglas Alert Service Bulletin A53-232, Revision 2, dated April 28, 1995.

(1) For Option I: If Option I was used for the inspection required by paragraph (h) of this AD, repeat the inspections specified in paragraphs (j)(1)(i), (j)(1)(ii), and (j)(1)(iii) of this AD at the intervals specified in paragraphs (j)(1)(i), (j)(1)(ii), and (j)(1)(iii) of this AD.

(i) Repeat the low frequency eddy current inspection for cracking of side areas above the floor between longerons L7 and L17 on the fuselage, at intervals not to exceed 1,500 flight cycles.

(ii) Repeat the general visual inspection for cracking of the top and lower areas from longeron L7 left side to longeron L7 right side, and lower fuselage longeron L17 to longeron L20 on the left and right sides, at intervals not to exceed 1,500 flight cycles.

(iii) Repeat the general visual inspection for cracking of the bottom areas from longeron L20 left side to longeron L20 right side, at intervals not to exceed 3,500 flight cycles.

(2) For Option II: If Option II was used for the inspection required by paragraph (h) of this AD, repeat the high and low frequency eddy current inspection for cracking around the entire periphery of the fuselage on the forward side of the bulkhead, at intervals not to exceed 2,500 flight cycles.

(k) Corrective Actions and Post-Replacement Inspections

If any cracking is found during any inspection required by paragraph (h) or (j) of this AD: Before further pressurized flight, replace each cracked tee section with an airworthy tee section having a part number listed in paragraph (h) of this AD, or with an original tee section having P/N 5910130-47,

5910130-51, 5910130-53, 5910130-54, 5910130-55, or 5910130-56, in accordance with the Accomplishment Instructions of McDonnell Douglas Alert Service Bulletin A53-232, Revision 2, dated April 28, 1995.

(1) If the tee section is replaced with an improved tee section listed in paragraph (h) of this AD, prior to the accumulation of 70,000 flight cycles after installation, inspect the tee section in accordance with paragraph (h) of this AD and do all applicable corrective actions and repetitive inspections in accordance with and at the times specified in paragraphs (j) and (k) of this AD.

(2) If the tee section is replaced with an original tee section listed in paragraph (k) of this AD, prior to the accumulation of 35,000 flight cycles after installation, inspect the tee section in accordance with paragraph (h) of this AD and do all applicable corrective actions and repetitive inspections in accordance with and at the times specified in paragraphs (j) and (k) of this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

(m) Related Information

For more information about this AD, contact Eric Schrieber, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5348; fax: 562-627-5210; email: eric.schrieber@faa.gov.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on September 4, 1996 (61 FR 39860, July 31, 1996).

(i) McDonnell Douglas Alert Service Bulletin A53-232, Revision 2, dated April 28, 1995.

(ii) Reserved.

(4) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>.

(5) You may view this service information FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-06 The Boeing Company: Amendment 39-18011 ; Docket No. FAA-2013-0836;
Directorate Identifier 2013-NM-126-AD.

(a) Effective Date

This AD is effective December 17, 2014.

(b) Affected ADs

This AD replaces AD 2005-07-12, Amendment 39-14036 (70 FR 17596, April 7, 2005).

(c) Applicability

(1) This AD applies to The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/082838ee177dbf62862576a4005cdfc0/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/082838ee177dbf62862576a4005cdfc0/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of new findings of cracking at various locations of the stations (STA) 277 to STA 291.5 frames and intercostals, including webs, chords, clips, and shear ties, between stringers 7R and 17R. We are issuing this AD to detect and correct fatigue cracking of the aft frame and frame support structure of the forward galley door, which could result in a severed fuselage frame web, rapid decompression of the airplane, and possible loss of the forward galley door.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Group 1 Airplanes: Inspections and Corrective Actions

For airplanes identified as Group 1 in Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013: Within 120 days after the effective date of this AD, do inspections for cracking from STA 277 to STA 328, stringer 7R to 17R of the forward galley door cutout, using a method

approved in accordance with the procedures specified in paragraph (m) of this AD. Do all applicable corrective actions before further flight using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(h) Group 2 and Group 3 Airplanes: Inspections and Corrective Actions

(1) For airplanes identified as Group 2 and Group 3 in Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013: Except as provided by paragraph (k)(2) of this AD, at the applicable times specified in tables 1 and 2 in paragraph 1.E, "Compliance," of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, do detailed and surface high frequency eddy current (HFEC) inspections, as applicable, for cracking in the forward galley door cutout, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013. Repeat the detailed and surface HFEC inspections thereafter at the applicable intervals specified in tables 1 and 2 in paragraph 1.E, "Compliance," of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013. If any crack is found, before further flight, do all applicable corrective actions in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, except as required by paragraph (k)(1) of this AD. Accomplishment of a repair specified in Steps 1.a., 2.a., 6.a., or 6.b. of Part 2, of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, as applicable, and except as required by paragraph (k)(1) of this AD, terminates the inspections required by this paragraph for the repaired area(s) only.

(2) Removal and replacement of a cracked part, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, does not terminate the repetitive inspections required by paragraph (h)(1) of this AD.

(i) Terminating Action

The inspections required by paragraph (h)(1) of this AD may be terminated at areas with repairs installed prior to the effective date of this AD, provided the repairs meet the conditions specified in note 11 or note 13 of paragraph 3.A., "General Information," of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013.

(j) Optional Terminating Action

Accomplishment of the preventive modification on the STA 291.5 frame web, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, terminates the inspections required by paragraph (h)(1) of this AD for the area that is common to the preventive modification.

(k) Exceptions to the Service Information

(1) Where Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, specifies to contact Boeing for a corrective action: Before further flight, do the applicable action using a method approved in accordance with the procedures specified in paragraph (m) of this AD.

(2) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, specifies a compliance time "after the date on Revision 1 of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(3) The title to each page of figure 5 of Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013, is incorrect and refers to "Stringer 16R" when it should refer to "Stringer 14R."

(l) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 737-53A1241, dated June 13, 2002, which is not incorporated by reference in this AD.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (n)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for the actions specified in AD 2005-07-12, Amendment 39-14036 (70 FR 17596, April 7, 2005), are approved as AMOCs for the corresponding provisions of this AD.

(n) Related Information

(1) For more information about this AD, contact Alan Pohl, Aerospace Engineer, Airframe Branch, ANM-120S, FAA Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6450; fax: 425-917-6590; email: alan.pohl@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (o)(3) and (o)(4) of this AD.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1241, Revision 1, dated June 11, 2013. (ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Ave. SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.
Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-07: Amendment 39-18012. Docket No. FAA-2014-0483; Directorate Identifier 2014-NM-082-AD.

(a) Effective Date

This AD becomes effective December 12, 2014.

(b) Affected ADs

This AD replaces AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013).

(c) Applicability

This AD applies to the airplanes specified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, serial numbers 10002 and subsequent.

(2) Bombardier, Inc. Model CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) airplanes, serial numbers 15001 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Reason

This AD was prompted by a report of corrosion of the components of the main landing gear (MLG) retraction actuator found in service; the corrosion was found at the interface of the rod end and the piston, and at the bracket and related pins. We are issuing this AD to prevent disconnection of the MLG retraction actuator, which could result in extension of the MLG without damping, and consequent structural damage and collapse of the MLG during landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection of the MLG Retraction Actuator and Corrective Actions With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with no changes. For any airplane with an MLG retraction actuator assembly having any part number and serial number identified in paragraph 1.A., Effectivity, of Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012, except airplanes on which modification status "32-64" is marked on the identification plate: At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD, perform a detailed inspection of the retraction

actuator assembly for evidence of corrosion and security of the jam nut, as applicable, in accordance with Part A of the Accomplishment Instructions of Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012; and Goodrich Service Bulletin 49600-32-63 R1, dated May 17, 2011. If any corrosion or unsecured jam nut is found, before further flight, replace the retract actuator with a new or serviceable retract actuator; and install the retract actuator, in accordance with Part A of the Accomplishment Instructions of Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012. Repeat the inspection thereafter at intervals not to exceed 1,200 flight hours or 12 months, whichever occurs first.

(1) For MLG retraction actuator assemblies on which, as of September 24, 2013 (the effective date of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013)), 8,000 or more total flight hours have accumulated since new or since overhaul, or that have been in service for more than 4 years since new or since overhaul: Inspect within 1,200 flight hours or 12 months after September 24, 2013, whichever occurs first.

(2) For MLG retraction actuator assemblies on which, as of September 24, 2013 (the effective date of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013)), less than 8,000 total flight hours have accumulated since new or since overhaul, and that have been in service for 4 years or less since new or since overhaul: Inspect before the accumulation of 9,200 total flight hours on the MLG retraction actuator assembly since new or since overhaul or within 5 years in service since new or since overhaul, whichever occurs first.

(h) Retained Inspection of MLG Retraction Actuator Bracket and Related Pins, and Corrective Actions With No Changes

This paragraph restates the requirements of paragraph (h) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with no changes. For any airplane with an MLG dressed shock strut having any part number and serial number identified in paragraph 1.A., Effectivity, of Bombardier Service Bulletin 670BA-32-033, Revision B, dated June 26, 2012: Within 4,400 flight hours or 24 months after September 24, 2013 (the effective date of AD 2013-16-08), whichever occurs first, perform a detailed inspection of the retract actuator bracket assembly, associated pins, and the mating lugs on the outer cylinder for evidence of corrosion, in accordance with Bombardier Service Bulletin 670BA-32-033, Revision B, dated June 26, 2012; and Goodrich Service Bulletin 49000-32-46 R2, dated November 11, 2011. Do all applicable corrective actions before further flight (i.e., replace retract actuator bracket assembly and pins, or outer cylinder lugs, as applicable).

(i) Retained Installation of New Jam Nut With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with no changes. For any airplane with an MLG retraction actuator assembly having any part number and serial number identified in paragraph 1.A., Effectivity, of Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012, except airplanes on which modification status "32-64" is marked on the identification plate: Within 20,000 flight hours or 10 years after September 24, 2013 (the effective date of AD 2013-16-08), whichever occurs first, install a new jam nut having part number 49606-5, in accordance with Part B of the Accomplishment Instructions of Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012; and Goodrich Service Bulletin 49600-32-64 R3, dated December 15, 2011.

(j) Retained Credit for Previous Actions With Change to Paragraph (j)(1)(iii) of This AD

(1) This paragraph restates the credit provided by paragraph (j)(1) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with a change to the service information citation in paragraph (j)(1)(iii) of this AD. This paragraph provides credit for the actions required by paragraphs (g) and (i) of this AD, if those actions were performed before September 24, 2013 (the

effective date of AD 2013-16-08), using the service information specified in paragraph (j)(1)(i), (j)(1)(ii), or (j)(1)(iii) of this AD, which is not incorporated by reference in this AD.

- (i) Bombardier Service Bulletin 670BA-32-031, dated March 14, 2011.
- (ii) Bombardier Service Bulletin 670BA-32-031, Revision A, dated June 9, 2011.
- (iii) Bombardier Service Bulletin 670BA-32-031, Revision B, dated July 29, 2011.

(2) This paragraph restates the credit provided by paragraph (j)(2) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with no changes. This paragraph provides credit for the actions required by paragraph (h) of this AD, if those actions were performed before September 24, 2013 (the effective date of AD 2013-16-08), using the service information specified in paragraph (j)(2)(i) or (j)(2)(ii) of this AD, which is not incorporated by reference in this AD.

- (i) Bombardier Service Bulletin 670BA-32-033, dated March 14, 2011.
- (ii) Bombardier Service Bulletin 670BA-32-033, Revision A, dated July 29, 2011.

(k) Retained Parts Installation Limitations With Change to Paragraph (k)(2) of This AD

(1) This paragraph restates the parts installation limitation specified in paragraph (k)(1) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with no changes. As of September 24, 2013 (the effective date of AD 2013-16-08), no person may install on any airplane an MLG retraction actuator assembly having any part number and serial number identified in paragraph 1.A., Effectivity, of Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012, unless that retraction actuator assembly has been inspected as specified in paragraph (g) of this AD, and all applicable corrective actions (i.e., replacement of the retract actuator) specified in paragraph (g) of this AD have been done. Repeat the inspection specified in paragraph (g) of this AD thereafter at the intervals specified in paragraph (g) of this AD.

(2) This paragraph restates the parts installation limitation specified in paragraph (k)(2) of AD 2013-16-08, Amendment 39-17546 (78 FR 51055, August 20, 2013), with a revised part name. As of the effective date of this AD, no person may install on any airplane an MLG dressed shock strut having any part number and serial number identified in paragraph 1.A., Effectivity, of Bombardier Service Bulletin 670BA-32-033, Revision B, dated June 26, 2012, unless that retraction actuator assembly has been inspected and all applicable corrective actions have been done, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-32-033, Revision B, dated June 26, 2012.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2011-36R1, dated October 3, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0483-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(4), (n)(5), and (n)(6) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on September 24, 2013 (78 FR 51055, August 20, 2013).

(i) Bombardier Service Bulletin 670BA-32-031, Revision C, dated April 17, 2012.

(ii) Bombardier Service Bulletin 670BA-32-033, Revision B, dated June 26, 2012.

(iii) Goodrich Service Bulletin 49000-32-46 R2, dated November 11, 2011.

(iv) Goodrich Service Bulletin 49600-32-63 R1, dated May 17, 2011.

(v) Goodrich Service Bulletin 49600-32-64 R3, dated December 15, 2011.

(4) For Bombardier service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(5) For Goodrich service information identified in this AD, contact Goodrich Corporation, Landing Gear, 1400 South Service Road, West Oakville L6L 5Y7, Ontario, Canada; telephone 905-825-1568; email jean.breed@goodrich.com; Internet <http://www.goodrich.com/TechPubs>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-08 Airbus: Amendment 39-18013. Docket No. FAA-2014-0452; Directorate Identifier 2013-NM-185-AD.

(a) Effective Date

This AD becomes effective December 17, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes; certificated in any category; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits and Maintenance Checks.

(e) Reason

This AD was prompted by a determination that more restrictive airworthiness limitations are necessary. We are issuing this AD to prevent a safety-significant latent failure (which is not announced) which, in combination with one or more other specific failures or events, would result in a hazardous or catastrophic failure condition.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 30 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, by incorporating Airbus A318/A319/A320/A321 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 1, dated June 15, 2012. The initial compliance time for accomplishing the tasks specified in Airbus A318/A319/A320/A321 ALS Part 3, CMR, Revision 1, dated June 15, 2012, is at the applicable time specified in the Record of Revisions of Airbus A318/A319/A320/A321 ALS Part 3, CMR, Revision 1, dated June 15, 2012; or within 30 days after the effective date of this AD, whichever occurs later.

(h) No Alternative Actions or Intervals

After accomplishing the revisions required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance in accordance with the procedures specified in paragraph (i) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directive 2013-0148, dated July 16, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0452-0002>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus A318/A319/A320/A321 Airworthiness Limitations Section (ALS) Part 3, Certification Maintenance Requirements (CMR), Revision 1, dated June 15, 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office–EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.
Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-09 The Boeing Company: Amendment 39-18014 ; Docket No. FAA-2014-0430;
Directorate Identifier 2014-NM-083-AD.

(a) Effective Date

This AD is effective December 17, 2014.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01920SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/59027f43b9a7486e86257b1d006591ee/\\$FILE/ST01920SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/59027f43b9a7486e86257b1d006591ee/$FILE/ST01920SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01920SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by a report of a trailing edge (TE) flap rotary actuator that had slipped relative to its mating reaction ring, which is attached to the flap support rib. We are issuing this AD to detect and correct flap rotary actuator gear disengagement from its mating reaction ring. This disengagement with flaps extended could cause an uncommanded roll due to flap blowback, overload, or flap departure from the airplane, which could compromise safe flight and landing of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections, Related Investigative Actions, and Corrective Actions

Except as provided by paragraph (h) of this AD, at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-27A0229, dated March 4, 2014: Do a detailed inspection for corrosion of the rotary actuator assembly fixed ring gear and reaction ring splines for each support position; and do all applicable related investigative and corrective actions if

necessary; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 767-27A0229, dated March 4, 2014. Do all applicable related investigative and corrective actions before further flight. Repeat the inspection of the rotary actuator assembly fixed ring gear and reaction ring splines for each support position thereafter at the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-27A0229, dated March 4, 2014.

(h) Exception to the Requirements of Paragraph (g) of this AD

Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-27A0229, dated March 4, 2014, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time "after the effective date of this AD."

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) If the service information contains steps that are labeled as RC (Required for Compliance), those steps must be done to comply with this AD; any steps that are not labeled as RC are recommended. Those steps that are not labeled as RC may be deviated from, done as part of other actions, or done using accepted methods different from those identified in the specified service information without obtaining approval of an AMOC, provided the steps labeled as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to steps labeled as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Allen Rauschendorfer, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6487; fax: 425-917-6590; email: Allen.Rauschendorfer@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 767-27A0229, dated March 4, 2014.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.

Jeffrey E. Duven
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-11 The Boeing Company: Amendment 39-18016; Docket No. FAA-2014-0289; Directorate Identifier 2013-NM-146-AD.

(a) Effective Date

This AD is effective December 17, 2014.

(b) Affected ADs

This AD replaces AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012).

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747-400F, 747SR, and 747SP series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an analysis by the manufacturer indicating that tension ties are susceptible to widespread fatigue damage. The actions were developed to support the airplane's limit of validity of the engineering data that support the established structural maintenance program. We are issuing this AD to prevent tension ties from becoming severed or disconnected from the frames, which could lead to reduced structural integrity and sudden decompression of the airplane in flight.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Actions for Group 1 and Groups 3 Through 6 Airplanes

This paragraph restates the requirements of paragraph (g) of AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012). For Group 1, and Groups 3 through 6 airplanes identified in Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005: At the applicable time in paragraph (g)(1) or (g)(2) of this AD, do detailed and high frequency eddy current (HFEC) inspections for cracking of each affected tension tie and of the surrounding structure. If any cracking is found: Before further flight, do all applicable corrective and related investigative actions. Do all actions in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005; or Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010. Where Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005; or Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17,

2010; specifies to contact Boeing for repair instructions: Before further flight, repair the area using a method approved in accordance with the procedures specified in paragraph (n) of this AD. As of August 14, 2012 (the effective date of AD 2012-13-08), only Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, may be used to accomplish the actions required in this paragraph.

(1) For airplanes identified in Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005, as Groups 1, 3, and 6 airplanes: Do the first inspections before the accumulation of 20,000 total flight cycles, or within 1,000 flight cycles after February 16, 2006 (the effective date of AD 2006-01-07, Amendment 39-14446 (71 FR 1947, January 12, 2006)), whichever occurs later; and repeat the inspections thereafter at intervals not to exceed 4,000 flight cycles until the modification required by paragraph (j) of this AD is accomplished.

(2) For airplanes identified in Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005, as Groups 4 and 5 airplanes: Do the first inspections before the accumulation of 17,000 total flight cycles, or within 1,000 flight cycles after February 16, 2006 (the effective date of AD 2006-01-07, Amendment 39-14446 (71 FR 1947, January 12, 2006)), whichever occurs later; and repeat the inspections thereafter at intervals not to exceed 3,000 flight cycles until the modification required by paragraph (j) of this AD is accomplished.

(h) Retained Inspections for Group 2 Airplanes

This paragraph restates the requirements of paragraph (h) of AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012). For Group 2 airplanes identified in Boeing Alert Service Bulletin 747 53A2502, Revision 1, dated June 17, 2010: At the applicable times specified in paragraphs (h)(1) and (h)(2) of this AD, do detailed and HFEC inspections for cracking of each affected tension tie and of the surrounding structure, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005; or Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010. If any cracking is found: Before further flight, do all applicable corrective and related investigative actions. Do all actions in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005; or Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010. Where Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005; or Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010; specify to contact Boeing for repair instructions: Before further flight, repair the area using a method approved in accordance with the procedures specified in paragraph (n) of this AD. As of August 14, 2012 (the effective date of AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012)), only Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, may be used to accomplish the actions required by this paragraph. Repeat the inspections thereafter at intervals not to exceed 3,000 flight cycles until the modification required by paragraph (j) of this AD is accomplished.

(1) For stations (STA) 780 through 940: Before the accumulation of 17,000 total flight cycles, or within 1,000 flight cycles after February 16, 2006 (the effective date of AD 2006-01-07, Amendment 39-14446 (71 FR 1947, January 12, 2006)), whichever occurs later.

(2) For STA 720, 740, and 760: At the earlier of the times specified in paragraph (h)(2)(i) or (h)(2)(ii) of this AD.

(i) Before the accumulation of 17,000 total flight cycles, or within 1,000 flight cycles after February 16, 2006 (the effective date of AD 2006-01-07, Amendment 39-14446 (71 FR 1947, January 12, 2006)), whichever occurs later.

(ii) Before the accumulation of 8,000 total flight cycles, or within 1,000 flight cycles after August 14, 2012 (the effective date of AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012)), whichever occurs later.

(i) Retained One-Time Inspection for Group 2 Airplanes

This paragraph restates the requirements of paragraph (i) of AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012). For airplanes identified in Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, as Group 2 airplanes: Before the accumulation of 8,000 total flight cycles, or within 1,000 flight cycles after August 14, 2012 (the effective date of AD 2012-13-08), whichever occurs later, do a general visual inspection for correct configuration, as identified in Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, of each affected tension tie and of the surrounding structure, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010.

(1) If all tension ties match the correct configurations specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, no further work is required by this paragraph.

(2) If any incorrect configuration is found, before further flight, do detailed and open fastener-hole HFEC inspections for cracking in the tension tie and frame, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010.

(i) If no crack is found during the inspections required by paragraph (i)(2) of this AD: Before further flight, install the correct configuration for the tension ties at locations where the incorrect configuration was found, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010; except where Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, specifies to contact Boeing for installation instructions, use a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(ii) If any crack is found during the inspections required by paragraph (i)(2) of this AD, before further flight, do the actions specified in paragraphs (i)(2)(ii)(A) and (i)(2)(ii)(B) of this AD.

(A) Repair the crack in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010; except where Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, specifies to contact Boeing for appropriate action, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(B) Install the correct configuration for the tension ties at locations where the incorrect configuration was found, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010; except where Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010, specifies to contact Boeing for installation instructions, use a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(j) New Tension Tie and Frame Modification and Inspections

(1) For Groups 1 through 16, Configuration 1, airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: At the applicable compliance time specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, except as required by paragraph (l)(1) of this AD, do tension tie and frame modifications, in accordance with Part 1, and surface HFEC inspections for cracks, in accordance with Part 4, of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013. Accomplishment of these modifications terminates the repetitive inspections required by paragraphs (g) and (h) of this AD. If any crack is found, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(2) For Groups 17 and 18 airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: At the applicable time specified in table 6 or table 7, as applicable,

of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, do a tension tie and frame modification (replacement of tension ties and frame structure), in accordance with Part 5 or Part 6, as applicable, of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013. Accomplishment of these modifications terminates the repetitive inspections required by paragraph (g) of this AD.

(k) New Repetitive Post-Modification Detailed Inspections of Unmodified Areas; Repetitive Post-Modification HFEC Inspections of Modified and Unmodified Areas

(1) For Groups 1 through 16 airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: At the applicable time specified in table 2 or table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, do a detailed inspection for cracking in the unmodified areas of the tension ties, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013. If any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD. Repeat the detailed inspection thereafter at the applicable time specified in table 2 or table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013.

(2) For Groups 1 through 16 airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: At the applicable time specified in table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, do eddy current inspections for cracking in all areas of the tension ties (modified and unmodified), in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013. If any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD. Repeat the eddy current inspections thereafter at the time specified in table 4 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013.

(3) For Groups 1 through 16, Configuration 2, airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: At the applicable time specified in table 5 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, except as provided by paragraph (l)(1) of this AD, do surface HFEC inspections for cracking in the unmodified tension tie center sections, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013. If any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD. If no cracking is found, no further action is required until the repetitive inspections required by paragraphs (k)(1) and (k)(2) begin.

(4) For Groups 17 and 18 airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: At the applicable time specified in table 6 or table 7 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, do detailed and HFEC inspections of the modified tension tie and frame structure for cracking, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010. Except as required by paragraph (l)(4) of this AD, if any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD. Repeat the detailed and HFEC inspections thereafter at the times specified in table 6 or table 7, as applicable, of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013.

(l) Service Information Clarifications and Exceptions

(1) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, specifies a compliance time "after the revision 3 date of this service bulletin," this AD requires compliance within the specified time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, specifies to contact Boeing for repair instructions, this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(3) Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, refers to Section 51-10-02 of the Boeing 747-400F Structural Repair Manual (SRM) and Section 51-10-01 of the Boeing 747-100/200/300 SRM as additional sources of guidance for removing small cracks and fatigue damage material from the existing holes in the unmodified center section of the tension tie channels. Where those SRM sections state that "zero-timing must only be used where specifically permitted in an SRM chapter-section-repair," this AD allows the zero-timing procedures specified in those SRM sections.

(4) Where Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013, specifies to contact Boeing for repair instructions, this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(m) Credit for Previous Actions

(1) This paragraph restates the credit provided in paragraph (m) of AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012). This paragraph provides credit for the actions required by paragraphs (j)(1) and (k)(1) of this AD, if those actions were performed before August 14, 2012 (the effective date of AD 2012-13-08) using Boeing Alert Service Bulletin 747-53A2605, dated December 8, 2009, which was incorporated by reference in AD 2012-13-08.

(2) For Groups 1 through 16 airplanes identified in Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013: This paragraph provides credit for the actions required by paragraphs (j)(1) and (k)(1) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747-53A2605, Revision 2, dated December 9, 2011, which is not incorporated by reference in this AD.

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (o)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(4) AMOCs approved for inspections required by AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012) are approved as AMOCs for the corresponding inspection provisions of paragraphs (g), (h), and (i) of this AD.

(5) AMOCs approved for AD 2012-13-08, Amendment 39-17110 (77 FR 40481, July 10, 2012) that granted modification deviations are approved as AMOCs for the corresponding modification required by paragraph (j)(1) of this AD.

(o) Related Information

(1) For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: Nathan.P.Weigand@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(6) and (p)(7) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on December 17, 2014.

(i) Boeing Alert Service Bulletin 747-53A2605, Revision 3, dated July 10, 2013.

(ii) Reserved.

(4) The following service information was approved for IBR on August 14, 2012 (77 FR 40481, July 10, 2012).

(i) Boeing Alert Service Bulletin 747-53A2502, Revision 1, dated June 17, 2010.

(ii) Reserved.

(5) The following service information was approved for IBR on February 16, 2006 (71 FR 1947, January 12, 2006).

(i) Boeing Special Attention Service Bulletin 747-53-2502, dated April 21, 2005.

(ii) Reserved.

(6) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(7) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(8) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 28, 2014.

Jeffrey E. Duven,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.