

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT**

**BIWEEKLY 2019-17**

*8/5/2019 - 8/18/2019*



Federal Aviation Administration  
Continued Operational Safety Policy Section, AIR-141  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

### MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250



## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-03-09		Airbus SAS	A310-304, -322, -324, and -325 airplanes
2019-03-10	R 2017-07-05	Airbus SAS	A300 airplanes
2019-03-11		Airbus SAS	A350-941 and -1041 airplanes
2019-03-15		Airbus SAS	A330-201, -202, and -203; A330-301, -302, and -303 airplanes
2019-03-17	A 2017-25-04	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-19		Saab AB, Saab Aeronautics	SAAB 2000 airplanes
2019-03-20	A 2014-16-23 A 2016-16-09	Dassault Aviation	FALCON 7X airplanes
2019-03-21		Embraer S.A.	ERJ 190-100 STD, -100 LR, and -100 IGW; ERJ 190-200 STD, -200 LR, and -200 IGW airplanes
2019-03-23		Airbus SAS	A330, A340 airplanes
<b>Biweekly 2019-06</b>			
2019-03-13		Gulfstream Aerospace LP	Gulfstream G150 airplanes
2019-03-14		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes
2019-03-16	A 2006-25-06 A 97-04-08	Fokker Services B.V.	F.27 Mark 100, 200, 300, 400, 500, 600, and 700 airplanes
2019-03-18		Airbus SAS	A318, A319, A320 airplanes
2019-03-22		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2019-03-24		The Boeing Company	737-400 series airplanes
2019-03-25	A 2008-02-15	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-26		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-03-27		Dassault Aviation	Falcon 10 airplanes
2019-03-28	R 2016-07-23	Airbus SAS	A318, A319, A320, A321 airplanes
2019-03-30		Empresa Brasileira de Aeronautica S.A.	EMB-135, EMB-145 airplanes
2019-05-01	R 2017-11-06	Pratt & Whitney Division	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2643, and F117-PW-100 turbofan engines
2019-05-02	R 2017-22-13	Rolls-Royce plc	RB211-Trent 970-84 and RB211-Trent 972-84 turbofan engines
2019-05-08	R 2015-12-08	Airbus SAS	A318, A319, A320, A321 airplanes
<b>Biweekly 2019-07</b>			
2019-05-07	R 2017-20-01	Honeywell International Inc.	TFE731-20R, -20AR, -20BR, and TFE731-40, -40AR, -40BR, and -40R turbofan engines
2019-05-09		Airbus SAS	A320-251N and -271N, and A321-253N airplanes
2019-05-10		Airbus SAS	A350-941 airplanes
2019-05-12		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2019-05-13	R 2007-22-05	Airbus SAS	A300-600 and A310 series airplanes
2019-05-14	R 2012-02-18	Dassault Aviation	MYSTERE-FALCON 50 airplanes
2019-06-01	R 2018-24-01	International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-06-02		Pratt & Whitney Division	PW4158 turbofan engines
2019-06-06		International Aero Engines AG	V2500-A1, V2522-A5, V2524-A5, V2525-D5, V2527-A5, V2527E-A5, V2527M-A5, V2528-D5, V2530-A5, V2533-A5 turbofan engines
2019-06-07	R 2016-22-05	Pratt & Whitney Division	Certain PW4000 engines (see AD)
<b>Biweekly 2019-08</b>			
2019-06-01	R 2018-24-01	International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2019-06-02	COR	Pratt & Whitney Division	PW4158 turbofan engines
2019-06-03	A 2017-01-08	Airbus SAS	A330 and A340 airplanes
2019-06-08		Airbus SAS	A330-223, A330-223F, A330-321, A330-322, and A330-323 airplanes
2019-06-09		Airbus SAS	A350-941 airplanes

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-06-12		Airbus SAS	A330-201, -202, and -203; A330-301, -302, and -303 airplanes
2019-07-03		Zodiac Seats France	536-Series Cabin Attendant Seats
<b>Biweekly 2019-09</b>			
2019-07-01	A 2014-26-07	Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G airplanes
2019-07-04	COR	The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2019-07-05	R 2016-19-04	Airbus SAS	A318, A319, A320 and A321 airplanes
2019-07-06		Bombardier, Inc	Model BD-100-1A10 airplanes
2019-07-09		Rolls-Royce plc	Trent 1000-A2, Trent 1000-AE2, Trent 1000-C2, Trent 1000-CE2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 model turbofan engines
<b>Biweekly 2019-10</b>			
2019-03-29		Bombardier, Inc	Model BD-100-1A10 airplanes
2019-06-13		The Boeing Company	Model 787 series airplanes
2019-07-05	COR, A 2016-19-04	Airbus SAS	A318, A319, A320 airplanes
2019-08-01		RECARO Aircraft Seating GmbH & Co. KG	Passenger Compartment Equipment
2019-08-02		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-08-05		The Boeing Company	Model 787-8 and 787-9 airplanes
2019-08-06	R 2016-16-01	Airbus SAS	A330-223F and -243F, A330-201, -202, -203, -223, -243 A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2019-08-09	A 2017-04-13	The Boeing Company	Model 747-8 and 747-8F series airplanes
2019-08-12		Viking Air Limited	Model CL-215-6B11 (CL-215T Variant) and CL-215-6B11 (CL-415 Variant)
<b>Biweekly 2019-11</b>			
2019-08-03		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-08-07	R 2014-20-04	Airbus SAS	A318, A319, A320 and A321 airplanes
2019-08-08	R 2010-14-05	Bombardier, Inc.	Model CL-600-1A11 (600), Model CL-600-2A12 (601), Model CL-600-2B16 airplanes
2019-09-01		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
<b>Biweekly 2019-12</b>			
2019-08-04	R 2012-25-02	Bombardier, Inc.	Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2019-08-11	R 2008-24-14	Bombardier, Inc.	Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2019-10-03		The Boeing Company	Model 737-100, -200, -200C, -300, -400, and -500 series airplanes
2019-10-04		BRP-Rotax GmbH & Co KG	BRP-Rotax GmbH & Co KG (Rotax) 912 F2, 912 F3, and 912 F4 engines, Rotax 912 S2, 912 S3, and 912 S4 engines, Rotax 914 F2, 914 F3, and 914 F4 engines, and Rotax 912 F2, 912 F3, 912 F4, 912 S2, 912 S3, 912 S4, 914 F2, 914 F3, and 914 F4 engines
2019-10-05		Viking Air Limited	Models DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300, and DHC-6-400 airplanes
<b>Biweekly 2019-13</b>			
2019-10-01		Bombardier, Inc	Model CL-600-2A12 (601) airplanes
2019-11-01		Airbus SAS	Model A350-941 airplanes
2019-11-02	R 2017-16-10	The Boeing Company	Model 777-200, -200LR, -300, -300ER, and 777F series airplanes
2019-11-03		The Boeing Company	Model 737-700C, -800, and -900ER series airplanes

# LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-11-06	A 2013-19-23	The Boeing Company	Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2019-11-07		Rolls-Royce plc	RB211-524G2-19, RB211-524G2-T-19, RB211-524G3-19, RB211-524G3-T-19, RB211-524H2-19, RB211-524H2-T-19, RB211-524H-36 and RB211-524H-T-36 engines
2019-11-08		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1129G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM model turbofan engines
2019-11-09		Airbus SAS	Model A319-113 and -114 airplanes, and Model A320-211 and -212 airplanes
2019-12-01		CFM International S.A	LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B3, -1B28B2C, -1B28BBJ1, and -1B28BBJ2 model turbofan engines
2019-12-05		CFM International S.A	CFM56-5B1, -5B2, -5B4, -5B5, -5B6, -5B7, -5B1/P, -5B2/P, -5B3/P, -5B4/P, -5B5/P, -5B6/P, -5B7/P, -5B8/P, -5B9/P, -5B3/P1, -5B4/P1, -5B1/2P, -5B2/2P, -5B3/2P, -5B4/2P, -5B6/2P, -5B9/2P, -5B3/2P1, -5B4/2P1, -7B20, -7B22, -7B24, -7B26, -7B27, -7B22/B1, -7B24/B1, -7B26/B1, -7B26/B2, -7B27/B1, -7B27/B3, -7B20/2, -7B22/2, -7B24/2, -7B26/2, -7B27/2, -7B27A model turbofan engines
<b>Biweekly 2019-14</b>			
2019-12-03		Bombardier, Inc.	Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes
2019-12-04	R 2018-19-18 A 2014-20-18	Airbus SAS	Model A300 B4-603, B4-620, B4-622, B4-605R, B4-622R, C4-605R Variant F, F4-605R, and F4-622R airplanes
2019-12-07	R 2007-11-11 R 2018-01-11	Airbus SAS	Model A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, A320-211, -212, -214, -216, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2019-12-10	A 2017-06-06 A 2012-12-07	Fokker Services B.V	Model F28 Mark 0070 and 0100 airplanes
2019-12-13		The Boeing Company	Model 757-200, -200PF, -200CB, and -300 series airplanes
<b>Biweekly 2019-15</b>			
2019-10-02		Saab AB, Saab Aeronautics	Model SAAB 2000 airplanes
2019-12-02		Bombardier Inc.	Model BD-700-1A10 and BD-700-1A11 airplanes
2019-12-08		Bombardier, Inc.	Model CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2019-12-09		Rockwell Collins, Inc.	Flight Display System Application FDSA-6500
2019-12-11		Bombardier, Inc	Model CL-600-2B19 (Regional Jet Series 100 & 440)
2019-12-16		Airbus SAS	Model A350-941 airplanes
2019-12-17		Bombardier, Inc.	Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2019-13-02		The Boeing Company	Model 737-200, -200C, -300, -400, and -500 airplanes
<b>Biweekly 2019-16</b>			
2019-07-10		Northrop Grumman LITEF GmbH LCR-100	Attitude and Heading Reference System (AHRS) Note: This AD was included in Small AD Biweekly 2019-09, but was inadvertently left off the Large AD Biweekly.
2019-13-03		Trig Avionics Limited	Mode S transponders
2019-13-04		ATR-GIE Avions de Transport Régional	Model ATR72-101, -102, -201, -202, -211, -212, and -212A
2019-14-01		Rolls-Royce Deutschland Ltd & Co KG	TAY 650-15 and TAY 651-54 turbofan
2019-14-02		The Boeing Company	Model 737 series
2019-14-04		Airbus SAS	Model A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -216, -231, -232, -233, -251N, -252N, and -271N,

## LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; R – Replaces, A – Affects			
2019-14-05 2019-15-05		B/E Aerospace Fischer GmbH Rolls-Royce Deutschland Ltd & Co KG	A321-111, -112, -131, -211, -212, -213, -231, -232, -251N, - 251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, - 272N, and -272NX airplanes Common Seats Trent 1000-AE3, Trent 1000-CE3, Trent 1000-D3, Trent 1000-G3, Trent 1000-H3, Trent 1000-J3, Trent 1000-K3, Trent 1000-L3, Trent 1000-M3, Trent 1000-N3, Trent 1000- P3, Trent 1000-Q3 and Trent 1000-R3 engines
<b>Biweekly 2019-17</b>			
2019-14-06		Airbus SAS	A319-111, -112, -115, and -131 airplanes, and Airbus SAS Model A320-214 and -232 airplanes
2019-14-07		Airbus SAS	A320-251N and -271N airplanes; and Model A321-251N, - 253N, -271N, and -272N airplanes
2019-14-09		Airbus SAS	A330-223F and -243F
2019-14-10	R 2018-02-11	Airbus SAS	A330-223, -243, -301, -302, -321, -322, -323, -341, -342, and -343 airplanes; and Model A340-211, -212, -213, -311, -312, and -313 737-8 and 737-9
2019-14-12		The Boeing Company	Model 767-200, -300, -300F, and, -400ER series airplanes
2019-14-13		The Boeing Company	A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2019-14-15	R 2017-25-12	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2019-15-01		Bombardier, Inc.	Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes
2019-15-03		328 Support Services GmbH	Model 328-100 airplanes
2019-15-04		Bombardier, Inc.	Model BD-100-1A10 airplanes
2019-15-06	R 2018-22-07	Engine Alliance	GP7270, GP7272, and GP7277 model turbofan
2019-15-07		The Boeing Company	Model 737-100, 737-200, 737-200C, 737-300, 737-400, and 737-500 series
2019-15-08	R2002-07-05	Airbus SAS	Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4- 103, and B4-203, A300 B4-601, B4-603, B4-620, and B4- 622, A300 B4-605R and B4-622R, A300 C4-605R Variant F, A300 F4-605R
2019-15-09		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2019-15-10		Safran Aerosystems	life jackets
2019-16-01		International Aero Engines AG	V2525-D5 and V2528-D5 model turbofan engines
2019-16-02		GE Honda Aero Engines	HF120 model turbofan engines
2019-16-04	R 2019-03-04	Engine Alliance	GP7270 and GP7277 model turbofan engines



**2019-14-06 Airbus SAS:** Amendment 39-19684; Docket No. FAA-2019-0527; Product Identifier 2019-NM-112-AD.

**(a) Effective Date**

This AD becomes effective August 23, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Airbus SAS Model A319-111, -112, -115, and -131 airplanes, and Airbus SAS Model A320-214 and -232 airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) Emergency AD 2019-0151-E, dated June 28, 2019 (“EASA Emergency AD 2019-0151-E”).

**(d) Subject**

Air Transport Association (ATA) of America Code 32, Landing gear.

**(e) Reason**

This AD was prompted by a report of the fracture of a main landing gear (MLG) sliding tube axle, and an investigation that determined the cause to be an incorrect repair. The FAA is issuing this AD to address cracks and damage in the MLG sliding tube axle, which if not detected and corrected, could lead to MLG sliding tube axle fracture, possibly resulting in MLG collapse.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA Emergency AD 2019-0151-E.

**(h) Exceptions to EASA Emergency AD 2019-0151-E**

(1) For purposes of determining compliance with the requirements of this AD: Where EASA Emergency AD 2019-0151-E refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA Emergency AD 2019-0151-E does not apply to this AD.

(3) For purposes of determining compliance with the requirements of this AD: Where paragraph (2) of EASA Emergency AD 2019-0151-E refers to “28 June, 2019,” this AD requires using the effective date of this AD.

(4) Where paragraph (6) of EASA Emergency AD 2019-0151-E specifies to report the inspection results, this AD requires reporting the inspection results at the applicable time specified in paragraph (h)(4)(i) or (h)(4)(ii) of this AD. If operators have reported findings as part of obtaining any corrective actions approved by Airbus SAS's EASA Design Organization Approval (DOA), operators are not required to report those findings as specified in this paragraph.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

### **(i) Special Flight Permit**

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed except as specified in Note 1 of EASA Emergency AD 2019-0151-E.

### **(j) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA Emergency AD 2019-0151-E that contains RC procedures and tests: Except as required by paragraph (j)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) Paperwork Reduction Act Burden Statement: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

**(k) Related Information**

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) Emergency AD 2019-0151-E, dated June 28, 2019.

(ii) [Reserved]

(3) For EASA Emergency AD 2019-0151-E, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA Emergency AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA Emergency AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA Emergency AD 2019-0151-E may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0527.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 16, 2019.

Suzanne Masterson,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-14-07 Airbus SAS:** Amendment 39-19685; Docket No. FAA-2019-0251; Product Identifier 2019-NM-057-AD.

**(a) Effective Date**

This AD is effective September 12, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Airbus SAS Model A320-251N and -271N airplanes; and Model A321-251N, -253N, -271N, and -272N airplanes; certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019-0081, dated April 3, 2019 (“EASA AD 2019-0081”).

**(d) Subject**

Air Transport Association (ATA) of America Code 26, Fire protection.

**(e) Reason**

This AD was prompted by a report that during a calibration check, some torqueing tools used on the final assembly line have been found out of tolerance. The FAA is issuing this AD to address connections of sense and fire extinguishing lines within the pylon area that have been under-torqued, which could lead to leaks or disconnections of those lines and possibly result in reduced engine control and reduced safety margin in case of engine fire.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0081.

**(h) Exceptions to EASA AD 2019-0081**

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019-0081 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0081 does not apply to this AD.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019-0081 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(j) Related Information**

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0081, dated April 3, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0081, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0081 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0251.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 22, 2019.  
Dionne Palermo,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-14-09 Airbus SAS:** Amendment 39-19687; Docket No. FAA-2019-0255; Product Identifier 2019-NM-018-AD.

**(a) Effective Date**

This AD is effective September 9, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Airbus SAS Model A330-223F and -243F airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 35, Oxygen.

**(e) Reason**

This AD was prompted by reports of cracked flexible hoses of the oxygen crew and courier distribution system (OCCDS) on A330 freighter airplanes. The FAA is issuing this AD to address cracked oxygen hoses. This condition, if not addressed, could lead to oxygen leakage in the flexible hose of the OCCDS, which, in combination with in-flight depressurization, smoke in the flight deck, or a smoke evacuation procedure, could result in crew injury and reduced control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Aviation Safety Agency (EASA) AD 2019-0027, dated February 4, 2019 (“EASA AD 2019-0027”).

**(h) Exceptions to EASA AD 2019-0027**

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019-0027 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0027 does not apply to this AD.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019-0027 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(j) Related Information**

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2019-0027, dated February 4, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0027, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0027 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0255.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 18, 2019.

Suzanne Masterson,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-16701 Filed 8-2-19; 8:45 am]



**2019-14-10 Airbus SAS:** Amendment 39-19688; Docket No. FAA-2019-0574; Product Identifier 2018-NM-150-AD.

**(a) Effective Date**

This AD becomes effective August 23, 2019.

**(b) Affected ADs**

This AD replaces AD 2018-02-11, Amendment 39-19164 (83 FR 2894, January 22, 2018) (“AD 2018-02-11”).

**(c) Applicability**

This AD applies to Airbus SAS Model A330-223, -243, -301, -302, -321, -322, -323, -341, -342, and -343 airplanes; and Model A340-211, -212, -213, -311, -312, and -313 airplanes; certificated in any category; as identified in European Aviation Safety Agency (EASA) AD 2018-0226, dated October 22, 2018 (“EASA AD 2018-0226”).

**(d) Subject**

Air Transport Association (ATA) of America Code 55, Stabilizers.

**(e) Reason**

This AD was prompted by a report of cracking in the top skin of the horizontal stabilizer (HS) center box (CB) of an airplane in pre-modification 41330 configuration. This AD was also prompted by report of additional cracking found on different airplanes, and of an update to the fatigue and damage tolerance analysis. The FAA is issuing this AD to address cracking in the horizontal stabilizer center box, which could lead to reduced structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2018-0226.

**(h) Exceptions to EASA AD 2018-0226**

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2018-0226 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2018-0226 refers to a compliance time of after May 17, 2017, this AD requires using February 6, 2018 (the effective date of AD 2018-02-11).

(3) The “Remarks” section of EASA AD 2018-0226 does not apply to this AD.

(4) Paragraphs (5) and (6) of EASA AD 2018-0226 specify to report “no discrepancy” inspection results to Airbus at certain times. For this AD, report inspection results at the applicable time specified in paragraph (h)(4)(i) or (h)(4)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

#### **(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2018-0226 that contains RC procedures and tests: Except as required by paragraph (h)(4) and (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) Paperwork Reduction Act Burden Statement: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

#### **(j) Related Information**

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018-0226, dated October 22, 2018.

(ii) [Reserved]

(3) For EASA AD 2018-0226, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2018-0226 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0574.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 23, 2019.

Dionne Palermo,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-14-12 The Boeing Company:** Amendment 39-19690; Docket No. FAA-2019-0575; Product Identifier 2019-NM-113-AD.

**(a) Effective Date**

This AD is effective August 30, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 737-8 and 737-9 airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019.

**(d) Subject**

Air Transport Association (ATA) of America Code 27, Flight Controls.

**(e) Unsafe Condition**

This AD was prompted by a report that certain main slat track assemblies were manufactured incorrectly and are affected by hydrogen embrittlement. The FAA is issuing this AD to address main slat track assemblies that have reduced strength due to hydrogen embrittlement. This condition, if not addressed, could result in failure of main slat track assemblies, which could cause the slat to depart and potentially strike the airplane, resulting in injury to airplane occupants and/or preventing continued safe flight and landing.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737-27A1311, dated June 24, 2019, which is referred to in Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019.

## **(h) Exceptions to Service Information Specifications**

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019, uses the phrase “the original issue date of requirements bulletin 737-27A1311 RB,” this AD requires using “the effective date of this AD.”

(2) Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019, specifies to report inspection results to Boeing within a certain compliance time. For this AD, the compliance time to report inspection results is at the applicable time specified in paragraph (h)(2)(i) or (h)(2)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 3 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 3 days after the effective date of this AD.

(3) Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019, specifies to ship affected parts to Boeing within a certain compliance time if, during the inspection, it has been determined that any main slat track assembly has a suspect lot number or has a lot number that cannot be determined. For this AD, the compliance time for shipping affected parts to Boeing is at the applicable time specified in paragraph (h)(3)(i) or (h)(3)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Ship the affected part to Boeing within 30 days after removing the affected part.

(ii) If the inspection was done before the effective date of this AD: Ship the affected part to Boeing within 30 days after the effective date of this AD.

## **(i) Paperwork Reduction Act Burden Statement**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

## **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification

deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(k) Related Information**

For more information about this AD, contact Greg Rutar, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3529; email: Greg.Rutar@faa.gov.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-27A1311 RB, dated June 24, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 23, 2019.

Michael Kaszycki,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-14-13 The Boeing Company:** Amendment 39-19691; Docket No. FAA-2018-1011; Product Identifier 2018-NM-131-AD.

**(a) Effective Date**

This AD is effective September 12, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

(1) This AD applies to all The Boeing Company Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01920SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01920SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

**(d) Subject**

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

**(e) Unsafe Condition**

This AD was prompted by reports of uncommanded fore/aft movements of the Captain's and First Officer's seats. The FAA is issuing this AD to address uncommanded fore/aft movement of the Captain's and First Officer's seats. An uncommanded fore/aft seat movement during a critical part of a flight, such as take-off or landing, could cause a flight control obstruction or unintended flight control input, which could result in the loss of the ability to control the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Seat Identification and On-Condition Actions**

Within 36 months after the effective date of this AD, do an inspection to determine the part number, and serial number as applicable, of the Captain's and First Officer's seats, and do all applicable on-condition actions, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767-25-0539, Revision 1, dated July 17, 2018. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number and serial number of the Captain's and First Officer's seats can be conclusively determined from that review.

## **(h) Detailed Inspection and Repetitive Checks of Horizontal Movement System and On-Condition Actions**

Except as specified in paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 767-25-0549, Revision 1, dated August 10, 2018 ("BSASB 767-25-0549, Revision 1"), do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of BSASB 767-25-0549, Revision 1.

## **(i) Exceptions to Service Information Specifications**

For purposes of determining compliance with the requirements of this AD: Where BSASB 767-25-0549, Revision 1, uses the phrase "the original issue date of this service bulletin," this AD requires using "the effective date of this AD."

## **(j) Optional Terminating Action for Repetitive Checks**

(1) For Group 1, Configuration 2 and 4 airplanes identified in BSASB 767-25-0549, Revision 1: Installation of a serviceable Captain's seat, as specified in, and in accordance with, the Accomplishment Instructions of BSASB 767-25-0549, Revision 1, terminates the repetitive checks of the Captain's seat as required by paragraph (h) of this AD for that airplane only.

(2) For Group 1, Configuration 3 and 4 airplanes identified in BSASB 767-25-0549, Revision 1: Installation of a serviceable First Officer's seat, as specified in, and in accordance with, the Accomplishment Instructions of BSASB 767-25-0549, Revision 1, terminates the repetitive checks of the First Officer's seat as required by paragraph (h) of this AD for that airplane only.

## **(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided

the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(l) Related Information**

For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3569; email: Brandon.Lucero@faa.gov.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 767-25-0539, Revision 1, dated July 17, 2018.

(ii) Boeing Special Attention Service Bulletin 767-25-0549, Revision 1, dated August 10, 2018.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 23, 2019.

Dionne Palermo,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-14-14 Airbus SAS:** Amendment 39-19692; FAA-2019-0192; Product Identifier 2019-NM-004-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category, as identified in European Aviation Safety Agency (EASA) AD 2019-0006, dated January 17, 2019 (“EASA AD 2019-0006”).

(1) Airbus SAS Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes, Model A300 B4-605R and B4-622R airplanes, Model A300 F4-605R and F4-622R airplanes, and Model A300 C4-605R Variant F airplanes.

(2) Airbus SAS Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

**(d) Subject**

Air Transport Association (ATA) of America Code 55, Stabilizers.

**(e) Reason**

This AD was prompted by a determination that a certain aircraft maintenance manual task provided instructions for a visual inspection of composite and metallic vertical tailplane (VTP) attachment fittings, but the inspection method did not specify detection of delamination length, which could possibly extend beyond the defined allowable limits. The FAA is issuing this AD to address this condition, which, if not detected and corrected, could lead to failure of the VTP attachment fittings, possibly resulting in loss of control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0006.

**(h) Exceptions to EASA AD 2019-0006**

For purposes of determining compliance with the requirements of this AD, the following exceptions to EASA AD 2019-0006 apply.

(1) Where EASA AD 2019-006 refers to its effective date, this AD requires using the effective date of this AD.

(2) Replace the language in paragraph (2) of EASA AD 2019-0006 that states “it is determined that the maintenance records are incomplete,” with “maintenance records cannot be used to positively determine that the applicable maintenance actions have been accomplished.”

(3) Replace the language in paragraph (2) of EASA AD 2019-0006 that states “concurrently,” with “before further flight.”

(4) The “Remarks” section of EASA AD 2019-0006 does not apply to this AD.

(5) Where paragraph (3) of EASA AD 2019-0006 refers to “discrepancies” found in the inspection, this AD defines discrepancies as any damage or delamination found outside of specified allowable damage limits.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019-0006 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(j) Related Information**

For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2019-0006, dated January 17, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0006, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0006 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0192.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 23, 2019.

Michael Kaszycki,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-14-15 The Boeing Company:** Amendment 39-19693; Docket No. FAA-2019-0249; Product Identifier 2019-NM-010-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

This AD replaces 2017-25-12, Amendment 39-19126 (82 FR 59967, December 18, 2017) (“AD 2017-25-12”).

**(c) Applicability**

(1) This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by reports of cracking in the webs of the stub beams at certain fuselage stations (STAs), and cracking of the stub beam at fuselage STA 685 at the inboard end of the upper chord and the outboard end of the lower chord. The FAA is issuing this AD to address such cracking, which, if not corrected, could result in the loss of structural integrity of the airframe during flight, collapse of the main landing gear, and failure of the pressure deck.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions for Group 1 Airplanes**

For airplanes identified as Group 1 in Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018: Within 120 days after the effective date of this AD, inspect the stub beams and stub beam webs for any cracking or existing repairs, and do all applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

## **(h) Required Actions for Groups 2 Through 6 Airplanes**

Except as specified by paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018.

## **(i) Exceptions to Service Information Specifications**

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018, uses the phrase “the revision 1 issue date of this service bulletin,” this AD requires using “the effective date of this AD,” except where Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018, uses the phrase “the original issue date of this service bulletin” in a note or flag note.

(2) Where Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018, specifies contacting Boeing for repair instructions: This AD requires doing the repair before further flight using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

## **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified by paragraph (i) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(k) Related Information**

For more information about this AD, contact Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5234; fax: 562-627-5210; email: Peter.Jarzomb@faa.gov.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1364, Revision 1, dated October 25, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 26, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-17505 Filed 8-14-19; 8:45 am]



**2019-15-01 Bombardier, Inc.:** Amendment 39-19694; Docket No. FAA-2019-0186; Product Identifier 2018-NM-153-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 32, Main landing gear.

**(e) Reason**

This AD was prompted by a report that main landing gear (MLG) side stay actuators have been assembled using nonconforming split ball bearings. The FAA is issuing this AD to address the affected bearings, which could potentially result in asymmetric MLG gear extension or retraction, and subsequent gear collapse during landing.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspection To Verify the Serial Number**

For airplane serial numbers (S/Ns) 5301 through 5665 inclusive, 5701 through 5988 inclusive, and 6050 through 6091 inclusive, equipped with any MLG side stay actuator assembly containing split ball bearing part number (P/N) 104467672: For the left and right MLG side stay actuator assemblies having P/Ns 19011-103 and 19011-105, at the applicable time specified in figure 1 to paragraphs (g) and (h) of this AD, perform an inspection to verify the serial number, in accordance with paragraphs 2.A. and 2.B. of the Accomplishment Instructions of the applicable service information specified in figure 2 to paragraphs (g), (h), and (i) of this AD.

**Figure 1 to paragraphs (g) and (h) – Compliance times**

<b>Total Flight Cycles</b>	<b>Compliance Time</b>
As of the effective date of this AD: 3,350 total flight cycles or fewer on an MLG side stay actuator assembly	Before the MLG side stay actuator assembly reaches 3,750 total flight cycles or 48 months from the effective date of this AD, whichever occurs first.
As of the effective date of this AD: more than 3,350 total flight cycles on an MLG side stay actuator assembly	Within 400 flight cycles or 12 months from the effective date of this AD, whichever occurs first.

**Figure 2 to paragraphs (g), (h), and (i) – Service information**

<b>Model</b>	<b>Airplane S/N</b>	<b>Service Information</b>
CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes	5301 through 5665 inclusive	Bombardier Service Bulletin 604-32-029, Revision 02, dated May 10, 2018
	5701 through 5988 inclusive	Bombardier Service Bulletin 605-32-006, Revision 02, dated May 10, 2018
	6050 through 6091 inclusive	Bombardier Service Bulletin 650-32-002, Revision 02, dated May 10, 2018

**(h) Replacement**

If, during the inspection specified in paragraph (g) of this AD, the identified serial number of the MLG side stay actuator assembly is listed in table 1 or table 2 of paragraph 2.B. of the Accomplishment Instructions of the applicable service information specified in figure 2 to paragraphs (g), (h), and (i) of this AD: At the applicable time specified in figure 1 to paragraphs (g) and (h) of this AD, replace the split ball bearing having P/N 104467672, in accordance with paragraph 2.C. of the Accomplishment Instructions of the applicable service information specified in figure 2 to paragraphs (g), (h), and (i) of this AD. If the identified serial number of the MLG side stay actuator assembly is not listed in table 1 or table 2 of paragraph 2.B. of the Accomplishment Instructions of the applicable service information specified in figure 2 to paragraphs (g), (h), and (i) of this AD, no further action is required by this paragraph.

**(i) Parts Installation Limitation**

As of the effective date of this AD, no person may install, on any Bombardier, Inc., Model CL-600-2B16 (601-3A, 601-3R, and 604 Variants) airplanes, an MLG side stay actuator assembly with a serial number listed in table 1 or table 2 of paragraph 2.B. of the Accomplishment Instructions of the applicable service information specified in figure 2 to paragraphs (g), (h), and (i) of this AD, unless the split ball bearing having P/N 104467672 has been previously replaced as specified in paragraph (h) of this AD.

**(j) Credit for Previous Actions**

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the service information in paragraphs (j)(1) through (j)(3) of this AD.

- (1) Bombardier Service Bulletin 604-32-029, Revision 01, dated February 5, 2018.
- (2) Bombardier Service Bulletin 605-32-006, Revision 01, dated February 5, 2018.
- (3) Bombardier Service Bulletin 650-32-002, Revision 01, dated February 5, 2018.

**(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-26R1, dated May 22, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0186.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

- (i) Bombardier Service Bulletin 604-32-029, Revision 02, dated May 10, 2018.
- (ii) Bombardier Service Bulletin 605-32-006, Revision 02, dated May 10, 2018.
- (iii) Bombardier Service Bulletin 650-32-002, Revision 02, dated May 10, 2018.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 23, 2019.

Michael Kaszycki,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-15-03 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH):** Amendment 39-19696; Docket No. FAA-2019-0117; Product Identifier 2018-NM-169-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328-100 airplanes, certificated in any category, all serial numbers.

**(d) Subject**

Air Transport Association (ATA) of America Code 57, Wings.

**(e) Reason**

This AD was prompted by a report indicating that undetected cracks may develop at the roll spoiler bearing arms. The FAA is issuing this AD to address cracking at the roll spoiler bearing arms, which, if not detected and corrected, could lead to a roll spoiler becoming unresponsive to flight crew control inputs, possibly resulting in loss of control of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Definition of Affected Parts**

For the purposes of this AD, an affected part is the bearing arm of roll spoilers having part number (P/N) 001B577A1200000, 001B577A1200001, 001B577A1200002, 001B577A1200003, 001B577A1200004, or 001B577A1200005.

**(h) Inspection**

Within the compliance time specified in Figure 1 to paragraph (h) of this AD, as applicable, do a non-destructive test (NDT) inspection of each affected part, in accordance with the Accomplishment Instructions of 328 Support Services Alert Service Bulletin ASB-328-57-043, dated September 21,

2018. The flight cycles (FC) specified in Figure 1 to paragraph (h) of this AD are the FC accumulated on the airplane since first flight of the airplane, unless otherwise specified.

**Figure 1 to paragraph (h) – *Affected Parts Inspection***

<b>Total FC Accumulated</b>	<b>Compliance Time</b>
More than 25,000 FC	Within 2,500 flight hours (FH) after the effective date of this AD
25,000 FC or less	Before exceeding 25,000 total FC, or within 2,500 FH after the effective date of this AD, whichever occurs later

**(i) Corrective Action**

If any crack is found during any inspection required by paragraph (h) of this AD: Before further flight, obtain corrective actions approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or 328 Support Services GmbH's EASA Design Organization Approval (DOA); and accomplish the corrective actions within the compliance time specified therein. If approved by the DOA, the approval must include the DOA-authorized signature.

**(j) No Reporting Requirement**

Although 328 Support Services Alert Service Bulletin ASB-328-57-043, dated September 21, 2018, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (1)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or 328 Support Services GmbH's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0254R1, dated June 4, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0117.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3228.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) 328 Support Services Alert Service Bulletin ASB-328-57-043, dated September 21, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D-82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; email gsc.op@328support.de; internet <http://www.328support.de>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 26, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-17504 Filed 8-14-19; 8:45 am]



**2019-15-04 Bombardier, Inc.:** Amendment 39-19697; Docket No. FAA-2019-0578; Product Identifier 2019-NM-111-AD.

**(a) Effective Date**

This AD becomes effective August 23, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc., Model BD-100-1A10 airplanes, certificated in any category, serial numbers 20001 through 20337 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 27, Flight controls.

**(e) Reason**

This AD was prompted by a report of a mis-installed no-back pawl discovered on a horizontal stabilizer trim actuator (HSTA). The FAA is issuing this AD to address the possible unavailability of the no-back pawl which, in combination with loss of or degraded HSTA motor brake assembly (MBA) braking capability, could lead to a loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspection**

Within 100 flight hours or 60 days, whichever occurs first, after the effective date of this AD: Perform an inspection to verify the part number (P/N) of the horizontal stabilizer trim electronic control unit (HSTECU) installed on the airplane, in accordance with paragraph 2.B.(1) of the Accomplishment Instructions of Bombardier Service Bulletin 100-27-15, Revision 01, dated June 11, 2019. If the installed HSTECU has P/N C47329-007 or subsequent configurations, no further action is required by this paragraph.

**(h) Installation of HSTECUs With Upgraded Software**

(1) If, during the inspection specified in paragraph (g) of this AD, the installed HSTECU has P/N C47329-003: Within 100 flight hours or 60 days, whichever occurs first, after the effective date of

this AD, remove the HSTECU and install an upgraded HSTECU having P/N C47329-010, C47329-011 or C47329-012, in accordance with paragraphs 2.B.(2) through 2.B.(4) of the Accomplishment Instructions of Bombardier Service Bulletin 100-27-15, Revision 01, dated June 11, 2019.

(2) If, during the inspection specified in paragraph (g) of this AD, the installed HSTECU has P/N C47329-004, C47329-005 or C47329-006: Within 100 flight hours or 60 days, whichever occurs first, after the effective date of this AD, remove the HSTECU, upgrade the HSTECU software, and reinstall the upgraded HSTECU, in accordance with paragraphs 2.B.(2) through 2.B.(4) of the Accomplishment Instructions of Bombardier Service Bulletin 100-27-15, Revision 01, dated June 11, 2019.

**(i) Parts Installation Limitation**

As of the effective date of this AD, no person may install, on any airplane, an HSTECU having P/N C47329-003, C47329-004, C47329-005 or C47329-006.

**(j) No Reporting Requirement**

Although Bombardier Service Bulletin 100-27-15, Revision 01, dated June 11, 2019, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

**(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2019-23, dated June 18, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0578.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 100-27-15, Revision 01, dated June 11, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 23, 2019.

Dionne Palermo,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-15-06 Engine Alliance:** Amendment 39-19699; Docket No. FAA-2019-0459; Product Identifier 2018-NE-36-AD.

**(a) Effective Date**

This AD is effective August 30, 2019.

**(b) Affected ADs**

This AD replaces AD 2018-22-07, Amendment 39-19480 (83 FR 66609, December 27, 2018).

**(c) Applicability**

This AD applies to all Engine Alliance (EA) GP7270, GP7272, and GP7277 model turbofan engines.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

**(e) Unsafe Condition**

This AD was prompted by a shop finding of axial cracks in the interstage 5-6 seal teeth of the high-pressure compressor (HPC) stages 2-5 spool spacer arm due to an incorrectly installed stage 6 seal ring. The FAA is issuing this AD to prevent failure of the HPC interstage 5-6 seal teeth and uncontained HPC stages 2-5 spool release. The unsafe condition, if not addressed, could result in an uncontained release of the HPC stages 2-5 spool, damage to the engine, and damage to the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) For all HPC stages 2-5 spools, perform an initial borescope inspection (BSI) of the HPC stage 6 seal ring position:

(i) Borescope inspect the HPC stage 6 seal ring location in accordance with the Accomplishment Instructions, paragraph 1.F, of EA Alert Service Bulletin (ASB) EAGP7-A72-395, Revision No. 3, dated June 3, 2019, and within the compliance times specified in Table 1 to paragraph (g)(1) of this AD or within 230 engine cycles after the effective date of this AD, whichever occurs first. If the HPC stage 6 seal ring is installed incorrectly, remove the HPC stages 2-5 spool from service within 50 engine cycles and replace with a part eligible for installation, and correct the location of the stage 6 seal ring.

(ii) Borescope inspect the HPC interstage 5-6 seal tooth forward and aft face for cracks and missing coating in accordance with the Accomplishment Instructions, paragraphs 2.C and 2.E, of EA ASB EAGP7-A72-395, Revision No. 3, dated June 3, 2019, and within the compliance times specified in Table 1 to paragraph (g)(1) of this AD or within 230 engine cycles after the effective date of this AD, whichever occurs first.

(A) If the coating is missing on the HPC interstage 5-6 seal tooth forward or aft face, thereafter, repeat the BSI required by paragraph (g)(1)(ii) of this AD for cracks within every 150 engine cycles since you performed the last BSI.

(B) If cracks are found in the HPC interstage 5-6 seal tooth forward or aft face, remove the HPC stages 2-5 spool from service and replace with a part eligible for installation before further flight.

**Table 1 to Paragraph (g)(1)–Compliance Times**

<b>Cycles since new (CSN) on HPC stages 2-5 spool as of January 11, 2019 (the effective date of AD 2018-22-07)</b>	<b>Complete the inspection</b>
2,499 or less	Within 900 engine cycles after January 11, 2019, but not to exceed 2,850 CSN.
2,500 to 3,499	Within 350 engine cycles after January 11, 2019, but not to exceed 3,600 CSN.
3,500 or more	Within 100 engine cycles after January 11, 2019.

(2) For HPC stages 2-5 spools listed in Table 1 of Appendix A of EA SB EAGP7-72-413, dated February 4, 2019, perform the following repetitive on-wing inspections:

(i) Borescope inspect the HPC interstage 5-6 seal tooth forward and aft face for cracks and missing coating in accordance with the Accomplishment Instructions, paragraphs 1.E. and 1.G., of EA SB EAGP7-72-413, dated February 4, 2019, within 300 engine cycles after completion of the initial inspection required by paragraph (g)(1)(ii) of this AD. If the engine has already accumulated more than 200 engine cycles since the inspection required by paragraph (g)(1)(ii) of this AD, perform this BSI of the HPC interstage 5-6 seal tooth forward and aft face within the next 100 engine cycles after the effective date of this AD, but before exceeding 500 engine cycles since the last inspection required by paragraph (g)(1)(ii) of this AD.

(A) If the coating is found missing on the HPC interstage 5-6 seal tooth forward or aft face during the BSI, thereafter, repeat the BSI required by paragraph (g)(2)(i) of this AD for cracks within every 150 engine cycles since last BSI required by paragraph (g)(2)(i).

(B) If cracks are found in the HPC interstage 5-6 seal tooth forward or aft face during the BSI, remove the HPC stages 2-5 spool from service and replace with a part eligible for installation before further flight.

(ii) Thereafter, repeat the BSI required by paragraph (g)(2)(i) of this AD at intervals not exceeding 300 engine cycles since the last BSI.

**(h) Mandatory Terminating Action for HPC Stages 2-5 Spools Identified in Paragraph (g)(2) of This AD**

As a terminating action to the on-wing repetitive BSI required by paragraph (g)(2) of this AD, at the next engine shop visit after the effective date of this AD, perform the following inspections and, if necessary, replacement of any HPC stages 2-5 spools listed in Table 1 of Appendix A of EA SB EAGP7-72-413, dated February 4, 2019.

(1) Visually inspect for the location of the HPC stage 6 seal ring in accordance with the Accomplishment Instructions, paragraph 1, of EA SB EAGP7-72-398, dated February 4, 2019. If the

seal ring is found to be installed incorrectly, remove the HPC stages 2-5 spool and the HPC stage 6 seal ring from service and replace with parts eligible for installation.

(2) Perform an eddy current inspection (ECI) of the HPC interstage 5-6 seal teeth on the HPC stages 2-5 spool in accordance with Accomplishment Instructions, paragraph 2, of EA SB EAGP7-72-398, dated February 4, 2019. If there are ECI indications, as defined in paragraph 2 of EA SB EAGP7-72-398, remove the HPC stages 2-5 spool from service and replace with a part eligible for installation.

(3) Dimensionally inspect the diameter of the middle tooth of the HPC interstage 5-6 seal teeth on eight equally spaced points of the HPC stages 2-5 spool in accordance with the Accomplishment Instructions, paragraph 3, of EA SB EAGP7-72-398, dated February 4, 2019. If the average diameter is larger than the “expected diameter,” as defined in the Accomplishment Instructions, Figure 4 and Figure 5, of EA SB EAGP7-72-398, dated February 4, 2019, remove the HPC stages 2-5 spool from service and replace with a part eligible for installation.

### **(i) Definition**

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine case flanges, except for the following situations, which do not constitute an engine shop visit:

(1) Separation of engine flanges solely for the purposes of transportation of the engine without subsequent maintenance.

(2) Separation of engine flanges solely for the purpose of replacing the fan or propulsor without subsequent engine maintenance.

### **(j) No Reporting Requirement**

The reporting requirements in the Accomplishment Instructions, paragraphs 1 and 2 of EA SB EAGP7-72-398, dated February 4, 2019, are not required by this AD.

### **(k) Credit for Previous Actions**

You may take credit for any of the initial inspections required by paragraph (g)(1) of this AD if you performed the initial inspection before the effective date of this AD using EA ASB EAGP7-A72-395, Revision No. 2, dated August 2, 2018. The repetitive inspections required by paragraph (g)(1) of this AD are still required if the HPC stage 6 seal ring position is installed incorrectly or the HPC interstage 5-6 seal tooth forward or aft face is cracked or missing coating as determined by the initial BSI required by paragraph (g)(1).

### **(l) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (m) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved for AD 2018-22-07, Amendment 39-19480 (83 FR 66609, December 27, 2018) are approved as AMOCs for paragraph (g)(1) of this AD.

**(m) Related Information**

For more information about this AD, contact Matthew Smith, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7735; fax: 781-238-7199; email: Matthew.C.Smith@faa.gov.

**(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Engine Alliance (EA) Alert Service Bulletin EAGP7-A72-395, Revision No. 3, dated June 3, 2019.

(ii) EA Service Bulletin (SB) EAGP7-72-413, dated February 4, 2019.

(iii) EA SB EAGP7-72-398, dated February 4, 2019.

(3) For EA service information identified in this AD, contact Engine Alliance, 411 Silver Lane, East Hartford, CT 06118; phone: 800-565-0140; email: help24@pw.utc.com; website: [www.engineallianceportal.com](http://www.engineallianceportal.com).

(4) You may view this service information at FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 2, 2019.

Karen M. Grant,  
Acting Manager, Engine and Propeller Standards Branch,  
Aircraft Certification Service.



**2019-15-07 The Boeing Company:** Amendment 39-19700; Docket No. FAA-2019-0023; Product Identifier 2018-NM-145-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

(1) This AD applies to The Boeing Company Model 737-100, 737-200, 737-200C, 737-300, 737-400, and 737-500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1362, dated September 20, 2018 (“BASB 737-53A1362”).

(2) Installation of Supplemental Type Certificate (STC) ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by reports of cracks in the frames below the passenger floor. The FAA is issuing this AD to address cracks that could propagate until the frame severs. Continued operation of the airplane with multiple adjacent severed frames, or the combination of a severed frame adjacent to fuselage skin chem-mill cracks, could result in an uncontrolled decompression and loss of structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions for Group 1 Airplanes**

For airplanes identified as Group 1 in BASB 737-53A1362: Within 120 days after the effective date of this AD, accomplish actions to correct the unsafe condition (e.g., inspections and on-condition actions) using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

### **(h) Required Actions for Group 2 Through 20 Airplanes**

For airplanes identified as Group 2 through 20 in BASB 737-53A1362: Except as specified in paragraph (i) of this AD, at the applicable times specified in paragraph 1.E., “Compliance,” of BASB 737-53A1362, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of BASB 737-53A1362.

### **(i) Optional Terminating Action for Certain Repetitive Inspections**

For airplanes identified as Group 2 through 20 in BASB 737-53A1362, accomplishment of part 13, “Preventive Modification of the Frame Web Tooling Hole and Insulation Attachment Hole in the Section 46 Lower Lobe Frame,” in accordance with the Accomplishment Instructions of BASB 737-53A1362, terminates the repetitive open hole high frequency eddy current inspections required by paragraph (h) of this AD, for the modified tooling hole or insulation attachment hole location only.

### **(j) Exceptions to Service Information Specifications**

(1) For purposes of determining compliance with the requirements of this AD: Where BASB 737-53A1362 uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD,” except where BASB 737-53A1362 uses the phrase “the original issue date of this service bulletin” in a note or flag note.

(2) Where BASB 737-53A1362 specifies contacting Boeing for repair instructions or alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

### **(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (j)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided

the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(l) Related Information**

For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email: george.garrido@faa.gov.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737-53A1362, dated September 20, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 30, 2019.

Michael Kaszycki,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-15-08 Airbus SAS:** Amendment 39-19701; Docket No. FAA-2019-0319; Product Identifier 2019-NM-005-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

This AD replaces 2002-07-05, Amendment 39-12699 (67 FR 16983, April 9, 2002; corrected April 23, 2002 (67 FR 19810)) (“AD 2002-07-05”).

**(c) Applicability**

This AD applies to Airbus SAS Model airplanes specified in paragraphs (c)(1) through (c)(5) of this AD, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019-0011R1, dated February 22, 2019 (“EASA AD 2019-0011R1”).

- (1) Model A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes.
- (2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.
- (3) Model A300 B4-605R and B4-622R airplanes.
- (4) Model A300 C4-605R Variant F airplanes.
- (5) Model A300 F4-605R airplanes.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Reason**

This AD was prompted by reports of cracked frame (FR) 40 aft fittings at stringer 33 on the left and right sides of the fuselage, and a determination that the existing inspection compliance times were not sufficient to address the unsafe condition and needed to be reduced. We are issuing this AD to address propagation of cracks on the FR40 aft fittings due to local stress concentrations at the upper flange runout of FR40, which could result in reduced structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019-0011R1.

**(h) Exceptions to EASA AD 2019-0011R1**

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019-0011R1 refers to its effective date, or February 6, 2019 (the effective date of EASA AD 2019-0011, dated January 23, 2019), this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2019-0011R1 does not apply to this AD.

(3) Paragraphs (7) and (8) of EASA AD 2018-0011R1 specify to report inspection results to Airbus within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(3)(i) or (h)(3)(ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2002-07-05 are approved as AMOCs for the corresponding provisions of EASA AD 2019-0011R1 that are required by paragraph (g) of this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019-0011R1 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(4) Paperwork Reduction Act Burden Statement: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

**(j) Related Information**

For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0011R1, dated February 22, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0011R1, contact the EASA, at Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 30, 2019.

Michael Kaszycki,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-15-09 Bombardier, Inc.:** Amendment 39-19702; Docket No. FAA-2019-0120; Product Identifier 2018-NM-167-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc., Model DHC-8-400, -401, and -402 airplanes, certificated in any category, serial numbers (S/Ns) 4001 through 4547 inclusive, having outboard spoiler actuator mounting brackets with part numbers (P/Ns) 85714052-101 or 85714052-102.

**(d) Subject**

Air Transport Association (ATA) of America Code 57, Wings.

**(e) Reason**

This AD was prompted by a report of a cracked outboard spoiler actuator mounting bracket. The FAA is issuing this AD to address cracking of the outboard spoiler actuator mounting brackets, which could cause inoperability or jam of a single spoiler panel and possible jam of the aileron circuit. This condition, if not corrected, could adversely affect the continued safe operation and landing of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Repetitive Inspections**

At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD: Do a general visual inspection for cracks in the left and right outboard spoiler actuator mounting brackets having P/N 85714052-101 or 85714052-102 (belonging to assemblies having P/N 85714018-001 or P/N 85714018-002, respectively), in accordance with Section 3.B, Part A, of the Accomplishment Instructions of Bombardier Service Bulletin 84-27-72, Revision A, dated November 9, 2017. Repeat the inspection thereafter at intervals not to exceed 8,000 flight hours.

(1) For airplanes having less than 12,000 total flight hours as of the effective date of this AD: Prior to the accumulation of 18,000 total flight hours.

(2) For airplanes having 12,000 total flight hours or more as of the effective date of this AD: Within 6,000 flight hours after the effective date of this AD.

### **(h) Part Replacement**

(1) If, during any inspection required by paragraph (g) of this AD, either the left or right outboard spoiler actuator mounting bracket is found cracked: Before further flight, replace both the left and right brackets with new bracket assemblies having P/N 85714018-003 or P/N 85714018-004, including doing all applicable related investigative actions and corrective actions, in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 84-27-72, Revision A, dated November 9, 2017; except, where the service information specifies contacting Bombardier for corrective action, this AD requires accomplishing the action using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(2) If, during any inspection required by paragraph (g) of this AD, no cracking is found on the left and right outboard spoiler actuator mounting brackets, and the left and right outboard spoiler actuator mounting brackets have not already been replaced per the requirements of paragraph (h)(1) of this AD: Replace both the left and right brackets with new bracket assemblies having P/N 85714018-003 or P/N 85714018-004, including doing all applicable related investigative actions and corrective actions, at the applicable time specified in paragraph (h)(2)(i) or (h)(2)(ii) of this AD, in accordance with Section 3.B, Part B, of the Accomplishment Instructions of Bombardier Service Bulletin 84-27-72, Revision A, dated November 9, 2017; except, where the service information specifies contacting Bombardier for corrective action, this AD requires accomplishing the action using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature. Related investigative and corrective actions must be done before further flight.

(i) For airplanes that have accumulated less than 34,000 total flight hours as of the effective date of this AD: Replace the outboard spoiler actuator mounting brackets prior to the airplane accumulating 40,000 total flight hours.

(ii) For airplanes that have accumulated 34,000 total flight hours or more as of the effective date of this AD: Replace the outboard spoiler actuator mounting brackets within 6,000 flight hours after the effective date of this AD.

### **(i) Terminating Action for Repetitive Inspections**

Replacement of an outboard spoiler actuator mounting bracket, in accordance with the requirements of paragraph (h) of this AD, is terminating action for the repetitive inspections required by paragraph (g) of this AD for the replaced bracket.

### **(j) Credit for Previous Actions**

This paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84-27-72, dated January 19, 2017.

### **(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight

Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

### **(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-21R1, effective November 1, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0120.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516-287-7329; fax: 516-794-5531; email: Aziz.Ahmed@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

### **(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 84-27-72, Revision A, dated November 9, 2017.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on July 30, 2019.

Michael Kaszycki,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.



**2019-15-10 Safran Aerosystems (formerly Zodiac Aerospace Services):** Amendment 39-19703; Docket No. FAA-2019-0207; Product Identifier 2019-NE-02-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

(1) This AD applies to Safran Aerosystems life jackets with part number (P/N) 210225-2, P/N 216200-0, or P/N 216203-0, and with a serial number listed in Table 1 of Zodiac Aerospace Services Service Bulletin (SB) 25-65-33, Revision 02, dated March 15, 2019, that are not marked with “Mod.per SB 25-65-34” in the identification area.

(2) These appliances are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR 42 and ATR 72, Airbus A318/A319/A320/A321, Airbus A330, Airbus A340, Airbus A350, and Airbus A380 airplanes.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 2561, Life Jacket.

**(e) Unsafe Condition**

This AD was prompted by reports of defective welding on certain life jackets around the inflation system. The FAA is issuing this AD to prevent failure of the life jacket. The unsafe condition, if not addressed, could result in injury to the wearer of the life jacket.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Within six months after the effective date of this AD, remove each affected life jacket from the airplane and, before further flight, replace the life jacket with a life jacket eligible for installation.

**(h) Installation Prohibition**

After the effective date of this AD, do not install on any airplane an affected life jacket unless it has been repaired and marked to indicate compliance with such repair in accordance with Zodiac

Aerospace Services SB 25-65-34, Revision 01, dated March 15, 2019, or Original Issue, dated January 8, 2019; or a method approved by the FAA.

**(i) Definition**

A life jacket eligible for installation is a new life jacket not listed in Table 1 of Zodiac Aerospace Services SB 25-65-33, Revision 02, dated March 15, 2019, or a life jacket repaired in accordance with Zodiac Aerospace Services SB 25-65-34, Revision 01, dated March 15, 2019, or Original Issue, dated January 8, 2019; or by a method approved by the FAA.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Boston ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(k) Related Information**

(1) For more information about this AD, contact Erin King, Aerospace Engineer, Boston ACO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone 781-238-7655; fax: 781-238-7199; email: erin.king@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2019-0010, dated January 23, 2019, for more information. You may examine the EASA AD in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0207.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Zodiac Aerospace Services Service Bulletin (SB) 25-65-33, Revision 02, dated March 15, 2019.

(ii) Zodiac Aerospace Services SB 25-65-34, Revision 01, dated March 15, 2019.

(3) For Safran Aerosystems service information identified in this AD, contact Zodiac Aerospace Services, 61 Rue Pierre Curie, CS20001, 78370 Plaisir Cedex, France; phone: + 33 1 61 34 23 23; fax: + 33 1 61 34 21 13; email: Technical.Retrofit@zodiac aerospace.com; internet: <http://tpi.services.zodiac aerospace.com>.

(4) You may view this service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 2, 2019.  
Karen M. Grant,  
Acting Manager, Engine and Propeller Standards Branch,  
Aircraft Certification Service.



**2019-16-01 International Aero Engines AG:** Amendment 39-19704; Docket No. FAA-2019-0274; Product Identifier 2019-NE-07-AD.

**(a) Effective Date**

This AD is effective September 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all International Aero Engines AG (IAE) V2525-D5 and V2528-D5 model turbofan engines.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7250, Turbine section.

**(e) Unsafe Condition**

This AD was prompted by reports of a cracked turbine exhaust case (TEC). The FAA is issuing this AD to prevent failure of the TEC. The unsafe condition, if not addressed, could result in engine separation and loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) At the next engine shop visit, but not later than 4,000 flight cycles (FCs) after the effective date of this AD, perform an eddy current inspection (ECI) and high sensitivity fluorescent penetrant inspection (FPI) of the TEC front and rear mount stiffener rails for cracking indications as follows:

(i) Perform an ECI using the Accomplishment Instructions, Part I–For Engines Installed on Aircraft, paragraphs 2 through 19 inclusive, or Part II–For Engines Not Installed on Aircraft, paragraphs 2 through 18 inclusive, of IAE Non-Modification Service Bulletin (NMSB) V2500-ENG-72-0694, Revision No. 2, dated July 2, 2018 (“IAE NMSB V2500-ENG-72-0694”).

(ii) If a rejectable indication was found during the ECI, perform a local high sensitivity FPI to confirm a crack.

(iii) If a rejectable indication was found during the ECI, but no crack(s) were confirmed using the local high sensitivity FPI, then clean, blend and repeat the ECI in the local area of the part. Use the Accomplishment Instructions, Part I–For Engines Installed on Aircraft, paragraph 20.A.(3), or

Part II—For Engines Not Installed on Aircraft, paragraph 19.A.(3), of IAE NMSB V2500-ENG-72-0694 to perform the cleaning and blending. Use the Accomplishment Instructions, Part I—For Engines Installed on Aircraft, paragraphs 2 through 19 inclusive, or Part II—For Engines Not Installed on Aircraft, paragraphs 2 through 18 inclusive, of IAE NMSB V2500-ENG-72-0694 to perform the repeat ECI.

(iv) If a rejectable indication was again found during the repeat ECI, then repeat the local high sensitivity FPI inspection in the local area of the part. If the local high sensitivity FPI does not confirm a crack, follow the instructions in the Accomplishment Instructions, Part I—For Engines Installed on Aircraft, paragraph 20.A.(5)(a), or Part II—For Engines Not Installed on Aircraft, paragraph 19.A.(5)(a), of IAE NMSB V2500-ENG-72-0694.

(2) If no cracks were found, within 2,000 FCs since the last inspection, and thereafter, repeat the inspections of paragraphs (g)(1)(i) through (iv) of this AD.

(3) If a crack was confirmed during the FPI and visual inspection required by paragraphs (g)(1)(ii) or (iv), before further flight, remove the part from service and replace with a part eligible for installation.

#### **(h) Credit for Previous Actions**

You may take credit for the inspections required by paragraph (g)(1) of this AD if you performed these inspections before the effective date of this AD, using IAE NMSB V2500-ENG-72-0694, Revision No. 1, dated February 7, 2018; or IAE NMSB V2500-ENG-72-0694, Original Issue, dated January 5, 2018.

#### **(i) No Reporting Requirement**

No reporting requirement contained within the NMSB referenced in paragraph (g) of this AD is required by this AD.

#### **(j) Definition**

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine case flanges, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

#### **(k) Special Flight Permit**

A special flight permit is not permitted if the crack indication extends past the mount stiffener rail or if there is evidence of an FPI indication on the outer diameter of the case.

#### **(l) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (m) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(m) Related Information**

For more information about this AD, contact Martin Adler, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7157; fax: 781-238-7199; email: Martin.Adler@faa.gov.

**(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) International Aero Engines Non-Modification Service Bulletin V2500-ENG-72-0694, Revision No. 2, dated July 2, 2018.

(ii) [Reserved]

(3) For International Aero Engines service information identified in this AD, contact International Aero Engines AG, 400 Main Street, East Hartford, CT, 06118; phone: 800-565-0140; email: help24@pw.utc.com; internet: <http://fleetcare.pw.utc.com>.

(4) You may view this referenced service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 7, 2019.

Robert J. Ganley,  
Manager, Engine and Propeller Standards Branch,  
Aircraft Certification Service.



**2019-16-02 GE Honda Aero Engines:** Amendment 39-19705; Docket No. FAA-2019-0352; Product Identifier 2019-NE-09-AD.

**(a) Effective Date**

This AD is effective September 13, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to all GE Honda Aero Engines (GHAE) HF120 model turbofan engines with fuel pump metering unit (FPMU) assembly, part number (P/N) 24100-Q0A-F000, installed.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7321, Fuel Control/Turbine Engines.

**(e) Unsafe Condition**

This AD was prompted by damage found on the permanent magnetic alternator drive gear within the FPMU assembly. The FAA is issuing this AD to prevent failure of the FPMU assembly. The unsafe condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Within 20 engine hours after the effective date of this AD, or before accumulating 600 engine hours since new, whichever occurs later, remove the affected FPMU assembly from service and replace it with a part eligible for installation.

**(h) Installation Prohibition**

After the effective date of this AD, do not install on any engine an FPMU assembly, P/N 24100-Q0A-F000.

**(i) Definition**

For the purposes of this AD, a “part eligible for installation” is:

- (1) an FPMU assembly, P/N 24100-Q0A-G000 or P/N 24100-Q0A-F100; or
- (2) an FPMU assembly, P/N 24100-Q0A-F000, that is rebuilt and marked as P/N 24100-Q0A-G000 or P/N 24100-Q0A-F100.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(k) Related Information**

For more information about this AD, contact Michael Richardson-Bach, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7747; fax: 781-238-7199; email: michael.richardson-bach@faa.gov.

**(l) Material Incorporated by Reference**

None.

Issued in Burlington, Massachusetts, on August 6, 2019.

Robert J. Ganley,  
Manager, Engine & Propeller Standards Branch,  
Aircraft Certification Service.



**2019-16-04 Engine Alliance:** Amendment 39-19707; Docket No. FAA-2019-0465; Product Identifier 2018-NE-19-AD.

**(a) Effective Date**

This AD is effective August 30, 2019.

**(b) Affected ADs**

This AD replaces AD 2019-03-04, Amendment 39-19556 (84 FR 4694, February 19, 2019).

**(c) Applicability**

This AD applies to all Engine Alliance (EA) GP7270 and GP7277 model turbofan engines.

**(d) Subject**

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

**(e) Unsafe Condition**

This AD was prompted by an uncontained failure of the engine fan hub. The FAA is issuing this AD to detect defects, damage, and cracks that could result in an uncontained failure of the engine fan hub assembly. The unsafe condition, if not addressed, could result in uncontained failure of the engine fan hub assembly, damage to the engine, and damage to the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

(1) For EA GP7270 and GP7277 model turbofan engines, with engine fan hub assembly part numbers (P/Ns) 5760221 or 5760321, and with serial numbered engine fan hub assemblies identified in Planning Information, Table 4, in EA Alert Service Bulletin (ASB) EAGP7-A72-389, Revision No. 4, dated June 14, 2019, within 3,000 cycles since new, or before further flight after the effective date of this AD, whichever occurs later:

(i) For engine fan hub assemblies at the low-pressure compressor (LPC) module assembly level:

(A) Perform a visual inspection of the engine fan hub assembly, in accordance with the Accomplishment Instructions, For Fan Hubs at LPC Module Assembly Level, paragraphs 1.A.(1), 1.A.(4), and 1.A.(6)(a), of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(B) Perform an eddy current inspection (ECI) of the engine fan hub blade slot bottoms and front edges in accordance with the Accomplishment Instructions, For Fan Hubs at LPC Module Assembly Level, paragraphs 2.A and 2.B, of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(ii) For engine fan hub assemblies at the piece part level:

(A) Perform a visual inspection of the engine fan hub assembly, in accordance with the Accomplishment Instructions, For Fan Hubs at Piece Part Level, paragraphs 1.A.(1) and 1.A.(3), of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(B) Perform an ECI of the engine fan hub blade slot bottoms and front edges, in accordance with the Accomplishment Instructions, For Fan Hubs at Piece Part Level, paragraphs 2.A and 2.B, of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(iii) For engine fan hub assemblies installed in an engine (on-wing or off-wing):

(A) Perform a visual inspection of the engine fan hub assembly, in accordance with the Accomplishment Instructions, For Fan Hubs Installed in an Engine, paragraphs 1.C.(1), 1.C.(5), and 1.C.(7)(a), of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(B) Perform an ECI of the engine fan hub blade slot bottoms and front edges, in accordance with the Accomplishment Instructions, For Fan Hubs Installed in an Engine, paragraphs 1.D.(1) and 1.D.(2), of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(iv) If the engine fan hub assembly visual inspection reveals defects or damage to the engine fan hub assembly outside the serviceable limits specified in Table 6 in the Accomplishment Instructions of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019, before further flight, remove the engine fan hub assembly from service and replace with a part eligible for installation.

(v) If the engine fan hub assembly ECI results in a rejectable indication per the Appendix, Added Data, of EA ASB EAGP7-A72-389, Revision No. 4, dated June 14, 2019, remove the engine fan hub assembly from service and, before further flight, replace with a part that is eligible for installation.

(2) For all GP7270 and GP7277 model turbofan engines, after the effective date of this AD:

(i) At the next disassembly of the engine fan hub blade lock assembly, visually inspect the following areas for damage:

(A) The fan hub blade lock retention hooks (also known as lock ring contact area); and

(B) The fan hub rim face.

(ii) At the next reassembly of the fan hub blade lock assembly, visually inspect the following areas of the engine fan hub for damage:

(A) The fan hub scallop areas;

(B) The fan hub bore area behind the balance flange;

(C) The fan hub fan blade lock retention hooks;

(D) The fan hub rim face; and

(E) The clinch nut holes.

(iii) After any reassembly per paragraph (g)(2)(ii), before further flight, perform an independent inspection of all areas of the engine fan hub referenced in paragraph (g)(2)(ii) of this AD for damage.

(iv) Thereafter, repeat inspections as required by paragraph (g)(2)(i), (g)(2)(ii), and (g)(2)(iii) of this AD at each disassembly and reassembly of the engine fan hub blade lock assembly.

(v) As an optional terminating action to the inspection requirements and independent inspection requirements of paragraph (g)(2)(i), (g)(2)(ii), and (g)(2)(iii) of this AD, insert the requirements for the visual inspections and independent inspections required by these paragraphs as Required Inspection Items in the approved continuous airworthiness maintenance program for the airplane.

(vi) If damage is found outside serviceable limits as the result of the inspections required by (g)(2)(i), (g)(2)(ii), or (g)(2)(iii) of this AD, before further flight, remove the engine fan hub assembly from service and replace with a part eligible for installation.

(3) For GP7270 and GP7277 model turbofan engines with engine serial numbers P550101 through P550706, remove the engine fan hub blade lock assembly, P/N 5700451, by September 1, 2020, and replace with a part eligible for installation. Refer to EA ASB EAGP7-A72-418, Revision No. 1, dated January 11, 2019, for guidance on replacement of the engine fan hub blade lock assembly.

### **(h) Credit for Previous Actions**

You may take credit for the inspection required by paragraph (g)(1) of this AD if you performed the inspection before the effective date of this AD using EA ASB EAGP7-A72-389, Revision No. 3, dated October 18, 2018, or an earlier version.

### **(i) Definitions**

(1) For the purpose of this AD, a part eligible for installation for replacement of the engine fan hub blade lock assembly is:

(i) A part that is not P/N 5700451, or

(ii) An engine fan hub blade lock assembly that has been modified in accordance with EA ASB EAGP7-A72-418, Revision No. 1, dated January 11, 2019 or EA ASB EAGP7-A72-418, Revision No. 0, dated December 7, 2018.

(2) For the purpose of this AD, an independent inspection is a second inspection performed by an individual qualified to perform inspections who was not involved in the original inspection of the engine fan hub assembly following disassembly and reassembly of the engine fan hub blade lock assembly.

### **(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) AMOCs approved for AD 2018-11-16 (83 FR 27891, June 15, 2018) and AD 2019-03-04 (84 FR 4694, February 19, 2019) are approved as AMOCs for the corresponding provisions of this AD.

### **(k) Related Information**

For more information about this AD, contact Matthew Smith, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7735; fax: 781-238-7199; email: matthew.c.smith@faa.gov.

### **(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Engine Alliance (EA) Alert Service Bulletin EAGP7-A72-389, Revision No. 4, dated June 14, 2019.

(ii) [Reserved]

(3) For EA service information identified in this AD, contact Engine Alliance, 411 Silver Lane, East Hartford, CT 06118; phone: 800-565-0140; email: help24@pw.utc.com; website: www.engineallianceportal.com.

(4) You may view this service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on August 9, 2019.

Karen M. Grant,  
Acting Manager, Engine & Propeller Standards Branch,  
Aircraft Certification Service.