

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2014-22**

10/20/2014 - 11/2/2014



Federal Aviation Administration
Engineering Procedures Office, AIR-110
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2014-01

2013-25-04		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE., -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW
2013-25-06		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-01 2013-26-02		CFM International S.A. Bombardier, Inc.	CFM56-3 series and CFM56-7B series turbofan engines CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2013-26-03	S 2011-24-09	Airbus	A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, and A340-642
2013-26-04 2013-26-06	S 2010-19-01	The Boeing Company Rolls-Royce Corporation	747-400, -400D, and -400F series AE 3007A, A1, A1/1, A1/2, A1/3, A1P, A1E, and A3 turbofan engines
2013-26-07		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-08 2013-26-10		The Boeing Company Rolls-Royce plc	737-600, -700, -700C, -800, -900, and -900ER series RB211-524G2-19, RB211-524G3-19, RB211-524H-36, and RB211-524H2-19 turbofan engines
2013-26-12	S 2009-14-02	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series

Biweekly 2014-02

There were no AD's published in this Large Bi-weekly period

Biweekly 2014-03

2013-24-04	S 2003-19-11	Learjet Inc.	60
2013-25-03	S 2000-17-05 S 2001-04-09	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-01-04		Bae Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2014-01-05 2014-02-01	S 2011-03-13	The Boeing Company Bombardier, Inc.	737-100, -200, -200C, -300, -400, and -500 series CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)

Biweekly 2014-04

2014-03-07 2014-03-08	S 2009-26-16	The Boeing Company Airbus	MD-11 and MD-11F A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-03-09		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, -500, ATR72-101, -201, -102, -202, -211, -212, and -212A
2014-03-14		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2014-03-16		Rolls-Royce Deutschland Ltd & Co. KG	Tay 620-15, 650-15, and 651-54 turbofan engines
2014-03-17		Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, & CL-604 Variants)

Biweekly 2014-05

2014-01-03 2014-03-04 2014-03-05 2014-03-06		Saab AB, Saab Aerosystems Bombardier, Inc. Bombardier, Inc. Boeing	340A (SAAB/SF340A) and SAAB 340B DHC-8-400, -401, and -402 BD-700-1A10 737-100, -200, -200C, -300, -400, and -500 series
--	--	---	---

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-03-12	S 2002-23-19	Dassault Aviation	FALCON 2000
2014-03-13		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-03-15	S 2008-14-16	328 Support Services GmbH	328-100, 328-300
2014-03-19		Boeing	737-600, -700, -800, -900, and -900ER series
2014-03-21		Boeing	727-200 and 727-200F series
2014-04-05		Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-04-08		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2014-05-02	S 2002-10-11	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-03		Boeing	777-200, -200LR, -300, -300ER, and -777F series
2014-05-05		Boeing	777-200, -200LR, -300, -300ER, and 777F series
Biweekly 2014-06			
2014-05-09	S 2012-12-08	Boeing	777-200 and -300 series
2014-05-12	S 2010-15-08	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-13	S 2004-12-07	Boeing	757-200, -200PF, and -200CB series
2014-05-16		Boeing	747-200B, 747-300, 747-400, 747-400D, 747-400F, 767-200, -300, -300F, and -400ER series
2014-05-18		Bombardier	DHC-8-400, -401, and -402
2014-05-19		Boeing	747-200B, 747-200F, 747-300, 747SP, 747-400, 747-400F, 767-300 series
2014-05-20		Boeing	757-200, -200PF, -200CB, and -300 series
2014-05-21	S 2008-11-04	Boeing	737-100, -200, -200C, -300, -400, and -500 series
2014-05-22		Boeing	717-200
2014-05-23		Bombardier	BD-100-1A10 (Challenger 300)
2014-05-24	S 84-19-01	Boeing	747-100, 747-200B, and 747-200F series
2014-05-25		Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2014-05-30	S 2013-07-07	Boeing	737-600, -700, -700C, -800, -900, and -900ER series
2014-06-02		Boeing	747-400 series
Biweekly 2014-07			
2013-26-14	S 2008-08-04	Airbus	A318, A319, A320, A321
2014-04-09		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-04-10		Airbus	A330, A340 airplanes
2014-05-14		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-05-17		Bombardier	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2014-05-27		Rockwell Collins	Mode S transponders
2014-05-28		Bombardier	DHC-8-400, -401, and -402
2014-05-31	S 2008-08-25	Boeing	747-400F, 747-400 series
2014-05-32		Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2240, PW2337, PW2643, and F117-PW-100 turbofan engines
2014-06-04		Boeing	747-8 and 747-8F series
2014-06-05	S 2007-03-02	Rolls-Royce Deutschland	Tay 620-15, Tay 650-15 and Tay 651-54 turbofan engines
2014-06-08		Bombardier	DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315
2014-06-09	S 2009-18-18	ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, -500 ; ATR72-101, -201, -102, -202, -211, -212, and -212A
2014-06-10	S 2014-06-10	Airbus	A330, A340
2014-07-02		Rolls-Royce Deutschland	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2014-08			
2014-05-32	COR	Pratt & Whitney	PW2037, PW2037D, PW2037M, PW2040, PW2040D, PW2043, PW2143, PW2240, PW2337, PW2643, and F117-PW-100 turbofan engines
2014-07-03		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-07-05		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-08-02		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R
2014-08-03		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2014-08-05		Rolls-Royce Deutschland Ltd & Co KG	BR700-715A1-30, BR700-715B1-30, and BR700-715C1-30 turbofan engines
Biweekly 2014-09			
2013-25-02	S 2000-11-06	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-07-01		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2014-08-01	S 2014-03-08	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-08-04	S 2012-03-04	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-08-08		The Boeing Company	737-200, -200C, -300, -400, and -500 series
2014-08-09		The Boeing Company	767-200, -300, -300F, and -400ER series
2014-08-11	S 2009-24-07	The Boeing Company	737-600, -700, -700C, -800 and -900 series
2014-09-05		Airbus	A330-201, A330-202, A330-203, A330-223, A330-243, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313
2014-09-06		The Boeing Company	777F series
Biweekly 2014-10			
2014-09-08	S 2007-16-19	The Boeing Company	747-200B, 747-300, and 747-400 series
2014-09-10		The Boeing Company	767-200, -300, -300F, and -400ER series
Biweekly 2014-11			
2014-09-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2014-09-09		The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series
Biweekly 2014-12			
2008-21-07R1		Dowty Propellers	R408/6-123-F/17 propellers
2014-11-01		The Boeing Company	777-200 and -300 series
2014-11-04		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343 A340-211, -212, -213, -311, -312, -313, -541, and -642
2014-11-06		Lockheed	P-3A or P3A
2014-12-03		Rolls-Royce Deutschland	BR700-725A1-12 turbofan engines
2014-12-52	E	Honeywell International	TFE731-4, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, 40AR, -40R, -40BR, -50R, and -60 turbofan engines
Biweekly 2014-13			
2014-12-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-12-10		The Boeing Company	727-100 series
2014-13-03		Rolls-Royce plc	RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61 turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2014-14

2014-12-02		Dassault Aviation	FALCON 2000 and FALCON 2000EX
2014-12-13		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2014-12-52	S 2014-12-52	Honeywell International Inc.	TFE731-4, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, -40AR, -40R, -40BR, -50R, and -60 turbofan engines
2014-13-02		Rolls-Royce plc	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan engines
2014-14-01		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2014-14-02		Pratt & Whitney Canada Corp.	PW120, PW121, PW121A, PW124B, PW127, PW127E, PW127F, PW127G and PW127M turboprop engines

Biweekly 2014-15 (AD 2014-15-01 was originally left off this Biweekly, but was added Oct. 23, 2014, and also will be included in Large AD Biweekly 2014-22)

2014-11-03		The Boeing Company	777-200, -200LR, -300, and -300ER series airplanes
2014-11-10	S 2008-08-09	Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2014-13-06		Learjet Inc.	45 airplanes
2014-13-07		The Boeing Company	737-300, -400, and -500 series airplanes; 737-600, -700, -700C, -800, -900, and -900ER series airplanes
2014-13-10		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2014-13-11		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body series airplanes; 720 and 720B series airplanes
2014-13-14		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2014-13-15		EADS CASA	CN-235-300 airplanes
2014-13-16		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000) airplanes
2014-13-17		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2014-13-18		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2014-14-03	S 2014-07-01	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes
2014-14-05		Airbus	A320-211, -212, and -231 airplanes
2014-14-06		Airbus	A318-111 and -112; A319-111, -112, -113, -114, and -115; A320-111, -211, -212, and -214; A321-111, -112, -211, -212, and -213 airplanes
2014-15-01		M7 Aerospace LLC	SA227-AT, SA227-AC, SA227-BC, SA227-CC, SA227-DC airplanes
2014-15-03		Pratt & Whitney Canada Corporation	PW150A turboprop engines

Biweekly 2014-16

2014-13-12		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-13-13		Fokker Services B.V.	F.28 Mark 0070 and 0100
2014-14-04	S 2003-18-10	The Boeing Company	767-200, -300, -300F, and -400ER series
2014-15-04		Saab AB, Saab Aerosystems	SAAB 2000
2014-15-05		Airbus	A310-304, -322, -324, and -325
2014-15-06		The Boeing Company	747-100B SUD, 747-200B, 747-300, 747-400, and 747-400D series
2014-15-07		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2014-15-08		Beechcraft Corporation	Hawker 800XP, 850XP, and 900XP
2014-15-09		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and -642

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-15-10 2014-15-11		Dassault Aviation Bombardier, Inc.	FALCON 7X CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2014-15-12 2014-15-14		The Boeing Company The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2014-15-15 2014-15-16		Beechcraft Corporation Airbus	MU-300, 400, 400A, 400T (T-1A), and 400T (TX) A319-111, -112, -115, -132, -133, A320-214, -232, -233, A321-211, -231, and -232
2014-15-17		Bombardier, Inc.	CL-600-2B16 (CL-604 Variant)
Biweekly 2014-17			
2013-13-13		Airbus	A310-203, -204, -221, -222, 304, -322, -324, -325, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F
2014-15-13	R 2005-15-04	Bombardier, Inc.	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), and CL-600-2B16 (CL-604 Variant)
2014-15-20 2014-15-21 2014-16-02	S 2006-26-06	Bombardier, Inc. The Boeing Company Bombardier, Inc.	DHC-8-400, -401, and -402 777-200 and -300 series CL-600-1A11 (CL-600)
2014-16-04 2014-16-06 2014-16-07 2014-16-08	R 2008-14-17 R 2011-15-09	Airbus Bombardier, Inc. Bombardier, Inc. Bombardier, Inc.	A330-201, -202, -203, -223, -243, A340-311, -312, and -313 CL-600-2B16 (CL-604 Variant) DHC-8-400, -401, and -402 CL-215-6B11 (CL-215T Variant) and CL-215-6B11 (CL-415 Variant)
2014-16-09		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body, 707-300, -300B, -300C, and -400 series, 720 and 720B series, 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series, 737-100, -200, and -200C series
2014-16-10 2014-16-11 2014-16-14 2014-16-16	S 2013-12-01	Rolls-Royce plc The Boeing Company The Boeing Company Embraer S.A.	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines 777-200 series 737-600, -700, -700C, -800, and -900 series ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, -200 STD, -200 LR, and -200 IGW
2014-16-19	See AD	Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2014-16-20		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203
2014-16-22		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, A340-541 and -642
2014-17-51	E	Bombardier, Inc.	CL-600-2B16
Biweekly 2014-18			
2014-16-05		Embraer S.A.	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 170-200 LR, -200 SU, and -200 STD
2014-16-12 2014-16-13		Dassault Aviation Airbus	FALCON 2000EX A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203
2014-16-18		BAE Systems (Operations) Limited	BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2014-16-21 2014-16-23 2014-16-25	R 2011-16-01 R 2007-06-12	Dassault Aviation Dassault Aviation Airbus	FALCON 7X FALCON 7X A330-201, -202, -203, -223, -243, A330-301, -321, -322, -323, -341, -342, and -343
2014-16-26 2014-16-27 2014-16-28		Dassault Aviation Dassault Aviation Empresa Brasileira de Aeronautica S.A.	FALCON 900EX FALCON 900EX EMB-135BJ
2014-17-02	R 2013-18-09	Honeywell ASCa Inc	See AD

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-17-04		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2014-17-05		The Boeing Company	767-400ER series
2014-17-06	R 2011-17-08	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2014-17-07		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2014-17-10		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-18-02	R 2014-05-02	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
Biweekly 2014-19			
2013-15-06		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2013-25-07	R 2007-18-09	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2013-26-05		Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, G, MYSTERE-FALCON 200, MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2014-15-19	R 2013-03-23	Gulfstream Aerospace LP	G150
2014-19-02		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2014-20			
2014-18-01		Rockwell Collins, Inc.	Appliance: See AD
2014-19-03		The Boeing Company	747-8 and 747-8F series
2014-19-04	R 2004-03-19	Airbus	A320-111, -211, -212, and -231
2014-20-01		Bombardier, Inc.	CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants)
2014-20-02		The Boeing Company	767-200, -300, -300F, and -400ER series
2014-20-03		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11
2014-20-04	R 94-12-03	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-20-06		The Boeing Company	737-600, -700, -700C, -800, -900, -900ER series, 777-200, 777-200LR, 777-300, 777-300ER, and 777F series
2014-20-07	R 2010-03-05	The Boeing Company	747-200C and -200F series
2014-20-08		Lockheed Martin Corporation	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2014-20-09		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2014-21			
2014-20-10	R 2013-11-14	The Boeing Company	777-200 and -300 series airplanes
2014-20-11	R 2011-07-05	Zodiac Seats France	9140, 9166, 9173, 9174, 9184, 9188, 9196, 91B7, 91B8, 91C0, 91C2, 91C4, 91C5, 91C9, 9301, and 9501 series passenger seat assemblies
Biweekly 2014-22			
(AD 2014-15-01 should have been included in Large AD Biweekly 2014-15. We have corrected the online version, but have also included it here for the print subscribers.)			
2012-26-15 R1	R 2012-26-15	Honeywell International Inc.	Appliance: See AD
2014-15-01		M7 Aerospace LLC	SA227-AT, SA227-AC, SA227-BC, SA227-CC, and SA227-DC
2014-17-51		Bombardier, Inc.	CL-600-2B16
2014-21-01	S 90-26-01, S 91-20-02, S 2009-05-02	General Electric Company	CF6-80C2 and CF6-80E1 series turbofan engines
2014-21-04		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88
2014-21-05		The Boeing Company	DC-10-10, DC-10-10F, DC-10-30, DC-10-30F (KC-10A)

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2014-21-06 2014-21-07		Beechcraft Corporation Bombardier, Inc.	and KDC-10), DC-10-40, MD-10-10F, and MD-10-30F 400 Beechjet, 400A Beechjet, 400T Beechjet, and MU-300 CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL- 600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000)
2014-21-08 2014-21-09	R 2005-14-07	Bombardier, Inc. The Boeing Company	BD-700-1A11 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series
2014-21-10		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, - 322, -323, -341, -342, -343, A340-211, -212, -213, -311, - 312, and -313
2014-22-02		Rolls-Royce plc	Trent 1000-A, 1000-C, 1000-D, 1000-E, 1000-G, and 1000- H turbofan engines



2012-26-15 R1 Honeywell International Inc.: Amendment 39-17990; Docket No. FAA-2014-0285; Directorate Identifier 2014-NM-035-AD.

(a) Effective Date

This AD becomes effective December 3, 2014.

(b) Affected ADs

This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).

(c) Applicability

This action applies to air data pressure transducers, as installed in air data computers (ADC), air data modules (ADM), air data attitude heading reference systems (ADAHRS), and digital air data computers (DADC) having the part numbers and serial numbers identified in Honeywell Alert Service Bulletin ADM/ADC/ADAHRS-34-A01, dated November 6, 2012. This appliance is installed on, but not limited to, the aircraft specified in paragraphs (c)(1) through (c)(16) of this AD.

- (1) Airbus Model A318-111, -112, -121, and -122 airplanes.
- (2) Airbus Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes.
- (3) Airbus Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes.
- (4) Airbus Model A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.
- (5) Airbus Model A330-223F, -243F, -201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.
- (6) Airbus Model A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes.
- (7) AGUSTA S.p.A. Model AW139 helicopters.
- (8) Bell Helicopter Textron Canada Limited Model 429 helicopters.
- (9) The Boeing Company Model 767-200, -300, -300F, and -400ER series airplanes; and Model 777-200, -200LR, -300, -300ER, and 777F series airplanes.
- (10) Cessna Aircraft Company Model 560XL (560 Excel and 560 XLS) airplanes.
- (11) Dassault Aviation Model MYSTERE-FALCON 900 airplanes and Model FALCON 2000 airplanes.
- (12) Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ airplanes.
- (13) Gulfstream Aerospace Corporation Model GIV-X and GV-SP airplanes.
- (14) Learjet Inc. Model 45 airplanes.
- (15) PILATUS AIRCRAFT LTD. Model PC-12/47E airplanes.
- (16) Viking Air Limited (Type Certificate previously held by Bombardier Inc.; de Havilland, Inc.) Model (Twin Otter) DHC-6-400 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

Issued in Renton, Washington, on September 23, 2014.
Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-15-01 M7 Aerospace LLC: Amendment 39-17903; Docket No. FAA-2014-0308; Directorate Identifier 2014-CE-012-AD.

(a) Effective Date

This AD is effective August 27, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the M7 Aerospace LLC airplanes listed in paragraphs (c)(1) through (c)(5) of this AD that are equipped with a bayonet shear pin main cabin door latching mechanism and are certificated in any category. Airplanes equipped with a "click-clack" main cabin door latching mechanism are not affected by this AD. Figure 3 of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, and M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, is a picture showing both styles of latching mechanisms.

- (1) Model SA227-AT airplanes, serial numbers (S/Ns) AT570 through AT631, and AT695.
- (2) Model SA227-AC airplanes, S/Ns AC570 through AC788.
- (3) Model SA227-BC airplanes, S/Ns BC762, BC764, BC766, and BC770 through BC789.
- (4) Model SA227-CC airplanes, S/N CC827, CC829, and CC840 through CC844.
- (5) Model SA227-DC airplanes, S/Ns DC784, DC790 through DC826, DC828, DC830 through DC839, and DC845 through DC904.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America—Code 5310, Fuselage Main, Structure.

(e) Unsafe Condition

This AD was prompted by fatigue cracks found in the internal door surround doubler, the external skin fuselage skin, and the door corner fittings at the fuselage upper forward corner of the main cabin door cutout. We are issuing the AD to prevent decompression failure with possible loss of structural integrity of the cabin structure.

(f) Compliance

Comply with this AD within the compliance times specified in paragraph (g) through paragraph (k) of this AD, including all subparagraphs, unless already done.

(g) Inspections

(1) Do the initial inspections of the fuselage upper forward corner and other 3 corners of the main cabin door cutout for cracks following Table 1 in Step 2. ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005 or M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, as applicable. Do the inspections at the compliance times specified in paragraphs (g)(1)(i) through (g)(1)(iv) of this AD. For the purposes of this AD, owner/operators who do not track total aircraft flight cycles (TAC), use a .5 to 1 conversion, e.g., 35,000 TAC is equivalent to 17,500 hours time-in-service (TIS). For owner/operators who do not track flight cycles, use a 1 to 1 conversion, e.g., 300 flight cycles are equivalent to 300 hours TIS.

(i) For aircraft with more than 35,000 TAC, inspect within the next 300 flight cycles after August 27, 2014 (the effective date of this AD).

(ii) For aircraft with 20,001–35,000 TAC, inspect within the next 600 flight cycles after August 27, 2014 (the effective date of this AD).

(iii) For aircraft with 12,000–20,000 TAC, inspect within the next 1,000 flight cycles after August 27, 2014 (the effective date of this AD).

(iv) For aircraft with less than 12,000 TAC, inspect at 12,000 flight cycles or within the next 1,000 flight cycles after August 27, 2014 (the effective date of this AD), whichever occurs later.

(2) If no cracks are found during the inspections required by paragraph (g)(1) of this AD, repetitively thereafter at intervals not to exceed 2,000 flight cycles do the inspections of the fuselage upper forward corner and other 3 corners of the main cabin door cutout for cracks following Table 1 in Step 2. ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005 or M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, as applicable.

(h) Repair Cracks and Repetitively Inspect

(1) If any cracks are found during any inspection required in paragraph (g) through paragraph (i) of this AD, before further flight after the inspection in which a crack is found, repair or replace the cracked structure following Step 3. REPAIR OF CRACKED INNER DOUBLE, Step 4. REPAIR OF CRACKED FUSELAGE SKIN, and/or Step 5. REPAIR OF CRACKED CORNER FITTING of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, or M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, as applicable.

(2) If you made the repairs required in paragraph (h)(1) of this AD by installing repair kit drawing 27K24191-001, do the threshold and repeat inspections following Table 2 in Step 2. ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, dated November 15, 2013; or M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, dated November 15, 2013, as applicable.

(3) If you made the repairs required in paragraph (h)(1) of this AD by replacing the fuselage skin by installing repair kit drawing 27K24191-003, or if the corner fitting was replaced and no other cracks are present, repetitively thereafter inspect following Table 1 in Step 2. ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, or M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, as applicable.

(i) Extend Repetitive Inspection Intervals

After any inspection required in paragraph (g)(1) and (g)(2) of this AD and if no damage, defects, or cracks are found, you may install repair kit drawing 27K24191-001 following Step 6. ADDITION OF KIT DRAWING REPAIR MEMBERS AS PREVENTATIVE ACTION of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, or M7 Aerospace

LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, as applicable, to extend the inspection intervals. After installing repair kit drawing 27K24191-001, do the threshold and repeat inspections following Table 3 of Step 2. ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, or M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, both dated November 15, 2013, as applicable.

(j) Reporting Requirement

Within 30 days after any inspection required by paragraph (g) through paragraph (i) of this AD where a crack or any other damage is found, report the results of that inspection to M7 Aerospace LLC following the instructions specified in Step 2.I. of the ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, dated November 15, 2013; or Step 2.J. of the ACCOMPLISHMENT INSTRUCTIONS of M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, dated November 15, 2013, as applicable.

(k) Credit for Previous Repairs

As of August 27, 2014 (the effective date of this AD), owner/operators who had the an inspection and any resulting repairs done before the effective date of this AD using procedures different from those specified in M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, dated November 15, 2013; and M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, dated November 15, 2013, may apply for an alternative method of compliance (AMOC) following the instructions in paragraph (m) of this AD.

(l) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Fort Worth Airplane Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(n) Related Information

For more information about this AD, contact Andrew McAnaul, Aerospace Engineer, FAA, ASW-150 (c/o San Antonio MIDO), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; phone: (210) 308-3365; fax: (210) 308-3370; email: andrew.mcanaul@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) M7 Aerospace LLC SA227 Series Commuter Category Service Bulletin CC7-53-005, dated November 15, 2013.

(ii) M7 Aerospace LLC SA227 Series Service Bulletin 227-53-009, dated November 15, 2013.

(3) For M7 Aerospace LLC service information identified in this AD, contact M7 Aerospace LLC, 10823 NE Entrance Road, San Antonio, Texas 78216; phone: (210) 824-9421; fax: (210) 804-7766; Internet: <http://www.m7aerospace.com>; email: MetroTech@M7Aerospace.com.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on July 14, 2014.

Kelly A. Broadway,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.



2014-17-51 Bombardier, Inc.: Amendment 39-17999; Docket No. FAA-2014-0581; Directorate Identifier 2014-NM-167-AD.

(a) Effective Date

This AD is effective November 12, 2014 to all persons except those persons to whom it was made immediately effective by Emergency AD 2014-17-51, issued on August 19, 2014, which contained the requirements of this amendment.

(b) Affected ADs

The requirements of this AD terminate the requirements of AD 2014-03-17, Amendment 39-17754 (79 FR 9389, February 19, 2014), only for the airplanes identified in paragraph (c) of this AD.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B16 airplanes, certificated in any category, serial numbers 5301 through 5665 inclusive, and 5701 through 5920 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of fractured fastener heads on the inboard flap hinge-box forward fitting at Wing Station (WS) 76.50 due to incorrect installation. We are issuing this AD to detect and correct incorrectly oriented or fractured fasteners, which could result in premature failure of the fasteners attaching the inboard flap hinge-box forward fitting. Failure of the fasteners could lead to the detachment of the flap hinge box and the flap surface, and consequent loss of control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection: Airplanes Not Previously Inspected

For airplanes on which the actions required by AD 2014-03-17, Amendment 39-17754 (79 FR 9389, February 19, 2014), have not been done as of the effective date of this AD: Within 10 flight cycles after the effective date of this AD, or within 100 flight cycles after March 6, 2014 (the effective date of AD 2014-03-17, Amendment 39-17754 (79 FR 9389, February 19, 2014)), whichever occurs first: Do a detailed visual inspection of each inboard flap fastener of the hinge-box forward fitting at WS 76.50 and WS 127.25, on both wings, to determine if the fasteners are correctly oriented and intact (non-fractured, with intact fastener head). Do the inspection in accordance with

the Accomplishment Instructions of Bombardier Alert Service Bulletin A604-57-006, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5301 through 5665 inclusive); or Bombardier Alert Service Bulletin A605-57-004, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5701 through 5920 inclusive).

(1) If all fasteners are found intact and correctly oriented, no further action is required by this AD.

(2) If any fastener is found fractured: Before further flight, remove and replace all forward and aft fasteners at WS 76.50 and WS 127.25, regardless of condition or orientation, on both wings, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A604-57-006, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5301 through 5665 inclusive); or Bombardier Alert Service Bulletin A605-57-004, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5701 through 5920 inclusive). After replacement of all fasteners as required by paragraph (g)(2) of this AD, no further action is required by this AD.

(3) If any incorrectly oriented but intact fastener is found, and no fractured fastener is found, repeat the inspection required by paragraph (g) of this AD thereafter at intervals not to exceed 10 flight cycles, until the requirements of paragraph (i)(1) of this AD have been done.

(h) Airplanes Previously Inspected, With Incorrectly Oriented Fastener(s)

For airplanes on which an inspection required by paragraph (g) or (j) of AD 2014-03-17, Amendment 39-17754 (79 FR 9389, February 19, 2014), has been done as of the effective date of this AD, and on which any incorrectly oriented fastener, but no fractured fastener, was found: Except as provided by paragraph (i)(3) of this AD, do a detailed visual inspection of all inboard flap fasteners of the hinge-box forward fitting at WS 76.50 and WS 127.25, on both wings, to determine if the fasteners are intact (non-fractured, with intact fastener head). Inspect within 10 flight cycles after the effective date of this AD, or within 100 flight cycles after the most recent inspection done as required by AD 2014-03-17, whichever occurs first. Inspect in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A604-57-006, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5301 through 5665 inclusive); or Bombardier Alert Service Bulletin A605-57-004, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5701 through 5920 inclusive).

(1) If all fasteners are found intact, repeat the inspection thereafter at intervals not to exceed 10 flight cycles, until the requirements of paragraph (i)(1) of this AD have been done.

(2) If any fastener is found fractured: Before further flight, remove and replace all forward and aft fasteners at WS 76.50 and WS 127.25, regardless of condition or orientation, on both wings, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A604-57-006, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5301 through 5665 inclusive); or Bombardier Alert Service Bulletin A605-57-004, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5701 through 5920 inclusive). After replacement of all fasteners as required by paragraph (h)(2) of this AD, no further action is required by this AD.

(i) Terminating Action

(1) Replacement of all forward and aft fasteners at WS 76.50 and WS 127.25, on both wings, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A604-57-006, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5301 through 5665 inclusive); or Bombardier Alert Service Bulletin A605-57-004, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013, or Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013 (for serial numbers 5701 through 5920 inclusive); terminates the requirements of this AD.

(2) Accomplishment of the applicable requirements of this AD constitutes terminating action for the requirements of AD 2014-03-17, Amendment 39-17754 (79 FR 9389, February 19, 2014), for that airplane only.

(3) Replacement, before the effective date of this AD, of all fractured and incorrectly oriented fasteners, as provided by paragraph (i) or (k) of AD 2014-03-17, Amendment 39-17754 (79 FR 9389, February 19, 2014), is acceptable for compliance with the requirements of this AD.

(j) Special Flight Permit

Special flight permits to operate the airplane to a location where the airplane can be repaired in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) are not allowed.

(k) Other FAA Provisions

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office, ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York Aircraft Certification Office, ANE-170, FAA; or the TCCA; or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Emergency Airworthiness Directive CF-2014-27, dated August 15, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0581.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on November 12, 2014.

(i) Bombardier Alert Service Bulletin A604-57-006, Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013.

(ii) Bombardier Alert Service Bulletin A605-57-004, Revision 02, dated January 22, 2014, including Appendices 1 and 2, dated September 26, 2013.

(4) The following service information was approved for IBR on March 6, 2014 (79 FR 9389, February 19, 2014).

(i) Bombardier Alert Service Bulletin A604-57-006, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013.

(ii) Bombardier Alert Service Bulletin A605-57-004, Revision 01, dated September 26, 2013, including Appendices 1 and 2, dated September 26, 2013.

(5) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-01 General Electric Company: Amendment 39-17993; Docket No. FAA-2007-28413; Directorate Identifier 2007-NE-25-AD.

(a) Effective Date

This AD is effective November 28, 2014.

(b) Affected ADs

This AD supersedes AD 90-26-01, Amendment 39-6810 (55 FR 49611, November 30, 1990); AD 91-20-02, Amendment 39-8036 (56 FR 55231, October 25, 1991); and AD 2009-05-02, Amendment 39-15826, (74 FR 8161, February 24, 2009).

(c) Applicability

This AD applies to all General Electric Company (GE) CF6-80C2 and CF6-80E1 series turbofan engines with fuel manifold, part number (P/N) 1303M31G04, 1303M32G04, 1303M31G06, 1303M32G06, 1303M31G07, 1303M32G07, 1303M31G08, 1303M32G08, 1303M31G12, 1303M32G12, 2420M70G01, or 2420M71G01, installed.

(d) Unsafe Condition

This AD was prompted by a report of an under-cowl fire caused by a fuel manifold high-pressure fuel leak, and several additional reports of fuel leaks. We are issuing this AD to prevent failure of the fuel manifold, which could lead to uncontrolled engine fire, engine damage, and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Fuel Manifold Removal.

(i) After the effective date of this AD, do not return to service any CF6-80C2 or CF6-80E1 series engine with fuel manifold P/N 1303M31G04, 1303M32G04, 1303M31G06, 1303M32G06, 1303M31G07, 1303M32G07, 1303M31G08, or 1303M32G08, installed.

(ii) At the next engine shop visit after the effective date of this AD, remove from service fuel manifold P/Ns 1303M31G12, 1303M32G12, 2420M70G01, and 2420M71G01.

(2) Fuel Manifold, Loop Clamp, and Tube (Block) Clamp Initial and Repetitive Inspection and Replacement.

(i) For CF6-80C2 and CF680E1 series engines, with fuel manifold, P/N 1303M31G12, 1303M32G12, 2420M70G01, or 2420M71G01 installed, inspect the fuel manifold and replace if required by inspection results, and replace the loop clamps as follows:

(A) For CF6-80C2 series engines, use paragraphs 3.A, 3.C, and 3.D of GE CF6-80C2 Service Bulletin (SB) No. S/B 73-0326 R04, Revision 4, dated December 23, 2009, to do the inspection and replacements.

(B) For CF6-80E1 series engines, use paragraphs 3.A, 3.B, and 3.C of GE CF6-80E1 SB No. S/B 73-0061 R04, Revision 4, dated December 23, 2009, to do the inspection and replacements.

(C) Compliance time for fuel manifold inspection and loop clamp replacement:

(1) If the engine is a first-run engine, inspect the fuel manifold and replace the loop clamps within 7,500 flight hours (FH) time-since-new (TSN).

(2) If the engine's fuel manifold was ever inspected and new loop clamps were previously installed, inspect the fuel manifold and replace the loop clamps within 7,500 FH time-since-last-inspection (TSLI).

(3) If the engine's fuel manifold was not inspected, new loop clamps were not installed, or it is unknown when the loop clamps were installed, inspect the fuel manifold and replace the loop clamps within 1,750 FH time-since-last-shop-visit or within 4 months after the effective date of this AD, whichever occurs later.

(ii) For CF6-80C2 and CF6-80E1 series engines, with fuel manifold, P/N 1303M31G12, 1303M32G12, 2420M70G01, or 2420M71G01, with tube (block) clamp, P/N 1153M26G15, installed, inspect fuel manifold and tube (block) clamps, and replace if required by inspection results, as follows:

(A) For CF6-80C2 series engines, use paragraphs 3.A.(1) through 3.A.(8) and 3.C.(1) through 3.C.(2) of GE CF6-80C2 SB No. S/B 73-0414, Revision 1, dated May 29, 2014, to do the inspection.

(B) For CF6-80E1 series engines, use paragraphs 3.A.(1) through 3.A.(6) and 3.C.(1) through 3.C.(2) of GE CF6-80E1 SB No. S/B 73-0121, Revision 1, dated May 29, 2014, to do the inspection.

(C) Compliance time for fuel manifold and tube (block) clamp inspection:

(1) If the engine is a first-run engine, inspect the fuel manifold and tube (block) clamps within 7,500 FH TSN or within 3 months after the effective date of this AD, whichever occurs later.

(2) If the engine was previously inspected using either of GE CF6-80C2 SB No. S/B 73-0414, Revision 1, dated May 29, 2014, or GE CF6-80E1 SB No. S/B 73-0121, Revision 1, dated May 29, 2014, or earlier versions, then inspect the fuel manifold and tube (block) clamps within 7,500 FH TSLI or within 3 months after the effective date of this AD, whichever occurs later.

(3) If the engine is not a first-run engine and was not previously inspected using GE CF6-80C2 SB No. S/B 73-0414, Revision 1, dated May 29, 2014, or GE CF6-80E1 SB No. S/B 73-0121, Revision 1, dated May 29, 2014, or earlier versions, then inspect the fuel manifold and tube (block) clamps within 7,500 FH TSN or within 3 months after the effective date of this AD, whichever occurs later.

(iii) Thereafter, inspect fuel manifold, P/Ns 1303M31G12, 1303M32G12, 2420M70G01, and 2420M71G01, and tube (block) clamps, replace if required by inspection results, and replace the loop clamps within every 7,500 FH TSLI, using paragraphs (e)(2)(i)(A), (e)(2)(i)(B), (e)(2)(ii)(A), and (e)(2)(ii)(B) of this AD, as applicable.

(f) Definition

(1) For the purposes of this AD, an engine shop visit is the induction of an engine into the shop where the separation of a major engine flange occurs, except that induction into the shop for any of the reasons in paragraphs (f)(i) through (f)(iv) of this AD is not an engine shop visit:

(i) Induction of an engine into a shop solely for removal of the compressor top or bottom case for airfoil maintenance, or for variable stator vane bushing replacement;

(ii) Induction of an engine into a shop solely for replacement of the turbine rear frame;

(iii) Induction of an engine into a shop solely for replacement of the accessory gearbox or transfer gearbox, or both; or

(iv) Induction of an engine into a shop solely for core vibration trim balance procedure that requires separation of a major engine flange.

(2) For the purposes of this AD, a first-run engine is an engine that has not had a shop visit since entering service.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(2) Previously approved AMOCs for AD 2009-05-02 (74 FR 8161, February 24, 2009) remain approved for the corresponding requirements of paragraphs (e)(1) and (e)(2) of this AD.

(h) Related Information

(1) For more information about this AD, contact Kasra Sharifi, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. 01803; phone (781) 238-7773; fax: (781) 238-7199; email: kasra.sharifi@faa.gov.

(2) For additional details of the under cowl fire that prompted this AD, refer to National Transportation Safety Board (NTSB) safety recommendation (SR) A-13-028. The NTSB SR is available on the Internet at <http://www.nts.gov/doclib/recletters/2013/A-13-028.pdf>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) General Electric Company (GE) CF6-80C2 Service Bulletin (SB) No. 73-0326 R04, Revision 4, dated December 23, 2009.

(ii) GE CF6-80C2 SB No. S/B 73-0414, Revision 1, dated May 29, 2014.

(iii) GE CF6-80E1 SB No. 73-0061 R04, Revision 4, dated December 23, 2009.

(iv) GE CF6-80E1 SB No. S/B 73-0121, Revision 1, dated May 29, 2014.

(3) For GE service information identified in this AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: geae.aoc@ge.com.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call (781) 238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on October 7, 2014.

Kim Smith,
Acting Directorate Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2014-21-04 The Boeing Company: Amendment 39-17996 ; Docket No. FAA-2014-0451;
Directorate Identifier 2013-NM-122-AD.

(a) Effective Date

This AD is effective December 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all the Boeing Company Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 airplanes; certificated in any category.

(d) Subject

Air Transport Association (ATA) Code 55, Stabilizers.

(e) Unsafe Condition

This AD was prompted by reports of cracks emanating from the aft-most barrel nut holes of the left and right upper rear spar caps of the horizontal stabilizer. We are issuing this AD to detect and correct cracks in the horizontal stabilizer, which could propagate until an upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

At the applicable compliance time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013; except as provided by paragraph (i) of this AD: Do a high frequency eddy current inspection (ETHF) for cracks in the areas around the two aft-most barrel nut holes of the left and right upper rear spar caps, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013. Thereafter, repeat the ETHF inspection at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013; except as provided by paragraph (i) of this AD. If any cracking is found during any inspection, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013.

(h) Post-Repair/Replacement Actions

For airplanes on which a splice repair or replacement was done, as specified in Boeing Alert Service Bulletin MD80-55A070: At the applicable compliance time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013, do a ETHF inspection for cracks at the two aft-most barrel nut holes of any repaired or replaced upper rear spar cap, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013. Thereafter, repeat the ETHF inspection at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013. If any cracking is found during any inspection, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013.

(i) Exception to the Service Information Specifications

Where Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin MD80-55A070, dated May 22, 2013, which is not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5357; fax: 562-627-5210; email: george.garrido@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD80-55A070, Revision 1, dated December 17, 2013.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-05 The Boeing Company: Amendment 39-17997 ; Docket No. FAA-2014-0423;
Directorate Identifier 2013-NM-233-AD.

(a) Effective Date

This AD is effective December 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model DC-10-10, DC-10-10F, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, MD-10-10F, and MD-10-30F airplanes, certificated in any category, as identified in Boeing Service Bulletin DC10-53-182, dated June 28, 2013.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the forward cargo compartment frames are subject to widespread fatigue damage (WFD). We are issuing this AD to prevent fatigue cracking of the forward cargo compartment frames, which could result in loss of the fail-safe structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Prior to the accumulation of 30,000 total flight cycles, or within 72 months after the effective date of this AD, whichever occurs later: Do a high frequency eddy current inspection for cracking of the attachment holes at the forward cargo compartment frames and the cargo liner, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-182, dated June 28, 2013. If any crack is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(h) Installation of New Fasteners

If no cracking is found during the inspection required by paragraph (g) of this AD: Before further flight, install new oversized fasteners to attach the forward cargo liner to the forward cargo

compartment frame, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC10-53-182, dated June 28, 2013.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Nenita Odesa, Aerospace Engineer, Airframe Branch, ANM 120L, Los Angeles Aircraft Certification Office (ACO), FAA, 3960 Paramount Boulevard, Lakewood, CA 90712 4137; phone: 562-627-5234; fax: 562-627-5210; email: nenita.odesa@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin DC10-53-182, dated June 28, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA 98057-3356. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-06 Beechcraft Corporation (Type Certificate Previously Held by Hawker Beechcraft Corporation; Raytheon Aircraft Company; Beech Aircraft Corporation): Amendment 39-17998; Docket No. FAA-2014-0345; Directorate Identifier 2013-NM-230-AD.

(a) Effective Date

This AD is effective November 28, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Beechcraft Corporation (Type Certificate Previously Held by Hawker Beechcraft Corporation; Raytheon Aircraft Company; Beech Aircraft Corporation) airplanes identified in paragraphs (c)(1)(i), (c)(1)(ii), and (c)(1)(iii) of this AD.

(i) Model 400 Beechjet airplanes having serial numbers RJ-1 through RJ-65, inclusive.

(ii) Model 400A Beechjet airplanes having serial numbers RK-1 through RK-604, inclusive.

(iii) Model 400T Beechjet airplanes having serial numbers TT-1 through TT-180, inclusive; and TX-1 through TX-13, inclusive.

(2) Beechcraft Corporation (Type Certificate Previously Held by Hawker Beechcraft Corporation; Raytheon Aircraft Company; Mitsubishi Heavy Industries, Inc. Ltd.) Model MU-300 airplanes, having serial numbers A003SA through A093SA, inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by a report of a failure of the Acme nut threads in a pitch trim actuator (PTA). We are issuing this AD to prevent failure of the Acme nut threads in the PTA, which could lead to loss of control of pitch trim and reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Determination of Serial Number and Part Number

Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, inspect to determine the serial number and part number of the PTA, in accordance with the

Accomplishment Instructions of Hawker Beechcraft Service Bulletin SB 27-4100, dated March 2012. A review of manufacturer delivery and operator maintenance records is acceptable in lieu of the inspection, if the serial number and part number of the PTA can be conclusively determined from that review.

(h) Replacement

If any serial number and part number found during any inspection required by paragraph (g) of this AD is one listed in Table 1 or Table 2 of Hawker Beechcraft Service Bulletin SB 27-4100, dated March 2012: Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, replace the PTA with a serviceable PTA or an overhauled PTA having an Acme nut and jackscrew replaced with a new Acme nut and jackscrew, in accordance with the Accomplishment Instructions of Hawker Beechcraft Service Bulletin SB 27-4100, dated March 2012.

(i) Repetitive Replacements

Within 1,800 flight hours after the effective date of this AD, or at the next PTA overhaul, whichever occurs first, replace the PTA with a new PTA or an overhauled PTA having the Acme nut and jackscrew replaced with a new Acme nut and jackscrew, in accordance with sections 3.A.(2), (3), and (5) through (10) of Hawker Beechcraft Service Bulletin SB 27-4100, dated March 2012. Repeat the replacement thereafter at intervals not to exceed 1,800 flight hours, or at every PTA overhaul, whichever occurs first.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Ann Johnson, Aerospace Engineer, Systems and Propulsion Branch, ACE-116W, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, KS 67209; phone: 316-946-4105; fax: 316-946-4107; email: Ann.Johnson@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Hawker Beechcraft Service Bulletin SB 27-4100, dated March 2012.

(ii) Reserved.

(3) For service information identified in this AD, contact Beechcraft Corporation, TMDC, P.O. Box 85, Wichita, KS 67201-0085; telephone 316-676-8238; fax 316-671-2540; email tmdc@beechcraft.com; Internet <http://pubs.beechcraft.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-07 Bombardier, Inc.: Amendment 39-18000. Docket No. FAA-2014-0287; Directorate Identifier 2013-NM-247-AD.

(a) Effective Date

This AD becomes effective December 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Bombardier, Inc. airplanes specified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Model CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes, serial numbers 10303 through 10333 inclusive.

(2) Model CL-600-2D24 (Regional Jet Series 900) airplanes, serial numbers 15257 through 15284 inclusive.

(3) Model CL-600-2E25 (Regional Jet Series 1000) airplanes, serial numbers 19011 through 19024 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by a report that certain parts of the aft baggage door did not conform to the design specifications and were of degraded strength. We are issuing this AD to prevent cracking and deformations of stop fittings and striker plates, which could result in the opening of the aft baggage bay door and rapid decompression or reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections of the Aft Baggage Bay Door Stop Fittings and Striker Plates

Within 600 flight hours or 6 months after the effective date of this AD, whichever occurs first: Do a detailed visual inspection for cracking and deformations of the stop fittings and striker plates of the aft baggage bay door, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-52-037, Revision B, dated September 16, 2013. Repeat the inspection thereafter at intervals not to exceed 2,000 flight hours or 12 months, whichever occurs first, until the terminating action specified in paragraph (h) of this AD has been accomplished. If a crack or

deformation is found on a stop fitting or striker plate, before further flight, replace the affected fittings and striker plates, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-52-037, Revision B, dated September 16, 2013.

(h) Terminating Action—Replacement of the Aft Baggage Bay Door Stop Fittings and Striker Plates

Within 6,000 flight hours or 36 months, whichever occurs first, after the effective date of this AD: Replace the affected stop fittings and striker plates, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA-52-037, Revision B, dated September 16, 2013. Replacement of the affected stop fittings and striker plates of the aft baggage bay door constitutes terminating action for the repetitive inspections required by paragraph (g) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2013-37, dated November 28, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0287-0002>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 670BA-52-037, Revision B, dated September 16, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-08 Bombardier, Inc.: Amendment 39-18002. Docket No. FAA-2013-0548; Directorate Identifier 2013-NM-008-AD.

(a) Effective Date

This AD becomes effective December 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model BD-700-1A11 airplanes, certificated in any category, modified by FAA Supplemental Type Certificate (STC) ST02140NY, issued October 14, 2005

(http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/6B8CF26D01F5E6DE862570C7006DCD7E?OpenDocument&Highlight=st02140ny); and to airplanes, certificated in any category, modified by FAA STC ST02033NY, issued December 2, 2004

(http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/99FF781E0BD20AD886256FA300558250?OpenDocument&Highlight=02033).

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by a report that certain lanyards for the passenger oxygen masks are longer than the specified length, possibly leading to inactive oxygen masks in an emergency. We are issuing this AD to detect and correct lanyards of incorrect length, which might not activate the flow of oxygen in an emergency, resulting in injury to passengers.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 750 flight hours or 15 months after the effective date of this AD, whichever occurs first: Replace lanyards having part numbers (P/N) B431564-503 and -505 for all passenger oxygen dispensing units, with lanyards having P/N B431564-507, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 700-1A11-35-009, Revision 02, dated May 28, 2013.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2012-31R1, dated September 17, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0548-0004>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 700-1A11-35-009, Revision 02, dated May 28, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-09 The Boeing Company: Amendment 39-18003; Docket No. FAA-2014-0431; Directorate Identifier 2013-NM-041-AD.

(a) Effective Date

This AD is effective December 3, 2014.

(b) Affected ADs

This AD replaces AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005).

(c) Applicability

This AD applies to Boeing Model 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes, certificated in any category, as listed in Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of broken carriage attach fittings of the inboard and outboard foreflaps found during an inspection and an additional report of broken inboard and outboard carriage attach fittings of the outboard foreflaps found during an inspection. We are issuing this AD to detect and correct fatigue cracking of the attach fittings of the foreflap carriage of the wings, which could result in partial or complete loss of the foreflap and consequent loss of controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspections

This paragraph restates the requirements of paragraph (f) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with revised service information and a new compliance time. Except as provided by paragraph (l) of this AD: Within 1,000 flight cycles after August 15, 2005 (the effective date of AD 2005-14-07) or within 6 months after the effective date of this AD, whichever occurs first, and thereafter at intervals not to exceed 1,000 flight cycles, except as required by paragraph (m) of this AD (for outboard foreflaps), inspect as specified in paragraphs (g)(1) and (g)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or Revision 4, dated September 26, 2012. As of the effective date of this AD, use only Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated

September 26, 2012. Accomplishing the actions of paragraph (m) or (o) of this AD terminates the inspections required by this paragraph for outboard foreflaps only.

(1) A detailed inspection to detect cracks and surface deviations on all edges, surfaces, and lug attachment fastener holes on the two carriage attach fittings on the inboard and outboard foreflaps of each wing.

(2) A high frequency eddy current (HFEC) inspection to detect cracks at the lug attachment fastener holes on the two carriage attach fittings on the inboard and outboard foreflaps of each wing.

(h) Retained Replacement

This paragraph restates the requirements of paragraph (g) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with revised service information. If any crack is detected or if any surface deviation beyond the limits specified in Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or Revision 4, dated September 26, 2012; is detected during any inspection required by paragraph (g) or (m) of this AD, before further flight, replace the carriage attach fitting with a new, improved fitting or a new fitting having the same part number as the existing fitting, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or Revision 4, dated September 26, 2012. As of the effective date of this AD, use only Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012.

(i) Retained Measurement and Associated Corrective Action(s)

(1) This paragraph restates the requirements of paragraph (h) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with revised service information. Within 3,500 flight cycles after August 15, 2005 (the effective date of AD 2005-14-07), inspect for interference between the carriage attach fitting and the carriage lug fitting, and do other related investigative actions by accomplishing all the actions specified in paragraph 3.C. and Figure 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or paragraph 3.B.3 and Figure 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012. Do the actions in accordance with Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or Revision 4, dated September 26, 2012. As of the effective date of this AD, use only Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012.

(2) Paragraphs (i)(2)(i) and (i)(2)(ii) of this AD restate the requirements of paragraph (i) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with revised service information.

(i) If any discrepancy is found during any action required by paragraph (i)(1) of this AD, before further flight, accomplish applicable corrective action(s) (e.g., adding a shim or reworking the carriage attachment lug assembly), in accordance with paragraph 3.C. and Figure 2 or 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or paragraph 3.B.3. and Figure 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012; except as required by paragraph (i)(2)(ii) of this AD. As of the effective date of this AD, use only Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012.

(ii) Where Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; or Revision 4, dated September 26, 2012; specify to contact the manufacturer if rework of the improved fitting is required: Before further flight, rework in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), or Los Angeles ACO, FAA; or in accordance with data meeting the type certification basis of the airplane approved by an Authorized Representative (AR) for the Boeing Delegation Option Authorization (DOA) Organization who has been authorized by the FAA to make such findings; or using a method approved in accordance with the procedures specified in paragraph (s) of this AD. For a repair method to be approved, the repair

must meet the certification basis of the airplane, and the approval must specifically reference this AD. As of the effective date of this AD, any new repair approval must be done using a method approved in accordance with the procedures specified in paragraph (s) of this AD.

(j) Retained Concurrent Requirements

(1) This paragraph restates the requirements of paragraph (j) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with new paragraph reference. For Model 727 airplanes listed in Boeing 727 Service Bulletin 57-59, Revision 1, dated September 27, 1965: Before or at the same time with the requirements of paragraph (i) or (o) of this AD, install guide blocks and bushings in the midflap ribs in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-59, Revision 1, dated September 27, 1965.

(2) This paragraph restates the requirements of paragraph (k) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with new paragraph reference. For Model 727 airplanes listed in Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972: Before or at the same time with the requirements of paragraph (i) or (o) of this AD, do the actions specified in paragraphs (j)(2)(i) and (j)(2)(ii) of this AD, as applicable.

(i) For Groups I and II airplanes identified in Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972: Do a one-time inspection of the airload support roller for travel on the foreflap track, in accordance with Part I of the Accomplishment Instructions of Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972.

(A) If the airload support roller travels within the limits specified in Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972, modify the control drum of the inboard flap and inboard jackscrews of the outboard flap, in accordance with Part II of the Accomplishment Instructions of Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972.

(B) If the airload support roller travels beyond the limits specified in Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972, repair in accordance with a method approved by the Manager, Seattle ACO, or Los Angeles ACO, FAA; or in accordance with data meeting the type certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the FAA to make such findings; or using a method approved in accordance with the procedures specified in paragraph (s) of this AD. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically reference this AD. As of the effective date of this AD, any new repair approval must be done using a method approved in accordance with the procedures specified in paragraph (s) of this AD.

(ii) For Group III airplanes identified in Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972: Modify the inboard jackscrews of the outboard flap (i.e., replacing the down stop at the inboard jackscrews of the outboard flap) in accordance with Part II of the Accomplishment Instructions of Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972.

(3) This paragraph restates the requirements of paragraph (l) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with new paragraph reference. For Model 727 airplanes listed in Boeing 727 Service Bulletin 57-72, dated September 21, 1966: Before or at the same time with the requirements of paragraph (i) or (o) of this AD, do the actions specified in paragraphs (j)(3)(i) through (j)(3)(iv) of this AD.

(i) Chamfer the upper and lower flanges at the aft end of the foreflap tracks in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-72, dated September 21, 1966.

(ii) Do a standard magnetic particle inspection of the entire foreflap tracks for cracks in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-72, dated September 21, 1966. If any crack is detected, before further flight, repair in accordance with a method approved by the Manager, Seattle ACO, or Los Angeles ACO, FAA; or in accordance with data meeting the type certification basis of the airplane approved by an AR for the Boeing DOA Organization who has been authorized by the FAA to make such findings; or using a method approved in accordance with the procedures specified in paragraph (s) of this AD. For a repair

method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically reference this AD. As of the effective date of this AD, any new repair approval must be done using a method approved in accordance with the procedures specified in paragraph (s) of this AD.

(iii) Do a general visual inspection of the track rib faces at the front and rear spars to verify if the opening in the spars is flush with or clear of the plane of the rib faces, in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-72, dated September 21, 1966. If the opening is not flush or clear with the plane, before further flight, rework the spar opening in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-72, dated September 21, 1966.

(iv) Do a general visual inspection of the head or shank of bolts by securing the foreflap links to the foreflap tracks to verify if they protrude beyond the edge of the track flange in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-72, dated September 21, 1966. If the head or shank of the bolts protrude beyond the edge of the track flange, before further flight, rework in accordance with the Accomplishment Instructions of Boeing 727 Service Bulletin 57-72, dated September 21, 1966.

(v) For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to enhance visual access to all exposed surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(4) This paragraph restates the requirements of paragraph (m) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with a new paragraph identifier. For airplanes other than those identified in the service information specified in paragraphs (j)(1) through (j)(3) of this AD: Before or at the same time with the requirements of paragraph (i) or (o) of this AD, do an inspection to verify if any of the parts listed in the "Spares Affected" paragraph of each service information referenced in paragraphs (j)(1) through (j)(3) of this AD are installed on the airplane. If any part identified in that paragraph is found installed, before further flight, do the applicable corrective and investigative action(s) specified in paragraphs (j)(1) through (j)(3) of this AD.

(k) Retained Optional Terminating Actions

This paragraph restates the requirements of paragraph (n) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with no changes. Replacement of the two carriage attach fittings on the inboard and outboard foreflaps of each wing with new, improved fittings, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; and accomplishment of the actions specified in paragraphs (j)(1) through (j)(4) of this AD, as applicable, before or concurrently with the replacement; constitutes terminating action for paragraphs (g) through (j) of this AD and paragraph (l) of this AD for those replaced fittings on the outboard and inboard foreflaps.

(l) Retained Optional Deferral of Inspection

This paragraph restates the optional deferral of paragraph (o) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with no changes. Replacement of the two carriage attach fittings on the inboard and outboard foreflaps of each wing with new fittings having the same part number as the existing fittings, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002; and accomplishment of the actions specified in paragraphs (j)(1) through (j)(4) of this AD, as applicable, before or concurrently with the

replacement; defers the next inspection required by paragraph (g) of this AD for 10,000 flight cycles after the replacement. Thereafter, repeat the inspections required by paragraph (g) of this AD at intervals not to exceed 1,000 flight cycles, except as required by paragraph (m) of this AD.

(m) New Detailed and HFEC Inspections of Outboard Foreflaps, With Reduced Repetitive Intervals

Within 1,000 flight cycles after the most recent accomplishment of the inspections required by paragraph (g) of this AD, do a detailed inspection to detect cracks and surface deviations on all edges, surfaces, and lug attachment fastener holes, and a HFEC inspection to detect cracks at the lug attachment fastener holes, on the two carriage attach fittings on the outboard foreflaps of each wing, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012, and do all applicable corrective actions required by paragraph (h) of this AD. Repeat the inspections thereafter at intervals not to exceed 200 flight cycles until the requirements of paragraph (o) of this AD is accomplished. Accomplishing the requirements of this paragraph terminates the requirements of paragraph (g) of this AD for the outboard foreflaps only.

(n) New Inspection and Check of Outboard Foreflap Installation and Corrective Action

Within 200 flight cycles or 6 months after the effective date of this AD, whichever occurs first, do a general visual inspection and function check for damage and incorrect operation of the outboard foreflap installations, and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012. Do the applicable corrective actions before further flight. Thereafter, repeat the inspection and check at intervals not to exceed 500 flight cycles.

(o) New Replacement of Previously Un-Replaced (or "Original Configuration") Carriage Attach Fittings on the Outboard Foreflap

For airplanes on which any production carriage attach fitting is still installed on the outboard foreflap: Within 3,000 flight cycles or 3 years after the effective date of this AD, whichever occurs first, replace all production carriage attach fittings with new, improved carriage attach fittings, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012, and do all applicable concurrent actions required by paragraph (k) of this AD. Accomplishing the requirements of this paragraph terminates the requirements of paragraphs (g) and (m) of this AD for outboard foreflaps only.

(p) New Inspection, Corrective Action and Replacement of Fittings Replaced in Accordance With Paragraph (l) of This AD

For airplanes on which a new carriage attach fitting with the original part number on the outboard foreflap was installed in accordance with paragraph (l) of this AD: Do the actions specified in paragraphs (p)(1) and (p)(2) of this AD.

(1) Within 1,000 flight cycles after the effective date of this AD, do a detailed inspection for cracks and surface deviation on all edges surfaces, and lug attachment fastener holes, and a HFEC inspection for cracks at the lug attachment fastener holes, on the carriage attach fittings for the outboard foreflaps, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012. Repeat the inspection at intervals not to exceed 200 flight cycles. Do all applicable corrective actions before further flight.

(2) Within 3,000 flight cycles or 3 years after the effective date of this AD, replace the fitting with a new, improved fitting in accordance with the Accomplishment Instructions of Boeing Alert

Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012. Accomplishing the requirements of this paragraph terminates the requirements of paragraphs (g), (m), and (p)(1) of this AD for that outboard foreflap only.

(q) New Inspection and Corrective Actions on Fittings Replaced According to Paragraph (k), (o), or (p) of This AD on Outboard Foreflaps

For airplanes on which a new, improved carriage attach fitting on the outboard foreflap was replaced in accordance with the requirements of paragraph (k), (o), or (p) of this AD: Within 20,000 flight cycles after installing that fitting, do a detailed inspection for cracks and surface deviation on all edges surfaces, and lug attachment fastener holes, and a HFEC inspection for cracks at the lug attachment fastener holes, on the carriage attach fittings for the outboard foreflaps, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012. Do all applicable corrective actions before further flight. Repeat the inspection thereafter at intervals not to exceed 1,400 flight cycles. Accomplishing the requirements of this paragraph terminates the requirements of paragraph (g) of this AD for outboard foreflaps only.

(r) Retained Credit for Previously Accomplished Service Bulletins

(1) This paragraph restates the credit provided by paragraph (p) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with no changes. Installations accomplished before August 15, 2005 (the effective date of AD 2005-14-07), in accordance with Boeing 727 Service Bulletin 57-59, dated September 2, 1965, are acceptable for compliance with the requirements of paragraph (j)(1) of this AD.

(2) This paragraph restates the credit provided by paragraph (q) of AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), with no changes. Inspections and modifications accomplished before August 15, 2005 (the effective date of AD 2005-14-07), in accordance with Boeing Service Bulletin 727-27-133, dated October 7, 1971, are acceptable for compliance with the requirements of paragraph (j)(2) of this AD.

(s) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (t)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2005-14-07, Amendment 39-14184 (70 FR 39647, July 11, 2005), are approved as AMOCs for the corresponding provisions of this AD.

(t) Related Information

(1) For more information about this AD, contact Chandraduth Ramdoss, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5239; fax: 562-627-5210; email chandraduth.ramdoss@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (u)(5) and (u)(6) of this AD.

(u) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on December 3, 2014.

(i) Boeing Alert Service Bulletin 727-57A0135, Revision 4, dated September 26, 2012.

(ii) Reserved.

(4) The following service information was approved for IBR on August 15, 2005 (70 FR 39647, July 11, 2005).

(i) Boeing Alert Service Bulletin 727-57A0135, Revision 3, dated June 27, 2002.

(ii) Boeing Service Bulletin 727-27-133, Revision 1, dated May 9, 1972. Pages 1, 12, 14 through 18, and 27 of this document are identified as Revision 1, dated May 9, 1972. Pages 2 through 11, 13, 19 through 26, and 28 are original, dated October 7, 1971.

(iii) Boeing 727 Service Bulletin 57-59, Revision 1, dated September 27, 1965. Pages 1, 4, and 6 of this document are identified as Revision 1, dated September 27, 1965. Pages 2, 3, and 5 are original, dated September 2, 1965.

(iv) Boeing 727 Service Bulletin 57-72, dated September 21, 1966.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this referenced service information at the FAA, Transport Aircraft Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 15, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-21-10 Airbus: Amendment 39-18004. Docket No. FAA-2014-0140; Directorate Identifier 2013-NM-176-AD.

(a) Effective Date

This AD becomes effective December 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Model A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes, all manufacturer serial numbers, on which Airbus Modification 48825 has been embodied in production; except for airplanes on which Airbus Modification 52485, 40161, or 201669 has been embodied.

(2) Model A340-211, -212, -213, -311, -312, and -313 airplanes, all manufacturer serial numbers, on which Airbus Modification 48825D42865 has been embodied in production; except for airplanes on which Airbus Modification 55606 or 40161 has been embodied.

(d) Subject

Air Transport Association (ATA) of America Code 92, Wiring Elements.

(e) Reason

This AD was prompted by a report of contact between certain electrical harnesses and the hatrack rod that could cause chafing between the harnesses and surrounding structure. We are issuing this AD to prevent chafing and possible short circuit of two oxygen chemical generator containers in different wiring routes, which could result in malfunction of the electrical opening of all the containers connected to these routes. Such conditions, during a sudden depressurization event, could result in lack of oxygen and consequent injuries to airplane occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 24 months after the effective date of this AD: Modify the routing of electrical harnesses 1523VB on the left-hand side and 1524VB on the right-hand side, at the level of the door 3 area between frames 53.6 and 53.8, and between stringers 14 and 15, in accordance with the

Accomplishment Instructions of Airbus Service Bulletin A330-92-3098 or A340-92-4084, both dated January 11, 2013, as applicable.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) 2013-0196, dated August 28, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0140-0002>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-92-3098, dated January 11, 2013.

(ii) Airbus Service Bulletin A340-92-4084, dated January 11, 2013.

(3) For service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 15, 2014.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2014-22-02 Rolls-Royce plc: Amendment 39-18006; Docket No. FAA-2014-0705; Directorate Identifier 2014-NE-13-AD.

(a) Effective Date

This AD is effective November 14, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Rolls-Royce plc (RR) Trent 1000-A, 1000-C, 1000-D, 1000-E, 1000-G, and 1000-H turbofan engines.

(d) Reason

This AD was prompted by a finding that an intermediate pressure (IP) shaft failure may not be detected by engine electronic controller (EEC) software earlier than standard MB6.15. We are issuing this AD to detect IP shaft failure and prevent IP compressor turbine burst, uncontained engine failure, and damage to the airplane.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Within 30 days or 180 flight cycles after the effective date of this AD, whichever occurs first, remove from the engine any EEC software standard earlier than software standard MB6.15.

(2) Install EEC software eligible for installation.

(f) Installation Prohibition

After the effective date of this AD, do not install any EEC containing a software standard earlier than software standard of MB6.15, into any engine.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Kenneth Steeves, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7765; fax: 781-238-7199; email: kenneth.steeves@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2014-0192, dated September 1, 2014, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2014-0705.

(3) RR Alert Service Bulletin No. TREN 1000 73-AH914, dated July 23, 2014, which is not incorporated by reference in this AD, can be obtained from RR using the contact information in paragraph (h)(4) of this AD.

(4) For service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE248BJ; phone: 011-44-1332-242424; fax: 011-44-1332-249936; email: http://www.rolls-royce.com/contact/civil_team.jsp; Internet: <https://www.aeromanager.com>.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(i) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on October 17, 2014.
Colleen M. D'Alessandro,
Assistant Directorate Manager, Engine & Propeller Directorate,
Aircraft Certification Service.