

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS**

BIWEEKLY 2016-08

4/4/2016 - 4/17/2016



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes; R - Replaces

Biweekly 2016-01

2015-26-04	S 2002-13-11	Airbus Helicopters	EC120B helicopters
2015-26-08		Piper Aircraft, Inc.	PA-44-180, PA-44-180T airplanes
2015-26-10		Sikorsky Aircraft Corporation	S-76A, S-76B, and S-76C helicopters

Biweekly 2016-02

2015-12-09 R1	R 2015-12-09	Airbus Helicopters Deutschland GmbH	EC135P1, EC135T1, EC135P2, EC135T2, EC135P2+, EC135T2+, and MBB-BK 117 C-2
2016-01-01		Piper Aircraft, Inc.	PA-46-500TP
2016-01-06		Agusta S.p.A.	AB139 and AW139
2016-01-14		Airbus Helicopters Deutschland GmbH	MBB-BK 117 A-1, A-3, A-4, B-1, B-2, C-1, and C-2
2016-01-15		Agusta S.p.A.	AB139 and AW139
2016-01-19		MD Helicopters Inc.	500N and 600N

Biweekly 2016-03

2015-22-51		Agusta S.p.A.	A109A and A109AII helicopters
2016-02-06		Bell Helicopter Textron Canada Limited	429 helicopters

Biweekly 2016-04

2016-03-02		Turbomeca S.A.	ARRIEL 2C, 2C1, 2C2, 2S1, and 2S2 turboshaft engines
2016-03-05	S 2014-13-01	Airbus Helicopters Deutschland GmbH	MBB-BK 117 C-2 and MBB-BK 117 D-2 helicopters
2016-04-05	S 2014-03-18	B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN2A MK. III, BN2A MK. III-2, and BN2A MK. III-3 airplanes

Biweekly 2016-05

2016-04-04		M7 Aerospace LLC	SA26-AT, SA226-T(B), SA226-AT, SA226-T, SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), and SA227-TT
2016-04-14		Turbomeca S.A.	Arriel IE2
2016-04-15		MD Helicopters Inc.	369A, 369D, 369E, 369FF, 369HE, 369HM, 369HS, 500N, and 600N
2016-05-06	S 2014-07-52	Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP

Biweekly 2016-06

2016-04-12		Turbomeca S.A.	Arriel 2B, 2B1, 2C, 2C1, 2C2, 2D, 2E, 2S1, and 2S2 turboshaft engines
2016-05-01	R 96-12-12	Piper Aircraft, Inc.	PA-31, PA-31-300, PA-31-325 and PA-31-350
2016-05-08	R 2006-23-17	Turbomeca S.A.	Turmo IV A and IV C turboshaft engines.
2016-05-09		MD Helicopters, Inc.	369A (Army OH-6A), 369H, 369HE, 369HM, 369HS, and 369D; 369E, 369F and 369FF, 500N
2016-05-10		Airbus Helicopters	AS 365 N3, EC 155B, and EC155B1
2016-05-11		Sikorsky Aircraft Corporation	S-92A
2016-05-13		Pratt & Whitney Canada Corp.	PT6A-60AG, BS919 and BS1048; PT6A-65AG, BS708, BS903, BS1101, and BS1102; PT6A-67AF; and PT6A-67AG
2016-06-01	S 2007-06-06	B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN2A MK. III, BN2A MK. III-2, BN2A MK. III-3 BN2A, BN2B, and BN2A MKIII, BN2A, BN2B, and BN2A MKIII

Biweekly 2016-07

2016-06-09		Turbomeca S.A.	Makila 2A and 2A1
2016-07-01	S 2014-07-04R1	Sikorsky Aircraft Corporation	S-92A
2016-07-02		Honeywell International Inc.	TFE731-4, -4R, -5AR, -5BR, and -5R
2016-07-11		Weatherly Aircraft Company	201, 201A, 201B, 201C, 620, 620A, 620B, 620B-TG, and 620TP

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes; R - Replaces

Biweekly 2016-08

2016-07-13		GE Aviation Czech s.r.o	M601E-11
2016-07-19		Technify Motors GmbH	TAE 125-02-99 and TAE 125-02-114
2016-07-21	R 2015-20-13	Piper Aircraft, Inc.	PA-28-161, PA-28-181, and PA-28R-201
2016-07-24		Textron Aviation, Inc.	310 through 310R, E310H, E310J, T310P through T310R, 310J-1, 320 through 320F, 320-1, 335, 340, 340A, 401 through 401B, 402 through 402C, 411, 411A, 414, 414A, and 421 through 421C
2016-07-26	R 2010-23-02	Airbus Helicopters	SA-365N, SA-365N1, AS-365N2, and AS 365 N3
2016-07-27		Airbus Helicopters	SA341G and SA342J
2016-07-29		Airbus Helicopters	EC225LP, AS332C, AS332L, AS332L1, and AS332L2
2016-08-08	S 92-06-10	SOCATA	MS 880B, MS 885, MS 892A-150, MS 892E-150, MS 893A, MS 893E, MS 894A, MS 894E, Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, and Rallye 235C



2016-07-13 GE Aviation Czech s.r.o. (Type Certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.): Amendment 39-18458; Docket No. FAA-2016-3692; Directorate Identifier 2016-NE-05-AD.

(a) Effective Date

This AD is effective April 22, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to GE Aviation Czech s.r.o M601E-11 turboprop engine models with engine power turbine (PT) disk, part number 3220.6 and serial number EE8, EF8, or KR5, installed.

(d) Reason

This AD was prompted by discovery of damage to certain engine PT disks during engine shop visits. We are issuing this AD to prevent failure of the engine PT disk, which could result in release of high-energy debris, damage to the engine, and reduced control of the airplane.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Within 90 days after the effective date of this AD, perform visual, dimensional, and fluorescent penetrant inspections of the engine PT disk. Use Appendix B, paragraph 5 of GE Aviation Czech s.r.o. Alert Service Bulletin (ASB) No. SB-2016-72-50-00-1/00, dated January 21, 2016, to do the inspections.

(2) If the engine PT disk fails to meet the acceptance criteria in Appendix B, paragraph 5 of GE Aviation Czech s.r.o. ASB No. SB-2016-72-50-00-1/00, dated January 21, 2016, replace the PT disk with a part eligible for installation.

(f) Installation Prohibition

After the effective date of this AD:

(1) Do not operate any engine with a PT disk serial number listed in paragraph (c) of this AD, unless the disk was inspected per the requirements of paragraph (e) of this AD; and

(2) Do not install a PT disk that does not meet the acceptance criteria in Appendix B, paragraph 5 of GE Aviation Czech s.r.o. ASB No. SB-2016-72-50-00-1/00, dated January 21, 2016, onto any engine.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Kenneth Steeves, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7765; fax: 781-238-7199; email: kenneth.steeves@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2016-0025-E, dated January 26, 2016 (corrected January 27, 2016), for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2016-3692.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) GE Aviation Czech s.r.o. Alert Service Bulletin No. SB-2016-72-50-00-1/00, dated January 21, 2016.

(ii) Reserved.

(3) For GE Aviation Czech s.r.o service information identified in this AD, contact GE Aviation Czech s.r.o., Beranov[yaacute]ch 65, 199 02 Praha 9–Let[ncaron]any, Czech Republic; phone: +420 222 538 111; fax: +420 222 538 222.

(4) You may view this service information at FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7125.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on March 24, 2016.
Colleen M. D'Alessandro,
Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2016-07-19 Technify Motors GmbH (Type Certificate previously held by Thielert Aircraft Engines GmbH): Amendment 39-18464; Docket No. FAA-2015-5193; Directorate Identifier 2015-NE-35-AD.

(a) Effective Date

This AD becomes effective May 9, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Technify Motors GmbH TAE 125-02-99 and TAE 125-02-114 reciprocating engines with a fuel feed pump, part number (P/N) 05-7312-K0073xx, or P/N 05-7312-K0133xx, where "xx" can be any number, installed.

(d) Reason

This AD was prompted by reports of in-flight shutdowns on TAE 125-02 engines. We are issuing this AD to prevent failure of the fuel feed pump, damage to the engine, and damage to the airplane.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done. Remove from service each affected fuel feed pump before it exceeds 600 operating hours (OH) time in service (TIS) or within 110 OH after the effective date of this AD, whichever occurs later.

(f) Installation Prohibition

After the effective date of this AD, do not install onto any engine, any fuel feed pump, P/N 05-7312-K0073xx or P/N 05-7312-K0133xx, where "xx" can be any number, if the fuel feed pump has 600 hours or more TIS. If TIS of a fuel feed pump is unknown or has exceeded 600 hours TIS, then the fuel feed pump is not eligible for installation. Rebuilt, overhauled, or repaired fuel feed pumps or fuel feed pumps that lack a serial number, are not eligible for installation.

(g) Related Information

(1) For more information about this AD, Philip Haberlen, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7770; fax: 781-238-7199; email: philip.haberlen@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2015-0189, dated September 21, 2015, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2015-5193.

(3) For service information identified in this AD, contact Technify Motors GmbH, Platanenstrasse 14, D-09356 Sankt Egidien, Germany; phone: +49-37204-696-0; fax: +49-37204-696-2912; email: support@continentaldiesel.de.

(4) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(h) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on March 25, 2016.
Colleen M. D'Alessandro,
Manager, Engine & Propeller Directorate,
Aircraft Certification Service.



2016-07-21 Piper Aircraft, Inc.: Amendment 39-18466; Docket No. FAA-2016-5432; Directorate Identifier 2016-CE-009-AD.

(a) Effective Date

This AD is effective April 26, 2016.

(b) Affected ADs

This AD replaces AD 2015-20-13, Amendment 39-18292 (80 FR 61725) ("AD 2015-20-13").

(c) Applicability

This AD applies to the following Piper Aircraft, Inc. airplanes certificated in any category.

(1) Airplanes previously affected by AD 2015-20-13: Model PA-28-161 airplanes, serial numbers (S/Ns) 2842393 through 2842395; Model PA-28-181 airplanes, S/Ns 2843769 through 2843775 and 2843779 through 2843791; and Model PA-28R-201 airplanes, S/N 2844152.

(2) Airplanes new to this AD: Model PA-28-161 airplanes, S/Ns 2842010 through 2842392; Model PA-28-181 airplanes, S/Ns 2843021 through 2843768; and Model PA-28R-201 airplane, S/Ns 2844004 through 2844151.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 5712, Wing Ribs/Bulkhead.

(e) Unsafe Condition

This AD was prompted by reports of cracks found in the wing rib on airplanes outside the Applicability, paragraph (c), of AD 2015-20-13. The cracks occurred in production during forming of the wing rib bead radius. We are issuing this AD to detect and correct cracks in the wing rib, which if not corrected, could result in reduced structural integrity of the wing with consequent loss of control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspect

(1) Inspect the right wing rib at wing station (WS) 140.09 for cracks at the following compliance times.

(i) For airplanes previously affected by AD 2015-20-13: Within the next 25 hours time-in-service after (TIS) after October 29, 2015 (the effective date retained from AD 2015-20-13) following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1279, dated August 26, 2015, or Piper Aircraft, Inc. Service Bulletin No. 1279A, dated March 3, 2016.

(ii) For airplanes new to this AD: Within the next 25 hours TIS after April 26, 2016 (the effective date of this AD) following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1279A, dated March 3, 2016.

(2) If any crack is detected during the inspection required by paragraph (g)(1) of this AD, before further flight, obtain and implement an FAA-approved repair scheme, approved specifically for this AD. At the operator's discretion, assistance may be provided by contacting Piper Aircraft, Inc. at the address identified in paragraph (k)(5) of this AD.

(h) Special Flight Permit

A special flight permit is allowed for this AD per 14 CFR 39.23 for the inspection required in paragraph (g)(1) of this AD. If a crack is found during the inspection required in paragraph (g)(1) of this AD, a special flight permit is allowed with the following limitations:

- (1) Flight must be planned to the nearest location where repairs can be done;
- (2) Indicated airspeed must be 120 knots or less for the entire flight;
- (3) Bank angle is not to exceed 30 degrees for the entire flight;
- (4) Maximum load factors must be between +3.0 and -1.0 for the entire flight; and
- (5) Flight must be performed VFR, with no turbulence greater than "light" forecast for the planned flight route and altitude.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Gregory "Keith" Noles, Aerospace Engineer, FAA, Atlanta ACO, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5551; fax: (404) 474-5606; email: gregory.noles@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on April 26, 2016.

(i) Piper Aircraft, Inc. Service Bulletin No. 1279A, dated March 3, 2016.

(ii) Reserved.

(4) The following service information was approved for IBR on October 29, 2015 (80 FR 61725, October 14, 2015).

(i) Piper Aircraft, Inc. Service Bulletin No. 1279, dated August 26, 2015.

(ii) Reserved.

(5) For Piper Aircraft, Inc. service information identified in this AD, contact Piper Aircraft, Inc., Customer Service, 2926 Piper Drive, Vero Beach, Florida 32960; telephone: (877) 879-0275; fax: none; email: customer.service@piper.com; Internet: www.piper.com.

(6) You may review the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2016-5432.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 28, 2016.

Jacqueline Jambor,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.



2016-07-24 Textron Aviation, Inc.: Amendment 39-18469; Docket No. FAA-2016-5457;
Directorate Identifier 2016-CE-008-AD.

(a) Effective Date

This AD is effective April 26, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Textron Aviation, Inc. Models 310 through 310R, E310H, E310J, T310P through T310R, 310J-1, 320 through 320F, 320-1, 335, 340, 340A, 401 through 401B, 402 through 402C, 411, 411A, 414, 414A, and 421 through 421C airplanes (type certificates 3A10, 3A25, and A7CE previously held by Cessna Aircraft Company), all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 2731, Elevator Tab Control System.

(e) Unsafe Condition

This AD was prompted by lessons learned in accident investigation support, analysis of past accidents, and NTSB determinations of probable cause. That information confirms that following the loss of the attachment hardware connecting the elevator trim tab actuator to the elevator trim tab push-pull rod, the elevator tab may jam in a position outside the normal limits of travel and could result in loss of control. We are issuing this AD to correct the unsafe condition on these products.

(f) Actions and Compliance

Unless already done, do the actions in paragraphs (f)(1) through (f)(3) of this AD within the compliance times specified.

(1) Within the next 90 days after April 26, 2016 (the effective date of this AD), replace the elevator trim push-pull rod attachment hardware on the elevator trim actuator and the trim tab ends of the push-pull rod following steps 2 through 5 of the accomplishment instructions in Textron Aviation, Inc. (Cessna) Multi-engine Service Bulletin No. MEB-27-02, dated February 29, 2016.

(2) Following the replacement required in paragraph (f)(1) of this AD, at intervals not to exceed 100 hours TIS or 12 months, whichever occurs first, repetitively inspect the elevator trim push-pull rod attachment hardware on the elevator trim actuator and the trim tab ends of the push-pull rod, and replace the hardware if necessary before further flight following the Compliance NOTE on page 1 of Textron Aviation, Inc. (Cessna) Multi-engine Service Bulletin No. MEB-27-02, dated February 29, 2016.

(3) After April 26, 2016 (the effective date of this AD), any time the elevator trim push-pull rod attachment hardware on the elevator trim actuator and/or trim tab ends of the push-pull rod is removed for any reason, discard the old hardware (bolt, nut, washer and cotter pin) and replace with new hardware following steps 3 and/or step 5 of Textron Aviation, Inc. (Cessna) Multi-engine Service Bulletin No. MEB-27-02, dated February 29, 2016.

(g) Special Flight Permit

Special flight permits are allowed for this AD per 14 CFR 39.23 with the following limitation: Before flight a pre-flight inspection is required of the attachment hardware connecting the elevator trim tab actuator to the elevator trim tab push-pull rod. Confirmation of the presence of a castellated nut and cotter pin is required.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Adam Hein, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 S. Airport Road, Room 100, Wichita, Kansas 67209; phone: (316) 946-4116; fax: (316) 946-4107; email: adam.hein@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Textron Aviation, Inc. (Cessna) Multi-engine Service Bulletin No. MEB-27-02, dated February 29, 2016.

(ii) Reserved.

(3) For Textron Aviation, Inc. (Cessna) service information identified in this AD, contact Textron Aviation Customer Service, P.O. Box 7706, Wichita, Kansas 67277; telephone: (316) 517-5800; fax: (316) 517-7271; email: customercare@cessna.textron.com; Internet: <https://support.cessna.com/custsupt/csupt/newlogin.jsp>

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5457.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 30, 2016.
Jacqueline Jambor,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.



2016-07-26 Airbus Helicopters (previously Eurocopter France): Amendment 39-18471; Docket No. FAA-2015-4112; Directorate Identifier 2014-SW-043-AD.

(a) Applicability

This AD applies to Model SA-365N, SA-365N1, AS-365N2, and AS 365 N3 helicopters, with a horizontal stabilizer, part number 365A13-3030-1901, -1902, -1903, -1904, -1905, -1906, -1908, -1909; 365A13-3036-00, -0001, -0002, -0003; or 365A13-3038-00, installed, except those with modification 0755B28 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as vibration during descent at high speed. This condition could result in failure of the horizontal stabilizer and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD replaces AD 2010-23-02, Amendment 39-16491 (75 FR 68169, November 5, 2010).

(d) Effective Date

This AD becomes effective May 16, 2016.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

Before further flight:

(1) Revise the airspeed operating limitation in the Limitations section of the Rotorcraft Flight Manual (RFM) by making pen and ink changes or by inserting a copy of this AD into the RFM stating: "The never-exceed speed (VNE) is limited to 150 knots indicated airspeed (KIAS)" and "The rate-of-descent (R/D) must not exceed 1,500 ft/min when the airspeed is beyond 140 KIAS."

(2) Install one or more self-adhesive placards, with 6 millimeter red letters on white background, on the cockpit instrument panel in full view of the pilot and co-pilot to read as follows: "VNE LIMITED TO 150 KIAS" and "R/D MUST NOT EXCEED 1,500 ft/min when airspeed is beyond 140 KIAS"

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, Rotorcraft

Directorate, FAA, 10101 Hillwood Pkwy., Fort Worth, Texas 76177; telephone (817) 222-5110; email 9-asw-ftw-amoc-requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

(1) Eurocopter Emergency Alert Service Bulletin (EASB) No. 01.00.60, 01.00.16, and 01.28, Revision 1, dated December 2, 2008, and Airbus Helicopters Service Bulletin No. AS365-55.00.06, Revision 0, dated November 14, 2014, which are not incorporated by reference, contain additional information about the subject of this final rule. For service information identified in this final rule, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2008-0204R1, dated May 21, 2014. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2015-4112.

(i) Subject

Joint Aircraft Service Component (JASC) Code 5310: Horizontal Stabilizer Structure.

Issued in Fort Worth, Texas, on March 31, 2016.

James A. Grigg,
Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2016-07-27 Airbus Helicopters (formerly Eurocopter France): Amendment 39-18472; Docket No. FAA-2015-5914; Directorate Identifier 2014-SW-056-AD.

(a) Applicability

This AD applies to Model SA341G and SA342J helicopters with a main rotor head torsion bar (torsion bar) part number 704A33633274 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in the coating of the torsion bar resulting in corrosion. This condition could result in failure of a torsion bar, loss of a main rotor blade, and subsequent loss of control of the helicopter.

(c) Effective Date

This AD becomes effective May 18, 2016.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) For each torsion bar with less than 5 years since the first date of installation on any helicopter, within the compliance time shown in Table 1 to paragraph (e)(1) of this AD:

(i) Remove the torsion bar and, using a magnifying glass with a maximum magnification level of 10X, visually inspect for a crack in the polyurethane (PU) coating of the torsion bar as depicted in Figure 1 of Gazelle Inspection–Check 65.12.607, "Main Rotor Head: Torsion Tie-Back Check (Post MOD 076171)," dated August 2008, of the Eurocopter Gazelle Helicopter Maintenance Manual, Tome 1. This type of task is commonly called a "work card" and will be referenced in this AD as "the work card." Consider two cracks that are less than 5 mm (.196 in) apart as a single crack. If there is a crack in the PU coating that is more than 5 mm (.196 in), replace the torsion bar before further flight. Do not rework the PU coating of the torsion bar in any way.

(ii) Inspect the angle, dimension alpha, as depicted in View on Arrow F of Figure 1 of the work card. If the angle is 7 or more degrees, replace the torsion bar before further flight.

(iii) Inspect each bushing for corrosion on the inside diameter. If any corrosion cannot be removed by rubbing it with an abrasive pad, replace the torsion bar before further flight.

(iv) Using an outside micrometer, measure the thickness, dimension a, of each bushing as depicted in Detail AA of Figure 1 of the work card. If the thickness is less than 37.520 mm (1.477 in), replace the torsion bar before further flight.

(v) Using an inside micrometer, measure the inside diameter, dimension b, of each bushing as depicted in Detail AA of Figure 1 of the work card. If the diameter is larger than 21.040 mm (.828 in), replace the torsion bar before further flight.

(vi) Inspect the two faces of each bushing for missing varnish. If varnish is missing from more than 15% of the surface area on a face of a bushing, before further flight, remove all varnish using 400-grit abrasive paper. Finish with an abrasive pad and apply a coat of P05 paint to the face of the bushing.

Table 1 to Paragraph (e)(1)

Time accumulated on torsion bar	Compliance time
(i) Less than 320 hours time-in-service (TIS) since new and has never been inspected in accordance with Airbus Helicopters 341G—342J Airworthiness Limitations, Revision 18, dated June 2014 (limitations inspection)	Before accumulating 420 hours TIS since new or within 24 months since the date of first installation on any helicopter, whichever occurs first.
(ii) 320 or more hours TIS since new and has never had a limitations inspection	Within 100 hours TIS, or before accumulating 600 hours TIS since new, or within 24 months since the date of first installation on any helicopter, whichever occurs first.
(iii) Less than 320 hours TIS since the last limitations inspection	Before accumulating 420 hours TIS since the last limitations inspection or within 24 months since the last limitations inspection, whichever occurs first.
(iv) 320 or more hours TIS since the last limitations inspection	Within 100 hours TIS, or before accumulating 600 hours TIS since the last limitations inspection, or within 24 months since the last limitations inspection, whichever occurs first.

(2) For each torsion bar with 5 or more years since the first date of installation on any helicopter, within the compliance time shown in Table 2 to paragraph (e)(2) of this AD, do the inspections required by paragraphs (e)(1)(i) through (vi) of this AD.

Table 2 to Paragraph (e)(2)

Time accumulated on torsion bar	Compliance time
(i) Less than 320 hours TIS since new, and less than 6 months since the date of first installation on any helicopter, and has never had a limitations inspection	Before accumulating 420 hours TIS since new or within 12 months since the date of first installation on any helicopter, whichever occurs first.
(ii) 320 or more hours TIS since new or more than 6 months since the date of first installation on any helicopter, and has never had a limitations inspection	Within 100 hours TIS, or within 6 months, or before accumulating 600 hours TIS since new, or within 24 months since the date of first installation on any helicopter, whichever occurs first.
(iii) Less than 320 hours TIS since last limitations inspection and less than 6 months since the last limitations inspection	Before accumulating 420 hours TIS since last limitations inspection or 12 months since last limitations inspection, whichever occurs first.

(iv) 320 or more hours TIS since last limitations inspection or 6 or more months since the last limitations inspection	Within 100 hours TIS, or within 6 months, or before accumulating 600 hours TIS since the last limitations inspection, or within 24 months since the last limitations inspection, whichever occurs first.
--	--

(3) Repeat the inspections required by paragraphs (e)(1)(i) through (vi) of this AD as follows:

(i) For torsion bars with less than 6 years since the date of installation on any helicopter, at intervals not to exceed 420 hours TIS or 24 months, whichever occurs first.

(ii) For torsion bars with 6 or more years since the date of installation on any helicopter, at intervals not to exceed 420 hours TIS or 12 months, whichever comes first.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Airbus Helicopters Alert Service Bulletin ASB No. SA341/SA342-05.40, Revision 0, dated April 28, 2014, which is not incorporated by reference, contains additional information about the subject of this final rule. For Airbus Helicopters service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2014-0216, dated September 24, 2014. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2015-5914.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6700, Main Rotor.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Gazelle Inspection–Check 65.12.607, "Main Rotor Head: Torsion Tie-Back Check (Post MOD 076171)," dated August 2008, of the Eurocopter Gazelle Helicopter Maintenance Manual, Tome 1.

(ii) Reserved.

(3) For Eurocopter service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on March 31, 2016.

James A. Grigg,
Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2016-07-29 Airbus Helicopters (Previously Eurocopter France): Amendment 39-18474; Docket No. FAA-2014-0333; Directorate Identifier 2013-SW-025-AD.

(a) Applicability

This AD applies to Airbus Helicopters Model EC225LP, AS332C, AS332L, AS332L1, and AS332L2 helicopters with a TECALEMIT main gear box (MGB) hydraulic flexible hose (hose) installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as loss of hydraulic pressure because of the failure of a hose. This condition could result in loss of the hydraulic system and consequently, loss of helicopter control.

(c) Effective Date

This AD becomes effective May 16, 2016.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 110 hours time-in-service (TIS), and thereafter at intervals not to exceed 110 hours TIS, visually inspect each TECALEMIT hose installed in the MGB compartment for a cut, crack, or other damage.

(2) If there is a cut, crack, or any other damage in the hose sheath that allows you to see the metal braid underneath when pinching or twisting the sheath, replace the hose before further flight.

(3) If there is a cut, crack, or any other damage in the hose sheath on the right hand hydraulic system that does not allow you to see the metal braid underneath, replace the hose within 300 hours TIS.

(4) If there is a cut, crack, or any other damage in the hose sheath on the left hand hydraulic system that does not allow you to see the metal braid underneath, replace the hose within 600 hours TIS.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Rao Edupuganti, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Eurocopter Service Bulletin (SB) No. EC225-05-027 and SB No. AS332-05.00.92, both Revision 1 and dated July 17, 2013; Eurocopter SB No. AS332-29.00.17 and SB No. EC225-29-005, both Revision 0 and both dated June 21, 2013; and Eurocopter Information Notice No. 2506-I-29, Revision 2, dated July 24, 2013; which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in the European Aviation Safety Agency (EASA) AD No. 2013-0069, dated March 18, 2013. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2014-0333.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 2910, Main Hydraulic System.

Issued in Fort Worth, Texas, on March 31, 2016.

James A. Grigg,
Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.



2016-08-08 SOCATA: Amendment 39-18484; Docket No. FAA-2016-0068; Directorate Identifier 2015-CE-037-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective May 18, 2016.

(b) Affected ADs

This AD supersedes AD 92-06-10 Amendment 39-8190 (57 FR 8063; March 6, 1992) ("AD 92-06-10").

(c) Applicability

This AD applies to SOCATA Models MS 880B, MS 885, MS 892A-150, MS 892E-150, MS 893A, MS 893E, MS 894A, MS 894E, Rallye 100S, Rallye 150ST, Rallye 150T, Rallye 235E, and Rallye 235C airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 32: Landing Gear.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as fatigue failure of the nose landing gear wheel axle. We are issuing this AD to detect and correct chafing and cracking of the nose gear wheel axle, which could lead to failure of the nose landing gear with consequent damage to the airplane and/or occupants.

(f) Actions and Compliance

Do the actions in paragraphs (f)(1) through (f)(5) of this AD, including all subparagraphs. If the initial actions of paragraphs (f)(1), (f)(2), (f)(3), and (f)(4) of this AD have already been done before the effective date of this AD, then do the repetitive actions of these paragraphs at the specified times.

(1) Do a detailed visual inspection of the intersection between the axle radius and the nose landing gear fork area for chafing at whichever occurs later in paragraph (f)(1)(i) or (f)(1)(ii) of this AD and repetitively thereafter at intervals not to exceed 200 hours time-in-service (TIS) following Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 3, dated September 2015:

(i) Upon accumulating 200 hours TIS since the airplane's first flight or 200 hours TIS since the last inspection required by AD 92-06-10; or

(ii) Within the next 50 hours TIS after May 18, 2016 (the effective date of this AD) or within 500 hours TIS since the last inspection required by AD 92-06-10, whichever occurs first.

(2) Do a dye penetrant inspection on the nose wheel axle for cracks, distortion, and nicks or wear at whichever occurs later in paragraph (f)(2)(i) or (f)(2)(ii) of this AD and repetitively thereafter at intervals not to exceed 200 hours time-in-service (TIS) following Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 3, dated September 2015:

(i) Upon accumulating 200 hours TIS since the airplane's first flight or 200 hours TIS since the last inspection required by AD 92-06-10; or

(ii) Within the next 50 hours TIS after May 18, 2016 (the effective date of this AD) or within 500 hours TIS since the last inspection required by AD 92-06-10, whichever occurs first.

(3) If any cracks or damage is found in any inspection required by paragraphs (f)(1) or (f)(2) in this AD, contact SOCATA for FAA-approved repair or replacement instructions approved specifically for this AD and, before further flight, implement those instructions. Use the contact information found in paragraph (j) of this AD to contact SOCATA.

(4) Replace the nose landing gear wheel axle attachment screws with new screws at whichever occurs later in paragraph (f)(4)(i) or (f)(4)(ii) of this AD following Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 3, dated September 2015:

(i) Upon accumulating 2,000 hours TIS since airplane's first flight or 2,000 hours TIS since last nose landing gear wheel attachment screw replacement with new screws; or

(ii) Within 50 hours TIS since April 17, 1992 (the effective date retained from AD 92-06-10).

(5) After May 18, 2016 (the effective date of this AD), a used nose landing gear or a used nose landing gear wheel axle may be installed provided it has been inspected and found free of cracks and/or damage and the nose landing gear wheel axle attachment screws have been replaced with new screws as specified in paragraphs (f)(1), (f)(2), and (f)(4) of this AD.

(g) Credit for Actions Accomplished in Accordance With Previous Service Information

This AD allows credit for the inspections required in paragraph (f)(1) and (f)(2) of this AD, if done before May 18, 2016 (the effective date of this AD), following Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 2, dated January 1994.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: albert.mercado@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD 2015-0203, dated October 7, 2015; and Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 2, dated January 1994, for related information. The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2016-0068-0002>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Daher-Socata Mandatory Service Bulletin SB 150-32, Revision 3, dated September 2015.

(ii) Reserved.

(3) For SOCATA service information identified in this AD, contact SOCATA, Direction des services, 65921 Tarbes Cedex 9, France; phone: +33 (0) 5 62 41 73 00; fax: +33 (0) 5 62 41 76 54; email: info@socata.daher.com; Internet: <http://www.tbm.aero/>. For the United States, contact SOCATA NORTH AMERICA, North Perry Airport, 601 NE 10 Street, Pompano Beach, Florida 33060; phone: (954) 366-3331; Internet: <http://www.socatanorthamerica.com/default.htm>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0068.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on April 4, 2016.

Pat Mullen,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.