



**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES  
LARGE AIRCRAFT**

**BIWEEKLY 2006-16**

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation  
Federal Aviation Administration  
Regulatory Support Division  
Delegation and Airworthiness Programs Branch, AIR-140  
P. O. Box 26460  
Oklahoma City, OK 73125-0460  
FAX 405-954-4104



## LARGE AIRCRAFT

| AD No.  | Information          | Manufacturer                     | Applicability   |
|---|----------------------|----------------------------------|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |                      |                                  |   |
| <b>Biweekly 2006-01</b>   |                      |                                  |   |
| 2005-22-10  | R                    | Airbus                           | A320-111, -211, -212, -214, -231, -232, and -233  |
| 2005-24-11  | COR,<br>S 2003-09-03 | Embraer                          | EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP   |
| 2005-25-01  | COR                  | Embraer                          | EMB-120, -120ER, -120FC, -120QC, and -120RT   |
| 2005-26-07  |                      | Airbus                           | A318-111, A318-112, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, and A321-231              |
| 2005-26-09  |                      | Pratt & Whitney                  | Engine: JT9D-7R4 turbofan   |
| 2005-26-15  |                      | Embraer                          | EMB-135BJ, -135ER, -135KE, -135KL, -135LR; EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP  |
| 2005-26-16  | S 98-19-22           | Airbus                           | A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325                                |
| 2005-26-17  |                      | Airbus                           | A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, C4-605R Variant F, F4-605R, F4-622R; A310-203, -204, -221, -222, -304, -322, -324, and -325  |
| 2005-26-18  | S 2002-01-29         | Rolls-Royce Deutschland          | Engine: Tay 650-15 and 651-54 turbofan  |
| 2006-01-06  |                      | Airbus                           | A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, and -313  |
| 2006-01-51  | E                    | Frakes Aviation                  | G-73  |
| <b>Biweekly 2006-02</b>   |                      |                                  |   |
| 2006-01-01  |                      | Gulfstream Aerospace LP          | Gulfstream 100, Astra SPX, AND 1125 Westwind Astra  |
| 2006-01-02  |                      | McDonnell Douglas                | DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, MD-90-30 |
| 2006-01-03  |                      | Airbus                           | A300 B2-1A, B2-1C, B2K-3C, B2-203, A300 B4-2C, B4-103, and B4-203   |
| 2006-01-04  | S 94-11-03           | Raytheon                         | DH.125, HS.125, and BH.125 series; BAe.125 Series 800A (C-29A and U-125), 800B, 1000A, 1000B; Hawker 800 (including variant U-125A), and 1000   |
| 2006-01-07  |                      | Boeing                           | 747-100, 747-100B, 747-200B, 747-200C, 747-200F, 747-400F, 747SR, and 747SP series  |
| 2006-01-08  |                      | BAE Systems (Operations) Limited | Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A   |
| 2006-01-09  |                      | BAE Systems (Operations) Limited | BAe 146-100A and -200A series   |
| 2006-01-10  |                      | Airbus                           | A300 B4-600, B4-600R, F4-600R series, C4-605R Variant F (collectively called A300-600 series airplanes). A310 series  |
| 2006-01-51  | FR                   | Frakes Aviation                  | G-73 (Mallard) series; and G-73   |
| 2006-02-01  |                      | Airbus                           | A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, -313, -541, and -642  |
| 2006-02-02  |                      | Embraer                          | EMB-120, -120ER, -120FC, -120QC, and -120RT   |
| 2006-02-03  |                      | Raytheon                         | Hawker 800XP  |
| 2006-02-04  |                      | Bombardier, Inc.                 | CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604)  |
| 2006-02-05  |                      | Bombardier, Inc.                 | CL-600-2B19 (Regional Jet Series 100 & 440)   |
| 2006-02-06  |                      | Airbus                           | A310-203, -204, and -222, A310-304, -322, -324, and -325  |

## LARGE AIRCRAFT

| AD No. | Information | Manufacturer | Applicability |
|--------|-------------|--------------|---------------|
|--------|-------------|--------------|---------------|

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

**Biweekly 2006-03**

|            |  |                   |   |
|------------|--|-------------------|---|
| 2006-02-09 |  | Airbus            | A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313              |
| 2006-02-10 |  | Bombardier, Inc.  | CL-600-2B19 (Regional Jet Series 100 & 440)   |
| 2006-02-11 |  | McDonnell Douglas | C-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F |
| 2006-03-01 |  | Embraer           | ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU  |
| 2006-03-02 |  | Dassault Aviation | Falcon 2000, Falcon 2000EX  |
| 2006-03-03 |  | Rolls-Royce plc   | Engine: RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, and 560A2-61 turbofan                            |

## LARGE AIRCRAFT

| AD No.  | Information  | Manufacturer               | Applicability  |
|---|--------------|----------------------------|--|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |              |                            |  |
| <b>Biweekly 2006-04</b>   |              |                            |  |
| 2006-03-04  |              | McDonnell Douglas          | DC-8-33, DC-8-51, DC-8-53, DC-8-55, DC-8F-54, DC-8F-55, DC-8-63, DC-8-62F, DC-8-63F, DC-8-71, DC-8-73, DC-8-71F, DC-8-72F, and DC-8-73F  |
| 2006-03-05  | S 93-02-03   | Short Brothers             | SD3-60 SHERPA, SD3-SHERPA, and SD3-60  |
| 2006-03-06  |              | EMBRAER                    | EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP   |
| 2006-03-07  |              | Fokker                     | F.28 Mark -700 and 0100  |
| 2006-03-09  |              | Airbus                     | A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, -343, A340-211, -212, -213 -311, -312, -313, -541, and -642  |
| 2006-03-10  |              | Airbus                     | A318-111 and -112; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, and -233; and A321-111, -112, -131, -211 and -231   |
| 2006-03-11  |              | British Aerospace          | HS 748   |
| 2006-03-12  |              | Boeing                     | 737-100, -200, -200C, -300, -400, and -500   |
| 2006-03-13  |              | McDonnell Douglas          | DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F and MD-10-30F, MD-11 and MD-11F   |
| 2006-03-14  |              | Rolls-Royce plc            | Engine: RB211 Trent 500 Turbofan   |
| 2006-03-16  |              | Hamburger Flugzeugbau GmbH | HFB 320 HANSA  |
| 2006-04-01  |              | Airbus                     | A300 B2-1A, B2-1C, B2K-3C, and B2-203 airplanes; Model A300 B4-2C, B4-103, and B4-203 airplanes; Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes; Model A300 B4-605R and B4-622R airplanes; Model A300 F4-605R and F4-622R airplanes; Model A300 C4-605R Variant F airplanes; Model A310-203, -204, -221, and -222 airplanes; and Model A310-304, -322, -324, and -325 |
| 2006-04-03  |              | Airbus                     | A330-201, -202, -203, -223, and -243 airplanes; Model A330-301, -321, -322, -323, -341, -342, and -343 airplanes; Model A340-211, -212, and -213 airplanes; Model A340-311, -312, and -313 airplanes; Model A340-541 airplanes; and Model 340-642  |
| 2006-04-04  |              | Meggitt                    | Appliance: Smoke Detectors   |
| 2006-04-05  |              | Bombardier                 | CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900)  |
| 2006-04-06  | S 2000-24-02 | Airbus                     | A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111 airplanes; Model A320-211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, and -131 airplanes.   |
| 2006-04-07  |              | BAE Systems                | Bae 146 and Avro 146-RJ  |
| 2006-04-08  |              | Airbus                     | A300 B4-601, B4-603, B4-620, and B4-622 airplanes, A300 B4-605R and B4-622R airplanes, A300 F4-605R and F4-622R airplanes, and A300 C4-605R Variant F airplanes; and Airbus Model A310-304, -322, -324, and -325   |
| 2006-04-09  |              | Bombardier                 | CL-600-2C10 (Regional Jet Series 700, 701, & 702) airplanes CL-600-2D15 (Regional Jet Series 705) airplanes, CL-600-2D24 (Regional Jet Series 900) airplanes.  |
| 2006-04-10  |              | Cessna                     | 500, 550, S550, 560, 560XL, and 750  |

## LARGE AIRCRAFT

| AD No.  | Information                                    | Manufacturer   | Applicability   |
|---|--|--|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |  |  |   |
| <b>Biweekly 2006-05</b>   |  |  |   |
| 2000-24-03 R1<br>2006-04-02   | R 2000-24-03                                   | AvCraft Aerospace GmbH<br>Embraer                                    | 328-100<br>EMB-135BJ, -135ER, -135KE, -135KL, -135LR, EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP   |
| 2006-04-11<br>2006-04-12  | S 2004-07-15<br>S 2004-15-03R1                 | Airbus<br>General Electric Company                                   | A321-111, -112, and -131<br>Engine: CF34-3A1, -3B1, CF34-1A, -3A, -3A1, -3A2, and -3B series turbofan   |
| 2006-04-13<br>2006-04-14<br>2006-05-01  | COR  | Gulfstream<br>Boeing<br>Rolls-Royce plc                              | GIV-X, GV-SP series<br>757-200, 757-300 series<br>Engine: RB211 Trent 553-61, 556B-61, 556-61, 560-61, 553A2-61, 556A2-61, 556B2-61, 560A2-61, 768-60, 772-60, 772B-60, 892-17, 884-17, 892B-17, 895-17, 875-17, 884B-17, and 877-17 turbofan   |
| 2006-05-02<br>2006-05-04  | S 2001-10-03                                   | Boeing<br>General Electric Company                                   | 747-200F, 747-200C, 747-400, 747-400D, and 747-400F series<br>Engine: CF34-1A, -3A, -3A1, -3A2, -3B, and -3B1 turbofan  |
| <b>Biweekly 2006-06</b>   |  |  |   |
| 2006-03-09  | COR  | Airbus   | A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, -343, A340-211, -212, -213 -311, -312, -313, -541, and -642   |
| 2006-03-15  |  | Boeing   | 747SP, 747SR, 747-100, -100B, -100B SUD, -200B, -200C, -200F, and -300 series   |
| 2006-05-01  | COR  | Rolls-Royce plc  | Engine: RB211 Trent 553-61, 556B-61, 556-61, 560-61, 553A2-61, 556A2-61, 556B2-61, 560A2-61, 768-60, 772-60, 772B-60, 892-17, 884-17, 892B-17, 895-17, 875-17, 884B-17, and 877-17 turbofan   |
| 2006-05-03  |  | Rolls-Royce plc  | Engine: RB211 Trent 768-60, Trent 772-60, and Trent 772B-60 turbofan  |
| 2006-05-05  |  | MT-Propeller Entwicklung GmbH  | Propeller: MT, MTV-1, MTV-2, MTV-3, MTV-5, MTV-6, MTV-7, MTV-9, MTV-10, MTV-11, MTV-12, MTV-14, MTV-15, MTV-17, MTV-18, MTV-20, MTV-21, MTV-22, MTV-24, and MTV-25  |
| 2006-05-06  | S 2001-14-07,<br>2001-15-03, and<br>2003-19-08 | Boeing   | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series  |
| 2006-05-07<br>2006-05-08<br>2006-05-09<br>2006-05-10  |  | Aerospatiale<br>Boeing<br>Boeing<br>BAE Systems (Operations) Limited | ATR42-200, -300, and -320<br>777-200 series<br>747-200C, -200F, -400, -400D, and -400F series<br>BAe 146-100A, -200A, -300A series, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A   |
| 2006-05-11<br>2006-06-03<br>2006-06-04  | S 2004-02-07<br>S 93-13-07                     | Bombardier, Inc.<br>Cessna<br>McDonnell Douglas                      | CL-600-2B19 (Regional Jet Series 100 & 440)<br>500, 501, S550, 550, 551, and 560<br>DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC 9-32F (C-9A, C-9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), and DC-9-82 (MD-82) |
| 2006-06-05  |  | Boeing   | 720 and 720B series   |

## LARGE AIRCRAFT

| AD No.  | Information  | Manufacturer      | Applicability   |
|---|--------------|-------------------|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |              |                   |   |
| <b>Biweekly 2006-07</b>   |              |                   |   |
| 2006-05-11 R1   | R 2006-05-11 | Bombardier        | CL-600-2B19 (Regional Jet Series 100 & 440)   |
| 2006-06-07  |              | Fokker            | F.28 Mark 0070 and 0100   |
| 2006-06-08  |              | General Electric  | Engine: CF6-80C2D1F turbofan  |
| 2006-06-09  |              | Embraer           | ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU  |
| 2006-06-10  |              | Boeing            | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series   |
| 2006-06-11  |              | Boeing            | 747-100B SUD, 747-300, 747-400, 747-400D, and 747-200B series   |
| 2006-06-12  |              | Aerospatiale      | ATR72-101, -102, -201, -202, -211, -212, and -212A  |
| 2006-06-13  |              | Airbus            | A330-201, -202, -203, -223, -243, A330-301, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, and -313  |
| 2006-06-14  |              | Airbus            | A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, A321-211, -212, -213, -231, and -232   |
| 2006-06-15  |              | Airbus            | A318-111-112, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, A321-211, -212, -213, -231, and -232        |
| 2006-07-01  |              | Embraer           | EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP   |
| 2006-07-02  |              | Bombardier        | DHC-8-301, -311, and -315   |
| 2006-07-03  |              | Airbus            | A321-111, -112, -131, A321-211 and -231   |
| 2006-07-04  |              | Boeing            | 737-600, -700, -700C, -800, and -900 series   |
| 2006-07-05  |              | Airbus            | A319-131, -132, -133, A320-232, -233, A321-131, -231, and -232  |
| 2006-07-07  |              | Airbus            | A300 B4-600, B4-600R, F4-600R series, and C4-605R variant F   |
| 2006-07-08  |              | McDonnell Douglas | DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, and DC-9-51 |
| 2006-07-09  |              | Airbus            | A318-111 -112, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, A321-211, -212, -213, -231 and -232        |
| 2006-07-11  |              | McDonnell Douglas | DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, and MD-90-30   |
| 2006-07-12  |              | Boeing            | 737-100, -200, -200C, -300, -400, and -500 series   |
| 2006-07-13  |              | Airbus            | A310, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, A300 C4-605R Variant F   |

## LARGE AIRCRAFT

| AD No.  | Information  | Manufacturer                     | Applicability   |
|---|--------------|----------------------------------|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |              |                                  |   |
| <b>Biweekly 2006-08</b>   |              |                                  |   |
| 2005-05-20  |              | Boeing                           | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-300, 747-400, 747-400D, 747SP, 747SR, 767-200, 767-300, 777-200, 777-300, and 777-300ER  |
| 2006-04-13 R1   | R 2006-04-13 | Gulfstream                       | GIV-X, GV-SP series   |
| 2006-07-10  | S 91-09-07   | Boeing                           | 727, 727C, 727-100, 727-100C, 727-200, and 727-200F   |
| 2006-07-14  |              | Boeing                           | 767-200, -300, and -300F series   |
| 2006-07-16  |              | Bombardier                       | DHC-8-400 series  |
| 2006-07-17  |              | Boeing                           | 727, 727C, 727-100, 727-100C, and 727-200 series  |
| 2006-07-18  |              | Embraer                          | EMB-120, -120ER, -120FC, -120QC, and -120RT   |
| 2006-07-19  |              | Aerospatiale                     | ATR42-200, -300, -320, -500, ATR72-101, -201, -102, -202, -211, -212, and -212A   |
| 2006-07-21  |              | Boeing                           | 757-200, and -200PF   |
| 2006-07-22  |              | BAE Systems (Operations) Limited | BAe 146-100A, -200A, -300A series, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A  |
| 2006-07-23  |              | Boeing                           | 757-200, -200PF, -200CB, and -300 series  |
| 2006-07-24  |              | Boeing                           | 757-200 and 757-300 series  |
| 2006-07-25  | S 89-14-02   | McDonnell Douglas                | DC-8-11, DC-8-12, DC-8-21, DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, DC-8-43, DC-8-51, DC-8-52, DC-8-53, DC-8-55, DC-8F-54, DC-8F-55, DC-8-61, DC-8-62, DC-8-63, DC-8-61F, DC-8-62F, DC-8-63F, DC-8-71, DC-8-72, DC-8-73, DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 |
| 2006-07-26  |              | Aerospatiale                     | ATR42-200, -300, -320, and -500   |
| 2006-08-02  | S 2004-03-11 | Boeing                           | 747-200C and -200F series   |
| 2006-08-03  |              | Sicma Aero Seat                  | Appliance: Cabin attendant seats  |
| 2006-08-04  |              | Boeing                           | 767-200, -300, -300F series, and 767-400ER series   |
| 2006-08-05  |              | Fokker                           | F.28 Mark 0100  |
| <b>Biweekly 2006-09</b>   |              |                                  |   |
| 2006-07-07  | COR          | Airbus                           | A300 B4-600, B4-600R, F4-600R series, and C4-605R variant F   |
| 2006-08-10  |              | General Electric                 | Engine: CT64-820-4 turboprop  |
| 2006-09-01  | S 2005-19-06 | Boeing                           | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series   |
| 2006-09-02  |              | Boeing                           | 757-200 and -200PF series   |
| 2006-09-03  |              | Boeing                           | 727, 727C, 727-100 and 727-100C series  |
| 2006-09-08  |              | Bombardier, Inc.                 | CL-600-2B19 (Regional Jet Series 100 & 440)   |

## LARGE AIRCRAFT

| AD No.  | Information  | Manufacturer                 | Applicability   |
|---|--------------|------------------------------|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |              |                              |   |
| <b>Biweekly 2006-10</b>   |              |                              |   |
| 2004-03-15 R1   | R 2004-03-15 | Bombardier, Inc.             | DHC-8-102, -103, -106, -201, -202, -301, -311, and -315   |
| 2006-09-04  |              | Dassault Aviation            | Falcon 900EX  |
| 2006-09-05  |              | Airbus                       | A310-203, -204, -221, -222, A310-304, -322, -324, and -325  |
| 2006-09-06  | S 99-07-12   | Boeing                       | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747-400, 747-400D, and 747SR series   |
| 2006-09-07  |              | Airbus                       | A330-201, -202, -203, -223, -243, A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, -313, A340-541, and A340-642  |
| 2006-09-09  |              | Boeing                       | 767-200, -300, -300F, and -400ER series   |
| 2006-09-11  |              | Airbus                       | A319-111, -112, -113, -114, -115, -131, -132, -133; A320-211, -212, -214, -231, -232, -233; A321-111, -112, -131; A321-211 and -231   |
| 2006-09-12  |              | Airbus                       | A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F airplanes (collectively called A300-600 series airplanes); A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2006-09-13  | S 95-04-11   | Honeywell International Inc. | Engine: ALF502L, ALF502L-2, ALF502L-2A, ALF502L-2C, and ALF502L-3 series turbofan, and ALF502R series   |
| 2006-10-01  | S 2003-14-17 | Bombardier, Inc.             | CL-600-2B19 (Regional Jet Series 100 & 440)   |
| 2006-10-02  |              | Boeing                       | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series  |
| 2006-10-03  |              | Airbus                       | A319-111, -112, -113, -114, -115, -131, -132, -133; A320-111, -211, -212, -214, -231, -232, and -233  |
| 2006-10-04  |              | Boeing                       | 747-200B, 747-200C, 747-200F, 747-300, 747-400, and 747SP series  |
| 2006-10-05  |              | SAAB AIRCRAFT AB             | SAAB-Fairchild SF340A (SAAB/SF340A) and SAAB 340B   |
| 2006-10-06  |              | Bombardier, Inc.             | CL-600-2B19 (Regional Jet Series 100 and 440)   |
| 2006-10-07  |              | Hamilton Sundstrand          | Propeller: 14RF-9   |

## LARGE AIRCRAFT

| AD No.  | Information                  | Manufacturer                     | Applicability   |
|---|------------------------------|----------------------------------|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |                              |                                  |   |
| <b>Biweekly 2006-11</b>   |                              |                                  |   |
| 2006-10-07  | COR                          | Hamilton Sundstrand              | Propeller: 14RF-9   |
| 2006-10-08  | S 2002-01-15                 | Boeing                           | 767-200, -300, and -300F series   |
| 2006-10-09  |                              | EMBRAER                          | EMB-120, -120ER, -120FC, -120QC, and -120RT   |
| 2006-10-10  |                              | Bombardier, Inc.                 | BD-100-1A10   |
| 2006-10-11  |                              | Airbus                           | A310-203, -204, -221, -222, -304, -322, -324, and -325  |
| 2006-10-12  |                              | BAE Systems (Operations) Limited | BAe 146-100A, -200A, -300A series, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A  |
| 2006-10-13  |                              | Airbus                           | A330-223, -321, -322, and -323  |
| 2006-10-14  |                              | McDonnell Douglas                | DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, MD-90-30; and 717-200 |
| 2006-10-15  |                              | Learjet                          | 45  |
| 2006-10-16  | S 2002-06-02<br>S 2003-13-09 | Boeing                           | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series  |
| 2006-10-17  |                              | Boeing                           | 737-600, -700, -700C, -800, and -900 series   |
| 2006-11-01  | S 2004-23-08                 | Airbus                           | A300 B4-605R, B4-622R, A300 F4-605R and F4-622R   |
| 2006-11-02  |                              | Viking Air Limited               | DHC-7-1, DHC-7-100, DHC-7-101, DHC-7-102, and DHC-7-103   |
| 2006-11-03  |                              | Gulfstream                       | GV and GV-SP series   |
| 2006-11-04  | S 2005-12-07                 | Airbus                           | A318, A319, A320, and A321  |
| 2006-11-05  | S 2004-01-20                 | Rolls-Royce plc                  | Engine: RB211-22B, RB211-524B, -524C2, -524D4, -524G2, -524G3, -524H, RB211-535C, and -535E series turbofan   |
| 2006-11-06  |                              | Boeing                           | 767-200 and -300 series   |
| 2006-11-07  |                              | Raytheon                         | Hawker 800XP  |
| 2006-11-08  | S 2002-03-07                 | BAE Systems (Operations) Limited | BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A   |
| 2006-11-09  |                              | Bombardier, Inc.                 | CL-600-2B19 (Regional Jet Series 100 & 440)   |
| 2006-11-10  |                              | EMBRAER                          | EMB-120, -120ER, -120FC, -120QC, and -120RT   |
| 2006-11-11  | S 2001-20-12                 | Boeing                           | 757-200, -200PF, -200CB, and -300 series  |
| 2006-11-12  |                              | Boeing                           | 767-200, -300, -300F, and -400ER series   |
| 2006-11-13  |                              | Boeing                           | 777-200 and -300 series   |
| <b>Biweekly 2006-12</b>   |                              |                                  |   |
| 2006-04-11 R1   | R 2006-04-11                 | Airbus                           | A321-111, -112, and -131  |
| 2006-10-18  |                              | Gulfstream Aerospace LP          | Galaxy and Gulfstream 200   |
| 2006-11-15  |                              | Embraer                          | ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 190-100 STD, -100 LR, and -100 IGW  |
| 2006-12-03  |                              | Boeing                           | 747-100B, 747-200B, 747-200F, 747-300, 747-400, 747-400F, and 747SP series  |
| 2006-12-04  |                              | Viking Air Limited               | DHC-7-1, DHC-7-100, DHC-7-101, DHC-7-102, and DHC-7-103   |
| 2006-12-05  | S 2004-08-03                 | Airbus                           | A300 B4-601, B4-603, B4-620, B4-622, A300 C4-605R Variant F, A300 B4-2C, B4-103, B4-203, A310-203, -204, -221, -222, A310-304, -322, -324, and -325   |
| 2006-12-06  |                              | Boeing                           | 737-300, -400, -500, -700, -800 series, 747-400, 747-400F series, 757-200 series, 767-300 series, 777-300 series  |

## LARGE AIRCRAFT

| AD No.  | Information                         | Manufacturer                        | Applicability  |
|---|-------------------------------------|-------------------------------------|--|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |                                     |                                     |  |
| <b>Biweekly 2006-13</b>   |                                     |                                     |  |
| 2000-11-19 R1<br>2006-10-01   | R 2000-11-19<br>COR<br>S 2003-14-17 | Boeing<br>Bombardier, Inc.          | 767-200 and -300 series<br>CL-600-2B19 (Regional Jet Series 100 & 440)   |
| 2006-12-01  |                                     | Airbus                              | A300 B4-605R, B4-622R, A300 C4-605R Variant F, A300 F4-605R, F4-622R, A310-304, -322, -324, and -325   |
| 2006-12-02  |                                     | Airbus                              | A318, A319, A320, and A321   |
| 2006-12-08  |                                     | Goodrich                            | Appliance: Evacuation Systems  |
| 2006-12-09  | S 2004-01-07                        | BAE Systems (Operations)<br>Limited | BAe 146-100A, -200A, -300A series, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A   |
| 2006-12-10  |                                     | Boeing                              | 747-400 series   |
| 2006-12-11  |                                     | Boeing                              | 737-600, -700, -700C, -800, and -900 series  |
| 2006-12-12  | S 2001-14-22                        | Boeing                              | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series  |
| 2006-12-13  | S 2000-05-07                        | Airbus                              | A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F                 |
| 2006-12-14  |                                     | Embraer                             | EMB-120, -120ER, -120FC, -120QC, and -120RT  |
| 2006-12-15  |                                     | Bombardier, Inc.                    | DHC-8-400, DHC-8-401, and DHC-8-402  |
| 2006-12-16  |                                     | Bombardier, Inc.                    | DHC-8-102, -103, -106, -201, -202, -301, -311, -314, and -315  |
| 2006-12-17  | S 99-12-08                          | Boeing                              | 737-200C series  |
| 2006-12-18  |                                     | Short Brothers PLC                  | SD3-60 SHERPA, SD3-SHERPA, SD3-30, and SD3-60  |
| 2006-12-19  |                                     | Hamilton Sundstrand                 | Propeller: 14RF-19   |
| 2006-12-20  |                                     | Raytheon                            | HS.125 series 700A, 700B, BAe.125 series 800A (including variants C-29A and U-125), 800B, 1000A, and 1000B, Hawker 800 (including variant U-125A) and 1000, Hawker 800XP |
| 2006-12-21  | S 98-20-01                          | Bombardier, Inc.                    | CL-600-2B19 (Regional Jet Series 100 & 400)  |
| 2006-12-22  |                                     | Airbus                              | A320, A319 and A321  |
| 2006-12-23  | S 2002-01-01                        | Boeing                              | 737-100, -200, -200C, -300, -400, and -500 series  |
| 2006-12-24  | S 95-17-15                          | General Electric                    | Engine: CF6-45/-50 and CF6-80A turbofan  |
| 2006-12-26  |                                     | Boeing                              | 777-200, -300, and -300ER series   |
| 2006-13-01  | S 86-17-05 R1                       | Boeing                              | 727-200 series   |
| 2006-13-02  |                                     | Embraer                             | ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU   |
| 2006-13-03  |                                     | Boeing                              | 757-200, -200PF, and -200CB series   |
| 2006-13-04  |                                     | Airbus                              | A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, B4-601, B4-603, B4-605R, B4-620, B4-622, B4-622R, F4-605R, F4-622R, and C4-605R Variant F                      |
| 2006-13-07  | S 2000-14-12                        | McDonnell Douglas                   | MD-11 and MD-11F   |
| 2006-13-08  |                                     | Airbus                              | A330-201, -202, -203, -223, -243, A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, -313, A340-541, and A340-642           |
| 2006-13-09  |                                     | Boeing                              | 747-400 and 747-400D series  |
| 2006-13-13  |                                     | Boeing                              | 737-100, -200, -200C, -300, -400, -500, -600, -700, -700C, -800 and -900 series  |

## LARGE AIRCRAFT

| AD No.  | Information                 | Manufacturer                 | Applicability   |
|---|-----------------------------|------------------------------|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |                             |                              |   |
| <b>Biweekly 2006-14</b>   |                             |                              |   |
| 2006-12-08  | COR                         | Goodrich                     | Appliance: Evacuation Systems   |
| 2006-13-13  | COR                         | Boeing                       | 737-100, -200, -200C, -300, -400, -500, -600, -700, -700C, -800 and -900 series   |
| 2006-13-16  |                             | Boeing                       | 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series  |
| 2006-13-17  |                             | Boeing                       | 757-200 series  |
| 2006-13-18  |                             | McDonnell Douglas            | DC-9-31, DC-9-32, DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-41, and DC-9-51   |
| 2006-14-01  |                             | Airbus                       | A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, -313; A340-541 and -642   |
| 2006-14-02  |                             | Airbus                       | A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, -343; A340-211, -212, -213, -311, -312, and -313  |
| 2006-14-03  |                             | Honeywell International Inc. | Engine: TPE331-1, -1U, -1UA, -2, -2UA, -3U, -3UW, -3W, -5, -5A, -5AB, -5B, -5U, -6, -6A, -6U, -8, -8A, -9, -9U, -10, -10A, -10AV, -10B, -10G, -10GP, -10GR, -10GT, -10J, -10N, -10P, -10R, -10T, -10U, -10UA, -10UF, -10UG, -10UGR, -10UJ, -10UK, -10UR, -11U, -11UA, -12, -12B, -12JR, -12UA, -12UAR, -12UER, and -12UHR series turboprop and TSE331-3U model turboshaft |
| 2006-14-06  |                             | Airbus                       | A300 F4-605R, F4-622R, and A300 C4-605R Variant F   |
| <b>Biweekly 2006-15</b>   |                             |                              |   |
| 2006-13-17  | COR                         | Boeing                       | 757-200 series  |
| 2006-14-05  | S 2003-19-51                | Bombardier, Inc.             | CL-600-2C10 (Regional Jet Series 700, 701, and 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)   |
| 2006-14-07  | S 76-11-05 R1               | Boeing                       | 737-100, -200, and -200C series   |
| 2006-14-09  |                             | Airbus                       | A330-201, 202, -203, -223, and -243; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; and A340-311, -312, and -313   |
| 2006-15-04  | S 2003-26-10 and 2004-18-13 | Airbus                       | A300 B2-1A, B2-1C, B2K-3C, and B2-203; A300 B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F  |
| 2006-15-05  |                             | Boeing                       | 737-200, -300, and -400 series  |
| 2006-15-06  | S 2000-23-07                | Airbus                       | A300 B2-203 and A300 B4-203; B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, F4-622R, and A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325   |
| 2006-15-08  |                             | Honeywell International Inc. | Engine: TPE331-1, -2, -2UA, -3U, -3UW, -5, -5A, -5AB, -5B, -6, -6A, -10, -10AV, -10GP, -10GT, -10P, -10R, -10T, -10U, -10UA, -10UF, -10UG, -10UGR, -10UR, -11U, -12JR, -12UA, -12UAR, and -12UHR turboprop  |

## LARGE AIRCRAFT

| AD No.  | Information    | Manufacturer                             | Applicability   |
|---|----------------|--|---|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency |                |  |   |
| <b>Biweekly 2006-16</b>   |                |  |   |
| 2006-15-09  |                | Airbus                                   | A300 and A310; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F  |
| 2006-15-10  |                | Airbus                                   | A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, and -222; A310-304, -322, -324, and -325 |
| 2006-15-11  |                | Construcciones Aeronauticas, S.A. (CASA) | C-212-CC  |
| 2006-15-12  |                | Construcciones Aeronauticas, S.A. (CASA) | C-212-CC  |
| 2006-15-13  |                | McCauley Propeller Systems               | Propeller: B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0   |
| 2006-15-15  |                | McDonnell Douglas                        | DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88   |
| 2006-15-16  |                | Raytheon                                 | 400 and 400A series   |
| 2006-15-17  |                | Fokker                                   | F.28 Mark 0070 and 0100   |
| 2006-15-18  |                | Boeing                                   | 737-300, -400, and -500 series; 737-600, -700, -700C, -800, and -900 series   |
| 2006-16-01  | S 2006-12-19   | Hamilton Sundstrand                      | Propeller: 14RF-19  |
| 2006-16-02  |                | McDonnell Douglas                        | DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88   |
| 2006-16-03  |                | McDonnell Douglas                        | DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F   |
| 2006-16-05  | S 2000-16-02R1 | Pratt & Whitney                          | Engine: PW4164, PW4168, and PW4168A series turbofan   |

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-09 Airbus:** Amendment 39-14689. Docket No. FAA-2006-24779; Directorate Identifier 2006-NM-044-AD.

## Effective Date

- (a) This AD becomes effective August 29, 2006.

## Affected ADs

- (b) None.

## Applicability

(c) This AD applies to the Airbus airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) All Model A300 airplanes and Model A310 airplanes.

(2) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes; Model A300 B4-605R and B4-622R airplanes; Model A300 F4-605R and F4-622R airplanes; and Model A300 C4-605R Variant F airplanes; except those airplanes identified in paragraphs (c)(2)(i) and (c)(2)(ii) of this AD.

(i) Airplanes not equipped with trim fuel tanks on which Airbus Modifications 12226, 12365, and 12308 have been incorporated in production.

(ii) Airplanes equipped with trim fuel tanks on which Airbus Modifications 12226, 12365, 12308, 12294, and 12476 have been incorporated in production.

## Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to ensure continuous electrical bonding protection of equipment in the wing, center, and trim fuel tanks and to prevent damage to wiring in the wing and center fuel tanks, due to failed P-clips used for retaining the wiring and pipes, which could result in a possible fuel ignition source in the fuel tanks.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Service Bulletin References

(f) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of the service bulletin identified in Table 1 of this AD, as applicable.

**Table 1.—Service Bulletin References**

| <b>For Airbus—</b>   | <b>And the actions specified in—</b> | <b>Use Airbus Service Bulletin—</b> | <b>Dated—</b>       |
|--|--------------------------------------|-------------------------------------|---------------------|
| Model A300 airplanes   | Paragraph (g) of this AD             | A300–28–0081                        | July 20, 2005.      |
|  | Paragraph (h) of this AD             | A300–28–0079                        | September 29, 2005. |
| Model A310 airplanes   | Paragraph (g) of this AD             | A310–28–2143                        | July 20, 2005.      |
|  | Paragraph (h) of this AD             | A310–28–2142                        | August 26, 2005.    |
|  | Paragraph (i) of this AD             | A310–28–2153                        | July 20, 2005.      |
| Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes; Model A300 B4–605R and B4–622R airplanes; Model A300 F4–605R and F4–622R airplanes; and Model A300 C4–605R Variant F airplanes. | Paragraph (g) of this AD             | A300–28–6068                        | July 20, 2005.      |
|  | Paragraph (h) of this AD             | A300–28–6064                        | July 28, 2005.      |
|  | Paragraph (i) of this AD             | A300–28–6077                        | July 25, 2005.      |
|  |                                      |                                     |                     |

### **Inspection and Corrective Actions**

(g) Within 59 months after the effective date of this AD: Do a general visual inspection of the right and left wing fuel tanks and center fuel tank, if applicable, to determine if any NSA5516-XXND and NSA5516-XXNJ type P-clips are installed for retaining wiring and pipes in any tank, and do all applicable corrective actions before further flight after the inspection, by accomplishing all the actions specified in the service bulletin.

**Note 1:** For the purposes of this AD, a general visual inspection is: “A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.”

### **Installation of Bonding Leads and Points for Wing and Center Fuel Tanks**

(h) Within 59 months after the effective date of this AD: Do the actions specified in paragraphs (h)(1) and (h)(2) of this AD, by accomplishing all the actions specified in the service bulletin.

(1) In the center fuel tank, if applicable, do a general visual inspection of the electrical bonding points of the equipment identified in the service bulletin for the presence of a blue coat, and do all related investigative and corrective actions before further flight after the inspection.

(2) In the left and right wing fuel tanks and center fuel tank, if applicable, install bonding leads and electrical bonding points on the equipment identified in the service bulletin.

### **Installation of Bonding Leads and Points for the Trim Fuel Tank**

(i) For Model A310 airplanes; Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes; Model A300 B4-605R and B4-622R airplanes; Model A300 F4-605R and F4-622R airplanes; and Model A300 C4-605R Variant F airplanes; equipped with a trim fuel tank: Within 59 months after

the effective date of this AD, install a new bonding lead(s) on the water drain system of the trim fuel tank and install electrical bonding points on the equipment identified in the service bulletin in the trim fuel tank, by accomplishing all the actions specified in the service bulletin, as applicable.

### Parts Installation

(j) As of the effective date of this AD, no person may install any NSA5516-XXND or NSA5516-XXNJ type P-clip for retaining wiring and pipes in any wing, center, or trim fuel tank, on any airplane.

### Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### Related Information

(l) French airworthiness directive F-2006-031, dated February 1, 2006, also addresses the subject of this AD.

### Material Incorporated by Reference

(m) You must use the Airbus service bulletins identified in Table 2 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

**Table 2.—Material Incorporated by Reference**

| <b>Airbus Service Bulletin—</b> | <b>Dated—</b>       |
|---------------------------------|---------------------|
| A300–28–0079                    | September 29, 2005. |
| A300–28–0081                    | July 20, 2005.      |
| A300–28–6064                    | July 28, 2005.      |
| A300–28–6068                    | July 20, 2005.      |
| A300–28–6077                    | July 25, 2005.      |
| A310–28–2142                    | August 26, 2005.    |
| A310–28–2143                    | July 20, 2005.      |
| A310–28–2153                    | July 20, 2005.      |

Issued in Renton, Washington, on July 14, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-11713 Filed 7-24-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-10 Airbus:** Amendment 39-14690. Docket No. FAA-2005-22630; Directorate Identifier 2001-NM-323-AD.

## Effective Date

(a) This AD becomes effective August 29, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to all of the following Airbus airplanes, certificated in any category:

Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes

Model A300 B4-605R and B4-622R airplanes

Model A300 F4-605R and F4-622R airplanes

Model A300 C4-605R Variant F airplanes

Model A310-203, -204, -221, and -222 airplanes

Model A310-304, -322, -324, and -325 airplanes

## Unsafe Condition

(d) This AD results from reports of trimmable horizontal stabilizer actuators (THSAs) that have reached their design operational life. We are issuing this AD to extend the operational life of the THSA to prevent a possible failure of high-time units, which could result in reduced controllability of the airplane.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Service Bulletin References

(f) Unless otherwise specified in this AD, the term "service bulletin," as used in this AD, means the applicable required service bulletin identified in Table 1 of this AD. The service bulletins refer to Goodrich Actuation Systems Service Bulletin 47142-27-11, Revision 3, dated April 25, 2005, as an additional source of service information for the required actions.

**Table 1.–Service Bulletins**

| <b>Required Airbus Service Bulletin</b>              | <b>Approved Airbus service bulletin version for actions done before the effective date of this AD</b> | <b>Airbus airplane model</b>  |
|--|---|---|
| A300–27–6044, Revision 04, dated September 10, 2001. | A300–27–6044, Revision 02, dated August 26, 2000; or Revision 03, dated June 28, 2001.                | A300 B4–601, B4–603, B4–620, and B4–622.<br>A300 B4–605R and B4–622R.<br>A300 F4–605R and F4–622R.<br>A300 C4–605R Variant F. |
| A310–27–2089, Revision 02, dated June 28, 2001.      | A310–27–2089, Revision 01, dated August 25, 2000  | A310–203, –204, –221, and –222.<br>A310–304, –322, –324, and –325.  |

### Inspection

(g) At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD, do a detailed inspection of specified components of the THSA in accordance with paragraph 1.E.(2)(a) and the Accomplishment Instructions of the applicable service bulletin. Repair any discrepancy before further flight in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent). TRW Aeronautical Systems/Lucas Aerospace Component Maintenance Manual 27-44-13, dated September 14, 2001, is one acceptable method for the repair.

(1) If the flight hours accumulated on the THSA can be positively determined: Inspect at the earlier of:

(i) Before the accumulation of 47,000 total flight hours on the THSA, or within 600 flight hours after the effective date of this AD, whichever occurs later.

(ii) Within 25 years since the THSA was new or within 600 flight hours after the effective date of this AD, whichever occurs later.

(2) If the flight hours accumulated on the THSA cannot be positively determined: Inspect before the accumulation of 47,000 total flight hours on the airplane, or within 600 flight hours after the effective date of this AD, whichever occurs later.

**Note 1:** For the purposes of this AD, a detailed inspection is: “An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.”

### Follow-on Repetitive Tasks

(h) After the inspection required by paragraph (g) of this AD: Do the repetitive tasks in accordance with the Accomplishment Instructions and at the times specified in paragraph 1.E.(2)(b) of the service bulletin, as applicable, except as provided by paragraph (i) of this AD. The repetitive tasks are valid only until the THSA operational life exceeds 65,000 flight hours, 40,000 flight cycles, or 25 years, whichever occurs first. Before the THSA is operated beyond these extended life goals, it must be replaced with a new THSA, except as required by paragraph (i) of this AD.

## **THSA Replacement**

(i) For any THSA, whether discrepant or not, that is replaced with a new THSA: Within 47,000 flight hours or 25 years, whichever occurs first, after the THSA is replaced, do the applicable tasks specified in paragraph 1.E.(2)(a) and the Accomplishment Instructions of the applicable service bulletin. Thereafter repeat the tasks within the repetitive intervals specified in paragraph 1.E.(2)(b) of the applicable service bulletin.

## **Alternative Methods of Compliance (AMOCs)**

(j)(1) The Manager, International Branch, ANM-116, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

## **Related Information**

(k) French airworthiness directive 2001-242(B), dated June 27, 2001, also addresses the subject of this AD.

## **Material Incorporated by Reference**

(l) You must use Airbus Service Bulletin A300-27-6044, Revision 04, dated September 10, 2001; and Airbus Service Bulletin A310-27-2089, Revision 02, dated June 28, 2001; as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 14, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-11700 Filed 7-24-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-11 Construcciones Aeronauticas, S.A. (CASA):** Amendment 39-14691. Docket No. FAA-2005-22504; Directorate Identifier 2003-NM-281-AD.

## Effective Date

- (a) This AD becomes effective August 29, 2006.

## Affected ADs

- (b) None.

## Applicability

(c) This AD applies to CASA Model C-212-CC airplanes, certificated in any category, modified in accordance with Supplemental Type Certificate (STC) ST02177AK, or by field approval using STC ST02177AK as a basis for the field approval.

## Unsafe Condition

(d) This AD was prompted by our determination that affected airplanes, when carrying both cargo and passengers in the same compartment, cannot achieve the required level of performance. We are issuing this AD to prevent a hazardous quantity of smoke, flames, and/or fire extinguishing agent from the cargo compartment from entering a compartment occupied by passengers or crew.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Modification

(f) As of 12 months after the effective date of this AD, no person may operate an airplane in the combi configuration, unless the actions specified by either paragraph (f)(1) or (f)(2) are done in accordance with a method approved by the Manager, Anchorage Aircraft Certification Office (ACO), FAA.

(1) Modify the airplane to incorporate a protective liner between the passengers and the cargo and to ensure compliance with § 25.855 ("Cargo or baggage compartment") of the Federal Aviation Regulations (14 CFR 25.855).

(2) Comply with the terms and conditions specified in paragraphs (f)(2)(i) through (f)(2)(vi) of this AD.

(i) There are means to extinguish or control a fire without requiring a crewmember to enter the compartment.

(ii) There are means to exclude hazardous quantities of smoke, flames, or extinguishing agent from any compartment occupied by the crew or passengers.

(iii) There is a separate approved smoke detector or fire detector system to give warning at the pilot or flight engineer station.

(iv) Crew members must receive training in the use of the fire extinguishers and the cargo fire containment covers; they must also receive training in the use of the approved procedure for the elimination of smoke and fumes that is specified in the airplane flight manual (AFM).

(v) Two additional fire extinguishers must be carried on the airplane.

(vi) Limitations (f)(2)(i) through (f)(2)(v) must be documented as operating limitations in the Limitations section of the CASA C-212-CC AFM supplement.

### **Special Flight Permits**

(g) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be modified (if the operator elects to do so), provided no passengers are onboard.

### **Alternative Methods of Compliance (AMOCs)**

(h)(1) The Manager, Anchorage ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### **Material Incorporated by Reference**

(i) None.

Issued in Renton, Washington, on July 14, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-11701 Filed 7-24-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-12 Construcciones Aeronauticas, S.A. (CASA):** Amendment 39-14692. Docket No. FAA-2005-22505; Directorate Identifier 2003-NM-283-AD.

## Effective Date

- (a) This AD becomes effective August 29, 2006.

## Affected ADs

- (b) None.

## Applicability

(c) This AD applies to CASA Model C-212-CC airplanes, certificated in any category, modified in accordance with Supplemental Type Certificate (STC) ST02129AK, or by field approval using STC ST02129AK as a basis for the field approval.

## Unsafe Condition

(d) This AD was prompted by our determination that affected airplanes, when carrying both cargo and passengers in the same compartment, cannot achieve the required level of performance. We are issuing this AD to prevent a hazardous quantity of smoke, flames, and/or fire extinguishing agent from the cargo compartment from entering a compartment occupied by passengers or crew.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Modification

(f) As of 12 months after the effective date of this AD, no person may operate an airplane in the combi configuration, unless the actions specified by either paragraph (f)(1) or (f)(2) are done in accordance with a method approved by the Manager, Anchorage Aircraft Certification Office (ACO), FAA.

(1) Modify the airplane to incorporate a protective liner between the passengers and the cargo and to ensure compliance with section 25.855 ("Cargo or baggage compartment") of the Federal Aviation Regulations (14 CFR 25.855).

(2) Comply with the terms and conditions specified in paragraphs (f)(2)(i) through (f)(2)(vi) of this AD.

(i) There are means to extinguish or control a fire without requiring a crewmember to enter the compartment.

(ii) There are means to exclude hazardous quantities of smoke, flames, or extinguishing agent from any compartment occupied by the crew or passengers.

(iii) There is a separate approved smoke detector or fire detector system to give warning at the pilot or flight engineer station.

(iv) Crew members must receive training in the use of the fire extinguishers and the cargo fire containment covers; they must also receive training in the use of the approved procedure for the elimination of smoke and fumes that is specified in the airplane flight manual (AFM).

(v) Two additional fire extinguishers must be carried on the airplane.

(vi) Limitations (f)(2)(i) through (f)(2)(v) must be documented as operating limitations in the Limitations section of the CASA C-212-CC AFM supplement.

### **Special Flight Permits**

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be modified (if the operator elects to do so), provided no passengers are onboard.

### **Alternative Methods of Compliance (AMOCs)**

(h)(1) The Manager, Anchorage ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with 14 CFR 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### **Material Incorporated by Reference**

(i) None.

Issued in Renton, Washington, on July 14, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-11706 Filed 7-24-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-13 McCauley Propeller Systems:** Amendment 39-14693. Docket No. FAA-2006-25173; Directorate Identifier 2006-NE-24-AD.

## Effective Date

(a) This airworthiness directive (AD) becomes effective August 10, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to McCauley Propeller Systems propeller models B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0. These propellers are installed on BAE Systems (Operations) Limited Jetstream Model 4100 and 4101 series airplanes (Jetstream 41).

## Unsafe Condition

(d) This AD results from a report of two propeller blades on the same propeller assembly, found cracked during propeller overhaul. We are issuing this AD to detect cracks in the propeller blade that could cause failure and separation of the propeller blade and loss of control of the airplane.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

## Onetime Propeller Blade Inspection

(f) Perform a onetime fluorescent penetrant inspection and eddy current inspection of propeller blades, using the Equipment Required and Accomplishment Instructions of McCauley Propellers Alert Service Bulletin ASB252, dated June 6, 2006, using the following compliance schedule:

**Table 1.–Compliance Schedule**

| <b>If the propeller blade:</b>  | <b>Then inspect the propeller blade:</b>                            |
|---|---|
| (1) Has 1,200 operating hours or more time-in-service (TIS) and has not reached first overhaul. | Within 100 operating hours TIS after the effective date of this AD. |
| (2) Has 1,000 operating hours or more TIS since last overhaul                                   | Within 100 operating hours TIS after the effective date of this AD. |
| (3) Has fewer than 1,200 operating hours TIS  | Before the propeller blade reaches 1,300 operating hours TIS.       |
| (4) Has been overhauled but has fewer than 1,000 operating hours time-since-overhaul (TSO).     | Upon reaching 1,100 operating hours TSO.                            |

**Propeller Blades Found Cracked**

(g) Remove from service propeller blades found with any crack indications.

**Reporting Requirements**

(h) Within 10 calendar days of the inspection, use the Reporting Form for Service Bulletin 252 to report all inspection findings to:

(1) The FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, KS 67209, Attention: Jeff Janusz, telephone (316) 946-4148; FAX (316) 946-4107, e-mail: jeff.janusz@faa.gov; and

(2) McCauley Propeller Systems, 7751 East Pawnee, Wichita, KS 67277.

(3) The Office of Management and Budget (OMB) has approved the reporting requirements and assigned OMB control number 2120-0056.

**Alternative Methods of Compliance**

(i) The Manager, Wichita Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

**Special Flight Permits**

(j) Under 39.23, we are limiting the availability of special flight permits for this AD. Special flight permits are available only if:

(1) The operator has not seen signs of external oil leakage from the hub; and

(2) The operator has not observed abnormal propeller vibration or abnormal engine vibration; and

(3) The operator has not observed any other abnormal operation from the engine or propeller; and

(4) The operator has not made earlier reports of abnormal propeller vibration, abnormal engine vibration, or other abnormal engine or propeller operations, that have not been addressed.

**Related Information**

(k) None.

**Material Incorporated by Reference**

(1) You must use McCauley Propeller Systems Alert Service Bulletin ASB252, dated June 6, 2006, to perform the inspections required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact McCauley Propeller Systems, 7751 East Pawnee, Wichita, KS 67277, for a copy of this service information. You may review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on July 18, 2006.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-11799 Filed 7-25-06; 8:45 am]



**2006-15-15 McDonnell Douglas:** Amendment 39-14696. Docket 2001-NM-387-AD.

Applicability: Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 airplanes; certificated in any category; as identified in Boeing Alert Service Bulletin MD80-29A070, Revision 1, dated July 28, 2005.

Compliance: Required as indicated, unless accomplished previously.

To prevent shorted wires or arcing at the auxiliary hydraulic pump, which could result in loss of auxiliary hydraulic power, or a fire in the wheel well of the airplane; and to reduce the potential of an ignition source adjacent to the fuel tanks, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane; accomplish the following:

## One-Time Inspection

(a) For airplanes in Configurations 1 through 4, as defined in Boeing Alert Service Bulletin MD80-29A070, Revision 1, dated July 28, 2005: Within 18 months after the effective date of this AD, do a one-time general visual inspection for chafing or signs of arcing of the wire bundle for the auxiliary hydraulic pump, and do all applicable corrective and other specified actions, in accordance with the Accomplishment Instructions of the service bulletin. Accomplish all applicable corrective actions before further flight after the inspection.

**Note 1:** For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

## Installation of Additional Wiring Protection

(b) For airplanes in Configuration 4, as defined in Boeing Alert Service Bulletin MD80-29A070, Revision 1, dated July 28, 2005: Within 18 months after the effective date of this AD, install additional protective sleeving on the upper portion of the auxiliary hydraulic pump wire assembly in accordance with the procedures under Configuration 4 in the Accomplishment Instructions of the service bulletin.

## Actions Accomplished Previously

(c) Actions accomplished before the effective date of this AD in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD80-29A070, dated August 3, 2004, are acceptable for compliance with paragraph (a) of this AD, except that the additional requirements of paragraph (b) of this AD must be done on airplanes in Configuration 4, as defined in Boeing Alert Service Bulletin MD80-29A070, Revision 1, dated July 28, 2005.

### **Alternative Methods of Compliance**

(d)(1) In accordance with 14 CFR 39.19, the Manager, Los Angeles Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### **Incorporation by Reference**

(e) Unless otherwise specified in this AD, the actions must be done in accordance with Boeing Alert Service Bulletin MD80-29A070, Revision 1, dated July 28, 2005. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get copies of this service information, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). To inspect copies of this service information, go to the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; to the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or to the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

### **Effective Date**

(f) This amendment becomes effective on September 5, 2006.

Issued in Renton, Washington, on July 20, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-12094 Filed 7-28-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-16 Raytheon Aircraft Company (Formerly Beech):** Amendment 39-14697. Docket No. FAA-2006-24694; Directorate Identifier 2006-NM-018-AD.

## Effective Date

(a) This AD becomes effective September 5, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to the airplanes identified in Table 1 of this AD, certificated in any category.

**Table 1.—Applicability**

| <b>Raytheon (Beech)<br/>model—</b> | <b>Serials—</b>                 | <b>On which—</b>   |
|------------------------------------|---------------------------------|--|
| (1) 400 series                     | RJ-1 through<br>RJ-65 inclusive | Kit part number (P/N) 128-3004-1 P or 128-3004-3 P has been incorporated (Lucas Aerospace/Goodrich Direct Current (DC) Starter Generator). |
| (2) 400A series<br>airplanes       | RK-1 through<br>RK-23 inclusive | Kit P/N 128-3004-1 P or 128-3004-3 P has been incorporated (Lucas Aerospace/Goodrich DC Starter Generator).                                |

## Unsafe Condition

(d) This AD results from reports of over-voltage conditions of the DC starter generator. We are issuing this AD to prevent over-voltage conditions of the DC starter generator due to the incompatibility between certain generator control units (GCUs), which could result in the loss of normal electrical power, damage to some electrical components, or blown fuses during flight, and consequent unrecoverable loss of some or all essential equipment.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Service Bulletin

(f) The term “service bulletin,” as used in this AD, means the Accomplishment Instructions of Raytheon Service Bulletin SB 24-3713, dated November 2005.

## Review of Logbook

(g) Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, review the airplane logbook to determine whether GCU installation kit, P/N 128-3001-1 P or 128-3001-3 P, is installed, in accordance with the service bulletin.

### Installation Kit Not Found Installed: Replacement of Shinko GCUs

(h) If no GCU installation kit, P/N 128-3001-1 P or 128-3001-3 P, is found installed or if the kit P/N cannot be conclusively determined during the review required by paragraph (g) of this AD: Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, replace the Shinko GCUs with new Lucas Aerospace/Goodrich GCUs (installation kit P/N 128-3001-1 P or 128-3001-3 P), in accordance with the service bulletin.

### Installation Kit Found Installed: Inspections of GCUs and Current Sense Transformers and Replacement of Transformers as Applicable

(i) If any GCU installation kit, P/N 128-3001-1 P or 128-3001-3 P is found installed during the review required by paragraph (g) of this AD: Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, inspect to determine the P/N of both GCUs, in accordance with the service bulletin; and at the times specified in Table 2 of this AD, do the applicable action(s) in that table.

**Table 2.—Inspection and Replacement of Current Sense Transformers**

| <b>If—</b>  | <b>Then, within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first—</b>  | <b>If—</b>  | <b>Then—</b>  |
|---|--|---|---|
| (1) Both GCUs have P/N 45AS88801-19 or -25.           | Inspect to determine the P/N of both current sense transformers on the lower inboard quadrant of the left-hand and right-hand engine inlets, in accordance with the service bulletin.  | Both current sense transformers have P/N 45AS88801-21.                    | No further action is required by this AD.   |
|   |  | Either current sense transformer is not identified with P/N 45AS88801-21. | Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, replace the current sense transformer with a new transformer, P/N 45AS88801-21, in accordance with the service bulletin. |
| (2) Either GCU does not have P/N 45AS88801-19 or -25. | Replace the GCU with a new GCU, P/N 45AS88801-19 or -25, and inspect to determine the P/N of both current sense transformers on the lower inboard quadrant of the left-hand and right-hand engine inlets, in accordance with the service bulletin. | Both current sense transformers have P/N 45AS88801-21.                    | No further action is required by this AD.   |
|   |  | Either current sense transformer is not identified with P/N 45AS88801-21. | Within 200 flight hours or 6 months after the effective date of this AD, whichever occurs first, replace the current sense transformer with a new transformer, P/N 45AS88801-21, in accordance with the service bulletin. |

**Alternative Methods of Compliance (AMOCs)**

(j)(1) The Manager, Wichita Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

**Material Incorporated by Reference**

(k) You must use Raytheon Service Bulletin SB 24-3713, dated November 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 20, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-12107 Filed 7-28-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-17 Fokker Services B.V.:** Amendment 39-14698. Docket No. FAA-2006-24868;  
Directorate Identifier 2006-NM-103-AD.

## Effective Date

(a) This AD becomes effective September 5, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to all Fokker Model F.28 Mark 0070 and 0100 airplanes, certificated in any category.

## Unsafe Condition

(d) This AD results from a report of electrical sparks coming out of the flight deck from a panel behind the left seat. We are issuing this AD to prevent failure of the sliding window heating element(s), due to electrical overload, which could result in smoke and fire in the cockpit.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Modification of Wiring Distribution

(f) Within 36 months after the effective date of this AD, modify the wiring distribution of the alternating current bus transfer power system and the right-hand and left-hand windshield anti-icing system, by accomplishing all of the actions specified in the Accomplishment Instructions of Fokker Service Bulletin SBF100-30-027, dated May 9, 2005, as applicable; including Fokker Manual Change Notification–Maintenance Documentation MCNM F100-098, dated May 9, 2005, and the drawings listed in Table 1 of this AD. (To conform to certain Office of the Federal Register requirements for incorporating these materials by reference, the table identifies the date of the service bulletin for undated drawings.)

**Table 1.–Drawings Included in Fokker Service Bulletin SBF100-30-027**

| <b>Fokker drawing</b> | <b>Sheet</b> | <b>Issue</b> | <b>Date</b>  |
|-----------------------|--------------|--------------|--------------|
| W41043                | 007          | H            | May 9, 2005. |
| W41043                | 008          | H            | May 9, 2005. |
| W41249                | 006          | F            | May 9, 2005. |
| W41249                | 007          | F            | May 9, 2005. |
| W41249                | 008          | F            | May 9, 2005. |
| W41249                | 009          | G            | May 9, 2005. |
| W41249                | 010          | G            | May 9, 2005. |

### **Alternative Methods of Compliance (AMOCs)**

(g)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### **Related Information**

(h) Dutch airworthiness directive NL-2005-009, dated June 30, 2005, also addresses the subject of this AD.

### **Material Incorporated by Reference**

(i) You must use Fokker Service Bulletin SBF100-30-027, dated May 9, 2005; including Fokker Manual Change Notification–Maintenance Documentation MCNM F100-098, dated May 9, 2005; and the Fokker drawings identified in Table 2 of this AD; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA).

For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

**Table 2.–Attached Drawings Incorporated by Reference**

| <b>Fokker drawing</b> | <b>Sheet</b> | <b>Issue</b> | <b>Date</b>  |
|-----------------------|--------------|--------------|--------------|
| W41043                | 007          | H            | May 9, 2005. |
| W41043                | 008          | H            | May 9, 2005. |
| W41249                | 006          | F            | May 9, 2005. |
| W41249                | 007          | F            | May 9, 2005. |
| W41249                | 008          | F            | May 9, 2005. |
| W41249                | 009          | G            | May 9, 2005. |
| W41249                | 010          | G            | May 9, 2005. |

Issued in Renton, Washington, on July 20, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-12092 Filed 7-28-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-15-18 Boeing:** Amendment 39-14699. FAA-2004-19245; Directorate Identifier 2004-NM-108-AD.

## Effective Date

(a) This AD becomes effective September 5, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to Boeing Model 737-300, -400, and -500 series airplanes identified in Boeing Special Attention Service Bulletin 737-33-1132, Revision 2, dated September 8, 2005; and Model 737-600, -700, -700C, -800, and -900 series airplanes identified in Boeing Service Bulletin 737-33-1133, Revision 3, dated September 8, 2005; certificated in any category.

## Unsafe Condition

(d) This AD results from a report that the master dim and test system circuit does not have wiring separation of the test ground signal for redundant equipment in the flight compartment. We are issuing this AD to prevent a single fault failure in flight from simulating a test condition and showing test patterns instead of the selected radio frequencies on the communications panels, which could inhibit communication between the flightcrew and the control tower, affecting the continued safe flight of the airplane.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Modification

(f) Within 48 months after the effective date of this AD: Modify the wiring for the master dim test system in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-33-1132, Revision 2, dated September 8, 2005 (for Model 737-300, -400, and -500 series airplanes); and Boeing Service Bulletin 737-33-1133, Revision 3, dated September 8, 2005 (for Model 737-600, -700, -700C, -800, and -900 series airplanes); as applicable.

## Actions Required To Be Accomplished Prior to or Concurrently With Paragraph (f) of This AD

(g) Prior to or concurrently with accomplishment of paragraph (f) of this AD, do the actions specified in Table 1 of this AD, as applicable.

**Table 1.–Prior/Concurrent Actions**

| <b>For—</b>  | <b>Accomplish all actions associated with—</b>   | <b>According to the Accomplishment Instructions of—</b>                   |
|--|--|---|
| Group 57 airplanes identified in Boeing Special Attention Service Bulletin 737–33–1132, Revision 2, dated September 8, 2005. | Installing an engine instrument system (EIS) and   | Boeing Service Bulletin 737–77–1022, Revision 1, dated October 26, 1989.  |
|  | Modifying the advisory system for the EIS  | Boeing Service Bulletin 737–77–1023, Revision 1, dated November 9, 1989.  |
| Group 37 and 46 airplanes identified in Boeing Service Bulletin 737–33–1133, Revision 3, dated September 8, 2005.            | Installing wiring for the test system for the audio control panel lamp.  | Boeing Service Bulletin 737–33–1121, Revision 1, dated December 19, 2002. |
| Group 2 airplanes identified in Boeing Service Bulletin 737–33–1121, Revision 1, dated December 19, 2002.                    | Installing splice SP896  | Boeing Service Bulletin 737–26A1083, Revision 1, dated November 15, 2001. |
| Group 39 airplanes identified in Boeing Service Bulletin 737–33–1133, Revision 3, dated September 8, 2005.                   | Installing a smoke detection and fire extinguishing system in the cargo compartment.                             | Boeing Service Bulletin 737–26A1083, Revision 1, dated November 15, 2001. |
| Group 59 airplanes identified in Boeing Special Attention Service Bulletin 737–33–1132, Revision 2, dated September 8, 2005. | Replacing the very high frequency (VHF) and high frequency (HF) communications panels with radio control panels. | Boeing Service Bulletin 737–23–1102, dated June 3, 1999.                  |

**Actions Accomplished per Previous Issue of Service Bulletins**

(h) Actions accomplished before the effective date of this AD in accordance with the service bulletins identified in Table 2 of this AD are considered acceptable for compliance with the corresponding actions specified in this AD.

**Table 2.–Previous Issues of Service Bulletins**

| <b>Service Bulletin</b>                               | <b>Revision level</b> | <b>Date</b>        |
|---|-----------------------|--------------------|
| Boeing Special Attention Service Bulletin 737–33–1133 | Original              | December 19, 2002. |
| Boeing Service Bulletin 737–33–1133                   | Revision 1            | April 17, 2003.    |
| Boeing Service Bulletin 737–33–1133                   | Revision 2            | December 4, 2003.  |
| Boeing Special Attention Service Bulletin 737–33–1132 | Original              | March 20, 2003.    |
| Boeing Special Attention Service Bulletin 737–33–1132 | Revision 1            | March 4, 2004.     |

**Alternative Methods of Compliance (AMOCs)**

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

**Material Incorporated by Reference**

(j) You must use the service information identified in Table 3 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

**Table 3.—Material Incorporated by Reference**

| <b>Service Bulletin</b>                               | <b>Revision level</b> | <b>Date</b>        |
|---|-----------------------|--------------------|
| Boeing Service Bulletin 737-23-1102                   | Original              | June 3, 1999.      |
| Boeing Service Bulletin 737-26A1083                   | 1                     | November 15, 2001. |
| Boeing Service Bulletin 737-33-1121                   | 1                     | December 19, 2002. |
| Boeing Service Bulletin 737-33-1133                   | 3                     | September 8, 2005. |
| Boeing Service Bulletin 737-77-1022                   | 1                     | October 26, 1989.  |
| Boeing Service Bulletin 737-77-1023                   | 1                     | November 9, 1989.  |
| Boeing Special Attention Service Bulletin 737-33-1132 | 2                     | September 8, 2005. |

Boeing Service Bulletin 737-77-1022, Revision 1, dated October 26, 1989, contains the following effective pages:

| <b>Page No.</b>            | <b>Revision level shown on page</b> | <b>Date shown on page</b> |
|----------------------------|-------------------------------------|---------------------------|
| 1, 3, 5-7, 10, 17, 28-55.  | Revision 1                          | Oct. 26, 1989.            |
| 2, 4, 8, 9, 11- 16, 18-27. | Original                            | June 15, 1989.            |

The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 20, 2006.  
 Ali Bahrami,  
 Manager, Transport Airplane Directorate, Aircraft Certification Service.  
 [FR Doc. E6-12099 Filed 7-28-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-16-01 Hamilton Sundstrand:** Amendment 39-14701. Docket No. FAA-2005-21691;  
Directorate Identifier 2005-NE-13-AD.

## Effective Date

- (a) This airworthiness directive (AD) becomes effective August 15, 2006.

## Affected ADs

- (b) This AD supersedes AD 2006-12-19.

## Applicability

(c) This AD applies to Hamilton Sundstrand Model 14RF-19 propellers with propeller system actuator yoke arms, part number (P/N) 810436-2, which might be installed in actuator assemblies P/N 790199-6. These propellers are installed on, but not limited to, SAAB 340 airplanes.

## Unsafe Condition

(d) This AD results from the discovery of a part number (P/N) error in the applicability paragraph of AD 2006-12-19. We are issuing this AD to prevent actuator yoke arms breaking during flight, which could cause high propeller vibration and contribute to reduced controllability of the airplane.

## Compliance

(e) You are responsible for having the actions required by this AD performed within 60 days after the effective date of this AD, unless the actions have already been done.

## Install Improved Actuator Yoke Arms

(f) Using the Accomplishment Instructions of Hamilton Sundstrand Service Bulletin 14RF-19-61-113, Revision 1, dated September 2, 2003, replace all actuator yoke arms, P/N 810436-2, with improved actuator yoke arms, P/N 810436-3.

(g) Mark newly installed actuators using the Accomplishment Instructions of Hamilton Sundstrand Service Bulletin 14RF-19-61-113, Revision 1, dated September 2, 2003.

(h) After the effective date of this AD, do not install any actuator yoke arms, P/N 810436-2, into any propeller assembly.

## Alternative Methods of Compliance

(i) The Manager, Boston Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

## **Related Information**

(j) None.

## **Material Incorporated by Reference**

(k) You must use Hamilton Sundstrand Service Bulletin 14RF-19-61-113, Revision 1, dated September 2, 2003, to perform the replacements and marking required by this AD. The Director of the Federal Register previously approved the incorporation by reference of this service bulletin as of July 18, 2006 (71 FR 34003; June 13, 2006) in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Hamilton Sundstrand, A United Technologies Company, Publication Manager, Mail Stop 1A-3-Z63, One Hamilton Road, Windsor Locks, CT 06096; fax 1-860-654-5107, for a copy of this service information. You may review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on July 24, 2006.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-12109 Filed 7-28-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-16-02 McDonnell Douglas:** Amendment 39-14702. Docket No. FAA-2006-24786; Directorate Identifier 2006-NM-087-AD.

## Effective Date

(a) This AD becomes effective September 7, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to McDonnell Douglas Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 airplanes, certificated in any category; as identified in Boeing Service Bulletin MD80-28-213, dated May 16, 2005.

## Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent arcing on the in-tank side of the fueling valve during a lightning strike, which could result in an ignition source that could ignite fuel vapor and cause a fuel tank explosion.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Electrical Bond Installation

(f) Within 60 months after the effective date of this AD, install a clamp, a bonding jumper assembly, and attaching hardware to the refueling manifold in the right wing refueling station area; in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD80-28-213, dated May 16, 2005.

## Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

## **Material Incorporated by Reference**

(h) You must use Boeing Service Bulletin MD80-28-213, dated May 16, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal-register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal-register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 21, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-12298 Filed 8-2-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-16-03 McDonnell Douglas:** Amendment 39-14703. Docket No. FAA-2006-24780; Directorate Identifier 2006-NM-069-AD.

## Effective Date

(a) This AD becomes effective September 7, 2006.

## Affected ADs

(b) None.

## Applicability

(c) This AD applies to McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F airplanes, certificated in any category; as identified in the applicable service bulletin listed in Table 1 of this AD.

**Table 1.—Service Bulletins**

| <b>McDonnell Douglas<br/>DC-10 Service Bulletin</b> | <b>Revision<br/>Level</b> | <b>Date</b>     | <b>For airplanes with –</b>           |
|---|---------------------------|-----------------|---------------------------------------|
| 53-109  | 4                         | October 7, 1992 | Extended wing-to-fuselage fillets     |
| 53-111  | 3                         | August 24, 1992 | Conventional wing-to-fuselage fillets |

## Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to reduce the potential of ignition sources inside fuel tanks in the event of a severe lightning strike, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Installation or Replacement

(f) Within 7,500 flight hours or 60 months after the effective date of this AD, whichever occurs earlier: Install or replace with improved parts, as applicable, the bonding straps between the metallic frame of the fillet and the wing leading edge ribs, on both the left and right sides of the airplane, in accordance with the Accomplishment Instructions of the applicable service bulletin identified in Table 1 of this AD.

### **Alternative Methods of Compliance (AMOCs)**

(g)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

### **Material Incorporated by Reference**

(h) You must use McDonnell Douglas DC-10 Service Bulletin 53-109, Revision 4, dated October 7, 1992; or McDonnell Douglas DC-10 Service Bulletin 53-111, Revision 3, dated August 24, 1992; as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 21, 2006.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-12299 Filed 8-2-06; 8:45 am]

# AIRWORTHINESS DIRECTIVE

[www.faa.gov/aircraft/safety/alerts/](http://www.faa.gov/aircraft/safety/alerts/)  
[www.gpoaccess.gov/fr/advanced.html](http://www.gpoaccess.gov/fr/advanced.html)

U.S. Department  
of Transportation  
**Federal Aviation  
Administration**



**2006-16-05 Pratt & Whitney:** Amendment 39-14705. Docket No. 97-ANE-44-AD.

## Effective Date

- (a) This AD becomes effective September 8, 2006.

## Affected ADs

- (b) This AD supersedes AD 2000-16-02R1.

## Applicability

(c) This AD applies to Pratt & Whitney (PW) PW4164, PW4168, and PW4168A series turbofan engines, with front pylon mount bolts, part number (P/N) 54T670 or 51U615, installed. These engines are installed on, but not limited to, Airbus A330 series airplanes.

## Unsafe Condition

(d) This AD results from analysis by the manufacturer that MP159 material pylon bolts do not meet the full life cycle torque check interval requirement, in a bolt-out condition. We are issuing this AD to prevent front pylon mount bolt and primary mount thrust load path failure, which could result in an engine separating from the airplane.

## Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

## INCO 718 Material Bolts Torque Checks

(f) Perform initial and repetitive torque checks of INCO 718 material front pylon mount bolts, P/N 54T670, and replace, if necessary, with new bolts, using the Accomplishment Instructions of PW Alert Service Bulletin (ASB) PW4G-100-A71-9, Revision 1, dated November 24, 1997, as follows:

(1) For front pylon mount bolts, P/N 54T670, with fewer than 1,000 cycles-since-new (CSN) on the effective date of this AD, do the following using Part (A) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check before accumulating 1,250 CSN or at the next engine removal for cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 cycles-in-service (CIS) since last torque check.

(2) For front pylon mount bolts, P/N 54T670, with 1,000 CSN or more but fewer than 5,750 CSN on the effective date of this AD, do the following using Part (A) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or at the next engine removal for any cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 CIS since last torque check.

(3) For front pylon mount bolts, P/N 54T670, with 5,750 CSN or more on the effective date of this AD, do the following using Part (B) of the Accomplishment Instructions of the ASB:

(i) Perform an initial torque check within 250 CIS after the effective date of this AD, or before the next engine removal for any cause, whichever occurs sooner.

(ii) Thereafter, perform torque checks at intervals of no fewer than 750 or no more than 1,250 CIS since last torque check.

(4) Remove from service front pylon mount bolts P/N 54T670, at or before reaching the life limit of 11,000 CSN.

(5) Before further flight, replace all four bolts using Part (A), Paragraph 1(D) of the Accomplishment Instructions of the ASB, if any of the bolts are loose or broken.

### **MP159 Material Bolts Inspections**

(g) Perform initial and repetitive torque checks of front pylon mount bolts, P/N 51U615, using the Accomplishment Instructions of PW ASB PW4G-100-A71-32, dated April 15, 2005, as follows:

(1) For front pylon mount bolts with fewer than 2,200 CSN on the effective date of this AD, perform the initial torque inspection before accumulating 2,700 CSN, or at the next engine removal for any cause, whichever occurs sooner.

(2) For front pylon mount bolts with 2,200 CSN or more on the effective date of this AD, perform the initial torque check within the next 500 CIS, or at the next engine removal for any cause, whichever occurs sooner.

(3) Thereafter, perform torque inspections at intervals not to exceed 2,700 CIS since last torque inspection.

(4) Before further flight, replace all four bolts using Paragraph 1.E. of the Accomplishment Instructions of the ASB, if any are loose or broken.

### **Primary Mount Thrust Load Path Inspections**

(h) Perform initial and repetitive visual inspections of the primary mount thrust load path using the Accomplishment Instructions of PW ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002, as follows:

(1) For forward engine mount assemblies with fewer than 1,000 CSN on the effective date of this AD, perform the initial visual inspection at the earlier of the following:

(i) Before accumulating 1,250 CSN; or

(ii) The next engine removal for any cause.

(2) For forward engine mount assemblies with 1,000 CSN or more on the effective date of this AD, perform the initial visual inspection within 250 CIS after the effective date of this AD, or the next engine removal for any cause, whichever occurs sooner.

(3) Thereafter, perform visual inspections at intervals of no fewer than 750 or no more than 1,250 CIS since-last-visual-inspection.

(4) Before further flight, replace all cracked parts with serviceable parts and inspect the primary thrust load path components using Paragraph 4 of the Accomplishment Instructions of the ASB.

**Terminating Action**

(i) Replacement of the forward engine mount bearing housing, P/N 59T794 or P/N 54T659 with P/N 52U420, using SB PW4G-100-71-22, dated January 15, 2002, constitutes terminating action to the inspection requirements of paragraph (h) of this AD.

**Alternative Methods of Compliance**

(j) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

**Related Information**

(k) None.

**Material Incorporated by Reference**

(l) You must use the Pratt & Whitney service information specified in Table 1 of this AD to perform the actions required by this AD. The Director of the Federal Register approved the incorporation by reference of Pratt & Whitney Alert Service Bulletin (ASB) PW4G-100-A71-32, dated April 15, 2005, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. The Director of the Federal Register previously approved the incorporation by reference of Pratt & Whitney ASB PW4G-100-A71-9, Revision 1, dated November 24, 1997, as of October 16, 2000, and, ASB PW4G-100-A71-18, Revision 2, dated January 15, 2002, and ASB PW4G-100-71-22, dated January 15, 2002, as of February 6, 2003. Contact Pratt & Whitney, 400 Main St., East Hartford, CT 06108; telephone (860) 565-7700, fax (860) 565-1605 for the service information identified in this AD. You may review copies at the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001, on the Internet at <http://dms.dot.gov>, or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**Table 1 – Incorporation by Reference**

| <b>Alert Service Bulletin (ASB) or Service Bulletin (SB) No.</b> | <b>Page</b> | <b>Revision</b> | <b>Date</b>        |
|--|-------------|-----------------|--------------------|
| ASB PW4G-100-A71-9   | 1           | 1               | November 24, 1997  |
|  | 2           | Original        | July 31, 1997      |
|  | 3           | 1               | November 24, 1997  |
|  | 4-7         | Original        | July 31, 1997      |
|  | 8-9         | 1               | November 24, 1997  |
| Total Pages: 11  | 10-11       | Original        | July 31, 1997      |
| ASB PW4G-100-A71-18  | 1-2         | 2               | January 15, 2002   |
|  | 3           | 1               | December 9, 1999   |
|  | 4           | 2               | January 15, 2002   |
|  | 5-6         | Original        | September 15, 1999 |
|  | 7           | 2               | January 15, 2002   |
| Total Pages: 12  | 8-12        | Original        | September 15, 1999 |
| SB PW4G-100-71-22  | ALL         | Original        | January 15, 2002   |
| Total Pages: 8   |             |                 |                    |
| ASB PW4G-100-A71-32  | ALL         | Original        | April 15, 2005     |
| Total Pages: 9   |             |                 |                    |

Issued in Burlington, Massachusetts, on July 27, 2006.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-12564 Filed 8-3-06; 8:45 am]