

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2015-26**

12/14/2015 - 12/27/2015



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2015-01			
2014-26-03		Saab AB, Saab Aerosystems	340B
Biweekly 2015-02			
2014-25-51		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-25-52		Airbus	A330-223F, -243F, A330-201, -202, -203, -223, -243, A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, -313, A340-541 and A340-642
2014-26-06		ATR–GIE Avions de Transport Régional	ATR42-500 and ATR72-212A
2014-26-07		Dassault Aviation	FAN JET FALCON and FAN JET FALCON SERIES C, D, E, F, and G
2014-26-09	R 2014-03-05	Bombardier, Inc.	BD-700-1A10
2014-26-10		Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-53		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-01-01	R 2011-09-11	The Boeing Company	777-200 and -300 series
Biweekly 2015-03			
2014-23-15	R 2011-14-06	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2014-26-08	R 2011-13-09	Airbus	A330-201, -202, -203, -223, -223F -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2015-02-02		Bombardier, Inc	CL-215-6B11 (CL-215T Variant), CL-215-6B11 (CL-415 Variant)
2015-02-03		Airbus	A300 B4-601, B4-603, B4-605R, F4-605R, and C4-605R Variant F
2015-02-04		Dassault Aviation	MYSTERE-FALCON 50
2015-02-05		The Boeing Company	717-200, DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F, MD-10-10F and MD-10-30F, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87), MD-88, MD-90-30
2015-02-06		Bombardier, Inc	CL-600-2B16 (CL-604 Variant)
2015-02-08		Rolls-Royce Corporation (RRC)	AE 2100D2, 2100D2A, 2100D3, 2100P and AE 3007A1, A1/1, A1/3, A1E, A1P, A2, A3, C, C1, and C2
2015-02-11		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-02-12		Bombardier, Inc	DHC-8-400, -401 and -402
2015-02-13		Empresa Brasileira de Aeronautica S.A. (Embraer)	EMB -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2015-02-16	R 2009-06-06	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-02-17		Airbus	A330-201, -202, -203, -223, -223F, -243, and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2015-02-18		Airbus	A330-201, -202, -203, -301, -302, and -303
2015-02-19	R 95-24-04	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R, A300 C4-605R Variant F

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-02-20	S 2013-15-10	Rolls-Royce plc (RR)	RB211-Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61, 768-60, 772-60, 772B-60, 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, 895-17, 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84
2015-02-23		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants)
2015-02-26	R 2013-24-13	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series, 737-600, -700, -700C, -800, and -900 series
Biweekly 2015-04			
2015-02-24	R 2007-03-18 R2008-17-02 R2012-08-03 R2012-15-14	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, A300 B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-02-25		Bombardier, Inc.	DHC-8-400, -401, and -402
2015-03-01		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2015-03-02		Airbus	A319-115, A319-133, A320-214, A320-232, and A320-233
2015-03-04		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2015-03-05	R 2012-09-07	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-111, -211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-03-06	R 2007-22-10	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213 -311, -312, -313, -541, and -642
Biweekly 2015-05			
2015-02-14	R 2009-20-05	Airbus	A318-111, -112, -121, -122, A319-111, -112, -113, -114, -115, -131, -132, -133, A320-211, -212, -214, -231, -232, -233, A321-111, -112, -131, -211, -212, -213, -231, -232.
2015-03-03		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, B4-203, A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R. A300 C4-605R Variant F.
2015-04-02		CFM International S.A.	CFM56-7B series
2015-04-03		Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60
2015-04-06		Rolls-Royce plc	RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17.
Biweekly 2015-06			
2015-04-07		Boeing	767-200 and -300 series airplanes
2015-05-01		Boeing	757-200, -200PF, -200CB, and -300 series airplanes; and 767-200, -300, -300F, and -400ER series airplanes
2015-05-03		Bombardier	CL-600-2B19 (Regional Jet Series 100 & 440) airplanes
2015-05-07	R 2015-02-06	Bombardier	CL-600-2B16 (CL-604 Variant) airplanes
2015-05-08		Lockheed Martin	382, 382B, 382E, 382F, and 382G airplanes
2015-06-01	S 2014-06-03	British Aerospace	Jetstream Series 3101 and Jetstream 3201 airplanes
Biweekly 2015-07			
2015-04-08	R 2014-06-08	Bombardier, Inc	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2015-05-02	R 2014-23-15	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2015-06-04	R 2011-13-07	Dassault	FALCON 7X
2015-06-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-06-06 2015-06-07 2015-07-01		BAE Systems The Boeing Company Rolls-Royce plc	A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes. 4101 airplanes 737-100, -200, -200C, -300, -400, and -500 series airplanes RB211-524B-02, RB211-524B-B-02, RB211-524B2-19, RB211-524B2-B-19, RB211-524B3-02, RB211-524C2-19, and RB211-524C2-B-19 turbofan engines
Biweekly 2015-08			
2015-06-08	R 2011-09-03	Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G
2015-07-05		BAE Systems (Operations) Limited	146-100A, -200A, and -300A; and Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2015-07-06		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2015-07-07 2015-08-02	R 2015-02-04	The Boeing Company Dassault Aviation	777-200, -200LR, -300ER, and 777F series MYSTERE-FALCON 50
Biweekly 2015-09			
2015-06-10		ATR-GIE Avions de Transport Régional	ATR72-212A
2015-07-02		Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A and CL-601-3R Variants), CL-600-2B16 (CL-604 Variants)
2015-08-01 2015-08-03 2015-08-05	R 2013-26-05	The Boeing Company Bombardier, Inc. Dassault Aviation	757-200, -200PF, -200CB, and -300 series DHC-8-400, -401, and -402 FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2015-08-06	R 2007-14-05	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-08-08	R 2014-26-53 and 2015-03-02	Airbus	A319-115, A319-132, A319-133, A320-214, A320-232, and A320-233
2015-08-09 2015-09-02 2015-09-03		The Boeing Company Bombardier, Inc. Airbus	737-600 and -700 series CL-600-2E25 (Regional Jet Series 1000)
2015-09-07		The Boeing Company	A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 787
Biweekly 2015-10			
2015-08-07 2015-09-05 2015-09-08		Zodiac Aerotechnics The Boeing Company Airbus	See AD 747-400 and 747-400F A300 B4-601, B4-603, and B4-605R; and A300 F4-605R; and A300 C4-605R Variant F; and A310-204 and -304
2015-09-09	R 2004-07-11	The Boeing Company	767-200, -300, and -400ER series
Biweekly 2015-11			
2015-10-02	R 2014-20-11	Zodiac Seats France	9140, 9166, 9173, 9174, 9184, 9188, 9196, 91B7, 91B8, 91C0, 91C2, 91C4, 91C5, 91C9, 9301, and 9501 series passenger seat assemblies
2015-10-03	R 2014-09-05	Airbus Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-10-04	R 2012-09-09	International Aero Engines AG	IAE V2500-A1, IAE V2525-D5, IAE V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, and V2533-A5
2015-11-04		The Boeing Company	707-100 long body, -200, -100B long body, and -100B short body; 707-300, -300B, -300C, -400; 720 and 720B series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2015-12			
2015-10-01		Bombardier, Inc.	DHC-8-401, -402, and -403
2015-11-02	R 95-26-11	Lockheed Martin Corporation	L-1011-385-1, L-1011-385-1-14, L-1011-385-1-15, and L-1011-385-3
2015-11-03		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A; ATR42-200, -300, -320, and -500; ATR72-101, -201, -102, -202, -211, -212, and -212A
2015-11-05		The Boeing Company	747-400, 747-400D, 747-400F, 747-8F, and 747-8 series
Biweekly 2015-13			
2015-10-51		Avidyne Corporation	Integrated Flight Displays (IFDs)
2015-12-03	COR R 2007-13-05	The Boeing Company	777-200, -200LR, -300, and -300ER series
2015-12-05	R 2008-06-18	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F
2015-12-06		Learjet Inc.	45
2015-12-07		The Boeing Company	747-8F and 747-8 series
2015-12-08		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-12-10		Pratt & Whitney Division	PW6122A and PW6124A
2015-12-11	COR	The Boeing Company	767-200, -300, -300F, and -400ER series, 777-200, -200LR, -300, -300ER, and 777F
2015-12-12		Fokker Services B.V.	F.28 Mark 0070 and 0100
2015-13-01		ATR-GIE Avions de Transport Régional	ATR42-500, ATR72-212A
2015-13-02		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2015-14			
2015-13-08		Dassault Aviation	FALCON 2000EX
2015-14-01		Bombardier, Inc.	DHC-8-400, -401, and -402
Biweekly 2015-15			
2015-13-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-13-07	R 98-13-23	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; and A300 C4-605R Variant F
2015-14-03		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2015-14-05		Pratt & Whitney	JT8D-217C and JT8D-219
2015-14-06		The Boeing Company	747-8 and 747-8F series
2015-14-07		The Boeing Company	787-8
2015-14-08		Airbus	A310-203
2015-14-09		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, 747SP, 747-8F, and 747-8 series
2015-15-01	R 2004-13-02	The Boeing Company	747-100, -200B, and -200F series
2015-15-02	R 2012-13-06	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203; A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R; and A300 C4-605R Variant F
2015-15-03		General Electric Company	GENx-1B and GENx-2B
2015-15-05	R 98-22-10 R 90-06-02	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-15-08		Bombardier, Inc.	BD-100-1A10 (Challenger 300)
2015-15-09		BAE Systems (Operations) Limited	4101
2015-15-10		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces

Biweekly 2015-16

2012-11-09 R1		Transport Category Airplanes	Chemical oxygen generators
2015-13-06	R 2013-14-05	The Boeing Company	747-400 and -400F series
2015-15-07	R 2015-10-01	Bombardier, Inc.	DHC-8-400, -401, and -402
2015-15-11		The Boeing Company	747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2015-15-12		Airbus	A318-111 and -112, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-111, -211, -212, -214, -231, -232, and -233
2015-15-13		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-15-14		BAE Systems (Operations) Limited	ATP
2015-15-15		The Boeing Company	777-200, 777-200LR, 777-300ER, and 777F series

Biweekly 2015-17

2015-16-01	R 2012-19-11	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series; 737-600, -700, -700C, -800, -900, and -900ER series
2015-16-02	R 2003-14-11 R 2004-11-08 R 2004-13-25 R 2004-18-14 R 2007-05-12 R 2008-06-07 R 2009-18-20 R 2010-15-02 R 2012-04-07	Airbus	A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343
2015-16-03		Rolls-Royce plc	RB211-524B-02, RB211-524B2-19, RB211-524B3-02, RB211-524B4-02, RB211-524B4-D-02, RB211-524C2-19, RB211-524D4-19, RB211-524D4-39, and RB211-524D4X-19
2015-16-04		Kidde Graviner	See AD
2015-16-05		British Aerospace Regional Aircraft	Jetstream Series 3101 and Jetstream Model 3201
2015-16-06		British Aerospace Regional Aircraft	Jetstream Model 3201
2015-17-04		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900)
2015-17-06		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-17-09	R 98-18-02	Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F

Biweekly 2015-18

2015-16-08	R 2011-08-51	The Boeing Company	737-300, -400, and -500 series
2015-17-03		Bombardier, Inc	DHC-8-400, -401, and -402
2015-17-05		Bombardier, Inc	BD-700-1A10 and BD-700-1A11
2015-17-07		Airbus	A300 B4-603, B4-605R, B4-620, B4-622, and B4-622R, A300 C4-605R Variant F, A300F4-605R
2015-17-08		Bombardier, Inc	DHC-8-400, -401, and -402 series
2015-17-12		Cessna Aircraft Company	500, 501, 550, 551, S550, 560, 650
2015-17-13		The Boeing Company	777-200 and -300 series
2015-17-14		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-17-15		Bombardier, Inc	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and Model CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000).

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-17-16 2015-17-17		Bombardier, Inc Pratt & Whitney	CL-600-2B19 (Regional Jet Series 100 & 440) PW4164-1D, PW4168-1D, PW4168A-1D and PW4170, PW4164, PW4168, and PW4168A
2015-17-22		Airbus	A330-243, A330-243F, A330-341, A330-342, and A330-343
2015-17-23		Empresa Brasileira de Aeronautica S.A. (Embraer)	EMB-135BJ
2015-17-24 2015-17-25 2015-18-02		The Boeing Company Bombardier, Inc Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	787-8 DHC-8-400, -401, and -402 382, 382B, 382E, 382F, and 382G
Biweekly 2015-19			
2015-17-19 2015-18-04 2015-18-05 2015-19-01 2015-19-02 2015-19-03 2015-19-04	R 97-07-14	Rolls-Royce plc CFM International S.A. Airbus The Boeing Company The Boeing Company The Boeing Company The Boeing Company	RB211 Trent 768-60, 772-60, and 772B-60 CFM56-7B and CFM56-3 A320-211 and -231 777-200, -200LR, -300, -300ER, and 777F series 767-200, -300, -300F, and -400ER series 737-600, -700, -700C, -800, -900, and -900ER series 757-200, -200PF, -200CB, and -300 series
Biweekly 2015-20			
2015-19-06 2015-19-08	R 2012-24-10 R 2011-19-04	The Boeing Company Airbus	747-400 and -400F series A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2015-19-09 2015-19-12 2015-19-13 2015-19-16 2015-20-02	R 2013-02-10	The Boeing Company The Boeing Company Bombardier, Inc. The Boeing Company Airbus	787-8 767-200, -300, -300F, and -400ER series DHC-8-400, -401, and -402 777-200, -200LR, -300,-300ER, and 777F series A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2015-20-05		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	188A and 188C
Biweekly 2015-21			
2015-15-06 2015-20-01	R 2003-13-01	The Boeing Company Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	767-200, -300, and -300F series; 67-400ER series 188A and 188C
2015-20-03 2015-20-06 2015-20-07	R 2014-14-02	Pratt & Whitney Canada Corp Viking Air Limited Bombardier, Inc	PW120, PW121, and PW121A; PW124B, PW127, PW127E, PW127F; PW127E, PW127F; and PW127G DHC-7-1 and DHC-7-100 CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
2015-20-08		Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5
2015-20-10		Gulfstream Aerospace Corporation	GVI
Biweekly 2015-22			
2015-17-21 2015-18-04 2015-21-02 2015-21-03 2015-21-05	COR R 2010-08-08 R2011-06-04	Rolls-Royce plc CFM International S.A. Bombardier, Inc. Airbus Fokker Services B.V.	RB211-535E4-37, RB211-535E4-B-37, and RB211-535E4-C-37 CFM56-7B and CFM56-3 DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 A330-243, -341, -342, and -343; and A330-243F F.27 Mark 200, 300, 400, 500, 600, and 700

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-21-07		Airbus	A330-201, -202, -203, -223, and -243; A330-223F and -243F; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, and -213; A340-311, -312, and -313; A340-541; A340-642
2015-21-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2015-21-09	R 2015-19-02	The Boeing Company	767-200, -300, -300F, and -400ER series
2015-21-10	R 2015-19-03	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2015-21-11	R 2015-16-01	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series; 737-600, -700, -700C, -800, -900, and -900ER series
2015-22-01	R 2007-16-08	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series
2015-22-03		Pratt & Whitney Division	PW4164, PW4168, PW4168A, PW4164C, PW4164C/B, PW4164-1D, PW4168-1D, PW4168A-1D, PW4170, PW4164C-1D, and PW4164C/B-1D; PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650
Biweekly 2015-23			
2015-21-06	R 2002-07-08	The Boeing Company	737-200, -200C, -300, -400, and -500 series airplanes
2015-22-05	R 2009-18-15	Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes; A300 B4-601, B4-603, B4-620, and B4-622 airplanes; A300 B4-605R and B4-622R airplanes; A300 F4-605R and F4-622R, and A300 C4-605R Variant F airplanes; and A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2015-22-06		Airbus	A318-111, -112, -121, and -122 airplanes; A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; A320-211, -212, -214, -231, -232, and -233 airplanes; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes.
2015-22-07		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	188A and 188C airplanes
2015-22-08		Airbus	A318-111, -112, -121, and -122 airplanes; A319 -111, -112, -113, -114, -115, -131, -132, and -133 airplanes; A320-211, -212, -214, -231, -232, and -233 airplanes
2015-22-09		The Boeing Company	787-8 airplanes
2015-22-10		Airbus	A318-111, -112, -121, and -122 airplanes; A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; A320-211, -212, -214, -231, -232, and -233 airplanes; A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2015-23-04		General Electric Company	GENx-1B model turbofan engines
Biweekly 2015-24			
2015-22-11	R 2011-09-04	Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	382, 382B, 382E, 382F, and 382G airplanes
2015-23-05		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F airplanes, A330-301, -302, -303, -321, -322, -323, -341, -342, -343 airplanes, A340-211, -212, -213, -311, -312, -313 airplanes.
2015-23-06	R 2008-22-20	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-311, -312, and -313 airplanes
2015-23-07		Bombardier, Inc.	BD-100-1A10 (Challenger 300) airplanes
2015-23-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2015-23-09		Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems)	Flightcrew oxygen mask regulators (See AD)
2015-23-10		The Boeing Company	747-8 series airplanes
2015-23-11		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747SR, and 747SP series airplanes
2015-23-12		ATR–GIE Avions de Transport Régional	ATR42-200, -300, -320, -500; and ATR72-101, -201, -102, -202, -211, -212, and -212A airplanes
2015-23-13		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133 A320-211, -212, -214, -231,

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2015-23-14 2015-24-01		Fokker Services B.V. Airbus	-232, and -233 A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes. F.28 Mark 0070 and 0100 airplanes A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
Biweekly 2015-25			
2015-24-04		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
2015-24-06		Gulfstream Aerospace Corporation	GVI airplanes
Biweekly 2015-26			
2015-25-01 2015-25-02		The Boeing Company Airbus	757-200, 757-200CB, and 757-200PF A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642
2015-25-03	R 2013-23-03	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series
2015-25-05		Bombardier, Inc.	CL-600-2A12 (CL-601); CL-600-2B16 (CL-601-3A, CL-601-3R Variants); CL-600-2B16 (CL-604 Variant)
2015-25-08 2015-25-09		The Boeing Company Airbus	777-200, -200LR, -300, -300ER, and 777F series A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313



2015-25-01 The Boeing Company: Amendment 39-18339; Docket No. FAA-2013-0300; Directorate Identifier 2011-NM-163-AD.

(a) Effective Date

This AD is effective January 26, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 757-200, 757-200CB, and 757-200PF airplanes; certificated in any category; as identified in Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Unsafe Condition

This AD was prompted by a report that a forward-most cam latch on the forward center cam latch pair on a main cargo door (MCD) broke during flight. We are issuing to detect and correct cracked or damaged cam latches, latch pins, and latch pin cross bolts, which could reduce the structural integrity of the MCD, and result in potential loss of the cargo door and rapid decompression of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive MCD Inspections, Other Specified Actions, Related Investigative Actions, and Corrective Actions (Including Bolt Replacement and MCD Rigging)

At the applicable times specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014, except as provided by paragraph (j)(1) of this AD: Do a general visual inspection for broken or missing cam latches, latch pins, and latch pin cross bolts; torque the cross bolts in the latch pins; measure the extension of the latch pins; replace all alloy steel cross bolts through the latch pins with corrosion resistant steel (CRES) cross bolts; do a general visual inspection of all cam latches for lip deformation; do a high frequency eddy current (HFEC) or magnetic particle inspection of cam latch 1 and cam latch 2 for cracks and replace all cracked or broken parts; check the rig of the MCD and re-rig as applicable; and do all applicable related investigative and corrective actions; and thereafter do all applicable

repetitive inspections specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014, except as required by paragraph (j)(2) of this AD. Do all applicable related investigative and corrective actions at the applicable time specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014. Do all applicable repetitive inspections at the applicable time and intervals specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014, until the rig of the MCD has been checked in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014.

(1) For Condition 2 as defined in Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014: Do repetitive general visual inspections for broken or missing cam latches, latch pins, and latch pin cross bolts.

(2) For Condition 3 as defined in Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014: Repetitive general visual inspections for broken or missing cam latches, latch pins, and latch pin cross bolts and repetitive detailed inspections of the discrepant cam latch and mating latch pin for any cracks, or gouges in critical areas.

(3) For Condition 4 as defined in Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014: Repetitive general visual inspections for broken or missing cam latches, latch pins, and latch pin cross bolts; repetitive detailed inspections of the cam latches and latch pins for any cracks, or any gouges in critical areas; and, unless replaced with new or reworked parts, repetitive HFEC or magnetic particle inspections of cam latch 1 and cam latch 2 for any cracks.

(h) Repetitive MCD Post-Rigging Inspections and Corrective Actions

At the applicable times specified in table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014: Do general visual inspections for any broken or missing cam latches, latch pins, and latch pin cross bolts; a detailed inspection of the cam latches and latch pins for any cracks, or any gouges in critical areas; and an HFEC or magnetic particle inspection of cam latch 1 and cam latch 2 for cracks; and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014; except as required by paragraph (j)(2) of this AD. Do all applicable corrective actions before further flight. Repeat the inspections thereafter at the applicable times specified in table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install an alloy steel bolt as a cross bolt through any latch pin fitting assembly in the lower sill of the MCD on any airplane.

(j) Exceptions to Service Bulletin Specifications

The following exceptions apply in this AD.

(1) Where Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014, specifies a compliance time after the original issue date of that service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014, specifies to contact Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(k) Credit for Previous Actions

This paragraph provides credit for the corresponding actions required by paragraphs (g) and (h) of this AD, if those actions were done before the effective date of this AD, using Boeing Alert Service Bulletin 757-52A0091, dated March 9, 2010, which is not incorporated by reference in this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(m) Related Information

(1) For more information about this AD, contact Kimberly DeVoe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6495; fax: 425-917-6590; email: kimberly.devoe@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 757-52A0091, Revision 1, dated December 19, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 25, 2015.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-25-02 Airbus: Amendment 39-18340. Docket No. FAA-2015-0675; Directorate Identifier 2014-NM-213-AD.

(a) Effective Date

This AD becomes effective January 26, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Airbus Model A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes, all manufacturer serial numbers, except those on which Airbus Modification 202702 has been embodied in production.

(2) Airbus Model A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by reports of cracks at certain frames of the forward cargo door. We are issuing this AD to detect and correct cracking at certain frames, which could result in the loss of structural integrity of the forward cargo door.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Repair

(1) Within 200 flight cycles after the effective date of this AD, do a detailed inspection for cracking of an affected forward cargo door, having a part number identified in paragraphs (g)(1)(i) through (g)(1)(xii) of this AD, at frames 20A, 20B, and 21 areas located above beam 3, from outside and inside, in accordance with Airbus Alert Operators Transmission (AOT) A52L010-14, dated September 30, 2014, except as required by paragraph (k) of this AD. A review of airplane maintenance records is acceptable to determine if an affected forward cargo door is installed provided that the part number of the forward cargo door can be conclusively determined from that review.

(i) F523-70500-000.

- (ii) F523-70500-004.
- (iii) F523-70500-006.
- (iv) F523-70500-008.
- (v) F523-70500-010.
- (vi) F523-70500-012.
- (vii) F523-70500-014.
- (viii) F523-70550-000.
- (ix) F523-70550-002.
- (x) F523-70550-004.
- (xi) F523-70550-008.
- (xii) F523-70550-050.

(2) If any crack is found during the inspection required by paragraph (g)(1) of this AD, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(h) Definition of Detailed Inspection

For the purposes of this AD, a detailed inspection is an intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as a mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required.

(i) Reporting Requirement

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g)(1) of this AD to Serge KIYMAZ, Structure Engineer, Structure Engineering–SEES1 CUSTOMER SERVICES, Phone: +33(0)5 82 05 10 33, Fax: +33(0)5 61 93 36 14, email: serge.kiyamaz@airbus.com, at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the information identified in Airbus AOT A52L010-14, dated September 30, 2014.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Parts Installation Limitation

As of the effective date of this AD, installation of a forward cargo door having any part number specified in paragraphs (g)(1)(i) through (g)(1)(xii) of this AD is permitted on any airplane, provided that prior to installation, the door is inspected and, depending on the findings, corrected, in accordance with Airbus AOT A52L010-14, dated September 30, 2014, except as required by paragraph (k) of this AD.

(k) Exception to the Service Information

On page 1 of Airbus AOT A52L010-14, dated September 30, 2014, at section "2. Referenced Documentation," "Ref. 5" specifies page block "PB.801," which is incorrect. This page block should be "PB.401" instead.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM 116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES 200.

(m) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0228, dated October 20, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0675-0002>.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission A52L010-14, dated September 30, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 25, 2015.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-25-03 The Boeing Company: Amendment 39-18341; Docket No. FAA-2015-0828; Directorate Identifier 2014-NM-146-AD.

(a) Effective Date

This AD is effective January 28, 2016.

(b) Affected ADs

This AD replaces AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013).

(c) Applicability

This AD applies to The Boeing Company Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of the fracture of an inboard actuator attach fitting of the outboard flap. An inspection of the attach fitting revealed that it was incorrectly machined with a cylindrical profile instead of a conical profile, resulting in reduced wall thickness. A machining defect was also found on some actuator assemblies inspected during manufacture at the point where the tapered machining transitioned to the hemispherical machining at the top of the inner surface. This defect could lead to fatigue cracking and subsequent fracture. We are issuing this AD to detect and correct defective inboard actuator attach fittings which, combined with loss of the outboard actuator load path, could result in uncontrolled retraction of the outboard flap, damage to flight control systems, and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Part Number Inspection With Revised Service Information

This paragraph restates the requirements of paragraph (g) of AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013), with revised service information. Within 90 days after November 29, 2013 (the effective date of AD 2013-23-03): Inspect to determine the part number of the inboard actuator attach fittings of the outboard flaps, in accordance with Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, dated September 12,

2013; or Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014. As of the effective date of this AD, only Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014, may be used.

(h) Retained Actions for Certain Attach Fittings With Revised Service Information

This paragraph restates the requirements of paragraph (h) of AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013), with revised service information. If, during the inspection required by paragraph (g) of this AD, any inboard actuator attach fitting having part number (P/N) 65B08564-7 is found, before further flight, do the actions specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Do a detailed inspection of the inboard actuator attach fitting for a cylindrical defect, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, dated September 12, 2013; or Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014. As of the effective date of this AD, only Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014, may be used. For airplanes on which the detailed inspection is done before the effective date of this AD: If any cylindrical defect is found, before further flight, do the actions specified in paragraph (h)(1)(i) or (h)(1)(ii) of this AD.

(i) Do a minimum thickness inspection of the inboard actuator attach fitting to determine minimum wall thickness of the actuator fitting assembly, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, dated September 12, 2013; or Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014. If the minimum thickness of the wall is less than 0.130 inch: Before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, dated September 12, 2013.

(ii) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, dated September 12, 2013.

(2) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, dated September 12, 2013; or Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014. As of the effective date of this AD, only Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014, may be used.

(i) New Actions for Certain Airplanes on Which Any Cylindrical Defect Is Found

For airplanes on which the detailed inspection required by paragraph (h)(1) of this AD is done on or after the effective date of this AD: If any cylindrical defect is found during any inspection required by paragraph (h)(1) of this AD, before further flight, do the actions specified in paragraph (i)(1) or (i)(2) of this AD.

(1) Determine the minimum wall thickness of the actuator attach fitting either by doing an ultrasonic inspection or by mechanically measuring the thickness and do a detailed inspection of the inner conical section to determine if the machining defect is present, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(i) If the minimum thickness of the wall is less than 0.130 inch: Before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(ii) If the minimum thickness of the wall is 0.140 inch or greater and the machining defect is present, before further flight, do the actions specified in paragraph (i)(1)(ii)(A) or (i)(1)(ii)(B) of this AD.

(A) Overhaul the inboard actuator attach fitting of the outboard flap, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(B) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(iii) If the minimum thickness of the wall is 0.130 inch or greater and less than 0.140 inch and the machining defect is not present, within 48 months or 3,000 flight cycles after the effective date of this AD, whichever occurs first, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(iv) If the minimum thickness of the wall is 0.130 inch or greater and less than 0.140 inch and the machining defect is present, before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(2) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(j) New Actions for Airplanes on Which No Cylindrical Defects Are Found

If no cylindrical defect is found during any inspection required by paragraph (h)(1) of this AD, within 24 months after the effective date of this AD, do the actions specified in paragraph (j)(1) or (j)(2) of this AD.

(1) Determine the minimum wall thickness of the actuator attach fitting either by doing an ultrasonic inspection or by mechanically measuring the thickness and do a detailed inspection of the inner conical section to determine if the machining defect is present, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(i) If the minimum thickness of the wall is less than 0.130 inch: Before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747 57A2443, Revision 1, dated June 23, 2014.

(ii) If the minimum thickness of the wall is 0.140 inch or greater and the machining defect is present, before further flight, do the actions specified in paragraph (j)(1)(ii)(A) or (j)(1)(ii)(B) of this AD.

(A) Overhaul the inboard actuator attach fitting of the outboard flap, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(B) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(iii) If the minimum thickness of the wall is 0.130 inch or greater and less than 0.140 inch and the machining defect is not present, within 48 months or 3,000 flight cycles after the effective date of this AD, whichever occurs first, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(iv) If the minimum thickness of the wall is 0.130 inch or greater and less than 0.140 inch and the machining defect is present, before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014

(2) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(k) New Inspection or Replacement for Certain Fittings That Were Previously Inspected

For airplanes on which the detailed inspection required by paragraph (h)(1) of this AD is done before the effective date of this AD, except as required by paragraph (m) of this AD: If any cylindrical defect is found during any inspection required by paragraph (h)(1) of this AD and the replacement of the inboard actuator attach fitting of the outboard flap was not done as specified in Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, within 24 months after the effective date of this AD, do the actions specified in paragraph (k)(1) or (k)(2) of this AD.

(1) Do a detailed inspection of the inner conical section for machining defects and do an ultrasonic inspection to determine the minimum thickness or mechanically determine the minimum thickness, in accordance with Part 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014. A review of airplane maintenance records, if available, is acceptable to determine the wall thickness and to determine if there are machining defects, provided wall thickness and machining defects can be positively determined from the records review.

(i) If any machining defect is found and the minimum thickness of the wall is 0.140 inch or greater: Before further flight, do the actions specified in paragraph (k)(1)(i)(A) or (k)(1)(i)(B) of this AD.

(A) Overhaul the inboard actuator attach fitting of the outboard flap, in accordance with Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(B) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(ii) If any machining defect is found and the minimum thickness of the wall is 0.130 inch or greater and less than 0.140 inch: Before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(iii) If no machining defect is found and the minimum thickness of the wall is 0.130 inch or greater and less than 0.140 inch: Within 48 months or 3,000 flight cycles after the effective date of this AD, whichever occurs first, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(iv) If a machining defect is or is not found and the minimum thickness of the wall is less than 0.130 inch: Before further flight, replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(2) Replace the inboard actuator attach fitting of the outboard flap, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(l) Parts Installation Limitation

As of the effective date of this AD, no actuator attach fitting having P/N 65B08564-7 may be installed on any airplane unless the inspection specified in paragraph (h)(1) of this AD is done prior to installation and the applicable actions specified in paragraphs (i) and (j) of this AD are done within the applicable times specified in paragraphs (i) and (j) of this AD. A review of airplane maintenance

records, if available, is acceptable to determine if the inspection and applicable actions have been done, provided the inspection and actions can be positively determined from the records review.

(m) Action for Parts Installed After AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013) Was Accomplished

For airplanes on which the detailed inspection required by paragraph (h)(1) of this AD is done before the effective date of this AD and the inboard actuator attach fitting was replaced since that inspection: Within 90 days after the effective date of this AD, inspect to determine the part number of the inboard actuator attach fittings of the outboard flaps and, for inboard actuator attach fittings having P/N 65B08564-7, do the applicable actions specified in paragraphs (h), (i), and (j) of this AD within the applicable times specified in paragraphs (h), (i), and (j) of this AD. A review of airplane maintenance records, if available, is acceptable to determine the part number, provided the part number can be positively determined from the records review.

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (o) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) If any service information contains steps that are identified as RC (Required for Compliance), those steps must be done to comply with this AD; any steps that are not identified as RC are recommended. Those steps that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC provided the steps identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to steps identified as RC require approval of an AMOC.

(5) AMOCs approved for AD 2013-23-03, Amendment 39-17658 (78 FR 68345, November 14, 2013) are approved as AMOCs for the corresponding provisions of this AD.

(o) Related Information

For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: nathan.p.weigand@faa.gov.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on January 28, 2016.

(i) Boeing Alert Service Bulletin 747-57A2443, Revision 1, dated June 23, 2014.

(ii) Reserved.

(4) The following service information was approved for IBR on November 29, 2013 (78 FR 68345, November 14, 2013).

(i) Boeing Alert Service Bulletin 747-57A2443, dated September 12, 2013.

(ii) Reserved.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 24, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-30881 Filed 12-23-15; 8:45 am]



2015-25-05 Bombardier, Inc.: Amendment 39-18343; Docket No. FAA-2014-0625; Directorate Identifier 2014-NM-044-AD.

(a) Effective Date

This AD becomes effective January 28, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Model CL-600-2A12 (CL-601) airplanes, serial numbers 3001 through 3066 inclusive.

(2) Model CL-600-2B16 (CL-601-3A, CL-601-3R Variants) airplanes, serial numbers 5001 through 5194 inclusive.

(3) Model CL-600-2B16 (CL-604 Variant) airplanes, serial numbers 5301 through 5665 inclusive, and 5701 through 5934 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Reason

This AD was prompted by a report of an aft equipment bay fire due to chafing and subsequent arcing of the integrated drive generator (IDG) power cables. Additionally, we have received several reports of broken support brackets of the hydraulic lines. We are issuing this AD to detect and correct broken support brackets of the hydraulic lines, which could result in inadequate clearance between the IDG power cables and hydraulic lines and chafing of the IDG power cables, and consequent high energy arcing and an uncontrolled fire in the aft equipment bay.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One-Time Inspection and Corrective Actions

Within 400 flight hours or 18 months after the effective date of this AD, whichever occurs first: Perform a one-time detailed inspection of the IDG power cables for chafing between the cables and the adjacent hydraulic and pneumatic lines, and for any cracked or broken support bracket of the hydraulic lines, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD. If any chafing of the power

cables or any cracked or broken support bracket is found, before further flight, repair or replace, as applicable, in accordance with the Accomplishment Instructions of the applicable service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD.

(1) Bombardier Service Bulletin 605-24-007, Revision 01, dated January 13, 2014 (for Model CL-600-2B16 airplanes (CL-604 Variant)).

(2) Bombardier Service Bulletin 604-24-026, Revision 01, dated January 13, 2014 (for Model CL-600-2B16 airplanes (CL-604 Variant)).

(3) Bombardier Service Bulletin 601-0625, Revision 01, dated January 13, 2014 (for Model CL-600-2A12 (CL-601) and CL-600-2B16 airplanes (CL-601-3A and CL-601-3R Variants)).

(h) Credit for Previous Actions

This paragraph provides credit for action required by paragraph (g) of this AD, if the conditions specified in both paragraphs (h)(1) and (h)(2) of this AD are met.

(1) The action was performed before the effective date of this AD using Bombardier Service Bulletin 605-24-007, Bombardier Service Bulletin 604-24-026, or Bombardier Service Bulletin 601-0625, all dated September 18, 2012. This service information is not incorporated by reference in this AD.

(2) The action specified in Service Request for Product Support Action (SRPSA) 27512, SRPSA 30806, SRPSA 32727, SRPSA 32864, or SRPSA 33161 has not been done.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-553. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-05, dated January 20, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0625-0003>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 605-24-007, Revision 01, dated January 13, 2014.

(ii) Bombardier Service Bulletin 604-24-026, Revision 01, dated January 13, 2014.

(iii) Bombardier Service Bulletin 601-0625, Revision 01, dated January 13, 2014.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514 855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington on December 8, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-25-08 The Boeing Company: Amendment 39-18346; Docket No. FAA-2015-1281; Directorate Identifier 2014-NM-241-AD.

(a) Effective Date

This AD is effective January 28, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder indicating that the lap splices of the aft pressure bulkhead webs are subject to widespread fatigue damage on aging Model 777 airplanes that have accumulated at least 38,000 total flight cycles. We are issuing this AD to detect and correct fatigue cracking in the aft webs of the radial lap splices of the aft pressure bulkhead; such cracking could result in reduced structural integrity of the airplane, decompression of the cabin, and collapse of the floor structure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of Lap Splice in the Web of the Aft Pressure Bulkhead

Except as required by paragraph (h) of this AD: At the times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0078, dated December 5, 2014, do a medium frequency eddy current inspection for any cracking in the aft webs of the radial lap splices of the aft pressure bulkhead, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0078, dated December 5, 2014. Repeat the inspection thereafter at intervals not to exceed 8,400 flight cycles from the previous inspection. If any crack is found during any inspection required by this AD, do the applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0078, dated December 5, 2014. If a corrective action described in Boeing Alert Service Bulletin 777-53A0078, dated

December 5, 2014, specifies to contact Boeing for appropriate action: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(h) Exception to Service Information Specifications

Where Boeing Alert Service Bulletin 777-53A0078, dated December 5, 2014, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (1)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6412; fax: 425-917-6590; email: Eric.Lin@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777-53A0078, dated December 5, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206 766 5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 10, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2015-25-09 Airbus: Amendment 39-18347. Docket No. FAA-2015-0083; Directorate Identifier 2014-NM-131-AD.

(a) Effective Date

This AD becomes effective January 28, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model A330-201, -202, -203, -223, -243, -223F, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes, all manufacturer serial numbers except those on which Airbus Modification 203287 has been embodied in production.

(2) Model A340-211, -212, -213, -311, -312, and -313 airplanes, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Reason

This AD was prompted by reports that a bracket that attaches the cockpit instrument panel to the airplane structure does not sustain the fatigue loads of the design service goal. We are issuing this AD to detect and correct cracking on a bracket of the cockpit instrument panel, which, combined with failure of the horizontal beam, could lead to collapse of the cockpit panel, and reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of Bracket No. 6 of the Cockpit Instrument Panel

At the latest of the times specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD: Do a detailed inspection of bracket No. 6 (part number (P/N) F2511012820000, pre-modification Number 55128S18242; or P/N F2511373420000, post-modification Number 55128S18242) of the cockpit instrument panel for cracking and to determine if both bracket lugs are fully broken, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014; or Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014; as applicable. Repeat the inspection thereafter at intervals not to exceed 2,600 flight cycles.

- (1) Prior to accumulating 17,200 total flight cycles since the airplane's first flight.
- (2) Prior to bracket No. 6 of the cockpit instrument panel accumulating 17,200 total flight cycles since installation on an airplane.
- (3) Within 500 flight cycles after the effective date of this AD.

(h) Inspection and Corrective Actions

(1) If, during any inspection required by paragraph (g) of this AD, any cracking of bracket No. 6 (P/N F2511012820000, pre-modification Number 55128S18242; or P/N F2511373420000, Post-modification Number 55128S18242) of the cockpit instrument panel is found, and both bracket lugs are not fully broken: Within 2,600 flight cycles after that inspection, replace bracket No. 6 of the cockpit instrument panel with a serviceable part, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014; or Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014; as applicable. Replacement of bracket No. 6 (P/N F2511012820000, pre-modification Number 55128S18242; or P/N F2511373420000, post-modification Number 55128S18242) of the cockpit instrument panel does not constitute terminating action for the repetitive inspections required by paragraph (g) of this AD.

(2) If, during any inspection required by paragraph (g) of this AD, any cracking of bracket No. 6 (P/N F2511012820000, pre-modification Number 55128S18242; or P/N F2511373420000, Post-modification Number 55128S18242) of the cockpit instrument panel is found and both bracket lugs are fully broken: Before further flight, do a detailed inspection of bracket No. 7 (P/N F2511012820000, pre-modification Number 55128S18242; or P/N F2511373420000, Post-modification Number 55128S18242) of the cockpit instrument panel for cracking, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014; or Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014; as applicable.

(i) If, during the inspection required by paragraph (h)(2) of this AD, no cracking is found in bracket No. 7 of the cockpit instrument panel: Before further flight, replace bracket No. 6 and bracket No. 7 of the cockpit instrument panel with serviceable parts, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014; or Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014; as applicable. Replacement of bracket No. 6 (P/N F2511012820000, pre-modification Number 55128S18242; or P/N F2511373420000, post-modification Number 55128S18242) of the cockpit instrument panel does not constitute terminating action for the repetitive inspections required by paragraph (g) of this AD.

(ii) If, during the inspection required by paragraph (h)(2) of this AD, any cracking is found in bracket No. 7 of the cockpit instrument panel: Although Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014; and Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014; specify to contact Airbus for repair instructions, and specify that action as "RC" (Required for Compliance), repair the cracking before further flight using a repair method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(i) Optional Terminating Modification for Paragraph (g) of This AD

Modifying an airplane by replacing bracket No. 6 of the cockpit instrument panel with a new, reinforced bracket, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-25-3548, dated October 31, 2013; or Airbus Service Bulletin A340-25-4354, dated October 31, 2013; as applicable; terminates the repetitive inspections required by paragraph (g) of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (j)(1), (j)(2), or (j)(3) of this AD, which is not incorporated by reference in this AD.

- (1) Airbus Service Bulletin A330-25-3538, dated September 10, 2013.
- (2) Airbus Service Bulletin A330-25-3538, Revision 01, dated April 24, 2014.
- (3) Airbus Service Bulletin A340-25-4351, dated September 10, 2014.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as required by paragraph (h)(2)(ii) of this AD, if Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014; or Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014; contain procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures and tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from, using accepted methods in accordance with the operators maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0127, dated May 15, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2015-0083-0002>.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-25-3538, Revision 02, dated April 24, 2014.

(ii) Airbus Service Bulletin A330-25-3548, dated October 31, 2013.

(iii) Airbus Service Bulletin A340-25-4351, Revision 01, dated January 31, 2014.

(iv) Airbus Service Bulletin A340-25-4354, dated October 31, 2013.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 9, 2015.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.