

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

**LARGE AIRCRAFT
BIWEEKLY 2018-26**

12/10/2018 - 12/23/2018



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects

Biweekly 2018-01

2017-26-06		Rolls-Royce Corporation	AE 3007A, AE 3007A1, AE 3007A1/1, AE 3007A1/2, AE 3007A1/3, AE 3007A1P, AE 3007A1E, AE 3007A3, AE 3007C and 3007C1 turbofan engines
2017-26-07		The Boeing Company	757-200, -200CB, and -300 series airplanes
2017-26-08		ATR-GIE Avions de Transport Régional	ATR42-500 and ATR72-212A airplanes
2017-26-09		ATR-GIE Avions de Transport Régional	ATR42-500 and ATR72-212A airplanes
2017-26-10		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes,
2018-01-01		The Boeing Company	MD-11 and MD-11F airplanes
2018-01-02	R 2017-02-03	The Boeing Company	767-200, -300, and -400ER series airplanes
2018-01-03		Airbus	A300, A310 airplanes
2018-01-04	R 2011-04-05	Airbus	A340 airplanes
2018-01-05		Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes
2018-01-06		Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes

Biweekly 2018-02

2018-01-07		Airbus	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes
2018-01-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-01-09	R 95-25-02	Fokker Services B.V.	F28 Mark 0100 series airplanes
2018-01-10	R 2011-14-10	Airbus	A330-342 airplanes
2018-01-11		Airbus	A319-115 and A319-133 airplanes
2018-02-03		Fokker Services B.V.	F28 Mark 0070 and Mark 0100 series airplanes
2018-02-06		Dassault Aviation	FALCON 7X, FALCON 2000EX, FALCON 900EX airplanes

Biweekly 2018-03

2018-02-09	R 2008-06-20 R1	Fokker Services B.V.	F28 Mark 1000, 2000, 3000, and 4000 airplanes
2018-02-10		Pratt & Whitney Division	PW4074, PW4074D, PW4077, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
2018-02-11		Airbus	A330-301, -321, -322 and A330-342 airplanes
2018-02-12	R 2016-02-01	Airbus	A320-211, -212, and -231 airplanes
2018-02-15	S 2007-08-06	British Aerospace Regional Aircraft	HP.137 Jetstream Mk.1, Jetstream Series 200 and 3101, and Jetstream Model 3201 airplanes
2018-02-16		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes

Biweekly 2018-04

2018-02-17	R 2012-12-12 R 2013-16-26	Airbus	A330, A340 airplanes
2018-02-18		Airbus	A318, A319, A320, A321 airplanes
2018-02-20		The Boeing Company	777-200, -200LR, -300, and -300ER series airplanes
2018-03-02		328 Support Services GmbH	328-300 airplanes
2018-03-04		Rosemount Aerospace, Inc.	Model 851AK pitot probes
2018-03-06	R 2015-02-18	Airbus	A330-201, -202, -203, -301, -302, and -303 airplanes
2018-03-07		Airbus	A330-202, -203, -223, and -243; A340-211, -212, -311, and -313 airplanes
2018-03-08	R 2005-19-28	Airbus	A330-301, -321, -322, and -342; A340-211, -212, -213, -311, -312, and -313 airplanes
2018-03-09		Airbus	A321-211 and -231 airplanes
2018-03-10		The Boeing Company	757-300 series airplanes
2018-03-11		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2018-03-12		Airbus	A318, A319, A320, A321 airplanes
2018-03-13		General Electric Company	CT7-5A2, CT7-5A3, CT7-7A, CT7-7A1, CT7-9B, CT7-9B1, CT7-9B2, CT7-9C and CT7-9C3 model turboprop engines
2018-03-19		Dassault Aviation	FALCON 7X airplanes,
2018-03-20		Airbus	A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes
2018-03-21		Airbus	A330-202, -203, -223, and -243 airplanes
2018-03-22		GE Aviation Czech s.r.o.	M601D-11, M601E-11, M601E-11A, M601E-11AS, M601E-11S, and M601F turboprop engines
2018-04-01		Airbus	A320-271N, A321-271N, and A321-272N airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects			
Biweekly 2018-05			
2017-06-06	R 2012-22-15	Fokker Services B.V.	F28 Mark 0070 and Mark 0100 airplanes
2018-04-03		Fokker Services B.V.	F28 Mark 0100 airplanes
2018-04-04		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2018-04-05		Airbus	A319-112, A319-115, A320-214, A320-232, and A321-211 airplanes
2018-04-06	R 2012-12-05	The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-04-07		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes
2018-04-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
Biweekly 2018-06			
2018-02-17	R 2012-12-12	Airbus	A330, A340 airplanes
2018-04-12		The Boeing Company	737-100, -200, -200C, -300, -400, -500 series airplanes
2018-04-13		Honeywell International Inc.	AS907-1-1A model turbofan engines
2018-05-04		Airbus	A318, A319, A320, A321 airplanes
2018-05-05		Dassault Aviation	MYSTERE-FALCON 900, FALCON 900EX, FALCON 2000, and FALCON 2000EX airplanes
2018-05-06	R 2016-09-12	The Boeing Company	787-8 and 787-9 airplanes
2018-05-07		The Boeing Company	787-8 and 787-9 airplanes
2018-05-11		Airbus	A320-214, -251N, and -271N airplanes
2018-06-03	R 2009-18-16	Airbus	A310-203, -204, -221, -222, -304, -322, -324 and -325 airplanes
2018-06-06		Bombardier, Inc.	CL-600-2B16 (CL-604 Variant) airplanes
2018-06-08		The Boeing Company	757-200 series airplanes
Biweekly 2018-07			
2018-06-01		Airbus	A318, A319, A320, A321 airplanes
2018-06-02		Bombardier, Inc.	CL-600-2B19, -2C10, -2D15, -2D24 airplanes
2018-06-04		Airbus	A318, A319, A320, A321 airplanes
2018-06-05		The Boeing Company	737-300 and -500 series airplanes
2018-06-07		The Boeing Company	757-200, -200CB, and -300 series airplanes
Biweekly 2018-08			
2018-07-05		General Electric Company	CF6-80A, -80A1, -80A2, and -80A3 turbofan engines
2018-07-06		The Boeing Company	747-8 series airplanes
2018-07-07		Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES D, E, F, and G; MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes
2018-07-09		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2018-07-10		Embraer S.A.	EMB-500 and EMB-505 airplanes
2018-07-11		Fokker Services B.V.	F28 Mark 0100 airplanes
2018-07-12		Airbus	A350-941 airplanes
Biweekly 2018-09			
2018-07-18	R 2015-19-12	The Boeing Company	767-200, -300, -300F, and -400ER series airplanes
2018-07-19		The Boeing Company	787-8 and 787-9 airplanes
2018-07-20	R 2014-03-07	The Boeing Company	MD-11 and MD-11F airplanes
2018-07-21	R 2005-12-16	Fokker Services B.V.	F28 Mark 0100 airplanes
2018-08-02		Rolls-Royce plc	Trent 1000-A2, Trent 1000-AE2, Trent 1000-C2, Trent 1000-CE2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 turbofan engines
2018-08-03		The Boeing Company	787-8 and 787-9 airplanes
2018-09-05		The Boeing Company	787-8 and 787-9 airplanes
2018-09-51		CFM International S.A.	CFM56-7B engines
Biweekly 2018-10			
2018-09-01		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-09-02	R 99-23-16	Airbus	A330 and A340 airplanes
2018-09-03	R 2009-11-08	Airbus	A330-202, -223, -243, -301, -322, and -342 airplanes
2018-09-04		Gulfstream Aerospace Corporation	G-IV, GIV-X airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects			
2018-09-07		Rolls-Royce plc	Viper Mk. 601-22 engines
2018-09-08		The Boeing Company	737-200, -300, -400, and -500 series airplanes
2018-09-09		Airbus	A318, A319, A320, and A321 airplanes
2018-09-10		CFM International S.A.	CFM56-7B engines
2018-09-11		Airbus	A330 and A340 airplanes
2018-09-15	R 2016-25-18	Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2018-09-16	R 2015-15-13	Airbus	A319, A320, and A321 airplanes
2018-10-02		The Boeing Company	787-8 airplanes
Biweekly 2018-11			
2018-09-09	Republication	Airbus	A318, A319, A320, and A321 airplanes
2018-09-12		The Boeing Company	747-200B, 747-300, and 747-400 series airplanes
2018-09-13		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-09-14	R 2016-11-02	Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, and -2E25 airplanes
2018-09-17		Bombardier, Inc.	CL-600-1A11, -2A12, and -2B16 airplanes
2018-09-51		CFM International S.A.	CFM56-7B engines
2018-10-05	R 2016-23-01	Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2018-10-08	R 2016-09-05	The Boeing Company	717-200 airplanes
2018-10-11	R 2018-09-10	CFM International S.A.	CFM56-7B engines
2018-10-12		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-11-02		Lockheed Martin Corporation/Lockheed Martin Aeronautics Company	188A and 188C airplanes; and P3A, P-3A, and P3B airplanes
Biweekly 2018-12			
2018-11-04		Aircraft Industries a.s.	L 410 UVP-E20 and L 410 UVP-E20 CARGO airplanes
2018-11-06		Airbus	A310-203, -221, -222, -304, -322, -324, and -325 airplanes
2018-11-07		Saab AB, Saab Aeronautics	SAAB 2000 airplanes
2018-11-08		The Boeing Company	767-200 and -300 series airplanes
2018-11-09	R 2014-02-01	Bombardier, Inc.	CL-600-2C10, -2D15, -2D24 airplanes
2018-11-10	R 2017-01-07	Dassault Aviation	FAN JET FALCON, FAN JET FALCON SERIES C, D, E, F, and G; MYSTERE-FALCON 200, 20-C5, 20-D5, 20-E5, 20-F5, and 50 airplanes
2018-11-11		Airbus	A350-941 airplanes
2018-11-12		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2018-11-13		The Boeing Company	787-8 airplanes
2018-11-14		The Boeing Company	767-300 and -300F series airplanes
2018-11-15		Airbus	A320-271N; A321-271N, -271NX, -272N and -272NX airplanes
2018-12-02		Airbus	A318, A319, A320, A321 airplanes
2018-12-04		The Boeing Company	777-300ER series airplanes
2018-12-05		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
Biweekly 2018-13			
2016-19-13	COR	Dassault Aviation	See AD; FALCON 2000 was originally missing from the applicability table in AD Biweekly 2016-22.
2018-09-04	COR	Gulfstream Aerospace Corporation	G-IV, GIV-X airplanes
2018-11-16		Engine Alliance	GP7270, GP7272, and GP7277 model turbofan engines
2018-12-06		The Boeing Company	787-8 and 787-9 airplanes
2018-12-07	R 2015-24-06	Gulfstream Aerospace Corporation	GVI airplanes
2018-13-02		Pratt & Whitney Division	PW4052, PW4056, PW4060, PW4062, PW4062A, PW4152, PW4156A, PW4158, PW4460, and PW4462 turbofan engine models
2018-13-04		Bombardier, Inc.	BD-100-1A10 airplanes
Biweekly 2018-14			
2018-13-03		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects

Biweekly 2018-15

2018-12-08	R 2017-07-07	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-212, -213, -312, and -313 airplanes	
2018-13-06	R 2016-01-11	The Boeing Company	767-300 and -300F series airplanes	
2018-13-08		Airbus	A318, A319, A320, A321 airplanes	
2018-14-02		The Boeing Company	777-200, -200LR, -300, and -300ER series airplanes	
2018-14-03		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes	
2018-14-04		Airbus	A330, A340 airplanes	
2018-14-05		Bombardier, Inc.	BD-100-1A10 airplanes	
2018-14-08		A 2016-11-03	The Boeing Company	777-200LR series airplanes
2018-14-09		Airbus	A318, A319, A320, A321 airplanes	
2018-14-11		ATR-GIE Avions de Transport Régional	ATR72-101, -102, -201, -202, -211, -212, and -212A airplanes	

Biweekly 2018-16

2018-07-04		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, and MD-90-30 airplanes
2018-13-07		Rolls-Royce plc	Trent 1000-A, Trent 1000-C, Trent 1000-D, Trent 1000-E, Trent 1000-G, and Trent 1000-H turbofan engines
2018-14-12		General Electric Company	GEnx-1B64, -1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, -1B70/75/P1, -1B70/75/P2, -1B70/P1, -1B70/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, and -1B74/75/P2 engines
2018-15-01		Rolls-Royce plc	Trent 1000-A, Trent 1000-C, Trent 1000-D, Trent 1000-E, Trent 1000-G, Trent 1000-H, Trent 1000-A2, Trent 1000-C2, Trent 1000-D2, Trent 1000-E2, Trent 1000-G2, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 engines
2018-15-03		The Boeing Company	787 series airplanes
2018-15-05		Airbus SAS	A319-115, -132, and -133 airplanes; and Model A320-214, -216, -232, -233, -251N, and -271N airplanes
2018-16-05		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2018-16-07		General Electric Company	GEnx-1B54, -1B58, -1B64, -1B67, -1B70, -1B54/P1, -1B58/P1, -1B64/P1, -1B67/P1, -1B70/P1, -1B54/P2, -1B58/P2, -1B64/P2, -1B67/P2, -1B70/P2, -1B70C/P1, -1B70/72/P1, -1B70/75/P1, -1B74/75/P1, -1B75/P1, -1B70C/P2, -1B70/72/P2, -1B70/75/P2, -1B74/75/P2, -1B75/P2, -1B76/P2, -1B76A/P2, -1B78/P2, -2B67, -2B67B, and -2B67/P turbofan engines

Biweekly 2018-17

2018-16-02		Airbus SAS	A318, A319, A320, and A321 airplanes
2018-16-03		Airbus SAS	A319-133 and A321-232 airplanes
2018-16-04		Airbus SAS	A318, A319, A320, and A321 airplanes
2018-16-06		The Boeing Company	747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, -400, -400D, 747SP, and 747SR series; 747-8 airplanes
2018-16-12		Airbus	A319, A320, and A321 airplanes
2018-17-02		Bombardier, Inc.	CL-600-1A11, -2A12, -2B16 airplanes
2018-17-03		The Boeing Company	787-8 and 787-9 airplanes
2018-17-04		Roll-Royce Corporation	AE 2100D2A, AE 2100D3 turboprop engines; AE 3007A2 turbofan engines
2018-17-05		Airbus SAS	A350-941 and -1041 airplanes
2018-17-06		Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes
2018-17-07	R 2017-24-01	ATR-GIE Avions de Transport Régional	ATR42-500 and ATR72-212A airplanes

Biweekly 2018-18

2018-14-10	R 2017-12-03	Pratt & Whitney Division	PW2037, PW2037M, and PW2040 turbofan engines
2018-15-04		General Electric Company	CF6-80 series engines
2018-16-10		GE Aviation Czech s.r.o.	H80-200 turboprop engines
2018-17-09		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2018-17-10	R 2017-15-17	Airbus SAS	A300 B4-605R and B4-622R; A300 C4-605R Variant F; A300 F4-605R and F4-622R airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects			
2018-17-16		Airbus SAS	A300, A310 airplanes
2018-17-17		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2018-17-18	R 2015-02-17	Airbus SAS	A330 airplanes
2018-17-19		Airbus SAS	A318, A319, A320, A321 airplanes
2018-17-20		The Boeing Company	727, 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes
2018-17-21		Airbus SAS	A318, A319, A320, A321 airplanes
2018-17-22		Airbus SAS	A319-115 and -132, and A320-214, -216, -232, and -233 airplanes
2018-17-23		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-18-04		Airbus SAS	A350-941 and -1041 airplanes
2018-18-05		ATR-GIE Avions de Transport Régional	ATR42-200, -300, and -320 airplanes
Biweekly 2018-19			
2018-17-12		General Electric Company	GE90-76B, GE90-77B, GE90-85B, GE90-90B, and GE90-94B turbofan engines
2018-17-13		Rolls-Royce Deutschland Ltd & Co KG	Tay 620-15 turbofan engines
2018-17-24		Airbus SAS	A350-941 airplanes
2018-17-25		Airbus SAS	A350-941 and -1041 airplanes
2018-18-03		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-18-06	R 2013-02-04	Rolls-Royce plc	RB211-Trent 970-84, RB211-Trent 970B-84, RB211-Trent 972-84, RB211-Trent 972B-84, RB211-Trent 977-84, RB211-Trent 977B-84, and RB211-Trent 980-84 turbofan engines
2018-18-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series airplanes
2018-18-08		Airbus SAS	A330, A340 airplanes
2018-18-09		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes
2018-18-10		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes
2018-18-13		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-18-14		Rolls-Royce Deutschland Ltd & Co KG	BR700-710A2-20, BR700-710C4-11 turbofan engines
2018-18-16	R 2018-12-08	Airbus SAS	A330, A340 airplanes
2018-18-17	R 2016-13-06	Saab AB, Saab Aeronautics	340A (SAAB/SF340A), 340B airplanes
Biweekly 2018-20			
2018-16-09		The Boeing Company Airplanes	737-100, -200, -200C, -300, -400, and -500
2018-16-13		Zodiac Seats France	Note: This AD was inadvertently left out of BW 2018-17
2018-18-15		Rolls-Royce plc	537-Series Cabin Attendant Seats
2018-18-18		Airbus SAS	RB211-Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17 and 895-17 turbofan engines
2018-18-19		Airbus SAS	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2018-18-20		Airbus SAS	A300 and A310 airplanes
2018-18-21		Airbus SAS	A300 and A310 airplanes
2018-19-02		Airbus Defense and Space S.A.	A300 and A310 airplanes
2018-19-03		Fokker Services B.V.	C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes
2018-19-04		Learjet, Inc.	F28 Mark 0070 and 0100 airplanes
2018-19-05		Dassault Aviation	28, 29, 31, 31A, 35, 35A, 36, 36A, 55, 55B, 55C, and 60 airplanes
2018-19-12	R 2015-17-04	Bombardier, Inc.	MYSTERE-FALCON 900 airplanes
2018-19-13		328 Support Services GmbH	CL-600-2C10, -2D15, and -2D24 airplanes
2018-19-14		Dassault Aviation	328-100 and -300 airplanes
2018-19-17		Airbus SAS	FALCON 2000 and FALCON 2000EX airplanes
2018-19-19		Airbus SAS	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203 airplanes
2018-19-20	R 2010-25-06	The Boeing Company	A350-941 airplanes
			737-200, -300, -400, and -500 series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects			
2018-19-21		The Boeing Company	707-100 long body, -200, -100B long body, -100B short body, -300, -300B, -300C, and -400 series; 720 and 720B series airplanes
2018-19-25		Dassault Aviation	FALCON 2000 airplanes
2018-19-28		Embraer S.A.	ERJ 190-100 ECJ, -100 STD, -100 LR, and -100 IGW; and Model ERJ 190-200 STD, -200 LR, and -200 IGW airplanes
2018-19-30		BAE Systems (Operations) Limited	4101 airplanes
2018-19-31		Airbus SAS	A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes
2018-19-32		The Boeing Company	707-100 Long Body, -200, -100B Long Body, and -100B Short Body; 707-300, -300B, -300C, and -400; and 720 and 720B series airplanes
2018-19-33		Airbus SAS	A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes
2018-20-02	R 98-18-24	Airbus SAS	A320-211 and A320-231 airplanes
2018-20-04		Gulfstream Aerospace Corporation	GVI airplanes
2018-20-05		The Boeing Company	727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes
Biweekly 2018-21			
2018-17-14		General Electric Company	CF34-8E turbofan engines
2018-18-01	R 2018-10-11	CFM International S.A.	CFM56-7B engines
2018-19-06		Dassault Aviation	FALCON 900EX airplanes
2018-19-07		Airbus SAS	A300, A310 airplanes
2018-19-15		GEVEN S.p.A.	Type D1-02 and D1-03 in-arm table, standard, and last row seats
2018-19-16		CFM International S.A.	CFM LEAP-1A23, -1A24, -1A24E1, -1A26, -1A26E1, -1A26CJ, -1A29, -1A29CJ, -1A30, -1A32, -1A33, -1A33B2, and -1A35A turbofan engines
2018-19-18		Airbus SAS	A300 B4-603, A300 B4-620, A300 B4-622, A300 B4-605R, A300 B4-622R, A300 C4-605R Variant F, and A300 F4-605R airplanes
2018-19-22		General Electric Company	CF34-10A16, CF34-10E2A1, CF34-10E5, CF34-10E5A1, CF34-10E6, CF34-10E6A1, CF34-10E7, and CF34-10E7-B turbofan engines
2018-19-23	R 2013-01-02	The Boeing Company	747 and 757 airplanes
2018-19-24		BAE Systems (Operations) Limited	4101 airplanes
2018-19-26		Dassault Aviation	MYSTERE-FALCON 200 airplanes
2018-19-27		Dassault Aviation	FALCON 2000EX airplanes
2018-19-29		Airbus SAS	A330 and A340 airplanes
2018-20-06	R 2016-25-03	Airbus SAS	A300 F4-605R and A300 F4-622R airplanes
2018-20-07		Dassault Aviation	MYSTERE-FALCON 50 airplanes
2018-20-08		Airbus SAS	A318, A319, A320, and A321 airplanes
2018-20-10		Airbus SAS	A350-941 airplanes
2018-20-13		The Boeing Company	737 (see AD), 757, and 767 airplanes
Biweekly 2018-22			
2018-20-11		Bombardier, Inc.	DHC-8-301, -311, and -315 airplanes
2018-20-12		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 airplanes
2018-20-13		The Boeing Company	737, 757, 767 series airplanes (see AD)
2018-20-14		ATR-GIE Avions de Transport Régional	ATR42-500 airplanes
2018-20-15	R 2015-09-07	The Boeing Company	787-8 and 787-9 airplanes
2018-20-16	R 2013-11-12	Bombardier, Inc.	BD-100-1A10 airplanes
2018-20-17	R 2012-22-10	Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2018-20-18		Bombardier, Inc.	DHC-8-400, -401, and -402 airplanes
2018-20-19	R 2017-16-07	Airbus SAS	A330, A340 airplanes
2018-20-20		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2018-20-21		Bombardier, Inc.	CL-600-2B16 (CL-604 Variants) airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects			
2018-20-22		General Electric Company	GE90-110B1, GE90-113B, and GE90-115B turbofan engines
2018-20-23	R 2017-07-04	General Electric Company	GE90-110B1 and GE90-115B turbofan engines
2018-20-24		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series airplanes
2018-21-01	R 2017-20-06	Honeywell International Inc.	AS907-1-1A turbofan engines
2018-21-03		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2018-21-05		Airbus SAS	A319-131, A319-132, A319-133, A320-231, A320-232, A320-233, A321-131, A321-231, and A321-232 airplanes
2018-21-07		Airbus SAS	A330 airplanes
2018-21-08		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes
2018-21-09	R 2006-07-26	ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500 airplanes
2018-22-03	R 2016-24-03	Bombardier, Inc.	DHC-8-400, -401 and -402 airplanes
2018-22-04	R 2017-01-02	The Boeing Company	787 series airplanes
Biweekly 2018-23			
2018-21-10		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2018-21-11		Pratt & Whitney Division	PW4074D, PW4077D, PW4084D, PW4090, and PW4090-3 turbofan engines
2018-22-02		International Aero Engines	PW1133G-JM, PW1133GA-JM, PW1130G-JM, PW1127G-JM, PW1127GA-JM, PW1127G1-JM, PW1124G-JM, PW1124G1-JM, and PW1122G-JM turbofan engines
2018-22-05		Engine Alliance	GP7270, GP7272, and GP7277 turbofan engines
2018-22-06		Pratt & Whitney	PW2037, PW2037M, and PW2040 turbofan engines
2018-22-08		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2018-22-09		The Boeing Company	787 series airplanes
2018-22-10	R 2016-04-16	The Boeing Company	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, and DC-10-40F; MD-10-10F, MD-10-30F, MD-11, and MD-11F airplanes
2018-22-12		Bombardier, Inc.	CL-600-2C10, -2D15, -2D24, -2E25 airplanes
2018-22-13		Airbus SAS	A350-941 and -1041 airplanes
2018-23-03		Airbus SAS	A318, A319, A320, A321 airplanes
2018-23-05		Airbus SAS	A350-941, A350-1041 airplanes
2018-23-51		The Boeing Company	737-8 and -9 airplanes
Biweekly 2018-24			
2018-20-11		Bombardier, Inc.	DHC-8-301, -311, and -315 airplanes
2018-23-01		Zodiac Seats France	Cabin Attendant Seats, 536 Series
2018-23-02		Airbus SAS	A318, A319, A320, and A321 airplanes
2018-23-07		Airbus SAS	A350-941 airplanes
2018-23-09	R 2016-13-16	The Boeing Company	737-600, -700, -700C, -800, -900, and 900ER series airplanes
2018-23-10		Airbus SAS	A350-941 airplanes
2018-23-11		Airbus SAS	A319, A320, and A321 airplanes
2018-23-12		Zodiac Aero Evacuation Systems	Fusible plugs installed on emergency evacuation equipment
2018-23-15		Airbus SAS	A330 and A340 airplanes
Biweekly 2018-25			
2018-20-01		CFM International S.A.	LEAP-1B21, LEAP-1B23, LEAP-1B25, LEAP-1B27, LEAP-1B28, LEAP-1B28B1, LEAP-1B28B2, LEAP-1B28B2C, LEAP-1B28B3, LEAP-1B28BBJ1, and LEAP-1B28BBJ2 turbofan engines
2018-21-12		General Electric Company	GENx-2B67, -2B67B, and -2B67/P turbofan engines
2018-23-13		The Boeing Company	747-8 and 747-8F series
2018-23-14		Airbus SAS	A330 airplanes
2018-23-51		The Boeing Company	737-8 and -9 airplanes
2018-24-02		Dassault Aviation	MYSTERE-FALCON 50, MYSTERE-FALCON 900, and FALCON 900EX airplane
2018-24-03		Dassault Aviation	Falcon 10 airplanes
2018-24-04		Airbus SAS	A330 airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E – Emergency; COR – Correction; S – Supersedes; R – Replaces, A – Affects			
2018-24-05		Fokker Services B.V.	F28 Mark 0070, 0100, 1000, 2000, 3000, and 4000 airplanes
2018-25-01	R 2018-13-07	Rolls-Royce plc	Trent 1000-A, Trent 1000-C, Trent 1000-D, Trent 1000-E, Trent 1000-G, and Trent 1000-H turbofan engine models
2018-25-02		Airbus SAS	A318, A319, A320, A321 airplanes
93-14-19R1	R 93-14-19	The Boeing Company	767 series airplanes
Biweekly 2018-26			
2018-23-08		Airbus SAS	A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes
2018-23-51		The Boeing Company	737-8 and -9 airplanes
2018-25-03		Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes
2018-25-04		C Series Aircraft Limited Partnership	BD-500-1A10 and -1A11 airplanes
2018-25-05		Airbus SAS	A350-941 airplanes
2018-25-06		Airbus SAS	A330-223F and A330-243F airplanes
2018-25-07		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11 airplanes
2018-25-09		CFM International S.A.	LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B2C, -1B28B3, -1B28BBJ1, and -1B28BBJ2 turbofan engines
2018-25-10	R 2018-11-07	Saab AB, Saab Aeronautics	SAAB 2000 airplanes
2018-25-11		The Boeing Company	777-200 and -300 series airplanes
2018-25-12		Airbus SAS	A350-941 airplanes
2018-25-13		Dassault Aviation	FALCON 2000 airplanes
2018-25-14		Fokker Services B.V.	F28 Mark 0070 and 0100 airplanes
2018-25-15		The Boeing Company	727, 727-100, 727-100C, 727-200, 727-200F, and 727C series airplanes
2018-25-16		Airbus Defense and Space S.A.	CN-235, CN-235-200, and CN-235-300 airplanes
2018-25-18		ATR-GIE Avions de Transport Régional	ATR42-200, -300, -320, and -500 airplanes; and Model ATR72-101, -102, -201, -202, -211, -212, and -212A airplanes



2018-23-08 Airbus SAS: Amendment 39-19494; Docket No. FAA-2018-0584; Product Identifier 2017-NM-173-AD.

(a) Effective Date

This AD is effective January 16, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

(e) Reason

This AD was prompted by reports of dual flight management system (FMS) resets with the loss of flight plan (F-PLN) data. We are issuing this AD to address dual FMS reset and loss of F-PLN data, which in the context of required navigation performance-authorization required (RNP-AR) operations of the airplane could result in significantly reduced situational awareness of proximity to terrain and/or other aircraft to below acceptable safety margins, and out of the context of RNP-AR operations could lead to an unusually high pilot workload.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purposes of this AD, the definitions in paragraphs (g)(1) through (g)(3) of this AD apply.

(1) Group 1 airplanes are those that have flight management guidance envelope computer (FMGEC) standard P5H3 (Airbus SAS Modification 204758 Part Number (P/N) FMGEC C13226HA07 with P/N FMS operational SW PS4087700-906) embodied in production, or embodied in service as specified in Airbus Service Bulletin A330-22-3209; Airbus Service Bulletin A330-22-3225; Airbus Service Bulletin A330-22-3244; Airbus Service Bulletin A330-22-3247; or Airbus Service Bulletin A330-22-3262; except those that have RNP-AR.

(2) Group 2 airplanes have the same configuration as those in Group 1, but in addition have RNP-AR (Airbus SAS Modification 203441, or Airbus SAS Modification 203442, or Airbus SAS Modification 200624) embodied in production or Airbus Service Bulletin A330-34-3262; Airbus Service Bulletin A330-34-3308; or Airbus Service Bulletin A330-34-3345; embodied in service.

(3) Group 3 airplanes are those in any configuration other than that identified in paragraph (g)(1) or (g)(2) of this AD.

(h) Airplane Flight Manual (AFM) Revision

For Group 2 airplanes: Within 30 days after the effective date of this AD, revise the Limitations section of the Airbus A330/A340 AFM to include the information in Airbus A330/A340 AFM Temporary Revision TR774, RNP AR Operations Forbidden with FMGEC Standard P5H3, Issue 1, dated October 16, 2017 (“TR774”), and inform all flight crews, and, thereafter, operate the airplane accordingly, as specified in TR774. TR774 prohibits the RNP-AR operation on Airbus SAS Model A330 series airplanes equipped with FMGEC standard P5H3. Revising the AFM to include TR774 may be done by inserting a copy of TR774 in the AFM. When TR774 has been included in general revisions of the AFM, the general revisions may be inserted in the AFM, provided the relevant information in the general revision is identical to that in TR774, and TR774 may be removed.

Note 1 to paragraph (h) of this AD: The Airbus A330/A340 AFM for the aircraft affected by this AD is required to be furnished with the aircraft, in accordance with 14 CFR 25.1581. Further, operators of the aircraft affected by this AD must operate in accordance with the limitations specified in the AFM, in accordance with 14 CFR 91.9.

(i) FMS Software Modification

(1) For Group 1 and Group 2 airplanes: Within 60 days after the effective date of this AD, modify the airplane by installing FMS software P4A (P/N FMS operational SW PS4087700-905) on FMGEC standard P5H3 (P/N FMGEC C13226HA07 with P/N FMS operational SW PS4087700-906), in accordance with the instructions of Airbus Service Bulletin A330-22-3264, dated March 14, 2018.

(2) For Group 2 airplanes: After modification of an airplane as required by paragraph (i)(1) of this AD, the AFM revision required by paragraph (h) of this AD may be removed from the AFM of that airplane.

(j) Optional Modification

For Group 3 airplanes: From the effective date of this AD, it is allowed to modify any airplane into a Group 1 or Group 2 configuration, provided that, concurrently, that airplane is modified in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-22-3264, dated March 14, 2018.

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (i) of this AD and optional actions specified in paragraph (j) of this AD, if those actions were performed before the effective date of this AD using Airbus Alert Operators Transmission-AOT A22L002-17, dated October 20, 2017.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested

using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA authorized signature.

(3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2017-0233, dated November 23, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0584.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-22-3264, dated March 14, 2018.

(ii) Airbus A330/A340 Airplane Flight Manual Temporary Revision TR774, RNP AR Operations Forbidden with FMGEC Standard P5H3, Issue 1, dated October 16, 2017.

(3) For Airbus SAS service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 2, 2018.
Jeffrey E. Duven,
Director, System Oversight Division,
Aircraft Certification Service.



2018-23-51 The Boeing Company: Amendment 39-19512; Docket No. FAA-2018-0960; Product Identifier 2018-NM-151-AD.

(a) Effective Date

This AD is effective December 21, 2018 to all persons except those persons to whom it was made immediately effective by Emergency AD 2018-23-51, issued on November 7, 2018, which contained the requirements of this amendment.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 737-8 and -9 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Unsafe Condition

This AD was prompted by analysis performed by the manufacturer showing that if an erroneously high single angle of attack (AOA) sensor input is received by the flight control system, there is a potential for repeated nose-down trim commands of the horizontal stabilizer. We are issuing this AD to address this potential resulting nose-down trim, which could cause the flight crew to have difficulty controlling the airplane, and lead to excessive nose-down attitude, significant altitude loss, and possible impact with terrain.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Airplane Flight Manual (AFM): Certificate Limitations

Within 3 days after the effective date of this AD, revise the Certificate Limitations chapter of the applicable AFM to include the information in figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) of this AD – Certificate Limitations**Required by AD 2018-23-51****Runaway Stabilizer**

In the event of an uncommanded horizontal stabilizer trim movement, combined with any of the following potential effects or indications resulting from an erroneous Angle of Attack (AOA) input, the flight crew must comply with the Runaway Stabilizer procedure in the Operating Procedures chapter of this manual:

- Continuous or intermittent stick shaker on the affected side only.
- Minimum speed bar (red and black) on the affected side only.
- Increasing nose down control forces.
- IAS DISAGREE alert.
- ALT DISAGREE alert.
- AOA DISAGREE alert (if the option is installed).
- FEEL DIFF PRESS light.
- Autopilot may disengage.
- Inability to engage autopilot.

(h) AFM Revision: Operating Procedures

Within 3 days after the effective date of this AD, revise the Operating Procedures chapter of the applicable AFM to include the information in figure 2 to paragraph (h) of this AD.

Figure 2 to paragraph (h) of this AD – Operating Procedures**Required by AD 2018-23-51****Runaway Stabilizer**

Disengage autopilot and control airplane pitch attitude with control column and main electric trim as required. If relaxing the column causes the trim to move, set stabilizer trim switches to CUTOOUT. If runaway continues, hold the stabilizer trim wheel against rotation and trim the airplane manually.

Note: The 737-8/-9 uses a Flight Control Computer command of pitch trim to improve longitudinal handling characteristics. In the event of erroneous Angle of Attack (AOA) input, the pitch trim system can trim the stabilizer nose down in increments lasting up to 10 seconds.

In the event an uncommanded nose down stabilizer trim is experienced on the 737-8/-9, in conjunction with one or more of the indications or effects listed below, do the existing AFM Runaway Stabilizer procedure above, ensuring that the STAB TRIM CUTOOUT switches are set to CUTOOUT and stay in the CUTOOUT position for the remainder of the flight.

An erroneous AOA input can cause some or all of the following indications and effects:

- Continuous or intermittent stick shaker on the affected side only.
- Minimum speed bar (red and black) on the affected side only.
- Increasing nose down control forces.
- IAS DISAGREE alert.
- ALT DISAGREE alert.
- AOA DISAGREE alert (if the option is installed).
- FEEL DIFF PRESS light.
- Autopilot may disengage.
- Inability to engage autopilot.

Initially, higher control forces may be needed to overcome any stabilizer nose down trim already applied. Electric stabilizer trim can be used to neutralize control column pitch forces before moving the STAB TRIM CUTOOUT switches to CUTOOUT. Manual stabilizer trim can be used before and after the STAB TRIM CUTOOUT switches are moved to CUTOOUT.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Douglas Tsuji, Senior Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3548; email: Douglas.Tsuji@faa.gov.

(k) Material Incorporated by Reference

None.

Issued in Des Moines, Washington, on November 21, 2018.
Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2018-25-03 Fokker Services B.V.: Amendment 39-19514; Docket No. FAA-2018-0767; Product Identifier 2018-NM-068-AD.

(a) Effective Date

This AD is effective January 14, 2019.

(b) Affected ADs

This AD affects AD 2010-22-05, Amendment 39-16484 (75 FR 66649, October 29, 2010) (“AD 2010-22-05”).

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by service experience showing that debris from the parking brake shut off valve (PBSOV) could create a partial blockage of the restrictor check valve in the hydraulic return line of the PBSOV. We are issuing this AD to address this condition, which, if not corrected, may prevent complete main landing gear extension, possibly resulting in damage to the airplane during landing, and consequent injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purposes of this AD, the definitions in paragraphs (g)(1) through (g)(3) apply.

(1) An affected part is any hydraulic restrictor check valve having part number (P/N) D71293-003, P/N D71295-401, or P/N D71296-401.

(2) Group 1 airplanes are those that have an affected part installed.

(3) Group 2 airplanes are those that do not have an affected part installed.

(h) Required Actions

For Group 1 airplanes, within 24 months after the effective date of this AD, modify the airplane by replacing each affected part with a restrictor check valve that has a filter screen, P/N CKLX0517200B or P/N CKLX0520100B, as applicable, in accordance with the accomplishment instructions of Fokker Service Bulletin SBF100-32-163, Revision 1, dated February 21, 2018.

(i) Parts Installation Prohibition

Do not install an affected part on any airplane, as required by paragraph (i)(1) or (i)(2) of this AD, as applicable.

(1) For Group 1 airplanes: After modification of the airplane as required by paragraph (h) of this AD.

(2) For Group 2 airplanes: From the effective date of this AD.

(j) Terminating Actions for AD 2010-22-05

Accomplishing the actions required by paragraph (h) of this AD terminates all requirements of AD 2010-22-05.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA, FAA; or the European Aviation Safety Agency (EASA); or Fokker Services B.V.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2018-0077, dated April 6, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0767.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-32-163, Revision 1, dated February 21, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-04 C Series Aircraft Limited Partnership (CSALP) (Type Certificate Previously Held by Bombardier, Inc.): Amendment 39-19515; Docket No. FAA-2018-0799; Product Identifier 2018-NM-117-AD.

(a) Effective Date

This AD is effective January 14, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to C Series Aircraft Limited Partnership (CSALP) (Type Certificate Previously Held by Bombardier, Inc.) airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model BD-500-1A10 airplanes, serial numbers 50001 and subsequent, equipped with blow-out panel part number D762213-503, D762216-505, or D762209-503.

(2) Model BD-500-1A11 airplanes, serial numbers 55001 and subsequent, equipped with blow-out panel part number D762213-503, D762216-505, or D762209-503.

(d) Subject

Air Transport Association (ATA) of America Code 50, Cargo and accessory compartment.

(e) Reason

This AD was prompted by reports of dislodged cargo compartment blow-out panels. We are issuing this AD to address this condition, which could result in openings in the forward and aft cargo compartments. In the event of a cargo compartment fire, these unintended openings in the forward and aft cargo compartments would provide a path for smoke, fire, and Halon to enter the adjacent equipment bays, flight deck, and passenger cabin, which could delay smoke detection in the forward and aft cargo compartments and result in the forward and aft cargo compartments not being able to maintain the Halon concentration required for fire suppression. The cargo compartment fire may become uncontrollable if this condition is not addressed, which could result in the loss of controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections of the Forward and Aft Cargo Compartment Blow-Out Panels and Re-Installation

Within 7 days or 50 flight cycles, whichever occurs first, after the effective date of this AD, do a detailed inspection for any dislodged blow-out panel in the forward and aft cargo compartments, in accordance with C Series (Bombardier) Data Module BD500-A-J50-10-01-01AAA-310B-A, "Forward and aft cargo compartment blow-out panels–Visual check," Issue 002, dated May 16, 2018. Re-install all dislodged forward and aft cargo compartment blow-out panels before further flight, in accordance with C Series (Bombardier) Data Module BD500-A-J50-10-01-00AAA-521A-A, "Decompression panels dislodging–Return to basic configuration," Issue 002, dated May 16, 2018. Thereafter, at intervals not to exceed 100 flight cycles, repeat the detailed inspection for any dislodged blow-out panel in the forward and aft cargo compartments.

(h) Reporting

If any blow-out panel in the forward or aft cargo compartments is found dislodged during any inspection required by paragraph (g) of this AD, at the applicable time specified in paragraph (h)(1) or (h)(2) of this AD, report findings to the Bombardier customer response center (CRC) via email: crc_cseries@aero.bombardier.com. Reportable findings include the airplane serial number on which any dislodged blow-out panel was found, the date of inspection, and the part number and location of each dislodged blow-out panel.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(i) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or C Series Aircraft Limited Partnership's (CSALP's) TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-15, dated June 6, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0799.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Admin Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516 794 5531; email 9-avs-nyaco-cos@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) C Series (Bombardier) Data Module BD500-A-J50-10-01-00AAA-521A-A, “Decompression panels dislodging–Return to basic configuration,” Issue 002, dated May 16, 2018.

(ii) C Series (Bombardier) Data Module BD500-A-J50-10-01-01AAA-310B-A, “Forward and aft cargo compartment blow-out panels–Visual check,” Issue 002, dated May 16, 2018.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-05 Airbus SAS: Amendment 39-19516; Docket No. FAA-2018-0761; Product Identifier 2018-NM-088-AD.

(a) Effective Date

This AD is effective January 14, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A350-941 airplanes, certificated in any category, as identified in Airbus Service Bulletin A350-52-P012, dated September 7, 2017.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by reports that, for multimaterial (hybrid) joints of the passenger door frame fittings, the interfay sealant was not applied between all surfaces of the joint parts. We are issuing this AD to address water ingress in the hybrid joints and subsequent galvanic corrosion of the aluminum holes. This condition, if not corrected, could lead to failure of the door, resulting in reduced evacuation capacity from the airplane during an emergency and consequent injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification of Passenger Door Hybrid Joints

Within 48 months after the date of issuance of the original certificate of airworthiness or the original export certificate of airworthiness, whichever occurs earlier: Apply additional corrosion protection (e.g. primer/topcoat or corrosion prevention compound) to the hybrid joints of the left-hand and right-hand sides of the passenger door frame fittings at doors 1, 2, 3 and 4, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A350-52-P012, dated September 7, 2017.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (i)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0108, dated May 15, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0761.

(2) For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A350-52-P012, dated September 7, 2017.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email continued-airworthiness.a350@airbus.com; internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-06 Airbus SAS: Amendment 39-19517; Docket No. FAA-2018-0800; Product Identifier 2018-NM-107-AD.

(a) Effective Date

This AD is effective January 14, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD; all manufacturer serial numbers.

- (1) Airbus SAS Model A330-223F airplanes.
- (2) Airbus SAS Model A330-243F airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by a report of cracking on both left-hand (LH) and right-hand (RH) sides on the internal strap, butt strap, keel beam fitting, or forward fitting frame (FR) 40 flange. We are issuing this AD to address cracking at FR40 on the lower shell panel junction; such cracking could lead to reduced structural integrity of the fuselage.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Compliance Times for the Actions Required by Paragraph (h) of This AD

Accomplish the actions required by paragraph (h) of this AD before exceeding the compliance time “threshold” defined in paragraph 1.E., “Compliance,” of Airbus Service Bulletin A330-53-3215, Revision 03, dated January 22, 2018 (“A330-53-3215, R3”), depending on airplane utilization and configuration and to be counted from airplane first flight, and, thereafter, at intervals not to exceed the compliance times defined in paragraph 1.E., “Compliance,” of A330-53-3215, R3, depending on airplane utilization and configuration.

(h) Repetitive Inspections and Related Investigative and Corrective Actions

At the applicable compliance times specified in paragraph (g) of this AD: Accomplish a special detailed inspection of the 10 fastener holes located at FR40 lower shell panel junction on both LH and RH sides, in accordance with the Accomplishment Instructions of A330-53-3215, R3.

(1) If, during any inspection required by the introductory text of paragraph (h) of this AD, any crack is detected, before further flight, accomplish all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of A330-53-3215, R3, except where A330-53-3215, R3 specifies to contact Airbus for repair instructions, and specifies that action as Required for Compliance (RC), this AD requires repair before further flight using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or European Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(2) If, during any inspection required by the introductory text of paragraph (h) of this AD, the diameter of a fastener hole is found to be outside the tolerances of the transition fit as specified in A330-53-3215, R3, as applicable; and A330-53-3215, R3; specifies to contact Airbus for repair instructions, and specifies that action as "RC," before further flight, repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Accomplishment of corrective actions, as required by paragraph (h)(1) of this AD, does not constitute terminating action for the repetitive inspections required by the introductory text of paragraph (h) of this AD.

(4) Accomplishment of a repair on an airplane, as required by paragraph (h)(2) of this AD, does not constitute terminating action for the repetitive inspections required by the introductory text of paragraph (h) of this AD for that airplane, unless the method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA indicates otherwise.

(i) No Reporting Requirement

Although A330-53-3215, R3, specifies to submit certain information to the manufacturer, and specifies that action as RC, this AD does not include that requirement.

(j) Credit for Previous Actions

This paragraph provides credit for the inspections required by the introductory text of paragraph (h) of this AD and the related investigative and corrective actions required by paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD, using Airbus Service Bulletin A330-53-3215, dated June 21, 2013; or Revision 01, dated April 17, 2014; or Revision 02, dated November 23, 2016.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal

inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Except as specified by paragraphs (h)(1), (h)(2), and (i) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0146, dated July 12, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0800.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-53-3215, Revision 03, dated January 22, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-07 Bombardier, Inc.: Amendment 39-19518; Docket No. FAA-2018-0796; Product Identifier 2018-NM-104-AD.

(a) Effective Date

This AD is effective January 15, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category, serial numbers 9001 through 9707 inclusive, 9709 through 9717 inclusive, 9719 through 9726 inclusive, 9728, 9730, 9732 through 9734 inclusive, 9736 through 9740 inclusive, 9742 through 9745 inclusive, 9749, 9751, 9757, and 9998.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of drainage holes on the belly fairing forward and middle access panels being obstructed with sealant. We are issuing this AD to address fluid leakage that could lead to the accumulation of flammable fluids/vapors, beyond the design capacity of the belly fairing venting provisions, which could ignite if an ignition source (i.e., spark, static discharge, heat, etc.) is present.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Sealant Removal

Within 375 flight hours or 12 months, whichever occurs first, after the effective date of this AD, do a general visual inspection for and remove all sealant blocking the drainage holes on the belly fairing forward and middle access panels, in accordance with the Accomplishment Instructions of the applicable service information listed in figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) of this AD – *Service bulletins*

Airplane Model	Bombardier Service Bulletin	Issue Date
BD-700-1A10	700-53-051	May 17, 2017
BD-700-1A10	700-53-6009	May 17, 2017
BD-700-1A11	700-1A11-53-026	May 17, 2017
BD-700-1A11	700-53-5010	May 17, 2017

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO Branch, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2018-14, dated May 1, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0796.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

- (i) Bombardier Service Bulletin 700-1A11-53-026, dated May 17, 2017.
- (ii) Bombardier Service Bulletin 700-53-051, dated May 17, 2017.
- (iii) Bombardier Service Bulletin 700-53-5010, dated May 17, 2017.
- (iv) Bombardier Service Bulletin 700-53-6009, dated May 17, 2017.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-09 CFM International S.A.: Amendment 39-19520; Docket No. FAA-2018-1023; Product Identifier 2018-NE-37-AD.

(a) Effective Date

This AD is effective December 26, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all CFM International S.A. (CFM) LEAP-1B21, -1B23, -1B25, -1B27, -1B28, -1B28B1, -1B28B2, -1B28B2C, -1B28B3, -1B28BBJ1, and -1B28BBJ2 turbofan engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7600, Engine Controls.

(e) Unsafe Condition

This AD was prompted by aborted takeoffs on the similarly designed CFM LEAP-1A model turbofan engine after those engines did not advance to the desired takeoff fan speed due to icing in the pressure sensor line. While we have not received any reports of aborted takeoffs with the CFM LEAP-1B model engine, the unsafe condition is likely to exist because of similarities in design and instances of ice and moisture found in the pressure sense subsystem lines. We are issuing this AD to prevent icing in the pressure sensor lines and inaccurate pressure sensor readings. The unsafe condition, if not addressed, could result in failure of one or more engines, loss of thrust control, and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 60 days after the effective date of this AD, remove electronic engine control (EEC) system operation (OPS) software, P/N 2628M86P10 or earlier; and engine health monitoring (EHM) software, P/N 2628M87P10 or earlier, from the engine and from service.

(2) Before further flight after the removal of the EEC OPS and EHM software required by paragraph (g)(1) of this AD, install EEC OPS and EHM software that is eligible for installation.

(h) Installation Prohibition

After 60 days from the effective date of this AD, do not operate any engine identified in paragraph (c) of this AD with EEC OPS software, P/N 2628M86P10 or earlier, installed; or EHM software, P/N 2628M87P10 or earlier, installed.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Christopher McGuire, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7120; fax: 781-238-7199; email: chris.mcguire@faa.gov.

(k) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on December 3, 2018.
Robert J. Ganley,
Manager, Engine and Propeller Standards Branch,
Aircraft Certification Service.



2018-25-10 Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems):
Amendment 39-19521; Docket No. FAA-2018-0797; Product Identifier 2018-NM-096-AD.

(a) Effective Date

This AD is effective January 14, 2019.

(b) Affected ADs

This AD replaces AD 2018-11-07, Amendment 39-19295 (83 FR 24399, May 29, 2018) (“AD 2018-11-07”).

(c) Applicability

This AD applies to Saab AB, Saab Aeronautics (formerly known as Saab AB, Saab Aerosystems) Model SAAB 2000 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Reason

This AD was prompted by the identification of a manufacturing defect on certain aileron bellcrank support brackets that resulted in insufficient material thickness of the affected lug attaching the support bracket to the rear spar of the wing. We are issuing this AD to detect and correct a defect of the aileron bellcrank support bracket, which, in the event of an aileron jam, could lead to failure of the support bracket and result in reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Definitions, With No Changes

(1) This paragraph restates the definition specified in paragraph (g)(1) of AD 2018-11-07, with no changes. For the purposes of this AD, affected support brackets are aileron bellcrank support brackets, part number (P/N) 7327993-813 and P/N 7327993-814, for which it has been determined that the affected lug attaching the support bracket to the rear spar of the wing has a thickness of less than 2.75 millimeters (mm) (0.108 inch (in.)), as specified in Saab Service Bulletin 2000-27-056, dated April 18, 2018.

(2) This paragraph restates the definition specified in paragraph (g)(2) of AD 2018-11-07, with no changes. For the purposes of this AD, serviceable support brackets are aileron bellcrank support

brackets, P/N 7327993-813 and P/N 7327993-814, for which it has been determined that the affected lug attaching the support bracket to the rear spar of the wing has a thickness of 2.75 mm (0.108 in.) or more, as specified in Saab Service Bulletin 2000-27-056, dated April 18, 2018.

(h) Retained One-Time Inspection, With No Changes

This paragraph restates the requirements of paragraph (h) of AD 2018-11-07, with no changes. Within 100 flight cycles or 30 days, whichever occurs first after June 13, 2018 (the effective date of AD 2018-11-07), accomplish a detailed visual inspection for cracks, corrosion, and damage (including missing paint) of the affected lug and the adjacent area of the aileron bellcrank support brackets installed on the left-hand (LH) and right-hand (RH) wings, and measure the thickness of the affected lug attaching the aileron bellcrank support bracket to the rear spar of the wing, in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000-27-056, dated April 18, 2018.

(i) Retained Repetitive Inspections, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2018-11-07, with no changes. If, during the measurement required by paragraph (h) of this AD, it is determined that the affected lug attaching the aileron bellcrank support bracket to the rear spar of the wing has a thickness of less than 2.75 mm (0.108 in.), at intervals not to exceed 100 flight cycles, accomplish a detailed visual inspection for cracks, corrosion, and damage (including missing paint) of that affected support bracket in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000-27-056, dated April 18, 2018. Accomplishing the replacement specified in paragraph (l) of this AD terminates the repetitive inspections required by this paragraph for that bracket.

(j) Retained Corrective Actions, With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2018-11-07, with no changes. If, during any inspection required by paragraph (h) or (i) of this AD, any crack, corrosion, or damage (including missing paint) is found, before further flight, obtain corrective actions instructions approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature. Accomplish the corrective actions within the compliance time specified therein. If no compliance time is specified in the corrective actions instructions, accomplish the corrective action before further flight.

(k) Retained Parts Installation Limitation, With No Changes

This paragraph restates the requirements of paragraph (m) of AD 2018-11-07, with no changes. As of June 13, 2018 (the effective date of AD 2018-11-07), it is allowed to install on any airplane an aileron bellcrank support bracket P/N 7327993-813 or P/N 7327993-814, provided it is a serviceable support bracket.

(l) New Requirement of This AD: Replacement

Within 6 months after the effective date of this AD, replace each affected support bracket with a serviceable support bracket, in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000-27-056, dated April 18, 2018. Replacing each affected support bracket terminates the inspections required by paragraph (i) of this AD for that airplane.

(m) Other FAA AD Provisions

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (n)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2018-11-07, are approved as AMOCs for the corresponding provisions of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2018-0103, dated April 30, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0797.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on June 13, 2018 (83 FR 24399, May 29, 2018).

(i) Saab Service Bulletin 2000-27-056, dated April 18, 2018.

(ii) [Reserved]

(4) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; internet <http://www.saabgroup.com>.

(5) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 29, 2018.
James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-11 The Boeing Company: Amendment 39-19522; Docket No. FAA-2017-0246; Product Identifier 2017-NM-011-AD.

(a) Effective Date

This AD is effective January 18, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777-200 and -300 series airplanes, certificated in any category, equipped with Rolls-Royce Model RB211-Trent 800 engines, on which the actions specified in Boeing Alert Service Bulletin 777-78A0094 have been incorporated, and the condition specified in paragraph (c)(1) or (c)(2) of this AD is met on any engine, or both conditions specified in (c)(1) and (c)(2) of this AD are met on any engine.

(1) Thermal protection system (TPS) non-re-contoured insulation blankets having part numbers (P/N) 315W5115-2, -6, or -20 are installed on the thrust reverser (T/R) inner wall.

(2) Rolls-Royce Service Bulletin RR.211-71-H824, dated July 30, 2014, has not been incorporated on the engine.

(d) Subject

Air Transport Association (ATA) of America Code 78, Engine exhaust.

(e) Unsafe Condition

This AD was prompted by reports of inadequate clearance between the TPS insulation blankets and the electronic engine control (EEC) wiring, which resulted in damaged wires. We are issuing this AD to address damaged wires, which could result in in-flight shutdown of the engine, or the inability to properly control thrust, and consequent reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive EEC Wire Bundle Inspection

Within 2,000 flight hours since the most recent EEC wire bundle inspection done as specified in Boeing Special Attention Service Bulletin 777-78-0071; or Boeing Service Bulletin 777-78-0082; or within 500 flight hours after the effective date of this AD, whichever occurs later: Do a detailed inspection for damage of the EEC wire bundles and clips, and do all applicable corrective actions, in

accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-78-0082, Revision 1, dated June 15, 2015. Do all applicable corrective actions before further flight. Repeat the inspection thereafter at intervals not to exceed 2,000 flight hours.

(h) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the service information specified in paragraph (h)(1) or (h)(2) of this AD.

- (1) Boeing Special Attention Service Bulletin 777-78-0071, Revision 2, dated July 23, 2013.
- (2) Boeing Service Bulletin 777-78-0082, dated November 9, 2011.

(i) Optional Terminating Action

Accomplishing the actions in paragraph (i)(1) and (i)(2) of this AD terminates the repetitive inspections required by paragraph (g) of this AD for the modified engine installation only.

- (1) Installing re-contoured insulation blankets P/N 315W5115-60, -62, and -64 on the right T/R halves in accordance with the Accomplishment Instructions of either Boeing Special Attention Service Bulletin 777-78-0071, Revision 2, dated July 23, 2013; or Boeing Service Bulletin 777-78-0082, Revision 1, dated June 15, 2015.
- (2) Modifying an engine in accordance with the Accomplishment Instructions of Rolls-Royce Service Bulletin RR.211-71-H824, dated July 30, 2014.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Kevin Nguyen, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3555; email: kevin.nguyen@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 777-78-0082, Revision 1, dated June 15, 2015.

(ii) Boeing Special Attention Service Bulletin 777-78-0071, Revision 2, dated July 23, 2013.

(iii) Rolls-Royce Service Bulletin RR.211-71-H824, dated July 30, 2014.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 29, 2018.

James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-12 Airbus SAS: Amendment 39-19523; Docket No. FAA-2018-0791; Product Identifier 2018-NM-043-AD.

(a) Effective Date

This AD is effective January 18, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A350-941 airplanes, certificated in any category, as identified in European Aviation Safety Agency (EASA) AD 2018-0045, dated February 15, 2018; corrected February 22, 2018 (“EASA AD 2018-0045”).

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage; 55, Stabilizers.

(e) Reason

This AD was prompted by a determination that the section 19 holes for the vertical tail plane (VTP) tension bolts connection are not properly protected against corrosion. We are issuing this AD to address corrosion of the VTP tension bolts connection, which could reduce the structural integrity of the VTP, and could ultimately lead to reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified by paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2018-0045.

(h) Exceptions to EASA AD 2018-0045

(1) For purposes of determining compliance with the requirements of this AD, where EASA AD 2018-0045 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2018-0045 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): Any RC procedures and tests identified in the service information referenced in EASA AD 2018-0045 must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018-0045, dated February 15, 2018; corrected February 22, 2018.

(ii) [Reserved]

(3) For EASA AD 2018-0045, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2018-0045 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0791.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 29, 2018.
James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-13 Dassault Aviation: Amendment 39-19524; Docket No. FAA-2018-0809; Product Identifier 2018-NM-092-AD.

(a) Effective Date

This AD is effective January 18, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 2000 airplanes, certificated in any category, manufacturer serial numbers 70 through 231 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Reason

This AD was prompted by a report of chafing of a wire bundle located at the bottom of the right hand (RH) electrical cabinet. We are issuing this AD to address such chafing, which may cause damage to wires within the bundle, and, if not detected and corrected, could lead to improper functioning of airplane systems (such as loss of wing anti-icing or wing anti-icing inoperative indication, loss of normal braking indication, and loss of “No take-off” indication), which could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 25 months after the effective date of this AD, for airplanes equipped with a metallic plate at the bottom of the RH electrical cabinet, do the following actions as specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) Perform a general visual inspection of the wiring bundle for damage (including chafing), in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017.

(2) Measure the clearance between the metallic plate and the wire bundle at the bottom of the RH electrical cabinet in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017.

(h) Corrective Action

(1) If, during the inspection required by paragraph (g)(1) of this AD, any damage is found, before further flight, replace all damaged wires using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(2) If, during the measurement required by paragraph (g)(2) of this AD, the detected clearance is less than the criteria specified in Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017, before further flight, modify the metallic plate in accordance with the Accomplishment Instructions of Dassault Aviation Service Bulletin F2000-436, dated September 28, 2017.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Dassault Aviation's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0114, dated May 23, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0809.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Service Bulletin F2000-436, dated September 28, 2017.

(ii) [Reserved]

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 28, 2018.

James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-14 Fokker Services B.V.: Amendment 39-19525; Docket No. FAA-2018-0802; Product Identifier 2018-NM-082-AD.

(a) Effective Date

This AD is effective January 18, 2019.

(b) Affected ADs

This AD affects AD 95-21-20, Amendment 39-9407 (60 FR 53857, October 18, 1995) (“AD 95-21-20”).

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 49, Airborne auxiliary power.

(e) Reason

This AD was prompted by reports of electrical arcing between the auxiliary power unit (APU) starter motor positive terminal and the APU fuel drain line. We are issuing this AD to address this unsafe condition, which could lead to a fire during APU start and possibly result in damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 12 months after the effective date of this AD: Remove the two additional clamps, part number (P/N) MS21919WCH5 and P/N MS21919WCH13, and replace APU fuel drain line P/N D67066-409 with a new APU fuel drain line P/N W67066-401, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-49-037, dated October 31, 2016.

(h) Terminating Actions for AD 95-21-20

Accomplishing the actions required by paragraph (g) of this AD terminates all requirements of AD 95-21-20.

(i) Parts Installation Prohibition

No person may install APU fuel drain line P/N D67066-409 after modification of an airplane as required by paragraph (g) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Fokker Services B.V.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017-0008, dated January 16, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0802.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-49-037, dated October 31, 2016.

(ii) [Reserved]

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 29, 2018.
James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2018-25-15 The Boeing Company: Amendment 39-19526; Docket No. FAA-2018-0803; Product Identifier 2018-NM-098-AD.

(a) Effective Date

This AD is effective January 22, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 727, 727-100, 727-100C, 727-200, 727-200F, and 727C series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report of cracking in the inboard lower flange and adjacent web near the forward attachment of the outboard flap track at position 8 on a Model 737-300 airplane. The flap tracks of Model 737-300 airplanes are similar to the flap tracks of Model 727 airplanes. We are issuing this AD to address the inability of a principal structural element to sustain required flight loads, which could result in loss of the outboard trailing edge flap and reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as required by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018.

Note 1 to paragraph (g) of this AD: Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 727-57A0188, dated May 31, 2018, which is referred to in Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018, uses the phrase “the original issue date of Requirements Bulletin 727-57A0188 RB,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018, specifies contacting Boeing for repair instructions, this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Parts Installation Limitation

As of the effective date of this AD, no person may install, on any airplane, a wing outboard flap track having a part number listed in paragraph 1.B. of Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018, unless the inspections and applicable on-condition actions specified in the Accomplishment Instructions of Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018, are accomplished concurrently with the installation of the part on the airplane.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact Muoi Vuong, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5205; fax: 562-627-5210; email: muoi.vuong@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 727-57A0188 RB, dated May 31, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 29, 2018.

James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-16 Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.): Amendment 39-19527; Docket No. FAA-2018-0805; Product Identifier 2018-NM-103-AD.

(a) Effective Date

This AD is effective January 22, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Defense and Space S.A. (formerly known as Construcciones Aeronauticas, S.A.) Model CN-235, CN-235-200, and CN-235-300 airplanes, all manufacturer serial numbers, certificated in any category, with an original certificate of airworthiness or original export certificate of airworthiness issued on or before March 20, 2018. This AD does not apply to Model CN-235-300 airplanes in a Maritime Patrol (SM01) configuration.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. We are issuing this AD to address fatigue cracking, damage, and corrosion in principal structural elements; such fatigue cracking, damage, and corrosion could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate the information specified in Airbus Defence and Space Technical Document DT-86-3001, CN-235 Airworthiness Limitations List, Issue R, dated March 20, 2018. The initial compliance times for doing the tasks are at the applicable times specified in Airbus Defence and Space Technical Document DT-86-3001, CN-235 Airworthiness Limitations List, Issue R, dated March 20, 2018, or within 90 days after the effective date of this AD, whichever occurs later.

(h) No Alternative Actions or Intervals

After accomplishment of the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals, may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus Defense and Space S.A.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0134, dated June 25, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0805.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Defence and Space Technical Document DT-86-3001, CN-235 Airworthiness Limitations List, Issue R, dated March 20, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus Defense and Space, Services/Engineering Support, Avenida de Aragón 404, 28022 Madrid, Spain; telephone: +34 91 585 55 84; fax: +34 91 585 31 27; email: MTA.TechnicalService@airbus.com.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 29, 2018.
James Cashdollar,
Acting Director, System Oversight Division,
Aircraft Certification Service.



2018-25-18 ATR-GIE Avions de Transport Régional: Amendment 39-19530; Docket No. FAA-2018-0167; Product Identifier 2017-NM-131-AD.

(a) Effective Date

This AD is effective January 22, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to ATR-GIE Avions de Transport Régional Model ATR42-200, -300, -320, and -500 airplanes; and Model ATR72-101, -102, -201, -202, -211, -212, and -212A airplanes; certificated in any category; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by reports of cracking in certain main landing gear (MLG) universal joints (U-joints). We are issuing this AD to address cracking in MLG U-joints, which could lead to MLG structural failure and subsequent collapse of the MLG, possibly resulting in damage to the airplane and injury to the occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

(1) For the purposes of this AD, an affected U-joint is any U-joint identified by part number (P/N) and serial number listed in the applicable service bulletin specified in paragraph (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD.

(i) For Model ATR42-200, -300, and -320 airplanes: Safran Landing Systems Service Bulletin 631-32-249, Revision 2, dated February 13, 2018.

(ii) For Model ATR42-500 airplanes: Safran Landing Systems Service Bulletin 631-32-250, Revision 2, dated February 13, 2018.

(iii) For Model ATR72-101, -102, -201, -202, -211, -212, and -212A airplanes: Safran Landing Systems Service Bulletin 631-32-251, Revision 2, dated February 13, 2018.

(2) For the purposes of this AD, a serviceable part is an affected U-joint, as defined in paragraph (g)(1) of this AD, released to service by Safran Landing Systems, free of defect, with the letter “V” added on the part (on the identification plate, or in the vicinity of the P/N marking); or any other U-joint with chrome-plated faces that were never stripped or repaired; or any other U-joint with chrome-plated faces that were stripped and repaired as specified in the applicable component maintenance manual (CMM) identified in paragraph (g)(2)(i), (g)(2)(ii), or (g)(2)(iii).

(i) For Model ATR42-200, -300, and -320 airplanes: Safran Landing Systems CMM 32-18-28, Rev. 10, or Safran Landing Systems CMM 32-18-30, Rev. 8, both dated June 2, 2017.

(ii) For Model ATR42-500 airplanes: Safran Landing Systems CMM 32-18-45, Rev. 5, or Safran Landing Systems CMM 32-18-63, Rev. 6, both dated June 2, 2017.

(iii) For Model ATR72-101, -102, -201, -202, -211, -212, and -212A airplanes: Safran Landing Systems CMM 32-18-34, Rev. 9, dated June 2, 2017.

(h) Repetitive Inspections

Within 3 months or 500 flight cycles (FC), whichever occurs first, after the effective date of this AD, and thereafter at intervals not to exceed 500 FC: Do a detailed inspection for cracking of each affected U-joint, as identified in paragraph (g)(1) of this AD, in accordance with the Accomplishment Instructions of the applicable service bulletin specified in paragraph (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD.

(i) Corrective Action

If, during any inspection required by paragraph (h) of this AD, any cracked U-joint is found, before further flight: Replace the cracked U-joint with a serviceable part, as defined in paragraph (g)(2) of this AD, in accordance with the Accomplishment Instructions of the applicable service bulletin specified in paragraph (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD.

(j) Optional Terminating Action for Required Repetitive Inspections

Replacement of all affected U-joints on an airplane, as identified in paragraph (g)(1) of this AD, with serviceable parts, as defined in paragraph (g)(2) of this AD, constitutes terminating action for the repetitive inspections required by paragraph (h) of this AD for that airplane.

(k) Parts Installation Limitation

As of the effective date of this AD, no person may install, on any airplane, an affected U-joint, as identified in paragraph (g)(1) of this AD, unless it is a serviceable part, as defined in paragraph (g)(2) of this AD.

(l) No Reporting Requirement

Although the Accomplishment Instructions of the service bulletins identified in paragraphs (g)(1)(i), (g)(1)(ii), and (g)(1)(iii) of this AD specify to submit certain information to the manufacturer, this AD does not include that requirement.

(m) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (h) and (i) of this AD, if those actions were performed before the effective date of this AD using the applicable service bulletin specified in paragraph (m)(1), (m)(2), or (m)(3) of this AD, provided that affected U-joints not

identified in the service bulletin specified in paragraph (m)(1), (m)(2), or (m)(3) of this AD comply with the requirements of paragraphs (h) and (i) of this AD.

- (1) Safran Landing Systems Service Bulletin 631-32-249, Revision 1, dated June 26, 2017.
- (2) Safran Landing Systems Service Bulletin 631-32-250, Revision 1, dated June 26, 2017.
- (3) Safran Landing Systems Service Bulletin 631-32-251, Revision 1, dated June 26, 2017.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (o)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or ATR-GIE Avions de Transport Régional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0080, dated April 11, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0167.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Safran Landing Systems Service Bulletin 631-32-249, Revision 2, dated February 13, 2018.

(ii) Safran Landing Systems Service Bulletin 631-32-250, Revision 2, dated February 13, 2018.

(iii) Safran Landing Systems Service Bulletin 631-32-251, Revision 2, dated February 13, 2018.

(3) For service information identified in this AD, contact Safran Landing Systems, Inovel Parc Sud-7, rue Général Valérie André, 78140 VELIZY-VILLACOUBLAY-FRANCE; phone: +33 (0) 1 46 29 81 00; internet: www.safran-landing-systems.com.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on December 6, 2018.
Michael Kaszycki,
Acting Director, System Oversight Division,
Aircraft Certification Service.