



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2011-11

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

LARGE AIRCRAFT

| AD No. | Information | Manufacturer | Applicability |
|---------------------------------------------------------------------------------------------------|--------------|---------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency | | | |
| Biweekly 2011-01 | | | |
| 2010-25-06 | | Boeing | 737-200, -300, -400, and -500 series |
| 2010-26-05 | | Dassault Aviation | Falcon 10, Fan Jet Falcon, Fan Jet Falcon Series C, D, E, F, and G, Mystere-Falcon 20-C5, 20-D5, 20-E5, 20-F5, Mystere-Falcon 200, Mystere-Falcon 50, Mystere-Falcon 900, Falcon 900EX, Falcon 2000 and Falcon 2000EX |
| 2010-26-06 | | Boeing | 737-600, -700, -700C, -800, and -900 series |
| 2010-26-07 | | Boeing | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series |
| 2010-26-08 | | Boeing | 767-200, -300, -300F, and -400ER series |
| 2010-26-10 | S 2006-05-09 | Boeing | 747-200C, -200F, -400, -400D, and -400F series |
| 2010-26-12 | | Airbus | A321-211, -212, -231, and -232 |
| 2010-26-13 | | Bombardier | DHC-8-301, -311, and -315 |
| Biweekly 2011-02 | | | |
| 2010-02-05 | | Airbus | See AD |
| 2010-24-05 | COR | Pratt & Whitney Canada | Engine: PW305A and PW305B |
| 2010-24-06 | S 2006-12-18 | Short Brothers PLC | SD3-60 SHERPA, SD3-SHERPA, SD3-30, and SD3-60 |
| 2011-01-01 | S 2008-13-15 | Embraer | EMB-135BJ |
| 2011-01-02 | | Airbus | A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, 343, A340-211, -212, -213, -311, -312, and -313 |
| 2011-01-05 | | Boeing | 727, 727C, 727-100, 727-100C, 727-200, and 727-200F |
| 2011-01-06 | S 2007-02-22 | Airbus | A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2011-01-07 | | 328 Support Services GmbH | 328-100 and -300 |
| 2011-01-09 | | B/E Aerospace | Appliance: Protective breathing equipment (PBE) units |
| 2011-01-10 | | Bombardier | BD-700-1A10 and BD-700-1A11 |
| 2011-01-11 | | Boeing | MD-90-30 |
| 2011-01-12 | S 2008-21-03 | Boeing | 737-300, -400, and -500 series |
| 2011-01-13 | | Airbus | A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F |
| 2011-01-15 | | Boeing | 757-200, -200CB, and -300 series |
| 2011-01-16 | | Boeing | DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and MD-88 |
| 2011-02-01 | | Boeing | MD-11 and MD-11F |
| 2011-02-03 | | Boeing | 757-200, -200PF, -200CB, and -300 series |
| Biweekly 2011-03 | | | |
| 2011-02-05 | | Boeing | 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series |
| 2011-02-06 | | Boeing | 767-300 series |
| 2011-02-09 | | Airbus | A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313 |
| 2011-03-01 | S 2005-25-05 | Pratt & Whitney | JT8D-7, -7A, -7B, -9, -9A, -11, -15, -15A, -17, -17A, -17R, and -17AR series |

LARGE AIRCRAFT

| AD No. | Information | Manufacturer | Applicability |
|---------------------------------------------------------------------------------------------------|--------------|----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency | | | |
| Biweekly 2011-04 | | | |
| 2011-02-07 | S 2010-12-10 | General Electric | Engine: CF6-45A, CF6-45A2, CF6-50A, CF6-50C, CF6-50CA, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50E, CF6-50E1, CF6-50E2, CF6-50C2-F and CF6-50C2-R |
| 2011-03-07 | | Fokker Services | F.28 Mark 1000, 2000, 3000, 4000, and F.28 Mark 0100 |
| 2011-03-08 | | Bombardier | CL-215-1A10 (CL-215), CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant) |
| 2011-03-09 | | Boeing | MD-90-30 |
| 2011-03-10 | S 2005-20-32 | Airbus | A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313 |
| 2011-03-11 | | Airbus | A300 B4-601, B4-603, B4-620, B4-622, A300 B4-605R, B4-622R, A300 F4-605R, and A300 C4-605R Variant F |
| 2011-03-12 | | Hawker Beechcraft | 400A and 400T |
| 2011-03-13 | | Bombardier | CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) |
| 2011-03-14 | | Boeing | 737-100, -200, -200C, -300, -400, -500 series, and 737-400 series |
| 2011-04-02 | | Hamilton Sundstrand | Propeller: 247F series |
| Biweekly 2011-05 | | | |
| 2011-03-15 | | Boeing | 767-200, -300, -300F, and -400ER series |
| 2011-03-16 | | Cessna | 750 |
| 2011-04-01 | | Fokker | F.28 Mark 0070 and 0100 |
| 2011-04-03 | | Bombardier | CL-600-2B19 (Regional Jet Series 100 and 440) |
| 2011-04-04 | S 2005-18-02 | Pratt & Whitney | Engine: JT8D-209, -217, -217A, -217C, and -219 turbofan |
| 2011-04-05 | | Airbus | A340-211, -212, -213; A340-311, -312, -313; A340-541; and A340-642 |
| 2011-04-06 | | Airbus | A340-211, -212, -213; A340-311, -312, -313; A340-541; A340-642 |
| 2011-04-07 | | Fokker | F.28 Mark 0070 and 0100 |
| 2011-04-08 | | Learjet | 45 |
| 2011-04-10 | S 2009-23-10 | Boeing | 737-300, -400, and -500 series |
| 2011-05-03 | S 2005-06-04 | Bombardier | CL-600-2B19 (Regional Jet Series 100 & 440) |
| 2011-05-04 | S 2008-23-19 | Boeing | 757-200, -200CB, -200PF, and -300 series |
| 2011-05-05 | | Airbus | A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642 |
| Biweekly 2011-06 | | | |
| 98-09-27R1 | | Rolls-Royce plc | Engine: RB211-Trent 768, 772, and 772B turbofan |
| 2011-04-09 | | Transport Category Airplanes | Transport Category Airplanes |
| 2011-05-10 | | BAE Systems (Operations) Limited | ATP, HS 748 2A and series 2B |
| 2011-05-11 | S 2007-19-19 | Boeing | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SR, and 747SP series |
| 2011-05-12 | | Boeing | 777-200, -200LR, -300, and -300ER series |
| 2011-05-13 | | Saab AB, Saab Aerosystems | SAAB 2000 |
| 2011-05-14 | | Bombardier | DHC-8-400, -401, and -402 |
| 2011-06-04 | | Airbus | A330-243F |

LARGE AIRCRAFT

| AD No. | Information | Manufacturer | Applicability |
|---------------------------------------------------------------------------------------------------|-------------------|---------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency | | | |
| Biweekly 2011-07 | | | |
| 2011-06-03 | | Boeing | 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series |
| 2011-06-05 2011-06-08 | S 2007-18-52 | Boeing Bombardier | 737-600, -700, -700C, -800, -900, and -900ER series CL-600-2B19 (Regional Jet Series 100 & 440), CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) |
| 2011-06-09 | S 2009-11-09 | Airbus | A300 B4-601, A300 B4-603, A300 B4-620, A300 B4-622, A300 B4-605R, A300 B4-622R; A300 F4-605R, A300 F4-622R; and A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2011-06-11 | | Rolls-Royce plc | Engine: RB211-Trent 970-84, 970B-84, 972-84, 972B-84, 977-84, 977B-84, and 980-84 turbofan |
| 2011-06-12 2011-07-01 | S 2009-04-17 | Boeing General Electric | MD-90-30 Engine: CF6-45A, CF6-45A2, CF6-50A, CF6-50C, CF6-50CA, CF6-50C1, CF6-50C2, CF6-50C2B, CF6-50C2D, CF6-50E, CF6-50E1, CF6-50E2, and CF6-50E2B |
| 2011-07-02 | S 2005-02-03 | Pratt & Whitney | Engine: JT8D-209, -217, -217A, -217C, and -219 series turbofan |
| Biweekly 2011-08 | | | |
| 2011-07-04 | | Boeing | DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-32F (C-9A), DC-9-32F (C9-B), DC-9-33F, DC-9-34, DC-9-34F, DC-9-41, and DC-9-51 |
| 2011-07-05 2011-07-06 2011-07-07 2011-07-08 | | Sigma Aero Seat Bombardier, Inc Fokker Services B.V. Airbus | Appliance: See AD CL-600-2B19 (Regional Jet Series 100 & 440) F.28 Mark 1000, 2000, 3000, and 4000 A340-211, -212, -213, -311, -312 and -313 |
| 2011-07-10 2011-07-11 2011-08-51 | S 2010-10-18 E | Bombardier, Inc. Dassault Aviation Boeing | BD-100-1A10 (Challenger 300) Mystere-Falcon 50 737-300, -400, and -500 series |
| Biweekly 2011-09 | | | |
| 2011-07-12 2011-08-02 2011-08-03 2011-08-04 | | Fokker Services B.V. Fokker Services B.V. Airbus Bombardier, Inc | F.27 Mark 050 F.27 Mark 050 A340-541 and -642 CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900) |
| 2011-08-05 | | Airbus | A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2011-08-08 | | Embraer | ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, -100 LR, -100 ECJ, -100 IGW, ERJ 190-200 STD, -200 LR, and -200 IGW |
| 2011-08-10 | S 98-19-12 | Rolls-Royce plc | Engine: RB211-Trent 768-60 and RB211-Trent 772-60 turbofan |
| 2011-08-11 2011-08-12 | S 2005-13-19 | BAE Systems (Operations) Limited Airbus | BAe 146-100A, -200A, -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A A330-301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, A340-311, -312, and -313 |
| 2011-09-01 2011-09-02 2011-09-03 2011-09-05 2011-09-06 | S 2002-02-07 | Airbus Saab AB, Saab Aerosystems Lockheed Martin Corp Boeing Airbus | A340-541, and -642 340A (SAAB/SF340A) and SAAB 340B 382, 382B, 382E, 382F, and 382G 777-200, -300, and -300ER series A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, and -313 |

LARGE AIRCRAFT

| AD No. | Information | Manufacturer | Applicability |
|---------------------------------------------------------------------------------------------------|----------------------------------------------|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency | | | |
| Biweekly 2011-10 | | | |
| 2011-08-07 | | Rolls-Royce plc | Engine: RB211-Trent 875-17, RB211-Trent 877-17, RB211-Trent 884-17, RB211-Trent 884B-17, RB211-Trent 892-17, RB211-Trent 892B-17, and RB211-Trent 895-17 turbofan |
| 2011-09-07 | | Rolls-Royce plc | Engine: RB211-524G2-T-19, -524G3-T-19, -524H-T-36, -524H2-T-19; RB211 Trent 553-61, 553A2-61, 556-61, 556A2-61, 556B-61, 556B2-61, 560-61, 560A2-61; RB211 Trent 768-60, 772-60, 772B-60; RB211 Trent 875-17, 877-17, 884-17, 884B-17, 892-17, 892B-17, and 895-17 turbofan |
| 2011-09-10 | | Airbus | A300 B4-601, B4-603, B4-605R, C4-605R Variant F, and F4-605R airplanes, and A310-204 and -304 |
| 2011-09-11 | | Boeing | 777-200 and -300 series |
| 2011-09-12 | | Bombardier, Inc. | DHC-8-101, -102, -103, -106, -201, -202, -301, -311, -315, DHC-8-401, and -402 |
| 2011-09-13 | | Airbus | A340-211, -212, -213, -311, -312, and -313 |
| 2011-09-14 | | Boeing | 747-200B, -300, -400, -400D, and -400F series |
| 2011-09-15 | | Boeing | 777-200, -200LR, -300, and -300ER series |
| 2011-09-17 | S 2010-01-07 | Airbus | A340-211, -212, -213, -311, -312, -313, -541, and -642 |
| 2011-09-18 | | Dassault Aviation | FALCON 7X |
| 2011-10-01 | | Dassault Aviation | FALCON 7X |
| 2011-10-04 | | Rolls-Royce plc | Engine: RB211-Trent 875-17, -Trent 877-17, -Trent 884-17, -Trent 884B-17, -Trent 892-17, -Trent 892B-17, and -Trent 895-17 turbofan |
| Biweekly 2011-11 | | | |
| 2011-08-51 | | Boeing | 737-300, -400, and -500 series |
| 2011-09-04 | | Lockheed Martin Corporation | 382, 382B, 382E, 382F, and 382G |
| 2011-10-02 | | Boeing | 747-400, 747-400D, and 747-400F series |
| 2011-10-03 | | Embraer | ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, ERJ 170-200 LR, -200 SU, -200 STD, ERJ 190-100 STD, ERJ 190-100 LR, ERJ 190-100 IGW, ERJ 190-200 STD, ERJ 190-200 LR, and ERJ 190-200 IGW |
| 2011-10-05 | | Airbus | A310-203, -204, -222, -304, -322, and -324 |
| 2011-10-06 | | Airbus | A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2011-10-07 | | Airbus | A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2011-10-08 | S 98-26-01 S 91-13-01 | Airbus | A310-203, -204, -221, -222, -304, -322, -324, and -325 |
| 2011-10-10 | | Airbus | A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F |
| 2011-10-14 | S2010-24-08 | Dassault Aviation | MYSTERE-FALCON 50 |
| 2011-10-15 | | Airbus | A318-112, A319-111, A319-112, A319-115, A319-132, A319-133, A320-214, A320-232, A320-233, A321-211, A321-213, and A321-231 |
| 2011-10-17 | S 2007-04-11 S 2007-20-03 S 2007-25-02 | Airbus | A300 B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, B4-203, A310-203, -204, -221, -222, -304, -322, -324, 325, A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, A300 C4-605R Variant F |
| 2011-11-02 | | Bombardier, Inc. | DHC-8-400, -401, and -402 |



2011-08-51 The Boeing Company: Amendment 39-16701; Docket No. FAA-2011-0348; Directorate Identifier 2011-NM-069-AD.

Effective Date

(a) This AD is effective June 2, 2011 to all persons except those persons to whom it was made immediately effective by Emergency AD 2011-08-51, issued on April 5, 2011, which contained the requirements of this amendment.

Affected ADs

(b) None.

Applicability

(c) This AD applies to The Boeing Company Model 737-300, -400, and -500 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011.

Subject

(d) Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 53: Fuselage.

Unsafe Condition

(e) This AD was prompted by a report indicating that a Model 737-300 series airplane experienced a rapid decompression when the lap joint at stringer S-4L between body station (BS) 664 and BS 727 cracked and opened up due to cracking in the lower skin at the lower row of fasteners. We are issuing this AD to detect and correct such cracking, which could result in an uncontrolled decompression of the airplane.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Inspections

(g) At the applicable time specified in paragraph (g)(1), (g)(2), or (g)(3) of this AD: Except as provided by paragraphs (h) and (i) of this AD, do external eddy current inspections of the lap joint at stringers S-4R and S-4L, along the entire length from body station (BS) 360 to BS 908, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011. If any crack indication is detected, before further flight, either confirm the crack indication by doing eddy current inspections from the interior of the fuselage in the lower skin at the lower row of

fasteners at stringer S-4L and S-4R, in accordance with Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011, or repair in accordance with paragraph (j) of this AD.

(1) For airplanes that have accumulated fewer than 30,000 total flight cycles as of the effective date of this AD: Inspect before the accumulation of 30,000 total flight cycles, or within 20 days after the effective date of this AD, whichever occurs later.

(2) For airplanes that have accumulated 30,000 or more total flight cycles and fewer than 35,000 total flight cycles as of the effective date of this AD: Inspect within 20 days after the effective date of this AD.

(3) For airplanes that have accumulated 35,000 total flight cycles or more as of the effective date of this AD: Inspect within 5 days after the effective date of this AD.

(h) For areas repaired with external doublers, paragraphs (h)(1) and (h)(2) of this AD apply.

(1) If the repair meets the criteria specified in paragraphs 3.B.1.c.(1) and 3.B.1.c.(2) of Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011, no inspection of the lower skin at the lap joint lower fastener row is required under the doubler.

(2) If the repair does not meet the criteria specified in paragraphs 3.B.1.c.(1) and 3.B.1.c.(2) of Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011, inspect the lower skin lap joint lower row internally in the area covered by the doubler, in accordance with Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011.

(i) The inspections required by paragraph (g) of this AD may alternatively be done by internal eddy current and detailed inspections for cracks in the lower skin at the lower row of fasteners at stringer S-4L and S-4R, along the entire length from BS 360 to BS 908, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011.

(j) If any crack is found during any inspection required by this AD: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(k) Repeat the inspections specified in either paragraph (g) or (i) of this AD thereafter at intervals not to exceed 500 flight cycles. Either inspection method may be used at any repetitive inspection cycle.

Alternative Methods of Compliance (AMOCs)

(1)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be e-mailed to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for emergency AD 2011-08-51 are approved as AMOCs for the corresponding requirements of this AD.

Related Information

(m)(1) For further information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue,

SW., Renton, Washington 98057-3356; phone: 425-917-6447; fax: 425-917-6590; e-mail: wayne.lockett@faa.gov.

(2) For copies of the service information referenced in this AD, contact: Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

Material Incorporated by Reference

(n) You must use Boeing Alert Service Bulletin 737-53A1319, dated April 4, 2011, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on May 6, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-09-04 Lockheed Martin Corporation/Lockheed Martin Aeronautics Company:
Amendment 39-16666; Docket No. FAA-2009-1228; Directorate Identifier 2009-NM-015-AD.

Effective Date

- (a) This AD is effective June 22, 2011.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to all Lockheed Martin Corporation/Lockheed Martin Aeronautics Company Model 382, 382B, 382E, 382F, and 382G airplanes, certificated in any category.

Subject

- (d) Air Transport Association (ATA) of America Code 57, Wings.

Unsafe Condition

(e) This AD results from reports of fatigue cracks of the lower surface of the center wing box. The Federal Aviation Administration is issuing this AD to detect and correct such cracks, which could result in the structural failure of the wings.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(g) At the time specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, whichever occurs latest: Do a nondestructive inspection of the lower surface of the center wing box for any damage, in accordance with Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007. Repeat the inspections thereafter at intervals not to exceed 10,000 flight hours.

- (1) Prior to the accumulation of 40,000 total flight hours on the center wing.
- (2) Within 365 days after the effective date of this AD.
- (3) Within 10,000 flight hours on the center wing box after the accomplishment of the service bulletin if done before the effective date of this AD.

Note 1: These inspection procedures supplement the existing Hercules Air Freighter progressive inspection procedures and previously issued Lockheed Martin service bulletins. After the effective

date of this AD, there are no inspection procedures in those documents that fully meet the requirements of this AD.

Corrective Action

(h) If any damage is found during any inspection required by this AD: Before further flight, repair any damage using a method approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. For a repair method to be approved by the Manager, Atlanta ACO, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

Exceptions to the Service Bulletin

(i) Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, specifies that operators may adjust thresholds and intervals, use alternative repetitive inspection intervals, and use alternative inspection methods, if applicable. However, this AD requires that any alternative methods or intervals be approved by the Manager, Atlanta ACO. For any alternative methods or intervals to be approved by the Manager, Atlanta ACO, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

(j) Where Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, specifies that alternative repetitive inspection intervals may be used for cold-worked holes, this AD does not allow the longer interval. This AD requires that all cold-worked and non-cold worked holes be re-inspected at 10,000-flight-hour intervals.

(k) Where Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, describes procedures for submitting a report of any damages, this AD does not require such action.

Credit for Actions Accomplished in Accordance With Previous Service Information

(l) Actions done before the effective date of this AD in accordance with Lockheed Service Bulletin 382-57-85 (82-790), Revision 1, dated March 8, 2007, are acceptable for compliance with the requirements of paragraph (g) of this AD.

(m) Actions done before the effective date of this AD in accordance with Lockheed Service Bulletin 382-57-85 (82-790), dated August 4, 2005, are acceptable for compliance with the requirements of paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(n)(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Related Information

(o) For more information about this AD, contact Carl Gray, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474-5554; fax: (404) 474-5606; e-mail: Carl.W.Gray@faa.gov.

Material Incorporated by Reference

(p) You must use Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Lockheed Service Bulletin 382-57-85 (82-790), Revision 2, dated August 23, 2007, including Appendixes A, B, C, D, E, F, and G, all Revision 1, all dated March 8, 2007, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Lockheed Martin Corporation/Lockheed Martin Aeronautics Company, Airworthiness Office, Dept. 6A0M, Zone 0252, Column P-58, 86 S. Cobb Drive, Marietta, Georgia 30063; telephone 770-494-5444; fax 770-494-5445; e-mail ams.portal@lmco.com; Internet <http://www.lockheedmartin.com/ams/tools/TechPubs.html>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 12, 2011.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



FAA
Aviation Safety

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2011-10-02 The Boeing Company: Amendment 39-16683; Docket No. FAA-2010-0706; Directorate Identifier 2010-NM-064-AD.

Effective Date

(a) This AD is effective June 15, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to The Boeing Company Model 747-400, 747-400D, and 747-400F series airplanes; certificated in any category; equipped with General Electric CF6-80C2 series engines or Pratt & Whitney PW4000 series engines, as applicable.

Subject

(d) Air Transport Association (ATA) of America Code 78: Engine exhaust.

Unsafe Condition

(e) This AD was prompted by a report of automatic retraction of the leading edge flaps due to indications transmitted to the flap control unit (FCU) from the thrust reverser control system during takeoff. The Federal Aviation Administration is issuing this AD to prevent automatic retraction of the leading edge flaps during takeoff, which could result in reduced climb performance and consequent collision with terrain and obstacles or forced landing of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(g) For Model 747-400 and -400F airplanes equipped with Pratt & Whitney Model PW4000 series engines: Within 36 months after the effective date of this AD, modify the thrust reverser control system wiring to the FCU in the P252 and P253 thrust reverser relay panels, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-78A2184, Revision 1, dated December 23, 2010.

(h) For Model 747-400, -400D, and -400F airplanes equipped with General Electric Model CF6-80C2 series engines: Within 36 months after the effective date of this AD, modify the thrust reverser control system wiring to the FCU in the P414 and P415 power distribution panels, in accordance with Boeing Special Attention Service Bulletin 747-78-2183, Revision 1, dated December 23, 2010.

Credit for Actions Accomplished in Accordance With Previous Service Information

(i) Modifying the thrust reverser control system wiring before the effective date of this AD, in accordance with Boeing Special Attention Service Bulletin 747-78-2183 or Boeing Alert Service Bulletin 747-78A2184, both dated January 12, 2010, as applicable, is acceptable for compliance with the corresponding modification required by paragraph (g) or (h) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be e-mailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Related Information

(k) For more information about this AD, contact Tung Tran, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; phone: 425-917-6505; fax: 425-917-6590; e-mail: tung.tran@faa.gov.

(l) For information about AMOCs, contact Tung Tran, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; phone: 425-917-6505; fax: 425-917-6590; e-mail: tung.tran@faa.gov.

Material Incorporated by Reference

(m) You must use Boeing Special Attention Service Bulletin 747-78-2183, Revision 1, dated December 23, 2010; or Boeing Alert Service Bulletin 747-78A2184, Revision 1, dated December 23, 2010; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of the service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 20, 2011.
Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-03 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-16684.
Docket No. FAA-2011-0038; Directorate Identifier 2010-NM-153-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 15, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170-100 LR, -100 STD, -100 SE, and -100 SU airplanes; and Model ERJ 170-200 LR, -200 SU, and -200 STD airplanes; certificated in any category; serial numbers 17000002, 17000004 through 17000013 inclusive, 17000015 through 17000212 inclusive, 17000216 through 17000233 inclusive, 17000236, 17000269, 17000281 through 17000291 inclusive, and 17000293; and Model ERJ 190-100 STD, ERJ 190-100 LR, ERJ 190-100 IGW, ERJ 190-200 STD, ERJ 190-200 LR, and ERJ 190-200 IGW airplanes ; certificated in any category; serial numbers 19000002, 19000004, 19000006 through 19000108 inclusive, 19000110 through 19000139 inclusive, 19000141 through 19000157 inclusive, 19000160, 19000165, 19000167 through 19000176 inclusive, 19000178 through 19000199 inclusive, 19000273 through 19000276 inclusive, 19000279 through 19000286 inclusive, 19000288 through 19000295 inclusive, 19000297 through 19000304 inclusive, and 19000309.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

[T]he occurrence of drill marks [has been found] at the lower ring region of the rear pressure bulkhead between [the] circumferential splice joint and rear skin located between stringers 12 and 13. These marks may result in formation of fatigue cracks accelerated by corrosion reducing the structural strength of the rear pressure bulkhead, which may cause a sudden decompression of the passenger cabin.

* * * * *

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) Before the accumulation of 20,000 flight cycles, do a detailed inspection for signs of drill marks at the left and right lower ring region of the rear pressure bulkhead between the circumferential splice joint and rear skin between stringers 12 and 13, in accordance with EMBRAER Service Bulletin 170-53-0082 or 190-53-0042, both Revision 01, both dated April 28, 2010, as applicable. If drill marks are found, repair before further flight, in accordance with EMBRAER Service Bulletin 170-53-0082 or 190-53-0042, both Revision 01, both dated April 28, 2010, as applicable.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows:

Although EMBRAER Service Bulletins 170-53-0082 and 190-53-0042, both Revision 01, both dated April 28, 2010, specify doing a general visual inspection, this AD requires doing a detailed inspection.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to Attn: Cindy Ashforth, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone 425-227-2768; fax 425-227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(i) Refer to MCAI Brazilian Airworthiness Directives 2010-06-01R1 and 2010-06-02R1, both dated August 25, 2010; and EMBRAER Service Bulletins 170-53-0082 and 190-53-0042, both Revision 01, both dated April 28, 2010; for related information.

Material Incorporated by Reference

(j) You must use EMBRAER Service Bulletin 170-53-0082, Revision 01, dated April 28, 2010; or EMBRAER Service Bulletin 190-53-0042, Revision 01, dated April 28, 2010; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170–Putim–12227-901 São Jose dos Campos–SP–BRASIL; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; e-mail distrib@embraer.com.br; Internet <http://www.flyembraer.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 20, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-05 Airbus: Amendment 39-16686. Docket No. FAA-2010-1273; Directorate Identifier 2010-NM-089-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 15, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model A310-203, -204, -222, -304, -322, and -324 airplanes, certificated in any category, all serial numbers, except airplanes on which Airbus modification 06146 has been done in production.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

A specific area, the lower tail plane cut-out located in the tail cone is subject to an inspection programme [for cracking] * * *.

* * * * *

The unsafe condition is reduced structural integrity of the tail cone.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Initial Inspections of the Lower Tail Plane Cut-out Area and Corrective Actions

(g) Within the applicable time specified in Table 1 of this AD, do the inspections of the lower tail plane cut-out area in the tail cone specified in paragraphs (g)(1), (g)(2), (g)(3), (g)(4), (g)(5), and (g)(6) of this AD, as applicable, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008. Certain compliance times are applicable to short-range use (i.e., average flight time (AFT) equal to or less than 4 flight hours), or long-range use (i.e., AFT exceeding 4 flight hours). Inspection areas are specified in Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

Note 1: To establish the average flight time, take the accumulated flight time (counted from the take-off up to the landing) and divide by the number of accumulated flight cycles. This gives the average flight time per flight cycle.

Table 1—Initial Compliance Time

| Airplanes | Inspection Areas | Compliance Time (whichever occurs later) | |
|--------------------------------------------------------------|------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| Model A310-203, A310-204, and A310-222 airplanes | 1 and 2 | Prior to the accumulation of 18,000 total flight cycles or 36,000 total flight hours, whichever occurs first | Within 1,500 flight cycles or 3,000 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-203, A310-204, and A310-222 airplanes | 3 | Prior to the accumulation of 24,000 total flight cycles or 48,000 total flight hours, whichever occurs first | Within 1,500 flight cycles or 3,000 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, A310-322, and A310-324 short range airplanes | 1 and 2 | Prior to the accumulation of 12,000 total flight cycles or 33,750 total flight hours, whichever occurs first | Within 1,200 flight cycles or 3,300 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, A310-322, and A310-324 short range airplanes | 3 | Prior to the accumulation of 18,000 total flight cycles or 50,500 total flight hours, whichever occurs first | Within 1,200 flight cycles or 3,300 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, A310-322, and A310-324 long range airplanes | 1 and 2 | Prior to the accumulation of 7,500 total flight cycles or 37,500 total flight hours, whichever occurs first | Within 750 flight cycles or 3,750 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, A310-322, and A310-324 long range airplanes | 3 | Prior to the accumulation of 11,250 total flight cycles or 56,000 total flight hours, whichever occurs first | Within 750 flight cycles or 3,750 flight hours, whichever occurs first, after the effective date of this AD |

(1) For areas 1, 2, and 3: Do a detailed inspection for cracking and corrosion of the lower horizontal stabilizer cutout longeron, the corner fitting, the skin strap, and the skin, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(i) If any corrosion is found, before further flight, repair in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(ii) If any cracking is found, before further flight, contact Airbus for repair instructions and do the repair.

(2) For areas 1, 2, and 3 on which cracking is not found during the inspection required by paragraph (g)(1) of this AD: Do a detailed inspection for damaged sealant; and, if any damaged sealant is found, before further flight, replace the sealant; in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(3) For area 1: Do an eddy current inspection for cracking in area 1; and, if no cracking is found, before further flight, apply sealant and corrosion compound, as applicable; in accordance with the

Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(i) If cracking is equal to or less than 2.0 mm (0.079 inch) long and not more than 2 cracks with a minimum distance of 50.0 mm (1.969 inch) between the cracks: Before further flight, remove any cracking and do an eddy current inspection for cracking of the reworked area, in accordance with the Accomplishment Instructions of the Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008. If no cracking is found, before further flight, shot peen the reworked area, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(A) If cracking is found and the radius of the rework is less than 20.0 mm (0.787 inch), before further flight, increase the radius and do an eddy current inspection for cracking of the reworked area, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008. If no cracking is found, before further flight, shot peen the reworked area, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(1) If any cracking is found in the outer skin, before further flight, contact Airbus for repair instructions and do the repair.

(2) If any cracking is found in the corner fitting and area 3 has not been cold expanded, before further flight, install new corner fitting, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008, and do the rotating probe inspection in area 3 specified in paragraph (g)(5) of this AD.

(3) If any cracking is found in the corner fitting and area 3 has been cold expanded, before further flight, do the eddy current inspection of the longeron and outer skin specified in paragraph (g)(6) of this AD.

(B) If cracking is found and the radius of the rework is 20.0 mm (0.787 inch) or more, before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the European Aviation Safety Agency (EASA) (or its delegated agent)

(ii) If cracking is greater than 2.0 mm (0.079 inch) long or there are more than 2 cracks; or if there are more than 2 cracks with less than a minimum distance of 50.0 mm (1.969 inch) between the cracks: Before further flight, remove the corner fitting, and do the applicable actions specified in paragraph (g)(3)(ii)(A) or (g)(3)(ii)(B) of this AD.

(A) If any cracking is found and area 3 has not been cold expanded, before further flight, install a new corner fitting, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008; and do the rotating probe inspection in area 3 specified in paragraph (g)(5) of this AD.

(B) If any cracking is found and area 3 has been cold expanded, before further flight, do the eddy current inspection of the longeron and outer skin specified in paragraph (g)(6) of this AD.

(4) For area 2: Do an eddy current inspection for cracking of area 2, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008. If any cracking is found, before further flight, contact Airbus for repair instructions and do the repair.

(5) For area 3: Do a rotating probe inspection for cracking of specified fastener holes in area 3, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(i) If no cracking is found, before further flight, drill or ream fastener holes, cold expand the fastener holes and countersinks, and wet install with sealant, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008; except where this service bulletin specifies to contact Airbus if the fastener diameter does not meet specifications or if the distance between the hole center and material edge is less than specifications, before further flight, contact Airbus for repair instructions and do the repair.

(ii) If cracking is found, before further flight, drill or ream fastener holes, and do a rotating probe inspection for cracking of the fastener holes in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(A) If no cracking is found, cold expand the fastener holes and countersinks, drill or ream fastener holes, and wet install with sealant, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008; except where this service bulletin specifies to contact Airbus if the fastener diameter does not meet specifications or if the distance between the hole center and material edge is less than the specifications, before further flight, contact Airbus for repair instructions and do the repair.

(B) If cracking is found, before further flight, contact Airbus for repair instructions and do the repair.

(6) For airplanes on which cracking is found in the corner fitting during any inspection required by paragraph (g)(3) of this AD and area 3 is cold-expanded: Do an eddy current inspection for cracking of the longeron and outer skin, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(i) If no cracking is found, before further flight, install a new corner fitting and do a rotating probe inspection for cracking of the fastener holes, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(A) If no cracking is found, before further flight, drill or ream fastener holes, cold expand the fastener holes and countersinks, and wet install with sealant, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(B) If cracking is found and the hole diameter is less than the maximum oversize specification, before further flight, drill or ream holes and do a rotating probe inspection for cracking of the fastener holes, in accordance with Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(1) If no cracking is found, cold expand the fastener holes and countersinks, and wet install with sealant, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

(2) If cracking is found, before further flight, contact Airbus for repair instructions and do the repair.

(C) If cracking is found and the hole diameter is equal to or greater than the maximum oversize specification, before further flight, contact Airbus for repair instructions and do the repair.

(ii) If cracking is found, before further flight, contact Airbus for repair instructions and do the repair.

Repetitive Inspections of the Lower Tail Plane Cut-Out Area

(h) Repeat the inspections for area 1 required by paragraphs (g)(1) and (g)(3) of this AD thereafter at the applicable intervals specified in Table 2 of this AD. Certain compliance times are applicable to short-range use (AFT equal to or less than 4 flight hours), or long-range use (AFT exceeding 4 flight hours). Inspection areas are specified in Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

Table 2—Repetitive Interval for Areas 1 and 2

| Affected Airplanes | Interval (not to exceed) |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| (1) Model A310-203, A310-204, and A310-222 airplanes that have accumulated less than 30,000 total flight cycles and 60,000 total flight hours, as of the effective date of this AD | 6,000 flight cycles or 12,000 flight hours, whichever occurs first, until the airplane accumulates 30,000 total flight cycles or 60,000 total flight hours; then perform the inspections within the interval specified in paragraph (h)(2) of this AD |
| (2) Model A310-203, A310-204, and A310-222 airplanes that have accumulated 30,000 total flight cycles or more or 60,000 total flight hours or more, as of the effective date of this AD | 3,900 flight cycles or 7,800 flight hours, whichever occurs first |
| (3) Model A310-304, A310-322 and A310-324 short range airplanes that have accumulated less than 24,000 total flight cycles and 67,500 total flight hours, as of the effective date of this AD | 4,800 flight cycles or 13,500 flight hours, whichever occurs first, until the airplane accumulates 24,000 total flight cycles or 67,500 total flight hours; then perform the inspections within the interval specified in paragraph (h)(4) of this AD |
| (4) Model A310-304, A310-322 and A310-324 short range airplanes that have accumulated 24,000 total flight cycles or more or 67,500 total flight hours or more, as of the effective date of this AD | 3,100 flight cycles or 8,750 flight hours, whichever occurs first |
| (5) Model A310-304, A310-322 and A310-324 long range airplanes that have accumulated less than 15,000 total flight cycles and 75,000 total flight hours, as of the effective date of this AD | 3,000 flight cycles or 15,000 flight hours, whichever occurs first, until the airplane accumulates 15,000 total flight cycles or 75,000 total flight hours; then perform the inspections within the interval specified in paragraph (h)(6) of this AD |
| (6) Model A310-304, A310-322 and A310-324 long range airplanes that have accumulated 15,000 total flight cycles or more or 75,000 total flight hours or more, as of the effective date of this AD | 1,950 flight cycles or 9,750 flight hours, whichever occurs first |

(i) Repeat the inspections for area 2 required by paragraphs (g)(1) and (g)(4) of this AD thereafter at the applicable intervals specified in Table 2 of this AD. Certain compliance times are applicable to short-range use (AFT equal to or less than 4 flight hours), or long-range use (AFT exceeding 4 flight hours). Inspection areas are specified in Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008.

Credit for Actions Accomplished in Accordance With Previous Service Information

(j) Inspections accomplished before the effective date of this AD in accordance with Airbus Mandatory Service Bulletin A310-53-2074, Revision 03, dated October 13, 2006, are considered acceptable for compliance with the corresponding action specified in this AD.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: The MCAI and service information do not specify a corrective action if cracking is found and the radius of the

rework is 20.0 mm (0.787 inch) or more. Paragraph (g)(3)(i)(B) of this AD requires repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or EASA (or its delegated agent).

Other FAA AD Provisions

(k) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to Attn: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(1) Refer to MCAI EASA Airworthiness Directive 2009-0058, dated March 13, 2009; and Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008; for related information.

Material Incorporated by Reference

(m) You must use Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS–EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 22, 2011.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-06 Airbus: Amendment 39-16687. Docket No. FAA-2010-1274; Directorate Identifier 2010-NM-090-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 15, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes, certificated in any category, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

DGAC [Direction Générale de l'Aviation Civile] France AD 1992-106-132(B) * * *
was issued to require a set of inspection and modification tasks which addressed
JAR/FAR [Joint Aviation Regulation/Federal Aviation Regulation] 25-571
requirements related to damage-tolerance and fatigue evaluation of structure.

* * * * *

The unsafe condition is reduced structural integrity of the wings.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Cold Working of Trellis Boom Drainage Holes

(g) For Model A310-203, -204, -222, -304, -322 and -324 airplanes, except airplanes identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD: Within the applicable time specified in Table 1 of this AD, cold work the trellis boom drainage holes, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007. Certain compliance times specified in Table 1 of this AD are applicable to short range use, average flight time (AFT) equal to or less than 3.6 hours; or long range use, AFT exceeding 3.6 hours.

Table 1—Compliance Times for Paragraph (g) of This AD

| Airplanes, as Identified in Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007 | Compliance Time (Whichever Occurs Later) | |
|--------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|
| Configuration 01 airplanes | Prior to the accumulation of 31,800 total flight cycles or 63,600 total flight hours, whichever occurs first | Within 6 months after the effective date of this AD |
| Configuration 02 airplanes | Prior to the accumulation of 40,000 total flight cycles or 80,000 total flight hours, whichever occurs first | Within 6 months after the effective date of this AD |
| Configuration 03 short range airplanes | Prior to the accumulation of 30,950 total flight cycles or 86,750 total flight hours, whichever occurs first | Within 6 months after the effective date of this AD |
| Configuration 03 long range airplanes | Prior to the accumulation of 24,100 total flight cycles or 120,600 total flight hours, whichever occurs first | Within 6 months after the effective date of this AD |

(1) Airplanes on which Airbus modification 06130 was done in production.

(2) Airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 was done in service.

(3) Airplanes on which rework of cracked drain holes was done in accordance with Airbus Mandatory Service Bulletin A310-57-2050.

Inspection of Trellis Boom Drainage Holes

(h) For all airplanes: Within the applicable intervals specified in Table 2 of this AD, perform a detailed or rotating probe inspection for cracking in the drain holes on the lower skin panel in the center wing box between frames 42 and 46, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2050, Revision 02, dated August 27, 2009. Repeat the inspections thereafter at intervals not to exceed the applicable times specified in Table 3 of this AD. Certain compliance times specified in Tables 2 and 3 of this AD are applicable to short range use, average flight time (AFT) equal to or less than 3.6 hours; or long range use, AFT exceeding 3.6 hours.

Table 2—Compliance Times for Paragraph (h) of This AD

| Airplanes, as Identified in Airbus Mandatory Service Bulletin A310-57-2050, Revision 02, dated August 27, 2009 | Compliance Time (Whichever Occurs Later) | |
|-----------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| Configuration 01 airplanes | Prior to the accumulation of 17,800 total flight cycles or 35,600 total flight hours, whichever occurs first | Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD |

| | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| Configuration 02 airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007 | Within 32,850 flight cycles or 65,700 flight hours, whichever occurs first, after accomplishing Airbus Mandatory Service Bulletin A310-57-2048 | Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD |
| Configuration 02 airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has not been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007 | Within 8,600 flight cycles or 17,250 flight hours, whichever occurs first, after accomplishing the detailed inspection specified in Airbus Mandatory Service Bulletin A310-57-2048; OR Within 11,400 flight cycles or 22,800 flight hours, whichever occurs first, after accomplishing the rotating probe inspection specified in Airbus Mandatory Service Bulletin A310-57-2048 | Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD |
| Configuration 03 airplanes | Prior to the accumulation of 22,300 total flight cycles or 44,550 total flight hours, whichever occurs first | Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD |
| Configuration 04 airplanes | Prior to the accumulation of 41,550 total flight cycles or 83,100 total flight hours, whichever occurs first | Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD |
| Configuration 05 airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007 | Prior to the accumulation of 40,000 total flight cycles or 80,000 total flight hours, whichever occurs first | Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD |

| | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|
| <p>Configuration 05 airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has not been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007</p> | <p>Within 10,600 flight cycles or 21,150 flight hours, whichever occurs first, after accomplishing the detailed inspection specified in Airbus Mandatory Service Bulletin A310-57-2048;</p> <p>OR</p> <p>Within 13,900 flight cycles or 27,800 flight hours, whichever occurs first, after accomplishing the rotating probe inspection specified in Airbus Mandatory Service Bulletin A310-57-2048</p> | <p>Within 1,000 flight cycles or 2,000 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 06 short range airplanes</p> | <p>Prior to the accumulation of 17,250 total flight cycles or 48,400 total flight hours, whichever occurs first</p> | <p>Within 1,000 flight cycles or 2,800 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 06 long range airplanes</p> | <p>Prior to the accumulation of 13,450 total flight cycles or 67,250 total flight hours, whichever occurs first</p> | <p>Within 800 flight cycles or 4,000 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 07 short range airplanes</p> | <p>Prior to the accumulation of 32,150 total flight cycles or 90,050 total flight hours, whichever occurs first</p> | <p>Within 1,000 flight cycles or 2,800 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 07 long range airplanes</p> | <p>Prior to the accumulation of 25,050 total flight cycles or 125,150 total flight hours, whichever occurs first</p> | <p>Within 800 flight cycles or 4,000 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 08 short range airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007</p> | <p>Prior to the accumulation of 30,950 total flight cycles or 86,750 total flight hours, whichever occurs first</p> | <p>Within 1,000 flight cycles or 2,800 flight hours, whichever occurs first, after the effective date of this AD</p> |

| | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|
| <p>Configuration 08 short range airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has not been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007</p> | <p>Within 8,200 flight cycles or 23,000 flight hours, whichever occurs first, after accomplishing the detailed inspection specified in Airbus Mandatory Service Bulletin A310-57-2048;</p> <p>OR</p> <p>Within 10,800 flight cycles or 30,300 flight hours, whichever occurs first, after accomplishing the rotating probe inspection specified in Airbus Mandatory Service Bulletin A310-57-2048</p> | <p>Within 1,000 flight cycles or 2,800 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 08 long range airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007</p> | <p>Prior to the accumulation of 24,100 total flight cycles or 120,600 total flight hours, whichever occurs first</p> | <p>Within 800 flight cycles or 4,000 flight hours, whichever occurs first, after the effective date of this AD</p> |
| <p>Configuration 08 long range airplanes on which Airbus Mandatory Service Bulletin A310-57-2048 has not been done within the “recommended” compliance times specified in paragraph 1.E.(2), “Accomplishment Timescale,” of Airbus Mandatory Service Bulletin A310-57-2048, Revision 01, dated May 22, 2007</p> | <p>Within 6,400 flight cycles or 31,950 flight hours, whichever occurs first, after accomplishing the detailed inspection specified in Airbus Mandatory Service Bulletin A310-57-2048;</p> <p>OR</p> <p>Within 8,400 flight cycles or 42,150 flight hours, whichever occurs first, after accomplishing the rotating probe inspection specified in Airbus Mandatory Service Bulletin A310-57-2048</p> | <p>Within 800 flight cycles or 4,000 flight hours, whichever occurs first, after the effective date of this AD</p> |

Table 3—Repetitive Intervals for Paragraph (h) of This AD, Depending on Most Recent Inspection Type

| Airplanes, as Identified in Airbus Mandatory Service Bulletin A310-57-2050, Revision 02, dated August 27, 2009 | Type of Inspection Done During Most Recent Inspection | Repetitive Interval (Not to Exceed) |
|-----------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|---------------------------------------------------------------------|
| Configuration 01 and 02 airplanes | Detailed inspection | 8,600 flight cycles or 17,250 flight hours, whichever occurs first |
| | Rotating probe inspection | 11,400 flight cycles or 22,800 flight hours, whichever occurs first |
| Configurations 03, 04, and 05 airplanes | Detailed inspection | 10,600 flight cycles or 21,150 flight hours, whichever occurs first |
| | Rotating probe inspection | 13,900 flight cycles or 27,800 flight hours, whichever occurs first |
| Configurations 06, 07, and 08 short range airplanes | Detailed inspection | 8,200 flight cycles or 23,000 flight hours, whichever occurs first |
| | Rotating probe inspection | 10,800 flight cycles or 30,300 flight hours, whichever occurs first |
| Configurations 06, 07, and 08 long range airplanes | Detailed inspection | 6,400 flight cycles or 31,950 flight hours, whichever occurs first |
| | Rotating probe inspection | 8,400 flight cycles or 42,150 flight hours, whichever occurs first |

Corrective Actions for Paragraph (h) of This AD

(i) If any cracking is found during any inspection required by paragraph (h) of this AD, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2050, Revision 02, dated August 27, 2009; except where the service bulletin specifies to contact Airbus, before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or European Aviation Safety Agency (EASA) (or its delegated agent).

Inspection of Fuselage Frame 40 Upper Corner Fitting

(j) For all airplanes: Within the applicable time specified in Table 4 of this AD, perform an eddy current inspection for cracking of the upper corner fitting at left and right frame 40, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2064, Revision 02, dated December 21, 2007. Repeat the inspections thereafter at intervals not to exceed the applicable times specified in Table 5 of this AD. Certain compliance times specified in Tables 4 and 5 of this AD are applicable to short range use, average flight time (AFT) equal to or less than 3.23 hours; or long range use, AFT exceeding 3.23 hours.

Table 4—Compliance Times for Paragraph (j) of This AD

| Airplane Configurations Identified in Airbus Mandatory Service Bulletin A310-57-2064, Revision 02, dated December 21, 2007 | Compliance Time (Whichever Occurs Later) | |
|-----------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|
| Model A310-203, -204, -221, and -222 airplanes identified as Configuration 01 | Prior to the accumulation of 15,100 total flight cycles or 30,300 total flight hours, whichever occurs first | Within 1,300 flight cycles or 2,700 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-203, -204, -221, and -222 airplanes identified as Configurations 02 and 03 | Prior to the accumulation of 21,400 total flight cycles or 42,800 total flight hours, whichever occurs first | Within 1,300 flight cycles or 2,700 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, -322, -324, and -325 short range airplanes identified as Configuration 01 | Prior to the accumulation of 14,700 total flight cycles or 41,300 total flight hours, whichever occurs first | Within 600 flight cycles or 1,800 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, -322, -324, and -325 short range airplanes identified as Configurations 02 and 03 | Prior to the accumulation of 20,700 total flight cycles or 58,300 total flight hours, whichever occurs first | Within 600 flight cycles or 1,800 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, -322, -324, and -325 long range airplanes identified as Configuration 01 | Prior to the accumulation of 12,800 total flight cycles or 64,000 total flight hours, whichever occurs first | Within 500 flight cycles or 2,650 flight hours, whichever occurs first, after the effective date of this AD |
| Model A310-304, -322, -324, and -325 long range airplanes identified as Configurations 02 and 03 | Prior to the accumulation of 18,000 total flight cycles or 90,400 total flight hours, whichever occurs first | Within 500 flight cycles or 2,650 flight hours, whichever occurs first, after the effective date of this AD |

Table 5—Repetitive Intervals for Paragraph (j) of This AD

| Airplanes | Repetitive Interval (Not to Exceed) |
|------------------------------------------------------------|--------------------------------------------------------------------|
| Model A310-203, -204, -221, and -222 airplanes | 8,750 flight cycles or 17,550 flight hours, whichever occurs first |
| Model A310-304, -322, -324, and -325 short range airplanes | 5,800 flight cycles or 16,300 flight hours, whichever occurs first |
| Model A310-304, -322, -324, and -325 long range airplanes | 4,800 flight cycles or 24,050 flight hours, whichever occurs first |

Corrective Actions for Paragraph (j) of This AD

(k) If, during any inspection required by paragraph (j) of this AD, any crack is found, prior to further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2064, Revision 02, dated December 21, 2007; except where the service bulletin specifies to contact Airbus, before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or EASA (or its delegated agent).

Credit for Actions Accomplished in Accordance With Previous Service Information

(l) Actions accomplished before the effective date of this AD in accordance with Airbus Service Bulletin A310-57-2048, dated April 23, 1990, are considered acceptable for compliance with the corresponding action specified in paragraph (g) of this AD.

(m) Actions accomplished before the effective date of this AD in accordance with Airbus Service Bulletin A310-57-2050, dated April 23, 1990; or Airbus Mandatory Service Bulletin A310-57-2050, Revision 01, dated May 22, 2007; are considered acceptable for compliance with the corresponding actions specified in paragraphs (h) and (i) of this AD.

(n) Actions done before the effective date of this AD in accordance with Airbus Service Bulletin A310-57-2064, dated August 24, 1995; or, Airbus Mandatory Service Bulletin A310-57-2064, Revision 01, dated January 5, 2001; are acceptable for compliance with the corresponding actions specified in paragraphs (j) and (k) of this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No Differences.

Other FAA AD Provisions

(o) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate, or if sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-Requests@faa.gov. Before using any approved AMOC, notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(p) Refer to MCAI EASA Airworthiness Directive 2009-0057, dated March 13, 2009, and the service bulletins listed in Table 6 of this AD, for related information.

Table 6–Service Information

| Service Bulletin | Revision | Date |
|------------------------------------------------|-----------------|-------------------|
| Airbus Mandatory Service Bulletin A310-57-2048 | 01 | May 22, 2007 |
| Airbus Mandatory Service Bulletin A310-57-2050 | 02 | August 27, 2009 |
| Airbus Mandatory Service Bulletin A310-57-2064 | 02 | December 21, 2007 |

Material Incorporated by Reference

(q) You must use the applicable service information contained in Table 7 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

Table 7–All Material Incorporated by Reference

| Service Bulletin | Revision | Date |
|-----------------------------------------------------------------------|-----------------|-------------------|
| Airbus Mandatory Service Bulletin A310-57-2048 | 01 | May 22, 2007 |
| Airbus Mandatory Service Bulletin A310-57-2050, excluding Appendix 01 | 02 | August 27, 2009 |
| Airbus Mandatory Service Bulletin A310-57-2064, excluding Appendix 1 | 02 | December 21, 2007 |

(1) The Director of the Federal Register approved the incorporation by reference of the service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS–EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 22, 2011.

Ali Bahrami,
 Manager, Transport Airplane Directorate,
 Aircraft Certification Service.



2011-10-07 Airbus: Amendment 39-16688. Docket No. FAA-2010-1275; Directorate Identifier 2010-NM-091-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 15, 2011.

Affected ADs

(b) This AD affects AD 90-19-07, Amendment 39-6731 (55 FR 37455, September 12, 1990); and AD 91-06-18, Amendment 39-6940 (56 FR 10796, March 14, 1991).

Applicability

(c) This AD applies to Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes, certificated in any category, all certified models, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

DGAC [Direction Générale de l'Aviation Civile] France Airworthiness Directive (AD) 1992-106-132(B) * * * was issued to require a set of inspection- and modification tasks which addressed JAR/FAR [Joint Aviation Regulation/Federal Aviation Regulation] 25-571 requirements related to damage-tolerance and fatigue evaluation of structure.

* * * * *

The unsafe condition is reduced structural integrity of the wings.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Certain Requirements of AD 98-26-01, Amendment 39-10942 (63 FR 69179, December 16, 1998), With Reduced Compliance Times

Leading Edge Access Panels Landing—Lower Skin—Inspection for Cracks at Bolt Holes

(g) For Model A310-203 and A310-222 airplanes listed in Airbus Service Bulletin A310-57-2002, Revision 2, dated January 4, 1996, except airplanes on which Airbus modification No. 05101 has been embodied in production, or on which Airbus Service Bulletin A310-57-2003 has been embodied in service before the accumulation of 9,400 total flight cycles and 18,800 total flight hours: At the times specified in paragraph (h) of this AD, perform a detailed visual inspection to detect cracks in the external surface of the wing lower skin around the landing access panel holes of the leading edge, in accordance with the Airbus Service Bulletin A310-57-2002, Revision 1, dated July 2, 1992; Airbus Service Bulletin A310-57-2002, Revision 2, dated January 4, 1996; or Airbus Mandatory Service Bulletin A310-57-2002, Revision 03, dated November 28, 2006. If any discrepancy is found, prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent) or EASA (or its delegated agent). Except as required by paragraph (n) of this AD, repeat the detailed inspection specified in this paragraph at the earlier of the times specified in paragraphs (g)(1) and (g)(2) of this AD; and thereafter at intervals not to exceed 2,300 flight cycles or 4,700 flight hours, whichever occurs first. As of the effective date of this AD, use only Airbus Mandatory Service Bulletin A310-57-2002, Revision 03, dated November 28, 2006. Accomplishment of Airbus Modification 05101 before the effective date of this AD terminates the repetitive inspection requirements of this paragraph; however, airplanes identified in paragraph (n) of this AD are applicable to the new inspections required by paragraph (n) of this AD. As of the effective date of this AD: Accomplishment of Airbus Modification 05101 before the accumulation of 9,400 total flight cycles and 18,800 total flight hours terminates the repetitive inspection requirements of this paragraph.

Note 1: Airbus Service Bulletin A310-57-2003, Revision 03, dated October 16, 2006, is an additional source of guidance for accomplishing Airbus Modification 05101.

Note 2: As of the effective date of this AD, if Airbus Service Bulletin A310-57-2003 is done on or after the accumulation of 9,400 total flight cycles or on or after the accumulation of 18,800 total flight hours, the actions specified in paragraph (g) of this AD are still required.

(1) Within 3,000 flight cycles after doing the detailed inspection specified in paragraph (g) of this AD.

(2) At the later of the times specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD.

(i) Within 2,300 flight cycles or 4,700 flight hours, whichever occurs first, after doing the detailed inspection required by paragraph (g) of this AD.

(ii) Within 1,500 flight cycles or 3,000 flight hours, whichever occurs first, after the effective date of this AD.

(h) For Model A310-203 and A310-222 airplanes listed in Airbus Service Bulletin A310-57-2002, Revision 2, dated January 4, 1996, except airplanes on which Airbus modification No. 05101 has been embodied in production, or on which Airbus Service Bulletin A310-57-2003 has been embodied in service before the accumulation of 9,400 total flight cycles and 18,800 total flight hours: At the earlier of the times specified in paragraphs (h)(1) and (h)(2) of this AD, do the detailed inspection required by paragraph (g) of this AD.

(1) Prior to the accumulation of 12,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999 (the effective date of AD 98-26-01, amendment 39-10942), whichever occurs later.

(2) At the later of the times specified in paragraph (h)(2)(i) and (h)(2)(ii) of this AD.

(i) Prior to the accumulation of 9,400 total flight cycles or 18,800 total flight hours, whichever occurs first.

(ii) Within 1,500 flight cycles or 3,000 flight hours, whichever occurs first, after the effective date of this AD.

Inspect Area around Overwing Refueling Aperture at Ribs 13-14

(i) For Model A310-203, A310-204, A310-222, A310-304, A310-322, A310-324, and A310-325 airplanes that are listed in Airbus Service Bulletin A310-57-2006, Revision 3, dated May 2, 1996, and are identified as Configuration 1 in Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007: Prior to the accumulation of 6,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later, perform an eddy current inspection to detect cracks in the holes around the overwing refueling aperture at ribs 13-14, in accordance with Airbus Service Bulletin A310-57-2006, Revision 3, dated May 2, 1996; or Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007. If any discrepancy is found, prior to further flight, perform follow-on corrective actions, as applicable, in accordance with Airbus Service Bulletin A310-57-2006, Revision 3, dated May 2, 1996; or Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007; except where the service bulletin specifies to contact Airbus for repair, before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the DGAC (or its delegated agent) or EASA (or its delegated agent). Repeat the inspection specified in this paragraph at the earlier of the times specified in paragraphs (i)(1) and (i)(2) of this AD, and thereafter at intervals not to exceed 2,300 flight cycles or 4,600 flight hours, whichever occurs first. As of the effective date of this AD, use only Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007. Accomplishment of Airbus Modification 05891H5128 terminates the repetitive inspections required by this paragraph.

(1) Within 3,000 flight cycles after doing the last inspection required by paragraph (i) of this AD.

(2) At the later of the times specified in paragraphs (i)(2)(i) and (i)(2)(ii) of this AD.

(i) Within 2,300 flight cycles or 4,600 flight hours, whichever occurs first, after doing the most recent inspection required by paragraph (i) of this AD.

(ii) Within 380 flight cycles or 770 flight hours, whichever occurs first, after the effective date of this AD.

Note 3: Airbus Service Bulletin A310-57-2020, Revision 07, dated June 5, 2006, is an additional source of guidance for accomplishing Airbus Modification 05891H5128.

Upper Skin Forward of Front Spar—Inspection for Cracks

(j) For Model A310-203 and A310-222 airplanes listed in Airbus Service Bulletin A310-57-2032, Revision 3, dated January 4, 1996, except airplanes on which Airbus modification 05026 has been embodied in production, or on which Airbus Service Bulletin A310-57-2005 has been done in service before the accumulation of 10,500 total flight cycles and 21,000 total flight hours: At the times specified in paragraph (k) of this AD, perform a detailed visual inspection to detect cracks around the bolts in the wing top skin upper surface of the front spar between rib 7 and rib 28, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-57-2032, Revision 3, dated January 4, 1996; or Airbus Mandatory Service Bulletin A310-57-2032, Revision 04, dated December 1, 2006. If any discrepancy is found, prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or DGAC (or its delegated agent) or EASA (or its delegated agent). Except as required by paragraph (p) of this AD, repeat the detailed inspection specified in this paragraph at the earlier of the times specified in paragraphs (j)(1) and (j)(2) of this AD, and thereafter at intervals not to exceed 3,900 flight cycles or 7,900 flight hours, whichever occurs first. As of the effective date of

this AD, use only Airbus Mandatory Service Bulletin A310-57-2032, Revision 04, dated December 1, 2006. Accomplishment of Airbus Modification 05026H0878 before the effective date of this AD terminates the repetitive inspection requirements of this paragraph; however, airplanes identified in paragraph (p) of this AD are applicable to the new inspections required by paragraph (p) of this AD. As of the effective date of this AD: Accomplishment of Airbus Modification 05026H0878 before the accumulation of 10,500 total flight cycles and 21,000 total flight hours terminates the repetitive inspection requirements of this paragraph.

(1) Within 4,500 flight cycles after doing the last inspection required by paragraph (j) of this AD.

(2) At the later of the times specified in paragraphs (j)(2)(i) and (j)(2)(ii) of this AD.

(i) Within 3,900 flight cycles or 7,900 flight hours, whichever occurs first, after doing the most recent inspection required by paragraph (j) of this AD.

(ii) Within 850 flight cycles or 1,700 flight hours, whichever occurs first, after the effective date of this AD.

Note 4: Airbus Service Bulletin A310-57-2005, Revision 03, dated October 2, 2006, is an additional source of guidance for accomplishing Airbus Modification 05026H0878.

Note 5: As of the effective date of this AD, if Airbus Service Bulletin A310-57-2005 is done on or after the accumulation of 10,500 total flight cycles or on or after the accumulation of 21,000 total flight hours, the actions specified in paragraph (j) of this AD are still required.

(k) For Model A310-203 and A310-222 airplanes listed in Airbus Service Bulletin A310-57-2032, Revision 3, dated January 4, 1996, except airplanes on which Airbus modification 05026 has been embodied in production, or on which Airbus Service Bulletin A310-57-2005 has been done in service before the accumulation of 10,500 total flight cycles and 21,000 total flight hours: At the earlier of the times specified in paragraphs (k)(1) and (k)(2) of this AD, do the detailed inspection required by paragraph (j) of this AD.

(1) Prior to the accumulation of 12,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later.

(2) At the later of the times specified in paragraphs (k)(2)(i) and (k)(2)(ii) of this AD.

(i) Prior to the accumulation of 10,500 total flight cycles or 21,000 total flight hours, whichever occurs first.

(ii) Within 850 flight cycles or 1,700 flight hours, whichever occurs first, after the effective date of this AD.

Stringer Flanges at Rib 14 Wing Bottom Skin—Inspect for Cracks

(l) For Model A310-203 and A310-222 airplanes listed in Airbus Service Bulletin A310-57-2038, Revision 2, dated January 4, 1996, except airplanes on which Airbus modification 04987 has been done in production: At the compliance time specified in paragraph (m) of this AD, perform a high frequency eddy current (HFEC) or X-ray inspection to detect cracking of the stringer runouts inboard and outboard of rib 14 at stringers 6, 7, 8, and 9, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-57-2038, Revision 2, dated January 4, 1996; or Airbus Mandatory Service Bulletin A310-57-2038, Revision 04, dated October 19, 2006. Do the next inspection at the earlier of the times specified in paragraph (l)(1) and (l)(2) of this AD, and repeat the inspection thereafter at intervals not to exceed the applicable times specified in table 1 of this AD. If any crack is detected, prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or DGAC (or its delegated agent) or EASA (or its delegated agent). As of the effective date of this AD, use only Airbus Mandatory Service Bulletin A310-57-2038, Revision 04, dated October 19, 2006.

(1) Within the applicable interval specified in paragraph 1.B.(5) of Airbus Service Bulletin A310-57-2038, Revision 2, dated January 4, 1996.

- (2) At the later of the times specified in paragraph (l)(2)(i) and (l)(2)(ii) of this AD.
- (i) Within the applicable interval specified in table 1 of this AD after doing the most recent inspection specified in paragraph (l) of this AD.
- (ii) Within 1,100 flight cycles or 2,300 flight hours, whichever occurs first, after the effective date of this AD.

Table 1—Repetitive Intervals, Depending on Inspection Type

| Type of Inspection | Repetitive Interval (Not to Exceed) |
|---------------------------|--------------------------------------------------------------------|
| X-Ray | 7,200 flight cycles or 14,500 flight hours, whichever occurs first |
| HFEC | 9,400 flight cycles or 18,800 flight hours, whichever occurs first |

(m) For Model A310-203 and A310-222 airplanes listed in Airbus Service Bulletin A310-57-2038, Revision 2, dated January 4, 1996, except airplanes on which Airbus modification 04987 has been done in production: At the earlier of the times specified in paragraphs (m)(1) and (m)(2) of this AD, perform an inspection required by paragraph (l) of this AD.

(1) Prior to the accumulation of 12,000 total flight cycles, or within 1,500 flight cycles after January 20, 1999, whichever occurs later.

(2) At the later of the times specified in paragraphs (m)(2)(i) and (m)(2)(ii) of this AD.

(i) Prior to the accumulation of 12,000 total flight cycles or 24,000 total flight hours, whichever occurs first.

(ii) Within 1,100 flight cycles or 2,300 flight hours after the effective date of this AD, whichever occurs first.

New Requirements of This AD

Leading Edge Access Panels Landing—Lower Skin—Inspection for Cracks at Bolt Holes—Additional Inspections for Certain Airplanes

(n) For Model A310-203 and A310-222 airplanes, on which Airbus Service Bulletin A310-57-2003 has been done in service on or after the accumulation of 9,400 total flight cycles or on or after the accumulation of 18,800 total flight hours: Do the inspection required by paragraph (g) of this AD at the later of the times specified in paragraphs (n)(1) and (n)(2) of this AD. Repeat the inspection required by paragraph (g) of this AD thereafter at intervals not to exceed 2,300 flight cycles or 4,700 flight hours, whichever occurs first.

(1) Within 2,300 flight cycles or 4,700 flight hours, whichever occurs first, after doing the most recent detailed inspection required by paragraph (g) of this AD.

(2) Within 1,500 flight cycles or 3,000 flight hours, after the effective date of this AD, whichever occurs first.

Inspect Area Around Overwing Refueling Aperture at Ribs 13-14 for Additional Airplanes

(o) For Model A310-203, A310-204, A310-222, A310-304, A310-322, A310-324, and A310-325 airplanes, except for airplanes identified in paragraph (i) of this AD on which Airbus Modification 05891H5128 has not been done: At the applicable compliance time specified in table 2 of this AD, do the applicable actions specified in paragraph (o)(1) or (o)(2) of this AD, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007. If any cracking is found, before further flight, repair in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007; except where this service bulletin specifies to contact Airbus for repair, before

further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or EASA (or its delegated agent). Repeat the inspections thereafter at the applicable interval specified in table 2 of this AD. Certain compliance times specified in table 2 of this AD are applicable to short range use, average flight time (AFT) equal to or less than 4.0 hours, or long range use, AFT exceeding 4.0 hours. For airplanes identified as Configuration 01 in Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007, accomplishment of Airbus Modification 05891H5128 terminates the repetitive inspections required by this paragraph for Configuration 01 airplanes; thereafter do the applicable actions specified in paragraph (o)(2) of this AD at the times specified in table 2 of this AD.

Note 6: Airbus Service Bulletin A310-57-2020, Revision 07, dated June 5, 2006, is an additional source of guidance for accomplishing Airbus Modification 05891H5128.

(1) For Configuration 01 airplanes, as identified in Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007: Do a rotating probe eddy current inspection for cracking in the holes around the overwing refueling aperture at ribs 13-14.

(2) For Configuration 02 through 06 airplanes, as identified in Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007: Do an external detailed inspection for cracking of the top skin at ribs 13-14, and an internal detailed inspection for cracking of string 7 and string 8 of the overwing refuel aperture.

Table 2—Compliance Times for Configuration 01 Through 06 Airplanes

| Airplanes as Identified in Airbus Mandatory Service Bulletin A310-57-2006, Revision 04, dated May 21, 2007 | Compliance Time (Whichever Occurs Later) | | Repetitive Interval (Not to Exceed) |
|-------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| Configuration 01 airplanes | Prior to the accumulation of 6,000 total flight cycles | Within 380 flight cycles or 770 flight hours, whichever occurs first, after the effective date of this AD | 2,300 flight cycles or 4,600 flight hours, whichever occurs first |
| Configuration 02 airplanes | Within 30,900 flight cycles or 61,900 flight hours, whichever occurs first, after accomplishing Airbus Service Bulletin A310-57-2020 | Within 1,500 flight cycles or 18 months, whichever occurs first, after the effective date of this AD | 11,300 flight cycles or 22,600 flight hours, whichever occurs first |
| Configuration 03 airplanes | Within 30,900 flight cycles or 61,900 flight hours, whichever occurs first, after Airbus Modification 05891H5128 is done or Airbus Service Bulletin A310-57-2020 is accomplished | Within 1,500 flight cycles or 18 months, whichever occurs first, after the effective date of this AD | 12,000 flight cycles or 24,000 flight hours, whichever occurs first |

| | | | |
|-----------------------------------------------|------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| Configuration 04 and 05 short range airplanes | Before the accumulation of 25,900 total flight cycles or 72,500 total flight hours, whichever occurs first | Within 1,500 flight cycles or 18 months, whichever occurs first, after the effective date of this AD | 12,000 flight cycles or 33,600 flight hours, whichever occurs first |
| Configuration 04 and 05 long range airplanes | Before the accumulation of 18,800 total flight cycles or 94,200 total flight hours, whichever occurs first | Within 1,500 flight cycles or 18 months, whichever occurs first, after the effective date of this AD | 9,400 flight cycles or 47,200 flight hours, whichever occurs first |
| Configuration 06 | Before the accumulation of 30,900 total flight cycles or 61,900 total flight hours, whichever occurs first | Within 1,500 flight cycles or 18 months, whichever occurs first, after the effective date of this AD | 12,000 flight cycles or 24,000 flight hours, whichever occurs first |

Upper Skin Forward of Front Spar–Inspection for Cracks–Additional Inspections for Certain Airplanes

(p) For Model A310-203 and A310-222 airplanes on which Airbus Service Bulletin A310-57-2005 has been done in service on or after the accumulation of 10,500 total flight cycles or on or after 21,000 total flight hours: Do the inspection required by paragraph (j) of this AD at the later of the times specified in paragraphs (p)(1) and (p)(2) of this AD. Repeat the inspection specified in paragraph (j) of this AD thereafter at intervals not to exceed 3,900 flight cycles or 7,900 flight hours, whichever occurs first.

(1) Within 3,900 flight cycles or 7,900 flight hours, whichever occurs first, after doing the most recent inspection required by paragraph (j) of this AD.

(2) Within 850 flight cycles or 1,700 flight hours, whichever occurs first, after the effective date of this AD.

Inspection of Rear Spar at Selected Bolt Locations for Attachment of Main landing Gear Forward Pick-Up Fitting

(q) For Model A310-203, A310-204, A310-222, A310-304, A310-322, and A310-324 airplanes, except airplanes on which Airbus modification 07601 has been done in production: Do the applicable actions specified in paragraphs (q)(1), (q)(2), and (q)(3) of this AD. If any cracking is found during any inspection, before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or EASA (or its delegated agent).

Note 7: For Model A310-304, A310-322, and A310-324 airplanes on which Airbus modification 07601 has been done, guidance for post-modification inspections can be found in Structure Significant Item (SSI) 57.21.16 of the Maintenance Review Board Document (MRBD).

(1) For airplanes on which Airbus Modification 07925H1113 and Modification 11578H5436 have not been done: At the applicable time specified in table 3 of this AD, perform an ultrasonic inspection for cracking in certain bolt holes where the main landing gear forward pick-up fitting is attached to the rear spar, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2046, Revision 08, dated December 1, 2006. Repeat the inspection thereafter at the applicable interval specified in table 3 of this AD until Airbus Modification

07925H1113 or 11578H5436 has been done. After doing Airbus Modification 07925H1113 or 11578H5436 do the applicable actions specified in paragraph (q)(2) or (q)(3) of this AD at the times specified in paragraph (q)(2) or (q)(3) of this AD, as applicable. Certain compliance times specified in table 3 of this AD are applicable to short range use, average flight time (AFT) equal to or less than 4.0 hours, or long range use, AFT exceeding 4.0 hours.

Note 8: Airbus Service Bulletin A310-57-2049, Revision 6, dated November 26, 1997, is an additional source of guidance for accomplishing Airbus Modification 07925H1113. Airbus Service Bulletin A310-57-2074, Revision 03, dated July 3, 2006, is an additional source of guidance for accomplishing Airbus Modification 11578H5436.

Table 3—Compliance Times for Airplanes Pre-Mod 07925 and Pre-Mod 11578

| Airplanes | Compliance Time (Whichever Occurs Later) | | Repetitive Interval (Not to Exceed) |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|
| Model A310-203, A310-204, and A310-222 airplanes | Prior to the accumulation of 9,800 total flight cycles or 19,600 total flight hours, whichever occurs first | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 2,800 flight cycles or 5,700 flight hours, whichever occurs first |
| Model A310-304, A310-322, and A310-324 short range airplanes | Prior to the accumulation of 7,100 total flight cycles or 20,100 total flight hours, whichever occurs first | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 2,400 flight cycles or 6,900 flight hours, whichever occurs first |
| Model A310-304, A310-322, and A310-324 long range airplanes | Prior to the accumulation of 5,700 total flight cycles or 28,600 total flight hours, whichever occurs first | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 1,900 flight cycles or 9,800 flight hours, whichever occurs first |

(2) For airplanes on which Airbus Modification 07925H1113 has been done: At the applicable time specified in table 4 of this AD, perform an ultrasonic inspection for cracking in certain bolt holes where the main landing gear forward pick-up fitting is attached to the rear spar, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2046, Revision 08, dated December 1, 2006. Repeat the inspection thereafter at the applicable interval specified in table 4 of this AD. Certain compliance times specified in table 4 of this AD are applicable to short range use, AFT equal to or less than 4.0 hours, or long range use, AFT exceeding 4.0 hours.

Table 4–Compliance Times for Airplanes Post-Mod 07925

| Airplanes | Compliance Time (Whichever Occurs Later) | | Repetitive Interval (Not to Exceed) |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| Model A310-203, A310-204, and A310-222 airplanes | Prior to the accumulation of 14,700 total flight cycles or 29,400 total flight hours, whichever occurs first | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 9,400 flight cycles or 18,900 flight hours, whichever occurs first |
| Model A310-304, A310-322, and A310-324 short range airplanes | Prior to the accumulation of 11,900 total flight cycles or 33,500 total flight hours, whichever occurs first | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 5,000 flight cycles or 14,000 flight hours, whichever occurs first |
| Model A310-304, A310-322, and A310-324 long range airplanes | Prior to the accumulation of 9,500 total flight cycles or 47,700 total flight hours, whichever occurs first | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 4,000 flight cycles or 20,000 flight hours, whichever occurs first |

(3) For airplanes on which Airbus Modification 11578H5436 has been done: At the applicable time specified in table 5 of this AD, perform an ultrasonic inspection for cracking in certain bolt holes where the main landing gear forward pick-up fitting is attached to the rear spar, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-57-2046, Revision 08, dated December 1, 2006. Repeat the inspection thereafter at the applicable interval specified in table 5 of this AD. Certain compliance times specified in table 5 of this AD are applicable to short range use, average flight time (AFT) equal to or less than 4.0 hours, or long range use, AFT exceeding 4.0 hours.

Table 5–Compliance Times for Airplanes Post-Mod 11578

| Airplanes | Compliance Time (Whichever Occurs Later) | | Repetitive Interval (Not to Exceed) |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| Model A310-203, A310-204, and A310-222 airplanes | Within 29,600 flight cycles or 59,200 flight hours, whichever occurs first, after Airbus Modification 11578H5436 has been done | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 9,400 flight cycles or 18,900 flight hours, whichever occurs first |
| Model A310-304, A310-322, and A310-324 short range airplanes | Within 24,200 flight cycles or 67,900 flight hours, whichever occurs first, after Airbus Modification 11578H5436 has been done | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 5,000 flight cycles or 14,000 flight hours, whichever occurs first |

| | | | |
|-------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| Model A310-304, A310-322, and A310-324 long range airplanes | Within 19,300 flight cycles or 96,800 flight hours, whichever occurs first, after Airbus Modification 11578H5436 has been done | Within 750 flight cycles or 1,500 flight hours, whichever occurs first, after the effective date of this AD | 4,000 flight cycles or 20,000 flight hours, whichever occurs first |
|-------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|

Credit for Actions Accomplished in Accordance With Previous Service Information

(r) Actions done before the effective date of this AD in accordance with Airbus Service Bulletin A310-57-2038, Revision 03, dated September 4, 1998, are acceptable for compliance with the corresponding actions specified in paragraph (l) of this AD.

(s) Actions done before the effective date of this AD in accordance with Airbus Service Bulletin A310-57-2046, Revision 07, dated April 2, 1999, are acceptable for compliance with the corresponding actions specified in paragraph (q) of this AD.

Terminating Action for Paragraph (a) of AD 90-19-07

(t) Accomplishing an inspection in accordance with Airbus Service Bulletin A310-57-2038, Revision 2, dated January 4, 1996, or Revision 03, dated September 4, 1998; or Airbus Mandatory Service Bulletin A310-57-2038, Revision 04, dated October 19, 2006; terminates the requirements of paragraph (a) of AD 90-19-07.

Note 9: Airbus Service Bulletin A310-57-2038, Revision 2, dated January 4, 1996; and Airbus Mandatory Service Bulletin A310-57-2038, Revision 04, dated October 19, 2006; are referred to in paragraph (l) of this AD. Airbus Service Bulletin A310-57-2038, Revision 03, dated September 4, 1998, is referred to in paragraph (r) of this AD.

Terminating Action for AD 91-06-18

(u) Accomplishing an inspection in accordance with Airbus Service Bulletin A310-57-2046, Revision 4, dated October 16, 1996, as revised by Airbus Service Bulletin Change Notice 4A, dated October 16, 1996; Airbus Service Bulletin A310-57-2046, Revision 07, dated April 2, 1999; or Airbus Mandatory Service Bulletin A310-57-2046, Revision 08, dated December 1, 2006; terminates the requirements of AD 91-06-18.

Note 10: Airbus Mandatory Service Bulletin A310-57-2046, Revision 08, dated December 1, 2006, is referred to in paragraph (q) of this AD. Airbus Service Bulletin A310-57-2046, Revision 07, dated April 2, 1999, is referred to in paragraph (s) of this AD. Airbus Service Bulletin A310-57-2046, Revision 4, dated October 16, 1996, as revised by Airbus Service Bulletin Change Notice 4A, dated October 16, 1996, is referred to in paragraph (n) of AD 98-26-01.

FAA AD Differences

Note 11: This AD differs from the MCAI and/or service information as follows:

Although the MCAI or service information allows further flight after cracks are found during compliance with the required action, paragraph (j) of this AD requires that you repair the crack(s) before further flight.

Other FAA AD Provisions

(v) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your principal inspector or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 98-26-01, are approved as AMOCs for the corresponding provisions of this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(w) Refer to MCAI EASA Airworthiness Directive 2007-0242, dated September 4, 2007, and the Airbus service bulletins listed in table 6 of this AD for related information.

Table 6—Related Service Information

| Service Bulletin | Revision | Date |
|--------------------------------------------------------|-----------------|-------------------|
| Airbus Mandatory Service Bulletin A310-57-2002 | 03 | November 28, 2006 |
| Airbus Mandatory Service Bulletin A310-57-2006 | 04 | May 21, 2007 |
| Airbus Mandatory Service Bulletin A310-57-2032 | 04 | December 1, 2006 |
| Airbus Mandatory Service Bulletin A310-57-2038 | 04 | October 19, 2006 |
| Airbus Mandatory Service Bulletin A310-57-2046 | 08 | December 1, 2006 |
| Airbus Service Bulletin A310-57-2038 | 2 | January 4, 1996 |
| Airbus Service Bulletin A310-57-2038 | 03 | September 4, 1998 |
| Airbus Service Bulletin A310-57-2046 | 4 | October 16, 1996 |
| Airbus Service Bulletin A310-57-2046 | 07 | April 2, 1999 |
| Airbus Service Bulletin A310-57-2046, Change Notice 4A | Original | October 16, 1996 |

Material Incorporated by Reference

(x) You must use the service bulletins contained in table 7 of this AD to do the actions required by this AD, unless the AD specifies otherwise. If you accomplish the optional terminating actions specified by this AD, you must use the service information contained in table 7 of this AD to perform those actions unless the AD specifies otherwise.

Table 7—All Material Incorporated by Reference

| Service Bulletin | Revision | Date | Required/ Optional Action |
|--------------------------------------------------------|-----------------|-------------------|------------------------------------------|
| Airbus Mandatory Service Bulletin A310-57-2002 | 03 | November 28, 2006 | Required |
| Airbus Mandatory Service Bulletin A310-57-2006 | 04 | May 21, 2007 | Required |
| Airbus Mandatory Service Bulletin A310-57-2032 | 04 | December 1, 2006 | Required |
| Airbus Mandatory Service Bulletin A310-57-2038 | 04 | October 19, 2006 | Required and optional |
| Airbus Mandatory Service Bulletin A310-57-2046 | 08 | December 1, 2006 | Required and Optional |
| Airbus Service Bulletin A310-57-2038 | 2 | January 4, 1996 | Optional |
| Airbus Service Bulletin A310-57-2038 | 03 | September 4, 1998 | Optional |
| Airbus Service Bulletin A310-57-2046 | 4 | October 16, 1996 | Optional |
| Airbus Service Bulletin A310-57-2046 | 07 | April 2, 1999 | Optional |
| Airbus Service Bulletin A310-57-2046, Change Notice 4A | Original | October 16, 1996 | Optional |

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in table 8 of this AD under 5 U.S.C. 552(a) and 1 CFR part 51.

Table 8—New Material Incorporated by Reference

| Service Bulletin | Revision | Date |
|------------------------------------------------|-----------------|-------------------|
| Airbus Mandatory Service Bulletin A310-57-2002 | 03 | November 28, 2006 |
| Airbus Mandatory Service Bulletin A310-57-2006 | 04 | May 21, 2007 |
| Airbus Mandatory Service Bulletin A310-57-2032 | 04 | December 1, 2006 |
| Airbus Mandatory Service Bulletin A310-57-2038 | 04 | October 19, 2006 |
| Airbus Mandatory Service Bulletin A310-57-2046 | 08 | December 1, 2006 |
| Airbus Service Bulletin A310-57-2038 | 03 | September 4, 1998 |
| Airbus Service Bulletin A310-57-2046 | 07 | April 2, 1999 |

(2) The Director of the Federal Register previously approved the incorporation by reference of the service information contained in table 9 of this AD on January 20, 1999 (63 FR 69179, December 16, 1998).

Table 9—Material Previously Incorporated by Reference

| Service Bulletin | Revision | Date |
|--------------------------------------------------------|-----------------|------------------|
| Airbus Service Bulletin A310-57-2038 | 2 | January 4, 1996 |
| Airbus Service Bulletin A310-57-2046 | 4 | October 16, 1996 |
| Airbus Service Bulletin A310-57-2046, Change Notice 4A | Original | October 16, 1996 |

(3) For service information identified in this AD, contact Airbus SAS–EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 22, 2011.

Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-08 Airbus: Amendment 39-16689. Docket No. FAA-2010-1276; Directorate Identifier 2010-NM-092-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 15, 2011.

Affected ADs

(b) This AD supersedes AD 98-26-01, Amendment 39-10942, and AD 91-13-01, Amendment 39-7032.

Applicability

(c) This AD applies to Airbus Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes, certificated in any category, all certified models, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Codes 53: Fuselage, 55: Stabilizers, and 57: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

DGAC [Direction Générale de l'Aviation Civile] France AD 1992-106-132(B) * * *
has been issued in order to mandate a set of inspections/modifications which address
JAR/FAR [Joint Aviation Regulation/Federal Aviation Regulation] 25-571
requirements related to damage-tolerance and fatigue evaluation of structure.

* * * * *

The unsafe condition is reduced structural integrity of the wings, fuselage, and stabilizers.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Certain Requirements of AD 98-26-01

Actions for Service Bulletin A310-53-2016—No Changes

(g) For airplanes listed in Airbus Service Bulletin A310-53-2016, Revision 5, dated December 7, 1992: Prior to the accumulation of 12,000 total flight cycles, or within 1,000 flight cycles after

January 20, 1999 (the effective date of AD 98-26-01), whichever occurs later, perform a defectoscope or rototest inspection to detect cracks in the area of frame 47 and frame 54, and install new doublers, in accordance with Airbus Service Bulletin A310-53-2016, Revision 5, dated December 7, 1992. Except as provided by paragraph (m) of this AD, if any discrepancy is found, prior to further flight, perform follow-on corrective actions, as applicable, in accordance with Airbus Service Bulletin A310-53-2016, Revision 5, dated December 7, 1992.

Note 1: Airplanes on which Airbus Modification 04980 is done in production are not affected by paragraph (g) of this AD.

Actions for Service Bulletin A310-53-2054, With Latest Optional Modification

(h) For airplanes listed in Airbus Service Bulletin A310-53-2054, Revision 2, dated May 22, 1990: Prior to the accumulation of 12,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later, and thereafter at intervals not to exceed 3,000 flight cycles, perform a visual inspection to detect cracks on frame 46 between the left- and right-hand sides of stringers 21 and 22 on the forward and aft faces, in accordance with Airbus Service Bulletin A310-53-2054, Revision 2, dated May 22, 1990. If any crack is found, prior to further flight, repair in accordance with Airbus Service Bulletin A310-53-2054, Revision 2, dated May 22, 1990.

Note 2: Airplanes on which Airbus modification 05254 is done in production; or on which Airbus Service Bulletin A310-53-2019, Revision 2, dated May 22, 1990, or Revision 3, dated February 28, 1991, is done in service; are not affected by paragraph (h) of this AD.

(1) Prior to the effective date of this AD: Accomplishment of the repair required by paragraph (h) of this AD; or modification of the reinforcement angle runout in accordance with Airbus Service Bulletin A310-53-2019, Revision 2, dated May 22, 1990, or Revision 3, dated February 28, 1991; terminates the repetitive inspection requirements of paragraph (h) of this AD.

(2) On or after the effective date of this AD: Accomplishment of the repair required by paragraph (h) of this AD; or modification of the reinforcement angle runout in accordance with Airbus Service Bulletin A310-53-2019, Revision 3, dated February 28, 1991; terminates the repetitive inspection requirements of paragraph (h) of this AD.

Actions for Service Bulletin A310-53-2057—No Changes

(i) For airplanes listed in Airbus Service Bulletin A310-53-2057, Revision 1, dated April 30, 1992: Perform a visual inspection to detect cracks at the T-section connecting frame 50A to the beam between the left- and right-hand sides of frames 50 and 51, in accordance with Airbus Service Bulletin A310-53-2057, Revision 1, dated April 30, 1992. Perform the inspection at the time specified in paragraph (i)(1) or (i)(2) of this AD, as applicable. If any crack is found, prior to further flight, accomplish Airbus Modifications No. 4853 and No. 5273, in accordance with Airbus Service Bulletin A310-53-2057, Revision 1, dated April 30, 1992. Accomplishment of these modifications terminates the requirements of this paragraph.

Note 3: Airplanes on which Airbus modification 4853 is done are affected by paragraph (i) of this AD, except those airplanes on which Airbus Modification 5273 has been done or on which Airbus Service Bulletin A310-53-2011 has been done in service.

(1) For the airplane having manufacturer's serial number (MSN) 191: Prior to the accumulation of 24,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later; and thereafter at intervals not to exceed 6,000 flight cycles.

(2) For airplanes other than the airplane identified in paragraph (i)(1) of this AD: Prior to the accumulation of 12,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later; and thereafter at intervals not to exceed 6,000 flight cycles.

Actions for Service Bulletin A310-53-2059—No Changes

(j) For airplanes listed in Airbus Service Bulletin A310-53-2059, Revision 1, dated January 4, 1996: Perform a visual inspection to detect cracks in the lower milled side panel at the lap joint with the upper side panel at frame 47 and stringer 22, left- and right-hand sides, in accordance with Airbus Service Bulletin A310-53-2059, Revision 1, dated January 4, 1996. Perform the inspection at the time specified in paragraph (j)(1) or (j)(2) of this AD, as applicable. Except as provided by paragraph (m) of this AD, if any crack is found, prior to further flight, repair in accordance with Airbus Service Bulletin A310-53-2059, Revision 1, dated January 4, 1996. Thereafter, repeat the inspections at intervals not to exceed 9,000 flight cycles, or accomplish Airbus Modification 5997 (Airbus Service Bulletin A310-53-2058). Accomplishment of either the repair or Airbus Modification 5997 constitutes terminating action for the repetitive inspections required by this paragraph.

Note 4: Airplanes on which Airbus Modification 5997 has been done completely in production, or on which Airbus Service Bulletin A310-53-2058 has been done in service, are not affected by the actions in paragraph (j) of this AD.

(1) For Model A310-200 series airplanes, accomplish the inspection at the time specified in paragraph (j)(1)(i) or (j)(1)(ii) of this AD, as applicable.

(i) For airplanes that have accumulated less than 20,000 total flight cycles as of January 20, 1999: Prior to the accumulation of 18,000 total flight cycles, or within 2,000 flight cycles after January 20, 1999, whichever occurs later.

(ii) For airplanes that have accumulated 20,000 or more total flight cycles as of January 20, 1999: Within 1,000 flight cycles after January 20, 1999.

(2) For Model A310-300 series airplanes, accomplish the inspection at the time specified in paragraph (j)(2)(i) or (j)(2)(ii) of this AD, as applicable.

(i) For airplanes that have accumulated less than 19,700 total flight cycles as of January 20, 1999: Prior to the accumulation of 18,000 total flight cycles, or within 1,700 flight cycles after January 20, 1999, whichever occurs later.

(ii) For airplanes that have accumulated 19,700 or more total flight cycles as of January 20, 1999: Within 850 flight cycles after January 20, 1999.

Actions for Service Bulletin A310-55-2002—No Changes

(k) For airplanes listed in Airbus Service Bulletin A310-55-2002, Revision 4, dated April 28, 1989: Prior to the accumulation of 12,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later, perform an eddy current inspection to detect cracks on the upper integral part adjacent to the rear attach fittings on the horizontal stabilizer, and modify the horizontal stabilizer, in accordance with Airbus Service Bulletin A310-55-2002, Revision 4, dated April 28, 1989. Except as provided by paragraph (m) of this AD, if any discrepancy is found, prior to further flight, perform follow-on corrective actions, as applicable, in accordance with Airbus Service Bulletin A310-55-2002, Revision 4, dated April 28, 1989.

Actions for Service Bulletin A310-57-2039—No Changes

(l) For airplanes listed in Airbus Service Bulletin A310-57-2039, dated September 24, 1990: Perform either an eddy current or visual inspection to detect cracks on the left and right vertical posts, numbers 1 through 5 inclusive, in the wing center box at frame 40/41, in accordance with Airbus

Service Bulletin A310-57-2039, dated September 24, 1990. Perform the inspection at the time specified in paragraph (l)(1) or (l)(2) of this AD, as applicable. Except as provided by paragraph (m) of this AD, if any crack is found, prior to further flight, accomplish the modification specified in Airbus Service Bulletin A310-57-2041, dated September 24, 1990, in accordance with Airbus Service Bulletin A310-57-2039, dated September 24, 1990.

Note 5: Airplanes on which Airbus Modification 04977 has been done in production are not affected by the actions specified in paragraph (l) of this AD.

(1) For airplanes on which Airbus Modification 7541/S7973 (reference Airbus Service Bulletin A310-57-2041) has not been accomplished: Inspect prior to the accumulation of 21,000 total flight cycles, or within 1,000 flight cycles after January 20, 1999, whichever occurs later; and thereafter at intervals not to exceed 4,200 flight cycles (for a visual inspection), or 7,500 flight cycles (for an eddy current inspection).

(2) For airplanes on which Airbus Modification 7541/S7973 (reference Airbus Service Bulletin A310-57-2041) has been accomplished: Inspect at the time specified in the graph contained in Note 1 of paragraph 1.A.(2) of Airbus Service Bulletin A310-57-2039, dated September 24, 1990, or within 1,000 flight cycles after January 20, 1999, whichever occurs later; and thereafter at intervals not to exceed 5,000 flight cycles (for a visual inspection), or 8,600 flight cycles (for an eddy current inspection).

Exception to Certain Service Bulletin Repairs

(m) If any crack is found during any inspection required by paragraph (g), (j), (k), or (l) of this AD, and the applicable service bulletin specifies to contact Airbus for an appropriate action: Prior to further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, or the DGAC (or its delegated agent), or European Aviation Safety Agency (EASA) (or its delegated agent).

New Requirements of This AD: Actions

Actions for Service Bulletin A310-55-2004

(n) For airplanes listed in Airbus Mandatory Service Bulletin A310-55-2004, Revision 05, dated October 13, 2006: At the applicable time specified in paragraph (n)(1) or (n)(2) of this AD, do a high frequency eddy current inspection for cracking of the doubler plate edge, the rear spar area, and specified fastener holes in the top skin chordwise splice along the contour of the steel doubler between ribs 3 and 4 on the left-and right-hand center and side boxes on the horizontal stabilizer, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-55-2004, Revision 05, dated October 13, 2006. If any cracking is found, before further flight, repair in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A310-55-2004, Revision 05, dated October 13, 2006; except where this service bulletin specifies to contact Airbus, before further flight, repair in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA, or EASA (or its delegated agent). Thereafter, repeat the inspections at intervals not to exceed 9,700 flight cycles or 19,500 flight hours, whichever occurs first; except as required by paragraph (o) of this AD for the rear spar area.

Note 6: Airplanes on which Airbus Modification 06070 has been done in production are not affected by the actions specified in paragraph (l) of this AD.

(1) For airplanes on which Airbus Service Bulletin A310-55-2002 was accomplished prior to the accumulation of 6,000 total flight cycles on the airplane; and for airplanes having MSN 311 through

400 inclusive on which Airbus Modification 4933 was accomplished during production: Do the inspection at the later of the compliance times specified in paragraphs (l)(1)(i) and (l)(1)(ii) of this AD.

(i) Prior to the accumulation of 14,400 total flight cycles or 28,500 total flight hours, whichever occurs first.

(ii) Within 1,500 flight cycles or 18 months after the effective date of this AD, whichever occurs first.

(2) For airplanes on which Airbus Service Bulletin A310-55-2002 was accomplished on or after the accumulation of 6,000 total flight cycles: Do the inspection at the later of the times specified in paragraph (l)(2)(i) and (l)(2)(ii) of this AD.

(i) Within 9,700 flight cycles or 19,500 flight hours after accomplishing the modification, whichever occurs first.

(ii) Within 1,500 flight cycles or 18 months after the effective date of this AD, whichever occurs first.

(o) For airplanes on which the initial inspection required by paragraph (n) of this AD has been done and on which a repair was installed at fastener position A in accordance with Airbus Service Bulletin A310-55-2002: At the later of the times specified in paragraphs (o)(1) and (o)(2) of this AD, do a high frequency eddy current inspection for cracking of the rear spar area as specified in paragraph (n) of this AD, and repeat the high frequency eddy current inspection of the rear spar area thereafter at intervals not to exceed 4,800 flight cycles or 9,700 flight hours, whichever occurs first.

(1) Within 4,800 flight cycles or 9,700 flight hours, whichever occurs first, after doing the repair in accordance with Airbus Service Bulletin A310-55-2002.

(2) Within 400 flight cycles or 800 flight hours, whichever occurs first, after the effective date of this AD.

Credit for Actions Accomplished in Accordance With Previous Service Information

(p) Actions accomplished before the effective date of this AD in accordance with Airbus Service Bulletin A310-55-2004, Revision 2, dated February 7, 1991; Revision 3, dated April 16, 1997; and Revision 04, dated April 17, 2001; are acceptable for compliance with the corresponding actions specified in paragraph (n) of this AD.

FAA AD Differences

Note 7: This AD differs from the MCAI and/or service information as follows: No Differences.

Other FAA AD Provisions

(q) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-Requests@faa.gov. Before using any approved AMOC, notify your principal inspector or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 98-26-01, amendment 39-10942, are approved as AMOCs for the corresponding provisions of this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(r) Refer to MCAI EASA Airworthiness Directive 2007-0053R3, dated December 17, 2009, and the service bulletins listed in Table 1 of this AD, for related information.

Table 1—Related Information

| Service Bulletin | Revision | Date |
|------------------------------------------------|-----------------|--------------------|
| Airbus Mandatory Service Bulletin A310-55-2004 | 05 | October 13, 2006 |
| Airbus Service Bulletin A310-53-2016 | 5 | December 7, 1992 |
| Airbus Service Bulletin A310-53-2019 | 3 | February 28, 1991 |
| Airbus Service Bulletin A310-53-2054 | 2 | May 22, 1990 |
| Airbus Service Bulletin A310-53-2057 | 1 | April 30, 1992 |
| Airbus Service Bulletin A310-53-2059 | 1 | January 4, 1996 |
| Airbus Service Bulletin A310-55-2002 | 4 | April 28, 1989 |
| Airbus Service Bulletin A310-57-2039 | Original | September 24, 1990 |
| Airbus Service Bulletin A310-57-2041 | Original | September 24, 1990 |

Material Incorporated by Reference

(s) You must use the applicable service bulletins contained in Table 2 of this AD, to do the actions required by this AD, unless the AD specifies otherwise.

Table 2—All Material Incorporated by Reference

| Service Bulletin | Revision | Date |
|------------------------------------------------|-----------------|--------------------|
| Airbus Mandatory Service Bulletin A310-55-2004 | 05 | October 13, 2006 |
| Airbus Service Bulletin A310-53-2016 | 5 | December 7, 1992 |
| Airbus Service Bulletin A310-53-2019 | 3 | February 28, 1991 |
| Airbus Service Bulletin A310-53-2054 | 2 | May 22, 1990 |
| Airbus Service Bulletin A310-53-2057 | 1 | April 30, 1992 |
| Airbus Service Bulletin A310-53-2059 | 1 | January 4, 1996 |
| Airbus Service Bulletin A310-55-2002 | 4 | April 28, 1989 |
| Airbus Service Bulletin A310-57-2039 | Original | September 24, 1990 |
| Airbus Service Bulletin A310-57-2041 | Original | September 24, 1990 |

Note 8: Only pages 1 and 6 of Airbus Service Bulletin A310-53-2019, Revision 3, dated February 28, 1991, show revision level 3 and issue date February 28, 1991. All other pages of this document show the original issue date of February 8, 1985.

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in Table 3 of this AD under 5 U.S.C. 552(a) and 1 CFR part 51.

Table 3—New Material Incorporated by Reference

| Service Bulletin | Revision | Date |
|-----------------------------------------------------------------------|-----------------|--------------------|
| Airbus Mandatory Service Bulletin A310-55-2004, excluding Appendix 01 | 05 | October 13, 2006 |
| Airbus Service Bulletin A310-53-2019 | 3 | February 28, 1991 |
| Airbus Service Bulletin A310-57-2041 | Original | September 24, 1990 |

Note 9: Only pages 1 and 6 of Airbus Service Bulletin A310-53-2019, Revision 3, dated February 28, 1991, show revision level 3 and issue date February 28, 1991. All other pages of this document show the original issue date of February 8, 1985.

(2) The Director of the Federal Register previously approved the incorporation by reference of the service information contained in Table 4 of this AD on January 20, 1999 (63 FR 69179, December 16, 1998).

Table 4—Material Previously Incorporated by Reference

| Service Bulletin | Revision | Date |
|--------------------------------------|-----------------|--------------------|
| Airbus Service Bulletin A310-53-2016 | 5 | December 7, 1992 |
| Airbus Service Bulletin A310-53-2054 | 2 | May 22, 1990 |
| Airbus Service Bulletin A310-53-2057 | 1 | April 30, 1992 |
| Airbus Service Bulletin A310-53-2059 | 1 | January 4, 1996 |
| Airbus Service Bulletin A310-55-2002 | 4 | April 28, 1989 |
| Airbus Service Bulletin A310-57-2039 | Original | September 24, 1990 |

(3) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 22, 2011.
Ali Bahrami,
Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-10 Airbus: Amendment 39-16691. Docket No. FAA-2011-0037; Directorate Identifier 2010-NM-273-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 15, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Airbus Model A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes, certificated in any category, all certified models, all serial numbers, except airplanes on which Airbus Mandatory Service Bulletin A300-24-6102 (Airbus Modification 13381) has been embodied.

Subject

(d) Air Transport Association (ATA) of America Code 24: Electrical Power.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

[T]he FAA has published SFAR 88 (Special Federal Aviation Regulation 88).

In their letters referenced 04/00/02/07/01-L296, dated March 4th, 2002, and 04/00/02/07/03-L024, dated February 3rd, 2003, the JAA [Joint Aviation Authorities] recommended the application of a similar regulation to the National Aviation Authorities (NAA).

Under this regulation, all holders of type certificates for passenger transport aircraft * * * are required to conduct a design review against explosion risks.

During improvement of the protection of fuel pump wiring against short-circuit by accomplishment of Airbus Service Bulletin (SB) A300-24-6094, a study led by the manufacturer concluded that the harness, installed through the wing panel needed to be protected to prevent possible damage in case of chafing which could potentially lead to short-circuit [and intermittent function or loss of the inner tank fuel pump. Loss of both inner tank fuel pumps could result in inability to use the remaining fuel supply in the inner tank. A short-circuit could also result in an ignition source in a flammable leakage zone].

* * * * *

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) Within 30 months after the effective date of this AD, install Teflon bushes in the hydraulic reservoir panel at the lower left-hand side in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A300-24-6102, Revision 01, dated September 24, 2010.

Credit for Actions Accomplished in Accordance With Previous Service Information

(h) Actions done before the effective date of this AD in accordance with Airbus Mandatory Service Bulletin A300-24-6102, dated August 13, 2009, are acceptable for compliance with the corresponding requirements of this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(i) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to Attn: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(j) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2010-0225, dated November 5, 2010; and Airbus Mandatory Service Bulletin A300-24-6102, Revision 01, dated September 24, 2010; for related information.

Material Incorporated by Reference

(k) You must use Airbus Mandatory Service Bulletin A300-24-6102, Revision 01, dated September 24, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS-EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 26, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-14 Dassault Aviation: Amendment 39-16695. Docket No. FAA-2011-0042; Directorate Identifier 2010-NM-267-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective June 17, 2011.

Affected ADs

- (b) This AD supersedes AD 2010-24-08, Amendment 39-16527.

Applicability

- (c) This AD applies to DASSAULT AVIATION Model MYSTERE-FALCON 50 airplanes, certificated in any category, all serial numbers.

Subject

- (d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

On two occurrences on Mystère-Falcon 50 aeroplanes in service, it was detected that two pipes of the emergency brake system 2 located near the nose landing gear bearing were swapped.

The swapping of these two pipes implies that when the Left Hand (LH) brake pedal is depressed, the Right Hand (RH) brake unit is activated, and conversely, when the RH brake pedal is depressed, the LH brake unit is actuated. This constitutes an unsafe condition, which may go unnoticed as the condition is latent until the emergency brake system 2 is used. This condition, if not corrected, could ultimately lead to a runway excursion of the aeroplane.

* * * * *

Compliance

- (f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2010-24-08

Actions

(g) Within 7 days after December 9, 2010 (the effective date of AD 2010-24-08), do a general visual inspection for correct installation (as defined in Dassault Service Bulletin F50-515, dated October 12, 2010) of the emergency brake system number 2, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F50-515, dated October 12, 2010, except that work required by this AD can only be done by persons prescribed in 14 CFR 43.3 and 43.7.

(h) If the emergency brake system number 2 is found installed incorrectly during the inspection required by paragraph (g) of this AD: Before further flight, install the emergency brake system number 2 correctly, in accordance with the Accomplishment Instructions of Dassault Service Bulletin F50-515, dated October 12, 2010.

New Requirements of This AD

(i) Within 7 months after the effective date of this AD, paint the pipe ends of the emergency brake system 2 and related unions, in accordance with paragraph 2.C. of the Accomplishment Instructions of Dassault Service Bulletin F50-515, dated October 12, 2010.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows:

(1) European Aviation Safety Agency (EASA) AD 2010-0208-E, dated October 12, 2010, has a compliance time of "before the next flight after the effective date of this AD." This AD requires that the actions be done within 7 days after the effective date of AD 2010-24-08.

(2) EASA AD 2010-0208-E, dated October 12, 2010, allows the flightcrew to inspect the emergency brake system number 2 specified in accordance with Dassault Service Bulletin F50-515, dated October 12, 2010. However, this AD requires the inspection to be performed by certificated maintenance personnel.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(k) Refer to MCAI EASA AD 2010-0208-E, dated October 12, 2010; and Dassault Service Bulletin F50-515, dated October 12, 2010; for related information.

Material Incorporated by Reference

(l) You must use Dassault Service Bulletin F50-515, dated October 12, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register previously approved the incorporation by reference of Dassault Service Bulletin F50-515, dated October 12, 2010, on December 9, 2010 (75 FR 71530, November 24, 2010).

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606; telephone 201-440-6700; Internet <http://www.dassaultfalcon.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 28, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-15 Airbus: Amendment 39-16696. Docket No. FAA-2011-0390; Directorate Identifier 2011-NM-064-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective May 31, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A318-112, A319-111, A319-112, A319-115, A319-132, A319-133, A320-214, A320-232, A320-233, A321-211, A321-213, and A321-231 airplanes, certificated in any category, manufacturer serial numbers (MSN) 3603, 3605, 3607, 3610, 3613, 3615 to 3619 inclusive, 3622 to 3627 inclusive, 3629, 3631 to 3634 inclusive, 3636, 3639, 3645, 3647, 3653, 3655, 3657, 3660, 3661, 3663, 3671, 3675, 3687, 3689, 3691, 3694, 3696, 3700, 3702, 3704 and 3705.

Subject

(d) Air Transport Association (ATA) of America Code 92: Electric and Electronic Common Installation.

Reason

(e) The mandatory continued airworthiness information (MCAI) states:

Electrical discontinuity has been detected on terminal modules Part Number (P/N) NSA 937901M1604, manufactured by Deutsch, due to an insufficient crimping of the female contacts on the shunt, caused by a wrong setting of the crimping tool.

* * * * *

This condition, if not corrected, could potentially result in in-flight failure of the Electrical Flight Control System (EFCS) and consequent loss of control of the aeroplane. In addition, this condition could lead to a non detected passenger oxygen loss, which, in case of emergency, could result in a large number of passenger oxygen masks not being supplied with oxygen, possibly causing personal injuries.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) Within 600 flight hours after the effective date of this AD, identify the manufacturing date code of each Deutsch module part number (P/N) NSA 937901M1604 installed on the airplane, which can be installed on electronics rack 103VU, pylon harnesses, S15/19 harnesses and/or electronics rack 80VU, as applicable. If any module with manufacturing date code 08-14 is installed on the electronics rack 103VU, pylon harnesses, or S15/19 harnesses; or if any module with manufacturing date code 08-14 or 08-18 is installed on the electronics rack 80VU; as applicable: Before further flight, replace each affected module with a serviceable part having the same part number but a different date code, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-92A1072, dated March 13, 2009.

Parts Installation

(h) As of the effective date of this AD, no person may install, on any airplane, a Deutsch module P/N NSA 937901M1604 with a manufacturing date code of 08-14 or 08-18.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: The MCAI prohibits installation of the part identified in paragraph (h) of this AD after accomplishing the actions specified in paragraph (g) of this AD, but this AD prohibits installation of the part as of the effective date of this AD.

Other FAA AD Provisions

(i) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically refer to this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(j) Refer to MCAI EASA Airworthiness Directive 2011-0054, dated March 24, 2011; and Airbus Service Bulletin A320-92A1072, dated March 13, 2009; for related information.

Material Incorporated by Reference

(k) You must use Airbus Service Bulletin A320-92A1072, excluding Appendix 01, dated March 13, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office–EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 28, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-10-17 Airbus: Amendment 39-16698. Docket No. FAA-2011-0030; Directorate Identifier 2009-NM-183-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 17, 2011.

Affected ADs

(b) This AD supersedes AD 2007-04-11, Amendment 39-14943; AD 2007-20-03, Amendment 39-15213; and AD 2007-25-02, Amendment 39-15283.

Applicability

(c) This AD applies to all Airbus model airplanes identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Model A300 B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, and B4-203 airplanes.

(2) Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(3) Models A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, and F4-622R airplanes, and Model A300 C4-605R Variant F airplanes.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (t)(1) of this AD. The request should include a description of changes to the required inspections that will ensure the continued damage tolerance of the affected structure. The FAA has provided guidance for this determination in Advisory Circular (AC) 25-1529-1.

Subject

(d) Air Transport Association (ATA) of America Codes 52: Doors; 53: Fuselage; 54: Nacelles/pylons; 55: Stabilizers; 57: Wings; and 71: Powerplant (for Model A300-600 only).

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

The airworthiness limitations applicable to the Damage Tolerant Airworthiness Limitation Items (DT ALI) are currently listed in Airbus ALI Documents, which are referenced in the A300, A310, and A300-600 Airworthiness Limitations Section (ALS) Part 2. Airbus has recently revised the ALI Documents, which have been approved by the European Aviation Safety Agency (EASA).

* * * * *

The actions contained in these revised documents, which introduce more restrictive maintenance requirements and/or airworthiness limitations, have been identified as mandatory actions for continued airworthiness. * * *

The unsafe condition is fatigue cracking, damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Certain Requirements of AD 2007-04-11

(g) Within one year after August 9, 1996 (the effective date of AD 96-13-11), replace the revision of the maintenance program with the inspections, inspection intervals, repairs, and replacements defined in Airbus Industrie A300 Supplemental Structural Inspection Document, Revision 2, dated June 1994. Accomplish the actions specified in the service bulletins identified in Section 6, "SB Reference List," in Airbus Industrie A300 Supplemental Structural Inspection Document, Revision 2, dated June 1994, at the times specified in those service bulletins. The actions are to be accomplished in accordance with those service bulletins. Accomplishing the initial ALI tasks required by paragraph (s) of this AD terminates the actions required by this paragraph.

(1) For airplanes that have exceeded the threshold specified in any of the service bulletins identified in Section 6, "SB Reference List," in Airbus Industrie A300 Supplemental Structural Inspection Document, Revision 2, dated June 1994: Accomplish the actions specified in those service bulletins within the grace period specified in those service bulletins. The grace period is to be measured from August 9, 1996.

(2) For airplanes that have exceeded the threshold specified in any of the service bulletins identified in Section 6, "SB Reference List," in Airbus Industrie A300 Supplemental Structural Inspection Document, Revision 2, dated June 1994, and a grace period is not specified in that service bulletin: Accomplish the actions specified in that service bulletin within 1,500 flight cycles after August 9, 1996.

Revision of the Maintenance Inspection Program

(h) For airplanes identified in paragraph (c)(1) of this AD: Within 12 months after April 3, 2007 (the effective date of AD 2007-04-11), replace the revision of the maintenance program required by paragraph (g) of this AD with the supplemental structural inspections, inspection intervals, and repairs defined in Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, as revised by Airbus A300 Temporary Revision (TR) 3.1, dated April 2006. Accomplish the actions specified in Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, as revised by Airbus A300 TR 3.1, dated April 2006, at the times specified in that ALI, except as provided by paragraph (i) of this AD. The actions must be accomplished in accordance with Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, as revised by Airbus A300 TR 3.1, dated April 2006. Accomplishing the initial ALI tasks required by paragraph (s) of this AD terminates the actions required by this paragraph.

(i) For airplanes identified in paragraph (c)(1) of this AD that have exceeded the threshold or intervals specified in the Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, for the application tolerance on the first interval for new and revised requirements and have exceeded 50 percent of the intervals specified in sections

D and E of Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005: Do the actions within 6 months after April 3, 2007.

Corrective Actions

(j) Damaged, cracked, or corroded structure detected during any inspection done in accordance with the Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, must be repaired, before further flight, in accordance with Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, as revised by Airbus A300 TR 3.1, dated April 2006, except as provided by paragraph (k) of this AD; or other data meeting the certification basis of the airplane which is approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or by the European Aviation Safety Agency (EASA) (or its delegated agent).

(k) Where the Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, specifies contacting Airbus for appropriate action: Before further flight, repair the damaged, cracked, or corroded structure using a method approved by either the Manager, International Branch, ANM-116; or the EASA (or its delegated agent).

No Fleet Sampling

(l) Although Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, specifies to do a "Sampling Concept" in section B, this AD prohibits the use of such a sampling program and requires all affected airplanes of the fleet to be inspected.

No Reporting

(m) Although Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Restatement of Requirements of AD 2007-20-03

Actions and Compliance

(n) For airplanes identified in paragraph (c)(3) of this AD: Within 3 months after October 31, 2007 (the effective date AD 2007-20-03), revise the ALS of the Instructions for Continued Airworthiness to incorporate Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006. The tolerance (grace period) for compliance (specified in paragraph 2 of Section B—Program Rules) with Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006, is within 2,000 flight cycles after October 31, 2007, provided that none of the following is exceeded. Accomplishing the initial ALI tasks required by paragraph (s) of this AD terminates the actions required by this paragraph.

(1) Thresholds or intervals in the operator's current approved maintenance schedule that are taken from a previous ALI issue, if existing, and are higher than or equal to those given in Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006.

(2) 8 months after October 31, 2007.

(3) 50 percent of the intervals given in Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006.

(4) Any application tolerance given in the task description of Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006.

Restatement of Requirements of AD 2007-25-02

Revision of the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness (ICA)

(o) For airplanes identified in paragraph (c)(2) of this AD: Within 3 months after January 14, 2008 (the effective date of AD 2007-25-02), do the actions specified in paragraphs (o)(1) and (o)(2) of this AD. Accomplishing the initial ALI tasks required by paragraph (s) of this AD terminates the actions required by this paragraph.

(1) Revise the ALS of the ICA to incorporate the structural inspections and inspection intervals defined in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006 (approved by the EASA on May 31, 2006). Accomplish the actions specified in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, at the times specified in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, except as provided by paragraph (p) of this AD. Thereafter, except as provided by paragraphs (o)(2) and (t)(1) of this AD, no alternative structural inspection intervals may be approved. The actions specified in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, must be accomplished in accordance with Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006.

(2) Revise the ALS of the ICA to incorporate the new and revised structural inspections and inspection intervals defined in Airbus Temporary Revision (TR) 6.1, dated November 2006 (approved by the EASA on December 12, 2006), to Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006. Thereafter, except as provided by paragraph (t)(1) of this AD, no alternative structural inspection intervals may be approved.

Exception to Issue 6 of the ALI

(p) The tolerance (grace period) for compliance with Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, is within 1,500 flight cycles after January 14, 2008, provided that none of the following is exceeded.

(1) Thresholds or intervals in the operator's current approved maintenance schedule that are taken from a previous ALI issue, if existing, and are higher than or equal to those given in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006.

(2) 18 months after January 14, 2008.

(3) 50 percent of the intervals given in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006.

(4) Any application tolerance specified in Section D of Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006.

Corrective Actions

(q) Damaged, cracked, or corroded structure detected during any inspection done in accordance with Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, must be repaired, before further flight, in accordance with Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006; or in accordance with other data meeting the certification basis of the airplane that has been approved by either the Manager, International Branch, ANM-116, or the EASA (or its delegated agent). Where Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, specifies to contact Airbus for appropriate action: Before further flight, repair the

damaged, cracked, or corroded structure using a method approved by either the Manager, International Branch, ANM-116, or the EASA (or its delegated agent).

Reporting Requirement

(r) If any damage that exceeds the allowable limits specified in Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006, is detected during any inspection required by this AD: At the applicable time specified in paragraph (r)(1) or (r)(2) of this AD, submit a report of the finding to Airbus, Customer Service Directorate, Attn: Department Manager Maintenance Engineering, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; e-mail: sched.maint@airbus.com. The report must include the ALI task reference, airplane serial number, the number of flight cycles and flight hours on the airplane, identification of the affected structure, location and description of the finding including its size and orientation, and the circumstance of detection and inspection method used.

(1) If the inspection was done after January 14, 2008: Submit the report within 30 days after the inspection.

(2) If the inspection was accomplished prior to January 14, 2008: Submit the report within 30 days after January 14, 2008.

New Requirements of This AD

Revision of the ALS of the Instructions for ICA

(s) Within 3 months after the effective date of this AD: Revise the maintenance program to incorporate the structural inspections and inspection intervals defined in the applicable ALI document listed in Table 1 of this AD. Thereafter, except as provided by paragraph (t)(1) of this AD, no alternative structural inspections and inspection intervals may be approved. The actions must be accomplished in accordance with the applicable issue of the ALI. The initial ALI tasks must be done at the times specified in the applicable ALI document listed in Table 1 of this AD. Accomplishing the applicable initial ALI tasks constitutes terminating action for the requirements of paragraphs (g) through (r) of this AD for that airplane only.

Table 1–Airworthiness Limitations Items Document

| Model | Document | Issue | Date |
|--------------|------------------------------------------------------------------------------|--------------|-------------|
| A300 | Airbus A300 Airworthiness Limitation Items Document AI/SE-M2/95A.1308/07 | 4 | June 2008 |
| A310 | Airbus A310 Airworthiness Limitation Items Document AI/SE-M2/95A.1309/07 | 7 | June 2008 |
| A300-600 | Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.1310/07 | 12 | June 2008 |

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows:

Where the MCAI includes a compliance time of "from the effective date of this AD," we have determined that a compliance time of "within 3 months after the effective date of this AD" is appropriate. The manufacturer and EASA agree with this difference in compliance time.

Other FAA AD Provisions

(t) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 2007-04-11, Amendment 39-14943; AD 2007-20-03, Amendment 39-15213; and AD 2007-25-02, Amendment 39-15283; as applicable; are approved as AMOCs for the corresponding provisions of this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave., SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

Related Information

(u) Refer to MCAI EASA Airworthiness Directive 2009-0155, dated July 17, 2009; Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006; Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.1310/07, Issue 12, dated June 2008; Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, as revised by Airbus A300 Temporary Revision 3.1, dated April 2006; Airbus A300 Airworthiness Limitation Items Document AI/SE-M2/95A.1308/07, Issue 4, dated June 2008; Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006; Airbus Temporary Revision 6.1, dated November 2006; Airbus A310 Airworthiness Limitation Items Document, AI/SE-M2/95A.1309/07, Issue 7, dated June 2008; and Airbus Industrie A300 Structural Inspection Document, Revision 2, dated June 1994; for related information.

Material Incorporated by Reference

(v) You must use the service information contained in Table 2 of this AD to do the actions required by this AD, as applicable, unless the AD specifies otherwise.

Table 2—All Material Incorporated by Reference

| Document | Issue/ Revision | Date |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|----------------|
| Airbus A300 Airworthiness Limitation Items Document AI/SE-M2/95A.1308/07 | 4 | June 2008 |
| Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, as revised by Airbus A300 TR 3.1, dated April 2006 | 3 | September 2005 |
| Airbus A300 Airworthiness Limitation Items, Document SEM2/95A.1090/05, Temporary Revision 3.1, including attachment, dated April 2006, and including attachments dated September 2005 | Original | April 2006 |
| Airbus Temporary Revision 6.1, including pages 1 and 2 of Section D and page 1 of Section E, dated November 2006, to Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006 | Original | November 2006 |
| Airbus A310 Airworthiness Limitation Items Document AI/SE-M2/95A.1309/07 | 7 | June 2008 |
| Airbus A310 Airworthiness Limitations Items Document AI/SE-M2/95A.0263/06 | 6 | April 2006 |
| Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.1310/07 | 12 | June 2008 |
| Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06 | 11 | April 2006 |
| Airbus Industrie A300 Structural Inspection Document | 2 | June 1994 |

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in Table 3 of this AD under 5 U.S.C. 552(a) and 1 CFR part 51.

Table 3—New Material Incorporated by Reference

| Document | Issue | Date |
|------------------------------------------------------------------------------|--------------|-------------|
| Airbus A300 Airworthiness Limitation Items Document AI/SE-M2/95A.1308/07 | 4 | June 2008 |
| Airbus A310 Airworthiness Limitation Items Document AI/SE-M2/95A.1309/07 | 7 | June 2008 |
| Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.1310/07 | 12 | June 2008 |

(2) The Director of the Federal Register previously approved the incorporation by reference of Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006; and Airbus Temporary Revision 6.1, including pages 1 and 2 of Section D and page 1 of Section E, dated November 2006, to Airbus A310 Airworthiness Limitations Items Document, AI/SE-M2/95A.0263/06, Issue 6, dated April 2006; on January 14, 2008 (72 FR 69612, December 10, 2007).

(3) The Director of the Federal Register previously approved the incorporation by reference of Airbus A300-600 Airworthiness Limitation Items Document AI/SE-M2/95A.0502/06, Issue 11, dated April 2006, on October 31, 2007 (72 FR 54536, September 26, 2007).

(4) The Director of the Federal Register previously approved the incorporation by reference of Airbus A300 Airworthiness Limitations Items Document SEM2/95A.1090/05, Issue 3, dated September 2005, as revised by Airbus A300 Airworthiness Limitation Items Document SEM2/95A.1090/05, Temporary Revision 3.1, including attachment, dated April 2006, and including attachments, dated September 2005, on April 3, 2007 (72 FR 8604, February 27, 2007).

(5) The Director of the Federal Register previously approved the incorporation by reference of Airbus Industrie A300 Supplemental Structural Inspection Document, Revision 2, dated June 1994, on August 9, 1996 (61 FR 35122, July 5, 1996).

(6) For service information identified in this AD, contact Airbus SAS-EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(7) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(8) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on May 2, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2011-11-02 Bombardier, Inc.: Amendment 39-16700. Docket No. FAA-2011-0043; Directorate Identifier 2010-NM-192-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective June 22, 2011.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier, Inc. Model DHC-8-400, -401, and -402 airplanes, certificated in any category; having serial numbers 4001 through 4190 inclusive, 4199 through 4201 inclusive, and 4203 through 4216 inclusive; equipped with a motive flow check valve (MFCV) having part number (P/N) 2960018-101.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

During production quality inspections of the aeroplane fuel motive flow system, it was discovered that some motive flow check valves (MFCV) were manufactured with an outlet fitting containing red anodized threads. These MFCV do not provide adequate electrical bonding between the valve and the adjacent fitting.

In the absence of proper electrical bonding within the motive flow system, the aeroplane fuel tank could be exposed to ignition sources in the case of a lightning strike.

* * * * *

The unsafe condition is the potential for ignition sources inside the fuel tanks, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Actions

(g) Within 6,000 flight hours after the effective date of this AD, do a general visual inspection for red anodized threads of the outlet fitting of the MFCV having P/N 2960018-101 installed in the left and right wing fuel tanks, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-28-08, dated March 11, 2010. If the MFCV has a chemical film coating (gold color) outlet fitting, no further action is required by AD, except as required by paragraph (i) of this AD.

(h) If during the inspection required by paragraph (g) of this AD, a MFCV having a red anodized check valve outlet fitting is found: Before further flight, replace the MFCV with a MFCV that has a chemical film coating (gold color) check valve outlet fitting, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 84-28-08, dated March 11, 2010.

(i) As of the effective date of this AD, no person may install a replacement MFCV having P/N 2960018-101, with a red anodized check valve outlet fitting, on any airplane.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to Attn: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

Related Information

(k) Refer to Transport Canada Civil Aviation Airworthiness Directive CF-2010-21, dated July 20, 2010; and Bombardier Service Bulletin 84-28-08, dated March 11, 2010; for related information.

Material Incorporated by Reference

(l) You must use Bombardier Service Bulletin 84-28-08, dated March 11, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; e-mail thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on May 6, 2011.

Kalene C. Yanamura,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.