

**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES**

LARGE AIRCRAFT

BIWEEKLY 2016-12

5/30/2016 - 6/12/2016



Federal Aviation Administration
Continued Operational Safety Policy Section, AIR-141
P.O. Box 25082
Oklahoma City, OK 73125-0460

CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents
Government Printing Office
Mail List Branch SSOM
Washington, DC 20402

Telephone: (202) 512-1806
Facsimile: (202) 512-2250

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2016-01			
2015-25-03	COR	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series airplanes
2015-25-06	R 2010-06-04	Airbus	A300 B2-1C, B2-203, B2K-3C, B4-103, B4-203, and B4-2C; A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-605R, B4-620, B-622, and B4-622R airplanes
2015-26-02		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2015-26-03	R 2011-07-10	Bombardier, Inc.	BD-100-1A10 (Challenger 300) airplanes
2015-26-07		The Boeing Company	767-200, -300, -300F series airplanes
Biweekly 2016-02			
2015-25-10	R 2011-24-05	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, and -313
2015-26-05		Fokker Services B.V.	F.28 Mark 1000, 2000, 3000, and 4000
2015-26-06	R 2004-14-09	Airbus	A320-211, -212, and -231
2015-26-09		ATR-GIE Avions de Transport Régional (ATR)	ATR42-200, -300, -320, and -500
2015-27-01		General Electric Company (GE)	GE90-76B, -77B, -85B, -90B, and -94B
2016-01-02		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2016-01-03		Airbus	A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343; A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313
2016-01-04	R 2005-01-09	The Boeing Company	747-100, -100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, and 747SR series
2016-01-05		The Boeing Company	737-400 series
2016-01-07		Airbus	A319-113 and A319-114; A320-211 and A320-212
2016-01-08	R 2013-13-04	Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-01-09		Bombardier, Inc.	DHC-8-400, -401, and -402
2016-01-11	R 98-18-26	Airbus	A320-211, -212, and -231
2016-01-12		Bombardier, Inc.	BD-700-1A10 and BD-700-1A11
2016-01-13		Airbus	A310-203, -204, -221, -222, -304, -322, -324, and -325; A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; and A300 F4-605R, F4-622R, and A300 C4-605R Variant F
2016-01-16	R 2002-23-20	Dassault Aviation	Mystere-Falcon 900
2016-01-17		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702)
Biweekly 2016-03			
2015-25-08	COR	The Boeing Company	777-200, -200LR, -300, -300ER, and 777F series airplanes
2015-28-01		Engine Alliance	GP7270 turbofan engines
2016-01-10	R 2004-20-14	Airbus	A300 airplanes
2016-01-18	R 98-20-27	Airbus	A300 airplanes
2016-02-01	R 96-18-06	Airbus	A320-211, -212, and -231 airplanes
2016-02-02		Airbus	A318-111 and -112; A319-111, -112, and -115; A320-214; A321-111, -112, -211, -212, and -213 airplanes
2016-02-03		Airbus	A319-113 and -114; A320-211 and -212 airplanes
2016-02-04		CFM International S.A.	CFM56-5B engines
2016-02-05		Bombardier, Inc.	BD-100-1A10 (Challenger 300) airplanes
2016-03-01		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series airplanes

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
Biweekly 2016-04			
2016-03-04		Rolls-Royce plc	(RR) RB211-535E4-37, RB211-535E4-B-37, and RB211-535E4-C-37 turbofan engines
2016-03-06	R 2012-18-05	The Boeing Company	DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC 9 34F, DC 9 32F (C-9A, C 9B), DC-9-41, DC-9-51, DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, MD-90-30 airplanes.
2016-04-01	R 2015-26-02	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
2016-04-02	R 2010-26-10	The Boeing Company	747-200C, -200F, -400, -400D, and -400F series airplanes
2016-04-03		The Boeing Company	747-400F series airplanes
Biweekly 2016-05			
2016-04-06		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2016-04-07		The Boeing Company	767-200, -300, -300F, and -400ER series
2016-04-08		The Boeing Company	787-8
2016-04-09		Dassault Aviation	FALCON 900EX and FALCON 2000EX
2016-04-10		ATR-GIE Avions de Transport Régional	ATR42-500 and ATR72-102, -202, -212, and -212A
2016-04-11		General Electric Company	GEEx-1B54, -1B58, -1B64, -1B67, and -1B70
2016-04-17		The Boeing Company	777-200 series
2016-04-18		The Boeing Company	747-100, -200B, -200C, -200F, -300, -400, -400D, and -400F series
2016-04-19		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295
2016-04-20		The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series; 757-200, -200PF, -200CB, and -300 series; 767-200, -300, -300F, and -400ER series; 777-200, -200LR, -300, -300ER, and -777F series
2016-04-21	R 2008-26-07	The Boeing Company	DC-8-11, DC-8-12, DC-8-21, DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, DC-8-43, DC-8-51, DC-8-52, DC-8-53, DC-8-55, DC-8F-54, DC-8F-55, DC-8-61, DC-8-62, DC-8-63, DC-8-61F, DC-8-62F, DC-8-63F, DC-8-71, DC-8-72, DC-8-73, DC-8-71F, DC-8-72F, and DC-8-73F
2016-04-22		Fokker Services B.V.	F.27 Mark 200, 300, 400, 500, 600, and 700
2016-04-23		The Boeing Company	787-8
2016-04-24		The Boeing Company	757-200 series
Biweekly 2016-06			
2016-03-03	S 2013-11-13	Rolls-Royce plc	Viper Mk. 521, Viper Mk. 522, and Viper Mk. 601-22 turbojet engines
2016-03-07		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-04-13	S 2015-04-03	Rolls-Royce plc	RB211 Trent 768-60, 772-60, and 772B-60 turbofan engines
2016-04-16	R 2013-08-23	The Boeing Company	DC-10-10, DC-10-10F, DC-10-15, DC-10-30, DC-10-30F (KC-10A and KDC-10), DC-10-40, DC-10-40F, MD-10-10F, MD-10-30F, MD-11, and MD-11F
2016-05-02	R 2011-13-11 & R 2013-16-09	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-05-04		Dowty Propellers	R352/6-123-F/1, R352/6-123-F/2, and R410/6-123-F/35
2016-05-05		Airbus	A300 B2-1A, B2-1C, B2K-3C, B2-203, B4-2C, B4-103, and B4-203, A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-05-07		Engine Alliance	GP7270 turbofan engine
2016-05-12	R 2012-15-13	The Boeing Company	747-100B SUD, 747-300, 747-400, and 747-400D series, 747-200B series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-06-02		The Boeing Company	737-300, -400, and -500 series
2016-06-03		Airbus	A319-131, -132, and -133, A320-232 and -233, A321-131, -231, and -232
2016-06-04		The Boeing Company	737-300, -400, and -500 series
2016-06-05		The Boeing Company	777-200, -200LR, -300, -300ER, and -777F series
2016-06-06		Quest Aircraft Design, LLC	KODIAK 100
2016-06-07	R 2006-22-15	The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series
2016-06-08		The Boeing Company	787-8 and 787-9
Biweekly 2016-07			
2016-06-10		The Boeing Company	787-8
2016-06-11		Airbus Defense and Space S.A.	CN-235, CN-235-100, CN-235-200, and CN-235-300
2016-06-12		Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-06-13		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-07-03		The Boeing Company	747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747SR, and 747SP series
2016-07-05		The Boeing Company	747-8 series
2016-07-06		BAE Systems (Operations) Limited	BAe 146-100A, -200A, and -300A; Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2016-07-10		The Boeing Company	787-8 and 787-9
Biweekly 2016-08			
2016-06-14		General Electric Company	CF6-80E1
2016-07-02		Honeywell International Inc.	TFE731-4, -4R, -5AR, -5BR, and -5R
2016-07-04		Airbus	A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-07-07		The Boeing Company	757-200, -200PF, -200CB, and -300 series
2016-07-08		The Boeing Company	DC-9-83 (MD-83)
2016-07-09	R 2011-21-06	BAE SYSTEMS (Operations) Limited	4101
2016-07-12		Airbus	A318-111 and -112, A319-111, -112, -113, -114, and -115; A320-211, -212, and -214; A321-111, -112, -211, -212, and -213
2016-07-14		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-211, -212, -214, -231, -232, and -233; A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-07-15		Dassault Aviation	FALCON 7X
2016-07-16	R 2013-26-08	The Boeing Company	737-600, -700, -700C, -800, -900, and -900ER series
2016-07-17	R 97-20-07	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2016-07-18		Airbus Defense and Space S.A.	CN-235-200 and CN-235-300
2016-07-20	R 95-18-08	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2016-07-22		Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F; A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-07-25		The Boeing Company	787-8
2016-07-28		The Boeing Company	DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87); and MD-88
2016-07-30		Airbus	A330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642
2016-07-31	R 2013-22-11	The Boeing Company	747-400 and -400D series

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-08-03		The Boeing Company	777-200, -200LR, -300, and -300ER series
2016-08-04		Airbus	A330-223F and -243F
2016-08-05		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702); CL-600-2D15 (Regional Jet Series 705) and CL-600-2D24 (Regional Jet Series 900); CL-600-2E25 (Regional Jet Series 1000)
2016-08-06		Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R and F4-622R; A300 C4-605R Variant F
2016-08-07		Rolls-Royce plc	RB211-22B-02, RB211-22B (MOD 72-8700), RB211-524B-02, RB211-524B-B-02, RB211-524B2-19, RB211-524B2-B-19, RB211-524B3-02, RB211-524B4-02, RB211-524B4-D-02, RB211-524C2-19, RB211-524C2-B-19, RB211-524D4-19, RB211-524D4-B-19, RB211-524D4X-19, RB211-524D4X-B-19, RB211-524D4-39, RB211-524D4-B-39, RB211-524G2-19, RB211-524G3-19, RB211-524G2-T-19, RB211-524G3-T-19, RB211-524H-36, RB211-524H2-19, RB211-524H-T-36, and RB211-524H2-T-19
Biweekly 2016-09			
2016-08-01		Dassault Aviation	FALCON 7X airplanes
2016-08-09		Pratt & Whitney Division	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4060C, PW4062, PW4062A, PW4152, PW4156, PW4156A, PW4158, PW4160, PW4460, PW4462, and PW4650 turbofan engines
2016-08-10		General Electric Company	CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B1F1, CF6-80C2B1F2, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B3F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6-80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, CF6-80C2D1F, CF6-80C2L1F, CF6-80C2K1F, CF6-80E1A1, CF6-80E1A2, CF6-80E1A3, CF6-80E1A4, and CF6-80E1A4/B turbofan engines
2016-08-11	R 2012-17-13	The Boeing Company	707 airplanes; 720 and 720B series airplanes
2016-08-12		The Boeing Company	787-8 and 787-9 airplanes
2016-08-14	R 2014-03-14	Airbus	A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-211, -212, -213, -311, -312, -313, -541, and -642 airplanes
Biweekly 2016-10			
2016-07-23		Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232 airplanes
2016-08-02		Airbus	A320-214, -232, and -233, A321-211 and -231 airplanes
2016-08-13	R 2004-19-11	Airbus	A320-211, -212, -214, -231, -232, and -233
2016-08-15	R 2014-17-51	Bombardier, Inc	CL-600-2B16
2016-09-01		The Boeing Company	777-200 and -300 series
2016-09-03		Dassault Aviation	FALCON 2000, FALCON 2000EX, MYSTERE-FALCON 900 and FALCON 900EX
2016-09-04		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2016-09-05		The Boeing Company	717-200 airplanes
2016-09-06		Airbus	A318-111 and -112, A319-111, -112, -113, -114, and -115, A320-211, -212, and -214, A321-111, -112, -211, -212, and -213
2016-09-07		Airbus	A319-111, -112, -113, -114, -115, -131, -132, and -133, A320-211, -212, -214, -231, -232, and -233, A321-111, -112, -131, -211, -212, -213, -231, and -232
2016-09-08		The Boeing Company	747-8 series airplanes
2016-09-10	R 2007-10-10 R1	Airbus	A300 B4-600, B4-600R, and F4-600R series, A300 C4-605R Variant F airplanes (collectively called A300-600 series airplanes)

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes, R - Replaces			
2016-09-11		Airbus	A330-201, -202, -203, -223, -223F, -243 -243F, -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213, -311, -312, and -313
2016-09-12		The Boeing Company	787-8 and 787-9 airplanes
2016-09-13		The Boeing Company	737-300, -400, and -500 series
2016-10-02		The Boeing Company	777-200 and -300 series
Biweekly 2016-11			
2016-10-04		The Boeing Company	737-100, -200, -200C, -300, -400, and -500 series
2016-10-05		The Boeing Company	757-200, -200CB, -200PF, and -300
2016-10-06		Bombardier, Inc.	BD-700-1A10, BD-700-1A11
2016-10-07		Bombardier, Inc.	DHC-8-102, -103, -106, -201, -202, -301, -311, and -315
2016-10-08		Airbus	A330-201, -202, -203, -223, and -243, A330-223F and -243F, A330-301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, and -213, A340-311, -312, and -313, A340-541, A340-642
2016-10-09		The Boeing Company	787-8 and 787-9
2016-10-10	R 2014-20-01	Bombardier, Inc.	CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604 Variants)
2016-10-11	R 2015-03-06	Airbus	A330-201, -202, -203, -223, -223F, -243, -243F -301, -302, -303, -321, -322, -323, -341, -342, and -343, A340-211, -212, -213 -311, -312, -313, -541, and -642
2016-10-12		Fokker Services B.V.	F.28 Mark 0070 and 0100
2016-10-13		Airbus	A300 B4-601, B4-603, B4-620, and B4-622, A300 B4-605R and B4-622R, A300 F4-605R and F4-622R, A300 C4-605R Variant F, A310-203, -204, -221, -222, -304, -322, -324, and -325
2016-10-14		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900)
2016-10-16		Dassault Aviation	MYSTERE-FALCON 900, FALCON 900EX, FALCON 2000EX
2016-11-02		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), CL-600-2E25 (Regional Jet Series 1000)
Biweekly 2016-12			
2016-10-15		Fokker Services B.V.	F.28 Mark 0070 and 0100
2016-11-01		Airbus	A330-201, -202, -203, -223, and -243; A330-223F and -243F; A330-301, -302, -303, -321, -322, -323, -341, -342, and -343; A340-541; and A340-642
2016-11-03		The Boeing Company	777-200, -200LR, -300, -300ER, and -777F series
2016-11-04	R 2011-23-05	The Boeing Company	737-300, -400, and -500 series
2016-11-05	R 99-16-01	Airbus	A300 B4-601, B4-603, B4-620, and B4-622; A300 B4-605R and B4-622R; A300 F4-605R; and A300 C4-605R Variant F
2016-11-06	R 2005-18-18	The Boeing Company	757-200, -200PF, -200CB, and -300 series
2016-11-07		The Boeing Company	777-200 and -300 series
2016-11-08	R 2001-12-18	Airbus Defense and Space S.A.	CN-235; CN-235-100 and -200
2016-11-15		Fokker Services B.V.	F28 Mark 0070 and 0100
2016-11-17		The Boeing Company	787-8
2016-11-18		The Boeing Company	787
2016-11-20		B/E Aerospace	Protective Breathing Equipment (PBE)
2016-11-22		Fokker Services B.V.	F.28 Mark 0070 and 0100
2016-12-03	R 2011-17-10	Fokker Services B.V.	F.28 Mark 1000



2016-10-15 Fokker Services B.V.: Amendment 39-18526. Docket No. FAA-2015-5810; Directorate Identifier 2014-NM-116-AD.

(a) Effective Date

This AD becomes effective July 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category, equipped with a center wing tank.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by a design review which revealed that a wiring failure, external to the center wing fuel tank, could cause a hot short circuit to a maximum level sensor wire, and result in excessive heating of the maximum level sensor element. We are issuing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Wiring Modification

Within 24 months after the effective date of this AD: Modify the wiring of the maximum level sensors of the center wing fuel tank, as specified in paragraph (g)(1) or (g)(2) of this AD, as applicable. Before further flight after accomplishing the modification, do all applicable tests and corrective actions, in accordance with Part 5 of the Accomplishment Instructions of the service information identified in paragraph (j) of this AD.

(1) For post-SBF100-28-073 configuration airplanes: Do the modification in accordance with Part 1 or Part 3, as applicable, of the Accomplishment Instructions of the service information identified in paragraph (j) of this AD.

(2) For pre-SBF100-28-073 configuration airplanes: Do the modification in accordance with Part 2 or Part 4, as applicable, of the Accomplishment Instructions of the service information identified in paragraph (j) of this AD.

(h) Revise the Maintenance or Inspection Program

Within 30 days after installing the modification specified in paragraph (g)(1) or (g)(2) of this AD, as applicable: Revise the airplane maintenance or inspection program, as applicable, to incorporate the fuel airworthiness limitation items and critical design configuration control limitations (CDCCLs) specified in paragraph 2.L.(1)(c) of Fokker Service Bulletin SBF100-28-078, dated January 23, 2014.

(i) No Alternative Actions, Intervals, and/or CDCCLs

After accomplishing the revision required by paragraph (h) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, or CDCCLs are approved as an alternative method of compliance in accordance with the procedures specified in paragraph (k)(1) of this AD.

(j) Required Service Information

Do the actions specified in this AD in accordance with Fokker Service Bulletin SBF100-28-078, dated January 23, 2014, and Fokker Manual Change Notification MCNM-F100-166, dated January 23, 2014, as applicable.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0138, dated May 30, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-5810.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100-28-078, dated January 23, 2014, including the attached required drawings specified in paragraphs (m)(2)(i)(A), (m)(2)(i)(B), and (m)(2)(i)(C) of this AD, as applicable.

(A) Drawing W41192, Sheet 052, Issue AW, "Retro-Fit Wiring Diagram, Tank Fueling/Defueling, Center Tank," undated;

(B) Drawing W41192, Sheet 054, Issue AW, "Retro-Fit Wiring Diagram, Tank Fueling/Defueling," undated; and

(C) Drawing W59520-405, "Cableloom Connection List," Sheet 3, Issue F, dated May 12, 2011.

(ii) Fokker Manual Change Notification MCNM-F100-166, dated January 23, 2014.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 12, 2016.

Suzanne Masterson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-01 Airbus: Amendment 39-18528. Docket No. FAA-2015-7533; Directorate Identifier 2015-NM-080-AD.

(a) Effective Date

This AD is effective July 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes specified in paragraphs (c)(1) through (c)(5) of this AD, certificated in any category, from manufacturer serial number (MSN) 0715 through MSN 1507 inclusive, and MSN 1509, except airplanes on which all engines have been removed and/or replaced since the date of the first flight of the airplane.

- (1) Airbus Model A330-201, -202, -203, -223, and -243 airplanes.
- (2) Airbus Model A330-223F and -243F airplanes.
- (3) Airbus Model A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.
- (4) Airbus Model A340-541 airplanes.
- (5) Airbus Model A340-642 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Reason

This AD was prompted by a report of an under-torqued forward engine mount bolt. We are issuing this AD to detect and correct improperly torqued engine mount bolts, which could lead to detachment of the engine from the airplane during flight, and consequent damage to the airplane and injury to persons on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definition of Affected Engine

For the purpose of this AD, an affected engine is an engine that has never been removed and/or replaced since first flight of the airplane.

(h) Action for Airbus Model A330 Airplanes Equipped With Pratt and Whitney (PW) Engines

(1) For Airbus Model A330-200, -200 Freighter, and -300 series airplanes equipped with PW engines: At the earlier of the times specified in paragraph (h)(1)(i) and (h)(1)(ii) of this AD, accomplish a one-time torque check of the forward (FWD) and rear (AFT) engine mount bolts on each affected engine, at the locations specified in, and in accordance with the instructions of Section 4.2.2, "Inspection Requirements," of Airbus Alert Operators Transmission (AOT) A71L004-14, Revision 01, dated April 7, 2014.

(i) Within 2,000 flight hours after the effective date of this AD.

(ii) During the accomplishment of actions specified in Airbus Service Bulletin A330-71-3028, if done after the effective date of this AD.

(2) If, during the torque check required by paragraph (h)(1) of this AD, only one FWD engine mount bolt is found that rotates: Do the actions specified in paragraph (h)(2)(i), (h)(2)(ii), (h)(2)(iii), or (h)(2)(iv) of this AD, as applicable.

(i) For Airbus Model A330-200 and -300 series airplanes with an average flight time of greater than 132 minutes and having accumulated less than 2,350 flight cycles and less than 24,320 flight hours since first flight of the airplane: Before further flight, re-torque the affected engine mount bolt, and, within 2,350 flight cycles or 24,320 flight hours since first flight of the airplane, whichever occurs first, replace the 4 engine mount bolts and associated nuts, in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(ii) For Airbus Model A330-200 and -300 series airplanes with an average flight time of 132 minutes or lower and having accumulated less than 1,950 flight cycles and less than 20,210 flight hours since first flight of the airplane: Before further flight, re-torque the affected engine mount bolt, and within 2,350 flight cycles or 24,320 flight hours since first flight of the airplane, whichever occurs first, replace the 4 engine mount bolts and associated nuts, in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(iii) For Airbus Model A330-200 Freighter series airplanes having accumulated less than 2,140 flight cycles and less than 6,600 flight hours since first flight of the airplane: Before further flight, re-torque the affected engine mount bolt and within 2,140 flight cycles or 6,600 flight hours since first flight of the airplane, whichever occurs first, replace the 4 engine mount bolts and associated nuts, in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(iv) For airplanes identified in paragraphs (h)(2)(iv)(A), (h)(2)(iv)(B), and (h)(2)(iv)(C) of this AD: Before further flight, replace the 4 engine mount bolts and associated nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(A) Airbus Model A330-200 and -300 series airplanes with an average flight time of greater than 132 minutes and having accumulated 2,350 flight cycles or more or 24,320 flight hours or more since first flight of the airplane.

(B) Airbus Model A330-200 and -300 series airplanes with an average flight time of 132 minutes or lower and having accumulated 1,950 flight cycles or more or 20,210 flight hours or more since first flight of the airplane.

(C) Airbus Model A330-200 Freighter series airplanes having accumulated 2,140 flight cycles or more or 6,600 flight hours or more since first flight of the airplane.

(3) If, during the torque check required by paragraph (h)(1) of this AD, two or more FWD engine mount bolts are found that rotate: Before further flight, replace the 4 engine mount bolts and associated nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(4) If, during the torque check required by paragraph (h)(1) of this AD, one or more FWD engine mount bolts are found fully broken: Before further flight, replace the 4 engine mount bolts and associated nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014, except as required by paragraph (m)(2) of this AD.

(5) If, during the torque check required by paragraph (h)(1) of this AD, only one AFT engine mount bolt is found that rotates: Before further flight, re-torque the affected engine mount bolt, and replace the 4 engine mount bolts and associated nuts at the next engine removal, in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(6) If, during the torque check required by paragraph (h)(1) of this AD, two or more AFT engine mount bolts are found that rotate: Before further flight, replace the 4 engine mount bolts and associated nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(7) If, during the torque check required by paragraph (h)(1) of this AD, one or more AFT engine mount bolts are found fully broken: Before further flight, replace the 4 engine mount bolts and associated nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L004-14, Revision 01, dated April 7, 2014, except as required by paragraph (m)(2) of this AD.

(i) Clarification of Concurrent Actions for Airbus Model A330-223F, A330-223, A330-321, A330-322, and A330-323 Airplanes Equipped With Pratt and Whitney (PW) Engines

AD 2013-14-04, Amendment 39-17509 (78 FR 68352, November 14, 2013), requires a torque check of FWD engine mount bolts using Airbus Service Bulletin A330-71-3028, Revision 01, dated February 20, 2012. If accomplishing the torque check of FWD engine mount bolts, as specified in Airbus Service Bulletin A330-71-3028, within the compliance times specified in paragraph (g) of AD 2013-14-04, perform the torque check of the AFT engine mount bolts at the same time as required by paragraph (h)(1) of this AD.

(j) Action for Airbus Model A330 Airplanes Equipped With General Electric (GE) Engines

(1) For Airbus Model A330-200, -200 Freighter, and -300 series airplanes equipped with GE engines: Within 2,000 flight hours after the effective date of this AD, accomplish a one-time torque check of the FWD and AFT engine mount bolts on each affected engine, at the locations specified in, and in accordance with the instructions of Section 4.2.2, "Inspection Requirements," of Airbus AOT A71L006-14, dated July 22, 2014.

(2) If, during the torque check required by paragraph (j)(1) of this AD, only one FWD engine mount bolt is found that rotates: Do the actions specified in paragraphs (j)(2)(i) and (j)(2)(ii) of this AD, as applicable.

(i) For airplanes that have accumulated less than 4,000 flight cycles and less than 30,800 flight hours since first flight of the airplane: Before further flight, re-torque affected FWD engine mount bolt(s), in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L006-14, dated July 22, 2014, and, within 4,000 flight cycles or 30,800 flight hours since first flight of the airplane, whichever is first, replace the 5 engine mount bolts, as applicable, and their associated nuts with new engine mount bolts and nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L006-14, dated July 22, 2014.

(ii) For airplanes that have accumulated 4,000 flight cycles or more or 30,800 flight hours or more since first flight of the airplane: Before further flight, replace the 5 FWD engine mount bolts, as applicable, and their associated nuts with new engine mount bolts and nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L006-14, dated July 22, 2014.

(3) If, during the torque check required by paragraph (j)(1) of this AD, two or more FWD engine mount bolts are found that rotate: Repair before further flight using a method approved in accordance with the procedures specified in paragraph (p)(1) of this AD.

(4) If, during the torque check required by paragraph (j)(1) of this AD, one or more FWD engine mount bolts are found fully broken: Repair before further flight using a method approved in accordance with the procedures specified in paragraph (p)(1) of this AD.

(5) If, during the torque check required by paragraph (j)(1) of this AD, only one AFT engine mount bolt is found that rotates: Before further flight, re-torque the affected AFT engine mount bolt(s) in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L006-14, dated July 22, 2014, and, at the next engine removal, replace the 4 engine mount bolts and associated nuts with new engine mount bolts and nuts in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L006-14, dated July 22, 2014.

(6) If, during the torque check required by paragraph (j)(1) of this AD, two or more AFT engine mount bolts are found that rotate: Repair before further flight using a method approved in accordance with the procedures specified in paragraph (p)(1) of this AD.

(7) If, during the torque check required by paragraph (j)(1) of this AD, one or more AFT engine mount bolts are found fully broken: Before further flight, do all applicable corrective actions in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L006-14, dated July 22, 2014, except as required by paragraph (m)(2) of this AD.

(k) Action for Airbus Model A330 Airplanes Equipped With Rolls-Royce (RR) Trent 700 Engines

(1) For Airbus Model A330-200, -200 Freighter, and -300 series airplanes equipped with RR Trent 700 Engines: Within 2,000 flight hours after the effective date of this AD, accomplish a one-time torque check of the FWD and AFT engine mount bolts on each affected engine, at the locations specified in, and in accordance with the instructions of Section 4.2.2, "Inspection Requirements," of Airbus AOT A71L005-14, Revision 01, dated December 11, 2014.

(2) If, during the torque check required by paragraph (k)(1) of this AD, any discrepancy is detected (one engine mount bolt rotates, two or more engine mount bolts rotate, or one or more engine mount bolts are fully broken): Within the compliance time specified in Airbus AOT A71L005-14, Revision 01, dated December 11, 2014, accomplish all applicable corrective actions in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L005-14, Revision 01, dated December 11, 2014, except as required by paragraphs (m)(1) and (m)(2) of this AD.

(l) Action for Airbus Model A340-541 and -642 Airplanes Equipped With RR Trent 500 Engines

(1) For Airbus Model A340-541 and -642 airplanes equipped with RR Trent 500 Engines: Within 2,000 flight hours after the effective date of this AD, accomplish a one-time torque check of FWD and AFT engine mount bolts on each affected engine, at the locations specified in, and in accordance with the instructions of Section 4.2.2, "Inspection requirements," of Airbus AOT A71L008-14, Revision 01, dated December 18, 2014.

(2) If, during the torque check required by paragraph (l)(1) of this AD, any discrepancy is detected (one engine mount bolt rotates, two or more engine mount bolts rotate, or one or more engine mount bolts are fully broken): Within the compliance time specified in Airbus AOT A71L008-14, Revision 01, dated December 18, 2014, accomplish all applicable corrective actions, in accordance with the instructions of Section 4.2.3, "Findings," of Airbus AOT A71L008-14, Revision 01, dated December 18, 2014, except as required by paragraphs (m)(1) and (m)(2) of this AD.

(m) Service Information Exceptions

(1) Where Airbus AOTs A71L005-14, Revision 01, dated December 11, 2014; A71L006-14, dated July 22, 2014; and A71L008-14, Revision 01, dated December 18, 2014; specify to contact Airbus for further actions, before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

(2) Where Airbus AOT A71L004-14, Revision 01, dated April 7, 2014; AOT A71L005-14, Revision 01, dated December 11, 2014; AOT A71L006-14, dated July 22, 2014; and AOT A71L008-14, Revision 01, dated December 18, 2014, specify actions "if one pylon bolt fully broken," this AD requires that those actions be done if one or more engine mount bolt is found fully broken during any torque check required by paragraph (h)(1), (j)(1), (k)(1) or (l)(1) of this AD.

(n) Reporting

At the applicable time specified in paragraphs (n)(1) and (n)(2) of this AD: After accomplishment of any torque check required by paragraphs (h), (j), (k), and (l) of this AD, report all inspection results to Airbus, including no findings, in accordance with the "Reporting" section of the applicable service information specified in paragraphs (h), (j), (k), and (l) of this AD.

(1) If the torque check was done on or after the effective date of this AD: Submit the report within 30 days after the torque check.

(2) If the torque check was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(o) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Airbus AOT A71L004-14, dated April 1, 2014 (for Airbus Model A330 Airplanes Equipped with PW Engines), which is not incorporated by reference in this AD.

(2) This paragraph provides credit for the actions required by paragraph (k) of this AD, if those actions were performed before the effective date of this AD using Airbus AOT A71L005-14, dated September 29, 2014 (for Airbus Model A330 Airplanes Equipped with RR Trent 700 Engines), which is not incorporated by reference in this AD.

(3) This paragraph provides credit for the actions required by paragraph (l) of this AD, if those actions were performed before the effective date of this AD using Airbus AOT A71L008-14, dated September 29, 2014 (for Airbus Model A340 Airplanes Equipped with RR Trent 500 Engines), which is not incorporated by reference in this AD.

(p) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Reporting Requirements: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(q) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2015-0082, dated May 11, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-7533.

(r) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus AOT A71L004-14, Revision 01, dated April 7, 2014.

(ii) Airbus AOT A71L005-14, Revision 01, dated December 11, 2014.

(iii) Airbus AOT A71L006-14, dated July 22, 2014.

(iv) Airbus AOT A71L008-14, Revision 01, dated December 18, 2014.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 12, 2016.

Suzanne Masterson,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-03 The Boeing Company: Amendment 39-18530; Docket No. FAA-2015-1273; Directorate Identifier 2014-NM-194-AD.

(a) Effective Date

This AD is effective July 6, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777-200, -200LR, -300, -300ER, and -777F series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Unsafe Condition

This AD was prompted by reports of unreliable performance of the fuel scavenge system. We are issuing this AD to prevent fuel exhaustion and subsequent power loss of all engines due to loss of capability to scavenge fuel in the center fuel tank.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Fuel Scavenge System Changes, Wiring Changes, and Software Changes

For airplanes identified in Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015, except for Group 10 airplanes on which the actions specified in Boeing Service Bulletin 777-28-0060; or Work Package 2 of the Accomplishment Instructions of Boeing Service Bulletin 777-28-0062, have not been accomplished: Within 60 months after the effective date of this AD, do the applicable actions specified in paragraphs (g)(1) through (g)(6) of this AD; and do all applicable related investigative and corrective actions; in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015. Do all applicable related investigative and corrective actions before further flight.

(1) Do applicable mechanical changes to the main fuel tank water scavenge system and center fuel tank fuel scavenge system.

(2) Install relays and related equipment on the P301 and P302 panels in the main equipment center.

(3) Do applicable wiring changes between the P105, P110, and P301 panels, and between the P200, P205, P210, and P302 panels.

(4) Do wiring changes in the P105 panel.

(5) Install new electrical load management system 2 (ELMS2) software.

(6) Do a functional test consisting of operational tests, a leak test, system tests, and a fuel scavenge system functional test. If any of the tests fail, before further flight accomplish corrective actions and repeat the test and applicable corrective actions until the test is passed.

(h) Concurrent Actions

(1) For Groups 13 through 16 airplanes, as identified in Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015, concurrently with accomplishing the actions required by paragraph (g) of this AD, install a new P301 panel on the left side of the airplane, install a new P302 panel on the right side of the airplane, and change the wiring; or perform bonding resistance measurements and rework the airplane installations; as applicable; in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-28A0047, Revision 5, dated September 20, 2010; or Boeing Service Bulletin 777-28A0047, Revision 6, dated July 11, 2013.

(2) For airplanes identified in Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015, except for Group 10 airplanes on which the actions described in Boeing Service Bulletin 777-28-0060; or Work Package 2 of the Accomplishment Instructions of Boeing Service Bulletin 777-28-0062, have not been accomplished: Concurrently with accomplishing the requirements of paragraph (g) of this AD, do wiring changes in the P110 and P210 panels, in accordance with the applicable Accomplishment Instructions of GE Aviation Service bulletin 5000ELM-28-075, Revision 1, dated August 5, 2014; and GE Aviation Service Bulletin 6000ELM-28-076, Revision 1, dated August 5, 2014.

(i) Parts Installation Prohibition

For Group 10 airplanes, as identified in Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015, after completion of the actions required by paragraph (g) of this AD, no person may install an auxiliary fuel tank on any Group 10 airplane.

(j) Credit for Previous Actions

(1) This paragraph provides credit for actions required by paragraph (h)(1) of this AD, if those actions were performed before May 26, 2011 (the effective date of AD 2011-09-05, Amendment 39-16667 (77 FR 22305, April 21, 2011)), using a service bulletin identified in paragraph (j)(1)(i) or (j)(1)(ii) of this AD, which are not incorporated by reference in this AD.

(i) Boeing Service Bulletin 777-28A0047, Revision 3, dated June 11, 2009.

(ii) Boeing Service Bulletin 777-28A0047, Revision 4, dated May 20, 2010.

(2) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 777-28-0078, dated September 4, 2014, which is not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Sue Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6438; fax: 425-917-6590; email: suzanne.lucier@faa.gov.

(2) Boeing service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(5) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin 777-28A0047, Revision 5, dated September 20, 2010.

(ii) Boeing Service Bulletin 777-28A0047, Revision 6, dated July 11, 2013.

(iii) Boeing Special Attention Service Bulletin 777-28-0078, Revision 1, dated April 27, 2015.

(iv) GE Aviation Service Bulletin 5000ELM-28-075, Revision 1, dated August 5, 2014.

(v) GE Aviation Service Bulletin 6000ELM-28-076, Revision 1, dated August 5, 2014.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) For GE Aviation service information identified in this AD, contact GE Aviation Fleet Support, 1 Neumann Way, Cincinnati, OH 45215; telephone 513-552-3272; email: aviation.fleetsupport@ge.com; Internet <http://www.geaviation.com>.

(5) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 18, 2016.
Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-04 The Boeing Company: Amendment 39-18531; Docket No. FAA-2015-5812; Directorate Identifier 2015-NM-077-AD.

(a) Effective Date

This AD is effective July 6, 2016.

(b) Affected ADs

This AD replaces AD 2011-23-05, Amendment 39-16856 (76 FR 67343, November 1, 2011) ("AD 2011-23-05").

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-300, -400, and -500 series airplanes; certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) that indicates the fuselage frames and frame reinforcements are subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking of the fuselage frames and frame reinforcements, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection, With References to Terminating Actions

This paragraph restates the requirements of paragraph (g) of AD 2011-23-05, with references to terminating actions. At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, except as required by paragraphs (k)(1), (k)(2), and (k)(4) of this AD: Do a high frequency eddy current (HFEC) surface or HFEC hole/edge inspection for any cracking of the 1.04-inch nominal diameter wire penetration hole

in the frame and frame reinforcement between stringer (S) S-20 and S-21, in accordance with Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011. Accomplishment of the applicable inspections required by paragraphs (m) and (n) of this AD terminates the inspections required by this paragraph. Accomplishment of the modification required by paragraph (p) of this AD terminates the inspections required by this paragraph for the modified area only.

(h) Retained Repetitive Inspections, With References to Terminating Actions

This paragraph restates the requirements of paragraph (h) of AD 2011-23-05, with references to terminating actions. Within 4,500 flight cycles after accomplishment of the most recent inspection specified in Part 2 or Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, or within 90 days after November 16, 2011 (the effective date of AD 2011-23-05), whichever occurs later: Do an HFEC hole/edge inspection for cracking of the 1.04-inch nominal diameter wire penetration hole in the frame and frame reinforcement between S-20 and S-21, in accordance with Part 4 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011. Repeat the inspection thereafter at intervals not to exceed 4,500 flight cycles. Accomplishment of the applicable inspections required by paragraphs (m) and (n) of this AD, terminates the inspections required by this paragraph. Accomplishment of the modification specified in paragraph (j) or (p) of this AD terminates the repetitive inspections required by this paragraph for the modified area only. Accomplishment of the repair specified in paragraph (i) of this AD terminates the repetitive inspections required by this paragraph for the repaired area only.

(i) Retained Repair, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2011-23-05, with no changes. If any cracking is found during any inspection required by paragraph (g) or (h) of this AD: Before further flight, repair the crack including doing all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, except as required by paragraph (k)(3) of this AD. All applicable related investigative and corrective actions must be done before further flight. Accomplishment of the requirements of this paragraph terminates the repetitive inspection requirements of paragraph (h) of this AD for the repaired location of that frame.

(j) Retained Optional Terminating Action, With New Limitation

This paragraph restates the optional action provided in paragraph (j) of AD 2011-23-05, with a new limitation. Accomplishment of the preventive modification before the effective date of this AD, including doing all related investigative and applicable corrective actions, specified in Part 5 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, except as required by paragraph (k)(3) of this AD, terminates the repetitive inspection requirements of paragraph (h) of this AD for the modified location of that frame, provided the modification is done before further flight after an inspection required by paragraph (g) or (h) of this AD has been done, and no cracking was found on that frame location during that inspection.

(k) Retained Exceptions to Service Information Specifications, With No Changes

This paragraph restates the requirements of paragraph (k) of AD 2011-23-05, with no changes. The following exceptions apply as specified in paragraphs (g), (i), and (j) of this AD.

(1) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, refers to a compliance time "from date on Revision 1 of this

service bulletin," this AD requires compliance within the specified compliance time after November 16, 2011 (the effective date of AD 2011-23-05).

(2) For airplanes meeting all of the criteria specified in paragraphs (k)(2)(i), (k)(2)(ii), and (k)(2)(iii) of this AD: The compliance time for the initial inspection specified in Part 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, and required by paragraph (g) of this AD, may be extended to 90 days after November 16, 2011 (the effective date of AD 2011-23-05).

(i) Model 737-300 series airplanes in Group 1, line numbers 1001 through 2565 inclusive;

(ii) Airplanes that have accumulated 40,000 or more total flight cycles as of November 16, 2011 (the effective date of AD 2011-23-05); and

(iii) Airplanes on which the modification specified in Boeing Service Bulletin 737-53-1273, dated September 20, 2006; Revision 1, dated December 21, 2006; Revision 2, dated June 4, 2007; Revision 3, dated December 7, 2009; or Revision 4, dated July 23, 2010; has been done, including any configuration or deviation that has been approved as an AMOC during accomplishment of these service bulletins, by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle Aircraft Certification Office (ACO) or Los Angeles ACO to make those findings.

(3) Where Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, specifies to contact Boeing for appropriate repair instructions: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (u) of this AD.

(4) The "Condition" column of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, refers to total flight cycles "at the date of/on this service bulletin." However, this AD applies to the airplanes with the specified total flight cycles as of November 16, 2011 (the effective date of AD 2011-23-05).

(l) Retained Credit for Previous Actions, With No Changes

This paragraph restates the requirements of paragraph (l) of AD 2011-23-05, with no changes. Actions done in accordance with Boeing Alert Service Bulletin 737-53A1279, dated December 18, 2007, before November 16, 2011 (the effective date of AD 2011-23-05), are acceptable for compliance with the corresponding actions required by paragraphs (g), (h), (i), and (j) of this AD.

(m) New Requirement of This AD: Inspections of Frames and Frame Reinforcements Between S-19 and S-22 for Certain Airplanes on Which Certain Inspections Have Not Been Accomplished

For airplanes identified as Groups 1 through 6, Configuration 3, in Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, with 30,000 total flight cycles or fewer as of the effective date of this AD, on which any inspections specified in Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011, have not been accomplished: Except as required by paragraphs (t)(1) and (t)(2) of this AD, at the applicable time specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, or within 4,500 flight cycles after the effective date of this AD, whichever occurs later, do inspections for cracking at certain locations in the frames and frame reinforcements in accordance with "Part 2—Initial Detail and HFEC Inspection" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Repeat the inspections for cracking at certain locations in the frames and frame reinforcements as specified in "Part 4—Repeat Detail and HFEC Inspections" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, thereafter at the applicable interval specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015; or, before further flight after accomplishing the Part 2 or Part 4 inspections specified in this paragraph, and no cracking was found, do "Part 5—Preventative Modification" as specified in

the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Accomplishment of the preventive modification specified in this paragraph terminates the repetitive inspections required by this paragraph for the modified area only. Do all actions specified in this paragraph in accordance with Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015.

(n) New Requirement of This AD: Inspections of Frames and Frame Reinforcements Between S-19 and S-22 for Groups 1-6, Configuration 3, Airplanes

For airplanes identified as Groups 1 through 6, Configuration 3, in Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, with more than 30,000 total flight cycles as of the effective date of this AD, or that have been inspected as specified in Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011: Except as required by paragraphs (t)(1) and (t)(2) of this AD, at the applicable time specified in table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, do inspections for cracking at certain locations of the frames and frame reinforcements in accordance with "Part 4–Repeat Detail and HFEC Inspections" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Repeat the inspections thereafter at the applicable interval specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015; or, before further flight after accomplishing the Part 4 inspection specified in this paragraph, and no cracking was found, do "Part 5–Preventative Modification" as specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Accomplishment of the preventive modification specified in this paragraph terminates the repetitive inspections required by this paragraph for the modified area only.

(o) New Requirement of This AD: Repairs

If any crack is found during any inspection required by paragraph (m) or (n) of this AD: Before further flight, repair, in accordance with "Part 3–Repair" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, except where Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, specifies to contact Boeing for damage removal and repair instructions, repair before further flight using a method approved in accordance with the procedures specified in paragraph (u) of this AD. Accomplishing a repair terminates the inspections required by paragraphs (m) and (n) of this AD in the repaired area only. Accomplishment of a repair terminates the modification required by paragraph (p) of this AD at the repaired location only.

(p) New Requirement of This AD: Preventative Modification of the Frames Between S-19 and S-22

For airplanes identified as Groups 1 through 6, Configuration 3, in Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015: Except as required by paragraphs (t)(1) and (t)(2) of this AD, at the applicable time specified in table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, do the preventive modification of the frames between S-19 and S-22, in accordance with "Part 5–Preventative Modification" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Accomplishment of the modification required by this paragraph terminates the requirements of paragraphs (g), (h), (m), and (n) of this AD for the modified location only.

(q) New Requirement of This AD: Inspections of Preventive Modification for Groups 1-3, Configuration 1, Airplanes

For airplanes identified as Groups 1 through 3, Configuration 1, in Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015: Except as required by paragraph (t)(1) of this AD, at the applicable time specified in table 3 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, do HFEC, LFEC, and detailed inspections for cracking in accordance with "Part 7—INSPECTION OF PREVENTATIVE MODIFICATION" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Repeat the inspections thereafter at the applicable interval specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. If any cracking is found during any inspection required by this paragraph, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (u) of this AD.

(r) New Requirement of This AD: Inspections of Preventive Modification for Groups 1-6, Configuration 2, Airplanes

For airplanes identified as Groups 1 through 6, Configuration 2, in Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015: Except as required by paragraph (t)(1) of this AD, at the applicable time specified in table 4 or table 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, do HFEC, LFEC, and detailed inspections for cracking in accordance with "Part 8—INSPECTION OF PREVENTATIVE MODIFICATION" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Repeat the inspections thereafter at the applicable interval specified in table 4 or table 6 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. If any cracking is found during any inspection required by this paragraph, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (u) of this AD.

(s) New Requirement of This AD: Inspections of Preventive Modification for Groups 4-6, Configuration 1, Airplanes

For airplanes identified as Groups 4 through 6, Configuration 1, in Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015: At the applicable time specified in table 5 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, except as required by paragraph (t)(1) of this AD: Do HFEC and detailed inspections for cracking in accordance with "Part 7—INSPECTION OF PREVENTATIVE MODIFICATION" of the Accomplishment Instructions of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. Repeat the inspections thereafter at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015. If any cracking is found during any inspection required by this paragraph, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (u) of this AD.

(t) New Requirement of This AD: Exceptions to Service Bulletin Specifications

(1) Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, refers to a compliance time "after the Revision 2 date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) The "Condition" column in table 1 and table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015, refers to total flight cycles "at

the Revision 2 date of this service bulletin." However, this AD applies to the airplanes with the specified total flight cycles as of the effective date of this AD.

(u) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (v)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes ODA that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) AMOCs approved for the ADs in paragraphs (u)(4)(i) through (u)(4)(iii) of this AD are approved as AMOCs for the corresponding provisions of this AD.

(i) AD 2009-02-06, Amendment 39-15796 (74 FR 10469, March 11, 2009).

(ii) AD 2009-02-06 R1, Amendment 39-16015 (74 FR 45979, September 8, 2009).

(iii) AD 2011-23-05.

(v) Related Information

(1) For more information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5324; fax: 562-627-5210; email: galib.abumeri@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (w)(5) and (w)(6) of this AD.

(w) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on July 6, 2016.

(i) Boeing Alert Service Bulletin 737-53A1279, Revision 2, dated April 21, 2015.

(ii) Reserved.

(4) The following service information was approved for IBR on November 16, 2011 (76 FR 67343, November 1, 2011).

(i) Boeing Alert Service Bulletin 737-53A1279, Revision 1, dated September 2, 2011.

(ii) Reserved.

(5) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 18, 2016.
Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-05 Airbus: Amendment 39-18532; Docket No. FAA-2015-4813; Directorate Identifier 2013-NM-161-AD.

(a) Effective Date

This AD becomes effective July 15, 2016.

(b) Affected ADs

This AD replaces AD 99-16-01, Amendment 39-11236 (64 FR 40743, July 28, 1999) ("AD 99-16-01").

(c) Applicability

This AD applies to Airbus Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes; Model A300 B4-605R and B4-622R airplanes; Model A300 F4-605R airplanes; and Model A300 C4-605R Variant F airplanes; certificated in any category; all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by the results of a full-scale fatigue test when cracking was found on the rear spar of the wing, and the subsequent determination that the risk of such cracking is higher than initially determined. We are issuing this AD to detect and correct cracking of the rear spar of the wing, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspections and Corrective Actions, With Revised Service Information

This paragraph restates the requirements of paragraphs (a), (b), (c), (d), (e), and (f) of AD 99-16-01 with revised service information and reduced thresholds and repetitive intervals, for Airbus Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes; manufacturer serial numbers (MSNs) 252 through 553 inclusive; except those airplanes on which Airbus Modification 07601 has been accomplished prior to delivery.

(1) Perform a high frequency eddy current (HFEC) rototest inspection to detect cracks in certain bolt holes where the main landing gear (MLG) forward pick-up fitting and MLG rib 5 aft are attached to the rear spar, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6017, Revision 01, including Appendix 1, dated July 25, 1994; or Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011. As of the effective date

of this AD, only Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011, may be used for the actions required by this paragraph.

(i) For airplanes that have accumulated 17,300 total landings or less as of November 9, 1995 (the effective date of AD 95-20-02, Amendment 39-9380 (60 FR 52618, October 10, 1995)) ("AD 95-20-02"): Inspect prior to the accumulation of 17,300 total landings, or within 1,500 landings after November 9, 1995, whichever occurs later.

(ii) For airplanes that have accumulated 17,301 or more total landings, but less than 19,300 total landings as of November 9, 1995 (the effective date of AD 95-20-02): Inspect within 1,500 landings after November 9, 1995.

(iii) For airplanes that have accumulated 19,300 or more total landings as of November 9, 1995 (the effective date of AD 95-20-02): Inspect within 750 landings after November 9, 1995 (the effective date of AD 95-20-02).

(2) If no crack is found during the inspection required by paragraph (g)(1) of this AD, repeat that inspection thereafter at the time specified in either paragraph (g)(2)(i) or (g)(2)(ii) of this AD, as applicable.

(i) For airplanes on which Airbus Modification 07716 (as specified in Airbus Service Bulletin A300-57-6020) has not been accomplished: Inspect at the time specified in paragraph (g)(2)(i)(A) or (g)(2)(i)(B) of this AD, as applicable.

(A) For airplanes having MSNs 465 through 553 inclusive: Repeat the inspection at intervals not to exceed 13,000 landings, until the inspection required by paragraph (g)(4)(ii)(A)(1) of this AD has been accomplished.

(B) For airplanes having MSNs 252 through 464 inclusive: Repeat the inspection at intervals not to exceed 8,400 landings, until the inspection required by paragraph (g)(4)(ii)(A)(2) of this AD has been accomplished.

(ii) For airplanes on which Airbus Modification 07716 has been accomplished: Inspect at the time specified in either paragraph (g)(2)(ii)(A) or (g)(2)(ii)(B) of this AD, as applicable.

(A) For airplanes having MSNs 465 through 553 inclusive: Repeat the inspection at intervals not to exceed 11,800 landings, until the inspection required by paragraph (g)(4)(i)(B) of this AD has been accomplished.

(B) For airplanes having MSNs 252 through 464 inclusive: Repeat the inspection within 10,700 landings following the initial inspection required by paragraph (g)(1) of this AD, and thereafter at intervals not to exceed 7,500 landings, until the inspection required by paragraph (g)(4)(ii)(B)(2) has been accomplished.

(3) If any crack is found during the inspection required by either paragraph (g)(1) or (g)(2) of this AD, prior to further flight, accomplish the requirements of either paragraph (g)(3)(i) or (g)(3)(ii) of this AD, as applicable.

(i) For airplanes on which Airbus Modification 07716 has not been accomplished: Oversize the bolt hole by 1/32 inch and repeat the HFEC inspection required by paragraph (g)(1) of this AD, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6017, Revision 01, including Appendix 1, dated July 25, 1994. After accomplishing the oversizing and HFEC inspection, repeat the inspection, as required by paragraph (g)(2) of this AD, at the applicable schedule specified in that paragraph, until the inspection required by paragraph (g)(4)(ii)(B)(1) or (g)(4)(ii)(B)(2) of this AD has been accomplished.

(A) If no cracking is detected, install the second oversize bolt in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6017, Revision 01, including Appendix 1, dated July 25, 1994.

(B) If any cracking is detected, repair in accordance with a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate.

(ii) For airplanes on which Airbus Modification 07716 has been accomplished: Repair in accordance with a method approved by the Manager, International Branch, ANM-116. After repair, repeat the inspections as required by paragraph (g)(2) of this AD at the applicable schedule specified

in that paragraph, until the inspection required by paragraph (g)(4)(ii)(B)(1) or (g)(4)(ii)(B)(2) of this AD has been accomplished.

(4) Perform an ultrasonic inspection to detect cracks in certain bolt holes where the MLG forward pick-up fitting and MLG rib 5 aft are attached to the rear spar, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6017, Revision 03, dated November 19, 1997; or Revision 04, including Appendix 1, dated February 24, 2011; at the time specified in paragraph (g)(4)(i) or (g)(4)(ii) of this AD, as applicable. As of the effective date of this AD, only Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011, may be used for the actions in this paragraph.

(i) For airplanes not inspected prior to September 1, 1999 (the effective date of AD 99-16-01), as specified in Airbus Service Bulletin A300-57-6017, dated November 22, 1993; or Revision 01, including Appendix 1, dated July 25, 1994: Inspect at the time specified in paragraph (g)(4)(i)(A), (g)(4)(i)(B), or (g)(4)(i)(C) of this AD, as applicable. Accomplishment of this inspection terminates the requirements of paragraph (g)(1) of this AD.

(A) For airplanes that have accumulated 17,300 total landings or fewer as of the effective date of this AD: Inspect prior to the accumulation of 17,300 total landings, or within 1,500 landings after September 1, 1999 (the effective date of AD 99-16-01), whichever occurs later.

(B) For airplanes that have accumulated 17,301 total landings or more but fewer than 19,300 total landings as of September 1, 1999 (the effective date of AD 99-16-01): Inspect within 1,500 landings after September 1, 1999 (the effective date of AD 99-16-01).

(C) For airplanes that have accumulated 19,300 total landings or more as of September 1, 1999 (the effective date of AD 99-16-01): Inspect within 750 landings after September 1, 1999 (the effective date of AD 99-16-01).

(ii) For airplanes on which an HFEC inspection was performed prior to September 1, 1999 (the effective date of AD 99-16-01), in accordance with the requirements of paragraph (g)(1) of this AD, or in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6017, dated November 22, 1993: Inspect at the time specified in paragraph (g)(4)(ii)(A) or (g)(4)(ii)(B) of this AD, as applicable.

(A) If no cracking was detected during any HFEC inspection accomplished prior to September 1, 1999 (the effective date of AD 99-16-01), and if Airbus Modification 07716 has not been accomplished: Inspect at the time specified in paragraph (g)(4)(ii)(A)(1) or (g)(4)(ii)(A)(2) of this AD, as applicable.

(1) For airplanes having MSNs 465 through 553 inclusive: Inspect within 13,000 landings after the most recent HFEC inspection, and thereafter at intervals not to exceed 8,900 landings. Accomplishment of this inspection constitutes terminating action for the repetitive inspection requirement of paragraph (g)(2)(i)(A) of this AD.

(2) For airplanes having MSNs 252 through 464 inclusive: Inspect within 8,400 landings after the most recent HFEC inspection, and thereafter at intervals not to exceed 5,500 landings. Accomplishment of this inspection constitutes terminating action for the repetitive inspection requirement of paragraph (g)(2)(i)(B) of this AD.

(B) If any cracking was detected during any HFEC inspection performed prior to the effective date of this AD, regardless of the method of repair, or if Airbus Modification 07716 has been accomplished: Inspect at the time specified in paragraph (g)(4)(ii)(B)(1) or (g)(4)(ii)(B)(2) of this AD, as applicable.

(1) For airplanes having MSNs 465 through 553 inclusive: Inspect within 11,800 landings after the most recent HFEC inspection, and thereafter at intervals not to exceed 8,200 landings. Accomplishment of this inspection constitutes terminating action for the repetitive inspection requirement of paragraph (g)(3)(i) or (g)(3)(ii) of this AD, as applicable.

(2) For airplanes having MSNs 252 through 464 inclusive: Inspect within 10,700 landings after the initial inspection in accordance with paragraph (g)(1) of this AD, or within 7,500 landings after the most recent HFEC inspection, whichever occurs later, and thereafter at intervals not to exceed

4,900 landings. Accomplishment of this inspection constitutes terminating action for the repetitive inspection requirement of paragraph (g)(3)(i) or (g)(3)(ii) of this AD, as applicable.

(5) If no cracking is detected during the ultrasonic inspection required by paragraph (g)(4)(i) of this AD, repeat that inspection thereafter at the time specified in paragraph (g)(5)(i) or (g)(5)(ii) of this AD, as applicable, until the initial ultrasonic inspection required by paragraph (h) of this AD is done.

(i) For airplanes having MSNs 465 through 553 inclusive: Repeat the inspection at intervals not to exceed 8,900 landings.

(ii) For airplanes having MSNs 232 through 464 inclusive: Repeat the inspection at intervals not to exceed 5,500 landings.

(6) If any cracking is detected during any inspection performed in accordance with the requirements of paragraph (g)(4) or (g)(5) of this AD: Prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116; or the Direction Générale de l'Aviation Civile (or its delegated agent); or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA).

Note 1 to paragraph (g) of this AD: Airbus Service Bulletin A300-57-6017, Revision 01, including Appendix 1, dated July 25, 1994; and Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011; also reference Airbus Service Bulletin A300-57-6020, dated November 22, 1993, as an additional source of service information for installation of oversize studs in the bolt holes.

(h) New Repetitive Inspections

At the applicable times specified in paragraph 1.B.(5), "Accomplishment Timescale," of Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011: Do ultrasonic inspections to detect cracks in the MLG attachment fitting holes on the wing rear spar, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011. Repeat the inspections thereafter at the applicable intervals specified in paragraph 1.B.(5), "Accomplishment Timescale," of Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011. For airplanes modified as specified in Airbus Service Bulletin A300-57-6073, the initial inspection threshold is counted from the completion date of the modification. Clarification of compliance time terminology used in table 1, "Structural Inspection Program," of Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011, is provided in paragraphs (h)(1) through (h)(4) of this AD. Accomplishment of the initial inspection terminates the repetitive inspections required by paragraph (g)(5) of this AD.

(1) For pre-Airbus Modification 07716 or pre-Airbus Modification 11440 airplanes:

(i) The term "flight cycles" in the "Inspection Threshold" column is total flight cycles accumulated by the airplane.

(ii) The term "flight hours" in the "Inspection Threshold" column is total flight hours accumulated by the airplane.

(2) For post-Airbus Modification 07716 airplanes:

(i) The term "flight cycles" in the "Inspection Threshold" column is total flight cycles accumulated by the airplane.

(ii) The term "flight hours" in the "Inspection Threshold" column is total flight hours accumulated by the airplane.

(3) For post-Airbus Modification 11440 (Airbus Service Bulletin A300-57-6073) airplanes:

(i) The term "flight cycles" in the "Inspection Threshold" column is flight cycles accumulated by the airplane after the modification was done.

(ii) The term "flight hours" in the "Inspection Threshold" column is flight hours accumulated by the airplane after the modification was done.

(4) For post-Airbus Modification 07601 airplanes:

(i) The term "flight cycles" in the "Inspection Threshold" column is total flight cycles accumulated by the airplane.

(ii) The term "flight hours" in the "Inspection Threshold" column is total flight hours accumulated by the airplane.

(i) Repairs

If any crack is found during any inspection required by paragraph (h) of this AD: Before further flight, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Airbus's EASA DOA.

(j) Non-Terminating Repair

Accomplishment of any repair as required by paragraph (i) of this AD is not terminating action for the repetitive inspections required by paragraph (g) or (h) of this AD.

(k) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using any of the following service information.

(1) Airbus Service Bulletin A300-57-6017, dated November 22, 1993, which is not incorporated by reference in this AD.

(2) Airbus Service Bulletin A300-57-6017, Revision 01, including Appendix 1, dated July 25, 1994, which was incorporated by reference in AD 95-20-02 and is retained in this AD.

(3) Airbus Service Bulletin A300-57-6017, Revision 02, dated January 14, 1997, including Appendix 1, dated July 25, 1994, which is not incorporated by reference in this AD.

(4) Airbus Service Bulletin A300-57-6017, Revision 03, including Appendix 1, dated November 19, 1997, which was incorporated by reference in AD 99-16-01, but is not retained in this AD.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-2125; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(ii) AMOCs approved previously for AD 99-16-01 are approved as AMOCs for the corresponding provisions of this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or EASA; or Airbus's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2013-0180, dated August 9, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> searching for and locating Docket No. FAA-2015-4813.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(5) and (n)(6) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on July 15, 2016.

(i) Airbus Service Bulletin A300-57-6017, Revision 04, including Appendix 1, dated February 24, 2011.

(ii) Reserved.

(4) The following service information was approved for IBR on November 9, 1995 (60 FR 52618, October 10, 1995).

(i) Airbus Service Bulletin A300-57-6017, Revision 01, including Appendix 1, dated July 25, 1994.

(ii) Reserved.

(5) For service information identified in this AD, contact Airbus SAS, Airworthiness Office–EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 18, 2016.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-06 The Boeing Company: Amendment 39-18533; Docket No. FAA-2015-0496; Directorate Identifier 2014-NM-101-AD.

(a) Effective Date

This AD is effective July 6, 2016.

(b) Affected ADs

This AD replaces AD 2005-18-18, Amendment 39-14258 (70 FR 53554, September 9, 2005) ("AD 2005-18-18").

(c) Applicability

This AD applies to The Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes; certificated in any category; equipped with Rolls-Royce engines; as identified in Boeing Alert Service Bulletins 757-28A0073 and 757-28A0074, both Revision 2, both dated June 4, 2009.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Unsafe Condition

This AD was prompted by a report that the service information referenced in AD 2005-18-18, did not adequately address fuel shutoff valve (FSV) wires at the aft end of the strut, for both left and right engine struts. We are issuing this AD to prevent chafing between the wire bundle and the structure of the aft fairing, which could result in electrical arcing and subsequent ignition of flammable vapors and a possible uncontrollable fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained One-Time Inspections/Related Investigative and Corrective Actions, With New Service Information and an Exception to Certain Service Information

This paragraph restates the requirements of paragraph (f) of AD 2005-18-18, with new service information and an exception to certain service information. Within 60 months after October 14, 2005 (the effective date of AD 2005-18-18), do the actions required by paragraphs (g)(1) and (g)(2) of this AD. Where Boeing Alert Service Bulletin 757-28A0074, Revision 2, dated June 4, 2009, states "SWPM 20-10-11, Table IX," the correct phrase is "SWPM 20-10-11, 'Minimum Clearance' Table."

(1) Accomplish the detailed inspections for discrepancies of the wire bundles in the left and right engine-to-wing aft fairings, and applicable and related investigative and corrective actions if

necessary, as applicable, by doing all the actions specified in the Accomplishment Instructions of the applicable service bulletins listed in paragraphs (g)(1)(i) and (g)(1)(ii) of this AD. As of the effective date of this AD, use only Boeing Alert Service Bulletin 757-28A0073 or 757-28A0074, both Revision 2, both dated June 4, 2009, as applicable. Accomplish any related investigative and corrective actions before further flight, in accordance with the applicable service bulletin. For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

(i) For Boeing Model 757-200, -200CB, and -200PF series airplanes, use the service information identified in paragraphs (g)(1)(i)(A), (g)(1)(i)(B), and (g)(1)(i)(C) of this AD.

(A) Boeing Alert Service Bulletin 757-28A0073, dated November 20, 2003;

(B) Boeing Alert Service Bulletin 757-28A0073, Revision 1, dated February 24, 2005.

(C) Boeing Alert Service Bulletin 757-28A0073, Revision 2, dated June 4, 2009.

(ii) For Boeing Model 757-300 series airplanes, use the service information identified in paragraphs (g)(1)(ii)(A), (g)(1)(ii)(B), and (g)(1)(ii)(C) of this AD.

(A) Boeing Alert Service Bulletin 757-28A0074, dated November 20, 2003.

(B) Boeing Alert Service Bulletin 757-28A0074, Revision 1, dated February 24, 2005.

(C) Boeing Alert Service Bulletin 757-28A0074, Revision 2, dated June 4, 2009.

(2) Install back-to-back p-clamps between the wire and hydraulic supply tube at the aft end of the right-hand strut only; and re-route the wire bundles, if necessary; by doing all the applicable actions specified in the Accomplishment Instructions of the applicable service information identified in paragraphs (g)(2)(i) through (g)(2)(iv) of this AD. As of the effective date of this AD, use only the service information identified in paragraphs (g)(2)(ii) and (g)(2)(iv) of this AD, as applicable.

(i) Boeing Alert Service Bulletin 757-28A0073, Revision 1, dated February 24, 2005.

(ii) Boeing Alert Service Bulletin 757-28A0073, Revision 2, dated June 4, 2009.

(iii) Boeing Alert Service Bulletin 757-28A0074, Revision 1, dated February 24, 2005.

(iv) Boeing Alert Service Bulletin 757-28A0074, Revision 2, dated June 4, 2009.

(h) New Spiral Cable Wrap Installation

Within 60 months after the effective date of this AD, install spiral cable wrap on FSV wires at the aft end of the strut, for both left and right engines, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-28A0073 (for Model 757-200, -200CB, and -200PF series airplanes) or 757-28A0074 (for Model 757-300 series airplanes), both Revision 2, both dated June 4, 2009. Where Boeing Alert Service Bulletin 757-28A0074, Revision 2, dated June 4, 2009, states "SWPM 20-10-11, Table IX," the correct phrase is "SWPM 20-10-11, 'Minimum Clearance' Table." Do all applicable related investigative and corrective actions before further flight.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2005-18-18 are approved as AMOCs for the corresponding provisions of paragraph (g) of this AD.

(j) Related Information

For more information about this AD, contact William Bond, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5253; fax: 562-627-5210; email: william.bond@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on July 6, 2016.

(i) Boeing Alert Service Bulletin 757-28A0073, Revision 2, dated June 4, 2009.

(ii) Boeing Alert Service Bulletin 757-28A0074, Revision 2, dated June 4, 2009.

(4) The following service information was approved for IBR on October 14, 2005 (70 FR 53554, September 9, 2005).

(i) Boeing Alert Service Bulletin 757-28A0073, dated November 20, 2003.

(ii) Boeing Alert Service Bulletin 757-28A0073, Revision 1, dated February 24, 2005.

(iii) Boeing Alert Service Bulletin 757-28A0074, dated November 20, 2003.

(iv) Boeing Alert Service Bulletin 757-28A0074, Revision 1, dated February 24, 2005.

(5) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 17, 2016.

Dionne Palermo,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-07 The Boeing Company: Amendment 39-18534; Docket No. FAA-2015-8130; Directorate Identifier 2014-NM-175-AD.

(a) Effective Date

This AD is effective July 12, 2016.

(b) Affected ADs

This AD affects the ADs specified in paragraphs (b)(1) and (b)(2) of this AD.

(1) AD 2014-20-10, Amendment 39-17983 (79 FR 60331, October 7, 2014) ("AD 2014-20-10").

(2) AD 2015-17-13, Amendment 39-18246 (80 FR 52948, September 2, 2015) ("AD 2015-17-13").

(c) Applicability

This AD applies to The Boeing Company Model 777-200 and -300 series airplanes, certificated in any category, equipped with Pratt and Whitney engines, as identified in Boeing Special Attention Service Bulletin 777-71-0055, Revision 1, dated April 15, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Unsafe Condition

This AD was prompted by reports of blocked drain lines at the engine forward strut that caused flammable fluid to accumulate in a flammable leakage zone. We are issuing this AD to prevent blockage of forward strut drain lines. This condition could cause flammable fluids to collect in the forward strut area and potentially cause an uncontrolled fire or cause failure of engine attachment structure and consequent airplane loss.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Actions

Within 4,000 flight cycles or 750 days after the effective date of this AD, whichever occurs later: Accomplish the actions specified in paragraphs (g)(1) through (g)(4) of this AD on the left and right struts, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-71-0055, Revision 1, dated April 15, 2015; and accomplish the revision specified in paragraph (g)(5) of this AD.

(1) Disconnect and remove the forward strut drain lines.

(2) Clean the left system disconnect, the strut forward lower spar, and the forward fireseal pan drain lines.

(3) Install new forward strut drain lines and insulation blankets.

(4) Do a leak check of the forward strut drain lines for any leak, and repair if any leak is found.

(5) Revise the maintenance or inspection program, as applicable, to incorporate Airworthiness Limitation 54-AWL-01, "Forward Strut Drain Line" as specified in Section D.4, Pratt and Whitney Forward Strut Drain Line, dated March 2014, of the Boeing 777 Maintenance Planning Data (MPD) Document Section 9, Airworthiness Limitations (AWLs) and Certification Maintenance Requirements (CMRs), D622W001-9, dated October 2014. The initial compliance time for Airworthiness Limitation 54-AWL-01 is within 2,000 flight cycles or 1,500 days, whichever occurs first, after doing the actions specified in paragraphs (g)(1) through (g)(4) of this AD.

(h) No Alternative Actions or Intervals

After accomplishing the revision required by paragraph (g)(5) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k) of this AD.

(i) Terminating Action for Other ADs

(1) Accomplishing the actions required by paragraph (g) of this AD terminates the actions required by paragraph (g) of AD 2015-17-13 at the modified area only.

(2) Accomplishing the actions specified in paragraphs (i)(2)(i) and (i)(2)(ii) of this AD terminates the inspections required by paragraph (g) of AD 2014-20-10 at the modified area only, provided the actions are accomplished concurrently, or the actions specified in paragraph (i)(2)(ii) of this AD are done after accomplishing the actions specified in paragraph (i)(2)(i) of this AD.

(i) The actions specified in paragraphs (g)(1) through (g)(4) of this AD on the left and right struts are done in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-71-0055, Revision 1, dated April 15, 2015; and the revision specified in paragraph (g)(5) of this AD is done.

(ii) A one-time general visual inspection for hydraulic fluid contamination (including contamination caused by hydraulic fluid in its liquid, vapor, and/or solid (coked) form) of the interior of the strut forward dry bay, and all applicable related investigative and corrective actions (including checking drain lines for blockage due to hydraulic fluid coking, and cleaning or replacing drain lines to allow drainage) are done in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-54-0028, Revision 1, dated December 10, 2013, except where Boeing Special Attention Service Bulletin 777-54-0028, Revision 1, dated December 10, 2013, specifies to contact Boeing for repair, the repair must be done using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(j) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g)(1) through (g)(4) of this AD, if those actions were performed before the effective date of this AD using Boeing Special Attention Service Bulletin 777-71-0055, dated June 12, 2014, which is not incorporated by reference in this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14

CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Kevin Nguyen, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6501; fax: 425-917-6590; email: kevin.nguyen@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 777-54-0028, Revision 1, dated December 10, 2013.

(ii) Boeing Special Attention Service Bulletin 777-71-0055, Revision 1, dated April 15, 2015.

(iii) Airworthiness Limitation 54-AWL-01, "Forward Strut Drain Line," as specified in Section D.4, Pratt and Whitney Forward Strut Drain Line, dated March 2014, of the Boeing 777 Maintenance Planning Data Document Section 9, Airworthiness Limitations and Certification Maintenance Requirements, D622W001-9, dated October 2014.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 20, 2016.
Victor Wicklund,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-08 Airbus Defense and Space S.A. (formerly known as Construcciones Aeronauticas, S.A.): Amendment 39-18535; Docket No. FAA-2015-8465; Directorate Identifier 2014-NM-239-AD.

(a) Effective Date

This AD is effective July 6, 2016.

(b) Affected ADs

This AD replaces AD 2001-12-18, Amendment 39-12274 (66 FR 33014, June 20, 2001) ("AD 2001-12-18").

(c) Applicability

This AD applies to Airbus Defense and Space S.A. (formerly known as Construcciones Aeronauticas, S.A.) Model CN-235 airplanes, serial numbers C-001 through C-015 inclusive; and Model CN-235-100 and -200 airplanes, serial numbers C-016 through C-073 inclusive; certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 76, Engine Controls.

(e) Reason

This AD was prompted by reports of new occurrences of cable disruption on a certain part number; the disruption is caused by microcracks along the cable surface. We are issuing this AD to prevent fatigue of the engine control cables, leading to breakage of the cables, which could result in reduced controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Action for the Power Lever and Condition Lever Control Stops, With No Changes

This paragraph restates the requirements of paragraph (a) of AD 2001-12-18. Within 15 days after July 25, 2001 (the effective date of AD 2001-12-18): Rig the power lever and condition lever control stops, in accordance with CASA COM 235-140, Revision 01, dated March 21, 2000.

(h) New Requirement of This AD: Replacement

At the applicable compliance times specified in table 1 to paragraph (h) of this AD: Replace each power lever and condition lever Teleflex cable having part number (P/N) 72830-20 with a new or

serviceable part, in accordance with Airbus Military Alert Operators Transmission AOT-CN235-76-0001, dated May 27, 2014. Repeat the replacement thereafter at intervals not to exceed an accumulation of 5,000 total flight cycles on each Teleflex cable having P/N 72830-20.

Table 1 to Paragraph (h) of This AD—Replacement Compliance Time

Total flight cycles accumulated on the Teleflex cable having P/N 72830-20 (since first installation on an airplane) as of the effective date of this AD	Compliance time
Fewer than 4,700 total flight cycles	Before accumulating 5,000 total flight cycles.
Equal to or more than 4,700 total flight cycles, but fewer than 6,000 total flight cycles	Within 300 flight cycles or 12 months after the effective date of this AD, whichever occurs first.
Equal to or more than 6,000 total flight cycles, but fewer than 7,000 total flight cycles	Within 200 flight cycles or 6 months after the effective date of this AD, whichever occurs first.
Equal to or more than 7,000 total flight cycles	Within 100 flight cycles or 3 months after the effective date of this AD, whichever occurs first.

(i) Parts Installation Limitations

As of the effective date of this AD, no person may install, on any airplane, a Teleflex cable having P/N 72830-20, unless the cable has accumulated fewer than 5,000 total flight cycles since its first installation on an airplane.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or EADS CASA's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0262, dated December 5, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-8465.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on July 6, 2016.

(i) Airbus Military Alert Operators Transmission AOT-CN235-76-0001, dated May 27, 2014.

(ii) Reserved.

(4) The following service information was approved for IBR on July 25, 2001 (66 FR 33014, June 20, 2001).

(i) CASA COM 235-140, Revision 01, dated March 21, 2000.

(ii) Reserved.

(5) For service information identified in this AD, contact EADS-CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain; telephone +34 91 585 55 84; fax +34 91 585 55 05; email MTA.TechnicalService@casa.eads.net; Internet <http://www.eads.net>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 20, 2016.

Victor Wicklund,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-15 Fokker Services B.V.: Amendment 39-18542. Docket No. FAA-2015-8466; Directorate Identifier 2015-NM-045-AD.

(a) Effective Date

This AD is effective July 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by the need for more restrictive fuel system airworthiness limitations. We are issuing this AD to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance Program Revision

(1) Within 12 months after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate the fuel system airworthiness limitation items (ALIs) and critical design configuration control limitations (CDCCLs) specified in Fokker Services B.V. Engineering Report SE-672, "Fokker 70/100 Fuel ALI's and CDCCL's," Issue 5, released December 11, 2014.

(2) The initial compliance times and repetitive intervals for the actions are at the applicable times specified within Fokker Services B.V. Engineering Report SE-672, "Fokker 70/100 Fuel ALI's and CDCCL's," Issue 5, released December 11, 2014. If any discrepancy is found, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). Repair any discrepancy before further flight.

(h) No Alternative Inspections, Inspection Intervals, or CDCCLs

After accomplishment of the actions specified in paragraph (g) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used unless the inspections, intervals, or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Fokker Services B.V.'s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0032, dated February 24, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-8466.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Services B.V. Engineering Report SE-672, Fokker 70/100 Fuel ALI's and CDCCL's, Issue 5, released December 11, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 23, 2016.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-17 The Boeing Company: Amendment 39-18544 ; Docket No. FAA-2015-3987;
Directorate Identifier 2015-NM-066-AD.

(a) Effective Date

This AD is effective July 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to certain The Boeing Company Model 787-8 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin B787-81205-SB270024-00, Issue 001, dated September 24, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical power.

(e) Unsafe Condition

This AD was prompted by a report of wire chafing caused by a left wing spoiler actuator wire not having enough separation from a certain bracket when the spoiler is in the deployed position. We are issuing this AD to detect and correct wire chafing; such chafing could result in an electrical short and potential fire in a flammable fluid leakage zone and possible loss of several functions essential for safe flight.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Wire Separation Measurement, Related Investigative Actions, and Corrective Actions

Within 24 months after the effective date of this AD: Measure the separation between the electro-mechanical actuator wire W801182 of the left wing, spoiler 4, and the support bracket of the flap variable camber trim unit, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB270024-00, Issue 001, dated September 24, 2014. Do all applicable related investigative and corrective actions before further flight.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(i) Related Information

For more information about this AD, contact Sean J. Schauer, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6479; fax: 425-917-6590; email: sean.schauer@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin B787-81205-SB270024-00, Issue 001, dated September 24, 2014.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 20, 2016.

Victor Wicklund,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-18 The Boeing Company: Amendment 39-18545; Docket No. FAA-2015-2958; Directorate Identifier 2014-NM-248-AD.

(a) Effective Date

This AD is effective July 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 787 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Unsafe Condition

This AD was prompted by the disclosure that the inner diameters of some batches of landing gear pins were not shot peened in accordance with design specifications, and need to be replaced. We are issuing this AD to detect and correct insufficient shot peening that could lead to stress corrosion cracking and failure of the landing gear pin, and cause landing gear collapse and inability to control the airplane at high speeds on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Replacement

For airplanes on which the original airworthiness certificate or the original export certificate of airworthiness was issued on or before the effective date of this AD: At the applicable time specified in paragraph 5, "Compliance," of Boeing Alert Service Bulletin B787-81205-SB320022-00, Issue 002, dated April 6, 2016, do a landing gear pin part number and serial number inspection, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB320022-00, Issue 002, dated April 6, 2016. A review of airplane maintenance or delivery records is acceptable in lieu of this inspection if the part number and serial number of the installed landing gear pins can be conclusively determined from that review.

(1) If the part number and serial number do not match the list of affected pin numbers: No further action is required by this paragraph at that pin location.

(2) If the part number and serial number match the list of affected pin numbers: At the applicable time specified in paragraph 5, "Compliance," of Boeing Alert Service Bulletin B787-81205-

SB320022-00, Issue 002, dated April 6, 2016, replace the affected pin with a pin that does not have an affected part number and serial number, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB320022-00, Issue 002, dated April 6, 2016.

(h) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD, using Boeing Alert Service Bulletin B787-81205-SB320022-00, Issue 001, dated November 14, 2014. This service information is not incorporated by reference in this AD.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane a landing gear pin having an affected part number and serial number identified in Boeing Alert Service Bulletin B787-81205-SB320022-00, Issue 002, dated April 6, 2016.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Melanie Violette, Senior Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6422; fax: 425-917-6590; email: melanie.violette@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin B787-81205-SB320022-00, Issue 002, dated April 6, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 24, 2016.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-11-20 B/E Aerospace: Amendment 39-18547; FAA-2015-2134; Directorate Identifier 2015-CE-012-AD.

(a) Effective Date

This AD is effective July 15, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to B/E Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11, that is installed on airplanes.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 35; Oxygen.

(e) Unsafe Condition

This AD was prompted by a report of a PBE, P/N 119003-11, catching fire upon activation by a crewmember. We are issuing this AD to correct the unsafe condition on these products.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

Within 3 months after July 15, 2016 (the effective date of this AD), while still in the stowage box, physically inspect the PBE pouch to determine if it has an intact vacuum seal. Do this inspection following paragraph III.A.1. of the Accomplishment Instructions in B/E Aerospace Service Bulletin No. 119003-35-011, Rev. 000, dated February 4, 2015.

(h) Replacement

(1) If a PBE pouch is found that does not have an intact vacuum seal during the inspection required in paragraph (g) of this AD: Before further flight or following existing minimum equipment list (MEL) procedures, replace the PBE with a PBE, P/N 119003-21, following paragraphs III.C., III.D.(4), III.D.(6), and III.D.(7) of the Accomplishment Instructions in B/E Aerospace Service Bulletin No. 119003-35-009, Rev. 001, dated April 12, 2016, or replace it with another FAA-approved serviceable PBE.

(2) If a PBE pouch is found during the inspection required in paragraph (g) of this AD where the vacuum seal is intact: Within 18 months after July 15, 2016 (the effective date of this AD), remove PBE, P/N 119003-11, and replace the PBE with PBE, P/N 119003-21, following paragraphs III.C., III.D.(4), III.D.(6), and III.D.(7) of the Accomplishment Instructions in B/E Aerospace Service Bulletin No. 119003-35-009, Rev. 001, dated April 12, 2016, or replace it with another FAA-approved serviceable PBE.

(i) Credit for Actions Done Following Previous Service Information

If you performed the replacement action required in paragraphs (h)(1) and (2) of this AD before July 15, 2016 (the effective date of this AD) using B/E Aerospace Service Bulletin No. 119003-35-009, Rev. 000, dated November 9, 2015, you met the requirements of those paragraphs of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact David Enns, Aerospace Engineer, Wichita ACO, FAA, 1801 S. Airport Road, Room 100, Wichita, Kansas 67209; phone: (316) 946-4147; fax: (316) 946-4107; email: david.enns@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) B/E Aerospace Service Bulletin No. 119003-35-009, Rev. 001, dated April 12, 2016.

(ii) B/E Aerospace Service Bulletin No. 119003-35-011, Rev. 000, dated February 4, 2015.

(3) For B/E Aerospace, Inc. service information identified in this AD, contact B/E Aerospace, Inc., 10800 Pflumm Road, Commercial Aircraft Products Group, Lenexa, Kansas 66215; phone: (913) 338-9800; fax: (913) 338-8419; Internet: www.beaerospace.com.

(4) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-2134.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 25, 2016.
Pat Mullen,
Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.



2016-11-22 Fokker Services B.V.: Amendment 39-18549. Docket No. FAA-2016-0464; Directorate Identifier 2015-NM-046-AD.

(a) Effective Date

This AD is effective July 12, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by the need for more restrictive airworthiness limitations. We are issuing this AD to reduce the potential for significant failure conditions and consequent loss of controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Maintenance or Inspection Program

(1) Within 12 months after the effective date of this AD, revise the maintenance or inspection program, as applicable, to incorporate the certification maintenance requirements (CMR) specified in "Fokker 70/100 Certification Maintenance Requirements," of Fokker Services B.V. Engineering Report, Airworthiness Limitations Section (ALS), SE-473, Issue 11, released January 19, 2015.

(2) Do the applicable initial CMR inspection at the time specified in paragraph (g)(2)(i) or (g)(2)(ii) of this AD, as applicable, as specified in "Fokker 70/100 Certification Maintenance Requirements," of Fokker Services B.V. Engineering Report, ALS, SE-473, Issue 11, released January 19, 2015. If any discrepancy is found during any inspection, repair using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency; or Fokker B.V. Service's EASA Design Organization Approval (DOA). Repair any discrepancy before further flight.

(i) For CMR inspection 783100-CM-01: Within 1 year or 3,000 flight hours after the effective date of this AD, whichever occurs first, but not later than 12,000 flight hours after accomplishing Maintenance Review Board (MRB) Task 783100-00-04.

(ii) For CMR inspection 783500-CM-01: Within 1 year or 3,000 flight hours after the effective date of this AD, whichever occurs first, but not later than 10,000 flight hours after accomplishing MRB Task 783100-01-01.

(h) No Alternative Inspections or Inspection Intervals

After accomplishment of the actions specified in paragraph (g)(1) of this AD, no alternative actions (e.g., inspections) and intervals, may be used, unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the EASA; or Fokker Services B.V.'s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0027, dated February 20, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0464.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Services B.V. Engineering Report, Airworthiness Limitations Section (ALS), SE-473, Issue 11, released January 19, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350;

fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet
<http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 26, 2016.

Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.



2016-12-03 Fokker Services B.V.: Amendment 39-18552. Docket No. FAA-2015-8138; Directorate Identifier 2014-NM-112-AD.

(a) Effective Date

This AD becomes effective July 15, 2016.

(b) Affected ADs

This AD replaces AD 2011-17-10, Amendment 39-16774 (76 FR 50111, August 12, 2011) ("AD 2011-17-10").

(c) Applicability

This AD applies to Fokker Services B.V. Model F.28 Mark 1000 airplanes; certificated in any category; serial numbers (S/Ns) 11003 through 11041 inclusive, and S/Ns 11991 and 11992.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

(e) Reason

This AD was prompted by the issuance of revised service information to update the critical design configuration control limitations (CDCCLs) that address potential ignition sources inside fuel tanks. We are issuing this AD to prevent potential ignition sources inside the fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Inspection and Installation, With Revised Service Information

This paragraph restates the requirements of paragraph (g) of AD 2011-17-10, with revised service information. At a scheduled opening of the fuel tanks, but not later than 84 months after September 16, 2011 (the effective date of AD 2011-17-10), do a general visual inspection for the presence of a by-pass wire between the housing of each in-tank fuel quantity indication (FQI) cable plug and the cable shield, in accordance with Part 1 of the Accomplishment Instructions of Fokker Service Bulletin SBF28-28-053, Revision 1, dated September 20, 2010; or Fokker Service Bulletin SBF28-28-053, Revision 3, dated January 9, 2014. As of the effective date of this AD, only Fokker Service Bulletin SBF28-28-053, Revision 3, dated January 9, 2014, may be used.

(h) Retained Corrective Actions, With Revised Service Information

This paragraph restates the requirements of paragraph (h) of AD 2011-17-10, with revised service information. If during the general visual inspection required by paragraph (g) of this AD, it is found that a by-pass wire is not installed: Before the next flight, install the by-pass wire between the housing of the in-tank FQI cable plug and the cable shield, in accordance with Part 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF28-28-053, Revision 1, dated September 20, 2010; or Fokker Service Bulletin SBF28-28-053, Revision 3, dated January 9, 2014. As of the effective date of this AD, only Fokker Service Bulletin SBF28-28-053, Revision 3, dated January 9, 2014, may be used.

(i) Retained Maintenance Program Revision To Add Fuel Airworthiness Limitation, With a New Exception

This paragraph restates the requirements of paragraph (i) of AD 2011-17-10, with a new exception. Except as required by paragraph (k) of this AD, concurrently with the actions required by paragraph (g) of this AD, revise the airplane maintenance program by incorporating CDCCL-1 specified in paragraph 1.L.(1)(c) of Fokker Service Bulletin SBF28-28-053, Revision 1, dated September 20, 2010.

(j) Retained Requirement for No Alternative Actions, Intervals, and/or CDCCLs, With a New Exception

This paragraph restates the requirements of paragraph (k) of AD 2011-17-10 with a new exception. Except as required by paragraph (k) of this AD: After accomplishing the revision required by paragraph (i) of this AD, no alternative actions (e.g., inspection, interval) and/or CDCCLs may be used unless the actions, intervals, and/or CDCCLs are approved as an alternative methods of compliance (AMOC) in accordance with the procedures specified in paragraph (n)(1) of this AD.

(k) New Maintenance or Inspection Program Revision To Add Fuel Airworthiness Limitation

Within 30 days after the effective date of this AD: Revise the airplane maintenance or inspection program, as applicable, by incorporating CDCCL Item 1.7 as specified in paragraph 1.L.(1)(c) of Fokker Service Bulletin SBF28-28-053, Revision 3, dated January 9, 2014. Accomplishing the revision required by this paragraph terminates the revision required by paragraph (i) of this AD.

(l) No Alternative CDCCLs

After the maintenance or inspection program has been revised as required by paragraph (k) of this AD, no alternative CDCCLs may be used unless the CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (n)(1) of this AD.

(m) Credit for Previous Actions

This paragraph provides credit for the applicable actions required by paragraph (k) of this AD, if those actions were performed before the effective date of this AD using Fokker Service Bulletin SBF28-28-053, Revision 2, dated June 22, 2011. This document is not incorporated by reference in this AD.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(o) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0111, dated May 8, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-8138.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(5) and (p)(6) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on July 15, 2016.

(i) Fokker Service Bulletin SBF28-28-053, Revision 3, dated January 9, 2014.

(ii) Reserved.

(4) The following service information was approved for IBR on September 16, 2011 (76 FR 50111, August 12, 2011).

(i) Fokker Service Bulletin SBF28-28-053, Revision 1, dated September 20, 2010.

(ii) Reserved.

(5) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 31, 2016.
Michael Kaszycki,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.