

**FEDERAL AVIATION ADMINISTRATION  
AIRWORTHINESS DIRECTIVES**

**SMALL AIRPLANES, ROTORCRAFT, GLIDERS,  
BALLOONS, & AIRSHIPS**

**BIWEEKLY 2014-07**

*3/24/2014 - 4/6/2014*



Federal Aviation Administration  
Engineering Procedures Office, AIR-110  
P.O. Box 25082  
Oklahoma City, OK 73125-0460

## CHANGE OF ADDRESS NOTICE

Any change of address regarding the biweekly service must include the mailing label from a recent issue or your name and address printed exactly as they appear on the mailing label (including the computer number above the address).

Please allow one month for an address change.

### MAIL YOUR ADDRESS CHANGE TO:

Superintendent of Documents  
Government Printing Office  
Mail List Branch SSOM  
Washington, DC 20402

Telephone: (202) 512-1806  
Facsimile: (202) 512-2250

**SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Information Key: E - Emergency; COR - Correction; S – Supersedes

**Biweekly 2014-01**

2013-26-09		Turbomeca S.A.	ASTAZOU XIV B and XIV H engines
2013-26-13		Sikorsky Aircraft Corporation	S-70, S-70A, S-70C, S-70C (M), and S-70C (M1) helicopters
99-01-05 R1		See AD	See AD

**Biweekly 2014-02**

2013-25-13		Sikorsky Aircraft Corporation	S-70, S-70A, and S-70C helicopters
2013-26-11		Eurocopter France Helicopters	EC225LP helicopters
2014-01-01		Turbomeca S.A.	Arrius 2F turboshaft engines

**Biweekly 2014-03**

2014-01-02		Eurocopter Deutschland GmbH	EC135P2+ and EC135T2+ helicopters
2014-02-02		Bell Helicopter Textron Canada Limited	206L, L-1, L-3, and L-4 helicopters
2014-02-03	S 2011-27-51	Beechcraft Corporation	1900, 1900C, 1900C (Military) and 1900D
2014-02-04		Eurocopter France	EC 155B and EC155B1 helicopters
2014-02-05		Eurocopter France	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, and AS350D1 helicopters
2014-02-07		Costruzioni Aeronautiche Tecnam srl	P2006T
2014-02-08		Agusta S.p.A.	A109C, A109S, A109K2, A109E, and AW109SP helicopters
2014-02-09		Eurocopter France	EC225LP and AS332L1 helicopters

**Biweekly 2014-04**

2014-03-02		Airbus Helicopters	AS332C, AS332L, AS332L1, AS332L2, SA330J helicopters
2014-03-10		Various Restricted Category Helicopters	See AD
2014-03-11		Bell Helicopter Textron, Inc.	204B helicopters

**Biweekly 2014-05**

2014-02-06		Agusta S.p.A.	AB412 helicopters
2014-03-01		Agusta S.p.A.	AB139 and AW139 helicopters
2014-03-03		Cessna Aircraft Company	310, 320, 340, 401, 402, 411, 414, and 421 airplanes
2014-03-18		B-N Group Ltd.	BN-2 airplanes
2014-03-20		Piaggio Aero Industries S.P.A	P-180 airplanes
2014-04-01		Slingsby Aviation Ltd.	T67M260 airplanes
2014-04-02		Dornier Luftfahrt GmbH	228-212 airplanes
2014-04-03		Pacific Aerospace Limited	750XL airplanes
2014-04-04		Diamond Aircraft Industries GmbH	DA 42 NG and DA 42 M NG airplanes
2014-04-06		Turbomeca S.A.	Arrius 2B1, 2B1A, 2B2, and 2K1 turboshaft engines
2014-04-11		Airbus Helicopters	AS350B, BA, B1, B2, B3, D; and AS355E, F, F1, F2, and N helicopters
2014-04-12		Airbus Helicopters	EC225LP helicopters
2014-04-14		Agusta S.p.A.	A109S, AW109SP, A119, and AW119 MKII helicopters

**Biweekly 2014-06**

2011-22-05 R1		Airbus Helicopters	AS350B, B1, B2, B3, BA, C, D, D1; and Model AS355E, F, F1, F2, N, and NP helicopters
2014-04-13		Agusta S.p.A.	AB412 and AB412 EP helicopters
2014-05-01		Eurocopter Deutschland	EC135P1, EC135P2, EC135P2+, EC135T1, EC135T2, and EC135T2+ helicopters
2014-05-04		Eurocopter Deutschland	MBB-BK 117 C-2 helicopters
2014-05-06		Eurocopter Deutschland	EC135 P1, P2, P2+, T1, T2, and T2+ helicopters
2014-05-07		Airbus Helicopters	AS350B, BA, B1, B2, C, D, and D1 helicopters and Model AS355E, F, F1, F2, and N helicopters
2014-05-08		Airbus Helicopters	AS332L1 helicopters
2014-05-11		Airbus Helicopters	AS332C, AS332L, AS332L1, AS332L2, EC225LP, and SA330J helicopters
2014-05-15		Airbus Helicopters	AS332C, AS332L, AS332 L1, and AS332 L2 helicopters; SA330J helicopters

**SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

AD No.	Information	Manufacturer	Applicability
Information Key: E - Emergency; COR - Correction; S – Supersedes			
2014-05-29 2014-06-01	S 2009-16-03	Continental Motors M7 Aerospace	IO-520, TSIO-520, and IO-550 series reciprocating engines SA226-AT, SA226-T, SA226-T(B), SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), SA227-TT, SA26-AT, and SA26-T airplanes
<b>Biweekly 2014-07</b>			
2014-05-10	S 2012-25-04	Airbus Helicopters	AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters
2014-05-27 2014-06-03		Rockwell Collins British Aerospace Regional Aircraft	Mode S transponders Jetstream Series 3101 and Jetstream Model 3201 airplanes
2014-06-06 2014-06-07 2014-06-51	S 2013-12-06	SOCATA Alexander Schleicher Airbus Helicopters Deutschland	TBM 700 airplanes ASK 21 gliders MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, and MBB-BK 117 C-2 helicopters
2014-07-51 2014-07-52		Agusta Airbus Helicopters	AB139 and AW139 helicopters AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters



---

**2014-05-10 Airbus Helicopters (Type Certificate Previously Held By Eurocopter France):**  
Amendment 39-17783; Docket No. FAA-2013-0822; Directorate Identifier 2013-SW-004-AD.

**(a) Applicability**

This AD applies to Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3 (except AS350B3 helicopters with modification (MOD) 07 5606 installed), AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters, certificated in any category.

**(b) Unsafe Condition**

This AD defines the unsafe condition as severe vibrations due to failure of laminated half-bearings (bearings). This condition could result in failure of the tail rotor and subsequent loss of control of the helicopter.

**(c) Affected AD**

This AD supersedes AD No. 2012-25-04, Amendment 39-17285 (78 FR 24041, April 24, 2013).

**(d) Effective Date**

This AD becomes effective May 2, 2014.

**(e) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(f) Required Action**

(1) For Model AS350B3 helicopters with MOD 07 5601 installed:

Note 1 to paragraph (f) of this AD: MOD 075601 is an integral part of a specific Model AS350B3 configuration, commercially identified as "AS350B3e" and is not fitted on Model AS350B3 helicopters of other configurations.

(i) Before further flight:

(A) Install a velocity never exceed (VNE) placard that reads as follows on the instrument panel in full view of the pilot and co-pilot with 6-millimeter red letters on a white background:

VNE LIMITED TO 100 KTS IAS.

(B) Replace the IAS limit versus the flight altitude placard located inside the cabin on the center post with the placard as depicted in Figure 1 to paragraph (f) of this AD:

<b>VNE POWER ON</b>	
<b>Hp (ft)</b>	<b>IAS (kts)</b>
0	100
2000	97
4000	94
6000	91
8000	88
10000	85
12000	82
14000	79
16000	76
18000	73
20000	70
22000	67
<b>Valid for VNE POWER OFF</b>	

**Figure 1 to paragraph (f)**

(ii) Before further flight, revise the Rotorcraft Flight Manual (RFM) by inserting a copy of this AD into the RFM or by making pen and ink changes as follows:

(A) Revise paragraph 2.3 of the RFM by inserting the following:  
VNE limited to 100 kts IAS.

(B) Revise paragraph 2.6 of the RFM by inserting Figure 2 to paragraph (f) of this AD.

<b>VNE POWER ON</b>	
<b>Hp (ft)</b>	<b>IAS (kts)</b>
0	100
2000	97
4000	94
6000	91
8000	88
10000	85
12000	82
14000	79

16000	76
18000	73
20000	70
22000	67
Valid for VNE POWER OFF	

**Figure 2 to paragraph (f)**

(C) Add the following as paragraph 3.3.3 to the RFM:

### 3.3.3 IN-FLIGHT VIBRATIONS FELT IN THE PEDALS

Symptom:

#### IN-FLIGHT VIBRATIONS FELT IN THE PEDALS



1. CHECK PEDAL EFFECTIVENESS
  2. SMOOTHLY REDUCE THE SPEED TO VY
  3. AVOID SIDESLIP AS MUCH AS POSSIBLE
- LAND AS SOON AS POSSIBLE

(iii) Before further flight, and thereafter after each flight, without exceeding 3 hours time-in-service (TIS) between two checks, visually check each bearing as follows:

(A) Position both tail rotor blades horizontally.

(B) Apply load (F) by hand, perpendicular to the pressure face of one tail rotor blade (a), as shown in Figure 3 to paragraph (f) of this AD, taking care not to reach the extreme position against the tail rotor hub. The load will deflect the tail rotor blade towards the tail boom.

(C) While maintaining the load, check all the visible faces of the bearings (front and side faces) in area B of DETAIL A of Figure 3 to paragraph (f) of this AD for separation between the elastomer and metal parts, a crack in the elastomer, or an extrusion (see example in Figure 4 to paragraph (f) of this AD). A flashlight may be used to enhance the check.



DETAIL A




Figure 3 to paragraph (f)




Figure 4 to paragraph (f)

(D) Repeat paragraphs (f)(1)(iii)(A) through (f)(1)(iii)(C) of this AD on the other tail rotor blade.

(E) Apply load (G) by hand perpendicular to the suction face of one tail rotor blade as shown in Figure 5 to paragraph (f) of this AD. The load will deflect the tail rotor blade away from the tail boom.





Figure 5 to paragraph (f)

(F) While maintaining the load, check visible faces of Area C as shown in Figure 5 to paragraph (f) of this AD for any extrusion. A flashlight may be used to enhance the check.

(G) Repeat paragraphs (f)(1)(iii)(E) and (f)(1)(iii)(F) of this AD on the other tail rotor blade.

(iv) The actions required by paragraphs (f)(1)(iii)(A) through (f)(1)(iii)(G) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate, and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR §§ 43.9 (a)(1)-(4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR §§ 91.417, 121.380, or 135.439.

(v) If there is an extrusion on any bearing, before further flight, replace the four bearings with airworthy bearings.

(vi) If there is a separation or a crack on the pressure side bearing, measure the separation or the crack. If the separation or crack is greater than 5 millimeters (.196 inches) as indicated by dimension "L" in Figure 6 to paragraph (f) of this AD, before further flight, replace the four bearings with airworthy bearings.




Figure 6 to paragraph (f)

(vii) No later than after the last flight of the day, perform a one-time inspection by removing the bearings and inspecting for a separation, a crack, or an extrusion. This inspection is not a daily inspection. If there is a separation, crack, or extrusion, before further flight, replace the four bearings with airworthy bearings.

(viii) Within 130 hours TIS:

(A) Modify the chin weight support as described in the Accomplishment Instructions, paragraphs 3.B.2.a through 3.B.2.h, of Eurocopter Service Bulletin (SB) No. AS350-64.00.11, Revision 0, dated December 19, 2012.

(B) Remove the additional chin weights, install blanks on the chin weights, replace bearings with more than 5 hours TIS, and re-identify the blade assembly as described in the Accomplishment Instructions, paragraph 3.B.2.a., of Eurocopter SB No. AS350-01.00.66, Revision 1, dated February 15, 2013 (SB AS350-01.00.66).

(C) Modify and re-identify the rotating pitch-change spider assembly as described in the Accomplishment Instructions, paragraph 3.B.2.b., of SB AS350-01.00.66.

(D) Install a load compensator as described in the Accomplishment Instructions, paragraph 3.B.3.b., of SB AS350-01.00.66.

(E) Modify the electrical installation as described in the Accomplishment Instructions, section 3.B.4., of SB AS350-01.00.66.

Note 2 to paragraph (f) of this AD: The manufacturer refers to the actions in paragraphs (f)(1)(viii)(B) through (f)(1)(viii)(E) of this AD as MOD 07 5606.

(ix) After modification of a helicopter as required by paragraphs (f)(1)(viii)(A) through (f)(1)(viii)(E) of this AD, the actions of paragraph (f)(1)(iii) through (f)(1)(vii) of this AD are no longer required and the operating limitation placards and RFM procedures required by paragraphs (f)(1)(i) through (f)(1)(ii)(C) of this AD may be removed.

(2) For Model AS350B, AS350BA, AS350B1, AS350B2, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP helicopters, and Model AS350B3 helicopters that do not have MOD 07 5601 installed:

(i) No later than after the last flight of the day, and thereafter during each last flight of the day check, without exceeding 10 hours TIS between two checks, visually check each bearing as described in paragraphs (f)(1)(iii)(A) through (f)(1)(vi) of this AD.

(ii) If there is an extrusion on any bearing, before further flight, replace the bearing with an airworthy bearing.

(iii) If there is a separation or a crack on the bearing, measure the separation or the crack. If the separation or crack is greater than 5 mm (.196 inches) as indicated by dimension "L" and greater than 2 mm (.078 inches) as indicated by dimension "P" in Figure 3 of Eurocopter Emergency Alert Service Bulletin (EASB) No. 05.00.71 or No. 05.00.63, both Revision 2 and both dated December 19, 2012, as applicable to your model helicopter, before further flight, replace the bearing.

### **(g) Credit for Actions Previously Completed**

Actions accomplished before the effective date of this AD in accordance with Emergency AD No. 2012-21-51, dated October 19, 2012, or AD No. 2012-25-04, Amendment 39-17285 (78 FR 24041, April 24, 2013) are considered acceptable for compliance with the corresponding actions of this AD.

### **(h) Special Flight Permits**

Special flight permits are prohibited.

### **(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5328; email robert.grant@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

**(j) Additional Information**

(1) Eurocopter EASB No. 01.00.65 and No. 01.00.24, both Revision 3 and both dated February 4, 2013, which are co-published as one document and which are not incorporated by reference, contain additional information about the subject of this AD. For this service information, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review this service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in European Aviation Safety Agency AD No. 2013-0029, dated February 8, 2013, which can be found on the Internet at <http://www.regulations.gov> in Docket number 2013-0822.

**(k) Subject**

Joint Aircraft Service Component (JASC) Code: 6400: Tail Rotor.

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Service Bulletin No. AS350-64.00.11, Revision 0, dated December 19, 2012.

(ii) Eurocopter Service Bulletin No. AS350-01.00.66, Revision 1, dated February 15, 2013.

(iii) Eurocopter Emergency Alert Service Bulletin No. 05.00.71, Revision 2, dated December 19, 2012.

(iv) Eurocopter Emergency Alert Service Bulletin No. 05.00.63, Revision 2, dated December 19, 2012.

Note 3 to paragraph (l)(2): Eurocopter Emergency Alert Service Bulletin No. 05.00.71, Revision 2, dated December 19, 2012, and Eurocopter Emergency Alert Service Bulletin No. 05.00.63, Revision 2, dated December 19, 2012, are co-published as one document along with Eurocopter Emergency Alert Service Bulletin No. 05.00.46, Revision 2, dated December 19, 2012, and Eurocopter Emergency Alert Service Bulletin No. 05.00.42, Revision 2, dated December 19, 2012, which are not incorporated by reference in this AD.

(3) For Eurocopter service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on February 20, 2014.

Lance T. Gant,  
Acting Directorate Manager, Rotorcraft Directorate,  
Aircraft Certification Service.



---

**2014-05-27 Rockwell Collins, Inc.:** Amendment 39-17799; Docket No. FAA-2013-0966; Directorate Identifier 2013-CE-040-AD.

**(a) Effective Date**

This AD is effective May 2, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

(1) This AD applies to the following Rockwell Collins, Inc. Mode S transponders that are installed on but not limited to the airplanes listed in paragraphs (c)(2)(i) and (c)(2)(ii) of this AD:

(i) TPR-720: CPN 622-7878-001, 622-7878-020, 622-7878-120, 622-7878-200, 622-7878-201, 622-7878-301, 622-7878-440, 622-7878-460, 622-7878-480, 622-7878-901; and

(ii) TPR-900: CPN 822-0336-001, 822-0336-020, 822-0336-220, 822-0336-440, 822-0336-460, 822-0336-480, 822-0336-902.

(2) The products listed in paragraphs (c)(1)(i) and (c)(1)(ii) of this AD may be installed on but not limited to the following airplanes, certificated in any category:

(i) Airbus Models A319, A320, A330, A340; and

(ii) The Boeing Company Models B737, B747, B757, B767, B777, MD-80, and DC-9.

(3) The listing of airplanes in paragraphs (c)(2)(i) and (c)(2)(ii) of this AD is not intended as all-inclusive. The affected transponders may be installed using a supplemental type certificate or other means on other airplanes not listed in those paragraphs.

**(d) Subject**

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 34, Navigation.

**(e) Unsafe Condition**

This AD was prompted by the identification that the TPR-720 and TPR-900 Mode S transponders respond intermittently to Mode S interrogations from both ground-based and traffic collision avoidance system equipped airplanes. We are issuing this AD to correct possible misalignment issues with the transponders that could result in increased pilot and air traffic controller workload as well as reduced separation of airplanes.

**(f) Compliance**

Comply with this AD within the compliance times specified in paragraph (g) of this AD, unless already done.

**(g) Test and Calibration**

(1) Within the next 2 years after the effective date of this AD and repetitively thereafter at intervals not to exceed every 4 years, send the TPR-720 and TPR-900 Mode S transponders to a properly certified repair facility for test and calibration to assure proper alignment following Rockwell Collins Service Information Letter 13-1, Revision No. 1, 523-0821603-101000, dated October 24, 2013.

(2) Rockwell Collins Service Information Letter 13-1, Revision No. 1, 523-0821603-101000, dated October 24, 2013, recommends the affected transponders be sent to a Rockwell Collins authorized repair facility for the alignment and return to service testing; however, any properly certified repair facility may do this alignment and return to service testing.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(i) Related Information**

For more information about this AD, contact Roger A. Souter, FAA, Wichita ACO, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: 316-946-4134; facsimile: 316-946-4107; email address: roger.souter@faa.gov.

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rockwell Collins Service Information Letter 13-1, Revision No. 1, 523-0821603-101000, dated October 24, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Rockwell Collins, Inc., Collins Aviation Services, 350 Collins Road NE., M/S 153-250, Cedar Rapids, IA 52498-0001; telephone: 888-265-5467 (U.S.) or 319-265-5467; fax: 319-295-4941 (outside U.S.); email: techmanuals@rockwellcollins.com; Internet: [http://www.rockwellcollins.com/Services\\_and\\_Support/Publications.aspx](http://www.rockwellcollins.com/Services_and_Support/Publications.aspx).

(4) You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 4, 2014.  
Steven W. Thompson,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2014-06-03 British Aerospace Regional Aircraft:** Amendment 39-17807; Docket No. FAA-2013-1012; Directorate Identifier 2013-CE-037-AD.

**(a) Effective Date**

This airworthiness directive (AD) becomes effective May 2, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to British Aerospace Regional Aircraft Jetstream Series 3101 and Jetstream Model 3201 airplanes, all serial numbers, certificated in any category.

**(d) Subject**

Air Transport Association of America (ATA) Code 32: Landing Gear.

**(e) Reason**

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as stress corrosion cracking of the main landing gear yoke pintle housing. We are issuing this AD to prevent abrasion and subsequent corrosion from building on the main landing gear (MLG) yoke pintle housing. This condition if not corrected could cause structural failure of the MLG resulting in loss of control during take-off or landing.

**(f) Actions and Compliance**

Unless already done, do the following actions as applicable in paragraphs (f)(1) and (f)(2) of this AD:

(1) At the next scheduled MLG removal after May 2, 2014 (the effective date of this AD), modify the left hand (LH) and right hand (RH) MLG installation at the forward spigot following the accomplishment instructions of British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JM7862, Revision 1, dated May 7, 2013.

(2) As of May 2, 2014 (the effective date of this AD), do not install any LH or RH MLG on Jetstream Series 3101 airplanes and Jetstream Model 3201 airplanes unless it is found to be in compliance with the requirements of paragraph (f)(1) of this AD.

**(g) Credit for Actions Done in Accordance With Previous Service Information**

This AD allows credit for the requirements of paragraph (f)(1) of this AD if already done before May 2, 2014 (the effective date of this AD), following British Aerospace Jetstream Series 3100 & 3200 Service Bulletin SB 32-JM7862, original issue, dated April 8, 2013.

**(h) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**(i) Related Information**

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2013-0206, dated September 9, 2013, for related information. The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2013-1012-0002>.

**(j) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) British Aerospace Jetstream Series 3100 & 3200 Service Bulletin 32-JM7862, Revision 1, dated May 7, 2013.

(ii) Reserved.

(3) For British Aerospace Regional Aircraft service information identified in this AD, contact BAE Systems (Operations) Ltd, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; phone: +44 1292 675207, fax: +44 1292 675704; email: [RApublications@baesystems.com](mailto:RApublications@baesystems.com); Internet: <http://www.jetstreamcentral.com>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 14, 2014.

Earl Lawrence,  
Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2014-06-06 SOCATA:** Amendment 39-17810; Docket No. FAA-2013-1019; Directorate Identifier 2013-CE-038-AD.

**(a) Effective Date**

This airworthiness directive (AD) becomes effective May 2, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to SOCATA TBM 700 airplanes, all serial numbers, certificated in any category.

**(d) Subject**

Air Transport Association of America (ATA) Code 32: Landing Gear.

**(e) Reason**

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the landing gear actuator rod and piston becoming unscrewed during operation and the landing gear actuator ball joint becoming uncrimped. We are issuing this AD to detect and correct discrepancies in the pistons/rods and the ball joint centering of the nose landing gear and main landing gear, which could result in landing gear failure and lead to damage of the airplane and occupant injury.

**(f) Actions and Compliance**

Unless already done, do the actions in paragraphs (f)(1) through (f)(4) of this AD on any airplane with the landing gear actuators part number (P/N) T700A3230050000, P/N T700A323005000000, or P/N T700A323005300000 installed:

(1) Within the next 8 months after May 2, 2014 (the effective date of this AD), perform a detailed visual inspection (DVI) of the pistons and rods of the nose landing gear (NLG) and left hand (LH) and right hand (RH) main landing gear (MLG) actuators and measure the distance following the Accomplishment Instructions in DAHER-SOCATA Mandatory Service Bulletin SB 70-197, dated April 2013.

(2) Within the next 8 months after May 2, 2014 (the effective date of this AD), perform a DVI of the ball joint centering of the NLG and LH and RH MLG actuators and measure the ball joint mismatch following the Accomplishment Instructions in DAHER-SOCATA Mandatory Service Bulletin SB 70-206, dated April 2013.

(3) If any discrepancy is found during any inspection required in paragraphs (f)(1) or (f)(2) of this AD, before further flight, replace the affected actuator or rod end assembly if applicable with an airworthy part following the applicable Accomplishment Instructions in DAHER-SOCATA Mandatory Service Bulletin SB 70-197, dated April 2013; and/or DAHER-SOCATA Mandatory Service Bulletin SB 70-206, dated April 2013.

(4) As of May 2, 2014 (the effective date of this AD), do not install on any airplane a landing gear actuator P/N T700A3230050000, P/N T700A323005000000, or P/N T700A323005300000, unless it is found to be in compliance with the inspection requirements of paragraphs (f)(1) and (f)(2) of this AD. The landing gear actuator must be installed when doing these inspections.

#### **(g) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: [albert.mercado@faa.gov](mailto:albert.mercado@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### **(h) Related Information**

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2013-0227, dated September 23, 2013 for related information. The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!documentDetail;D=FAA-2013-1019-0002>.

#### **(i) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) DAHER-SOCATA Mandatory Service Bulletin SB 70-197, dated April 2013.

(ii) DAHER-SOCATA Mandatory Service Bulletin SB 70-206, dated April 2013.

(3) For SOCATA service information identified in this AD, contact SOCATA—Direction des Services—65921 Tarbes Cedex 9—France; telephone +33 (0) 62 41 7300, fax +33 (0) 62 41 76 54, or for North America: SOCATA NORTH AMERICA, 7501 South Airport Road, North Perry Airport, Pembroke Pines, Florida 33023; telephone: (954) 893-1400; fax: (954) 964-4141; email: [mysocata@socata.daher.com](mailto:mysocata@socata.daher.com); Internet: <http://mysocata.com>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 19, 2014.  
James E. Jackson,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.



---

**2014-06-07 Alexander Schleicher, Segelflugzeugbau:** Amendment 39-17811; Docket No. FAA-2014-0019; Directorate Identifier 2013-CE-045-AD.

**(a) Effective Date**

This airworthiness directive (AD) becomes effective May 8, 2014.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Alexander Schleicher, Segelflugzeugbau Model ASK 21 gliders, all serial numbers, certificated in any category, that have incorporated:

(1) Alexander Schleicher Segelflugzeugbau ASK 21 Technical Note No. 4, dated November 14, 1980; or

(2) Alexander Schleicher GmbH & Co. Segelflugzeugbau ASK 21 Technical Note 4a, dated November 25, 2004.

**(d) Subject**

Air Transport Association of America (ATA) Code 11: Placards and Markings.

**(e) Reason**

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as inadequate guidance for spin training operations. We are issuing this proposed AD to ensure the placard installed in the aircraft cockpit, the aircraft flight manual (AFM), and the instructions for continued airworthiness (ICA) all have adequate guidance for spin training operations.

**(f) Actions and Compliance**

Unless already done, do the following actions as specified in paragraphs (f)(1) through (f)(3) of this AD:

(1) For gliders modified following Alexander Schleicher Segelflugzeugbau ASK 21 Technical Note No. 4, dated November 14, 1980: Within 30 days after May 8, 2014 (the effective date of this AD), insert the amended pages into the glider's AFM and the ICA and install a cockpit placard following paragraph B) of the Action section in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASK 21 Technical Note Nr. 4b, Issue for US registered gliders, dated October 31, 2013.

(2) For gliders modified following Alexander Schleicher GmbH & Co. Segelflugzeugbau ASK 21 Technical Note 4a, dated November 25, 2004: Within 30 days after May 8, 2014 (the effective

date of this AD), insert the amended pages into the glider's AFM and the ICA following paragraph C) of the Action section in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASK 21 Technical Note Nr. 4b, Issue for US registered gliders, dated October 31, 2013.

(3) For all affected gliders: An owner/operator (pilot) holding at least a private pilot certificate may insert the amended pages into the AFM and ICA of the glider required by paragraphs (f)(1) and (f)(2) of this AD and must enter the action into the aircraft records showing compliance with this AD following 14 CFR 43.9 (a)(1)-(4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

### **(g) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any aircraft to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

### **(h) Related Information**

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2013-0123, dated June 5, 2013, for related information. The MCAI can be found in the AD docket on the Internet at: <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0019-0002>. You may also refer to Alexander Schleicher Segelflugzeugbau ASK 21 Technical Note No. 4, dated November 14, 1980; and Alexander Schleicher GmbH & Co. Segelflugzeugbau ASK 21 Technical Note 4a, dated November 25, 2004, for more information. For service information related to this AD, you may contact the manufacturer using the information found in paragraph (i)(3) of this AD.

### **(i) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Alexander Schleicher, Segelflugzeugbau Alexander Schleicher GmbH & Co. Segelflugzeugbau ASK 21 Technical Note Nr. 4b, Issue for US registered gliders, dated October 31, 2013.

(ii) Reserved.

(3) For Alexander Schleicher, Segelflugzeugbau service information identified in this AD, contact Alexander Schleicher GmbH & Co. Segelflugzeugbau, Alexander-Schleicher-Str. 1, D-36163 Poppenhausen, Germany; phone: +49 (0) 06658 89-0; fax: +49 (0) 06658 89-40; Internet: <http://www.alexander-schleicher.de/>; email: info@alexander-schleicher.de.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>

Issued in Kansas City, Missouri, on March 19, 2014.

James E. Jackson,  
Acting Manager, Small Airplane Directorate,  
Aircraft Certification Service.



**DATE: March 24, 2014**

**AD #: 2014-06-51**

This superseding emergency airworthiness directive (EAD) 2014-06-51 is being sent to owners and operators of Airbus Helicopters Deutschland GmbH (previously Eurocopter Deutschland GmbH) Model MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, and MBB-BK 117 C-2 helicopters with a Metro Aviation, Inc. (Metro) vapor-cycle air conditioning kit pulley (pulley), part number (P/N) 30001, installed in accordance with Supplemental Type Certificate (STC) No. SH3880SW.

### **Background**

On June 13, 2013 we issued AD 2013-12-06 (78 FR 40956, July 9, 2013) which required repetitively inspecting the air conditioning drive pulley for looseness and properly installed lockwire, and also required reinstalling the pulley. AD 2013-12-06 was prompted by two reports of the pulley detaching from the rotor brake disk on the tail rotor (T/R) driveshaft.

On December 20, 2013 Metro requested and we approved a global Alternative Method of Compliance (AMOC) for AD 2013-12-06 (78 FR 40956, July 9, 2013), which allowed installing a tabbed washer in lieu of performing the repetitive inspections required by paragraph (e) of that AD. On March 10, 2014, we received a report that an attaching bolt would not seat on the mating surface of the pulley. Compliance with the AMOC revealed a possible design deficiency and a manufacturing defect in some pulleys. Metro has determined that the pulley, along with two additional pulleys from other helicopters, did not have sufficient thread depth. This condition may allow the attaching bolts to come loose, resulting in the pulley detaching from the rotor brake disc, subsequent damage to the T/R driveshaft, and loss of control of the helicopter.

This EAD supersedes AD 2013-12-06 (78 FR 40956, July 9, 2013) and requires inspecting the pulley to determine if there is sufficient depth of the threads and removing the pulley if there is not sufficient depth. This EAD also requires installing a dual locking tab on each pulley attaching bolt. This EAD also requires reporting the inspection findings to the FAA. Finally, this EAD revises the applicability to helicopters with a pulley, P/N 30001, installed rather than to the air conditioning kit because this part has been determined to be the unsafe condition. These EAD actions are intended to prevent the pulley detaching from the rotor brake disc, subsequent damage to the T/R driveshaft, and loss of control of the helicopter.

### **FAA's Determination**

We are issuing this EAD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

## **Related Service Information**

We reviewed Metro Alert Service Bulletin No. MA145-21B-003, Revision B, dated December 20, 2013 (ASB MA145-21B-003), which describes procedures for installing a dual-locking tab on the air conditioning drive pulley attachment bolts.

## **EAD Requirements**

This EAD requires, within 5 hours time-in-service, inspecting each pulley attaching bolt hole to determine if there is sufficient depth of the threads. If the depth is less than .061 inch, this EAD requires removing the pulley. This EAD also requires installing dual locking tabs under each pulley attaching bolt by following the Accomplishment Instructions, paragraphs 3.E. through 3.G., of ASB MA145-21B-003. This EAD also requires submitting a report of the inspection findings to the FAA.

## **Differences Between This EAD and the Service Information**

This EAD requires determining the depth of the threaded portion of the pulley attaching bolt holes; the service information does not.

## **Paperwork Reduction Act**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this EAD is 2120-0056. The paperwork cost associated with this EAD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting required by this EAD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave., SW, Washington, DC 20591; ATTN: Information Collection Clearance Officer, AES-200.

## **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. "Subtitle VII, Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701, General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## **Adoption of the Emergency Airworthiness Directive (EAD)**

We are issuing this EAD under 49 U.S.C. Sections 106(g), 40113, and 44701 according to the authority delegated to me by the Administrator.

2014-06-51 **Airbus Helicopters Deutschland GmbH (Airbus) Helicopters (Type Certificate Previously Held By Eurocopter Deutschland GmbH):** Directorate Identifier 2014-SW-016-AD.

**(a) Applicability**

This EAD applies to Airbus Model MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, and MBB-BK 117 C-2 helicopters with a Metro Aviation, Inc. vapor-cycle air conditioning kit pulley (pulley) part number (P/N) 30001 installed in accordance with Supplemental Type Certificate (STC) No. SH3880SW.

**(b) Unsafe Condition**

This EAD defines the unsafe condition as insufficient thread depth which could allow the attaching bolts to come loose, resulting in the pulley detaching from the rotor brake disc, subsequent damage to the tail rotor (T/R) driveshaft, and loss of control of the helicopter.

**(c) Effective Date**

This EAD is effective upon receipt.

**(d) Affected ADs**

This AD supersedes AD 2013-12-06, Amendment 39-17484, (78 FR 40956, July 9, 2013), Directorate ID 2013-SW-027-AD.

**(e) Compliance**

You are responsible for performing each action required by this EAD within the specified compliance time unless it has already been accomplished prior to that time.

**(f) Required Actions**

Within 5 hours time-in-service, inspect each pulley attaching bolt hole to determine the depth:

(1) Relieve tension from the compressor drive belt and remove each bolt that attaches the pulley to the rotor brake disc. Do not remove all three bolts at the same time.

(2) Remove AN960-416 washer or MAI-145-DUAL LOCK TAB washer.

(3) Using a bolt or screw with ¼-28 threads with 0.5 inch of threads and a minimum of 0.8 inch grip length, coat the shank with blue dye or permanent marker and thread into hole until threads have lightly bottomed (finger tight). Scribe the shank flush with the face of the rotor brake disk. Measure distance from end to scribe mark (length protruding into assembly). This dimension represents total depth of threads and stack-up of the brake disk.

(4) If the depth measures less than 0.61 inch, remove the pulley.

(5) If the depth measures 0.61 inch or more, install dual locking tabs as described in the Accomplishment Instructions, paragraphs 3.E. through 3.G., of Metro Aviation Alert Service Bulletin No. MA145-21B-003, Revision B, dated December 20, 2013.

**(g) Reporting Requirement**

Within 10 days after inspecting the pulley as required by paragraph (f)(3) of this AD, submit a report with the helicopter model, helicopter serial number, hole number 1 thread depth, hole number 2 thread depth (if measured), and hole number 3 thread depth (if measured) to the person identified in paragraph (i)(1) of this AD.

**(h) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Rotorcraft Certification Office, FAA, may approve AMOCs for this EAD. Send your proposal to: Martin Crane, Aviation Safety Engineer, Rotorcraft Certification Office, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5170; email [7-AVS-ASW-170@faa.gov](mailto:7-AVS-ASW-170@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this EAD through an AMOC.

**(i) Additional Information**

(1) For further information contact: Martin Crane, Aviation Safety Engineer, Rotorcraft Certification Office, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5170; email [7-AVS-ASW-170@faa.gov](mailto:7-AVS-ASW-170@faa.gov).

(2) For a copy of the service information referenced in this AD, contact: Metro Aviation, Inc., 1214 Hawn Ave, Shreveport, LA 71107; phone: (318) 222-5529; website: [metroproductsupport.com](http://metroproductsupport.com).

**(j) Subject**

Joint Aircraft Service Component (JASC) Code: 6500: Tail Rotor Drive.

Issued in Fort Worth, Texas, on March 24, 2014.

Kim Smith,  
Manager, Rotorcraft Directorate,  
Aircraft Certification Service.



**DATE: March 27, 2014**

**AD #: 2014-07-51**

This emergency airworthiness directive (EAD) 2014-07-51 is being sent to owners and operators of AgustaWestland S.p.A. Model AB139 and AW139 helicopters.

### **Background**

This EAD was prompted by reports of certain Lower Half Scissor Spherical Bearings (bearings) dislodging from certain Main Rotor (M/R) Rotating Scissors. This EAD requires inspecting the M/R Rotating Scissors for play of the bearing. If the play is beyond allowable limits, this EAD requires removing the affected bearing and re-identifying the M/R Rotating Scissors. This EAD also requires removing all affected bearings. The actions of this EAD are intended to detect excessive play of the bearing and prevent failure of the M/R Rotating Scissors and subsequent loss of control of the helicopter.

### **Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, issued EASA EAD No. 2014-0073-E, dated March 20, 2014, to correct an unsafe condition for AgustaWestland S.p.A. Model AB139 and AW139 helicopters. EASA advises of reports of the dislodging of bearings, part number (P/N) 3G6230V00654, that were installed on M/R Rotating Scissors, P/N 3G6230A00733. EASA also states that as a result of the investigations accomplished by the supplier of the bearings, it was determined that a quality issue might have affected the production of the bearings. EASA advises that the condition, if not detected and corrected, could lead to loss of control of the helicopter. The EASA EAD requires repetitive inspections of certain M/R Rotating Scissors, P/N 3G6230A00733, that have been manufactured or repaired with the installation of certain potentially defective bearings, P/N 3G6230V00654. The EASA EAD also requires replacement of the affected bearings, or as an alternative, replacement of the M/R Rotating Scissors with an affected bearing, which constitutes terminating action for the repetitive inspections required by the EAD.

### **FAA's Determination**

These helicopters have been approved by the aviation authority of Italy and are approved for operation in the United States. Pursuant to our bilateral agreement with Italy, EASA, its technical representative, notified us of the unsafe condition described in the EASA EAD. We are issuing this EAD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs.

### **Related Service Information**

AgustaWestland issued Bollettino Tecnico No. 139-368, dated March 19, 2014 (BT), for Model AB139 and AW139 helicopters with certain serial numbered (S/Ned) M/R Rotating Scissors, P/N 3G6230A00733; or M/R Rotating Scissors, P/N 3G6230A00733, which have been repaired with the installation of certain S/Ned bearings, P/N 3G6230V00654. The BT also applies to affected parts

kept in stock. The BT was issued to identify and replace potentially defective bearings caused by a supplier quality issue. The BT also establishes an interim inspection schedule to reduce impact on operations.

AgustaWestland also issued Data Module No. 39-C-62-31-00-00A-286C-A, issue 001, dated August 6, 2012, for Model AB139 and AW139 helicopters to specify the detailed inspection of the fixed swashplate and rotating scissors.

### **EAD Requirements**

This EAD requires, within 5 hours time-in-service (TIS) and thereafter at intervals not to exceed 5 hours TIS, inspecting the M/R Rotating Scissors for play of the bearing. If there is play, this EAD requires, before further flight, a more detailed inspection of the M/R Rotating Scissors. If the detailed inspection results determine the play is beyond allowable limits, this EAD requires, before further flight, removing the bearing and re-identifying the M/R Rotating Scissors. This EAD also requires, within 50 hours TIS, removing any affected bearing.

### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. "Subtitle VII, Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701, General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Adoption of the Emergency Airworthiness Directive (EAD)**

We are issuing this EAD under 49 U.S.C. Sections 106(g), 40113, and 44701 according to the authority delegated to me by the Administrator.

2014-07-51 **AgustaWestland S.p.A. (Agusta):** Directorate Identifier 2014-SW-017-AD.

#### **(a) Applicability**

This EAD applies to the following Agusta Model AB139 and AW139 helicopters, certificated in any category:

(1) For helicopters with Main Rotor (M/R) Rotating Scissors, part number

(P/N) 3G6230A00733, with serial numbers (S/Ns) listed in Table 1 of AgustaWestland Bollettino Tecnico No. 139-368, dated March 19, 2014 (BT 139-368), on which the Lower Half Scissors Spherical Bearing (bearing), P/N 3G6230V00654, was not replaced; and

(2) For helicopters with M/R Rotating Scissors, P/N 3G6230A00733, on which the bearing, P/N 3G6230V00654, was replaced with a bearing with a S/N listed in Table 2 of BT 139-368.

**(b) Unsafe Condition**

This EAD defines the unsafe condition as excessive play of the bearing in the M/R Rotating Scissors. This condition could result in failure of the M/R Rotating Scissors and subsequent loss of control of the helicopter.

**(c) Effective Date**

This EAD is effective upon receipt.

**(d) Compliance**

You are responsible for performing each action required by this EAD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

(1) Within 5 hours time-in-service (TIS) and thereafter at intervals not to exceed 5 hours TIS, inspect the M/R Rotating Scissors for play of the bearing in accordance with paragraph 4. of Part I, Compliance Instructions, of BT 139-368.

(2) If there is play, before further flight, accomplish a detailed inspection of the M/R Rotating Scissors in accordance with steps 9.1 through 12.9 of Data Module No. 39-C-62-31-00-00A-286C-A, Rotating control installation – Fixed swashplate and rotating scissors – Detailed inspection, issue 001, dated August 6, 2012, of Chapter 62, Main Rotor, issue 003, dated July 15, 2006, Change 16, dated October 31, 2013, of AgustaWestland Aircraft Maintenance Publication, dated August 6, 2012, published October 31, 2013. If there is play beyond allowable limits, before further flight, remove the bearing.

(3) Within 50 hours TIS, remove any bearing listed in the Applicability section of this EAD.

(4) Prior to installing a M/R Rotating Scissors with a S/N listed in the Applicability section of this EAD, replace the bearing and re-identify the M/R Rotating Scissors in accordance with paragraphs 4.2. through 4.4. of Part II, Compliance Instructions, of BT 139-368.

(5) Do not install a bearing listed in the Applicability section of this EAD into any M/R Rotating Scissors.

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this EAD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this EAD through an AMOC.

**(g) Additional Information**

(1) For further information contact: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

(2) For a copy of the service information referenced in this AD, contact: AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D'Angelo; telephone 39-0331-664757; fax 39-0331-664680; or at <http://www.agustawestland.com/technical-bulletins>.

**(h) Subject**

Joint Aircraft Service Component (JASC) Code: 6200, M/R System.

Issued in Fort Worth, Texas, on March 27, 2014.

Lance T. Gant,  
Acting Directorate Manager, Rotorcraft Directorate,  
Aircraft Certification Service.



**DATE: March 28, 2014**

**AD #: 2014-07-52**

This emergency airworthiness directive (EAD) 2014-07-52 is being sent to owners and operators of Airbus Helicopters (previously Eurocopter France) Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with modification (MOD) 07 3215 or with a reinforcement angle, part number (P/N) 350A08.2493.21 or P/N 350A08.2493.23, installed.

### **Background**

This EAD was prompted by a report that cracks were found in the reinforcement angles of the rear structure to tailboom junction frame (reinforcement angles) on several AS355 helicopters. This EAD requires repetitively inspecting certain reinforcement angles for a crack, and repairing any cracked reinforcement angle. As an option to performing the 10 hour TIS repetitive inspections, this EAD allows an alternate 165 hour TIS repetitive inspection. These EAD actions are intended to detect a crack in the reinforcement angle, which if not corrected, could result in loss of the tailboom and subsequent loss of control of the helicopter.

### **Discussion**

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA EAD 2014-0076-E, dated March 25, 2014, to correct an unsafe condition for Airbus Helicopters Model AS350B, AS350BA, AS350BB, AS350B1, AS350B2, AS350B3, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with MOD 07 3215 or with at least one reinforcement angle, P/N 350A08.2493.21 or P/N 350A08.2493.23 installed. EASA advises that during the inspection of several AS355 helicopters, cracks were found in the reinforcement angles. EASA further states that a subsequent investigation revealed that cracks were initiated on the non-visible surface of the angle, which is the surface in contact with the frame, and that this condition, if not corrected, could lead to further crack propagation and subsequent loss of the tailboom, resulting in loss of the helicopter. The EASA EAD requires repetitive inspections of the reinforcement angles, and states that a terminating action is currently under investigation.

### **FAA's Determination**

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, EASA, its technical representative, has notified us of the unsafe condition described in the EASA EAD. We are issuing this EAD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs.

### **Related Service Information**

Airbus Helicopters has issued Emergency Alert Service Bulletin (EASB) No. 05.00.70 for Model AS350B, BA, BB, B1, B2, B3, and D helicopters and EASB No. 05.00.62 for Model AS355E,

F, F1, F2, N, and NP helicopters, both Revision 0 and dated March 24, 2014. Each EASB describes procedures for inspecting the angle reinforcements for a crack.

### **EAD Requirements**

This EAD requires, for helicopters with 640 or more hours time-in-service (TIS) since installation of MOD 07 3215 or since installation of an applicable reinforcement angle, within 10 hours TIS, inspecting certain reinforcement angles for a crack. If there is a crack, this EAD requires, before further flight, repairing the reinforcement angle. As an option to performing the 10 hour TIS repetitive inspections, this EAD allows an alternate 165 hour TIS repetitive inspection.

### **Differences Between This EAD and the EASA EAD**

This EAD is not applicable to the AS350BB as that model is not type certificated in the U.S. This EAD applies to Airbus Model AS350C and AS350D1 helicopters because these helicopters have a similar design. The EASA EAD requires a 165 hour TIS repetitive inspection, this EAD allows the 165 hour TIS inspection as an option. Finally, the EASA EAD requires operators to contact Airbus if there is a crack, this EAD does not, however it does require repairing the crack before further flight.

### **Interim Action**

We consider this EAD to be an interim action. If final action is later identified, we might consider further rulemaking then.

### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. "Subtitle VII, Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701, General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Adoption of the Emergency Airworthiness Directive (EAD)**

We are issuing this EAD under 49 U.S.C. Sections 106(g), 40113, and 44701 according to the authority delegated to me by the Administrator.

2014-07-52 **Airbus Helicopters (previously Eurocopter France):** Directorate Identifier 2014-SW-021-AD

#### **(a) Applicability**

This EAD applies to Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters, certificated in any category, with:

- (1) Modification (MOD) 07 3215 installed; or

(2) With a reinforcement angle, part number (P/N) 350A08.2493.21 or P/N 350A08.2493.23, installed.

**(b) Unsafe Condition**

This EAD defines the unsafe condition as a crack in a rear structure to tailboom junction frame reinforcement angle (reinforcement angle), which if not detected could result in loss of the tailboom and subsequent loss of control of the helicopter.

**(c) Effective Date**

This EAD is effective upon receipt.

**(d) Compliance**

You are responsible for performing each action required by this EAD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

(1) For helicopters with 640 or more hours time-in-service (TIS) since installation of MOD 07 3215 or since installation of an applicable reinforcement angle, within 10 hours TIS, and thereafter, at intervals not exceeding 10 hours TIS, inspect each reinforcement angle for a crack as depicted in Figure 1 of Airbus Helicopters Emergency Alert Service Bulletin No. 05.00.70 for Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1 helicopters and Airbus Helicopters Emergency Alert Service Bulletin No. 05.00.62 AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters, both Revision 0 and dated March 24, 2014.

(2) If there is a crack, before further flight, repair the reinforcement angle in a manner approved by the manager listed in paragraph (f)(1) of this EAD.

(3) As an optional terminating action for the repetitive inspections required by paragraph (e)(1) of this EAD, at intervals not exceeding 165 hours TIS, remove screw No. 5 from the reinforcement angle, thoroughly clean the area around the hole and inspect the reinforcement angle for a crack. If there is not a crack, reinstall the screw. Sequentially repeat the steps required by this paragraph for screws No. 6 through No. 12. If there is a crack, comply with paragraph (e)(2) of this EAD.

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this EAD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this EAD through an AMOC.

**(g) Additional Information**

(1) For further information contact: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

(2) For a copy of the service information referenced in this AD, contact: Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(3) The subject of this AD is addressed in European Aviation Safety Agency EAD No. 2014-0076-E, dated March 25, 2014.

**(h) Subject**

Joint Aircraft Service Component (JASC) Code: 5302: Rotorcraft Tailboom.

Issued in Fort Worth, Texas, on March 28, 2014.

Kim Smith,  
Manager, Rotorcraft Directorate,  
Aircraft Certification Service.