



FAA
Aviation Safety

SPECIAL AIRWORTHINESS INFORMATION BULLETIN

SUBJ: Alternative Methods of Compliance (AMOC) to Airworthiness
Directive (AD) 89-25-10 and AD 89-25-08

SAIB: CE-10-34
Date: May 18, 2010

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin is written to inform the public, users, operators, and repair and inspection facilities about how to obtain a copy of the universal global AMOC for AD 89-25-10 and AD 89-25-08.

Background

The two subject ADs require the inspection of certain areas of the wing to the requirements of the Hawker Beechcraft Corporation, Structural Inspection and Repair Manual (SIRM) 98-39006. The two respective ADs use and identify revision levels of the SIRM which were current when the ADs were written. Since that time, the HBC SIRM has been revised many times.

Recommendations

It is our recommendation and intent of this SAIB for you to use the attached universal global AMOCs to facilitate your compliance with the two subject ADs. That is, you may use these universal global AMOCs for compliance to the respective ADs following the identified (current) revision levels of 98-39006, Structural Inspection and Repair Manual (SIRM).

For Further Information Contact

Steven E. Potter, Aerospace Engineer, Wichita Aircraft Certification Office, 1801 Airport Rd, Wichita, Ks. 67209, Office Phone: (316) 946-4124; fax: (316) 946-4107; e-mail: Steven.Potter@faa.gov; or

Barry Ballenger, Aviation Safety Engineer, Small Airplane Directorate, 301 Locust, Room 301, Kansas City, Mo. 64106; phone: (816) 329-4152; fax: (816) 329-4149; e-mail: Barry.Ballenger@faa.gov