


SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRCRAFT CERTIFICATION SERVICE
800 INDEPENDENCE AVENUE, S.W.
WASHINGTON, DC 20591

No. ACE-98-41
July 24, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

Introduction:

The purpose of this Special Airworthiness Information Bulletin is to advise owners/operators of the Dornier Model 228 airplanes of the need to review the service information listed below.

Background:

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of specified Dornier Model 228 airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included; mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Owners/operators of Dornier Model 228 airplanes should also note that there have been Airworthiness Directives issued against these airplanes concerning other safety issues.

Recommendations:

The service information identified in this document is not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the Dornier Model 228 airplanes review their compliance with the service information listed below.

Service Information No.	Date	Title
SB-228-024 Revision 1	August 5, 1988	Stabilizer Connection - Modified Stabilizer/Fuselage Supports
SB-228-035 Revision 1	February 18, 1986	Replacement of Rivet on Horizontal Stabilizer Brackets and Inspection of Horizontal Stabilizer Connection Area
SB-228-143	March 3, 1989	Electrical System - Essential Bus Modification
SB-228-200	September 9, 1992	Improvement of Lightning Protection
SB-228-201 Revision 1	November 16, 1992	Main Brake System - Modification of Master Cylinder
SB-228-227 Revision 1	June 22, 1998	Flight Controls - Inspection of Aileron Control Rods.

2 ACE-98-41

SI-228-019

November 13, 1986

1) Inboard Wheel Bearing Cup Bore Repair

2) Main Wheel Assembly Inspection

The service information document can be obtained from:

Dornier Luftfahrt GmbH

Customer Support

P.O. Box 1103

D-82230 Wessling

Germany

Phone: (08153) 300;

Fax: (08153) 302985

For Further Information Contact:

Karl Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 1201 Walnut, Suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6934.