United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number **SE00223SE**

This certificate, issued to **Rocket Engineering Corporation**
East 6427 Rutter Road, Felts Field
Spokane, WA 99212

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

Original Product—Type Certificate Number: * See attached FAA Approved Model List (AML)

Make: * No. SE00223SE for list of approved engine

Model: * Models and applicable regulations

Description of the Type Design Change: Installation of Auto-Valve Inc. oil drain valve, manufactured in accordance with Auto-Valve Inc. Drawing Number BJ107R, dated July 12, 1995, or later FAA approved revision and installed in accordance with Rocket Engineering Installation Instructions Number BJ107, dated July 26, 1995, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model engines only. This approval should not be extended to other engines of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Model List (AML) No. SE00223SE, dated August 9, 1995, must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 26, 1995

Date of issuance: August 9, 1995

Date reissued:

Date amended:

By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA Form 8110-2(10-68)