United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA01725SE

This certificate, issued to:

Hawker Beechcraft Corporation
9709 East Central
Wichita, Kansas 67206

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 *of the* Federal Aviation *Regulations.*

Original Product—Type Certificate Number: TCDS 3A15
Make: Hawker Beechcraft
Model: G36/A36 Bonanza

Description of the Type Design Change: Installation of TAWS functionality and autopilot revisions in accordance with Garmin Master Data List 005-C0149-01, Revision H, or later FAA approved revision.

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. A36 model aircraft must have STC SA01595SE installed. A copy of this certificate must be maintained as part of the permanent records for the modified aircraft. Airplane Flight Manual Supplement 190-00422-05, Rev. D, Garmin G1000 Integrated Avionics with TAWS in a Hawker Beechcraft Corporation Model A36/G36 Bonanza, or later FAA approved revisions must be kept with the FAA approved Airplane Flight Manual.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 05, 2006
Date of issuance: May 16, 2007
Date reissued: August 14, 2007
Date amended:

By direction of the Administrator

(Signature)

Manager, Seattle Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA Form 8110-2(10-68)