United States of America

Department of Transportation — Federal Aviation Administration

Supplemental Type Certificate

Number SA1804CE

This certificate issued to Advanced Aircraft Extinguishers, Ltd.
P.O. Box 1117
Blue Springs, MO 64013-1117

certifies that the change in the type design for the following product with the limitations and conditions thereto as specified hereon meets the airworthiness requirements of Part 3 *of the* Civil Air *Regulations.* as defined by Type Certificate Data Sheet 5A3

Original Product — Type Certificate Number: 5A3

Make: Beech

Model: 45, A45, D45

Description of Type Design Change:

Installation of Total Flood Corporation fire extinguishing system in the cabin and/or a fire extinguishant system in the engine compartment per Total Flood Corporation Drawing List TFB10-0012-3 dated October 7, 1982, or later FAA approved revision. Flight Manual Supplement TFA09-0023-3 dated October 21, 1982, or later FAA approved revision must be inserted in the airplane Flight Manual when the airplane is modified per this STC.

Limitations and Conditions:

Effectivenss of the engine compartment fire extinguishant system was not evaluated. This approval should not be extended to other specific airplanes of this model on which other previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that airplane.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 12, 1982

Date of issuance: October 22, 1982

Date issued: February 1, 1993

Date amended:

By direction of the Administrator
Original Signed By
Ronald K. Rathgeber
(Signature)

Ronald K. Rathgeber, Acting Manager
Wichita Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA Form 8110-2 (10-49)