Lynn Brown

FYI
STC file in SW Region

United States of America
Department of Transportation — Federal Aviation Administration

Supplemental Type Certificate

P/N 190-474 WS

Number SA3643SW

This certificate, issued to The Rebound Company
P. O. Box 656
510 Ave. E
Marble Falls, Texas 78654

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 *of the* Civil Air *Regulations.*

Original Product — Type Certificate Number: 3A12
Make: Cessna
Model: 172

Description of Type Design Change:

Installation of seat restraint belt, pilot and/or copilot in accordance with The Rebound Company "Slide-No-More Seat Restraint Installation Instructions" for Single Engine "Cessnas" and Drawing No. 060686-0101 dated September 9, 1986.

Limitations and Conditions:

The compatibility of this modification with other previously approved modifications is the responsibility of the installer.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 7, 1986
Date of issuance: August 15, 1986
Date reissued: Nov 14, 1986
Date amended:

By direction of the Administrator

FEDERAL AVIATION ADMINISTRATION

for L. B. Andriesen *(Signature)*
Assistant Manager, Aircraft Certification Division, Southwest Region *(Title)*

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA Form 8110-2 (10-68)