United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SA10551SC

This Certificate issued to

Hartzell Propeller Inc.
One Propeller Place
Piqua, OH 45356

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product Type Certificate Number : 3A16

Make : Raytheon Aircraft Company

Model : 58, 58A, G58

Description of Type Design Change: Installation of Hartzell PHC-J3YF-2UF/FC7391D(B, K) propellers in accordance with Drawing No. 20002-0000, Rev. A, dated April 20, 2006, or later FAA approved revision. FAA approved Airplane Flight Manual Supplement AFMS20002-1, Rev. IR, dated July 6, 2006, or later FAA approved revision is required for Baron 58, 58A, and G58 airplanes, serial number TH-1389, TH-1396 and after. Airplane Flight Manual Supplement AFMS20002-2, Rev. IR dated July 6, 2006, or later FAA approved revision is required for Baron 58 and 58A airplanes, serial number TH-1 thru TH-1395, except TH-1389.

Limitations and Conditions: The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : September 30, 2004

Date of issuance : July 11, 2006

Date reissued :

Date amended :

By direction of the Administrator

(*Signature*)

S. Frances Cox
Manager, Special Certification Office
Southwest Region

(*Title*)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.