United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SA3511WE

This Certificate issued to **AIR MEDIC, L.L.C.**
7309 Clybourne Avenue, Unit 3
Sun Valley, California 91352

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 *of the* Federal Aviation *Regulations.*

Original Product Type Certificate Number : **A20WE**

Make : **The Boeing Company**

Model : **747-100, -200B, 200C, -300, -400, -400D Series**
747SR, 747SP Series

Description of Type Design Change: **Installation of Stretcher Carrier, in accordance with AIR MEDIC Stretcher Carrier Master Drawing List AM-2001, Revision "K", dated February 28, 1978, or later FAA approved revision and utilized in accordance with Air Medic Operations Specifications AM 2017, is required as part of this installation.**

Limitations and Conditions: **The approval of this change in type design applies basically to the Boeing 747 Series passenger versions only. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between the change and those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft.**

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : November 15, 1976

Date of issuance : March 21, 1978

Date reissued:

Date amended : November 24, 1992, August 21, 2003, July 26, 2007

By direction of the Administrator

(Signature)

Program Manager, Systems and Equipment Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.