United States Of America

Department of Transportation – Federal Aviation Administration

Supplemental Type Certificate

Number ST01595LA-D

This Certificate issued to Learjet Inc.
1255 E. Aero Park Blvd.
Tucson, Arizona 85706

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25* *of the Federal Aviation Regulations.*
(For Certification Basis see T.C.D.S. T00005NY)

Original Product Type Certificate Number: T00005NY
Make: Bombardier Aerospace, Inc.
Model: BD-100-1A10

Description of Type Design Change: Installation of Control Wheel Lighted Chart Holders, in accordance with Master Drawing List HC33105000, Revision "B", dated April 23, 2004, or later FAA Approved Revision.

Limitations and Conditions:
This STC should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. Modification of an aircraft by this Supplemental Type Certificate obligates the aircraft operator to include the maintenance information provided by Document Number HC33105000-IFCA-1 in the operator's Aircraft Maintenance Manual and the operator's Aircraft Scheduled Maintenance Program.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 03, 2004

Date of issuance: April 23, 2004

Date reissued:

Date amended: March 03, 2005

By direction of the Administrator

(Signature)
ANDREW GFRERER
(DAS-S-31) DAS ADMINISTRATOR
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

FAA Form 8110-2(10-68)

This certificate may be transferred in accordance with FAR 21.47.