United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA4718NM

This certificate, issued to **Machen, Inc.**
10555 Airport Drive
Coeur d'Alene Airport
Hayden Lake, ID 83835

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 *of the* Federal Aviation *Regulations.*

Original Product—Type Certificate Number: A17WE
Make: Piper
Model: PA-60-601P, -602P, and -700P

Description of the Type Design Change: Installation of a pneumatic door seal pressure system in accordance with Machen, Inc. Installation Instructions Report No. 65-30, dated March 15, 1989, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. this approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Airplane Flight Manual Supplement (AFMS), dated April 14, 1989, or later FAA approved revision, must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 4, 1989

Date of issuance: April 14, 1989

Date reissued:

Date amended: April 20, 1999

By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA FORM 8110-2(10-68)