United States of America

Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number **SR02120NY-D**

TRANSFERRED

This certificate issued to Honeywell International Inc.
23500 W. 105th Street
Olathe, KS 66061

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 29 *of the* Federal Aviation *Regulations.*

Original Product Type Certificate Number: R00002RD

Make: Agusta S.p.A

Model: AB139

Description of Type Design Change:
Installation of a Honeywell Chadwick Model 15175 VXP System in accordance with Keystone Helicopter Installation drawing List IDL01149 Rev. A dated 9/22/2006 or later approved revision.

Limitations and Conditions:
1. Keystone Helicopter Instructions for Continued Airworthiness, Honeywell Chadwick Model 15175 VXP System Installation in Agusta S.p.A Model AB139 Aircraft, Report No. IC01149 Rev. – dated 06/01/2006 or later approved revision is required for this modification.
2. FAA approved Rotorcraft Flight Manual Supplement, Supplement No. FM01149 Rev. – dated 09/22/2006 or later FAA approved revision is required for this modification.
3. The installer must determine whether this design change is compatible with previously approved modifications.
4. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 7, 2006

Date reissued: June 5, 2009

Date of issuance: September 22, 2006

Date amended:

By direction of the Administrator

(*Signature*)

FOR Anthony Socias
Manager
New York Aircraft Certification Office

(*Title*)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

 This certificate may be transferred in accordance with FAR 21.47.