United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SA00289WI

This certificate issued to: Hawker Beechcraft Services, Inc.
1980 Airport Road
Wichita, KS 67209

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 *of the* Federal Aviation *Regulations*.

Original Product - Type Certificate Number: A24CE

Make: Beech

Model: 1900D

Description of Type Design Change: Installation of a Trimble TNL 2100T Global Positioning System (GPS), interfaced to EFIS-84 and Collins Flight Director F/D-65. Data Required: (1) Master Document List No. RD9966-01, Revision B, dated March 20, 1995; and (2) United Beechcraft, Inc. Document No. RD9966-02, FAA Approved Airplane Flight Manual Supplement dated March 27, 1995; or later FAA approved revisions to (1) or (2).

Limitations and Conditions: This approval should not be extended to other specific airplanes of this model on which other previously approved modifications are incorporated, unless it is determined that the interrelationship between this change and any of these other previously approved modifications will introduce no adverse effect upon the airworthiness of that airplane. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 18, 1995

Date reissued: May 29, 2007

Date of issuance: February 21, 1995

Date amended:

By direction of the Administrator

Original signed by Charles Riddle

(*Signature*)

Charles D. Riddle
Program Manager
Wichita Aircraft Certification Office

(*Title*)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.