United States of America

Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SA00021MC

This certificate issued to: Michelin North America, Inc.
One Parkway South
Greenville, SC 29615

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product - Type Certificate Number: A00009WI

Make: Hawker Beechcraft

Model: 3000 (USAF and USN T-6)

Description of Type Design Change: Installation of Michelin Main Landing Gear Radial Tires, P/N M16301, in accordance with Michelin Technical Drawing AVTAN-06-03, Revision A, dated June 14, 2006 or later FAA approved revision.

Limitations and Conditions:

-Warning- Replacement of the Hawker Beechcraft OEM Bias Ply Main Landing Gear Tire with Michelin Radial Tire requires replacement of Hawker Beechcraft hydraulic line on the RH main landing gear actuator and tire clearance check in accordance with Michelin Technical Drawing Instructions.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: August 19, 2005

Date of issuance: December 30, 2008

Date reissued: January 23, 2009

Date amended:

By direction of the Administrator

Ronald K. Rathgeber
(Signature)

Ronald K. Rathgeber
Manager
Military Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.