United States of America
Department of Transportation_Federal Aviation Administration

Supplemental Type Certificate

Number SA00639SE

This certificate, issued to **Soloy, LLC**
450 Pat Kennedy Way, SW
Olympia, WA 98501

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 **of the** Civil Air **Regulations.**

Original Product—Type Certificate Number: 3A15
Make: Beech
Model: A36, A36TC

Description of the Type Design Change: Installation of Turbine Outlet Temperature Indicator in accordance with Soloy Master Drawing List 887-101, Revision -, dated July 30, 1998, or later FAA approved revision. This STC is only applicable to aircraft that have been modified in accordance with Soloy STC SA3523NM.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 28, 1998 **Date reissued:** December 2, 2004

Date of issuance: October 23, 1998 **Date amended:**

By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding $1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

FAA FORM 8110-2(10-68)