

Errata Sheet
for
Advisory Circular 150/5210-7D
Aircraft Rescue and Fire Fighting Communications

Last Update: April 24, 2008

This errata sheet logs content errors that were identified after the advisory circular (AC) was issued on 4/14/2008. These errors have been corrected in the electronic version of the AC available on the FAA website. All page numbers refer to the PDF version of the document posted on www.faa.gov.

#	Description of Correction	Location	Rationale	Date Correction was Published
1	For "Flashing Red", replace the text in the "Aircraft on the Ground" column with the following: "Taxi clear of runway in use".	Page A-3, Appendix 2, Table A2, "Meaning of ATCT Light Gun Signals."	Corrects an error.	4/24/2008