



Federal Aviation Administration

Memorandum

Date: OCT 07 2010

To: Lance T. Gant, Manager, Rotorcraft Certification Office, ASW-170
ACOLT
BASOO
GASOO

From: ~~For~~ David W. Hempe, Manager, Aircraft Engineering Division, AIR-100 *Sym Cohen*

Prepared by: Ralph Meyer, Delegation and Airworthiness Programs Branch, AIR-140

Subject: Deviation from Order 8100.15, Multiple Use Repairs Approved by TC ODA
(Your Request, July 21, 2010)

This memorandum grants a Rotorcraft Certification Office request to allow Bell Helicopter ODA to approve multiple use repairs under function code 8130.

As written, Order 8100.15 is currently very restrictive regarding TC holder-developed repairs, and future revisions to Order 8100.15 will allow TC ODA holders to specifically approve multiple-use "reusable" repair data. In addition to the specific repair approval authority provided for under function code 8130, approvals in support of repairs developed for service bulletins or service letters, etc., may be accomplished under function code 8010.

This deviation is also applicable to all TC ODA holders who need the ability to approve multiple reusable repairs. Appropriate revisions to the ODA holder's procedures manual must describe this authority and the procedures to approve multiple use repair data. This authority will also be provided for in the next revision to Order 8100.15

For more information, contact Ralph Meyer, AIR-140, 405.954.7072, Ralph.meyer@faa.gov.