


REVISED SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department
of Transportation
**Federal Aviation
Administration**

AIRCRAFT CERTIFICATION SERVICE
800 INDEPENDENCE AVENUE, S.W.
WASHINGTON, DC 20591

No. CE-98-04R1
July 24, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

Introduction:

The purpose of this Special Airworthiness Information Bulletin (SAIB) is to advise owners/operators of Extra Model airplanes of the need to review the service bulletins listed below. This SAIB revises SAIB ACE-98-04, dated October 17, 1998, by adding service bulletin SB-300-2-97 dated 9/25/97.

Background:

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of specified Extra airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included; mandated compliance by initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

Recommendations:

The service bulletins identified in this document were not considered appropriate for AD action at this time, however, the FAA strongly suggests that all owners/operators of the specified Extra Model airplanes review their compliance of the service bulletins listed below.

Service No.	Bulletin	Date	Title (Model Affected)
SB-300-1-91		10/22/91	Main Undercarriage U-Spring, EA-300.
SB-300-2-95		5/3/95	Upper Longeron Inspection, EA-300, EA-300/S, EA-300/L.
SB-300-5-94		1/31/95	Air Inlet Screen, EA-300, EA-300/S.
SB-300-6-94		1/31/95	Fire Protection Cowling Area and Firewall, EA-300, EA-300/S.
SB-300-2-97		9/25/97	Fuselage Structure/ Tail Spring Support, EA-300/L, EA300/200.

The service bulletins can be obtained from:

Extra Fluegzeugbau GmbH
Flugplatz Dinslaken
46569 Hünxe
Germany
Telephone: 01-49-2858-9137-13

For Further Information Contact:

Karl M. Schletzbaum, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 601 E. 12th Street, Kansas City, Missouri 64106, telephone: (816) 426-6934.