


# SPECIAL AIRWORTHINESS INFORMATION BULLETIN



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

AIRCRAFT CERTIFICATION SERVICE  
800 INDEPENDENCE AVENUE, S.W.  
WASHINGTON, DC 20591



No. ACE-98-29  
May 13, 1998

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

This is issued for informational purposes only and any recommendation for corrective action is not mandatory.

## Introduction

The purpose of this Special Airworthiness Information Bulletin is to advise operators of Piaggio Model P180 aircraft of the need to review the service bulletins listed below.

## Background

The Small Airplane Directorate, Aircraft Certification Service, of the Federal Aviation Administration (FAA) conducted a review of the specified Piaggio airplane service bulletins. The purpose of the review was to evaluate each service bulletin to determine the continued airworthiness safety aspect. The options considered by the FAA included: mandated compliance by the initiation of an FAA Airworthiness Directive (AD), various forms of notices, or no further action required.

## Recommendations

The service bulletins identified in this document were not considered appropriate for AD action at this time, however, the FAA strongly suggests that all operators of Piaggio Model P180 aircraft review their compliance of the service bulletins listed below.

<b>Service Bulletin No.</b>	<b>Date</b>	<b>Title</b>
SB 80-0094	August 7, 1997	Cabin Entry Door Pins Guides, Modification to Increase Life Limit.
SB 80-0093	May 10, 1996	Flap Drive Unit Inspection
SB 80-0082	April 28, 1997	Rear Pressurized Bulkhead Modification.
SB 80-0081	April 28, 1997	Forward Pressurized Bulkhead Modification.
SB 80-0061	March 30, 1994	Hydraulic System Cleaning.
SB 80-0060	April 18, 1994	Wing Trailing Edge/Aileron Seals - Modification.
SB 80-0055	April 15, 1994	Autopilot Wiring Modification.
SB 80-0039	June 23, 1993	Vertical Stabilizer Tip Fairing - Sealing.
SB 80-0020	April 8, 1992	Main Landing Gear Doors and Hinges - Modification.
SB 80-0017	November 13, 1991	Fuselage Sealing Inspection
SB 80-0016	November 7, 1991	Main Landing Gear Door System - Modification.
SB 80-0005 R1	August 1, 1991	Anti-Ice System Modifications.

The service bulletin information can be obtained from:

Rinaldo Piaggio  
Via Cibrario 4  
16154 Genova - ITALY

## For Further Information Contact

Dave Keenan, Aerospace Engineer, FAA, Project Support Branch (ACE-112), Small Airplane Directorate, 601 East 12 Street, Kansas City, Missouri 64106, telephone: (816) 426-6934; facsimile: (816) 426-2169.