

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SH1710GL

This certificate issued to Scott's-Bell 47, Inc.
100 Minnesota Avenue
Le Sueur, MN 56058

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations. (See Type Certificate Data Sheet 2H3 for complete certification basis).

Original Product--Type Certificate Number : 2H3

Make : Bell Helicopter Textron

Model : 47G-2A, 47G-2A-1, 47G-3, 47G-3B, 47G-3B-1, 47G-3B-2, 47G-3B-2A, 47G-4, 47G-4A, 47G-5, 47G-5A

Description of Type Design Change:

Install fixed elevator in lieu of synchronized elevator in accordance with Reabe Aircraft Improvement, Inc. Installation Instruction/Drawing No. 2, No Rev., dated November 22, 1991 or later FAA approved revisions.

Limitations and Conditions:

1. The installer must determine whether this design change is compatible with previously approved modifications.
2. FAA approved Rotorcraft Flight Manual Supplement, no rev., dated March 10, 1992 or later FAA approved revision is required.
3. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data, which is the basis for approval, shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : February 25, 1992

Date reissued : March 7, 2002; April 27, 2007; December 15, 2010; August 7, 2014

Date of issuance : March 10, 1992

Date amended : August 4, 1994

By direction of the Administrator

Original Signed By:
Karol Mordasiewicz

(Signature)

Karol Mordasiewicz
Manager, Airframe and Administrative Branch
Chicago Aircraft Certification Office

(Title)



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate
(Continuation Sheet)

Number SE144GL