

Supplemental Type Certificate

Number ST01891LA

This Certificate issued to LifePort, Inc.
1610 Heritage Street
Woodland, Washington 98674

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

Original Product Type Certificate Number : *See attached FAA Approved Model List (AML)

Make : *No. ST01891LA for list of approved airplane models

Model : *and applicable airworthiness regulations.

Description of Type Design Change: Installation of a Commercial Medical Stretcher in accordance with FAA Approved Model List (AML) No. ST01891LA, dated May 5, 2006 or later FAA approved revision. FAA approved Airplane Flight Manual Supplement No. EGR-808-11, dated May 1, 2006, or later FAA approved revision is required as part of this installation.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : February 21, 2006

Date reissued :

Date of issuance : May 5, 2006

Date amended :



By direction of the Administrator

(Signature)

Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.