

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number ST01786NY-D

This certificate issued to Dassault Falcon Jet- Wilmington Corp.
191 North DuPont Highway
New Castle, DE 19720

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number : A46EU
Make : Dassault Aviation
Model : Falcon 900EX

Description of Type Design Change : Installation of Honeywell Avionics Primus 2000 Flight Management System (FMS) NZ6.0 Upgrade in accordance with Dassault Falcon Jet-Wilmington Master Drawing List, 144480300, Revision -, dated August 29, 2005.

Limitations and Conditions :

- (1) Airplane Flight Manual Supplement 144480303, Revision -, FAA approved September 16, 2005 is required with this installation.

(See Continuation Sheet Page 2)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : August 20, 2005

Date reissued: -

Date of issuance : September 16, 2005

Date amended: -



By direction of the Administrator

(Signature)
Joseph Licata

Administrator, DAS-955240-NE

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number ST01786NY-D (Continued)

Date of Issuance: September 16, 2005

Date Amended :

Limitations and Conditions (continued)

- (2) Instructions for Continued Airworthiness (ICA) 144480306, Revision -, dated August 27, 2005 is required with this installation.
- (3) This design change is applicable to Dassault Aviation Falcon 900EX aircraft which have previously been equipped with Honeywell Avionics Primus 2000 Flight Management System (FMS), software version NZ5.2(), in accordance with the following:
 - a. Dassault Aviation Service Bulletins 196 or 201 (Mods M3322 / M3624 / M3512 / M3333)
or
 - b. Dassault Aviation Modification M3013
or
 - c. Dassault Aviation Service Bulletin 211 (Modification M3813)
or
 - d. Dassault Aviation Service Bulletin 225 (Modification M3827)
- (4) Compatibility of this design change with previously approved modifications must be determined by the installer
- (5) If the holder of this certificate permits another person to incorporate the modification, the holder will give the person written evidence of this permission

.....END.....