

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SA1557WE

This certificate issued to RAYJAY Parts LLC
10 Harbor Island Drive
Key Largo, Florida 33037

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product – Type Certificate Number: A3SO

Make : Piper

Model: PA-32-260

Description of Type Design Change: Installation of turbocharged Lycoming O-540-E4B5 engine in accordance with FAA Sealed Roto- Master (Rajay) Drawing List No. RJ0800 or later FAA approved revision.

Limitations and Conditions: FAA Approved Roto- Master (Rajay) Flight Manual Supplement dated December 8, 1967 or later FAA approved revision is required with this installation. The O-540-E4B5 engine must be modified to incorporate turbochargers in accordance with STC No. SE40WE. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will produce no adverse affect upon the airworthiness of that airplane. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : September 27, 1967

Date of issuance : December 8, 1967

Date reissued : Jan. 14, 1969; Feb. 10, 1982;
Oct. 23, 1987; Sept. 22, 1995 ;
Dec. 19, 2003; June 26, 2006

Date amended : Mar. 21, 1985



By direction of the Administrator

(Signature)
Melvin D. Taylor, Manager
Atlanta Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

