

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SA418NW

This certificate, issued to Jobmaster Company, Inc.

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

Original Product — Type Certificate Number: * *See attached Approved Model List (AML)
Make: * No. SA418NW for list of approved aircraft
Model: * models and applicable airworthiness regulations

Description of Type Design Change: Installation of a float spreader assembly in accordance with Jobmaster Company Document JB77, Revision A, or Document JB77A, or later FAA approved revisions.

NOTE: This installation is applicable to Edo float models 58-4580, 679-4930, 59-5250, and 61-5870 only.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and Approved Model List (AML) No. SA418NW must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 14, 1977

Date reissued:

Date of issuance: April 19, 1977

Date amended: July 6, 1977; June 28, 1988



By direction of the Administrator

D. L. Reagin
(Signature)

Asst. Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.